THE STORY OF AIRCRAFT AIRCRAFT MAINTENANCE MAINTENANCE RECORD RECORD SYSTEM

ENGINE MAINTENANCE RECORDS



ENGINE MAINTENANCE RECORDS

Log No. ____

Aircraft Registration No
Engine Manufacturer / COMING Model TO-360 - CIC Serial No. 1-10708-51 A
Date installed on aircraft Time Between Overhauls (TBO) ZOO Hours
lf used on multi-engine aircraft: ☐ Rìght ☐ Left ☐ Front ☐ Rear



(All applicable information must be filled in)

AEROTECH PUBLICATIONS INC.

P.O. Box 1359 / Southold, NY 11971-0965 (631) 765-9375 1-800-235-6444 FAX: (631) 765-9359

©1979 Aerotech Publications, Inc.

je No.

DATE TOTAL TIME IN SERVICE

TOTAL TACH OR RECORDING SINCE OVERHAUL TIME TIME

DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

16/06 3313.6

3313.6

TOTALS brought forward from previous page

This is to certify that engine described hereafter has been overhauled to manufacture's new part limits by Corona Cylinder and Engine Overhaul Inc.

Engine disassembled, cleaned, and inspected in accordance with manufacture's instructions. All steel parts magnafluxed. All applicable Airworthiness Directives and Mandatory Manufacturer's Service Bulletins are in compliance. A decription of these repairs is on file at this agency under:

JOB NO. 11077

MFG.LY CONNO

DATED 5/16/06

MODEL TO-360-CK

Serial No. L - 10708 - 51 A TTIS 3313.6

CORONA CYLINDER & ENGINE OVERHAUL

F.A.A. REPAIR STATION # 09VR726Y 1965 AVIATION DR. #A CORONA, CA 92880

951 736-6452 -

Authorized Signature



f.a.a. repair station # 09VR726Y / 1965 aviation drive corona,ca 92880 951 736-6452

· Engine Overhaul Warranty

IO-360 C1C L-10708-51A

· 5/16/2006 O-SMOH

Warranty. Corona Cylinder and Engine Overhaul, Inc. (hereafter referred to as Overhauler) warrants each overhauled engine to be free from defects in material workmanship. This Warranty is expressly subject to the terms and conditions set forth below and shall not apply outside the overhaul periods listed or to any engine which has been subject to misuse, neglect, accident or damage from the elements or which has been installed, repaired, maintained or altered in any manner which in the judgment of the Overhauler has had an adverse effect on the performance or reliability of engine or part.

Time Limits. This Warranty for parts and labor extends for a period of twelve (12) months from the date of service or three hundred (300) hours, whichever occurs first. The Overhauler considers the frequent use and operation of an engine to be an integral part in extending engine life. For this reason, Overhauler considers warranty hours based on a minimum usage of 25 hours per month regardless of actual engine operation hours, warranty will extend thru engine manufactures tho on a prorated basis as long as all warranty conditions are met and documented

Express Conditions. As time and condition of this Warranty, the customer is required to follow factory recommended service procedures and maintenance guidelines. Proper maintenance logbooks are to be kept by and maintained by the customer and shall be furnished to Overhauler on demand as a condition to the Warranty.

on demand as a condition to the Warranty.

Limitations and Exclusions. All parts and labor are to be approved by Overhauler prior to commencement of work under this warranty.

Overhauler's responsible only for the cost of reasonable labor and material necessary to repair or replace the parts. Overhauler determines to be defective in material or workmanship at Overhauler's place of business, located in Corona, Ca. Under no circumstances shall Overhauler be responsible for charges incurred in the removal and reinstallment of defective parts or engines. This warranty is exclusive and in lieu of all other warranties and representations, express or implied, or statutory, whether written or oral, including, but not limited to any warranty of merchantability or fitness and for any particular purpose, and implied warranty arising from any course of performance or dealing or trade usage. This warranty is also in lieu of any other obligation, liability, right of claim, whether in contract or in tort, including any right in strict liability, in or or any right arising from negligence on the part of the Overhauler, and Overhauler's liability on which claim shall in no case exceed the price Limitations and Liability. In no event, whether as a result or a breach of warranty contract or allowed academics of the Overhauler as a result or a breach of warranty.

allocable to the engine or part which gives rise to the claim.

Limitations and Liability. In no event, whether as a result or a breach of warranty, contract or alleged negligence, shall Overhauler be liable for special or consequential or any other damages, including but not limited to, loss of profits or revenues, loss or use of the engine or aircraft or cost or a replacement, personal injury or fatalities, or flight delays or cancellations. Cracked cylinders and crankcases are excluded from all warranties, unless it can be determined that the damage is a direct and proximate result of improper workmanship by Overhauler.

Accessory items are to be warranted by vendor of such items.




				BOBBORIANCE PAGE NO.
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED — SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
127/0	2			100 hr / annul 185 parts Englis 011 & Filter CHangel Spark plugs
				Cleaned & gapped, May timing
				CHecked Compression, 16, 77, 71, 75/80 CHanged Our Filter
				Copposed For Return To Service
				m/ch
				52323434474
3/15/	28	3525	0 Ta	THIS Engine inspected h as per looke / annual
)	\$ T			mot Inspection Changed Oil, Fill our Filter, Claudet gapped Sparl
CW	08/14/	Trictor	por Line	Pluss, Checked Timing Comp. 24, 75, 27, 26/80
		100 hr		appored For Return to Service
				MILL
				. 3294048
5/2/	09	3624		Thus engin was inspectal as po
		3 / 0.	8 5moH	The trip (con plug), the sections
				Changed Oil Oil Filter air filta chach Oil Liñas Chicked Timus Comp
				75,75,73,76/80 cm 08-14-07.
				aprival Fo Return to saye,
				CUP TOTAL C this page
				TOTALS-Carry forward to next page


DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
27-10	370/8	388.2	3701.8	Inspected in occordance with 100 hr Inspector of 16 F. ITer, Changel Plugs,
				C/w 08-14-07 aspor 58342 Due 2
				3801.8 Comp. 74 75 16 16/80
				cleand Intectors allected liming
				approved for Return to Service
				3294048 QEP
10/10-10	3760.1	446.5	3760.	Inspected In accordance with
				100 hr insp Changed Oil & Filter
				changed dir filter cleaned t gappe
				Sparkplugs C/w 08-14-07 aspen 5834. Due a 3860.1 Comp 73, 75, 76,
				75/80 checked Timing
				appoved for return to service
				Mell glob 3294048 aff
8-3-11	38082	494.6	3893.2	Inspected in according with 100 h
				Drap. Changel out a felle clevel
				I gapped part plugs chief and and
				Que e 3908.2 Charl ispector
				Comp 15, 72, 16 77 180
				appoint for return to some
				Jugle 32910 48 X 1
				SUB-TOTALS this page
				TOTALS-Carry forward to next page


DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK DATE 3862 2862 TOTALS brought forward from previous page ANNUALINS P. DF THIS FING. FER PORT 43 NEW ATT "D" CHECKLIST - ENG CONTROLS, ACCESSORIES, 100V1 BASICENS-4 MOONT ONKIL FOR OPERATION, WIND, TON AND SECURITY. - REMOVED BENDIX RISA SADI SERVO 4 INSTALLED NEW THROTTLE SHART LLEVER AND NEW ATTOTO PINS AT Date NOV.1, 2012 8- TACH 386Z BA. END OF LINKAGE - All WEAR IS NOW REMOVED AND I certify that this aircraft/engine has been inspected as NO MORE LOST MOTION required 91-409 (a) (i), IAW Part 43 for annual 100 hour inspection and has been found airworthy.

TTAF: 3 % TSMOH: 5+8 OBSERVED SYSTEM REINSTOLES JOB CHKIN A/P IA 1426586_ O/K= NO CONTAM IN OIL FITTER AND OMPRESSION EXCELLENT ON ALL CYLINDERS ANNUAL INSP. OF PROPELLOR HERELATERS Josep Sachiel A/AID 110858 Date: 05/15/2014 Aircraft # N55958 Serial # 28R-7335317 Total Time: 3921.85 SMOH: 608 45 I certify that this Engine has the been inspected in accordance with Far 43 Appendix D and was determined to be in airworthy condition this date Prepared By: Gary J Walker
Certification # A&P 563619440 IA Changed oil and filter serviced with 8qts of aero shell 50 wt oil cut filter and inspected no metal found cleaned and gapped spark plugs. removed mags and sent AEC in Redding Ca. for 500 hr inspection installed and timed to spec see form 8130-3. replaced all fluid caring hoses form Aviall see paper work replaced induction air filter installed new Brackett BA 10 element. replaced all fuel injection line clamps and compiled with AD 11-26-04 by inspection. inspected exhaust system by pressure test no defects noted, replaced all push tube seals and rocker box cover gaskets with new washed engine and test ran no leaks noted. TOTALS-Carry forward to next page



INSPI DETE SIGN	ECTED IAW AND RMINDED TO ED: David Vickers	DTERLING HIS PROPELLER H NOUAL INSPECTIC BE IN AIRWORTH LILLIO 5, IA 3161731 TSMO: 35-34 R	AS BEEN ON AND WAS BY CONDITION. ATE: 6-3-15	Page No ESCRIPTION OF WORK PERFORMED— CERTIFICATE NO. OF PERSON PERFORMING WORK ward from previous page
	ENGINE MODEL: ENGINE SIN: REG, NO: N59598 WORK ORDER: 1620 Engine Entries Remove starter and	San Carlos Fligh 655 Skyway Road, Ste 2: San Cairos CA 94070 Phone: (650) 946-1700 install new Skytec Starter Pr	5	DATE: 12/29/2015 A/C TSN: 3976.79 ENG TT: TACH: 3976.19 Work Order, 1620
900B W MONTA WORK AUGUS TT, PR 85.48 ALL ST SINCE SINCE ELT BA AD'S C PERFO	OP: 4007.33 ON 8-2 CRUTS RE-PACKE CENTRAL VAC A ALL FLUID LINE ATTERY IS DUE R HECKED THRU J RMED ANNUAL IN	J.C GUE RD 10-459-3392 ACH: 4007-33 TTAF: 400 7-02 SINCE OH PROFE D AND SERVICED 5/15/ ND REG FILTER CHAN REPLACEMENT: 85.48 EPLACEMENT: APA ULV 2016 ANNUAL ISPECTION IN ACCORD.	GE: 50.14 ON 5/15/14	NDIX D.
INJECT EXHAU OPERA CHECK WITH GROU NOTEL ACCO AIRW	ORS, INSTALLED JST, OK RIGHT MA LTION, INSTALLED GED FOR RESISTAN TEMPEST FINE WIN ND RUN OPERATIO	NEW BRACKET ELEME. G REMOVED AND SHIP D AFTER BENCH CHECK NCE VALUES AND ALL RE. DNAL CHECK AND LEAL AT THIS ENGINE HAS	PED OUT BECAUSE OF IN AND TIMED TO ENGINE, SHOWED HIGH, SUGGEST CCHECK PERFORMED, N BEEN INSPECTED ON A N AND DETERMINED TO A&P 52	TERMITANT PLUGS 1 REPLACING 0 PROBLEMS UGUST 1, 2016 IN
V	ses, or	HE THISE	find Lines, SUB-TOTALS	Mo Pholless, Noted. this page Kellot HHB 20707568 1.7 forward to next page






age No			
TEELMAN AVIATION, LLC	E RD	NORK PERFORMED— OF PERSON PERFORMING WORK	
IONTAGUE, CA 96064 30-459-3392 steelmanaviation1 VORK ORDER NO. 167 JUNE	5, 2019 N33930 THE 40 INSTALLED ON 8-27-02 SINCE	OH us page	
T, ENG: 4119.49 SOH, ENG: PROPELLER: 197.64 SINCE 5	500 HR MAG INSP: 197.64 SINCE RIGHT MAG REPAIR: KED AND SERVICED 5/15/2014 SINCE CENTRAL VAC AND SERVICED 5/15/2014 SINCE CENTRAL VAC AND SERVICE ENGI	ID INE	
REG FILTER CHANGE: 136.4 FLUID LINE REPLACEMEN 6-5-2019 REPLACE 6-2027 EL	T : 197.64 ON 5/15/14 SINCE OIL COOLER LINES REPLACE T BATTERY IS DUE REPLACEMENT: APRIL 2022, AD'S	ED	
ANNUAL INSPECTION ENGI PERFORMED ANNUAL INSPE	ECTION IN ACCORDANCE WITH FAR 43 APPENDIX D.	8qts ————————————————————————————————————	
eroshell 15x50, and installed nev engine, install new aft muffler fro	om knisley. Ground run operational check and leak check performed	ed	
of the oil cooler hose assemblies, of the fuel injector lines, no probl	lems noted, perform ea. 100hr/Annual or removal	3001	
ACCORDANCE WITH AN A	INE HAS BEEN INSPECTED ON JUNE 5, 2019 IN NNUAL INSPECTION AND DETERMINED TO BE		
AIRWORTHY ROBERT E. STEELMAN	KHEH Etcelan A&P 520707568 I.A		
ENGINE MODEL: ENGINE S/N:	Rossi Aircraft, Inc.	DATE: 9/19/2019 A/C TSN:	
REG. NO: N55958 WORK ORDER: 3695	Repair Station No. ZRSR378L 1903 Embarcadero Rd Palo Alto, CA 94303 Phone: 650-493-3326	ENG TT: TSMOH: TACH: 4130.47	
Engine Entries Removed , serviced ,	cleaned , gapped and re installed spark plugs.		
Maintenance Release The aircraft and/or comp	onent(s) on N55958 was repaired and inspected in accordance with current FARs return to service. Pertinent details of the repair we on file at this repair station.		
was found Airworthy for r DATE: 9/19/2019	orient(s) of Nosseso was repaired and inspected in accordance with current FARs return to service. Pertinent details of the repair are on file at this repair station un SIGNED:	nder Work Order No. 3695, Dated 9/19/2019.	
	Alberto Rossi Certified Repair Station No. ZRSR378L	Work Order: 3695 Printed by EBis 3 (datcomedia.com)	
ENGINE MODEL: 10-350-C1C ENGINE S/N: L-10708-51A	Rossi Aircraft, Inc.	DATE: 8/5/2020	
REG. NO: N55958 WORK ORDER: 4016	A Repair Station No. ZRSR378L 1903 Embarcadero Rd Palo Alto, CA 94303 Phone: 650-493-3326	A/C TSN: ENG TT: TSMOH: TACH: 4159,81	
Engine Entries Performed and complet	ted an Annual Inspection IAW Manufacturers MM & FAR Book 42 Appe		
AEROSHELL 15W50 o	il, inspected and replaced CH48110-1 oil filter, sent oil sample out to be	and cowling, serviced with 10 Qts. of	
and hoses. Inspected tr Compression test: #1-7	the Alternator/generator wiring and system. 78/80, #2-76/80, #3-78/80, #4-78/80	ations. Inspected the oil cooling system	
2020-14 Removed Cy	(#80), #2-78/60, #3-78/00, #3-78/00 sed wash on engine. Run a leak, check good All AD's Reviewed and ##8 and #1 hardware -silicone sealed and Re-torqued Cy#3 and #1 to alternator beit PN-73985-015, and Prop seal pin C-3317-228 Rem neto gaskets PN-LW12881 Removed and replaced statete pear ring	d complied with through AD Release# to manufacture's specifications loved and replaced (1) magneto gasket	
PN:62224 and (2) mag	placed starter gear ring		
PN:62224 and (2) mag	nent(s) on N55958 was repaired and inspected in		
PN:62224 and (2) mag	nen((s) on N55956 was repaired and inspected in accordance with current FARs s turn to service. Pertinent details of the repair are of file at this repair station under SIGNED;	rules of the Federal Aviation Regulations and der Work Order No. 4016, Dated 8/5/2020.	

DATE TOTAL TIME IN SERVICE	TOTAL TACH OR RECORDING SINCE METER OVERHAUL TIME	SIGNA	DESCRIPTION OF WC		WORK
Appendix D, part 43. Was		ion test: #1 72/80 #2 7	78/80 #3 74/80 #4	8	3 12/0/2
hoses ow found no defect, coupling inspection pew or #3 to removed both frozen new gaskets and secured h secured. Flushed oil coole new CH 48110-1 oil filter with new crush washer, tig new gaskets and torque. R Cleaned and lube engine or satisfactory and gauges with	nines & clamps & to tolunt in due; a clamp set when the text of a 472.6 fts, hoses replace n 05/15/2014 at 3921.85 fts, next #1 cylinder exhaust studs and nu ardware. Refit and reinstalled extra price and serviced engine w torque and safety wire. Remove thrend and safety wire. Cleaned, emoved and clean oil dip stick tu ontrol cable and rod-end bearings thir range. No leak noted. Clean t and applicable ADs thru Biweel t and applicable ADs thru Biweel	ement due 06/2027. 500 due 4421.85 tis. Remov ts and replaced with new haust shroud with some vith 8 qts of Aeroshell 15 d and clean oil sump suc, gaped and tested spark tibe and installed with ne . Performed post inspec ed and installed cowling	whour magneto impulse red exhaust risers #1 and re, reinstalled risers with missing hardware and 80%50 oil and installed tition screen, installed plug olugs and installed with w gasket and safety wire. tion engine run, operation	2003 4 CARC	of taler's
I certify this Engine has condition.		tin E. Pour 22713239IA	s found to be in Airworthy	MC H .	
	/10000 Airpark Way, Pacoima, 6		April 01, 2021 N 55958 Hobbs 1976.	SN PA28R-733	5317
1 1 1 1	biephone 316-095-642, 800-024-6 Brained engine oil with 8 qts of AS 15W	and removed oil filter, s	cent oil sample to Blackstone f CH48110-1 oil filter, torque a Dustin E. Pour A&P2713239	or analysis. Serviced engi	ne
Ask To a		TION INC. CA 91311 USA 43-6 scal fleet resilusation	April 27, 202 N 55958 Hobbs 2024	SN PA28R-733	15317
	filter, torque and safe Replaced all oil retur	aty wire. Removed and and in time flex hoses with ne	oil, removed oil filter, and to n 8 qts of AS 15W50 oil and i cleaned oil sump suction scre w. Retorque oil sump bolts a ory, no leak noted. Cleaned a Dustin E. Pour A&P2713239	nstalled new CH48110-1 on, installed plug and safety	
125/21 Drain ACH anal 18135) and	red engine oil \$ ysis. Services installed ne	dengine w	ter. Sent samp ith 89ts of	le to Blacks	tone for



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	SERVICE	OVERHAUL	IIME	TOTALS brought forward from previous page
-1-1				
7/9/21	43 16 31	1,002.4	4316.31	Drained engine oil & removed filter. Sent
A				sample to Blackstone for analysis & Serviced
	dam			engine with 8 gts of AS 15W50 oil
	Alan	HOH	unen	and installed new CH48110-1 oil filter.
				secured with safty wire
0/27/21	4340.96	1,027.36	4340.96	Drained engine oil & removed filter. Sent
				Seemple to Blackstone for analysis, Serviced
Add	em H.	Othu	an	engin with 8 gts of AS 15W50 oil
Ad	eem H.	Stren	-	and installed new CH48110-1 oil filter.
				Secured with safty wire. (HR on Oil 24.65)
1/28/22	4378.20	1,064.60	4378.20	Drained engine oil & removed filter. Sent
				sample to Blackstone for analysis. Serviced
Al	am H	. Otl	1 man	engine with 8 gts of 15 15 W 50 oil and
A	Jeem	40,24	nua '	installed new CH48110-1 oil Julier.
				Secured with Safty wire. (HR on oil 37.24)
				34.24)
3/4/22		10743	4387,7	Compression test: #1-75 #2-76#3-75,#4-76
				Character 1 200 12 17 18 18 - 10 #13 - 25 #11 16.
				Change oil, genice with 8 sts sensell
				Sw-50. Clean oil surtion screen
				Replace exhaust gaskets. Engine
			6	ground nun tleak cheeled RK mags Olt, been inspected in accordance with an 12015
			To	
	7			ADs through 2022 Os have been
				cnecked.
				SUB-TOTALS this page
			The state of the s	SUB-TOTAL C this see-



	OTAL TOTAL TIME TIME IN SINCE RVICE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED – SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
-11-23	1150sm	nety	Clw 100hr inspection, Changes	9
Tach Time I certify th accordance	at this Engine he with an Annual to be in airwor	_ Total Tinas been inspliction inspection thy condition	cil f Filter services with 79ts Apposhell INDPLOS aleases gapped 68 AFK Plugs a/w AD 2015-19-07 injetor Lines f clamps checks good e/w AD 2017 AD 95-26-13 oil cooler Lines checks good, DID 186hr inspection & was found Assurating Report C. WILT A10305663959 Al	
Date <u>DEC</u> .				
Date ARC.				
Date <u>Dec</u> .				
Date <u>Dec</u> .				
Date NEC.				
Date <u>Dec</u> .			SUB-TOTALS this page TOTALS-Carry forward to next page	

	Jane Land		

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	•			TOTALS brought forward from previous page
10/12/07			3484.4	OK CHL - FLAR () CUP - 51125211)
1/14/08			3505.4	OILCHO - FLAR CJERP 571252111
(121/08			3549.4	011 CH6 = FISTE CJens 57125211)
9/14/08			3577.5	OILCOX6 - FILTER C. Jung - 57125210)
12/24/08			3601.4	orlaws auto, venogrovery C. Sing 2721
512/9			3120.4	OIL CAG AT ALRUAL
9/7/9			3647.3	
11/23/9			3672.6	OIL CHL = FICAZ C. Jan 571252111
3/27/10			3201.8	11 C46+ FITTE Que 571 252111
6/26/10			3725.8	OIL CHG - ACTOL CJam 571252111
cololio			3760.1	OIL CUIG= FIRZ CSam 571252111
7/2/11			3798.5	OUCHES FIOTE, NEW MAINS STUDED, MERCES
8/3/11			\$68.2	OILCUIZ FILTOR WISCUIE agen 57125211)
215/12			3824.4	
5/12/12			38546	OPI change of filter lemost July 27765
				1 110 July 24 700
				SUB TOTAL C. II.
				SUB-TOTALS this page TOTALS-Carry forward to next page

