Fived (Prev. Page)  Reporté (Page Pr.  AF (Carry Fwd.)  Reporté  rection (By/Par: )page no / pa		10 10419 10430	7	10	7									
Fwd (Prev. Page) Reporté (Page Pr VF (Carry Fwd.) Reporté Tection (By/Par: )page no / pa		10419	7	10	7-					+			2010	
AF (Carry Fwd.) Reporté Trection (By/Par: )page no / pa			7		-		**************************************			1				
rection (By/Par: )page no / pa	ge n°		100	4)	1	1.10	28 Component Replaceme							
	aga ii		a	4		6259	Component & Part N	lumber / Composant et	nº de pièce	Pos.	S/N off / Nº	Nº de série enlevé	S/N on / N° de s	série installé
				4		6257								
						+2				-				
0. 19	Defect - Défectuosité	ités												
		750		2	20		Rectification			AME - TEA	-4	945		
					W1- (	ngine oil px, 1	unanc forage an	J - Lik o	21		<u> </u>	22 Lic.	23	Date
					torque !	transduced solution	al Connector Clea	and tank	HOM.			+		
										Mily		ALLIA		
					Me - to	H-00-001 OBS N	lufamance to	st Prifa	(MI)	N N		M16981	6 Mar	3,09
					THM -	4-00-001 OBS 1	nothing lames	limits	W. F	wheth	-	Antitio a	~	- 0
	2							· · ·	111	Amb		WAIPE	56 Mar	13,09
Next inspection due at: / Prochaine inspection planifiee à : TTAF 0451.8  Type of inspection: / Type d'inspection:	DI Mday inspectir	on carled out: / If	Q / insper	ction 7 jours effect	sctué "I have	e conducted an independant inspection of d by the work accomplished" / "J'ai effect andes de vol / réacteur qui étaient touché								

Signature & nº de licence

Defect / Défectuosité

		m																	
tals Totaux Page								+ 1	Compon	ant Benlaceme	nt / Remplaceme	nt day							
(Prev. Page) Reporté (Page Pr	éc.)											The Contract	TALLS.						
(Carry Fwd.) Reporté					-				Compa	onent & Part Nu	mber / Composa	nt et nº de pièc	0	Pos.	S/N off / N	de série enlevé	S/N	on / Nº de série in:	stallé
tion (By/Par: )page no / pa	ge n°				ŀ														
d Total Total révisé				1	-														
			_	-PROPELL	OWING BE CARE ER FEAT	S/N: 296 T.1 WORK HAS BI RIED OUT AS I THERING MICH SCREW ACTI	EEN PERFO PEP. AMM 1 PO SWITCH	RMED: 2-20-05	NDINGS: 6375 DNAL TEST CA -00	RRIED OUT	AMM, 76-1	-	f. /h	tuli		M1699		23 Date	09
Inspection due at: / Prochaine ction iee à: TTAFof inspection: / Type d'Inspection:	DI / 7day inspection		- 33	tion 7 jours effi ure & n° de lice	_ at	tected by the work	accomplished"	/ ". l'ai effectu	he <i>flight/powerplant</i> é une inspection ind s par le travail accor	Anondanto dos	ere	RMI / AHRS #1	RMI/ AHRS #2	Runway Hdg / Cap de Piste	Mag comp. Compas magnétique	White / Blanche	Distribut do not rema	ion  ove / ne pas enleve s / Dossiers tech. \	er
	25	Date:	/		-	Signature & Lice	non No	0:	& nº de licence		éfectuosité	27				Pink / Rose - Fit. Green / Verte - a	Operations	Opératione sér V	DW WC

		" [ s	<u>ā</u>
MAKE: Pilatus MOD	EL: PC-12/45 S/N: 296	REG: C-FMPN	-
DATE: 2009-06-29 W.O.	N/A T.T.S.N. 10,895	4 LANDINGS: 6,535	
REV. 9. Pratt and Whitney manual P.N.	. 3038336, table 601 periodic inspection.	50 hr inspection performed as per chapter 05-20-10, PC-12 maintenance manual,	
THE FOLLOWING ITEMS INSPEC	TED AS PER AMM 04-00-00.		
THE FOLLOWING REPLACED AS	warning system functional tested in accordan	ce with chapter 27-40-00, page block 501.	
Chapter 26			
<ul> <li>Fire extinguisher model BA51015GR- Chapter 73</li> </ul>	3 serial 15773 contents checked by weighing		
- Fuel pump outlet filter part # AN6235	-3A		
THE FOLLOWING ITEMS INSPEC	CTED AS PER AMM 05-10-20.		
Chapter 21  - Pressurization outflow and safety valve	res removed and cleaned as per AMM 21-30-(		
- riessurization adjustment test carried	out as per AMM 21-30-00	0.	
Chapter 22	nove for clutch check and installed AMM 22-	The one	
Chapter 24		10-00.	
- Starter/generator brushes examined fo - 2 <sup>nd</sup> generator brushes part # 524.32.12	r wear AMM 24-30-01.		
Chapter 27			
<ul> <li>Lubricate flap screw actuators AMM : Chapter 28</li> </ul>	27-50-00.		
- Tank cross vent pipe and outward che	ck valve test performed AMM 28-10-01		
Chapter 30			
<ul> <li>Apply a surface coating of Age Maste Chapter 32</li> </ul>	r # 1 to aerofoil de-icers in accordance with m	anufactures instructions.	
- Lubricate left and right wheel bearings	s with Mobil SHC-100 grease AMM 12-20-06		
<ul> <li>Inspect main landing gear axies and be</li> </ul>	ushings for cracks, corrosion and nitting using	a 10 power magnifying glass. Bushing measured for wear with a micrometer	
Chapter 34	gear axle due to wear part # 532.10.12.210.		
- Standby magnetic compass and attitud	le reading reference system (AHRS) swing ch	eck performed.	
Chapter 56 - Cockpit side windows Inspection/Che	ck (refer to DM 12-A-56-11-02-00 A 212A	c) Crack found in right side window part # 959.81.10.112 ( NP172113-02 ) serial #	
09103F16318 Installed	er (1010) 10 Divi 12-7-30-11-02-00-7-3134-7	) Crack found in right side window part # 959.81.10.112 (NP1/2115-02) Serial #	
Chapter 61 - Propeller lubricated ref. AMM 12-20-	05		
Chapter 71			
- Torque limiter test performance test ca	arried out as per AMM 71-00-00, table 501, ucers cleaned and inspected as per 71-10-02.		
Chapter 73			
- Fuel control inlet filter inspected for co	ontamination EMM 73-10-02.		
Chapter 74 - Spark igniter inspected for cleanliness	and erosion EMM 74-20-00.		
Chapter 76			
- Propeller feathering micro switches fu Chapter 79	nctional test carried out AMM 76-10-02.		
- Chip detector inspected as per P&WC			
The following extra work carried out - Replaced cargo door retract cable part			
- Repaired burnt wires from windshield	de ice timers installed under SB 30-006.		
<ul> <li>Pilot and co-pilot control column slip i</li> <li>Elevator bonding strips replaced part #</li> </ul>	ring part # 527.10.12.101 replaced due to wea	6	
- Elevator, aileron and rudder cables ten	sions adjusted. Elevator and rudder autopilot	cable tension adjusted. Stick pusher cable tension adjusted.	
- Nose landing gear "D" ring bushing re	placed (2) 532.20.12.203.		
<ul> <li>Air data computer KDC222 time expir</li> <li>Replaced right main landing gear shoc</li> </ul>	k absorber for worn spherical bearings part #	532.10.12.211 serial # 1L476 off VLG845 on.	
- Replace left main landing gear forward	phenolic bushing part # 941.22.57.509 repla	zed.	
- Fire extinguisher inspected and weight	ed 2.079 KG. s replaced due to wear part # 940.83.37.602		
- Right outboard flan actuator replaced f	or clattering noise part # 978.73.20.309 serial	# off 0294 on 0128.	
<ul> <li>Propeller replaced for grease leak mode</li> </ul>	el HC-E4A-3A serial # off HJ-1056 total time number 065-0089-16 replaced off serial # 19	3,307.1 hours on KX130.	
<ul> <li>Propeller low pitch warning micro rota</li> </ul>	ry switch replaced as per AMM 61-20-02 par	# 973.10.11.101 adjusted as per AMM 71-00-00.	
- The following parts replaced on cahin s	seats (1) shroud right side passenger seats par	# 959.30.01.237 and (4) magazine pockets assembly part # 959.30.01.239.	
- I CERTIFY THAT THE STATIC PI - I HAVE CONDUCTED AN INSPEC	TION FOR CONFORMANCE TO THE T	TED AND TESTED IN ACCORDANCE WITH C.A.R. 625, APPENDIX "C" TYPE OF FLIGHT / POWER PLANT CONTROLS THAT WERE AFFECTED BY	THI
WORK ACCOMPLISHED			
m 1	10 -011 10	•0	
	M281682	09-06-30	_
SIGNATURE:	LICENSE #	DATE:	
THE MAINTENANCE DESCRIBED	HAS BEEN PERFORMED IN ACCORDA	NCE WITH THE APPLICABLE STANDARDS OF AIRWORTHINESS	
0 2			
SA )	M143649	2009-06- JU	
ICNATURE:	LICENSE#	DATE:	
# # W			7
e pas sisiers attoni	Nº de sêne installé		49
s enle tech	Date	Type	9971
/ ne pas enlever Jossiers tech. Yow Jerations aér. Yow	<sup>9</sup>           nstall	e de of	7
		<u>8</u>     8	_

C-FMPN  Carried out AHRS calibration (compass swing) on both #1 & #2 and standby compass in accordance with Pilatus maintenance manu chapter 34-25-00 & 34-21-00  chapter 34-25-00 & 34-21-00  chapter 34-25-00 & 34-21-00  compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on both #1 & #2 and standby compass in accordance with Pilatus maintenance manual 71-00-00 test 14  Flore of the compass swing on the intention space of the flore of the pilatus maintenance manual 71-00-00 test 14  Flore of the standby compass in accordance with Pilatus part #94.78.81.410  Flore of the standby compass in accordance with Pilatus part #94.79.40.92.6127 serial #0.071.40.90.61.41  Flore of the standby compass in accordance with Pilatus part #94.79.40.92.6127 serial #0.071.40.90.60.61  Flore of the standby compass in accordance with #1.50.00.61.40.61  Flore of the standby compass in accordance with #1.50.00.61.40.61  Flore of the standby compass in		+ + -			-					1	1
chapter 34-23-00 d. 32-1-00  - Lower rudder static wick replaced part # 984.78.81.410  - Ground idle adjusted as per Pilatus maintenance manual 71-00-00 test 14.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  # 1 generator main relay replaced for serior interminent long between closed and part of out of part of part of part off											
chapter 34-23-00 & 24-21-00  - Lower rudder static wick replaced part # 984.78.81.410.  - Ground idle adjusted as per Pilatus maintenance manual 71-00-00 test 14.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced in termittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # 04.00.03 replaced.  - # 1 generator main relay replaced due to intermittent failure part # 974.00.0							0				
Character   24-25-00 & 24-25-00    - Lower rudder static wick replaced part # 984.78.81.410.  - Ground idle adjusted as per Pilatus maintenance manual 71-00-00 test 14.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # 0.00.200.12.000 on the right main failure part # 0.00.000.12.000 on the right main fail			-	_							
chapter 34-23-00 & 34-21-00  - Lower rudder static wick replaced part # 984.78.81 410.  - Ground idle adjusted as per Pilatus maintenance manual 71-00-00 test 14.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # off P147 on P585.  - # 1 generator main relay replaced due to intermittent failure part # 974.09.26.127 serial # 04.00.03 replaced.  - # 1 generator main relay replaced due to intermittent failure part # 974.09				V							
O.2 AHRS    Company   Comp	TEER FOR STEER 120 249 243 150 270 272 180 300 302	Left & right out as per PC the right han marks 11 & Flap aileron Functional to Operational Operational	chapter : - Lower - Ground - # 1 ger ilatus 009-07-10  ht wing removed C-12 S.R.M. 57- nd & left hand up 12 to a depth of interconnect bootest of landing get test of exterior left test of pitot tube	ad-25-00 & 34- rudder static wid idle adjusted a nerator main rel  MODEL:  W.O.  for wing to fus 00-03-02. New oper forward wi 0.015 MM. wden cable part car extension an lighting carried e heat and A.O.	ck replaced part as per Pilatus mai ay replaced due to   PC-12/45 N/A clage attachment parts include the ng attachment lor # 941.94.10.003 d retraction systematics.	984.78.81.410. Intenance manual or intermittent fail S/N: T.T.S.N. Inspection as per bushing kit P/n. Ig bolts P/n. 553. Ireplaced.	71-00-00 test 14 lure part # 974.09 1 296 10,896.4 AMM 05-10-20	REG: LANDIN	I # off P147 on C-FMPN NGS: 6,540 cted as per AMI	P585.   M 57-00-00-06	and lug repair car
SIGNATURE:  I HAVE CONDUCTED AN INSPECTION FOR CONFORMANCE TO THE TYPE OF FLIGHT / POWER PLANT CONTROLS THAT WERE AFFECTED BY THE WORK ACCOMPLISHED  STEER FOR STEER 118 240 247 1150 270 277 184 300 305 212 330 334  THE MAINTENANCE DESCRIBED HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE STANDARDS OF AIRWORTH Affected by the work accordance of the type of FLIGHT / POWER PLANT CONTROLS THAT WERE AFFECTED BY THE WORK ACCOMPLISHED  AFFECTED BY THE WORK ACCOMPLISHED	D.2 AHRS TEER FOR STEER	· I CERTIF						TESTED IN			
SIGNATURE:  I HAVE CONDUCTED AN INSPECTION FOR CONFORMANCE TO THE TYPE OF FLIGHT / POWER PLANT CONTROLS THAT WERE AFFECTED BY THE WORK ACCOMPLISHED  STEER FOR STEER 118 240 247  1150 270 277  184 300 305  212 330 334  THE MAINTENANCE DESCRIBED HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE STANDARDS OF AIRWORTH Affected by the work accordance of the type of FLIGHT / POWER PLANT CONTROLS THAT WERE AFFECTED BY THE WORK ACCOMPLISHED  MAGGORDA	150 270 269	. 5	11	سر سد الم		MIY	3649			2009	-07-
DBY COMPAS  STEER FOR STEER  118 240 247  1180 270 277  184 300 305  212 330 334  THE MAINTENANCE DESCRIBED HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE STANDARDS OF AIRWORTH  affected by the work acco commandes de vol/réaci  Affected by the work acco commandes de vol/réaci  DATE:		SIGNATU I HAVE O	DE: CONDUCTED ED BY THE W	AN INSPECTI	ON FOR CONF	ENSE # ORMANCE TO	THE TYPE OF	FLIGHT / P	OWER PLAN	DATE: T CONTROL	S THAT WERE
affected by the work acco commandes de vol / réaci  DATE:	STEER         FOR         STEER           118         240         247           1150         270         277           184         300         305	MSI SIGNAT	t Z	•	M9/	00604 ( CENSE#	(MZ)	VITH THE A			
NOTE TO A STATE OF THE STATE OF		cco éaci	10	<i></i>	n	1 14364	<del>(</del> 9		2	<u>6 69-0</u> date:	7-(0


otals Totaux I	Page			$\dashv \vdash$			28	Componen	t Replaceme	ent / Remplacemen	t des composants	,					
d (Prev. Page) (Carry Fwd.)	Reporté (Page Préc.)	10896	8			542			ent & Part N	umber / Composan	at et n° de pièce		Pos.	S/N off / N° d	e série enlevé	S/N on	/ N° de série installé
ction (By/Par:	)page no / page nº			-													
sed Total Total ré-	visé																
19	Defect - Déle			20			10780	tification			21	A .	AME - TE	A	22 Lic.		Date 23
Genora	her #1 will r	not come	onlin	Ge	porator	H 1	toggle	switch	h re	placed 1	with						
				Sev	rucable	Stom .	C-GFL	97361.4 A, grou	nd tes	tool serv	iceddi	Dard	Bon		m3953	13	09-07-14
OPE	RATIONAL TES	T ANO	A03087	MENT	OF TH	e Po	WER	CONTRO	L 14	VER SY	STEM				-		
	BATA CONTRO								AND	FAIGHT		Hos	long	Rober	m2386	23	14502409
Next inspection d inspection planifiee à : TTAF	Sing	inspection carried out:		jours effectué	"I have conducted a affected by the work commanded de vol	independant accomplished réalteur qui	t inspection of the distribution of the distri	he #ight/powerplan é une inspection in a par le travail acco	controls the dépendante mpli."	at were des	RMI / AHRS #1	RMI / AHRS #2	Runway Hdg / Cap de Piste	Mag comp. Compas magnétique	Yellow / Jaune -	Tech Records	on ove / ne pas enlever s / Dossiers tech. Yow Opérations aér. Yow


YEB	fit no N° du vol	Time (GMT) Up/Déc.	/ Heure (TU) Down/Atter	Air time / tem		Flight tin Temps de hours / heures	tov	Naut. miles Milles naut.	ldgs or / after, ou cy / rin	Perso	ons on board onnes à bord onbre lb	Fuel Carburant (lb)	Oil Huile (lb)	Baggage, cargo, equip. / Bagages, fret et équip.	Total takeoff wt. Masse totale au décollage	Fuel boarded / sur Carburant embard fournisseur	oplier Invoice   N° de la fa	No. octure or / ou Gal	CAN US	17 /
EK	1	13.4	16.5	3	1	3	2	<b>3</b> 94	1	å	150	2700	UHECK.	300	9800					1
EK	2		20.3	3	3	3		724	1	3	300	2700	~	50	9700				_	
1												51,73								
												1							+	
																			+	
																			+	
											Ц,			7957 37 72			1			
Totaux Pa	Ser section	in exercis		6	4	6	, 6		2	(1)/25	28		1.0%	ent / Remplacement			S/N off / N° de	cária anlavá	S/N on / Nº d	e série installé
-	Reporté (	Page Préc.)		10959	٦	1				57	_	Compor	nent & Part N	Number / Composant	t et n° de pièce	Pos.	S/N off / N° de	Selie erileve	37137713	9,940,00
.)	Reporté			10966	1	-			65	76	,					_				
ar:		no / page nº				-										_				
tal révisé											∤-									
+		Defect	- Défectuosité	19							Rectif	lication				AME - TE	A	Lic.	lians .	Date
+-		Delect	Donociassin				20	11.	и	470 TO 12 V			0.1.3		21	1		22	23	
+-							0	165 Mon	The state of the s				MYCCA	Mm 570.	2060	1. L. D.		MULLAR	h 1.	1,1179
+-						6)	Yeu	HCh 31			Sun		V.J.	Sherokak		hit all	ł.	Lucas		1.00
+						8	SKY	TARCHUA	inna i	neh	10 V	ned, the	kid	Servicable		T. P. C.	<b>}</b>	MILLOO	b Vi	14 360
+-				-		ă	CV.	trac Cu	L C	Sh 1	WC DIE	+ Outon	med,		sourced .	Lin Call		DALLIDE	210 1	111000
+-						- 4	pe	TANK CIT	urt (	)4 CAY	co per	here	10000	Chec you	sovery.	my conf		141716	26 0	my 31,0
+-				8												•				
duo at:	Prochaine	· In	day i pecton	carred out: / IQ	/ inspec	tion 7 jours effe	ctué	"I have conducte	d an indeper	ndant ins	pection of the	flight/powerplant	controls that	were	RMI/ RM		Mag comp.		Distribution	
	135,	y VX	11/18	calh	144	4986	_ [	affected by the v commandes de	vork accompl vol / réacteur	rqui étaie	nt touchées pa	ne inspection indé ar le travail accom	ppili."	74	AHRS AHR		Compas magnétique	White / Blanche -	do not remove / se	pas enlever
ohr	e a inspec	Sign	afure & Licence	Date:		/31,09		Ciar -t *	Liennes No		Signature & n	° de licence	Defect	Défectuosité	27			Pink / Rose - Fit. (	ech Records / Dos Operations / Opéra frame log / livret ce	siers tech. Yow
VIII	<u> </u>	25		Date	14		20	Signature &	Licence No.		orginature & n	ue mente	D01001	- University	21				THE TOWN INTERCENT	mule .

Totaux Page	(0	3	60	.3	Component Replacement / Remplacement 28	des composants			Southern Commission Co	S/N on / N° de série install
ige) Reporté (Page Préc.)	10979	3		6583	Component & Part Number / Composant	et nº de pièce	Pos.	S/N off /	/ N° de série enlevé	S/N dil / N de solle illomi
d.) Reporté	10985	6		6586						
Par: )page no / page nº	1.02									
otal révisé										
			MI I	+ of forque (	alibration check pretorn	red A		1		
			TAW AM	M 72-00-00, N	alibration check preform to Defects Cound.	Kay	Netcol		M41698	6 Aug 4

REG: C-FMPN THE FOLLOWING -150 HR INSPECTI	S N: 296 T.T.S N: 11000.00 LAX G WORK HAS BEEN PERFORMED: JON AS PER CHECK SHEETS ON FILE	DINGS: 6596			ı			
-PRATT & WHITN -STARTER/GENEF -LUBRICATE FLA -P3 AIR FILTER CI -PROPELLER FEA -SPARK IGNITERS -PRATT & WHITN -MIL 018 R1, ENGI -CHIP DETECTOR -FUEL PUMP OUT	IEY MANUAL P.N. 3038336, TABLE 601 PER RATOR BRUSHES EXAMINED FOR WEAR A IP SCREW ACTUATORS, AMM 27-50-00 LEANED ITHERING MICRO SWITCH FUNCTIONAL T S INSPECTED FOR CLEANLINESS AND ERC	MM 24-30-01, CHECKED SERVICEABLE  EST CARRIED OUT AMM, 76-10-02  SION, EMM 74-20-00  J 3038336 CH 72-00-00, TABLE 602 3B POST S/B 14172 TURBI AS3209-018	NE BLADE INSPECTED AS PER PARA	GRAPH 9.H.(2)		Pos.	S/N off / N	l° de série enlevé
-HEAT EXCHANG -SECONDARY HE. -WATER SEPERAT -SURVIVAL KIT R -COMPRESSOR IN	ER INSPECTION PREFORMED IAW AMM 03 AT THERMAL SWITCHES TEST PREFORME FOR INSP PREFORMED IAW AMM 21-40-02 EPLACED PN FE4A SN OFF A618-0306 SN O3 ILET SCREEN INSPECTED AS PER P&W CAI	D IAW AMM 21-40-09 N A618-0104 NADA EMM 72-00-00	×		_	AME - T	EA	22 L
SIGNATURE: AIRC	CRAFT RELEASE V. WHE CAN'T	LICENCE # M416986  MANCE TO THE TYPE OF POWERPLANT CONTROLS TH  LICENCES # 2845 7	DATE: 2009-08-14		ED			
on due at: / Prochaine	DI / 7day inspection carried out: / IQ / inspection		# AST					
TAF		anected by the work accomplished" / "J'ai effectué commandes de vol / réacteur qui étaient touchées n° de licence	una inspection indépendents des	RMI / AHRS #1	RMI / AHRS #2	Runway Hdg / Cap de Piste	Mag comp. Compas magnétique	White / Blanche Yellow / Jaune - Pink / Rose - Fl

Totaux Page	4	9	51	2	Component Replacement / Remplacement des com	posants				1
Page) Reporté (Page Préc.)	11072	6		6637	Component & Part Number / Composant et nº de ;	pièce I	Pos.	S/N off / Nº de série e	nlevé S	i/N on / N° de série installé
wd.) Reporté	11077			6639						
/Par: )page no / page nº										
Total révisé										
Defect - Défects	uosités		20	F	tectification	21	AME - TEA	22	Lic.	Date 23
			MI ELI	monthly inspect	on preformed ANW Artex	0 , 1	\			
			mm 57	0-50+0 Rev D.	No. 2	R. Metca	le_	M	416986	Huy 31,09
						ă l	0			3






Totaux Page  r. Page) Reporté (Page Préc.)	11210	7	0	9	678	7 28	Component Replacement / Ren Component & Part Number /	State of the sale of the sale	ACCESSOR	Pos.	S/N off /	N° de série enlevé	S/N on / N°	de série installé
wd.) Reporté	11211	200			67		-							
/Par: )page no / page nº														
Total révisé														
										ieta-				
Defect - Défec	uosités		20			Rectific	ation		21	AME -	TEA	22 Lic.	23	Date
			m	elt im	antilly in	so out	world Ithe Art	U		1				
			M	nu tena	a wam	ned 5	70-5060 Rev	7 ~	Ku	letialle		44169	Blo Se	pt 20,0
										V				ι .
												111		
			1000004400400	"I have conducte	d an independant in	spection of the fligi	ht/powerplant controls that were	RMI/	RMI/	Runway	Mag comp.		Distribution	
on due at: / Prochaine TTAF	ection carried out: / IQ /	/ inspection 7 jo	urs effectue	affected by the w	vork accomplished" / vol / réacteur qui éta	"J'ai effectué une	nspection indépendante des	AHRS #1	AHRS #2	Hdg / Cap de Piste	Compas magnétique	White / Blanche - do Yellow / Jaune - Tec	not remove / ne p	as enlever

	-										-						
age Totals Totaux Page	5	2	5	4		a	Component 28	Replacement	/ Remplaceme	nt des composa	ints						
. Fwd (Prev. Page) Reporté (Page Préc.)	11265	1			67	161	Compone	nt & Part Num	ber / Composa	nt et n° de pièc	,	Pos.	S/N off / N°	° de série enle	evé	S/N on / Nº de	série instali
TAF (Carry Fwd.) Reporté	11 270	3			67	61											
Correction (By/Par: )page no / page no						(C.S.)											
levised Total Total révisé																	
AMOR WACHINGS IN HEADSETS							" ADJWILDENT TBIED ON GROW,				KXI	(W)	\	M42	23683	200	7-10-
															,		
4.																	
3. 4. 5. 6.															17-		
5.															17		
4. 5. 6.	ion carried out: / K	2 / inspec	tion 7 jours effects	affected by	the work accom-	plished" / "J'a	ition of the <i>flight/powerplant</i> c effectué une inspection indép touchées par le travail accomp	endante des	re	RMI / AHRS #1	RMI / AHRS #2	Runway Hdg / Cap de Piste	Mag comp. Compas magnétique	White / E	Blanche - do r	Distribution not remove / ne, Records / Doss	pas enlever

Green / verte - airframe log / livret cellule	Green / Verte - a			1						and the second second			
Yellow / James - do not remove / ne pas enlever Yellow / James - Tech Records / Dos pas enlever Pink / Rose - Fit. Operations / Operations ach You Company of the Company o	Yellow / Jaune - Pink / Rose - Fit				97	Defect / Défectuosité		Signature & nº de licence	Signature & Licence No.	26			
Distribution	White / Blanche	Mag comp. Compas magnétique	Runway Hdg / Cap de Piste	RMI / AHRS	RMI / AHRS	were	werplant controls that viction indépendante des rail accompil."	ction of the <i>flight/por</i> al effectué une inspe touchées par le trav	<ul> <li>Tave conducted an independent inspection of the flightpowerplant controls that were affected by the work accomplished "."L'al effectué une inspection indépendante des commandes de vol / réacteur qui étalent touchées par le travail accompil."</li> </ul>		icence No. Signatur		planifiee à : TTAF Type of inspection: / Type d'inspection:
										-	DI / 7day inspection carried out; / IO / inspection 7 loves at a contract of the contract of t	DI / 7day inspe	Next Inspection due at: / Prochaine
4120 986 914M	91EM		Amila	1									
	<b>&gt;</b>				N. C.	017	Servical	heikid	HMM 34-30-04, C	FWM			
11 40 080	986 9HW		etally	KE	Time!	CKIC	M) Davis	THE BLOCK	- \$2 Generator Dr	***			
500			-	-			X Keplan	- 5	PN 959 30 01 131				
Lic. Date	22	EA	AME - TEA	21				reculication	What out I is		HICK WOOD FIND & DEF	が大分	Copilet Seat
											sités	Defect - Défectuosités	19
								L					
		in =						1					ised Total Total révisé
								1				ege n"	ection (By/Par: )page no / page nº
S/N on / N° de série Installé	S/N off / N° de série enlevé	S/N off	Pos.	рівсе	Composant et n° de pièce	umber / Compos	Component o Part Number	+	6164				(Carry Fwd.) Reporté
							Composite	30	27.		8 (851)	réc.)	wd (Prev. Page) Reporté (Page Préc.)
		-		posants	nent des comp	ent / Remplacem	Component Replacement / Remplacement des composants						lotaux Page
												-	Totale Totale
						•							

FB	fit no N° du	Time (GMT	) / Heure (TU)	Air time (to-						70	2 - 2		_ Cap	ı. Sig. & Lic.	/Sig. et lic. du	cdt: Fen	Kar	6	Date	-911-1
То / Å:	vol 2	Up/Déc. 3	Down/Atter.	Air time / ten hours / heures		Flight tim Temps de hours / heures	lov	Naut. miles Milles naut.	ldgs or / atter, ou cy / rin	Pers	ons on board onnes à bord Inbre lib	Fuel Carburant (lb)	Oil Huile (lb)	Baggage, cargo, equip. / Bagages, fret et équip.	Total takeoff wt. Masse totale au	Fuel boarded / supplier Carburant embarqué /	Invoice No. N° de la facture	Litres	cost / prix	Type of fit.
RT	1	13,0	165	3	5	3	6	637	7	7	1100	9	10	11	décollage 12	fournisseur 13	14	or/ou Gal	CAN US	Type de vol
EK	2	17,0	17.5	,	5		6	117	1	3					9900					1
-FB	3	17.8	2014	2	6	2		744	<del>-</del>	4	340	2700	~	50	9740					1
			-				T	TAT		4	520	2400		50	9620					i
					-															
otals Totaus s									-											
offals Totaux F	aren ve v	State Sanda Land		4	6	6	9			3	28	Componen	Replaceme	ent / Remplacement of	des composants					
(Carry Fwd.)	1.00.000.000	(Page Préc.)		11383	8		101. 104.		62	69	20	757		umber / Composant e		Pos. S.n	N off / N° de série ente		www.conduction.co	Charles and A
tion (By/Par:	Reporté )pag	ge no / page n	10	11289	4				67						Children and Andrews		TOTAL GO SOLIE GILL		S/N on / N° de :	série installé
d Total Total révi	sé																			
9		Defe	ect - Défectuosit	és																
			Comment of the Comment				20	21.1.	c		Rectific		0		21	AME - TEA	22	Lic.	23	Date
							211-	10 DI	SULUDU	11.781	balling	Altimet	W K	lal Duc	W PANA					
							21	1011 3	17 47	430	CINI	( d.l.	Nexy	ecked Non	may 0 1	T. A		11 0 =1	-	
							M1	infilat	101-1	ma 1	Atimotes	Linker	A Charle	Amm 34-1	mai Kily	et old	MA	486	Oct	21,09
							SN	1 pll 31	0392	SU	00 296	39 NEX	c ial	du ato	4200			-	_	
	_						20	11, 840	r Stat	ick	eck le	mplifed	The	iked Sev	V. R.M	iscala	M4	16986	od	21,09
t inspection due at ection iffiee à : TTAF 11 e of inspection: / T	ype d'insp	(1)	7day inspectio	cally ice No.	Mi	iction 7 jours effective & No 986 ture & n° de licen		commandes de	work accomp	gui étale	Jai effectue une	ght/powerplant co inspection indépi le travait accompi de licence	endante des	-	RMI/ AHRS AHRS #1 #2		as ique White / Bl Yellow / Ji Pink / Ros	anche - do not aune - Tech Re se - Fit. Operat	tribution remove / ne pas acords / Dossiers ions / Opérations log / livret cellule	tech. Yow aér. Yow



Is Totaux Page		5	2	5	н		2 28 0	omponent Replacen	ent / Remplacemen	nt des compos	sants					
Prev. Page) Reporté (Pa	e Préc.)	11329	9	- V	1	679		Component & Part I	lumber / Composar	nt et n° de piè	се	Pos.	S/N off / N°	de série enlevé	S/N o	n / Nº de série installé
rry Fwd.) Reporté		11 335	i			4 - 5,000	91			100						- most carrier and a straight.
(By/Par: )page no	/ page nº					101	·									
otal Total révisé																
	Defect - Défectuosité	s		20			Rectification				21	AME - T	EA	Lic.		Date 23
				MI	elt r	monthly INSP	Dreformed	L TAW A	vtex mn	$^{\prime}$	^					
					2+0-5	5060 KW D. Ch?	3.4 checke	d Noin	val —		Rille	telle	,	M4169	86	Oct 31,09
				M2 6	It A	Innual INSP D	ve form on	TAW DUL	MM X			, V		1		
				C	- 000	-5060 Res D Ch	4.1 No de	fects for	ound-	_	KMet	calle		M4169	86	Det 31.09
			_	M3.	FL	washed -				_	K.Me	tialle	)	M4160		Oct 31,09
			_									U				0 01
		arried out: /10 /	inenactio	a 7 lours offent												
ection due at: / Prochaine	DI / 7day inspection of	arriso 551.77Q7	кізреско	ii / Jours eneciti	affect	ve conducted an independant insy ted by the work accomplished" / " mandes de vol / réacteur qui étaie	l'ai effectué une increet	na indianadanta das	ere	RMI / AHRS #1	RMI / AHRS #2	Runway Hdg / Cap	Mag comp. Compas	2720 02	Distributio	
:TTAF 11387.9	DI / 7day inspection of										#Z	de Piste	magnétique	White / Blanche - o	to not remov	ve / ne pas enlever
pection due at:/Prochaine n a:TTAF 11387.49 repection:/Type d'inspection:	DI / 7day inspection of Signature & Licence	No. S	Signature	& nº de licence					Γ					Yellow / Jaune - Te	ch Recards	/ Dossiers tech. Yow Operations aer. Yow

	orté (Page Préc.)	6 9 7	3	4	Component Replacement / Re	emplacement des c	COmr
TAF (Carry Fwd.) Rep Correction (By/Par: Revised Total Total révisé	REG: C-FMPN S/N: 296  THE FOLLOWING WORK HAS BEEN PE	4 8 0 T.T.S.N: 11348.0 LA	NDINGS: 6799	6795	Component & Part Number		
No. 19	-150 HR INSPECTION AS PER CHECK SI -PRATT & WHITNEY MANUAL P.N. 303 -STARTER/GENERATOR BRUSHES EXALUBRICATE FLAP SCREW ACTUATOR -P3 AIR FILTER CLEANED -PROPELLER FEATHERING MICRO SWI -SPARK IGNITERS INSPECTED FOR CLI -PRATT & WHITNEY CANADA MAINTE -MIL 018 R1, ENGINE OIL DIPSTICK 'O' -CHIP DETECTOR INSPECTED AS PER FILTER REPLACE -FIRST AID KIT YEARLY INSPECTION P -TCAS SYSTEM INSP OF OAT SENSOR F -TCAS INSP OF ANTENNAS AND PROBE -TORQUE LIMITER CHECK PREFORMEI -BLEED VALVE OPERATIONAL CHECK -R/H MAIN WHEEL ASSY REPLACED IA - L/H TIRE REPLACED IAW CMM 32-45-	8336, TABLE 601 PERIODIC INS AMINED FOR WEAR AMM 24-3 AS, AMM 27-50-00 ITCH FUNCTIONAL TEST CARI EANLINESS AND EROSION, EM ENANCE MANUAL P/N 3038336 RING REPLACED P/N AS3209-0 P&W CANADA EMM 72-00-00 ED, P/NAN6235-3A PREFORMED, CHECKED SERVI PREFORMED IAW STC SA04-121 ES PREFORMED, CHECKED SE DI LAW EMM -72-00-00 LE PREFORMED IAW EMM 72-00-00 W AMM 32-40-01 SN ON 1060 S	O-01, CHECKED SERVICEAL RIED OUT AMM, 76-10-02 IM 74-20-00 CH 72-00-00, TABLE 601 3B 18 CEABLE L, CHECK SERVICABLE RVICABLE	12	ADE INSPECTED AS PER PARAGRAPH 9.H.	(2)	
	THE MAINTENANCE DESCRIBED HAS SIGNATURE: AIRCRAFT RELEASE		DRDANCE WITH THE APPI LICENCE #		DATE: 2009-11-05		
Next inspection due at: / Procinspection planifiee à : TTAF  Type of inspection: / Type d'in	7.9	/ IQ / inspection 7 jours effectué Signature & n° de licence	affected by the work ac	complished" / "J'ai effectué un acteur qui étaient touchées pa		RMI / AHRS #1	

1	101		100		1		1 1										
,		1															
					_												
																_	
																1	
					_												
												_		_		_	
otaux Page						-											
AND THE PARTY OF THE PARTY OF	Samuel Comment	100000000000000000000000000000000000000	$\vdash$					28	Component	Replacement / Re	mplacement des co	emposants					
age) Reporte	rté (Page Préc.)	11348				67	90	٦	Compone	nt & Part Number	Composant et n° c	In alkan			146 - 76 - 70°   1 - 1 - 1 - 1 - 1		
d.) Report	orté					61	17		oompone	m w Fait WurilDer	Composant et nº	ie biece	Pos.	S/N off / N°	de série enlevé	S/N or	/ N° de série installé
est in		+															
ar: )pa	page no / page nº																
otal révisé								╢									
	Defect - Défectuos	ités						Rectifica	otion								
				20	- X			131400 35123	200402.0			21	AME - TE	A	22 Lic		Date Date
				MI :	engine t	oraun.	Shik our	4L01	dol 0	v	Lander	ule .					-
						Wi Mary	said pu	SPECK	7 011			/ V ~ ^					Li.
							170			1255WC	J. Went	· // .	1 11			0	
				C	annon	plugs Ch	ared, A	MM	71-00-	03 check	ed Servi	K.N	rhala		M4160	186	Nov 5, 09
				(	annon	plugs ch	eared, A	hum	71-00-1	ressure 03 check	ud Surv.	K.N	escolo		M4160	186	Nov 5, 09
				(	annon	plugs ch	eared, A	hum	71-00-1	03 check	ud Surv.	K.W	exially		M4160	186	Nov 5, 09
				(	ànno n	plugs ch	eaned, A	pww.	71-00-1	03 check	ud Surv.	K.M	escolo		M4160	186	Nov 5, 09
					annon	plugs Cl.	eaned, A	hvw	71-00-1	03 check	ud Suv.	K.N	ekialo		M4160	186	Nov 5, 09
					ànno n	plugs Cl.	eared, A	prviv.	71-00-1	03 check	ud Surv.	K.M	escoly		M4160	186	Nov 5, 00
				(	ianno n	plugs Cl.	eared, A	protor.	71-00-1	03 check	ud Surv.	KA	escolo		M4160	186	Nov 5, 00
				(	annor	plugs Ci.	eaned, A		71-00-	03 Check	ud Suv.	K.w	etralp		M4160	186	Nov 5, 00
due at: / Pręchai	gine DI / 7day inspectio	on carried out: / IQ /	/inspection		é "I have conc	ducted an indepen	ndant inspection o	of the flio	obt/oowernisot co	untraise that ware				To T	M4160		
due at: / Prochai	aine DI / 7day inspectio	n carried out: / IQ /	/inspection		é "I have conc	ducted an indeper	ndant inspection c iished" / "J'ai effec	of the flig	pht/powerplant co	introls that were	RI A+	/II/ RM	I/ Runway Hdg/Cap			Distribut	on
	aine DI / 7day inspection Signature & Licer			7 jours effectu	é "I have conc affected by commandes	ducted an indepen	ndant inspection c iished" / "J'ai effec	of the flig	pht/powerplant co	introls that were	RI A+	All/ RM	I/ Runway Hdg/Cap	Mag comp. Compas magnétique	White / Blanche	Distribut	on ove / ne pas enlever
n due at: / Prochai AF 11 14 18 ( tion: / Type d'inspe	aine DI / 7day inspection: Signature & Licer				é "I have conc affected by commandes	ducted an indeper	ndant inspection c ished" / "J'ai effec rqui étaient touch	of the <i>flig</i> octué une hées par l	pht/powerplant co	introls that were	RI A+	/II/ RM	I/ Runway Hdg/Cap	Compas	White / Blanche Yellow / Jaune	Distribut - do not remi Tech Record t. Operations	on ove / ne pas enlever s / Dossiers tech. Yow / Opérations aér. Yow

6	4	66	2	Component Replacement / Remplacement							
	_			New 200 (20 (20) (20) (20)	ant et nº de pièc	.e	Pos.	S/N off / N°	de série enlevé	S/N on	/ N° de série installé
	0.00						$\overline{}$				
e n°			- 6 6 3 7				$\vdash$				
efect - Défectuosités		20	Recti	ification			AME T	53			
la						21		<u>^</u>	22 Lic.	- 4	23 Date
17 11/6		- P. L	right replaced			13	1:00 F	9-	Ma3	1305	09.11.20
I WO		101/2	- an order								1
				(4)							
JI / 7day inspection carried out: / /	O / Inspectio	2 form offered Manager	W 100								
Signature & Licence No.		affected comman			RMI/ AHRS #1	RMI / AHRS #2	Runway Hdg / Cap de Piste		White / Bloomby	Distribution	
Date	1 1	26 Sign	gnature & Licence No. Signature &	n° de licence Defect / Défectuosité					Yellow / Jaune -	Tech Records	/ Dossiers tech. Yow
e i l	II 397 II 40 3 In o II 40 3 In	II 397 5 II 40 3 9 Ino	II 397 5 II 40 3 9  Incomplete Signature & Licence No.  Signature & Licence No.  Signature & Date:  II 7 day inspection carried out: / IQ / Inspection 7 jours effectué affected command	11 397 5   6 8 3 2     11403 9   6 8 3 4	Component Replacement / Remplacement	Component Replacement / Remplacement des composant  Component & Part Number / Composant et n° de pièce  11403 9  G834  Component & Part Number / Composant et n° de pièce  Composant et n° de pièce  Composant et n° de pièce et	Component Replacement / Remplacement des composants  Component & Part Number / Composant et n° de pièce  11403 9 666 832  Component & Part Number / Composant et n° de pièce  Component & Part Number / Composant et n° de pièce  Component & Part Number / Composant et n° de pièce  Component & Part Number / Composant et n° de pièce  Rectification  21  Taxi Light le placea  Toxi Light le placea  Tox	Component Repriacement / Remplacement des composants  Component & Part Number / Composant et n° de pièce  Pos.  II 397 5  II 397 5  GR 3 2  Component & Part Number / Composant et n° de pièce  Pos.  II 40 3 9  GR 3 4  Rectification  AME - TE  Taki Light Fe placed  Total Light	Component Replacement / Remplacement des composants  11 397 5  11403 9  1661 Défectuosités  20  Rectification  21  AME - TEA  Taxi Light le places  Taxi Light le places  Forth and out: / IQ / Inspection 7 jours effectue  41 Taxy inspection carried out: / IQ / Inspection 7 jours effectue  42 They conducted an independent inspection of the flight/powerplant controls that were effected out of the flight-powerplant controls that were commanded de vol / réactiour qui disient touchées par le travail accompil.*  Signature & n' de licence  10 Taxy inspection carried out: / IQ / Inspection 7 jours effectue  43 They conducted an independent inspection of the flight/powerplant controls that were effective and work accompished? ' / 2 le effectue un inspection independente des commanded de vol / réactiour qui disient touchées par le travail accompil.*  5 Date /	Component Replacement / Remplacement des composants  Component & Part Number / Composant et n° de pièce  Pos. S/N off / N° de série enlevé  1140 3 9 6 6 8 3 4 Component & Part Number / Composant et n° de pièce  Pos. S/N off / N° de série enlevé  1140 3 9 6 6 8 3 4 Component & Part Number / Composant et n° de pièce  Pos. S/N off / N° de série enlevé  1140 3 9 6 6 8 3 4 Component & Part Number / Composant et n° de pièce  Pos. S/N off / N° de série enlevé  1140 3 9 6 6 8 3 4 Component & Part Number / Composant et n° de pièce  Pos. S/N off / N° de série enlevé  1140 3 9 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	G 4 G G 2 2 Component Replacement / Remplacement des composants    11 397 5   G 8 3 2   Component & Part Number / Composant et n° de pièce   Pos.   S/N off / N° de série enlevé   S/N on

Totaux Page  A. Page) Reporté (Page Préc.)  Fwd.) Reporté  By/Par: )page no / page n°	-	8 9 7	6 1		3 6834 6837	28 Component Replacement / Remplacem Component & Part Number / Compos	AND THE		Pos.	S/N off / N	° de sêrie enlevé	SAN	on / N° de série installé
yyrar. /page no / page n													
FT boscon U/S	0	ماردوه	1 pc7	p cy	eck O.K.	Rectification		21	AME - T		22 Lic.		23 Date 2009 /1 :
ion due at: / Prochaine TTAF 11 4 9 8 ection: / Type d'inspection: Signature & Lica	tion carried out: / IQ /	inspection 7	jours effectué	affected by the w	ed an independant inspection of t work accomplished" / "J'ai effectu vol / réacteur qui étalent touchée	the <i>flight/powerplant</i> controls that were use une inspection indépendante des ser le travail accompti."	RMI / AHRS #1	RMI / AHRS #2	Runway Hdg / Cap de Piste	Mag comp. Compas magnétique	White / Binache	Distributi	
ection: / Type d'inspection: Signature & Lice	ence No.		n° de licence	26 Signature &	**************************************	& n° de licence Defect / Défectuosité	27		de Piste	magnetique	Yellow / Jaune - T	Tech Records Operations /	ove / ne pas enlever s / Dossiers tech. Yow / Opérations aér. Yow livret cellule

leg.:_C	Fn							72				ice de l'a	air Cap	Aircrai	/Sig. et lic. du	_ogb	dan	1	NZ3	8456	Z Date	e: 09/11/6
de l'aéro	fit no N° du vol		/ Heure (TU)	Air time / tem	ps-air	Flight time Temps de v hours / heures	ol	Naut. miles Milles naut.	ldgs or / atter. ou cy / rin	Perso Perso	ns on board nnes à bord nbre lb	Fuel Carburant (lb)	Oil Huile (lb)	Baggage, cargo, equip. / Bagages, fret et équip.	Total takeoff wt. Masse totale au décollage	Fuel t	boarded / su urant embar fournisseur	pplier qué /	Invoice No. N° de la facture	Litres	cost / pr CAN L	ix Type of
GW	1	14.6	17,2	2	6	2	7	503	1	7	1170	1950	10 14 FIK	150	9920	10						
sk	2	17.9		,	5	,	6	91	1	7		1950		150	9920							1
ow		18.6		á	8	2	9	687	1	5	820	1700	-	100	9270							
											000	770		, , ,								
Totaux Pa	ige			5	9	6	2	8		3	28	Componer	nt Replacem	nent / Remplacement	des composants							
Page)	Reporté	(Page Préc.)		11438 11444		-			6	85	3	Compon	ent & Part N	Number / Composant	et nº de pièce	-	Pos.	S/N	N off / Nº de série	enlevé	S/N on / N	° de série installé
ly/Par:	)pag	e no / page nº		1.7.		1										1						
Total révis	6																					
											Rectifi	A MARKET					500000000000000000000000000000000000000	139				
			t - Défectuosité				20			<b>—</b>			1	+	21		AME - TE	A	22	Lic.	23	Date
LARE	No	0UT 200°	EA:	5A 251-E			N H)	200°	1-02	. /	e S	N 10	de	لىو		. /	1	1				
							P	xt =	£ 6	AB	ځروية	GR-	3		3/1		gst-	_	M	20319	150	9-11-28
							\$	M	16	1.00	4				_/_							
										-												
:TTAF pection:/T	/ Prochai	ne DI/:	7day inspection	n carried out: / IC	/inspec	ction 7 jours effec		affected by the v	vork accomp	lished" / "	J'al effectué un	ight/powerplant of e inspection indé r le travail accom	pendante d		RMI / RM AHRS AHR #1 #2	RS	Runway Hdg / Cap de Piste	Mag co Comp magnét	as		Distribution	
pection:/T	Pe d'inspi	Sig	nature & Licen	ce No. Date:	Signat /	ture & n° de licen	Ce 26	Signature &	Licence No.		Signature & n°	de licence	Defect /	/ Défectuosité	27		70.0	magnet	Yello	e / Blanche - do w / Jaune - Teo / Rose - Fit. Op n / Verte - airfra	I Hecords / Do	ne pas enlever ossiers tech. Yow rations aér. Yow celluls

								+						
90														
Reporté (Page Préc.)		9		4		28	Component Replaceme	ent / Remplacement des	s composants				The second of the second	
AND THE RESERVE TO TH	11455	6	7		6861		Component & Part No	lumber / Composant et n	1º de pièce	Pos.	S/N off / N°	° de série enlevé	S/N on / N° de	série installé
Reporté	11456	5	1		6867	And and								
)page no / page n°			,											
Defect - Défectu	wosités		20			Rectifica	ation		-	AME - TEA	A	Lic.		Date
1 -11		t to	m .B	maken w	SP 00	mten	tioneter rep le.	ared	21	27.70		22	23	Duit
man light	accs n	" · · · · · · · · · · · · · · · · · · ·		70.	110	40	The state of the s	arres,	00	0	_			V 320
2 map lyn	0005 N	×3	Fu.	which t	ested son	milleth	•						100	1
				inchion t	ested se	rviudo	۷.		Dark	Blon	9	m395303	09	-   2-0
									Varia	1 n h	1	m395303	) 09	-[2-0]
									MA	Dan 1	1			
							RACE) N 571-10-12		MH	fork.	<u></u>			
COWLING  F BROKEN  571.10.									MH	Ept.			95-09-	
	G HING N 12. 181	GE	IH Ne	HNGE EW F	HALF PART	e RE	BACED W. 571-10-12	(TN 2./81	MH	fork.				
COWLING F BROKEN 571.10.		GE	7 jours effectué "I aft	Thave conducted an affected by the work a	PART	P/N estion of the flight i effectué une in	RACED W. 571 JO. 17	OTA 2 / 8 /	IMI / RMI / AHRS	Runway	Mag comp.	M20319		
COWLING F BROKEN 571.10.	7 H(NE) 12, 181 ection carried out:/10/in:	GE	7 jours effectué "I aft	Thave conducted an affected by the work a	HALF ART  n independant inspection accomplished*/*J'al e	P/N estion of the flight i effectué une in	RACED W. 571 JO. 17	OTA 2 / 8 /	MI/ FIMI/	Runway Hdg / Cap	Mag comp. Compas magnétique	White / Blanche - do Yellow / Jaune - Took	95-09-	-12 o/

, i

	M	M						
		$\angle$ \						
REG: C-FMPN		S/N: 296 T	Г.T.S.N: 11495.5	5 LA	ANDINGS: 6877			

#### THE FOLLOWING WORK HAS BEEN PERFORMED:

- -150 HR INSPECTION AS PER CHECK SHEETS ON FILE
- -PRATT & WHITNEY MANUAL P.N. 3038336, TABLE 601 PERIODIC INSPECTION
- -STARTER/GENERATOR BRUSHES EXAMINED FOR WEAR AMM 24-30-01, CHECKED SERVICEABLE
- -LUBRICATE FLAP SCREW ACTUATORS, AMM 27-50-00
- -P3 AIR FILTER CLEANED
- -PROPELLER FEATHERING MICRO SWITCH FUNCTIONAL TEST CARRIED OUT AMM, 76-10-02
- -SPARK IGNITERS INSPECTED FOR CLEANLINESS AND EROSION, EMM 74-20-00
- -PRATT & WHITNEY CANADA MAINTENANCE MANUAL P/N 3038336 CH 72-00-00, TABLE 601 3B POST S/B 14172 TURBINE BLADE INSPECTED AS PER PARAGRAPH 9.H.(2)
- -MIL 018 R1, ENGINE OIL DIPSTICK 'O' RING REPLACED P/N AS3209-018
- -ELT MONTHLY INSPECTION PERFORMED IAW ARTEX MAINTENANCE MANUAL 570-5060 REV D, CH 3.7, CHECKED SERVICEABLE
- -CHIP DETECTOR INSPECTED AS PER P&W CANADA EMM 72-00-00
- -FUEL PUMP OUTLET FILTER REPLACED, P/NAN6235-3A
- -FUEL PUMP INLET FILTER CLEANED IAW EMM 73-10-00
- -COMPRESSOR INLET SCREEN INSPECTION PREFORMED IAW EMM 72-00-00, NO DEFECTS FOUND
- -COLD AIR UNIT RE-OIL PREFORMED IAW AMM 21-40-01 CHECKED SERVICEABLE
- -HEAT EXCHANGER INSP PREFORMED IAW AMM 21-40-01 CHECKED SERVICEABLE
- -WATER SEPERATOR INSP PREFORMED IAW AMM 21-40-02 CHECKED SERVICEABLE
- -FUNCTION CHECK OF SECONDARY HEAT THERMAL SWITCHES PREFORMED IAW AMM 21-40-09, CHECKED SERVICABLE
- -SKY TRAC INSP OF CDU AND CIRCUIT BREAKER TEST PREFORMED, NO DEFECTS FOUND,
- -INSP OF BACKLASH CHECK ON ALL FOUR FLAP ACTUATOR PREFORMED IAW AMM-27-50-03 ALL WITHIN LIMITS
- -FUEL LOW WARNING TEST PREFORMED IW AMM 28-40-00 CHECKED SERVICABLE
- -ADF ANTENNA REPLACED DUE TO CRACK, SN ON A85354 SN OFF 76771 FUNCTION CHECKED NORMAL AMM 23-00-00

THE MAINTENANCE DESCRIBED AAS BEEN PERFORME	IN ACCORDANCE WITH THE APPLICABLE STANDARDS OF AIRWORTHINESS
---	--

SIGNATURE: AIRCRAFT RELEASE & State all

LICENCE #

M416986

DATE: 2009-12-14

Préc.) 11.53 //.54		4 4	2 2	Component Replacement / Remptace	ment des composants				
Préc.) 11.53 11.54	90	4 4	1	Component Replacement / Remptace	ment des composants				
Préc.) 11.53 11.54	90	4 4	1	Component Replacement / Remplacer	ment des composants				
1154			1 .	10					
1154			6899	Component & Part Number / Compo	sant et nº de pièce	Pos.	S/N off / N°	de série enlevé	S/N on / N° de série installé
age nº			6901						
							0		
						1			
		ni overtemp Due to no Age mac	Switch Replaced time exp. po 92 to poolyged to A	d Itw AMM 21- 3.81,32.122.Charled. I delea Boots Charled	40-a 2 Survidle R.M. Surv R.M.	steelle Light		141698	
DI / 7day inspection carried out: / Id Signature & Licence No.		commandes	the work accomplished" / "J'ai effectué un	ne inspection indépendante des	RMI/ AHRS AHRS #1 #2	Runway Hdg / Cap de Piste	Mag comp. Compas magnétique	Yellow / Jaune - Tec Pink / Rose - Fit. Op	Distribution on not remove / ne pas enlever the Records / Dossers tech. Yow perations / Opérations aér. Yow
DI		/7day inspection carried out: / IQ / inspection 7 jours signature & Licence No. Signature & n° de	77day inspection carried out: / IQ / inspection 7 jours effectué affected by commandes  1. Signature & n° de licence	MI WUTEMP Switch Replace  Due to time copying of the Age marker popying of the affected by the work accomplished. It all affected by the work accomplished. It affected by the work accomplished by the work accomplished.	MI WITTIMP Switch Replaced Ith AMM 21-  Due to time exp. on 973.81, 32.122. Checked  may make a populated to the delicence of the dight powerplant controls that were affected by the work accomplished" / "J'ai effected une inspection indépendante des commandes de vol / réacteur qui étaient touchées par le travail accompli."	MI WITTIMP Switch Replaced The Amm 21-40-a  Due to time exp. pn 973.81, 32.122. Charled Switcher, the  May marker poplyful to All duke books checked Switcher, the  May marker poplyful to All duke books checked Switcher, the  Milliam repetion carried out: / 10 / inspection 7 jours effectue  There conducted an independant inspection of the flight/powerplant controls that were affected by the work accomplished." "I have conducted an independant inspection of the flight/powerplant controls that were affected by the work accomplished." "I have conducted an independant inspection of the flight/powerplant controls that were affected by the work accomplished." "I have conducted an independant inspection of the flight/powerplant controls that were affected by the work accomplished." AHRS AHRS commandes de vol / réacteur qui étaient touchées par le travail accompil."  Signature & Licence No.  Signature & n° de licence	MI WUTEMP Switch Replaced The Amm 21-40-a  Due to time ctp. Die 973.81, 32.122. Charked Switcher Mutember and Age maybe Appropred to the discussion of the flight/powerplant controls that were affected by the work accomplished." "The effected were inspection independented des commandes de vol / réacteur qui étaient touchées par le travail accompli."  Rumway Hdg / Cap de Piste signature & n° de licence.	MUTIMP Switch Replaced Itw Amm 21-40-00  Due to time exp. pn 973.81, 32.122. Charled Swinds Ribertalle  My mache polygred to the delice books which the swinds and independent inspection of the #ilight/powerplant controls that were affected by the work accomplished" / "I have conducted an independent inspection of the #ilight/powerplant controls that were affected by the work accomplished" / "I have conducted an independent inspection of the #ilight/powerplant controls that were affected by the work accomplished" / "I have conducted an independent inspection independent does commandes do vol / relacted une inspection independent does and place of the place of t	Mutamp Switch Replaced Ith Amm 21-40-a  Due to time up prograd to the discussion of the High/powerplant controls that were affected by the work accomplished "Thave conducted an independant inspection of the High/powerplant controls that were affected by the work accomplished" "I have conducted an independant inspection of the High/powerplant controls that were affected by the work accomplished" "I have conducted an independant inspection of the High/powerplant controls that were affected by the work accomplished" "I have conducted an independant inspection of the High/powerplant controls that were affected by the work accomplished" "I have conducted an independant inspection of the High/powerplant controls that were affected by the work accomplished" "Jai offectué une inspection indépendante des commandes de vol / réacteur qui étaient touchées par le travail accompli."    RMII

Clae	oner			61	VW	_ crew/Ed	quipa	age:		CTI	ww					0	1/1	40 10ut	o u acit	JIIEI U	OTCC
พ	fit no Nº du voi 2	Time (GMT) Up/Déc. 3	/ Heure (TU) Down/Atter.	Air time / ten		Flight time Temps de v hours / heures		Naut, miles Milles naut.	ldgs or / after, ou cy / rin	Perso	ons on boar	rd Fuel	Oil	Baggage, cargo, equip. / Bagages.	/Sig. et lic. d	Fuel boarded / run	plier In	voice No.	684 Litres	_ Date: 4	
al		16.5	1817	2	2	2	7	6	7	8	W230 (3)	9	(lb) 10 -	fret et équip.	décollage	Carburant embarq fournisseur	uė/ N° d	e la facture	or / eu Gal	CAN US	Type of fit. Type de voi
4	2	19.3	22.3	3		3	9			8	132	0 2050	Full	100	9920	13	14		15	16	17
_		.,,,,		- 0	0	2	)		1	8	132	20 2050	~	100							
														100	7100						
	-		-														-				
													-								
					-		-	-												-	
Totaux	2550			5	2	5	4				2	Compone	nt Replacen	nent / Remplacemen	t dos como const						
rge)	Reporté	(Page Préc.)		11569	2				1	091	1			Number / Composar	A DESCRIPTION OF STATE OF						
d.)	Reporté			1157	_					691		5,110	om a ran	Humber / Composar	st et n° de piece	Pos.	S/N off /	N° de série e	nlevé	S/N on / Nº de	série installé
Par: otal rév	_	e no / page n	•	-	-					- London											
		Defe	ct - Défectuosi	tés			20		14.1		179	Rectification			21	AME - TE	A	22	Lic.	23	Date
						W.	D.	t mon	2 520	FN.	90	preform w D Ch	22	AW	2110	n. L. II.		-			
							13.	144	, , ,	30	00 P	W U Ch	3, 1,	Charan	auv. K.	mercinge		- M	416980	. 30	m 8,10
																				-	
	at / Brocks	ine Di	/ 7day inchestic	on carried out:	IQ / insc	ection 7 jours effe	ectué	"I have condu	cted an indeb	endant in	spection of	the /light/powerplant	controls tha	it were	BMI/ B	MI / Runway	Mag comp.			Notab See	
TTAF ection:/	at: / Procha LL 645 Type d'insp	<u>.</u>	gnature & Lice			nature & n° de lice	_	affected by the	work accom	plished" /	"J'ai effects	ué une inspection inde es par le travail accor	pendante d		AHRS A	HRS Hdg / Cap #2 de Piste	Compas magnétique	Yellov	/ Blanche - do v / Jauns - Tecl	Distribution not remove / ne n Records / Doss	iers tech. Yow
	Wr.	05	a mining to mino	Date:	1	1	XMY Y	26 Signature	& Licence No	).	Signature	e & nº de licence	Defect	/ Défectuosité	27					erations / Opérat me log / livret ce	

Totaux Page							/	28	Compon	ent Replacer	nent / Remplace	ment des compo	sants						
v. Page) Reporté (Page Préc.)		11575	115750		6920			Component & Part Number / Composant et nº de pièce.			ce	e Pos.		S/N off / N° de série enlevé		S/N on / N° de série installé			
Fwd.) Reporté  By/Par: )page no	(page 6*	11579	0.2			65													
I Total révisé	page ii																		
	Defect - Défectuo		v	20	000			Rectifi	N. (1.55.06.)	8			21	AME - TE	Α	22	c.	23	Date
TART ATTENTED NO LIGHT AND					Conter operational Check Paceformed as per Amus						& netcelle			N41698		36 San 12,10			
				G	Pu Start	Refor	med	engin	g sto	act c	ornal		K.M.	teally		mula	86	-	12,10
				An	am p	All pe	ance Wan	retus	found	within	limite		& ru	feely		M4169	86	Jan	12,200
tion due at: / Prochaîne	DI / 7day inspecti	ion carried out: / IQ /	inspection 7 jo	urs effectué	"I have conduct affected by the							RMI /	RMI/ AHRS	Runway Hdg / Cap	Mag comp.		Distribu	tion	
TTAF 116 45, 4 pection: / Type d'inspection:	Signature & Lice	ence No.	Signature & nº	de licence	commandes de	vol / réacteur d	qui étalen	t touchées par	le travail accom	pli.*	Défectuosité	27	#2	de Piste	Compas magnétique	White / Blanche Yellow / Jaune - Pink / Rose - Fl Green / Verte -	Tech Record t. Operations	s / Dossiers / Opérations	tech. Yow adr. Yow

TO/A:	Nº du vol 2		Down/Atter			Temps de hours / heures	vol	Naut. miles Milles naut.	ldgs or / atter. ou cy / rin	Pers	ons on board onnes à bord / nbre lb	Fuel Carburant (lb)	Oil Huile (lb)	Baggage, cargo, equip. / Bagages, fret et équip.	Total takeoff w Masse totale a décollage	t. Fo	uel boarded / supplier Carburant embarqué / fournisseur	Invoice No. N° de la facture	Or / ou Gal	cost / prix CAN US	Type of fit. Type de vol
ZF		04.6	06.9	9 4	3	a	4	460	1	4	630	2000	HKK	200	1480	2		15	15		1
												Composes	Donlacem	ent / Remplacement	des composants						
Totaux Page 2 3				1001				28	28 Component Replacement / Remplacement des composants  Component & Part Number / Composant et n° de pièce Pos.					S/N off / Nº de série	N off / N° de série enlevé S/N on / N° de série installé						
		Page Préc.)		11579	2		6921														
y Fwd.)	Reporté			11581	5		-		64	20	_										
(By/Par:	)page	no / page nº			-		-														
al Total révisé																					
		Defect -	Défectuosité	is		2	20				Rectific			<i>(</i> )	21		AME - TEA	22	Lic.	23	Date
						mı	Pru	Caution	ary	_B	OCOSU	pe I	NSP	Hon	1		, 1/				. 12 400
							UD	VISUA	1 1	ef	ects	foura	/ _	Hon	$-\kappa$	Me	teage	71	141699	6 Ja	n 13,200
-																					
		Terrer	inencation	carried out: / IQ	/ inspectio	on 7 jours effects	ué "I	have conducted fected by the wo	an independ	ant inspe	ection of the flig ai effectué une	int/powerplant co	ntrols that vendante des	vere		RMI / HRS #2	Hdg / Cap Cor		/ Blanche - do l	Distribution not remove / ne p Records / Dossie	
ection due at: / F	rochaine	4	y arspection			- e ne da licance	. 00	fected by the wor orninandes de vo	l / réacteur q	ui étalen	t touchees par	10 1010.						interior.	Done - El One	rations / Opératione log / livret cellu	ris abi. Tow

## **AIRCRAFT LOG**

October 26, 2010 Airframe Log Entry PC-12/45 S/N 296 N840AG

Page 1 of 1

Total Time: 11974.3

Total Cycles: 7116



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

# Airframe Log Book #52 Opened with the following actions:

- Last two entries from VKPC Journey Log pages 296-01 and 296-02 copied and brought forward.
- Aircraft registration changed from C-FMPN (Canadian TCCA) to N840AG (USA FAA) with temporary registration installed in aircraft.
- Issuance of US FAA Certificate of Airworthiness pending the completion of required inspections and acceptance of major repairs and alterations performed while registered in Canada.
- FAA AD's checked through Bi-weekly 2010-21 with no outstanding AD's due at this time.

### Complied with Aircraft 100 Hour Inspection:

Performed the following inspections, tests and services:

- 100 Hour Inspection per inspection checklist from PC-12 AMM 12-A-05-20-10-00A-281A-A and FAA FAR Part 43 Appendix D.
- 6 month application of Age Master Airfoil de-ice boot treatment previously complied with during Annual Inspection dated September 29, 2010 by V. Kelner Pilatus Center, Thunder Bay Canada.

\*\*\* END \*\*\*

All required ground checks for the above maintenance has been corpleted with satisfactory results. No changes are noted in the aircraft compass system. No change to aircraft weight & balance data. No change to equipment list records.

Maintenance Release: The maintenance identified above was inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service. Details are on file under Work Order No. 296A-7-1.

This aircraft has been inspected and has been found safe for the intended flight in accordance with Special Flight Permit dated October 26, 2010 and issued by FAA FSDO Denver, Colorado for maintenance flight to Grand Junction, Colorado.

Total to Carry Forward		
Carry Forward		

TUSE

N840AG

PC12/45

S/N: 296

t Way, Broomfield, CO 80021


WEST/STAR AVIATION

WO: 22695 DATE: 11-18-10

HOBBS: <del>1879.6</del>

1975.3 QA-DC217

AIRFRAME ENTRY page 1 of 5






WO: 22695

DATE: 11-18-10

HOBBS: <del>1879.6</del>

1975.3 CA-DC217

### AIRFRAME ENTRY page 2 of 5



N840AG

PC12/45

S/N: 296

ELEVATOR WEIGHT Ib (kg)


WEST/ST/AR AVIATION

a N840AG = PC12/45 S/N: 296

AIRFRAME ENTRY page 3 of 5

WO: 22695 DATE: 11-18-10 HORBS: <del>1879 6</del>

HOBBS: <del>1879.6</del> /**975.3** QA-DC217



N840AG PC12.45 S/N: 296




WO: 22695

DATE: 11-18-10

HOBBS: <del>1879.6</del> 1**975**.**3**17

AIRFRAME ENTRY page 4 of 5



N840AG PC12/45 S/N: 296



WO: 22695

DATE: 11-18-10

HOBBS: <del>1879.6-</del> 19753

#### AIRFRAME ENTRY page 5 of 5

QA-DC217

Complete strip and paint with customer supplied scheme using the following colors:

MFG: Acry Glo Metallic P/N: 10586 COLOR: Steel Blue Metallic Acry Glo Metallic P/N: 10645 COLOR: Misty Blue Acry Glo Metallic P/N: 10679 COLOR: Titanium Jet Glo P/N: CM0840102 COLOR: Snow White Clear coated stripes.

- Balanced rudder after paint per Pilatus PC12/45 SRM DCM 12-A-51-60-03-00A-276A-A. Added 0.25 lbs. P/N 555,40.12.174. Re-installed Rudder per PC12/45 AMM 12A-55-40-01-00A-920A-A.
- Balanced left and right elevators as an assembly after paint IAW PC12/45 SRM DCM 12A-51-60-02-00A-276A-A. Balance is within limits. Re-installed elevators IAW PC12/45 AMM 12A-55-20-01-00A-920A-A.
- Balanced left aileron after paint IAW PC12/45 SRM DMC 12A-51-60-01-00A-276A-A. Balance is within limits. Re-installed aileron IAW PC12/45 AMM 12A-57-60-01-00A-920A-A.
- Balanced right aileron after paint IAW Pilatus PC12/45 SRM DMC 12A-51-60-01-00A-276A-A. Balance is within limits. Re-installed aileron IAW PC12/45 AMM 12A-57-60-01-00A-920A-A.
- Removed paint from screw holes of composite parts prior to installation IAW Pilatus Process Specification VV083-04 DTR2.
- Installed new left outboard de-ice boot P/N 27-7D5221-11, S/N MCQL640 (cure date 08-10). Work completed per Pilatus PC-12 M/M, Rev Sep08, Chapter 12-A-30-14-01-00A-920A-A. Re-installed left AOA transmitter IAW PC-12 MM ch 12-A-22-20-02-00A-920A-A and fillet sealed using PR-1422B2.

The above-described maintenance has been inspected and is approved for return to service with regards to the maintenance performed. Pertinent details are on file at this repair station under the above work order. A copy of this work order has been given to the operator.

Signature /

WEST STAR AVIATION, INC

796 Heritage Way

Grand Junction, CO 81506 (970) 243-7500

FAA CERTIFIED REPAIR STATION WTXR173J

N840AG PC12/45 S/N: 296



WO: 22695

DATE: 11-18-10

HOBBS: <del>1879.6-</del> 1975.3

QA-DC217

#### AIRFRAME ENTRY

= This aircraft has been inspected and has been found safe for the intended flight in accordance with Special Flight Permit dated November 17, 2010.

- Signature WEST STAR AVIATION, INC.

FAA CERTIFIED REPAIR STATION WTXR173J

796 Heritage Way

Grand Junction, CO 81506 (970) 243-7500

	1	l		L
			1700	
		2	N Years	
Total to Carry Forward				

Page 1 of 6

Total Time: 11976.3

Total Cycles: 7119



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

Aircraft has been modified by the following installations:

### PC-12 Interior Reconfigured as F.O. No Cabin Interior

Removed Interior code STD-9S previously installed in accordance with Pilatus Aircraft MDL # 525.25.12.296 by removing 9 standard seats, all cabin sidewall panels and headliner. Interior reconfigured as Factory Option No Cabin Interior by installing pilot and co-pilot bulkheads at frame 16 and all required cabin placards. Reference FAA Form 337 dated Dec 10, 2010 for additional cabin configuration and removals information.

### Cabin Entertainment System Provisions

Stamped wires, assembled and routed entertainment system harness providing for CD/DVD components in accordance with Pilatus Business Aircraft FAA STC SA00621DE.

### Flight Display System Moving Map Provisions

Installed wiring provisions for moving map display system per Pilatus Business Aircraft drawing PBA.525.025 Rev I/R. Moving map system to be installed in refreshment cabinet during interior installation process.

### Altitude Heading Reference System Units (AHRS) Replacement

Removed #1 and #2 Litef LCR-93 AHRS P/N 142185-2000 S/N's 1156 and 1166, respectively. Installed repaired #1 and #2 Litef LCR-92 AHRS P/N 124210-2022 S/N's 1468 and S/N 1179, respectively. Work performed in accordance with PC-12 AMM 12-A-34-25-01-00A-920A-A. Operational checks and compass swing performed in accordance with PC-12 AMM 12-A-34-25-00-00A-903A-A with normal results.

### Supplemental Air Conditioning Factory Option

Installed the VCCS system per factor option # 500.20.12.023. The following main components were installed:

- Condenser/Compressor unit, P/N 1134400-13 S/N 793
- Evaporator Modules P/N 1134200-43 S/N's 1024 and 1025
- Evaporator Module P/N 1134200-42 S/N 554
- Air Conditioning System Drain P/N 521.52.12.010

Reference FAA Form 337 dated December 10, 2010 for installation details and instructions for continued airworthiness.

### Honeywell KDR-610 Flight Information System FAA STC # SA00659DE

Stamped wires, assembled and routed system harness and installed the following components:

- Honeywell XM Data Receiver, P/N 4092743-902 S/N 33916419
- Honeywell FIS Module, P/N 071-00168-0311 S/N 3219 installed in KMD550/850.

Page 2 of 6

Total Time: 11976.3

Total Cycles: 7119



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

- Honeywell KMD850 Data Base Module, P/N 071-00161-0201 S/N 1987694708 installed in KMD550/850.

- Comant Antenna GPS, P/N CI 420-1 S/N 305696

Reference FAA Form 337 dated December 10, 2010 for installation details and instructions for continued airworthiness.

### Garmin GNS 430W/530W NAV/COM/GPS

- #1 and #2 Bendix/King KX 155A transceivers P/N 069-01032-0101 S/N's 13580 & 13062
- Bendix/King KLN 900 GPS receiver P/N 066-004034-0104 S/N 3447
- Comant GPS Antenna P/N CI405-2 S/N 61313
- Garmin GNS 430W #1 GPS/Com/Nav transceiver P/N 011-01060-00 S/N 23425743 with Main Software ver 3.30 & GPS ver 3.2
- #1 AeroAntenna GPS antenna P/N 013-00235-00 S/N 53084
- Garmin GNS 530W #2 GPS/Com/Nav transceiver P/N 011-01064-00 S/N 23822865 with Main Software ver 3.30 & GPS ver 3.2
- #2 AeroAntenna GPS antenna P/N 013-00235-00 S/N 53085
- Sandia Aerospace CDI Switch Relay P/N A S200-35 S/N 12663
- GPS Databases P/N DGRW72-430W & DC RW72-530W both expiring Jan 13, 2011.

Reference FAA Form 337, dated December 10, 2010 for installation details and instructions for continued airworthiness. Installed placard near both GNS units "GPS limited to VFR use only" pending completion of GPS/IFR check flight.

### Relocation of SkyTrac ISAT-100 DVI and CDP

Relocated the following to center pedestal:

- SkyTrac Systems Ltd. Dispatch Voice Interface, P/N DVI-250 S/N 13087
- SkyTrac Systems Ltd. Cockpit Display Panel, P/N CDP-250 S/N 11448

Reference FAA Form 337 dated December 10, 2010 for installation details and instructions for continued airworthiness LSA08-053/D.

### Removed SatTalk II Portable Communications System

Removed existing wiring harness for the SatTalk and pilot and copilot headset connectors, circuit breakers labeled SATPHONE and HEADSET POWER from the Avionics Bus 1, and antenna coax from LH pilot sidewall panel to the Iridium antenna.

Reference FAA Form 337 dated December 10, 2010 for removal details for LSTC 0-LSA01-521/D.

#### Removed AUX 28VDC Power Connector

Removed Aux 28VDC power connector from the co-pilot's sidewall, existing wiring harness for the power connector and circuit breaker from

December 10, 201 Airframe Log Entry PC-12/45 S/N 2 **N840AG** 

Avionics 2 bus. Re Removed Provision

Removed all wiring December 10, 20: Removed Headse

and connectors re Removed Transpo Pilatus Aircraft dr

The following ma

**Bucher Heavy D** standard cabin f Reconfiguration

Installed passer 003. Leak ched

Replacement o window, P/N 5!

Cabin Insulatio **Door Locks Re** 

Removed and Removed and

Removed and **Crew Seat Be** 

12-A-25-10-02 Pilot Oxygen

port, (same P

Performed Ca - 2 Year/150

30-01-00A-2!

Page 3 of 6 Total Time: 11976.3 Total Cycles: 7119



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

Avionics 2 bus. Reference FAA Form 337 dated December 10, 2010 for removal details.

#### Removed Provisions for Technisonic TDFM 614 Transciever

Removed all wiring was removed per installation drawings. Antennas for the system not removed. Reference **FAA Form 337** dated December 10, 2010 for removal details for LSTC 0-LSA00-876/D & LSTC 0-LSA04-105/D.

<u>Removed Headset Power Connectors</u> – from pilot/co-pilot sides in accordance with RCMP install drawings 25000-99-14 and -17. Wiring and connectors removed. Reference **FAA Form 337** dated December 10, 2010 for removal details for LSTC C-LSA00-870/D.

<u>Removed Transponder Setting Switch</u> – from the pilot side return panel, removed wiring and installed blanking plate in accordance with Pilatus Aircraft drawing PBA.534.435.

#### The following maintenance was performed:

Bucher Heavy Duty Floor Replacement - Removed Factory Installed Bucher Heavy Duty floor, P/N 0127470-401. Installed 14 serviceable standard cabin floor panels in accordance with PC-12 AMM 12-A-06-20.

Reconfiguration of Passenger Oxygen System - Removed passenger oxygen system for STD-9S per Pilatus drawing 535.21.12.003. Installed passenger oxygen system for 8 seat executive cabin configuration in accordance with Pilatus drawing 535.21.12.014 and SB 35-003. Leak check per armed with no leaks detected.

<u>Replacement of DV Window per Pilatus SB 56-002 - Removed DV window, P/N 959.81.10.121 S/N 99265H8580.</u> Installed new DV window, P/N 556.14.12.099 S/N 10078H1143 per instructions in service bulletin.

<u>Cabin Insulation Replaced</u> - Removed cabin insulation and replaced with new kit, P/N 500.50.12.184, in accordance with SB 25-012.

Door Locks Replacement Kit 552.10.12.411

Removed and replaced passenger/crew door lock in accordance with PC-12 AMM 12-A-52-10-02-00A-920A-A.

Removed and replaced service door lock in accordance with PC-12 AMM 12-A-52-40-01-00A-920A-A.

Removed and replaced cargo door lock in accordance with PC-12 AMM 12-A-52-30-01-00A-920A-A.

<u>Crew Seat Belt Replacement</u> – 12 year life limit replacement of belt assemblies, P/N 959.30.01.243 on both crew seats per PC-12 AMM 12-A-25-10-02-00A-920A-A. New belts date of manufacture 17/2010. Pilot seat belt S/N 21Nov9811. Co-Pilot seat belt S/N 07Jan9926. Pilot Oxygen Port Outlet Replaced – Removed pilot side quick disconnect port P/N 952.12.22.212 S/N 30575 and replaced with new

port, (same P/N) S/N 29/10.

<u>Performed Cabin Pressurization Leak Check and Pressure Relief Test</u> with normal results. Maintenance performed on the following:

- 2 Year/1500 hour Cleaning of Outflow and Safety Valves - Cleaned outflow valve and safety valve in accordance with PC-12 AMM 12-A-21-30-01-00A-250A.

Page 4 of 6

Total Time: 11976.3

Total Cycles: 7119



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

- 2 Year/ 1500 hour Adjustment test of Pressurization System - Performed adjustment test of Pressurization System in accordance with PC-12 AMM 12-A-21-30-00-00A-903A with normal results.

#### Complied with Aircraft 100 Hour Inspection:

Performed the following inspections, tests and services:

- 100 Hour Inspection per inspection checklist from PC-12 AMM 12-A-05-20-10-00A-281A-A and FAA FAR Part 43 Appendix D.

Altimeters and static system have been tested per PC-12 AMM 12-A-34-11-00-00A-903A-A and found to be in compliance with requirements of FAA FAR Part 91.217 for automatic pressure altitude reporting equipment.

Altimeter #1 Bendix/King P/N 066-03062-0010 S/N 4197 test/certify date: Aug 27, 2009 Due Aug 27, 2011 tes /certify date: Oct 20, 2009 Due Oct 20, 2011 Altimeter #2 United (encoding) P/N 5035P-P50 S/N 29639

ATC Transponders have been tested per PC-12 AMM 12-A-34-14-00-00A-903A-A and found to be in compliance with requirements for transponders per FAA FAR Part 91.413(b).

Transponder #1 Bendix/King KT 70 P/N 066-01141-0201 S/N 30303 test/certify date: Mar 15. 2010 Due Mar 15. 2012 Transponder #1 Bendix/King KT 70 P/N 066-01141-0201 S/N 304 37 test/certify date: Sept 02. 2009 Due Sept 02. 2011

#### FAA AD's checked through Bi-weekly 2010-25 No outstanding AD's due at this time. AD history/compliance for airframe and appliances items follows:

- AD 98-04-16 AILERON TIF ROD JAM NUTS Applicable to MSN 101-169, embodied at time of manufacture, 1999 SB 27-001
- AD 98-07-18 PROP DEICING CONTROLLER Applicable to MSN 101-169, embodied at time of manufacture, 1999 SB 30-002
- AD 98-08-26 UNDERWING ACCESS PANELS Applicable to MSN 101-169, embodied at time of manufacture, 1999
- AD 98-11-01 R2 FUEL TANK INWARD VENT VALVE Applicable to MSN 101-230, embodied at time of manufacture, 1999 SB 28-003 R1
- AD 98-11-20 LAVATORY AND SEAT CONFIGURATION Applicable to MSN 101-180, applies to executive interior, this is standard interior commuter
- AD 98-13-08 Superseded by AD 99-14-03
- AD 98-20-28 ICING POH limitations section 2-14 thru 2-16 dated March 30, 2001 meet requirements POH is at Rev 14 dated Jun 30, 2010.
- AD 98-21-27 PASSENGER SEATS Applies to MSN 101-230, embodied at time of manufacture, 1999 SB 25-006
- AD 99-06-05 ALTERNATE FLAP SYSTEM Applies to MSN 101-227, embodied at time of manufacture, 1999 SB 27-004

De Air

NE

Page 5 of 6

Total Time: 11976.3

Total Cycles: 7119



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

- AD 99-06-17 SECOND GENERATOR CONTROL UNIT Applies to MSN 101-180, embodied at time of manufacture, 1999 SB 24-009
- AD 99-14-03 STANDBY MAGNETIC COMPASS Applies to MSN 101-147, embodied at time of manufacture, 1999 SB 24-001 R1
- AD 99-17-01 FLAP DRIVE SHAFTS Applies to MSN 101-239, embodied at time of manufacture, 1999 SB 27-003
- AD 99-24-09 INBOARD FLAP ATTACHMENT FITTINGS Applies to MSN 101-300, embodied at time of manufacture, 1999 SB 57-004
- AD 00-02-31 STICK PUSHER CAPSTAN AND SERVO Applicable to MSN 101-180, embodied at time of manufacture, 1999 SB22-003
- AD 00-11-14 AFM ICE PROTECTION SYSTEM Inserted requirements for the activation of the pneumatic deicing boots in the AFM.
   Rev 14 (dated Jun 30, 2010) installed in POH 26 Oct 2010.
- AD 00-26-17 POH WINDSHIELD DEICING SYSTEM Complied with SB 30-006 Sept 2000
- AD 01-11-02 GENERATOR 2 EXCITATION Embodiec at time of manufacture 1999 SB 24-014. AD does not apply to aircraft S/N
- AD 01-22-15 CARGO DOOR Inspected per SB 52-004 Nov 2001 No further action required
- AD 01-25-10 FLAP ACTUATOR INTERNAL GEAR SYSTEM Replacement of flap control warning unit (FWCU) accomplished Jan 2001
- AD 02-06-10 OXYGEN FLOW AT REAR BENCH SEAT Aircraft in standard commuter configuration and does not apply
- AD 02-14-22 MAIN LANDING GEAR ASSEMBLY BOLTS Applies to aircraft S/N 349 and above. No action taken. SB 32-012
- AD 03-07-10 OVERHEAD ELECTRICAL PANEL SWITC! CAPS Does not apply. Applies to aircraft S/N 321 & 401 thru 457 only.
- AD 03-09-11 AFT FACING PASSENGER SEATS Aircraft in standard commuter configuration and does not apply. No rear facing seats installed.
- AD 03-11-17 REAR PRESSURE DOME Rear pressure dome inspected for damage IAW SB 53-003 Nov 26, 2002
- AD 03-20-15 POH FUEL BOOST PUMP SB 28-011 R1 complied with Jul 2003
- AD 04-04-01 ENGINE DRIVEN FUEL PUMP Pump inspected (P/N RG9570R1/M) and SB does not apply to P/N. Jun 2003 SB 28-009 & 28-010.
- AD 04-06-05 MAIN LANDING GEAR SHOCK ABSORBER ATTACHMENT BOLTS Aircraft inspected per SB 32-015 with no action required. Nov 2003.
- AD 04-12-11 FLAP FLEXSHAFTS Aircraft inspected and no action required due to P/N and color of flex shafts. Feb 2003. SB 27-015.
- AD 05-01-11 MAIN LANDING GEAR ACTUATOR Actuator replacement not required. Part S/N not affected. SB 32-017
- AD 05-04-16 WINDSHIELD DEICE WIRING Not applicable by aircraft serial number. SB 30-009
- AD 05-11-06 POH, PITCH ACTUATOR Autopilot pitch actuator replaced with new improved actuator P/N. Jul 2005. SB 22-004
- AD 05-22-04 "AM" SERIAL NUMBER LANDING GEAR COMPONENTS Not applicable by component P/N and S/N. Jul 2005. SB 32-016

Page 6 of 6

Total Time: 11976.3

Total Cycles: 7119



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

- AD 05-22-13 MLG HIDRAULIC ACTUATOR ROD END BOLT Bolt inspection completed with no action required. Jul 2005. SB 32-018.
- AD 06-08-11 CREW SEAT BUCKET ASSEMBLIES Seat backrest tubes replaced per SB 26-031. Sep 2008.
- AD 06-16-13 FRAME 21 WING ATTACHMENT LUG FITTINGS Inspection performed per SB 53-004 with no faults found. Nov 2006.
- AD 07-03-06 EXECUTIVE SEAT PEDESTAL LEGS Does not apply. Executive seats not installed in current configuration.
- AD 07-21-11 TORQUE OIL PRESSURE PIPE AND HOSE ASSEMBLIES Inspection completed per SB with no faults found. Sep 2007.
   SB 71-007.
- AD 08-02-03 MAIN LANDING GEAR SPECIAL BOLTS Completed SB with no faults found. Oct 2007. SB 32-020 R1
- AD 08-06-17 SUPERSEDED BY AD 2009-05-07 Complied with by replacing bolts on cable clamps per SB 27-018. Dec 2007.
- AD 08-07-11 AMM PITCH TOIM ACTUATOR AND ATTACHMENT PARTS Complied with by adding new life limits to pitch trim actuator and attachment parts. Oct 2008.
- AD 09-05-07 STICK PUSHER SERVO-CABLES Inspected stick pusher servo cables for correct installation per SB 27-020 R1. Mar 2009.
- AD 09-08-11 DEICE PRESSURE REGULATOR VENTING Outboard vent for the airfoil Deice System PX regulator performed per SB 30-011. Mar 2009.
- AD 09-14-13 NOSE LANDING GEAR RH UPPER DRAG LINK AND TORQUE TUBE Supersedes 03-14-07. Establish repetitive inspection
  of the NLG RH upper drag links. Mar 2009 installed new steering torque tube IAW SB 32-021.
- AD 74-24-13 UNITED INSTRUMENTS ALTIMETERS P/N 5932, 5934 N/A by serial number
- AD 86-05-02 UNITED INSTRUMENTS ALTIMETERS P/N 5934 N/A by serial number
- AD 96-21-13 LITEF GMBH LCR-92 HEADING & REFERENCE N/A by AHRS part number installed. (These parts were installed above)

\*\*\*END\*\*\*

All required ground checks for the above modifications and maintenance have been completed with satisfactory results. No changes are noted in the aircraft compass system. The **aircraft was weighed** with weight & balance records & equipment list records updated and installed in the POH. Updated POH document number 1973-001 to Rev 14 dated June 30, 2010.

Maintenance Release: The maintenance identified above was inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service. Details are on file under Work Order Nos. 296A-5, 296A-6, 296A-7.

Signature of Authorized Person (

Dudley Clark

for FAA Certified Repair Station No. ZP8R849Y

# Registration No. <u>N840AG</u>

and Remarks			Signature	Certificate No.
MAKE	PILATUS AIRCRAFT, LTD	MODEL		
S/N	296	ACTT	11976.3	
REGIS. #	N840AG	CYCLES	7119	
	I CERTIFY THAT I HAVE IN	SPECTED THIS	AIRCRAFT,	
FOUND THAT	TIT COMPLIES WITH THE RE	EQUIREMENTS	OF THE CERTIFICAT	TION
REQ	JESTED AND HAVE ISSUED	A STANDARD	CERTIFICATE OF	
-	AIRWORT		ED 2011	
	THE NEXT INSPECTION IS			
	DATED <u>Dec</u>	ember 10, 20	)10	
- Deloi	Hust		(AD's checked thro biweekly 2010-2	<u> </u>
Robert P. Hi	usted DARF351144NM			
*				
	9			

Date	N840AG PC-12/45 Date: 12-14-10 S/N 296 TT: Repaired LH & RH Side Cockpit Windows and All Cabin Windows. The above described maintenance has been inspected and is approved for return to service. Pertinent details are on file at this repair station under work order: CO-343 dated 12-14-10  Signature FAA Certified Repair Station VW6R328Y  Aviation Window Services 7114 Rustic Trail, Suite 100 Boulder, Colorado 80301 720.222.1224	Maintenance	Dece Airfri PC-1 N84 Aircr This date conc plac PC-: 50C new and cov Ca - A, Re FC - F Re TI
Total to Carry Forward			

Page 1 of 1

Total Time: 11977.3

Total Cycles: 7120



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

Aircraft has been modified by the following installations:

This aircraft has been modified by the approval of existing GPS equipment for IFR/Enroute & Approach. (Reference FAA Form 337 dated December C8, 2010 for details of the initial Garmin GNS 430W/530W installation.) A satisfactory functional flight evaluation was conducted in accordance with AC 20-138A. This GNS 430W/530W GPS installation is approved for IFR/Enroute & Approach and the placard labeled "GPS Not Approved for IFR Use" has been removed. Reference FAA Form 337 dated December 16, 2010 for IFR details.

<u>PC-12/45 Cabin Interior Code # EX-6S-STD-2S</u> Installed serviceable executive interior components IAW Pilatus Aircraft Factory Options # . 5002012445, 5252220010, 5252512233 & POH Section 6 and PC-12 AMM 12-A-25-21. Installed following executive interior upgrades; new cockpit glare shield, passenger & cargo door upgrades w/scuff plates, cockpit curtain, cargo net cover, pillows, heat register covers and headrest covers. The two RH and one LH sidewall video monitor connections, and the three inverter outlets located on the table covers, were previously installed and are all non-functioning and labeled "INOP" at this time.

<u>Cabin Entertainment System</u> Installed the following components to complete the system:

- A/I DVD/CD Player, P/N AV5008-00 S/N 2065, A/I PCU, P/N PCU20-00 S/N 2125 and A/I I/R Remote, P/N IRR020-01 Reference **FAA Form 337** dated December 16, 2010 for installation details and instructions for continued airworthiness.

FDS Cabin Moving Map Display Installed the following components to complete the system:

- FDS LCD Video Display, P/N FD70CV-V S/N 1010038020 and FDS Display Computer, P/N FD200CPU-7P S/N 8011003 Reference **FAA Form 337** dated December 16, 2010 for installation details and instructions for continued airworthiness. The following maintenance was also performed:
- Removed De-ice boot pressure switch, P/N 973.81.14.312 S/N 0855. Installed new pressure switch, P/N 973.81.14.313 S/N 5638, in accordance with PC-12 AMM 12A-30-10-00A-920A-A. Function check of pressure switch normal.
- Performed 3 Year Inspection of Oxygen Masks in accordance with PC-12 AMM 12A-35-20-00-00A-313A-A.
- Repair of Cockpit and Cabin Windows accomplished. Reference Aviation Window Services Log entry dated December 14, 2010 for details. 

  \*\*\*END\*\*\*

All required ground checks for the above modification have been completed with satisfactory results. No changes are noted in the aircraft compass system. The aircraft was weighed with aircraft weight & balance records & equipment list records revised.

Maintenance Release: The maintenance identified above was inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service. Pertinent details are on file under Work Order Nos. 296A-4 & 296A-7-3

Signature of Authorized Person (

\_\_ Dudley Clark

For FAA Certified Repair Station no. ZP8R849Y

Page 1 of 1 Total Time: 11978.6 Total Cycles: 7121



De

PC

NE

Th

Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

#### The following maintenance was performed:

- Removed Co-Pilot side quick-donning oxygen mask P/N MC10-06-121 S/N 58822. Installed overhauled oxygen mask P/N MC10-06-125 S/N 82785.
- Removed Gen 1 current sensor P/N 524.52.12.720 and installed new sensor unit same P/N in accordance with PC-12 AMM 12-A-24-30-08-00A-920A-A.
- Installed Navigation interface wiring for existing Artex ELT in accordance with Pilatus Business Aircraft drawing PBA.534.132 Rev A.

## FAA AD's checked through Bi-Weekly 2010-25 The following AD's now effective due to installation of Executive Interior arrangement on Dec 16, 2010.

- AD 03-09-11 AFT FACING PASSENGER SEATS Aircraft now in executive interior configuration. AD does not apply by seat part number installed. DeCrane base seat P/N installed is 403150 and is not affected. No action due at this time. Reference Pilatus Service Bulletin SB 25-025.
- AD 07-03-06 EXECUTIVE SEAT PEDESTAL LEGS Aircraft now in executive interior configuration. AD does not apply by seat serial numbers installed. DeCrane Service Bulletin SB05147 Rev D, issued June 26, 2006 checked for affectivity. No action due at this time. Reference Pilatus Service Bulletin SB 25-032.

End of AD compliance listing.

\*\*\*END\*\*\*

All required ground checks for the above maintenance have been completed with satisfactory results. No changes are noted in the aircraft compass system. Aircraft weight change negligible. No change to equipment list records.

Maintenance Release: The maintenance identified above was inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service. Pertinent details are on file under Work Order No. 296A-7-4

Signature of Authorized Person \_

**Dudley Clark** 

For FAA Certified Repair Station no. ZP8R849Y

Page 1 of 1

Total Time: 11978.8 Total Cycles: 7122



Pilatus Business Aircraft, 11755 Airport Way, Broomfield, CO 80021

The following maintenance was performed:

- Reconfigured Cabin Interior from Code # EX-6S-STD-2S to EX-6S-2 - Installed in accordance with PC-12 AMM POH Section 6.

Removed 2 standard seats 7 & 8 and repositioned executive seats 5 & 6 for the EX-6S-2 configuration.

\*\*\* END \*\*\*

The aircraft weight and balance was calculated for this configuration with an update inserted in the POH. No change to equipment list records.

Maintenance Release: The modifications and maintenance identified above have been inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service. Details are on file under Work Order No. 296-4.

Signature of Authorized Person

Qualley Charl

**Dudley Clark** 

For FAA Certified Repair Station No. ZP8R849Y

LANDMARK

6101 Burton Station Rd.

Norfolk, VA 23502

(757) 857-3413

Reference WO#: M01500

	A • 1 A 1 1 0 1.	 	
Aircraft #	N840AG		
Make:	Pilatus	Hobbs	2036.2
Model:	PC-12		
S/N:	296	Date	20 Jan 2011

. Reattached and sealed section of upper left wing outboard deice boot near inflation tube IAW Pilatus PC-12/45 MM 12A-30-14-01

The maintenance operations described above were performed and inspected in accordance with the applicable rules of 4CFR part 43.

**ADiRosa** 

gned Ma

Date: 1-21-201

A&P22406471

Columbia.	tecti, inc.
C. The second of	Experience the Skytech-Advantage

200 Airport Rd. Westminster, MD 21157

Phone: (410) 574-4144 / Fax: (410) 848-6451

 Aircraft Log Entry
 Hobbs: 2064.2
 Registration #: N840AG

 Date: March 4, 2011
 Total Time: 12064.2
 Make/Model: PC12/45

 W/O: DMW-100125
 Cycles: 7183
 S/N: 296

#### Performed a 100-HOUR Inspection:

- Performed a 100 Hour Inspection of this aircraft IAW 14 CFR Part 43, 43.15 and appendix D (as applicable). Utilized the following checklists: Pilatus PC-12 AMM, Chapter 05-20-10 100 Hour Inspection; P&WC PT6A-67B/P EMM, Chapter 72-00-00, Periodic Inspection, 100 hour and Minor inspection items.
- Inspected the ELT per FAR 91.207(d). Battery expiration date is July 2013

#### Complied with the following Special Inspections per Chapter 05-10-00:

- C/W 6 month ice and rain protection airfoil de-icers surface coating.
- C/W 3000 hour/1 year propeller feathering microswitch test.
- C/W 200 hour starter/generator brush inspection IAW Pilatus PC12 MM chapter 24-30-01. 55% brush life remaining.
- C/W 1 year/150 hour flap screw actuator lubrication.
- C/W 1 year corrosion and corrosion preventive compound inspection IAW Pilatus PC12 MM chapter 20-40-00.
- C/W 1 year EPU capacity test.

Total to				
	1	ı	1	
Carry Forward	1	1	1	

Expenence the Skytech Advantage

Phone: (410) 574-4144 / Fax: (410) 848-6451

## Complied with the following Instructions for Continuing Airworthiness:

- Performed ICA for SkyTrac ISAT-100 installation i/a/w SkyTrac Document ISAT-100-OPD-SOI rev.02.01.(Airborne Position Data Communicator Check and Circuit Breaker Check)
- Performed Instructions for Continued Airworthiness on CDP-250G Cockpit Display Panel.

### Complied with the following Service Bulletins (SB's):

• C/W Pilatus SB 55-002, Rev 1 (Ref No. 205) - Replacement of Vertical Stabilizer Shear Plate and Strap. Re-positioned slotted block to the rear face of the strap IAW the SB instructions. No further action required.

### Completed the following additional items:

- Installed new left hand outboard deice boot p/n SMR5221-11 s/n 1101 IAW PC12/45 MM 30-14-01.
- Relocated Flight Display "RS232 IN" from TB111-14 pin C to TB111-13 pin K (#1 GNS430 "RS232 OUT"). Ops check i/a/w Flight Display Systems FD200CPU-& Ver.P Installation and Operation Manual Revision B,May 2008
- Secured LH and RH landing light wire harnesses tye down blocks.
- Installed 5 flood lights in cockpit p/n 1044-06.

I certify that this AIRCRAFT has been inspected in accordance with a Pilatus 100 HR inspection and was determined to be in airworthy condition.

#### MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Perturent details of the repair are on file at this agency under <u>Work Order No</u>:

DMW-100125

Signed \_\_\_\_\_\_CRS# LF/1R294K

for Skytech, Inc.200 Airport Rd. Westminster, MD 21157.



### Aircraft Log Entry

DATE: 5-26-2011 W/O #929

Work Performed:

Removed Hartzell propeller P/N HC-E4A-3D/E10477K S/N: HJ-1056 and installed MT- propeller P/N MTV-27-1-N-C-F-R(P)/CFR260-65a S/N 110124 Blade S/N #1: ABK-41271, #2: ABK-41272, #3: ABK-41273, #4: ABK-41274, #5: ABK-41275 on aircraft Pilatus PC-12-45 S/N 296 Reg # N840AG at 12102.4 AFTT and AFTC 7214.0. Propeller TTSN 0.0 TCSN 0.0 TSO 0.0. IAW MT-Propeller Entwickklung GMBH installation instructions document number E-1824 and Pilatus MM 61-10-01 Rev. 2009-11-12.

Pertinent details of the repair are on file at the repair station under Work Order No. 929

Dated: May 26, 2011

FORM RSM-2010-0010

Signed Thomas.

Tempus Jet Centers

CRS 2PR844B 2TPR844B

1001 Providence Blvd

Newport News VA 23602

Total to
Carry Forward



#### 1370

SEDTE

DATE: June 10, 2011 W/O #<del>929</del> REG# N840AG SERIAL # 296

TOTAL TIME/HOURS: 12,115.4

TOTAL CYCLES: 7,228

#### Maintenance Record

1) Removed upper nose cowl and propeller spinner. Installed Dynamic Solutions Vibration sensor P/N 1880 S/N 149 at the 12 o'clock position on the engine. Reinstalled nose cowl and spinner attached Mini-Beam sensor SM312LVMHSQDM5V P/N 1015 at the 3 o'clock position.

Performed vibration survey in accordance with Dynamic Solutions Systems Inc. MicroVibII Vibration analyzer/balancer users manual P/N 1318.

Readings were within a nominal range (.003 grams at 276 degrees) across the entire RPM range. Removed nose cowl, spinner, vibration sensor, and mini-beam sensor. Reinstalled nose cowl and nose cone spinner in accordance with Pilatus maintenance manual 12-00-00 and MT Propeller

installation instructions Document #E1284.

2) Updated NAV DATA base in accordance with Pilatus AMM Chapter 34-57-00.

3) L/H MLG Indication light was reseated and operational check was performed tested satisfactory.

4) Replaced #2 AHRS Computer with repaired unit:

P/N Off: 124210-2022 S/N Off: 1179 P/N On: 124210-2022 S/N On: 1289

Operational check performed satisfactory in accordance with Pilatus AMM 34-25-00.

5) Replaced cockpit fire bottle with serviceable unit.

P/N Off: BA51015GR-3 S/N Off: 16614

P/N On: N752-1909 S/N On: 001590C

Next inspection due September 13, 2011

Continued to next page

6) Verified Corrosion preventative inspection due September 2011.

6) Verified Corrosion preventative inspection due september of the aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current maintenance rules. The aircraft, airframe, engine, properly of applications and so far as to the work performed is approved for return to service. Pertinent details of the repair are on

Dated: June 10, 2011

**Tempus Jet Centers** 

CRS 2TPR844B

1001 Providence Blvd

FORM RSM-2010-0010 Newport News VA 23602

		1	
:			
Total to Carry Forward			
Carry Forward			



DATE: June 25, 2011 W/O # 1468 REG# N840AG SERIAL # 296

TOTAL TIME/HOURS: 12,137.4

**TOTAL CYCLES: 7,247** 

### Maintenance Record

- 1) Reassembled beverage drawer slider rail in accordance with Pilatus MM 12-A-25-21-05-00A-920-A. Beverage drawer operates normally.
- 2) 275033 Complied with L/H flap actuator lubrication in accordance with Pilatus MM 12-A-27-50-00-00A-902A-A.
- 3) 275034 Complied with R/H flap actuator lubrication in accordance with Pilatus MM 12-A-27-50-00-00A-902A-A.

The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and so far as to the work performed is approved for return to service. Pertinent details of the repair are on file at the repair station under Work Order No. 1370 3570

Dated: June 10, 2011

Signed Tempus Jet Centers

CRS 2TPR844B

1001 Providence Blvd

Newport News VA 23602

FORM RSM-2010-0010



DATE: July 4, 2011 W/O # 1469

REG# N840AG SERIAL # 296

TOTAL TIME/HOURS: 12,140.4

TOTALCYCLES: 7249

#### Maintenance Record

- 1) 200141- Complied with aircraft wash in accordance with Pilatus MM 12-20-01.
- 2) De-icing switch panel backlighting is intermittent Tightened cover screws going to backlight panel in accordance with Pilatus MM 33-10-00.
- 3) L/H AOA found stuck in the up position during Pilot walk around- Removed AOA and installed repaired AOA transmitter and performed operational checks in accordance with Pilatus MM 22-20-00-00A-903A-A, 30-30-20-00A-903A-A and 22-20-02-00A-920A-A operational check satisfactory.

P/N Off: 0012AC9

S/N Off: 0411

P/N On: 0012AC11

S/N On: 0830

4) Updated NAV DATA BASE in accordance with Pilatus AMM CH 34-57-00. NAV DATA Base expires 28 July 2011

The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and so far as to the work performed is approved for return to service. Pertinent details of the repair are on file at the repair station under Work Order No. 1469

Dated: July 4, 2011

Signed

Tempus Jet Centers

CRS 2TPR844B

1001 Providence Blvd

Newport News VA 23602

FORM RSM-2010-0010

Carry Forward



DATE: July 7, 2011, 2011 W/O # 1493 REG# N840AG SERIAL # 296 Maintenance Record

TOTAL TIME/HOURS: 12,149.6

TOTAL CYCLES: 7,254

1) Replaced pusher light bulb in accordance with Pilatus MM 31-11-01-00A-920-A.

2) Nose wheel shimmies on landings – found nose tire pressure low serviced tire to 60 PSI in accordance with Pilatus MM 12-A-12-10-04-00A-

The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and so far as to the work performed is approved for return to service. Pertinent details of the repair are on

Dated: July 7, 2011

Signed

Tempus Jet Centers

CRS 2TPR844B

1001 Providence Blvd

Newport News VA 23602

FORM RSM-2010-0010

9) 790011 Complied with an engine magnetic chip detector bridge inspection. Inspected and reinstalled in accordance with Pratt & Whitney Canada EMM 72-00-00. 10) Updated 3 each NAV Data Bases new Data Bases expiration date 25 Aug. 2011. 11) Complied with 100 hour oil sample and shipped out to Aviation Laboratories in accordance with Pratt & Whitney Canada EMM 79-20-02. The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and so far as to the work performed is approved for return to service. Pertinent details of the repair are on file at the repair station under Work Order No. 1567. Dated: August 2, 2011 **Tempus Jet Centers** CRS 2TPR844B 1001 Providence Blvd N840AG S/N 296 Newport News VA 23602 Page 2 FORM RSM-2010-0010 Total to Carry Forward

Registration	No.	
--------------	-----	--

Performed ICA for SkyTrac Airborne Position Data Clinc document ICA08013-1 dated February 19, 2008.      Order of Broader Chack IAV	Communicator Check IAW Avionics Design Services	
<ul> <li>1 dated February 19, 2008.</li> <li>Performed ICA for SkyTrac GPS/Iridium Antenna insta ICA08013-1 dated February 19, 2008.</li> <li>Performed ICA for SkyTrac Cockpit Display Panel IAW 1 dated February 19, 2008.</li> <li>Checked operation of landing lights IAW Pilatus discrepancy noted</li> </ul>	W Avionics Design Services Inc document ICA08013- tallation IAW Avionics Design Services Inc document  W Avionics Design Services Inc document ICA08013- s PC12/45 AMM 12-A-33-41-00-00A-040A-A. No er p/n 959.90.22.128 IAW Enviro Systems Inc CMM  V45 AMM 12-A-30-10-00-00A-313A-A. Found small s IAW BF Goodrich Pinhole Repair kit # 74-451-AE. Pilatus PC12 MM Chapter 33-46-01.	
The aircraft and/or component identified above was reparted to the repair are on file of the rep	worthy for return to service with respect to the e at this agency under <b>Work Order No:</b> for Skytech, Inc.200 Airport Dr.	

at



200 Airport Dr. Westminster, MD 21157

Phone: (410) 574-4144 / Fax: (410) 848-6451

Registration #: 840AG Hobbs: 2217.6 Aircraft Log Entry

Make/Model: PC12/45 **Total Time: 12217.6** Date: September 1, 2011

S/N: 296 DMW-100446 W/O: Cycles: -----

The Altimeter(s) Static and Altitude Reporting Systems test as required by FAR 91.411 in accordance with FAR 43 Appendix E have been performed. Altimeters tested: L/H Model KEA 346 S/N 4197Tested To 30000 feet S/N 29639Tested To 30000 feet

The ATC transponder tests and inspections as required by FAR 91.413, in accordance with FAR 43, Appendix F have been performed. Transponders tested:

#1 Model KT 70 S/N 30487 #2 Model KT 70 S/N 30303

R/H Model 5035P-P50

- Altimeter and static system test required by 14 CFR 91.411 and transponder test, including data correspondence, required by 91.413, have been performed and found to comply with 14 CFR part 43, appendix E and F.
- C/W 1 year main landing gear axle and bushings inspection.
- C/W 1 year/1000 hour autoflight servo clutch inspection.
- C/W 1 Year/1000 hour/1300 landings flap actuator backlash inspection.
- C/W 1 year/3000 hour horizontal stabilizer trim runaway aural warning system test.
- C/W 1 year wheel bearing lubrication.
- C/W 6 month ice and rain protection airfoil de-icers surface coating
- C/W 1 year external corrosion and corrosion preventive compound inspection.

		<u>, , , , , , , , , , , , , , , , , , , </u>	
10	ī	1	
Carry Forward			

Tkylech, in ce the Skytech-Advantage 200 Airport Drive, Westminster, Maryland 21157

Phone: (410) 574-4144 / Fax: (410) 780-4439

**Engine Log Entry** 

September 23, 2011 Date:

DMW-100461 W/O:

Hobbs: 2248.7 Total Time: 11408.9

Cycles: 8741 TSO: 2307.4 Registration #:

**N840AG** Make/Model: PT6A-67B

S/N: PCE-PR0132

Performed a 100-HOUR Inspection:

Performed an Annual/100 Hour Inspection of this engine IAW 14 CFR Part 43, 43,15 and appendix D (as applicable). Utilized the following checklists: Pilatus PC12 AMM, Chapter 05-20-20 - Annual Inspection; P&WC PT6A-67B/P EMM, Chapter 72-00-00, Periodic Inspection, 100 hour and Minor inspection items.

#### Complied with the following Special Inspections per Chapter 05-10-00:

- C/W 1 year/200 hour spark igniter inspection.
- C/W 1 year/600 hour chip detector inspection.
- C/W 100 hour power recovery and turbine wash.
- C/W 100 hour FCU/reverse cam linkage and rod end inspection.
- C/W 100 hour oil filter inspection.
  - C/W 200 hour P3 filter cleaning.
- C/W 200 hour power turbine blade in-service inspection.
- C/W 400 hr fuel nozzle inspection and borescope inspection per the P&WC PT6A-67B/P MM chapters 73-11-05 and 72-00-00. Fuel nozzle inspection/repair performed by Skytech, Inc CRS C41R727N, w/o UZA100312.
- C/W 600 hour fuel pump outlet filter change by installing new filter p/n AN6235-3A.

C/W 600 hour fuel pump inlet screen inspection.

Complied with the following Airworthiness Directives (AD's):

AD notes checked thru bi-weekly 2011-18. See AD log dated September 23, 2011.

Completed the following additional items:

kytech, Experience the Skytech-Advantage 200 Airport Drive, Westminster, Maryland 21157

Phone: (410) 574-4144 / Fax: (410) 780-4439

- C/W 100 hour power recovery and turbine wash.
- C/W 100 hour FCU/reverse carn linkage and rod end inspection.
- C/W 100 hour oil filter inspection.
- C/W 200 hour P3 filter cleaning.
- C/W 200 hour power turbine blade in-service inspection.
- C/W 400 hr fuel nozzle inspection and borescope inspection per the P&WC PT6A-67B/P MM chapters 73-11-05 and 72-00-00. Fuel nozzle inspection/repair performed by Skytech, Inc CRS C41R727N, w/o UZA100312.
- C/W 600 hour fuel pump outlet filter change by installing new filter p/n AN6235-3A.
- C/W 600 hour fuel pump inlet screen inspection.

#### Complied with the following Instructions for Continuing Airworthiness:

Performed ICA for MT Propeller installation (100 hour visual inspection) IAW MT-Propeller E-1083 Issue 16 dated September 16, 2010.

#### Complied with the following Airworthiness Directives (AD's):

AD notes checked thru bi-weekly 2011-18. See AD log dated September 23, 2011.

#### Completed the following additional items:

- Inspected the ELT per FAR 91.207(d). Battery expiration date is July 2013.
- Adjusted # 1 generator voltage regulator IAW Pilatus PC12/45 AMM 12-A-71-00-00-00A-903A-A.
- Removed NLG shimmy damper assy p/n 532.20.12.215 s/n IL-216 and installed repaired shimmy damper assy p/n 532.20.12.215 s/n AM098 IAW PC12 AMM Ch 32-50-01. Shimmy damper repaired by Pilatus business aircraft, cert# ZP8R849Y ref w.o. B9511.
- Located and repaired intermittent connection of ground stud on pilot's RH lower switch panel lighting system IAW AC43.13-1B, chapter 11, section 8.
- Rotated both wing aileron center control pushrods rods 180 degrees due to wear at guide rollers. Work performed IAW Pilatus PC12/45 AMM 12-A-27-00-00-00A-313A-A.

cytech, Experience the Skytech-Advantage 200 Airport Drive, Westminster, Maryland 21157

Phone: (410) 574-4144 / Fax: (410) 780-4439

MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pertinent details of the repair are on file at this agency under Work Order No. DMW-100461

for Skytech, Inc., 200 Airport Dr., Westminster, MD 21157.

found in Englog for SNPCE-PROBZ

KELISTI		200 Airport Drive, We	stminster, wery
1 - AT		Phone: (410) 574-41	44 / Fax: (410) 780-4439
Experience the Skytech-Advantage		41 am #1	N840AG
Hobbs:	2240.1	Registration #: Make/Model: S/N:	PC12/45
Aircraft Log Entry  Aircraft Log Entry  Total Time: Cycles:	7342		
Date: September 23, 2011 Cycles:  N/O: DMW-100461  Performed an ANNUAL Inspection: Performed an Annual Inspection of this aircraft IAW 14  Performed an Annual Inspection of this aircraft IAW 14	CFR Part 43, 43.15 and	appendix D (as appli P&WC PT6A-67B/P E	icable). Utilized the MM, Chapter 72-00-
Date: DMW-100461  N/O: DMW-100461  Performed an ANNUAL Inspection:  Performed an Annual Inspection of this aircraft IAW 14 following checklists: Pilatus PC12 AMM, Chapter 05-20 following checklists: Pilatus PC12 AMM, Chapter 05-20 following checklists: Pilatus PC12 AMM, Chapter 05-10 following checklists: Pilatus PC1	-20 - Almuai more ems. <b>0-00:</b>		
00, Periodic May Special Inspections per Chapter Special Inspections per Chapter Special Inspections per Chapter Special Inspection in the Compiled with the following Special Inspection in the Compiled With the following Special Inspections per Chapter Special Inspection in the Chapter Special Inspection In			
C/W 400 hour generator 2 5/55  C/W 400 hour generator 2 5	d battery #2 capacity chec	ks.	
a seth ice and fall prove			
C/W 6 month/100 hour Er o date and corrosion preventive	compound inspection.		
C/W 1 year/150 hour flap screw actuator lubrication.			
<ul> <li>C/W 1 year/500 hour torque limiter test.</li> <li>C/W 1 year/500 hour torque and stick pusher transducer el</li> <li>C/W 12 year fire bottle replacement. Removed and replacement. Removed and replacement. It least tip test due October 2023.</li> </ul>	ectrical connector cleanin	ig. <sub>extinguisher with new</sub>	unit p/n C352CS.
C/W 12 year fire bottle replacement. Removed and replacement.     C/W 12 year fire bottle replacement. Removed and replacement.     C/W 12 year fire bottle replacement. Removed and replacement.	,ou ====1		

CW 1 year/600 hour chip detector inspection.

Next page

Next hydrostatic test due October 2023. C/W 1 year/200 hour spark igniter inspection.



200 Airport Drive, Westminster, Maryland 21157

Phone: (410) 574-4144 / Fax: (410) 780-4439

- Fabricated and installed new NLG wheel well ground strap IAW A.C. 43.13-1B chapter 11.
- Relabeled Copilot's Generator 1 Bus IAW PC12/45 IPC 12-A-11-30-00-16B-941A-A.
- Installed red safety thread on DV window emergency release handle IAW Pilatus PC12/45 MM 12-A-56-14-01-00A-920B-A.
- Serviced oxygen system with Aviator's Breathing Oxygen IAW Pilatus PC-12 MM chapter 12-10-05-03.
- Secured static line support under center floor with 2 part epoxy.
- Rigged the roll servo bridle cable IAW Pilatus PC12 MM Chapter 27-10-00.
- Rigged the rudder control system per the Pilatus PC-12 AMM chapter 27-20-00-05.
- Rigged the yaw servo bridle cable IAW Pilatus PC12 MM Chapter 27-20-00.
- Rigged the pitch servo bridle cable IAW Pilatus PC12 MM Chapter 27-30-00.
- Replaced one floodlight bulb on pilot's circuit breaker panel with new p/n 972.73.19.109 per AMM ch.33.
- Repaired pin hole leaks in LH elevator utilizing the BF Goodrich pin hole repair kit p/n 74-451-AE. Work done IAW the BF
- Inspected crew and passenger seat belt assemblies for manufacture dates. Pilot and Copilot May 2010, Passengers 1 thru
- Removed NAV Converter KN40 p/n 066-01130-0701, s/n 11442. Installed modified KN40 p/n 066-01130-0701, s/n 12185 (Honeywell International (PR2R093L), w.o.#AK5167). Performed check GNS 430 and GNS 530 accuracy of VOR, Localizer and Glideslope IAW Garmin GNS 400/500 series Installation manual 190-00356-02, rev.G, 2008.
- Adjusted Nf Governor RPM setting IAW Pilatus PC12/45 AMM 12-A-71-00-00-00A-903M-A.
- Cleaned and polished propeller deice sliprings using LPS electrical contact cleaner.

I certify that this AIRCRAFT has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy

Next page

Total to	 _
Carry Forward	_

Registration No. $\_$	
IV-B	200 Airport Drive, Westminster, Maryland 21157
1.climin.	Phone: (410) 574-4144 / Fax: (410) 780-4439
Expenence the Skytech-Adventage  Adjusted Nf Governor RPM setting IAW Pilatus PC12/45 AM  Adjusted Nf Governor RPM setting IAW Pilatus PC12/45 AM  Adjusted Nf Governor RPM setting IAW Pilatus PC12/45 AM	1M 12-A-71-00-00-00A-903M-A.
- i-a has peen mer	
IANCE RELEASE  General or component identified above was repaired and improve and or component identified above with respect to the work per	ted in accordance with current Federal Aviation Regulations formed. Pertinent details of the repair are on file at this
s found airworthy for return to service with services found airworthy for return to service with services are services with services and services with services are services and services with services are services are services with services are services are services are services are services and services are se	t Dr., Westminster, MD 21157. CRS# LF1R294K
J. G. S. Ioi en,	

at

\_

=



DATE: 12/04/11 W/O #: PHF- 62 REG#:N840AG SERIAL # 296 TOTAL TIME/HOURS: 12345.2 TOTAL CYCLES: 7433

#### MAINTENANCE RECORD

- 210015 Vapor cycle Cooling System 15 Min Run (Cold Season Only). Complied with code 210015 Vapor cycle Cooling System 15
   Min Run (Cold Season Only) run.
- 2) Code 050200 100 Hour Inspection Part 91.409 (b) Complied with 100 hour Airframe Inspection IAW FAR 914.409 (b) and Pilatus AMM 05-20-10-00A-281A-A.
- 3) 324026.1 Removed and replaced L/H Main Gear landing gear Tire IAW Pilatus GMM 12-A-32-40-01-00A-920A-A.

P/N OFF: 021-350-0

P/N ON: 021-350-0

S/N OFF: 6130W00274

S/N ON: 1006S00341

4) 324026.2 Removed and replaced R/H Main Gear landing gear Tire IAW Pilatus GMM 12-A-32-40-01-00A-920A-A.

P/N OFF: 021-350-0

P/N ON: 021-350-0

S/N OFF: 4056W00107

S/N ON: 1005S00424

5) 324016 Removed and replaced Nose Gear landing gear Tire IAW Pilatus GMM 12-A-32-40-02-00A-920A-A.

P/N OFF: 175K88-2

P/N ON: 175K88-2

S/N OFF: 50560221

S/N ON: 5788-1

6) 344160 Removed and Replaced XM weather Receiver IAW Bendix /King KMD 550/850 FIS Guide 006-18237-0000 Rev 6 Dated

CONTINUE

Feb/2009.

No further defects noted at this time.

P/N OFF: 4092743-902

P/N ON: 4092743-902

S/N OFF: 33916419

S/N ON: 818000490

Registration	No.	

Removed and reinstalled Co-pilots seat IAW Pilatus GMM 12-A-25-10-01-00A-920A-A. No further defects noted at this time.

P/N OFF: 959.30.01.132

P/N ON: 959.30.01.132

S/N OFF: 432

S/N ON: 432

- 721015 Complied with Engine 100 Hour inspection in accordance with FAR Part 91.409 (a) and Pratt & Whitney Canada EMM 72-00-00.
- 9) 610005 Complied with a 100 hour inspection in accordance with MT Propeller MM 61-00-83/24/06/2009.
- 10) Edge sealed R/H wing de-ice boot with Sealant PR1422B-2 Pt. No. P08-018 IAW AMM 12-A-30-14-01-00A-920A-A.
- 11) Edge sealed L/H wing de-ice boot with Sealant PR1422B-2 Pt. No. P08-018 IAW AMM 12-A-30-14-01-00A-920A-A
- DME #2 will be MEL'd IAW with the Orion Air Group MEL pg 34-13 item 34.11 Distance Measuring Equipment Systems. MEL Compliance date will be 14 Dec 2011.
- Co-Pilot's EADI will be MEL'd IAW with the Orion Air Group MEL pg 34-2 item 34.3 Attitude Heading Reference System (AHRS).

  MEL Compliance date will be 14 Dec 2011.
- Aircraft De-icing system will be MEL'd IAW with the Orion Air Group MEL pg 30-1 item 30.2 Surface Deice System. MEL Compliance date is 14 Dec 2011.
- Passenger seats configured to "STANDARD" arrangement IAW AMM 12-A-25-22-01-00A-920A-A Weight and Balance Calculation adjusted For Interior Code # EX-6S-2 Seating Configuration.

The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and so far as to the work performed is approved for return to service. Pertinent details of the repair are on file at the repair station under Work Order No. PHF- 62.

Dated:

Signed

**Tempus Jet Centers** 

CRS 2TPR844B

1001 Providence Blvd

Newport News VA 2360

FORM RSM-2010-0010

MODEL: SERIAL: HOUR METER: Troubleshoot gear system and found relay K601 badr serviceable unit (s/n on: R463/tis: 0.0) IAW AMM PC12 check good C/w ops check of all deice system AMM12-A-30-10-00-00A-903A-A(AIRFOILS)/12-A-30-6 relamped both landing lites (4596) and "GREEN) indicate	PILATUS WORK PACKAGE: T9347 PC12/45 TACH TIME: 12354.0 12354.0 TOTAL CYCLES/LANDINGS: 8839 replaced relay (974.09.26.112)(s/n off: P250) and installed wDM 29-10-00 and AMM 12-A-29-00-00-00A-903A-A, opsition lites (CM6839) IAW AMM 12-A-31-11-01-00A-920A-A, hecked to .008 IPS IAW AMM 12 A 61.00.00 and a control in the con	
The aircraft, airframe, engine, propeller or appliance iden current regulations of the Federal Aviation Administration repair are on file at this repair station under work package.  Signed:  Signed:  EDUA  Carry Forward	and is a lifer return to service. Pertinent details of the T9347  ARDOR. VARGAS	

	Registration	No			
EPPS:	AIRCRAFT REG: MFG: MODEL: SERIAL:	PILATUS PC-12/45	DATE: Work Package #.	12/13/2011 A5027	te No.
Photo Control of the	HOBBS/TACH	12354.0	TOTAL TIME:		
	DESCRIPTION OF WOR	RKCOMPL	ETED:		ik.
REMOVED BENDIX/KING KN4 S/N 12333. CHECKS GOOD IA	J PIN 066-01130-0701, SIN W KN40 I.M.	N 12185 AN	ID INSTALLED EXCHANG	EUNIT, SAME P/N,	э.
The aircraft, airframe, engine, propertient regulations of the Federal Pertinent details of this repair are	Aviation Administration and on file at this repair station Signed  For £2 Services	d is approve under work ee Seracus	ed for return to service.  A package No. A5027  e  AA CRS # ESMR688D,	n accordance with	

∌t

Date		Aircraf	t Time Recorder		Maintenance		
		This Date	Total	Reading	Waintenance	and	
		Brought ->					Weather Radai !012.
				iviaintenan	се кесога		
	Date: Decer	nber 23, 2011					certify all ma only for the w
1	Aircraft Mal	ke/Model: Pilatus F	PC 12/45	Aircraft TT:	12379.6		
	Aircraft Seri	ial Number: 296		Landings: 74	160		
1	Description	Of Work Performe	d:			`	ate: <u>Decer</u>
_						1	
1) Removed and replaced R/H Pitot static probe IAW Pilatus AMM 12-A-34-11-11-00A-920A-A. Performed Ops test IAW Pilatus AMM 12-A-34-11-20-00A-903A-A and 12-A-30-30-20-00A-903A with no defects noted at this time.  P/N OFF: 9651112302 P/N ON: unk  S/N OFF: PST305 S/N ON: 16140902  2) Removed and replaced #2 generator control unit IAW Pilatus AMM 12A-24-30-06-00A-920A-A and 12-A-71-00-00-00A-903A-A with no defects noted at this time.  P/N OFF: 9882115103 P/N ON: 9882115103  S/N OFF: 10185 S/N ON: 10025							gnature:
	time P/N OF	FF: 9728787322 F: 21666	P/N ON: 9728787322 S/N ON: 44221		920B-A. No defects noted at this		
Total to Carry F	o Forward						
2							

	Registrati	ion No			
and  Neather Ra	dar is MEL'D IAW Orion Air Group MEL Pilatus	s MEL dated 02/05/11 Rev 2 page	<b>1</b> 34-11 item 8 and will expire on Jan	1,	te No.
certify all m	aintenance and inspections have been accom ork performed. For details of work performe	plished IAW FAR 43.9 and the airced reference work order PHFN-17.	raft is approved for return to service	2	
ate:Decemb	Br 7, C. Bainson . AP! 360				Sa.
gnature:	100 DAMAN PAR. 3600	03471	I		
<u></u>					

at

	AINONALI	LOG		
Date	Maintenance	Record		
	Date: January 2, 2012			
	Aircraft Make/Model: Pilatus PC12-45	Aircraft TT: 12388.	3	
	Aircraft Serial Number: 296	Landings: 7469		
	Description Of Work Performed:			
	1. Removed and Replaced the KMD 540 N	fultifunction display of	ld PN 066	
	04035-0101/SN 5842 with new PN 066-04	035-0101/SN 8873 1A	W Honorman	
	installation Manual 006 10608 0012 and the	033-0101/310 00/3 IA	w noneywen	
	installation Manual 006-10608-0012 and the	ie KAC 503 Flight inf	ormation	
	system module card old PN 071-00168-03	11/SN 3219 with new	PN 071-00168-	
	0311/SN 2478 IAW Honeywell installation	n manual 159-08288-5	010 and the	
	KAC 501 Digital Weather Radar Module	old PN 071-00159-011	1/SN3730 with	
	new PN 071-00159-0111/SN 4867 IAW H	oneywell installation	manual 150	
	08288-5010, ck good.	was motanianon	manual 139-	
		a hava ka		
	I certify all maintenance and inspection FAR 43.9 and the aircraft is annual to	s have been accompl	ished IAW	
	FAR 43.9 and the aircraft is approved f	or return to service of	only for the	
	performed. For details of work n	erformed reference i	on repair	
	station work order PHF-27.			
	<b>D</b>			
	Date: <u>January 2, 2012</u>			
		M		
	Signature: Morris Banda	LAD RES	200 0	
Total to		MAY 337	2920	
Carry Forward				
		<u> </u>		

#### Dedictration No.

and	Maintenance Date: January 6, 2012	Certificate No.	
	Aircraft Make/Model: Pilatus PC12-45 Aircraft Serial Number: 296 Description Of Work Performed:  1. Removed and Replaced the Generator 2 100064 with overhauled PN 524.32.12.158/ 30-32, op ck good.  I certify all maintenance and inspections I FAR 43.9 and the aircraft is approved for work performed. For details of work performed station work order PHFN-32.	have been accomplished IAW	
	Date: January 6, 2012  AM  Signature: Adam McMullin AR 3060798	Chan huhlan	at is



200 Airport Drive, Westminster, Maryland 21157

Phone: (410) 574-4144 / Fax: (410) 780-4439

Aircraft Log Entry

Date:

February 21, 2012

W/O: DMW-100673

Hobbs: 2445.6

**Total Time: 12445.6** 

**Cycles: 7523** 

Registration #: N840AG

Make/Model: PC12/45

S/N: 296

Performed a 100-HOUR Inspection:

Performed a 100 Hour Inspection of this aircraft IAW 14 CFR Part 43, 43.15 and appendix D (as applicable). Utilized the following checklists: Pilatus PC-12 AMM, Chapter 05-20-10 - 100 Hour Inspection; P&WC PT6A-67B/P EMM, Chapter 72-00-00, Periodic Inspection, 100 hour and Minor inspection items.

#### Complied with the following Special Inspections per Chapter 05-10-00:

- C/W 500 hour cold air unit lubrication.
- C/W 500 hour secondary heater thermal protection switch test.
- C/W 500 hour water separator condenser cleaning.
- CW 6 month ice and rain protection airfoil de-icers surface coating.
- C/W 1 year EPU capacity test.
- CW 6 month external corrosion and corrosion preventive compound inspection.
- C/W 3000 hour/1 year propeller feathering microswitch test.
- C/W 2 year Gen 1 and Gen 2 ground point inspection.
- C/W 4 year/1000 hour fuel low level warning operational test.
- C/W 14 day vapor cycle 15 minute run.
- C/W 200 hour starter/generator brush inspection.
- C/W airframe exterior wash.
- C/W 1 year/200 hour spark igniter inspection
- C/W 1 year/600 hour chip detector inspection
- C/W 100 hour oil filter inspection.

	•			*	
Total to		1	'n		
Carry Forward					

Registration	No.	
--------------	-----	--

=

Consultation of the consul	Experience the Skytech-Advantage	200 Airport Drive, Westminster, Maryland 21157 Phone: (410) 574-4144 / Fax: (410) 780-4439
•	C/W 100 hour power recovery and turbine wash. C/W 200 hour power turbine blade in-service inspection.	
molied	with the following Instructions for Continuing Airworthiness:	
•	Performed ICA for SkyTrac ISAT-100 installation IAW SkyTrac Document Data Communicator Check and Circuit Breaker Check)	
•	Performed ICA for CDP-250G Cockpit Display Panel IAW Sky Trac System	s Document DOC0111 Rev 01.007.
•	Performed ICA for MT propeller installation IAW MT-Propeller E-1083 Issue	e 16, dated September 16, 2010.
mplied	with the following Airworthiness Directives (AD's):	(2.2.)
•	AD 2011-21-08 Sicma Aero Seat Backrest Link Replacement does not app further action required.	ly by passenger seat manufacture (DeCrane). No
•	AD notes checked thru bi-weekly 2012-02. See AD log dated February 21,	2012.
mpleted	the following additional items:	i varaden
•	Removed ART2000 p/n 071-01519-0101, s/n 8635. Installed overhauled A Aviation, JGVR194F, w.o. 14P0A). Also found KMD850 MFD p/n 066-040 Radar Module KAC 501. Removed KAC501 p/n 071-00159-0111, s/n 486 s/n 2760 (Honeywell International, PR2R093L, w/o AL1695). Ops checks sa	7. Installed tested KAC501 p/n 071-00159-0111, atisfactory.
•	Performed KAS297C altimeter alignment IAW Honeywell KAS297C Installa	tion Manual 006-00686-0002, rev.2, April 1997
•	"ATT2" and "HDG2" flags will display on copilot EADI when the AHRS # 2 No action taken at this time.	
•	Installed five new rivets p/n CR2343-4-3 rivets on lower Left flap skin (betw 1B Chapter 4 section 4.	
•	Installed new 3M anti-chafe tane #5423 on both LH and RH engine cowling	door frames.
•	leadalled new propeller reversing cable beta feedback block p/n A3026 IAW	PC12-45 MM Chapter 61-20-02.
•	Adjusted engine intake plenum adjacent to AGB bosses at 9 o'clock and 7o'	clock positions to avoid further chaining.
	Secured condition lever cable to oil breather tube at plenum with high temp.	tye-wraps.

at

is

M Rev. 1

200 Airport Drive Man

--- Pemarks

TT: 12468.9



A/c: N840AG S/N: <sup>296</sup>

**Cycles:** 7542

Date: 3/8/12

- Installed new middle prop de-ice brush block p/n 3E2011-1. Installed new wire harness p/n 2H1703-4.
  - Cleaned and inspected brush block/MOV module and slip rings. Checked brush alignment on slip rings. No discrepancies noted. Operational check of prop heat per Pilatus MM satisfactory. All blades heat normally and no problems noted at the brush block assembly.

I certify that all work has been performed in accordance with Pilatus maintenance publications and the current regulations of the FAA. This aircraft is approved for return to service only for the work performed.

Man hully ASP 3060798

ory.

utago

Carry Forward

ard

		1-1	200 Airport D	rive, Westminster, Maryland 21157
£	Chijle	Experience the Skylech-Advantage	,	) 574-4144 / Fax: (410) 780-4439
- I	Fabricated a s brushes to slip	shim for the propeller deice brush bl rings IAW PC12-45 MM Chapter 30-6	lock assembly utilizing .032" sheet alumin 60-02.  e with a 100-HOUR inspection and was d	
l	The aircraft and/or comport and was found airworthy for agency under Work Order  Signed	or return to service with respect to the No: DMW-1000673	d inspected in accordance with current Fedowork performed. Pertinent details of the re  O Airport Dr., Westminster, MD 21157.	eral Aviation Regulations pair are on file at this  CRS# LF1R294K
	•	N840AG	SN 296	HM 2468.3
)12				
viced l	eft and right main l	anding gear tires and nose	wheel tire to required manufac	cturers specifications with nitroge
			udar Daaltaga Has Reen Insnec	ted And The Item(s) Are Approversions and The Item(s) Are Approversions are the contract to th
	$\circ$			
D A	Lba dbell	TION, GREER, SC 2965		

rry Forward

Registration No. \_\_\_\_\_

and Remarks	Signature	Certificate No.
· AD97-22-08 on AFM Rev. 15 N/A	Ð	
was manufactured after release of		
AD and AFM Rev. was included		
at manufacture.		
0 AD98-05-06 on Fleur tor Rivet	<u> </u>	
length is NA by S/N and	4/16/2017	
date of man wacture of All		
· AD 74-08-04 R3 on Lau waste	Kaul	A+733390
Receptacles is NA since AC	Marle	
is Normal Catagory northous port		

Date This Date Total Experience the Skytech-Advantage

**Aircraft Time** 

Recorder Reading Maintenance

200 Airport Drive, Westminster, Maryland 21157

Complie

Comple

MA

Phone: (410) 574-4144 / Fax: (410) 848-6451

Aircra	ft Log Entry		N840AG	W/C	D: DMW-100814
Aircraft:	PC12/45	S/N:	296	ACTT:	Date. April 20, 2012
Engine:	PT6A-67B	S/N:	PCE-PR0132		147000 HOBBS: 2548.1
Propeller:	MTV-27-1-N-C-F-R		110124	PTSN:	

Performed a 100 Hour Inspection of this aircraft IAW 14 CFR Part 43, 43.15 and appendix D (as applicable). Utilized the following checklists: Pilatus PC-12 AMM, Chapter 05-20-10 - 100 Hour Inspection; P&WC PT6A-67B/P EMM, Chapter

### Complied with the following Special Inspections per Chapter 05-10-00:

- C/W 6 month ice and rain protection airfoil de-icers surface coating.
- C/W 6 month/100 hour EPU check.
- C/W 6 month external corrosion and corrosion preventive compound inspection.
  - C/W 1 year fire extinguisher weight/contents check.
- C/W 1 Year/1000 hour/1300 landings flap actuator backlash inspection.
- C/W 1 year/150 hour flap screw actuator lubrication.
- C/W 1 year/200 hour spark igniter inspection.
- C/W 1 year/600 hour chip detector inspection.
- C/W 100 hour power recovery and turbine wash.
- C/W 100 hour FCU/reverse cam linkage and rod end inspection.
- C/W 100 hour oil filter inspection.
- C/W 200 hour P3 filter cleaning.
- C/W 600 hour fuel pump outlet filter change by installing new filter p/n AN6235-3A.

### Complied with the following Instructions for Continuing Airworthiness:

Performed ICA for MT propeller installation (100 hour visual inspection) IAW MT-Propeller E-1083 Issue 16 dated September 16, 2010.

Experience the Skytech-Advantage

Phone: (410) 574-4144 / Fax: (410) 848-6451

at


is

Complied v	with the following Airworthiness Directives (AD's):		1 1 0 -
•	C/W AD 2001-25-10 - Prevent Current Surges in the Flap Control System (Effect actuators for correct end-play and backlash per paragraph (d)(5) of AD 2001-2011	ctive date: Jan 25, 2002). In -25-10. Next inspection due	spected flap at 13148.1
•	ACTT. AD notes checked thru bi-weekly 2012-07. See AD log dated April 20, 2012.		
Completed	the following additional items:		
•	Installed new oxygen discharge indicator disk p/n 171-10 IAW Scott Ove	erboard Discharge Indicator	Installation
•	Instructions. Installed new LH wing inboard fuel sump drain valve p/n 115.55.07.209 and o-MM chapter 28-00-00.		
•	Removed air conditioning drive motor s/n 2684 and installed overhauled drive Systems, w/o S41370, crs BD2R712K) IAW Enviro Systems component MM Chaper the Pilatus PC-12 AMM chapter 21-50-00.	e motor p/n 1134104-1 s/n 4 apter 21-00-23. Adjusted the	628 (Enviro belt tension
•	Removed FCWU s/n 112261. Installed an inspected (Pilatus Business Aircraft p/n 978.73.20.016 s/n 108914 IAW Pilatus PC12 MM chapter 27-50-05.		729) FCWU
•	Installed new tail beacon bulb p/n 34-0226010-91 IAW Pilatus PC12 MM chapter	r 33-46-01.	
•	Installed new flood light bulbs on pilot side 2 ea. p/n 1044-06 IAW Pilatus PC12 I Removed foot heater control relay s/n P273 and installed new relay p/n 974.09. chapter 21-40-00.	.26.111 s/n N693 IAW Pilatu	s PC12 MM
certify that t	this AIRCRAFT has been inspected in accordance with a 100-HOUR inspection and	d was determined to be in air	worthy condition.
The aircraft was found a	NCE RELEASE It end/or component identified above was repaired and inspected in accordance with airworthy for return to service with respect to the work performed. Pertinent details our No: DMW-100814	n current Federal Aviation Re of the repair are on file at this	gulations and agency under
Signed —	for Skytech, Inc., 200 Airport Dr., Westminster, MD	21157.	CRS# LF1R294K
	1		ı

- 1	Aircraft Date:	Log Entry April 20, 2012	Hobbs:	2548.1	Registration #:	N840AG
- 1	W/O:	DMW-100814	Total Time: Cycles:		Make/Model: S/N:	and or total
	•	Secured connector P58	2 at starter control unit. Starter OF	'S check well.		
	The aird and was	Craft and/or component ide s found airworthy for retur under Work Order No: D	entified above was repaired and insolution to service with respect to the work MW-100814	spected in accordance wi k performed. Pertinent de	th current Federal Avia etails of the repair are c	ition Regulations on file at this
	Signed	/ full =	for Skytech, Inc.200 A	irport Dr. Westminster, M	ID 21157.	CRS# LF1R294K
)12			N840AG	SN 296		HM: 2572.9
νi	iced tire	s as needed.				
fy T	That The	e Maintenance Ide	ntified In This Work Ord Of The Repair(s) Are O	ler Package Has E n File At This Ag	Been Inspected A gency Under Wo	And The Item(s) Are ork Order Number C
ify T 1 To (	That The	e Maintenance Ide e. Pertinent Details	Of the Repair(s) Are O	n File At This Ag	Been Inspected A gency Under Wo	And The Item(s) Are ork Order Number C
tify Ton To	That The Service	e Maintenance Ide e. Pertinent Details	ntified In This Work Ord Of The Repair(s) Are O IN GREER, SC 29651	n File At This Ag	Been Inspected Agency Under Wo	And The Item(s) Are ork Order Number C

at

is





Aircraft Log Entry Hobbs: 2,593.5 Registration #: N840AG Date: May 23, 2012 Total Time: 12.593.5 Make/Model: PC12/45 W/O: UZA-100569 Cycles: 7,626 S/N: 296

FCWU failure. Troubleshot and found FCWU to be inop. Removed carpet and floorboards for access. Removed FCWU99-3 PN- 978.73.20.016 SN- 108914 and installed inspected FCWU99-3 PN- 978.73.20.016 SN- 108920. Performed flap system set procedure, flap asymmetry, flap twist and flap functional tests. Performed functional check of extension and retraction system. Reinstalled carpet and floorboards. All work performed IAW Pilatus PC-12 MM. CH. 27

MAINTENANCE RELEASE

The aircraft apd/or/component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pertinent details of the repair are on file at this agency under Work Order No: UZA-100569 for Skytech, Inc., PO Box 37507, Rock Hill, SC 29732. CRS# C41R727N

For 909 Page 1 of 1

C/W 600 hour fuel pump outlet filter change by installing new filter p/n AINb235-3A.

C/W 30 day cockpit/cabin fire extinguisher inspection.

	Sigtection				200 Asport Unive, Western (410) 848-6451 Phone: (410) 574-4144 / Fax: (410) 848-6451			
			N840AG	W/C	D DMW-	100892	Date:	July 11, 2012
	eraft Log Entry	SN	296	ACTT:	12643.1	HOBBS:		ACSN: 7694 ECSN: 9266
Aircra Engin	e: PTEA-67B e: MTV-27-1-N-C-F-R(P)		PCE-PR0132 110124	PTSN:	540.7	PTSO		- in restrict the

Parlamed a 100 Hour inspection of this aircraft IAW 14 CFR Part 43, 43.15 and appendix D (as applicable). Utilized the durmed a 100-HOUR inspection: following deckins: Plans PC-12 AMM, Chapter 05-20-10 - 100 Hour Inspection; PEWC PT6A-678/P EMM, Chapter 72:00:00. Periodic inspection, 100 hour and Minor inspection items.

Complied with the following Special Inspections per Chapter 05: 10-00: CW 1000 hour statementariary eventual by installing overhauled started penerator pth 23085-024 s/h 28109 (AMETEK

845, CRS# NE2R028L, w/o R12-03134 and w/o R12-032065.

C/W 6 month ice and rain protection airfoil de-icers surface coaling.

C/W 6 month/100 hour EPU check. CW 1 year/150 hour flap screw actuator lubrication.

CW 6 month lead acid main aircraft battery #1 and #2 capacity checks. (Battery capacities above 90%)

CAV 24 month internal corrosion inspection IAW Pilatus PC12 MM chapter 20-40-00.

CW 1 year 200 hour spark igniter inspection. CW 1 year/600 hour chip detector inspection.

C/W 100 hour power recovery and turbine wash. CW 100 hour FCUlreverse cam linkage and rod end inspection.

CW 100 hour oil filter inspection.

C/W 200 hour P3 filter and filter drain valve housing assembly inspection/cleaning.

CW 200 hour power luthine blade in-service inspection MW PEWC MM Churcher 72-00-00. CW 400 for fuel nozzle inspection and borescope inspection IAW PBVIC PTEN-57RIP MIX chapters 73-11-05 and 72-00-

00, thel nozzle inspection/repair performed by Prime Turbines, UESR246N, wiu WT042294)

CW 600 hour fuel pump outlet filter change by installing new filter pin ANIS235.55. C/W 30 day cockpit/cabin fire extinguisher inspection.

Skylech.ir

200 Airport Drive, Westminster, Maryland 21157 Philine: (410) 574-4144 / Fax: (410) 848-6451

--

Complied with the following Instructions for Continuing Airworthiness: Performed ICA for MT propeller installation (100 hour visual inspection) UW MT-Propeller E-1083 Issue 16 dated

Complied with the following Airworthiness Directives (AD's):

AD notes checked thru bi-weekly 2012-13. See AD log dated July 10, 2012.

Completed the following additional items: Removed moving map flight display sin 10038000, installed a new flight display pin FD70CU-V sin 1210564038. Reinstalled required (Sinus Technologies CRS#15LR2768 WIG# RH061412) moving, map CPU pln FD200CPU-7 sin

8011003. Work performed IAW Flight display system installation instructions. Secured caron door interior latch opver panel with veloro. Installed new probes DEICE annunciator bulb pin 972.81.31.442 and tested IAW PC12.45 MM Chapter 33.00-00.

installed a new Co-pilot seat horizontal adjustment mechanism pln 959.30.01.222 IAW Israel Aircraft MM Document #504300036 chapter 25-10-99.

Suntaned longs rivet in 654 flap with new CR3213-4-3 rivet VAW AC43.13-18 4-57. Repaired pinholes on RH wing and both elevator deice boots utilizing Goodrich pinhole repair kit pln 74-451AE. Cleaned seal on emergency exit door "PUSH" handle and cleaned water out of the belly as needed.

Saftied oil temperature bulb cannon plug IAW AC 43,13-18 7-123.

installed new adel clamp (PIN MS21919WDF8) on alternator power wire IAW AC43.13.18 11.146. Performed engine adjustment/test IAW Pilatus PC12 MM Chapter 71-00-00 and PSWC PT6A-678 MM Chapter 71-00-00

Installed new connecter on RGB tannis heater plug IAW AC 43.13-18 Chapter 10 Section 8.

Updated dual GNS WAAS nav databases to cycle 1207 effective 6/28/12 to 7/26/12. I certify that this AIRCRAFT has been inspected in accordance with a 190-HOUR inspection and was determined to be in airworthy condition.

MAINTENANCE RELEASE The aircraft and or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found air body for return to service with respect to the work performed. Perfinent details of the regain are on file at this agency under

Work Order No:

for Stylech, Inc., 200 Almost Dr., Westminster, MD 21167.

CRS# LE1R294K

Total to Carry Forward

and Rema

NO	DISCREPANCIES NOTE	DONTH EPY CHELK.	Manhhli	A+1930W
_			1	1
	Skylech, iii		580 Airport Road, I	Rock Hill, SC 29732
_	Stateon, 2		Phone: (803) 366-5108 / 1	Fax: (803) 366-5230
_	Experience the Styl	ech-Advartage		
	Airframe Log Entry	Hobbs: 2721.1	Registration #:	N840AG
_	Date: 20 August 2012		Make/Model:	PC-12/45
	W/O: UZA-100554		S/N:	296
-				
	<ul> <li>Analyzed stored flap I</li> </ul>	istory. Found code E221	two times for right midd	tle resolver
_	limitations. Rotated ri	ght middle resolver 180 de	grees and performed fi	ap zero set
	IAW Pilatus PC-12/45			

Signature

Certificate No.

good, NDN.

and Remarks

1/12/2 .

MAINTENANCE RELEASE The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pertinent details of the repair are on file at this agency under Work Order No:

for Skytech, Inc., PO Box 37507, Rock Hill, SC 29732.

Skylech.

580 Airport Road, Rock Hill, SC 29732 Phone (803) 366-5108 / Fax (803) 366-5230

Airfran	ne Log Entry	Hobbs:	12,741.3	Registration #:	N840AG
Date:	September 14, 2012	Total Time:		Make/Model:	PC12/45
W/O:	UZA 100640	Cycles:		S/N:	295
Perfor	med an ANNUAL Inspecti	on:	occast IAW 14	CFR Part 43, 43.15 and a	spoendix D

- Performed an Annual Inspection of this aircraft IAW 14 CFR Part 43, 43.15 and appendix D (as applicable). Utilized the following checklists: Platus PC12 AMM, Chapter 05-20-20 -Annual Inspection; PAWC PT6A-67BIP EMM, Chapter 72-00-00, Periodic Inspection, 100 hour and Misror inspection items.
- Inspected the ELT per FAR 91.207(d). Battery expiration date is July 2013.

Complied with the following Airworthiness Directives (AD's):

AD 2012-14-15 Honeywell International KGS200 WAAS Global Navigation Satellite

- Sensor Units. Effective date of AD is July 19, 2012. N/A by equipment listed Honeywell KGS200 Mercury 2 not installed in atrust.

  C/W AD 2001-25-10. Prevent Current Surpris in the Flao Control System (Effective date:
- CAV AD 2001-25-10 Prevent Current Surrons in the Flap Control System (Effective date: Jan 25, 2002). Inspected flap achibition for correct end-play and backlash per paragraph (g)(5) of AD 2001-25-10. Next inspection dun at 13,341.3 ACTT.
  - AD's checked through FAA Biwesley 20-12-17.

Complied with the following Service Bulletins (38's):

Owner Notified Pilatus SB 32-023 (fold No. 254) - Nose Wheel Steering Rod Retention

Page 1 of 5

Improvement.

Total to Carry Forward Registration No.



580 Arport Road, Rock Hill, SC 29732 Phone (803) 366-5108 / Fax (803) 366-5230

- Owner Notified Pilatus SB 34-029 (Ref No. 270) Protection of the EFIS Display Cable
- Loom Owner Notified Pilatus SB 23-008 (278) - Oxygen Mask Microphone rewire.
- Owner Notified Pilatus recommended SB 11-005 (Ref No. 287) Replace The Fuel Filler Discard
- Owner Notified Pilatus optional SB 11-006 (Ref No. 288) Replace Engine Oil And Oxygen Charging Pressure Placards

#### Complied with the following Special Inspections: The following time limit items were completed: (Reference: Pilatus PC12 MM, Chapter 4.Chapter 5)

- Aircraft external corrosion preventative inspection. (Moderate)
- Airframe Wash (Moderate Environmental Conditions Only). Horizontal Stab Trim Runaway Aural Warning system functional test (100 hr, 1 yr)
- Cockpit fire extinguisher inspection. (30day)
- Over temp. Switch testing. (5 yr
- Pressurization outflow & safety valve creating. (1500 hr. 2 yr)
- Pressurization system adjustment/hist. (1500 hr. 2 yr)
- Servo mount clutch checks (p.ich roll and yarv), (1000 hr, 1 yr)
- #1 and #2 lead acid battery cap, check and service, (200 hr, 3 months)
- Generator 2 brushes insp. (400 hr. mod A & C)
- Flap actuators lubrication RH and LH. (w-400 hr, 1 yr)



580 Amort Boart Boys Hill SC 20230 Phone: (803) 366-5106 / Fax: (803) 366-5230

- Flag actuators backlash checks Black, (w-600 hr. 800 ft. 1 vr) RH IB SN 1056: .007, RH OB SN: 0128: .008. LH IB SN: 0733: .010. LH OB SN: 0291: .010.
- Fuel cross vent and outward check valve operational test. (1000 hrs)
- Landing gear wheel bearing lubrication LH,RH and nose. (1 vritire change)
  - Main gear axles and bushings insp RH and LH. (2000 hr, 1 yr) Engine torque limiter test. (500 hr. 1 yr)
  - Engine torque and stick pusher torque transducer connector cleaning, (500 hr. 1 yr)
  - P3 air filter cleaning. (200 hr) P3 air filter drain valve housing assembly inspection.
  - Engine magnetic chip detector bridge . (600 hr. 1 yr)
  - The following overhaul/replacement items were completed:
- Fire extinguisher, 1 yr contents check. Removed Primary Proceller Governor PN: 8210-137 SN: 12177806 and installed Primary Propeller Governor PN: 5210-137 SH: 14083626 8130-3 WO: 77969 (Overhauled) by
- International Governor Services dated 5/03/12, Work performed IAW PC12 MM CH 61
- Complied with the following technicitions for Continuing Airworthiness: Performed Visual Inspection of GPS//ridum Combination Antenna
- Completed the following additional items: Serviced oxygen system with Aviator's Breathing Oxygen IAW Pilatus PC12 MM chapter 12-10,05
  - Re-safetied pilots DV window.

Page 3 of 5

otal to arry Forward

Registration	No.	
--------------	-----	--

Skytech,2 Experience the Slynich-Advantage

580 Airport Road, Rock Hill, SC 29732 Phone (803) 366-5108 / Fax (803) 366-5230

- Installed new master caution bulbs OL-3112 on pilot instrument panel.
- Serviced air conditioning to proper specifications. IAW PC12 CH 21.
- ECS drain line deformed and cracked. Installed new drain line PN: 521.41.12.066. #5 and #6 passenger 02 mask have leaks. Installed new masks PN: 957.12.10.211.
- Both no smoking lights inop. Installed new bulb assemblies PN: 1202-300. All passenger seat clutches are loose. Adjusted clutch to proper operation.
- Several Eaton switch light bulbs inop on instrument panel. Installed new bulbs PN: CM-6839.
- O2 dust covers on sidewalls are pulling loose. Owner Notified
- Gen 2 belt is loose. Adjusted belt to proper specifications IAW Pilatus PC12 MM CH 24.
- Upper beacon bulb inop. Installed new bulb PN: 972.87.87.333.
- RH and LH aileron quide rollers are dry. Lubed.
- HF antenna attaching hardware is corroded. Removed corrosion and applied corrosion X
- treatment LH pilot circuit breaker panel light bulbs inop. Installed new bulbs PN: 972.73.19.109.
- Pilot / Copilot map lens light is missing. Installed new map light lens PN: 02-0330382-01.
- Dressed, primed and painted prop.
- Radar radome is in need of erosion boot. Installed new PM research boot PN: PM 190. Owner Notified, EGPWS database has expired N458N 6/15/10.
- Performed post inspection performance run-up, no defects noted.



Experience the Stotich Advantage

580 Arrest Board Born Hill SC 20732 Phone: (803) 366-5108 / Fax: (803) 366-5230

I certify that this AIRCRAFT has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.

#### MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pershent details of the repair are on file at this agency under Work Order No:

100640 Signes 1 (44 CESS C41RZ27N for Skytech, Inc., PO Box 37507, Rock Hill,

Total to Carry Forward

Page 5 of 5

	AIRCRAFT REG:	N840AG	DATE	9/26/12	
	MFG:	Pilatus	WORK PACKAGE:	T10491	
	MODEL:	PC-12/45	TACH TIME		
Aviation	SERIAL:	296	TOTAL TIME:	12758.2	lo.
=	HOUR METER:	2458.2	TOTAL CYCLESILANDINGS:	7787	
ReplacedRH & LH inner resolvers wi	th new units pin 978	3.73.20.021,	zero set and ops checked flaps	MMA WAI	
12-A-27-50-06-00A-920A-A					
Replaced RH MLG tire ph 021-350-0 — 12:A-32-40-01-00A-920A-A	with new, sih 1327	500397 IAW	Parker CMM 40-424 & Pilatus	AMM	_
_					_
-					—
-					_
The aircraft, airframe, engine, propeller of current regulations of the Federal Aviation repair are on file at this repair station und	n Administration ar	nd is approve	s repaired and inspected in a ed for return to service. Pertine T10491	cordance with ent details of the	
Spec Alum	Andrew F	uler			_
for Epps Air Service, Inc., ESMR688D,	1 Aviation Way, At	fanta, GA 31	3341		_
			Page 1 of 1		
				_	
				1	
				_	
				_	

at is

#### AIDODALT LOC AIRCRAFT REG: N840AG MEG: Platus

remove split and crimped on new socket. Reassembled connector

Replaced flap selector resolver MT035 with new, p/n 978 73 20 021

Completed flap zero set procedure and operational check, no defects noted.

MODEL: PC-12M5

Flaps failed, checked error codes - E211 Found RH inner resolver angle + 45 degrees from the other 3. Adjusted clamping force on RH inner resolver. Checked wires and connections and shielding at TB034 and fusielane connective

NDN Found soit in wire 3C123B24/RD insulation inside connector P029 at FCWU. Cut socket off wire shortened to

HOURMETER: 2458.4

WORK PACKAGE: T10499 SERIAL: 296

DATE: 9/28/12 TSMOH: TOTAL TIME: 12758.4

TIME SINCE HS:

shove was repaired and inspected in accordance with

T10499

approved for return to service. Pertinent details of the

TOTAL CYCLESI ANDINGS: 7788

Date: 10/15

Ren

4E3

Air

Cle

I certify th

current re

performe

Page 1 of 1

Ganta, GA 30341

for Epps Air Service, Inc., ESMR688D, 1 Av. 1

\_\_\_\_ The aircraft, airframe, engine, propeller or appliance id ....

current regulations of the Federal Aviation Advance

repair are on file at this repair station under ex-

Carry Forward

Signed



A/C: N840AG S/N: 296 TT: 12789.7 Cycles: 7813

Date: 10/15/12

Removed Prop de-ice controller/timer P/N 4E3163-1 S/N U0008 and installed repaired P/N
4E3163-2 S/N U196 for troubleshooting purposes. S/N U196 was repaired under AMETEK B&S
Aircraft Parts & Accessories (CRS# NE2R028L) WO# R12-04643.

Aircraft Parts & Accessores (crisi Mezmuzel) with Mizeween.

Cleaned and inspected brush block/MOV module and slip rings. Checked brush alignment on slip rings. No discrepancies noted.

silp rings. No discrepanies invest.

Certify that all work has been performed in accordance with Pilatus maintenance publications and the current resultations of the FAA. This should be approved for return to service only for the work.

current regulations of the FAA. This abrush is approved for return to service only for the work performed.

Abl 306078

Ullew purally 1751 3160118



- Lighter Company				
Airframe Log Entry Date: October 23, 2012 W/O: UZA 100728	Hobbs:	2803.2	Registration #: Make/Model: S/N:	N840AG PC12/45 296

Troubleshot prop heat. All boot resistances read within range according to MT-Propeller. Checked brushes, OAT probes, timer, MOD module, timer grounds. Found resistances reading high through prop slip rings. Cleaned prop slip rings. Prop heat op checks good IAW Pilatus PC-12/45 MM chapter 30 and MT-Propeller Service Instruction SI No. 4E. Removed Deice Timer P/N 4E3163-2 S/N U196 and reinstalled original Deice Timer P/N 4E3163-1 S/N 00008(Refer to Aerocab logbook entry dated 10/15/12). Prop Deice system op checks good. NDN.

#### MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pesigant details of the repair are of file at this agency under Work Order No: 100728 Signed Control Value of Skytech, Inc., PO Box 37507, Rock Hill, CRS# C41R727N SC 29732

Page 1 of 2

etal to arry Forward		

Skylech 2

o interested				
Airframe Log Entry	Hobbs:	2807.8	Registration #: Make/Model:	N840AG PC12/45
Date: October 26, 2012 W/O: UZA 100728			S/N:	296

 Prop heat de-ice lead harness has failed. Removed five failed deice lead harness and installed five deice lead harness PN: RA-C165013-0202 supplied by MT-Propeller USA Inc. Invoice & I-12-695 (New). Performed functional check of propheat.ops checked normal. Work performed IAW Mt.-Propeller Service Instruction SI No. 4E and Pilatus PCI 2 MM CH 61.

#### MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found alreadily for return to service with respect to the work performed. Petili

Return to service this date, October 30, 2012. Julius	12-A de-is leak
N840AG SN 296 HM 2828.4	
inspection Criecx. No Defects noted. recassioners when new tier hates with new tier Privacy and a specific privacy and safety.  Cleaned, inspected and repacked wheel bearings. Referablished on aircraft, torqued axle nut and saffied. Serviced tire with nitroom to follow as required. Referablished on aircraft, torqued axle nut and saffied. Serviced tire with nitroom to follow as required. Referablished on aircraft, torqued axle nut and saffied. Serviced tire with nitroom to follow as required.	9-201: Servic
Certify That The Maintenance Identified In This Work Order Package Has Been Inspected And The Item(s) Are Approved For Return To Sension Partition Thereifs Of The Repair(s) Jon On File At This Agency Under Work Order Number GSP-WO-3191	m To
For STEVENS AVIATION, GREER, SC 29651 CRS VIBASION SA-0505	



AIRCRAFT REG. N840AG MFG: PILATUS MODEL: PC12W5

DATE: 11/13/12 WORK PACKAGE: T10662 TACH TIME

SERIAL: 296

TOTAL TIME: 12.841.7 HOUR METER: 12.841.7 TOTAL CYCLESILANDINGS: 7870

CW Progressive inspection 100 HR, mini check #1 IAW PILATUS M.M. 12-A-5-30-02-00A-28 W.A. Aircraft corrosion inspected washed IAW Pllatus AMM 12-A-20-40-00-00A-901A-A. magnetic compass (C23-807) and AHRS swing checked IAW AMM 12-A-34-25-00-00A-903A-A-A 12.A-34-2100-00A-903A-A CAW 150 HR / 1 YR. L/H & R/H Flap actuators lubricated IAW Platus AMM

12-A-27-50-00-00A-902A-A C/W 200 HR, starter generator brushes inspected IAW Pilatus AMM 12-A-24-30-01-00A-313A-A CW 100 HR. EPS/EPU visually inspected. C/w forward lower cowling L/H de-ice to anti-ice pipe adusted for exhaust leak IAW AMM 12-A-30-20-02-00A-920A-A. All operational and

leak checks carried out satisfactory.

SN 296

ACTT 12874.7

11-29-2012

1.02 Serviced tires to proper requirements to the sittogen.

I Certify That The Maintenance Identified in Trais Work Order Package Has Been Inspected And The Item(s) Are Approved For Return To Service, Pertinent Details Of the Repair(s) Are On File At This Agency Under Work Order Number GSP-WO-3234

SIGNED Dendall Wood

For STEVENS AVIATION, GREER, SC 29651 CRS VIB8368K

SA-0505

	NS40AG	SN PC-12	HM 2895.0	
1/2012				-
Placed aircraft on jacks and with Pilatus Maintenance Y checked satisfactory. Rem	danual. Applied proper torque	. Installed customer supplie and safety as required. Perl	d new P/N532.20.12.296 in accordance formed several retracts, Operation	=
urn To Service, Pertinent D	etails Of The Repair(s) Are Or	er Package Has Been Inspec n File At This Agency Unde	ted And The Item(s) Are Approved For r Work Order Number GSP-WO-3262	
FOR STEVENS AVI	ATION, GREER, SC 29651	CRS VIB8368K	SA-0505	_
				_
				_
				_
				_
				_
				_



Phone (803) 305-5106 / Ear (813) 366-5235

Airframe	Log Entry	Hobbs:	2933.6	Registration #:	N840AG
Date:	January 7, 2013			Make/Model:	PC12/45
W/O:	UZA 100797			S/N:	296

Updated Garmin data bases to Cycle 1301 Jan 1 to Feb 7 2013.

#### Owner Notified

- Found and removed de-ice boot pressure switch S-135 P/N 973.81.14.312 S/N 0867 causing de-ice caution light. Installed new de-ice pressure switch PIN 973.81.14.312 S/N 5036 IAW Pilatus PC-12/45 MM chapter 30. Op checks good using shop air but falls on engine run. Refer to MEL 12271201
- Removed pressure regulator PIN 4D2095-141 S/N N0314 and installed overhauled pressure regulator/reliever (work performed by Ametek B&S Aircraft Parts and Accessories P/N 4D2095-41 S/N NO433. Pressure checks good IAW Pilatus PC-12/45 MM chapter 30. Boot deice system still fails after
- 7 cycles. Refer to MEL 12271201

#### MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pertinent details of the repair ere on file at this agency under Work Order No: 100797 Signed Amelical TV Many for Skytech, Inc., PO Box 37507, Rock Hill, SC 29732

In-



580 Arport Road, Reck Hill, SC 29732 Phone: (803) 366-5108 / Fax: (803) 366-5230

Airframe Log Entry	Hobbs:	2942.7	Registration #:	NR40AG
Date: January 25, 2013	Total Time:	12942.7	Make/Model:	PC12/45
W/O: UZA 100771	Landings:	7951	S/N:	296
Air conditioning	Hobbs:	305.1		

Performed a 200 hour Phase 1 Progressive Inspection per the Pilatus PC-12 AMM chapter 5-30-00

### Complied with the following Special Inspections:

The following time limit items were completed: (Reference: Pilatus PC12 MM, Chapter 4.Chapter 5)

- Air foil de-icers surface coating. Age Master #1 (6 months)
- PS-855 EPS/EPU 100Hr Check
- Cockpit Fire Extinguisher Inspection, Next Hydrostatic due 9/30/23. P3 air filter drain valve housing.
- P3 air filter inspection( due for new replacement see SQ 201)
- PS-855 EPS/EPU 3 month check
- Cold air unit re-oil. (500 hr) Water separator condenser cleaning, (500 hr)
- Secondary heaters thermal protection switches testing, (101-320, 500 hr)
- Insp. of heat exchanger matrix, (500 br)

otal to arry Forward		

#### Registration No.

Skylech ?

580 Argent Road, Rock Hill, SC, 29732 Phone (803) 366-5108 / Fax (803) 366-5230 lo.

P3 filter replacement. (1000 hr) PN: 3059788-01 Supplied by Pratt Whitney 8130.3 WO 2439954DO-117506 ( new) date: 9/28/12.

- Airframe wash (Moderate Environmental Conditions Only)
- Propeller feathering microswitches. (3000 hr/ 1 yr)
- Inspect oil scavenge inlet screen.
- Corrosion Preventative Inspection Application (moderate).
- PS-855 EPS/EPU Annual Check / Emergency Supply Capacity Test Flap actuators lubrication. (Black)
- Lead Acid battery capacitance check. (400 hr. 12 months) Work Card # 14
- Perform Foot heater check.
- Compressor/Turbine wash. (100 hr)
- Complied with the following Instructions for Continuing Airworthiness:
- Airborne Position Data communicator ISAT-100 Mod AB 2120
- Cockpit Display Panel (ICA) CDP-250G Mod A 11448
- Circuit Breaker Check (ICA) Skytrac

#### Airworthiness Directives (AD's): None applicable at this time

AD's checked through FAA Biweekly 2013-01.

Owner / Operator notified Service Bulletins (SB's) and items are due:

Back ordered EGPWS database PN: 071-00167-0101

Date	Aircraft Time	Recorder		
1 19	This Date Total		Maintenance	
	- · ·		580 Airport Road, Rock Hill, SC 29732	No.



U (sperience the Stylech-Advantage

Phone: (803) 366-5108 / Fay: (803) 366-5230

- Owner Notified is due Pilatus \$8 32-923 (Ref No. 254) Nose Wheel Steering Rod Retention Improvement.
- Owner Notified is due Pilatus SB 34-029 (Ref No. 270) Protection of the EFIS Display Cable Loom.
  - Owner Notified is due Pilatus SB 23-008 (278) Oxygen Mask Microphone rewire.
  - Owner Notified is due Pilatus recommended SB 11-005 (Ref No. 287) -The Fuel Filter Placard by installion new placards
    - Owner Notified is due Pilatus optional SB 11-006 (Ref No. 288) Replace Engine Oil And Oxygen Charging Pressure Placards
      - Owner Notified is due Pilatus SB 57-006 (295) Inspection of flap support arm

#### Completed the following additional items:

(CM6839)

- Troubleshot device boot cases failure dus to internal air leakage on Rt OB delice boot. Removes Ph 598 89 01 00 16 Installed new Goodrich RT OB FAST Dices boot PRP277-705221-12 SN NGC-1820 (Basche 5591400) Supplied by Goodrich Sensors and Integrated Systems 813-03 WO: 1931958 (New) dated 11/182012. Performed functional cherono defects noted. Work performed UMV Goodrich Installation Instructions CH30 dated 10/2008 and Palvas PC12 MM CH3 O. Reference Control I of 707 in Aircraft Firelt Log.
- Serviced oxygen system with Aviator's Breathing Oxygen IAW Pilatus PC12 MM chapter 12-10-05.
   Several Eaton pushbutton switch bulbs inop. Installed new bulbs PN: 972.73.19.106



Skylech, w.

- CAWS bulb inco on panel. Installed new bulb PN: 972.81.31.442 OL-632.
- Installed new fuel cap o-rings PN: MS-29513-232.
- Air conditioning belt wearing. Removed worn belt and installed new Platus belt PN:
- 959.90.22.105 UZA PO # 52905 date 1/10/13. Work performed IAW Pilatus CMM CH 21.
  Reapplied de-ice boot edging.
- Installed cargo door fitting inspection kit PN: 500.60.12.005 SN: N/A. Supplied by Pilatus Aircraft Ltd EASA Form 1 Wio: P61713 (new) dated 1/18/13. Performed functional check,no defects noted. Work performed IAW Pilatus PC12 MM CH 52.
- Applied Corrosion X treatment to turbine inlet case IAW Pratt & Whitney MM PN: 3038336 CH 72.
- Performed post inspection performance run-up, no defects noted.

Skylech

580 Airport Road, Rock Hill, SC 29732 Phone: (803) 366-5108 / Fax: (803) 366-5230

Locative that this AIRCRAFT has been inspected in accordance with a Progressive inspection and was

#### MAINTENANCE RELEASE

determined to be in airworthy condition.

The aircraft and/or component identified shows was repaired and inspected in accordance with current Federal Aviation. Regulations and with found aircraftly for return to service with respect to the work performer. Perfollant details to the repfix are on fise at this agency under Ward. Order Mo. 190711 Spread for Stylech, Inc., PO Box 37507, Rock Hill, 50 29732 e No.

and 12-14. Certify That The Maintenance Identified In This Work Order Package Has Been Inspected And The Item(s) Are Approved For Return To Service, Pertinent Details Of The Repair(s) Are On File At This Agency Under Work Order Number GS \*WO. This

SIGNED Dendall Wood

3/3/2013

N840AG SN 296 1.02 Mounted customer supplied new 4 lb. Amerex Portable Halon Fire Bottle P/N C352, NO Y-299808, under aft cabin ser

Seat will be reinstalled by customer. All work performed in accordance with AC 43.13-2B and load factor checked in accordance with par. 104, pages 2, 3 and 4. Bottle has manufacture date of 2012.

Carries That The Maintenance Identified In This Work Order Package Has Been Inspected And The Item(s) Are Approved Resum To Service. Pertinent Details Of The Repair(s) Are On File At This Agency Under Work Order Number GSP-WO-1

SIGNED Dendall Word

<del>-TEMPUS</del>

Part

No.

0+ O+b-4 070 73 30 300 0+30

verter,

exchange under

sara 12-11

Approved For 2-WO- 3366

ft cabin szot 1

Approved F F

recked in

March 15, 2013 Hobbs: 2998.9 Landines: 7991 Air Conditioner Hours: 305.1

Total Time: 12998.9 Propeller Total Time: 509.0

N840AG

Total

Total

Hours Lndes

2420 5 1627

Performed an Annual Inspection using the Pilatus PC12/45 checklist and FAR 43 Appendix D.

AIRFRAME

Airworthiness directive compliance checked through Revision 2013-03.

Previous

Backlash

unknown

Airworthiness Directives and Service Bulletins

Serial

-Complied with Pilatus AD 2012-26-16 by inserting Structural and Component Limitations/Airworthiness Limitations Document into the aircraft maintenance manual.

-Complied with Pilatus AD 2001-25-10 by performing wing flap actuator backlash inspection in accordance with the manufacturer's maintenance manual with results as follows: Current Rarklash

Rt	Inbd 978.73.20.309	1056	unknown	.006	2420.5	1627
Lt	Otbd 978.73.20.309	0291	unknown	.006	2420.5	1627
	Inbd 978.73.20.309		unknown	.007	2420.5	1627
Air	craft total landings 799	91. Recurrin	ng inspection d	ue each 600	) hours or at	annual inspection. Next inspection is due at

3598 hours or 3/2014. Complied with EASA AD2013-0020R1 Seat Belt Inspection. Seat belts installed have not been repaired and no action is

required at this time. Aircraft School of Maintenance and Inspections

-Complied a confect prooffs, 15 minute run of the vapor cycle cooling system. No discrepancies noted.

-Complete is to the Singerth application of Agemaster to the surface deicers per the manufacturer's instructions.

-Compiled with the Planta 5 month corrosion preventative compound condition inspection per the maintenance manual instructions. No discrepancies noted. -The 1 year consequence is over supply capacity test was complied with by Duncan Aviation on Serial Number 2526.

See FAA Form \$130-3 do and \$17/12/13 placed in the aircraft records Page 1 of 4 AIRFRAME (cont'd) March 15, 2013 N840AG Aircraft Scheduled Maintenance and Inspections

-Complied with the 1 year fire extinguisher contents check. No discrepancies noted.

-Complied with the 3 year passenger oxygen mask inspection. No discrepancies noted.

-Complied with the 1 year/3000 hour horizontal stabilizer trim runaway aural warning operational and functional tests.

Operational and functional checks good.

-Complied with the 1 year/3000 hour propeller feathering microswitch functional tests. No discrepancies noted.

-Complied with the 1 year wheel bearing lubrication.

-Removed and replace nose wheel bearings and races with new.

-Complied with the 1 year/100 hour landing gear shock strut pressure check per the Pilatus maintenance manual.

-Complied with the 1 year/2000 hour main landing gear axle and bushing inspection. No discrepancies noted.

-Complied with the 1 year/500 hour engine torque and stick pusher transducer electrical connector cleaning. -Complied with the 1 year/150 hour flap actuator lubrication service per the manufacturer's maintenance manual.

-Complied with the 5 year/2000 hour flight control cable inspection.

-Complied with the 150 hour elevator cable tension inspection. No defect noted.

-Complied with the 150 hour rudder control cable tension inspection. No defects noted. -Complied with the 4 year battery replacement. Removed battery #1 serial number 40327434 and installed serial number

40539000. Personnel Landery #2 serial number 40381592 and installed serial number 40538995. Operational checks good

-Complied work in the derfpenerator brush inspection. No discrepancies noted.

-Complied with the light sour reperator #2 drive housing inspection. No discrepancies noted.

-Complied with the 460 your generator #2 brush inspection. No discrepancies noted.

-Complied with the 2 year generator #1 and #2 ground point inspection and cleaning.

- Complied with the 3500 hour engine driven fuel pump overhaul by removing pump Serial Number 83949 and installed an overhauled pump Serial Number B4863 with a new gasket and seals. See FAA form 8130-3 dated 2/12/2013 from

Ametek B & S Aircraft Parts and Accessories placed in the aircraft records. Performed a ground run. Operational and lea

Page 2 of 4 check good

AIRFRAME (cont'd) March 15, 2013 N840AG

Aircraft Scheduled Maintenance and Inspections

-Complied with the 1 year fire extinguisher contents check. No discrepancies noted.

Complied with the 3 year passenger oxygen mask inspection. No discrepancies noted.

 Complied with the 1 year/3000 hour horizontal stabilizer trim runaway aural warning operational and functional tests. Operational and functional checks good.

-Complied with the 1 year/3000 hour propeller feathering microswitch functional tests. No discrepancies noted. -Complied with the 1 year wheel bearing lubrication.

-Removed and replace nose wheel bearings and races with new.

-Complied with the 1 year/100 hour landing gear shock strut pressure check per the Pilatus maintenance manual.

-Complied with the 1 year/2000 hour main landing gear axle and bushing inspection. No discrepancies noted.

-Complied with the 1 year/500 hour engine torque and stick pusher transducer electrical connector cleaning.

 Complied with the 1 year/150 hour flap actuator lubrication service per the manufacturer's maintenance manual. Complied with the 5 year/2000 hour flight control cable inspection.

-Complied with the 150 hour elevate, othle territor inspection. No defect noted.

-Complied with the 150 hours of fermiosisticable tension inspection. No defects noted.

-Complied with the 4 year 6 and to enter the entered battery #1 serial number 40327434 and installed serial number 40539000, Removed batton, 47 per 31 cerulated 40381592 and installed serial number 40538995. Operational checks good

Complied with 200 hour starter/conersupy brush inspection. No discrepancies noted.

-Complied with the 1000 hour renerator #2 sirive housing inspection. No discrepancies noted.

-Complied with the 400 hour generator #2 brush inspection. No discrepancies noted.

-Complied with the 2 year generator #1 and #2 ground point inspection and cleaning.

- Complied with the 3500 hour engine driven fuel pump overhaul by removing pump Serial Number 83949 and installed an overhauled pump Serial Number B4863 with a new gasket and seals. See FAA form 8130-3 dated 2/12/2013 from Ametek B & S Aircraft Parts and Accessories placed in the aircraft records. Performed a ground run. Operational and leak

check good Page 2 of 4

#### Pilatus PC-12/45 S/N:296

March 8, 2013

Performed a clutch torque check on the pitch, roll, and yow intopilot clutches LA,W Pilatus PC-12/45 AMM #02049 chapter 12-A-22-10-00-00A-313A-A dated 2012-12-15. Adjusted all clutches down to be within the specifications listed herein, Performed a basic autopilot operational test IA, W

Charged out the ELT buttery P.N.452-0133 that expires: July 2013 with a new battery P.N.452-0133 S.N.350982-066. Performed a 12 month important rate of the ELT system I.A. With First C.G.6-N Institution Manual 570-5000 Rev H dated MAR 1/13, no defects noted at 20 feet for the Ferformed I.A. We personer G.O. M consciounnets.

DT information:

170: 153-50-0 1 Cc 531//5304

Reft dattery \$1356982-066

510

Completed: 24 month certification of the #1/2 static pressure systems and the primary transponder system. The #1/2 altimeters, static pressure system costs with a pections, and automatic pressure admitsed reporting system tests required by Title 14 CTR Part 91.411, and the transponders static and the supporting or the property by Title 14 CTR Part 91.411, and the transponders static and the supporting or the property of the proper

3 The transparder was tested on 3/2/13. The movie data correspondence was tested to 35,000 feet on 3/2/13.

Line 1/2 this pressure systems were tested and inspected on 3/7/13, a.1 Alterna MANKEA-346, PAN 066-03062-0010, SAN 4197

#1 Transporter Min KT-79 P.N.066-01141-0201 S/N:30487

C The short described report of contractions is approximate for return to service. A detailed record in on-file under Work Order # 22X#1

UG7150761 Phone: 303-649-1790 for Juneau Avionies; Engleucod, CO 80112 Total Time: 12998.9 Total Landings: AIRERAME (cont'd) March 15, 2013 N840AG

Aircraft Maintenance Actions

Removed MT propeller MTV-27-1-N-C-F-R(P)/CFR260-65a serial number 100711 (PTTSN: 506.8 hour). Installed Hartzell propeller HC-E4A-3D/E104775K serial number KX846 (PTTSN: 509.0 hour).

Dynamically balanced the propeller with Chadwick/Helmuth equipment and procedures per Pilatus maintenance manu Removed and replaced propeller deice brush block assembly with new. Operational check good. isolated and replaced faulty FCWU with exchange, Removed 978,73,20,016 serial number 108920 and installed

978.73.20.017 serial number 110610. See FAA form 8130-3 dated 3/8/2013 from Pilatus Business Aircraft, placed in the aircraft records. Performed flap system functional tests and operational checks good.

-Removed and replaced ECS shut off valve with exchange. Removed serial number 898929-2 and installed serial number 1433, see FAA form 8130-3 dated 8/8/2012 from Honeywell Aerospace, placed in the aircraft records.

-Removed and replaced right inboard fuel quantity sensor with exchange. Removed serial number 412 and installed seri number 1628, see FAA form 8130-3 dated 11/7/2012 from DRJ Technologies, placed in the aircraft records.

Removed and replaced bulbs in circuit breaker lighting with new. -Removed right strobe light assembly serial number 44221 and installed new strobe light assembly, serial number

43838. Operational check good. -Removed hydraulic pump motor, cleaned and replaced the drive shaft O-ring with new, reinstalled pump motor.

Serviced hydraulic reservoir, operational and leak check good. Removed and replaced hydraulic low pressure switch with new. Operational and leak check good.

Removed and replaced left and right alleron inboard belicrank bearings with new.

Removed and replaced elevator lever control and axie bell crank with new.

Removed and replaced left and right alleron inhound hell crank bearings with new. Removed and replaced left and right afferon renter using push pull tubes and guide rollers with new.

-Removed and replace engine inlet deice for the pro-

-Lower engine cowling repaired by Straight Coest, Terrandonance release dated 03/13/13 placed in the aircraft record Page 3 of 4

NSJOAC Pilatus PC-12/45 DUNCAN March 15, 2013 Tempus Aircraft Sales & Sve S/N:296 AVIATION -heled to customer hanger. Removed HF Antenna Coupler PN: 064-1017-00, SN: 3038 and installed Serviceable Overhauled HF Antenna Coupler probed to easterned hanger. Kemoved the outcomes coupled risk operatories, so a sound were still getting time faults on lower frequencies to med treateshooting checking bending of equipment and wiring, located another fault with the Receiver exciter. Removed the RT P/N 064-100, S.N. and installed a serviceable exchange P.N.064-1015-00, S/N 4945. Performed ground checks of HF systems with no defects noted. Work iplished IAW Bendix King KHF-950 HF/SSB System Installation Manual 006-05389-0002 Rev. 2, Dated April, 2006. The Bowe described repair or maintenance is approved for return to service. A detailed record is on fife under Work Order # 22200A. for Duncan Avionics; Englewood, CO 80112 Phone: 303-649-1790 Total Time: 12998.9 Total Landines:

March 15, 2013 March 15, 2013 AIRFRAME (cont'd) e Overhauled HF Antenna Coupler Aircraft Maintenance Actions me faults on lower frequencies so Repaired pilots seat pan per procedures in Pilatus Service Letter 072. seiter. Removed the RT P.N 064. stem with no defects need Work

Order # 223/04.

ewood. CO 80112

Total Landings:

somewed and replace pilot's seat rollers with new.

.Adjusted passenger seats # 1, 2,3,4,5 & 6 swivel and recline mechanisms per the manufacturer's instructions.

Operational check good. . Ramoved and replaced left horizontal stabilizer pneumatic deicer with new serial number NBA5950. Operational

check good.

Removed and replaced right horizontal stabilizer pneumatic deicer with new serial number NBE9990. Operational check good.

Tighten loose fittings on air conditioner right evaporator lines. Leak check and operational check good.

-Cleaned cabin and cargo door seals. Secured Teflon chafe strip on the right side forward horizontal stabilizer fairing.

installed missing chafe strips on left and right main gear wheel wells. -Reglued loose right wing flap well chafe strips as necessary Repaired surface damage to right forward cabin floor panel as required.

Secured cabin sidewall upholstery in baggage compartment as required.

Regland passenger oxygen mast: covers to support brackets as required.

I certify that this Aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

For Tempus Aircraft Sales & Service ASB - A4 238 120 IA WO# 2097

Page 4 of 4

NR40AC

## THE COCAB MAINTENANCE RECORD

DATE: 05/13/13 AIRCRAFT MAKE / MODEL: Pilatus PC-12 AIRCRAFT REGISTRATION: N840AG

AIRCRAFT TT: 11704.0 LANDINGS: 7867

#### AIRCRAFT SERIAL NUMBER: 296 DESCRIPTION OF WORK PERFORMED:

SN off: 1060 3.) Tire

1.) Removed and replaced RH main wheel assembly with new IAW Pilatus MM and Parker CMM. 2.) Wheel PN off: 40-424 PN on: 40-424

PN on: 021-350-0 PN off: 021-350-0 SN off: 1327S00397 SN on: 2239S00423 This Aircraft is determined to be in airworthy condition and is returned to service only for the work

performed.

SN on: 2669

Name: ADAM MCMULEN Certificate AND 3060748 Signed Odam Kullin Date: 5/13/13

installed ! on the Air

check on for the al

-				
200	and Damades		Cleanture	Cartificate Ma
	=			
_	- <del>-</del> TEMPUS (275			
	-			07/14/2013
_	AIRCRAFT     Pilatus PC-12/45	N840AG S/N 0296		ACTT: 13135.6 LDGS: 8061
	Installed ISAT-100, 5th 2120, with new batter on the Altrome Position Data Communicator, check on the GPS/firidium Antenna with no die for the above referenced work. Tempus Jets 21008 GSP Drive Greer, SC 29651	Cockpit Display Panel, icrepancies noted. This	and Circuit Breaker, as	nd the 12-month r return to service
- - ,				

Registration No.



-TEMPUSIETS AIRCRAFT Pilatus PC-12/45

08/18/2013 ACTT: 13143.1 LDGS: 8066

13147.4 8066

06/2013

cted and pdate

-12

67

Performed an Aircraft Flap Actuator Lube as per Maintenance Manual 12-A-37-50/00/00A-902A-A. No Defects at this time

AIRCRAFT

Pilatus PC-12/45

-TEMPUSIETS

within limits. No defects at this time

NR40AG S/N 0296

N840AG

S/N 0296

Engine Cycles: 9459 Engine Total Time: 12314.2

08/18/2013

Performed a Starter/generator Brush check as per PC-12 MM 12-A-24-30-01-00A-313A-A. Brushes are well

der A&P 471084467

This Aircraft is approved for return to service for the above referenced work Tempus Jets 2100B GSP Drive Greer, SC 29651

TEMPUS/ETS		10/15/2013	-
-31011111111111111111111111111111111111			and Remarks
AIRCRAFT	N840AG	ACYT: 13226.0 LDGS: 8138	
Pilatus PC-12/45	S/N 0296	2030. 6136	
			£TEMP
Removed R/H main wheel assembly, p/n 4	0-424 sin 2669/2646, with a wo	orn tire. Installed Overhauled wheel	AIRCRAFT
assembly, o/n 40-424 s/n 1060 with new til	e, pin uz roco o an corre	anda for Chemin CNICARD & Chicken -	Pilatus PC-12/45
	neywell KMD850 MFD. This Air	ircraft is approved for return to	Removed defective VC
service for the above referenced work.		6 //1	motor (pin 1134104-1, the Compressor Conde
Tempus Jets	0.4	Gran troit	<ul> <li>Current VCCS hour me</li> </ul>
. 2100B GSP Drive	Tr	acy A. Prouty A&P 2769637	referenced work.
Greer, SC 29651		20,1070011001	Tempus Jets
			2100B GSP Drive
			Greer, SC 29651

and Remarks	Tention I	Signature	Certificate No
TEMPUS/E	75		
-ILIVII OD)	10		11/07/2013
AIRCRAFT Pilatus PC-12/45	N840AG S/N 0296		ACTT: 13249.9 LDGS: 8057
Removed defective VCCS compress motor (p/n 1134104-1, s/n 1608) IAW the Compressor Condenser Module / Current VCCS hour meter reading is	V Enviro Systems Inc. CMM. Op Assembly 500 Inspection at this	erational checks satisfac	ctory. Performed
referenced work.		1	
Tempus Jets		Mora to	)A -
		Tracy A. Prophy A&P	my -
Tempus Jets 21008 GSP Drive		Gracy VIII	my -

Degletssties No.

AIRCRAFT LOG =TEMPUS/ETS intration No. and Romarks ARCRAFT Printed PC-12/45 0100/2014 Companied the Project PC-12 100 Hour Higheston Mill the Prints PC-12 in Section follows the Section bull and related a new following the ACC 2004-0-51. Section for suppressions. Section 6-bit section bull and related a new following the ACC 2004-0-51. Section for suppressions. Section 6-bit section sold and related a new following the ACC 2004-0-51. June 10 - American Train : Septemble for copper system. Sociated at min, survivors and building and speciation and speciation and speciation and speciation and speciation and speciation and social format processing and speciation a Processor der 2 fem sanstenany results. Preferend the 150 fear feet amount of Completed the 6 month orable to the 150 fear feet amount of Completed the 6 month orable to the 150 fear feet amount of Completed the 6 month orable to the 150 fear feet amount of Completed the 6 month orable to the 150 fear feet amount of Completed to the 150 feet amount of Completed t Account with an electromorphism made, include Duptoy Plant, and Qualification, and the 12-medic share proved Connect and control of the Connect and Co Province and the devergence name in contact the related and come flavor appropriate contact to the entirely contact the related and come flavor appropriate contacts and the entirely Contact and the contact to the con 11008 GSP Drive Green, SC 29651

#### AIRCRAFT LOG IN. Recorder Aircraft Time Maintenance Reading Date This Date lot w and Remark: 64-10 . PERFORMED TYPE ACET: PC-12/45 SERIALE: 296 hard to 139 61-00-39 INSPECTION: ANNUAL/100HR CURRENT ACFT HRS: 13354.9 LANCINGS: 8164 I CERTIFY THAT IN ACCORDANCE WITH THE CHAPTER 5-20 OF THE PILATUS PC12 AMM AN ANNUAL AND . PERFORMED tplishe · PERFORMED 100 HOUR INSPECTIONS WHERE COMPLIED WITH ON THE ENGINE, AIRFRAME, PROPELLER AND Fibove di 200 HOUR HOPEL HAVE WHEN EXPENDED AND THEY ARE APPROVED FOR RETURN TO SERVICE. NEXT AMM 71-00-0 · PERFORMED INSPECTION DUE: 100 HOURS AT 1345.9 OR ANNUAL ON 19 MAR 15. NOTES AND DISCREPANCIES CORRECTED AND ADDITIONALLY THE FOLLOWING INSPECTIONS WHERE PERFORMED AND DISCREPANCIES CORRECTED AND PC12 AMM 71 · PERFORM 1 \* SEMOVED CRACKED RH WINDSHIELD PARTE 959.81.10.108 SERIALE 000591H1703. INSTALLED NEW ELECTRICAL ALL OUND TO BE IN AIRWORTHY CONDITION: RM WINDSHIELD PARTS 959.81.10.110. OPERATIONAL CHECKS GOOD REFERENCE PC12 AMM 56-11-01. · PERFORM 1 PERFORMED 12 MONTH CORROSION INSPECTION (INTERNAL) REFERENCE PC12 AMM 20-40-00 REFERENCE P \* PERFORMED 12 MONTH CORROSSION INSPECTION (EXTERNAL) REFERENCE PC12 AMM 20-40-00 . PERFORM 1 \* PERFORMED ASB PTGA-72-A14410 R2 NO.1 ENGINE SPARK IGNITERS, ALERT SERVICE BULLETIN PC12 AMM 7 • PERFORMED SB 57-006 FLAP SUPPORTS. INSPECTION OF THE FLAP SUPPORT ARM ATTACHMENTS . PERFORME 24-30-01 . PERFORMED 12 MONTH ELT TEST REFERENCE PC12 AMM 25-63-00 \* PERSORMED 12 MONTH FIRE BOTTLE INSPECTION REFERENCE PC12 AMM 26-20-00 PERFORME • PERFORMED 12 MONTH FUNCTIONAL TEST HORIZONTAL STABILIZER THIM RUNAWAY AURAL WARNING DESERRINCE NAME: ROR \* PERFORMED 12 MONTH INSPECTION/CHECK MAIN LANDING GEAR AXLE AND BUSHES REFERENCE A&P/IA: 335 DATE: 19 M PC12 AMM 32-10-00 CONTINUED TO NEXT PAGE

Carry Forward

and Remarks  • PERFORMED 12 MONTH NO.1 PROPELLER DETAILED INSPECTION REFEREN	Signature ACE HARTZELL CMM	Certificate No
139.61-00-39		
<ul> <li>PERFORMED 12 MONTH NO.1 PROPELLER LUBRICATION REFERENCE PC12</li> </ul>	AMM 12-20-05	
PERFORMED 12 MONTH OPERATION TEST POWER PLANT TORQUE LIMITE	R REFERENCE PC12	15
<ul> <li>AMM 71-00-00</li> <li>PERFORMED 12 MONTH OPERATIONAL TESTS POWER PLANT PERFORMAN</li> </ul>	ICE REFERENCE	
PC12 AMM 71-00-00		
<ul> <li>PERFORM 12 MONTH CLEAN ENGINE TORQUE AND STICK PUSHER TORQU</li> </ul>	E TRANSDUCERS	
ELECTRICAL CONNECTORS REFREENCE PC12 AMM 71-00-03  • PERFORM 12 MONTH FUNCTIONAL TEST PROPELLER FEATHERING MICRO:	CHATCHES	-
PERFORM 12 MONTH FUNCTIONAL TEST PROPELLER PERTHENING MICHO     REFERENCE PC12 AMM 76-10-02		-
PERFORM 12 MONTH NO.1 ENGINE BRIDGE CHECK MAGNETIC CHIP DETECTION	TOR REFERENCE	
PC12 AMM 79-30-01	-	
PERFORMED 200HR CHECK STARTER GENERATOR FOR BRUSH WEAR REFEI	RENCE PC12 AMM	
24-30-01  • PERFORMED 12 MONTH LH, RH AND NOSE LANDING GEAR WHEEL BEARIN	GLUBES	
REFERENCE PC12 AMM 32-40-01 AND 32-40-02	-	
NAME: ROBERT MARCHEWKA		
NAME: ROBERT MARCHEWKA A&P/IA: 3350439 SIGNATURE: //// A DATE: 19 MAR 14		
DATE: 19 MAR 14		

\_

AIRCRAFT LOG	
TYPE ACFT: PC-12/45 SERIAL#: 296 CURRENT ACFT HRS: 13350.0 LANDINGS: 8161	nance
RIGHT COCKPIT WINDSHIELD SHATTERED IN FLIGHT:  REMOVED RIGHT COCKPIT WINDSHIELD PR 959.81.10.108 SERIALR 00059H1703 INSTALLED BIGHT COCKPIT WINDSHIELD PR 959.81.10.110 SERIALR 1331644577 REFERENCE PC12 AMM 56-11-01. AIRCRAFT IS APPROVED FOR RETURN TO SERVICE.	
NAME: ROBERT MARCHEWKA  — A&P/IA: 3350439 SIGNATURE: PAAM  DATE: 17 March 2014	
TYPE ACFT: PC-12/45 SERIAL#: 296 .INSPECTION: AD 2005-01-09 CURRENT ACFT HRS: 13356.5 LANDINGS: 8166	
I CERTIFY THAT IN ACCORDANCE WITH AD 2005-01-09 AN INSPECTION WAS PERFORMED AND DEFINED THIS AIRWORTHINESS DIRECTIVE DOES NOT APPLY—  TO THE TRANSPONDER SYSTEM INSTALLED. THE AIRFRAME AND SYSTEMS ARE APPROVED FOR RETURN TO SERVICE.	
NAME: ROBERT MARCHEWKA A&P/A: 3350439 SIGNATURE:  DATE: 19 MAR 14	

and Remarks	Signature	Certificate N
TYPE ACFT: PC-12/45 SERIAL#: 296		_
CURRENT ACFT HRS: 13356.5 LANDINGS: 8166		1.19
HORIZONTAL STABILIZER TRIM ACTUATOR DUE 5 YE	AR TIME CHANGE:	
REMOVED HORIZONTAL STABILIZER TRIM ACTUATOR	R TIME CHANGE.	
PART# 129-1-1100-02 SERIAL# 669		
INSTALLED HORIZONTAL STABILIZER TRIM ACTUATOR	8	
PART# 129-1-1100-02 SERIAL# 1016		
OPERATIONAL CHECKS GOOD REFERENCE PC12 AMM	27-40-01. AIRCRAFT IS	
APPROVED FOR RETURN TO SERVICE.		
NAME: ROBERT MARCHEWKA M.		
NAME: ROBERT MARCHEWKA A&P/IA: 3350439 SIGNATURE:		
DATE: 26 March 2014		

AIRCRAFT LOG Aircraft Time Recorder Date Maintenance This Date Total Reading TYPE ACFT: PC-12/45 SERIAL#: 296 CURRENT ACFT HRS: 13356.5 LANDINGS: 8166 4 uplishe RIGHT MAIN LANDING GEAR TIRE LEAKING: REMOVED RIGHT MAIN LANDING GEAR TIRE P# 40-424 Fir Luncan INNER HUB SERIAL # 10-60 OUTER HUB SERIAL # 10-60 INSTALLED RIGHT MAIN LANDING GEAR ASSEMBLY P# 40-424 INNER HUB SERIAL # 26-46 OUTER HUB SERIAL # 26-69 REFERENCE PC12 AMM 32-40-01. AIRCRAFT IS APPROVED FOR RETURN TO SERVICE. NAME: ROBERT MARCHEWKA A&P/IA: 3350439 SIGNATURE DATE: 21 March 2014 Total to Carry Forward

TYPE ACFT: PC-12/45 SERIAL#: 296	Certificate No
CURRENT ACFT HRS: 13360.8 LANDINGS: 8215	
I CERTIFY THAT IN ACCORDANCE WITH THE APPLICABLE MAINTENANCE MANUALS THE FOLLOWING INSPECTIONS, MAINTENANCE AND OPERATIONAL TEST WHERE PERFORMED AND ALL FOUND TO BE IN INSWORTHY CONDITIONS.  - REMOVED AND REPLACED BE INSIDE FULL INDICATES. INSTALLED SERVICEABLE SET OF FUEL INDICATES FROM PRIME TURBINE (WORK ORDER NUMBER WOOD47261) REFERENCE PRIME COMM. 79-20-20 - PERFORMED ENGINE BORRESCOPE INSPECTION REFERENCE PRIME CAMM 72-00-00 - PERFORMED PULL TO FELL SERVICE BULLETIN NUMBER 72-004  NAME: ROBERT MARCHEWKA ASP/N: 3350439 SIGNATURE: MARCH SOME TO THE TOP TO THE TO	
Series and the series of the s	

**Paristration No.** 

INJE: 296 INJE:	D-1-	Aircraft	Aircraft Time	Recorder	**-11
NE LANDINGS: 8215  NCE WITH THE APPUCABLE MAINTENANCE MANUALS THE MAINTENANCE AND OPERATIONAL TEST WHERE PERFORMED AND RTHY CONDITION: REVO MOUNT (PITCH, ROLL & YAW) CLUTCH CHECK REFERENCE  8.82 BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (BIGHT INBD, OUTBO & LEFT INBD, OUTBO) PC12 ARM 27-50-03  PC12 ARM 27-50-03  FOLD DECE BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00	Date	This Date		Reading	Maintenance
INCE WITH THE APPUCABLE MAINTENANCE MANUALS THE MAINTENANCE AND OPERATIONAL TEST WHERE PERFORMED AND MITHY CONDITION.  ENVO MOUNT (PHTCH, ROLL & YAWI) CLUTCH CHECK REFERENCE  8.82 BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (RIGHT INBD, OUTBO & LEFT INBD, OUTBO)  PCL 24MM 27-50-03  FOLD ROLE BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00	TYPE ACFT: I	PC-12/45 SERIALE: 2	96		
INCE WITH THE APPUCABLE MAINTENANCE MANUALS THE MAINTENANCE AND OPERATIONAL TEST WHERE PERFORMED AND MITHY CONDITION.  ENVO MOUNT (PHTCH, ROLL & YAWI) CLUTCH CHECK REFERENCE  8.82 BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (RIGHT INBD, OUTBO & LEFT INBD, OUTBO)  PCL 24MM 27-50-03  FOLD ROLE BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00	CURRENT AC	FT HRS: 13360.8 LAN	DINGS: 8215		
AND TEMENT AND OPERATIONAL TEST WHERE PERSONAED AND WITHY CONDITION. RIVE OMDITION. RIVE ON MICHAEL & YAW) CLUTCH CHECK REFERENCE.  BAZ BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (RIGHT INBD, OUTBD & LEFT INBD, OUTBD) PC12 AMM 27-26-03 PC12 AMM 27-26-03 PC12 CAMM 27-26-03 PC12 CAMM 27-26-03 PC12 CAMM 27-26-03 PC12 CAMM 27-26-03	_				_
AND TEMENT AND OPERATIONAL TEST WHERE PERSONAED AND WITHY CONDITION. RIVE OMDITION. RIVE ON MICHAEL & YAW) CLUTCH CHECK REFERENCE.  BAZ BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (RIGHT INBD, OUTBD & LEFT INBD, OUTBD) PC12 AMM 27-26-03 PC12 AMM 27-26-03 PC12 CAMM 27-26-03 PC12 CAMM 27-26-03 PC12 CAMM 27-26-03 PC12 CAMM 27-26-03	I CERTIFY THA	AT IN ACCORDANCE W	ITH THE APPLICA	DIE MAINTENANCE	
RIVO MOUNT (PHTOR, ROLL & YAW) CLUTCH CHECK REFERENCE  1. BAZ BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (BIGHT INBD, OUTBO & LEFT INBD, OUTBO)  1. PCLZ AAM 27-50-03  1. PCLZ BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00				DATIONAL TENANCE MAN	UALS THE
IRVO MOUNT (PITCH, ROLL & YAW) CLUTCH CHECK REFERENCE  8.82 BATTERY CAPACITAINCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (BIGHT INBD, OUTBD & LEFT INBD, OUTBD)  1.PC12 AAMM 27-50-03  FOLD BICE BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00	ALL FOUND TO	D BE IN AIRWORTHY	CONDITIONS OF	RATIONAL TEST WHERE P	ERFORMED AND
8.82 BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM  AP ACTUATORS (BIGHT INBD, OUTBD & LEFT INBD, OUTBD) PCL2 AAMN 27-50-03 POLD BICE BOOTS CLEAN AND APPLY AGE MASTER SURFACE MM 30-10-00	PERFORMED	12 MONTH SERVO N	MOUNT (DITON D		
AP ACTUATORS (RIGHT INBO, OUTBO & LEFT INBO, OUTBO) FC12 AMM 27-50-03 FG12 ENCE BOOTS CLEAN AND APPLY AGE MASTER SURFACE MM 30-10-00	PC12 AMM 22	-10-00	OOM (PIICH, R	OLL & YAW) CLUTCH CHEC	X REFERENCE
AP ACTUATORS (RIGHT INBD, OUTBO & LEFT INBD, OUTBD) FC12 AMM 27-50-03 FG1L DEICE BOOTS CLEAN AND APPLY AGE MASTER SURFACE MM 30-10-00	PERFORMED	12 MONTH #1 8.#2 0	ATTENN		
AP ACTUATORS (RIGHT INBO, OUTBO & LEFT INBO, OUTBO) FC12 AMM 27-50-03 FG12 ENCE BOOTS CLEAN AND APPLY AGE MASTER SURFACE MM 30-10-00	24-30-10		ATTERY CAPACIT	ANCE CHECK REFERENCE	CONCORDE CMM
FOIL DEICE BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00	PERFORMED	12 MONTH ELAD ACT	IATORA (num		
FOIL DEICE BOOTS CLEAN AND APPLY AGE MASTER SURFACE  MM 30-10-00	BACKLASH CHE	CK REFERENCE DOLD	UATORS (RIGHT)	NBD, OUTBD & LEFT INBC	), OUTBO)
	PERFORMED 1	12 MONTH AIRCON	4MM 27-50-03		
	COATING REEER	ENCE DC12 AND OIL D	EICE BOOTS CLEA	AN AND APPLY AGE MAST	ER SURFACE
hl.M_	THE THE LIE	CHCE PC12 AMM 30-	10-00		
h.M.	NAME: DODGOT				
hh M	ARDAA: 22FO42	MARCHEWKA	111		
	ATT: 40 100 1	9 SIGNATURE:	Ma		
	MIE: 10 APR 14		11		
	IAME: ROBERT &P/IA: 335043 ATE: 10 APR 14	MARCHEWKA 9 SIGNATURE:	M	_	

Total to Carry Forward

and R Type ACFT: PC-12/45 SERIAL#: 296	rtific
CURRENT ACFT HRS: 13394.5 LANDINGS: 8234	
ECS OUTPUT AIR FLOW WEAK AT LOWER POWER SETTINGS:	
REMOVED HP SHUTOFF VALVE P# 959.90.20.131 SERIAL# 922942-5	
INSTALLED HP SHUTOFF VALVE P# 959.90.20.131 SERIAL# 1006	
REFERENCE PC12 AMM 21-40-03. AIRCRAFT IS APPROVED FOR RETURN TO	
SERVICE.	
NAME: ROBERT MARCHEWKA	
A&P/IA: 3350439 SIGNATURE:	
DATE: 28 April 2014	
	_
	_

-

			AIF	RCRAFT LOG	
	Date	Aircraft Time		Recorder	
		This Date	Total	Reading	Main
_	TYPE ACFT: P INSPECTION: CURRENT ACF		IGS: 8237		
				0 OF THE PILATUS PC12 AMN PRAME, PROPELLER AND ACCI VED FOR RETURN TO SERVICE	

ADDITIONALLY THE FOLLOWING MAINTENANCE WAS PERFORMED AND DISCREPANCY CORRECTED AND

REMOVED AND REPLACED TAXI LIGHT OPERATIONAL CHECK GOOD. REFERENCE PC12 AMM 33-42

Maintenance

and Rema

TYPE

INSE

CLIE

1.CE

HO

DUE: 100 HOURS AT 13499.0 OR ANNUAL ON 19 MAR 15.

FOUND TO BE IN AIRWORTHY CONDITION:

NAME: ROBERT MARCHEWKA A&P/IA: 3350439 SIGNATURE: DATE: 1 MAY 14

MIA Hed to

164-10

Found to

00,52

Polisho

Ac pove de

To Luncan /

Total to Carry Forward

and Remarks	Signature	Certificate No
TYPE ACT: PC-12/45 SERIALE: 296 INSPECTION: 100HR CURRENT ACT HISS: 1309.3 LANDINGS: 8309 LOGUE INSPECTION WAS COMPUED WITH THE CHAPTER 5-30 O HORITH INSPECTION WAS COMPUED WITH ON THE ENGINE, ACCESSIONES. ALL OPERATIONAL CHECKS GOOD AND THEY SERVICE, BUTCH INSPECTION DUE: 100 HOURS AT 135993-30.	ARE APPROVED FOR RETURN TO IR ANNUAL ON 19 MAR 15.	
SERVICE. NEXT INSPECTION DUE: 100 HOURS AT 1239-15 ADDITIONALLY THE FOLLOWING MAINTENANCE WAS PERFO- CORRECTED AND FOUND TO BE IN AIRWORTHY CONDITION  - CLEAN WATER SPRANCE OND CONDENSE. REFERENCE PCI.  - RE-OIL AIR CONDITIONING COLD AIR UNIT. REFERENCE PCI.  - INSPECT/CHECK HEAT EXCHANGER MATIOX. REFERENCE P.  - PERFORMED IN-SITU INSPECTION CHECK INBORAD FAR D.  - PERFORMED IN-SITU INSPECTION CHECK INBORAD FAR D.	DEMED AND/OR DISCRETATIONS: 12 AMM 21-40 C12 AMM 21-40 PC12 AMM	
27-51-00  • PERFORMED CLEAN VAPOR CYCLE COMPRESSOR CONDEN.  AMM 21-50-03  • EXAMINE GENERATOR 2 BRUSHES FOR WEAR. REFERENCY  • JAIRBORNE POSITION DATA COMMUNICATOR (PCA).  • OPS/BRIDIUM COMBINATION (ICA) ANTENNA.	ISER MODULE REFERENCE PC12	

-

#### IN AIRCRAFT LOG #d to Aircraft Time Recorder Date Maintenance 64-10 This Date Total Reading Band to and Remarks 00,57 . COCKPIT (ICA) DISPLAY PANEL. plishe . CHECK CIRCUIT BREAKER (ICA). TYPE ACET: PC-12/ Shove de CAPACITY CHECK EMERGENCY POWER SUPPLY. REFERENCE PC12 AMM 24-52 INSPECTION: 100H INSPECT LAVATORY WASTE RECEPTACLES. REFERENCE PC12 AMM 25-21 CURRENT ACFT HR Luncan / LUBRICATED ALL 4 FLAP ACTUATORS REFERENCE PC12 AMM 27-50-00 . ENGINE CHECK/CLEAN FUEL PLIMP FUEL INLET SCREEN. REFERENCE P&WC EMM I CERTIFY THAT IN REMOVED AND REPLACED 2 EACH PROP DEICE HARNESSES. REFERENCE HARTZELL EMM. HOUR INSPECTIO • REMOVED AND REPLACED LHIMLG WHEEL ASSEMBLY. REFERENCE PC12 AMM 32-40-01 ACCESSORIES, AL SERVICE, NEXT IN o REMOVED WHEEL ASSEMBLY PART# 40-424 SERIAL# 1030 ADDITIONALLY TO O INSTALLED WHEEL ASSEMBLY PART# 40-424 SERIAL# 1060 CORRECTED AND \* PERFORMED O NAME: ROBERT MARCHEWKA A&P/IA: 3350439 SIGNATURE: MALL DATE: 19 IULY 14 . EXAMINED PA . EXAMINED CA . EXAMINED FR • EXAMINED ST EXAMINED D · FXAMINED H . EXAMINED Y . EXAMINED 20-00-00 CONTINUED Total to Carry Forward

registration no.		
and Remarks	Signature	Certificate No.
TYPE ACFT: PC-12/45 SERIAL#: 296 INSPECTION: 100HR		
CURRENT ACFT HRS: 13546.9 LANDINGS: 8333		
A CERTIFY THAT IN ACCORDANCE WITH THE CHAPTER 5-20 OF THE PILATU	JS PC12 AMM A 100	

SERVICE. NEXT INSPECTION DUE: 100 HOURS AT 13646.9 OR ANNUAL ON 19 MAR 15.

ADDITIONALLY THE FOLLOWING MAINTENANCE WAS PERFORMED AND/OR DISCREPANCIES

CORRECTED AND FOUND TO BE IN AIRWORTHY CONDITION:

20-00-00 CONTINUED ON NEXT PAGE

ACCESSORIES. ALL OPERATIONAL CHECKS GOOD AND THEY ARE APPROVED FOR RETURN TO

HOUR INSPECTION WAS COMPLIED WITH ON THE ENGINE, AIRFRAME, PROPELLER AND

 EXAMINED FRONT PRESSURE BULKHEAD. REFERENCE PC12 AMM 20-00-00 EXAMINED STRUCTURE AROUND WINDOWS. REFERENCE 20-00-00

 EXAMINED VERTICAL STABILIZER INTERNAL SURFACES. REFERENCE PC12 AMM 20-00-00 EXAMINED WING INTERNAL SURFACES AND FLAP COMPARTMENTS. REFERENCE PC12 AMM

Dardstontion No.

PERFORMED OPERATIONAL TEST FUEL LOW LEVEL SYSTEM. REFERENCE PC12 AMM 28-40-00

 EXAMINED PASSENGER/CREW DOOR WITH TRIM REMOVED. REFERENCE PC12 AMM 20-00-00 EXAMINED CARGO DOOR WITH TRIM REMOVED. REFERENCE PC12 AMM 20-00-00

EXAMINED DOOR AND EMERGENCY EXIT FRAMES. REFERENCE PC12 AMM 20-00-00

EXAMINED HORIZONTAL STABILIZER INTERNAL SURFACE. REFERENCE PC12 AMM 20-00-00

ī	Т	Π	



	_	



and Remarks		Signature	Certificate N
TYPE ACFT: PC-12/45 SERIAL#: 296			
INSPECTION: 100HR			
CURRENT ACFT HRS: 13651.3 LANDINGS: 8390			
I CERTIFY THAT IN ACCORDANCE WITH THE CHAPTE			
HOUR INSPECTION WAS COMPUED WITH ON THE E	X 5-20 OF THE PILAT	US PC12 AMM A 100	
ACCESSORIES. ALL OPERATIONAL CHECKS GOOD AN	ID THEY ARE ARROSO	ROPELLER AND	
SCHARCE MEXI INSPECTION DUE: 100 HOURS AT 13	746 9 OR ANNUAL O	N 10 MAD 15	
ADDITIONALLY THE FOLLOWING INSPECTIONS WHEN	OF DEBEGORATO AND	IN 19 MAR 15.	
CONNECTED AND ALL FOUND TO BE IN AIRWORTHY	CONDITION:		
<ul> <li>REMOVED AND REPLACED ELECTRONIC ATTITUDE I</li> <li>AMM 34-26-03</li> </ul>	DIRECTIOAL INDICATE	OR REFERENCE PC12	
BENOVED 549-9-1			
PREMOVED EADI PART# SERI			
	AL#		
REMOVED AND INSTALLED NLG WHEEL ASSEMBLY R REMOVED NLG WHEEL ASSEMBLYPART# 3-1501 SER	REFERNECE PC12 AM	M 32-40-02	
INSTALLED NLG WHEEL ASSEMBLY PART# 3-1501 SER	IIAL# 0627	1	
THE WHILE AGSEMBLY PARTY 3-1501 SE	RIAL#		
ME: ROBERT MARCHEWKA  IP/IA: 35350439 SIGNATURE:		+	

INSPECTION: 100	/45 SERIALE: 296 HR		ntenance
INSPECTION: 100	HR.		
CURRENT ACET HE			and the second second
	S: 13746.8 LANDINGS: 8438		
ALL OPERATIONAL DUE: 100 HOURS ADDITIONALLY THE	ACCORDANCE WITH THE CHAPTER S- COMPLIED WITH ON THE ENGINE, AIR CHECKS GOOD AND THEY ARE APPRE IT 13846.9 OR ANNUAL ON 19 MAR 1 FOLLOWING INSPECTIONS WHERE P D BE IN AIRWORTHY CONDITION:	WED FOR RETURN TO SERV	ICE. NEXT INSPECTION
PERFORMED NO.     PERFORMED OPE     PERFORMED OPE     PERFORM NO.1 E     PERFORMED CHEC     PERFORMED CHEC     PERFORMED CAPA	ROSION INSPECTION (EXTERNAL) BE I PROPELLER DETAILED INSPECTION IN PROPELLER UNBERCATION REFEREN RATION TEST POWER PLANT TORQUE ATTOMATIONAL TEST POWER PLANT TORQUE ATTOMATIONAL TEST POWER PLANT PERFORMED FOR PROPERTY OF THE PROPERTY OF T	EFFERNCE MARIZELL CMI E PC12 AMM 12-20-05  LUMITER REFERENCE PC12  ORMANCE REFERENCE PC WEAR REFERENCE P WEAR REFERENCE PC12 AI  REFERENCE CONCORDE CM REFERENCE CONCORDE CM	(AMM 71-00-00 12 AMM 71-00-00 C12 AMM 79-30-01 MM 24-30-01 MM 24-30-18 MM 24-30-18

funcan /

PERFORMED #1 ENGINE INSPECT POWER TURBINE BLADES REFERENCE P&WC CMM 72-00-00	Certificate No
PERIORMED BI ENGINE (LLEMPILINCTIONAL CHICK SPARK IGNITIES REFERENCE PCIZ AMM 74:00:00     PERIORMED INSPECT RZ GENERATOR BRUSHES FOR WLAR REFERENCE PCIZ AMM 24:00:00     PERIORMED INSPECTION CHICK INDIAND FUR AMM EREFERENCE PCIZ AMM 27:50:00     LUBICATED ALL FLAR ACTUATORS REFERENCE PCIZ AMM 27:50:00     LUBICATED ALL FLAR ACTUATORS REFERENCE PCIZ AMM 27:50:00     APPUED OR MARTER TO AIRPOLO DICE SCOTS REFERENCE PCIZ AMM 30:50:00	- 4
NAME: ROBERT MARCHEWKA ARPINE: 3350439 SIGNATURE: R.J. ARL DATE: 6 NOVEMBER 14	

VIA ded to 64-10 hued tr 100, S7 phishe

		Aircraft Time Recorder	
vate	This Date	Total Reading	Maintenance
INSPECTION: CURRENT AC  I CERTIFY TH INSPECTION OFFRATIONAL 200 HOURS ADDITIONAL AND ALL FO PERFORM - LUBRICATI NAME: POI ASP/IA: 33	NSPECTION WAS COMPUED WITH ON  PPERATIONAL CHECKS GOOD AND THE  OD HOURS AT 19931.2 OR ANNUALO  ADDITIONALLY THE FOLLOWING INSPENDING  AND ALL FOUND TO BE IN AIRWORTHM  PERFORMED IN SITU INSPECTION CO- LUDRICATED ALL 4 FLAP ACTUATORS	THE CHAPTER S-20 OF THE PILATUS P THE ENGINE, AIRFRAME, PROPELLER, LY ARE APPROVED FOR RETURN TO SE IN 19 MAR 1S. ECTIONS WHERE PERFORMED AND/OH CONDITIONS: MECK INDOARD FLAP DRIVE ARMS REFI MECK INDOARD FLAP DRIVE ARMS REFI	AND ACCESSORIES. ALL RIVICE. NEXT INSPECTION DUE:

egistration	No
-------------	----

d Remarks	Certificate No
TYPE ACFT: PC-12/45 SERIALE: 296	
INSPECTION: 100HR CURRENT ACFT HRS: 13923.2 LANDINGS: 8584	91
I CERTIFY THAT IN ACCORDANCE WITH THE CHAPTER 5-20 OF THE PRATUS PC12 AMM A 200 HOUR INSPECTION WAS COMPILED WITH ON THE ENGINE, AIRFRAME, PROPELLER AND ACCESSORIES. ALL OPERATIONAL CHECKS GOOD AND THEY ARE APPROVED FOR RETURN TO SERVICE, NEXT INSPECTION DUE	
100 HOURS AT 14023.2 OR ANNUAL ON 19 MAR 15.	
ADDITIONALLY THE FOLLOWING INSPECTIONS WHERE PERFORMED AND/OR DISCREPANCIES CORRECTED AND ALL FOUND TO BE IN AIRWORTHY CONDITION:	
PERFORMED CLEAN VAPOR CYCLE COMPRESSOR CONDENSER MODULE REFERENCE PC12 AMM 21-50-0     PERFORMED IN-SITU INSPECTION CHECK INBOARD FLAP DRIVE ARMS REFERENCE PC12 AMM 27-51-00	8
PERFORMED IN-101 INSPECTION CHICAGONIA TO THE CONTROL OF THE	
NAME: ROBERT MARCHEWRA REPUR: 3350439 SIGNATURE:	
ABP/IA: 3350439 SIGNATURE: ////////////////////////////////////	-

l-10 ed tr 0, S/1 plishe

ove de

incan A

	Aircraft	Time	Recorder	Maintenance	
Date	This Date	Total	Reading	Waintenance	
	Brought Forward				
II		.0 LANDINGS:	CHAPTER 5-20 OF THE PILATUS	K AND ACCESSORIES. MEE	
1	OPERATIONAL CHECKS GOOD AND THEY ARE APPROVED FOR RETURN TO SERVICE. NEXT INSPECTION DE 100 HOURS AT 14123. OR ANNUAL ON 19 MAR 15.  ADDITIONALLY THE FOLLOWING INSPECTIONS WHERE PERFORMED AND/OR DISCREPANCIES CORRECTED AND ALL FOUND TO BE IN AIRWORTHY CONDITION:  • PERFORMED IN-SITU INSPECTION CHECK INBOARD FLAP DRIVE ARMS REFERENCE PC12 AMM 27-51-00  • LUBRICATED ALL 4 FLAP ACTUATORS REFERENCE PC12 AMM 27-50-00  • APPLIED AGE MASTER TO AIRFOIL DEICE BOOTS REFERENCE PC12 AMM 30-10-00  • REMOVED/CLEANED/INSPECTED AND INSTALLED PRESSURIZATION OUTFLOW VALVE AND SAFETY VAL				
R •	PERFORMED FUNCTIONA  AME: ROBERT MARCHEV  AP/IA: 3350439 SIGNAT	30-02 AND 21-3 L CABIN POSITIV	N-N3	EFERENCE PC12 AMM 21-30-00	
to Dy Forward	ATE: 11 FEBRUARY 15				

Registration No.
------------------

nd Ren	TYPE ACFT: PC-12/45 SERIAL#: 296	ficate No.
	INSPECTION: ANNUAL/100HR	
	CURRENT ACFT HRS: 14085.3 LANDINGS: 8629	
	I CERTIFY THAT IN ACCORDANCE WITH THE CHAPTER 5-20 OF THE PILATUS PC12 AMM AN ANNUAL AND 100 HOUR INSPECTIONS WHERE COMPLIED WITH ON THE ENGINE, AIRFRAME, PROPELLER AND ACCESSORIES.  ALL OPERATIONAL CHECKS GOOD AND THEY ARE APPROVED FOR RETURN TO SERVICE.  NEXT INSPECTION DUE: 100 HOURS AT 14185.3 OR ANNUAL ON 8 MAR 16.	
	ADDITIONALLY THE FOLLOWING INSPECTIONS WHERE PERFORMED AND DISCREPANCIES CORRECTED AND ALL FOUND TO BE IN AIRWORTHY CONDITION:	
	PERFORMED CORROSION INSPECTION (INTERNAL) REFERENCE PC12 AMM 20-40-00     PERFORMED CORROSION INSPECTION (INTERNAL)	
	PERFORMED CORROSION INSPECTION (EXTERNAL) REFERENCE PC12 AMM 20-40-00     PERFORMED SR 57 006 FLAR SURPORTS INSPECTION OF THE PROPERTY OF	
	PERFORMED SB 57-006 FLAP SUPPORTS. INSPECTION OF THE FLAP SUPPORT ARM ATTACHMENTS     PERFORMED FAA 2001 35 10 INSPECT FLAP ACTUATOR INTERPRETATION OF THE FLAP SUPPORT ARM ATTACHMENTS.	
	PERFORMED FAA 2001-25-10 INSPECT FLAP ACTUATOR INTERNAL GEAR SYSTEM     PERFORMED ALL 4 FLAP ACTUATORS BACKLASH SUISK REFERENCE BOXES AND ACTUATORS BACKLASH SUISK BAC	
	<ul> <li>PERFORMED ALL 4 FLAP ACTUATORS BACKLASH CHECK REFERENCE PC12 AMM 27-50-03</li> <li>LUBRICATED ALL 4 FLAP ACTUATORS REFERENCE PC12 AMM 27-50-00</li> </ul>	
	• PERFORMED SERVO MOUNT (PITCH, ROLL & YAW) CLUTCH CHECK REFERENCE PC12 AMM 22-10-00	
	• PERFORMED #1  BATTERY CAPACITANCE CHECK REFERENCE CONCORDE CMM 24-30-10	
	• PERFORMED EMERGENCY POWER SUPPLY CAPACITANCE CHECK REFERENCE PC12 AMMS 050-0233	
	• APPLIED AGE MASTER TO AIRFOIL DEICE BOOTS REFERENCE PC12 AMM 30-10-00	
	CONTINUED TO NEXT PAGE	
	그리고 그는 그리고 그리고 그리고 있다. 그는 그리고 전에 그렇게 되었다. 그리고 있었다. 그리고 있는 나는 그는 그리고 있다면 하지 않는 것이 없다.	

to 1-10 ed tr 0, S/1 plishe

ove de

ancan A

Date	Aircraft Time		Recorder	
Date	This Date	Total	Reading	Maintenance
	Brought Forward			
	PERFORMED FIRE B PERFORMED FUNCT REFERENCE PC12 AM PERFORMED INSPE PERFORMED NO.1 PERFORMED NO.1 PERFORMED OPER PERFORMED OPER PERFORMED CLEAN CONNECTORS REFER PERFORM FUNCTIO PERFORMED CHEC PERFORMED CHEC PERFORMED EXAM PERFORMED EXAM PERFORMED LH, RI AND 32-40-02 PERFORMED CLEAN	5A-72-14495R1 INSP OTTLE INSPECTION/ TIONAL TEST HORIZO IM 27-40-00 CTION/CHECK MAIN PROPELLER DETAILED PROPELLER LUBRICA ATION TEST POWER ATIONAL TESTS POW IN ENGINE TORQUE A ENCE PC12 AMM 71 ONAL TEST PROPELLE GINE BRIDGE CHECK K STARTER GENERAT INE GENERATOR 2 E INE THE PROTECTIV IN AND NOSE LANDIN IN VAPOR CYCLE CON	ECTION OF FUEL NOZZ CONTENTS CHECK REF ONTAL STABILIZER TRIN  LANDING GEAR AXLE A D INSPECTION REFEREN TION REFERENCE PC12 PLANT TORQUE LIMITI VER PLANT PERFORMA ND STICK PUSHER TOF -00-03 ER FEATHERING MICRO MAGNETIC CHIP DETE FOR FOR BRUSH WEAR BRUSHES FOR WEAR RE E LAYER GENERATOR 2 INTERESSOR CONDENSE	ERENCE PC12 AMM 26-20-00  M RUNAWAY AURAL WARNING SYSTEM  AND BUSHES REF PC12 AMM 32-10-00  NCE HARTZELL CMM 139 61-00-39
to Forward	CONTINUED TO NEX	T PAGE		

Registration	No.	TAPONA	
--------------	-----	--------	--

and Remarks	Signature	Certificate No.
REMOVED AND REPLACED FORWARD AND AFT BELLY DRAIN SEALS PARTE AMM 53-00  PERFORMED AD 2014-22-01 DOCKET# FAA 2014-0594; DIRECTORATE IDE AMENDMENT 39-18005; AD 2014-22-01  REMOVED AND REPLACED ENGINE OIL COOLER REFERENCE PC12 AMM 70 REMOVED OIL COOLER PART# 968.32.14.102 SERIAL# T0195  REMOVED AND REPLACED ENGINE DRIVEN FUEL PUMP REFERENCE PC12 REMOVED AND REPLACED ENGINE DRIVEN FUEL PUMP REFERENCE PC12 REMOVED FUEL PUMP PART# RG5970R1/M SERIAL# B4863  O INSTALLED FUEL PUMP PART# RG5970R1/M SERIAL# B4489  REMOVED AND REPLACED #1 ENGINE REFERENCE PC12 AMM 72-10-00 REMOVED ENGINE PART# PT6A-67B SERIAL# PCE-PR0132  O INSTALLED ENGINE PART# PT6A-67B SERIAL# PCE-PR0284  NAME: ROBERT MARCHEWKA  A&P/IA: 3350439 SIGNATURE:  DATE: 08 MAR 15	ENTIFIER 2014-CE-22-AD; 79-20-02 2 AMM 28-20-03	PC12



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14181.4 TCSN: 8676

Recorder Aircraft Time I certify that in accordance with the chapter 05 of the Pilatus PC12 AMM a 100 hour inspection was accomplished on the engine, airframe, propeller and accessories. All operational & leak checks good and they are approved for return to service.

Next Inspection due: 100 hours at 14281.4 airframe hours or annual inspection on 19 March 2016.

Additionally, the following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- Cleaned air-conditioner compressor/condenser VCCS module motor REF PC12 AMM CH 21-50-03
- Performed IN-STU inspection of inboard flap drive arms with no defects noted REF PC12M CH 27-51-00
- Lubricated right inboard & outboard, left inboard & outboard flap actuators REF PC12 AMM CH 27-50-00

Name: Pohort M	archauka	airfoils deicer surface		30-10-00	
A&P/IA cert#: 33 Date: 11 April 20	50439 <b>Signature</b> : 15	Robert. M	1		
Total to Carry Forward					

TYPE ACFT CURRENT

#2 AHRS I

REFEREN

NAME: A&P/IA

DATE:

TYPE ACFT: PC-12/45 SERIAL#: 296 CURRENT ACFT HRS: 14181.4 LANDINGS: 8680 **#2 AHRS INOPERABLE:**  REMOVED #2 AHRU LCR-92 PART# 1-24210-2022 SERIAL# 1055 INSTALLED #2 AHRU LCR-92 PART# 1-24210-2022 SERIAL# 1422 REFERENCE PC12 AMM 34-25-01. OPERATIONAL CHECKS GOO AND AIRCRAFT IS APPROVED FOR RETURN TO SERVICE. NAME: DANIEL MILLIGAN A&P/IA: 3117448 SIGNATURE: DATE: 13 APRIL 15



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14237.4 TCSN: 8705

I certify that in accordance with the chapter 05 of the Pilatus PC12 AMM a 100 hour inspection was accomplished on the engine, airframe propeller and accessories. All operational & leak checks good and they are approved for return to service.

Next Inspection due: 100 hours at 14337.4 airframe hours or annual inspection on 19 March 2016.

Additionally, the following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- Cleaned air-conditioner compressor/condenser VCCS module motor REF PC12 AMM CH 21-50-03
- Performed IN-STU inspection of inboard flap drive arms with no defects noted REF PC12M CH 27-51-00
- Lubricated right inboard & outboard, left inboard & outboard flap actuators REF PC12 AMM CH 27-50-00
- Applied Age Master coating to airfoils deicer surfaces REF PC12 AMM CH 30-10-00
- Removed and replaced right engine igniter lead assembly with new REF PC12 AMM 74-20-00
  - Removed P/N CH53399-02, S/N A7 and installed P/N CH53399-02, S/N 17397

Name: Robert Marchewka

A&P/IA cert#: 3350439 Signature:

Brought

Date: 6 May 2015

Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14275.9 TCSN: 8730

The following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- Removed and replaced RH inboard flap actuator for time change REF PC12 AMM 27-50-03
  - Removed P/N 978.73.20.309, S/N 1065
  - Installed P/N 978.73.20.309, S/N 1730 TTSN: 12110.4 TCSO: 6162 TTSO: 0.0 TCSO: 0
- Removed and replaced flap power drive unit for time change REF PC12 AMM 27-50-01
  - Removed P/N 978.73.20.003, S/N 0043
  - Installed P/N 978.73.20.309, S/N 0433 TTSN: 10929 TCSN: 12127 TTSO: 120.9 TCSO: 0

Name: Robert Marchewka

A&P/IA cert#: 3350439 Signature:

Date: 18 May 2015





The following

Name: R

A&P/IA Date: 21

I certify 1 propelle **Next Ins** 

Additio

Name

A&P

Date



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14287.6 TCSN: 8737

The following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

Compass swing check performed REF PC12 AMM 34-25-00

ATC transponder check performed REF PC12 AMM 34-54-00

Name: Robert Marchewka

A&P/IA cert#: 3350439 Signature:

Date: 21 May 2015



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14331.2 TCSN: 87672

I certify that in accordance with the chapter 05 of the Pilatus PC12 AMM a 100 hour inspection was accomplished on the engine, airframe, propeller and accessories. All operational & leak checks good and they are approved for return to service.

Next Inspection due: 100 hours at 14431.2 airframe hours or annual inspection on 19 March 2016.

Additionally, the following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- Cleaned air-conditioner compressor/condenser VCCS module motor REF PC12 AMM CH 21-50-03
- Performed IN-STU inspection of inboard flap drive arms with no defects noted REF PC12M CH 27-51-00
- Lubricated right inboard & outboard, left inboard & outboard flap actuators REF PC12 AMM CH 27-50-00
- Applied Age Master coating to airfoils deicer surfaces REF PC12 AMM CH 30-10-00

Name: Robert Marchewka

A&P/IA cert#: 3350439 Signature:

Date: 8 June 15



4-10 led tr 0, S/1 plishe

pove de

incan /

No Applied Solutions Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14331.2 TCSN: 8767
The following inspections where performed and/or discrepancies corrected and all found to be in all all all all all all all all all al
The following inspections where performed and or close eparatics deviced and an round to be in airworthy condition:  Removed and replaced flap power drive unit for popping circuit breaker several times REF PC12 AMM 27-50-01  Removed P/N 978.73.20.003, S/N 0433
ed tr = 0 Removed P/N 978.73.20.003, S/N 0433 o Installed P/N 978.73.20.309, S/N 1064 TTSN: 1705.2 TCSN: 2794 TTSO: 0.0 TCSO: 0
Removed and replaced defective left strobe light P/N 972.87.87.322 REF PC12 AMM 33-43-02
She Name: Robert Marchewka
Name: Robert Marchewka  A&P/IA cert#: 3350439 Signature:
Date: 8 June 2015
Nam
A&p
Date
<b>ETEMPUS</b>
Applied Solutions Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14261.3 TCSN: 8718
The following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:  • ECS over temperature switch P/N 973.81.32.122 due time change and replaced with new REF PC12 AMM 21-40-06
Replaced cabin altitude switch for failing on high side of test REF PC12 AMM 21-40-06  Replaced cabin altitude switch for failing on high side of test REF PC12 AMM 21-30-07
o Removed P/N 965.23.21.533, S/N 1004240 & Installed repaired P/N 965.23.21.533, S/N 1026315
Replaced cabin differential switch for failing on low side of test REF PC12 AMM 21-30-08
o Removed P/N 965.23.21.534, S/N 1004254 & Installed repaired P/N 965.23.21.534, S/N 1033406
Removed and replaced oil cooler supply line 946.37.70.103 for chaffing.
Name: Robert Marchewka
A&P/IA cert#: 3350439 Signature:
Date: 12 June 2015
Total to
Carry Forward

	Registration No.	5° - C 20
0-01	<b>ETEMPUS</b>	
ice	Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14420.1  The following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:	TCSN: 8821
	<ul> <li>Removed and replaced TCAS processor for being inoperable REF PC12 AMM 34-44-01</li> <li>Removed P/N 066-01178-2102, S/N 80024</li> </ul>	
	Name: Robert Marchewka  A&P/IA cert#: 3350439 Signature:	
	Date: 20 June 2015	
V: 8718 -		
		1

. 0/0/

led dr mi

d tr , S/1

lishe

we de

incan A

d . v . o

Date	Δircraft	Time	Recorder	
MUAG	This Date	Total	Reading	Maintenance
<b>ETEMP</b>	PUS>			
Applied	Type ai	rcraft: PC12 Ser	rial# 296 Registratio	on# N840AG TTSN: 14420.1 TCSN: 8821
Removed loaner				
Pilatus PC12 AMI	M 71-00-00.	rovernauled engi	ne. All performance r	runs and adjustments completed reference
	ed engine P/N PT6A	-67B, S/N PCE-PR	0284	
				TCSN: 10051 TTSO: 0.0 TSCO: 0.0
Removed and re	placed engine shock	mounts with nev	w. Reference Pilatus P	PC12 AMM chapter 71-00-02
Remove	ved RH lower engine	shock mount P/N	N 944.81.21.409, S/N 3	3756 and installed P/N 944.81.21.409, S/N 7763
Remove	ved RH upper engine	shock mount P/I	N 944.81.21.409, S/N	3661 and installed P/N 944.81.21.409. S/N 7785
Remove	ved top engine shoc	k mount P/N 944.	.81.21.409, S/N 3761 a	and installed P/N 944.81.21.409, S/N 7807
Remove	ved LH lower engine	shock mount P/N	N 944.81.21.409, S/N 3	3771 and installed P/N 944.81.21.409, S/N 7802
All operational a	ved LH lower engine	ormed with no do	N 944.81.21.409, S/N 3	3666 and installed P/N 944.81.21.409, S/N 7778 is approved for return to service.
All operational a	and leak cheeks peri	offied with no de	erects noted. Aircraft	is approved for return to service.
Name: Robert I				
A&P/IA cert#:	3350439 <b>Signatur</b>	" Roll M	11	
Date: 18 Augus	st 2015	100 11 -11	M	
Total to				
Carry Forward		3		보는 사람들이 되는 것이 살아보고 있다면 하는 것이 없었다.

Registration	No.	



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14420.1 TCSN: 8821

I certify that in accordance with the chapter 05 of the Pilatus PC12 AMM a 100 hour inspection was accomplished on the engine, airframe, propeller and accessories. All operational & leak checks good and they are approved for return to service. Next Inspection due: 100 hours at 14520.1 airframe hours or annual inspection on 19 March 2016.

Additionally, the following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- Performed P&WC SB PT6A-72-14507 (inspection of interconnect rod) with no defects noted
- Performed Pilatus PC12 SB 27-022 (Aileron control universal joint replacement) verified affected part not installed
- Performed GPS/Iridium combination antenna ICA with no defects noted
- Replaced generator 2 drive assembly aft and forward bearings REF PC12 AMM CH 24-30-04
- Cleaned air-conditioner compressor/condenser VCCS module motor REF PC12 AMM CH 21-50-03
- Checked starter/generator brushes for wear with no defects noted REF PC12 AMM CH 24-30-01
- Performed IN-STU inspection of inboard flap drive arms with no defects noted REF PC12M CH 27-51-00
- Lubricated right inboard & outboard, left inboard & outboard flap actuators REF PC12 AMM CH 27-50-00
- Accomplished a detailed inspection of the #1 propeller with no defects noted REF Hartzell HC-E4A-3D CMM
- Lubricated #1 propeller REF Hartzell HC-E4A-3D CMM
- Inspected lavatory waste receptacles with no defects noted REF PC12 AMM CH 25-21-00
- Performed external corrosion inspection with no defects noted REF PC12 AMM CH 20-40-00
- Applied Age Master coating to airfoils deicer surfaces REF PC12 AMM CH 30-10-00

Name: Robert Marchewka

Date: 18 August 2015


to 1-10 ed tr 0, S/1 plishe

love de

ancan A

		AINONAF		
Date	Aircraft Time	Control of the Contro	corder	Maintenance
Applied Solution	Type aircraft: F	C12 Serial# 296	Registration# N840	AG TTSN: 14432.8 TCSN: 8831
<ul> <li>Removed and r</li> </ul>	epiacea oxygen cymiae.	ALT 201 12006		
				15 Expiration date: 24 Nov 29 er aft corner REF PC12 AMM 52-10-03
Name: Robert Marche	wka			
A&P/IA cert#: 335043 Date: 18 Nov 2015	9 Signature.			
tal to arry Forward				

and Remarks		Signature	Certificate No.
TEMPU Applied Solution	Type aircraft: PC12 Serial# 296 Registration	on# N840AG <b>TTSN:</b> 14432.8	TCSN: 8831
Reviewed AD 2015  Reviewed AD 2015  Complied with AD 2 Limitations/Airword arms with no defect Reviewed AD 2013- Complied with AD 2 Reviewed AD 2012- action is required. Reviewed AD 2010-0 by model and/or inst Reviewed AD 2010-0 installed equipment.	where performed and/or discrepancies corrected and all for 19-15 found aircraft is not on affected aircraft serial number list and does not ago 14-10 found aircraft is not on affected aircraft serial number list and does not ago 14-22-01 and verified insertion by Pilatus of new limitations for the inboard flatchiness Limitations Document aircraft maintenance manual and into CAMP maintenance reference Pilatus PC12 AMM 27-51-00. No further action required. 19-10 found aircraft is not on affected aircraft serial number list and does not apo 12-26-15R1 and rescinded AD 2012-26-15 no further action is required. 14-15 and found Honeywell global navigation satellite sensors P/N 066-01201-01 (17-09 found aircraft is not on affected aircraft serial number list and does not appead found this only effects PC-12/47E models with Honeywell Primus EPIC and called equipment. No further action required (18-02 found this only effects PC-12/47E models with Honeywell Primary Flight Dis No further action required.	oply IAW SB 27-022. No further action requipply IAW SB 27-021. No further action requip drive arm into the Structural and Comportence tracking. Performed inspection of Rhaply IAW SB 34-038. No further action is requipply IAW SB 76-001. No further action requipply IAW SB 76-002.	ired. ired. ired. ient  I & LH inboard flap drive  uired.  does not apply. No further  red. es not apply to this aircraft
Complied with AD 20	-19 found aircraft does not have affected Garmin transponder installed. No fur	ther action is required.	
Name: Robert Marchew A&P/IA cert#: 3350439	Signature: Loff Manual		
Names Debant Manches	Signature: Loff My		



ed tr 0, S/1

lishe

ove de

Incan /

Total to

**Carry Forward** 

語語の表

**A** 

the airfram Next inspe

Additional

÷

•

•

.

:

:

Name: A&P/IA

Date:



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14434.5 TCSN: 8834

I certify that in accordance with the chapter 5-20 of the Pilatus PC 12 AMM an annual and 100 hour inspections where complied with on the airframe, engine, propeller and accessories. All operational checks good and they are approved for return to service.

Next inspection due: 100 hours at 14534.5 or annual on 30 January 2017.

Additionally, the following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- 12 month corrosion inspection (Internal) REF PC12 AMM 20-40-00
- 12 month corrosion inspection (External) REF PC12 AMM 20-40-00
- 12 month ELT test REF PC12 AMM 25-63-00
- 12 month fire bottle inspection REF PC12 AMM 26-20-00
- 12 month functional test horizontal stabilizer trim runaway aural warning system REF PC12 AMM 27-40-00
- 12 month inspection/check main landing gear axle and bushes REF PC12 AMM 32-10-00
- 12 month operational test power plant torque limiter REF PC12 AMM 71-00-00
- 12 month operational test power plant performance REF PC12 AMM 71-00-00
- 12 month clean torque and stick pusher transducers electrical connectors REF PC12 AMM 71-00-03
- 12 month functional test propeller feathering micro switches REF PC12 AMM 76-10-02
- 12 month No. 1 engine bridge check magnetic chip detector REF PC12 AMM 79-30-01
- 200hr check starter generator for brush wear REF PC12 AMM 24-30-01
- 12 month LH, RH and nose landing gear wheel bearing lubes REF PC12 AMM 32-40-01 AND 32-40-02
- Cleaned air-conditioner compressor/condenser VCCS module motor REF PC12 AMM CH 21-50-03
- Checked starter/generator brushes for wear REF PC12 AMM CH 24-30-01
- IN-STU inspection of inboard flap drive arms REF PC12M CH 27-51-00
- Lubricated right inboard & outboard, left inboard & outboard flap actuators REF PC12 AMM CH 27-50-00
- Applied Age Master coating to airfoils deicer surfaces REF PC12 AMM CH 30-10-00
- #1 Engine inspect power turbine blades REF P&WC CMM 72-00-00
- #1 & #2 battery capacitance check REF CONCORD CMM 24-30-18
  - o Battery voltage fluctuates on EIS panel. Replaced bad resistor R304, op check good REF PC12 AMM 24-00-00

Name: Robert Marchewka

A&P/IA cert#: 3350439 Signature:

Date: 30 January 2016

	Aircra	ft Time	Recorder	
Date	This Date	Total	Reading	Maintenance
	Brought Forward			
	I FIND REQUIRE REQUEST CERTIFI	MENTS FOR T ED AND HAVE CATE OF AIR	S/N 296 T THIS AIRCRAFT MEETS THE S FOR THE CERTIFICATION ND HAVE ISSUED A EXPORT OF AIRWORTHINESS FAA FORM	
	THE NEX	T ANNUAL IN	DATED 03/FEB/20: SPECTION IS DUE RT523002WP	16. JAN/2017.
	7,000		Live	
otal to				

Tot Ca



The following inspec

- 12 Month
- Fuel low
  - Performe
    - 0
    - 0
    - Clutch ir LH & RH
  - 36 mon
  - 12 Mon
  - Service
- Applied
- ECS Ter
  - (
- Complemask v
- Complex
   was for
- Comp

and h lame: Robert

A&P/IA cert#:

Date: 09 Febr



Type aircraft: PC12 Serial# 296 Registration# N840AG TTSN: 14434.5 TCSN: 8834

The following inspections where performed and/or discrepancies corrected and all found to be in airworthy condition:

- 12 Month emergency power supply capacitance check REF PC12 AMM CHAPTER 52-51.
- Fuel low level warning system operation test REF PC12 AMM CHAPTER 28-40.
- Performed ICA inspections on the follow items:
  - Airborne position data communicator,
  - Cockpit panel display
  - Circuit breaker panels
  - GPS/Iridium combination antenna
- Clutch inspection of the aileron, elevator and rudder auto flight servos REF PC12 AMM CHAPTER 22-10.
- LH & RH MLG shock absorber upper and lower attachment bolts inspection REF PC12 AMM CHAPTER 32-10.
- 36 month inspection/check of passenger oxygen mask REF PC12 AMM CHAPTER 35-20.
- 12 Month inspection of ELT transmitter REF FAR 91.207.
- Serviced flap up and down limit switches REF PC12 AMM CHAPTER 27-50
- Applied Age Master coating to airfoil deicer surfaces REF PC12 AMM CH 30-10-00
- ECS Temperature control valve stuck. Replaced valve operational checks good, REF PC12 AMM CHAPTER 21-60.
  - Removed temperature control valve P/N 5829C000, S/N 613098-1
  - o Installed overhauled temperature control valve P/N 6031C000-001, S/N 1992, TSO: 0.0
- Completed AD 2015-08-07 (Inspect the inflatable harnesses fitted to each oxygen mask regulator). Pilots and Co-pilots oxygen mask where not manufactured and/or repaired during the affected date. No further action required.
- Completed P&WC SB 14269R6 P3 air pressure tube assembly replacement. Engine model PT6A-67B Serial number PRE-0132 was found to not be on the affected serial number range and line not required to be replaced. No further action required
- Completed P&WC SB 14496R3 FUEL pump inspection/replacement. Affected HAMILTON SUNSTRAND fuel pump not installed and higher durability ARGOTECH fuel pump is installed. No further action is required.

Name: Robert Marchewka

A&P/IA cert#: 3350439 Signature:

Date: 09 February 2016

	This Dat	te Total	296 Registration# N	N840AG TTSN: 14434.5	CSN: 900
The following i	nspections where per	rformed and/or discrepancies MD 540 weather radar KAC-5	corrected and all found to	o be in airworthy conditions	0834
• Ren	rns. REF Pilatus PC12	rformed and/or discrepancies MD 540 weather radar KAC-5 2 AMM chapter 34-41.	01 card P/N 071-00159-01	111 for radar failing self test ar	nd showing no
			1		showing no =
A&P/IA cert#	3350439 Signat	ure: LAA. M			
Date: 5 April	2016	, , , , , ,			
					The fo
-					
					Nam A&P,

showing no	and Remarks	Rection	Signature	Certificate No
	TEMPUS Applied Solutions Type aircraft: PC12	Serial# 296 Registration	on# N840AG TTSN: 14434.5	5 <b>TCSN:</b> 8834
	The following inspections where performed and/or discrete FAA 2016-11-20 Physically inspect the PBE poservice bulletin NO. 119003-35-011 REV 000 c is required.  The following inspections where performed per Pilater Performed 72 month examine left main landing Performed Performed 72 month examine left main landing Performed Perfo	ouch to determine if it has an idated February 4, 2015 PARA etus PC12 AMM Chapter 32-1ing gear leg forward and rear a ing gear leg forward and rear a gactuator top and bottom at	intact vacuum seal in accordanc III.A.1. Equipment not installed 0-00: attachment bolts and nuts with a attachment bolts and nuts with n tachment bolts and nuts with n	and no further action of defects noted.  In o defects noted.  In o defects noted.
	Performed 72 month examine right main landing     Performed 72 month examine left main landing  Name: Robert Marchewka	g actuator top and bottom at	ttachment bolts and nuts with n	o defects noted.
	A&P/IA cert#: 3350439 Signature:	///		

MAYO	Aircraft Lime	recorder	
This	Date   Total	' Reading	
Tempus Jets		Work Order No.	and the second s
Pilatus PC-12, S/N: 296		AV7521	Date: Aug 4, 2016
N840AG			ACTT: 14477.8
			LDGS: 8847 c pressure altitude reporting systems, IAW and found to comply with Title 14 CER's
endices E and F. em certified to 30,000FT			c pressure altitude reporting systems, IAWT and found to comply with Title 14 CFR Part
: Alt Make/Model: KEA-346	Pilot XPDR Make/N	Model: KT-70	
Alt P/N: 066-03062-0010	Pilot XPDR P/N: 06	66-01141-0201	
Alt S/N: 4197	Pilot XPDR S/N: 30	)487	
lot Alt Make/Model: United	CoPilot XPDR Mak	e/Model: KT 70	territorio de transferio de descripción de como
lot Alt P/N: 5035P-P50	CoPilot XPDR P/N:	066-01141-0201	
ot Alt S/N: 29639	CoPilot XPDR S/N:	30303	and the second s
ify that the above work has been work performed."	performed in accordance with	stated references, current FAA Re	egulations, and is approved for return to service wi
nent details on file at this repair st	ation under work order AV752	1.	and the second control of the second control
ed Ma Or			그리아 그리아 그는 그 그 사람
	rhomas J Olmstead, A	vionics Inspector. CRS PE5R116N	V

dish

ove (

**Carry Forward** 

TEMPUSJETS

Registration #: N840AG

Hobbs: 4477.8

VCCS Hours: 802.3

Total Aircraft Time: 14477.80

13303.8 **Total Engine Time:** 

Total Propeller Time: 2124.6

Work Order #: 3170

**Total Aircraft Cycles: 8847 Total Engine Cycles: 10077** 

Total Propeller TSOH: 44.5

Date: 8/11/2016

# PC-12/45, S/N 296

- -Performed a 100 Hour Inspection using the Pilatus PC-12/45 100 hour checklist.
- -Airworthiness Directive compliance checked through Revision 2016-16.
- -Serviced aircraft oxygen referencing Pilatus PC-12 AMM Section DMC-12-A-12-10-05-00A-902A-A.
- -Complied with continued airworthiness inspection requirements for installed equipment as required.

## Aircraft Airworthiness Directives and Service Bulletins

- -Complied with Pilatus AD 2016-12-01 Inspection of wing fitting torlon plates. No defects noted at this time torlon plates installed correctly.
- -Complied with Pilatus Mandatory Service Bulletin 57-007 Inspection of wing torlon plates. No defects noted installed correctly referencing SB 57-007 instructions.
- -Complied with Pilatus Recommended Service Bulletin 34-043 by performing a compass swing and installing a new correction card.
- -Complied with Pilatus SB 11-005 (287) Replace the Fuel Filler Placard referencing the service bulletin instructions.

## Aircraft Scheduled Maintenance and Inspections

- -Complied with 6 month application of AgeMaster to surface de-icers referencing Pilatus PC-12 AMM Section
- DMC-12-A-05-10-20-00A-281A-A.
- -Complied with 6 month external corrosion and preventative compound condition inspection referencing Pilatus PC-12 AMM Section
- DMC-12-A-20-40-00-00A-901A-A. No discrepancies noted.
- -Complied with 200 hour starter/generator brush check referencing Pilatus PC-12 AMM Section DMC-12-A-24-30-01-00A-313A-A.
- No discrepancies noted.
- -Complied with 6 month/600 hour lead acid battery capacity test for main and secondary batteries referencing Pilatus PC-12 AMM Section
- DMC-12-A-24-30-07-00A-920A-A and Concorde CMM 24-30-71. Main battery tests good at 90% capacity and secondary battery tests good
- at 90% capacity. Next capacity test due 6 months/600 hours.
- -Complied with 2 year magnetic compass calibration swing referencing Pilatus PC-12 AMM Section DMC-12-A-34-21-00-00A-903A-A. A
- new compass correction card was installed.
  - -Complied with 2 year/3000 hour pressurization outflow valve and safety valve cleaning referencing Pilatus PC-12 AMM Section DMC-12-A-21-30-01-00A-250A-A.
- -Complied with 2 year/3000 hour cabin positive pressure relief test referencing Pilatus PC-12 AMM Section
- DMC-12-A-21-30-00-00A-903A-A. Operational test satisfactory.
- -Comply with 200 hr/12 months flap up and down limit switches. Referencing Pilatus PC-12 section DMC-12-A-27-50-07-00A-920A-A.

-Performed the 6 month short state of	N840AG Work Ond	-
- 23-20-00 No defects noted	N840AG  Work Order # 3170  ne Data Communicator. referencing Pilatus PC12 supplement No. ICA08013-1. No defects note yTrac) Cockpit display panel. Referencing Pilatus PC12 supplement No. ICA08013-1 ATA  (SkyTrac) circuit breaker operation. Referencing Pilatus PC12 supplement No. ICA08013-1 ATA  or condenser cleaning referencing Pilatus PC-12 AMM Section	AIRFRAME
211-10-02-00A-230A-A.	- I MANY SCOTION	-Removed P/N section DMC-
-Removed the no smoking light on the rear be Pilatus PC12 AMM Section DMC-12-A-33-2-Removed the fasten seat belt light on the bat Pilatus PC12 AMM Section DMC-12-A-33-2	ulk head P/N- 972.72.59.031 and replaced light bar with new P/N- 972.72.59.031. Referencing	DMC-12-A-3 -Removed lef Component N
DMC-12-A-25-21-01-00A-920A-A.  -Installed locally fabricated placard "static po-Replaced Bulbs PN- OL6839 on Pilots AD	ort keep clear" at the left static pressure port.  HRS select switch and replaced DME select switch Asamble DN ore se	-Removed le wheel bearin Pilatus AMN -Removed (2
DMC-12-A-33-10-05-00A-920A-A.  -Removed left wing inboard surface deice box	d dome light switch with new P/N- 973.61.42.110 referencing Pilatus PC-12 AMM section	13830 refere -Removed si see 8130-3 o AMM section
NDK-1720 referencing Pilatus PC- AMM sec -Removed left wing outboard surface deice be	oot PN-27-7D5221-10; SN- unreadable and installed new boot PN-P27-7D5221-10; SN- ction DMC-12-B-30-14-01-00A-920A-A.	I certify that condition as
NDB-3670 referencing Pilatus PC ANDA and	boot PN-27D-7D5221-12; SN-unreadable and installed new boot PN- P27-7D5221 12: 51	For Tempus WO# 3170
SN-NDJ8280 referencing Pilatus PC 12 AAG	Ice boot PN-27S-7D5221-13; SN- unreadable and installed new boot PN- P27S-7D5221-13; seige boot PN- 27S-7D5221-13; eige boot PN- 27S-7D5221-14; eige boot PN- 27S-7D5221-14;	
To all to	Page 2 of 3	

13-1. No defects noted CA08013-1 ATA	AIRFRAME (continued)	Registration No	Work Order # 3170
No. ICA08013-1 ATA	-Removed P/N- MS29513-232 and r section DMC-12-A-28-00-00-00A-9 -Removed and replaced the wing ice	replaced fuel cap packing on left and right with new P/01A-A light bulb with new, P/N 972.87.87.227. Referencing	Pilatus PC-12 AMM section
9.031. Referencing	-Removed left MLG tire P/N: 850T0 Component Maintenance Manual an- -Removed Right MLG tire P/N: 021-	06-1, S/N: 12090980. Installed new tire P/N: 025-350-d Pilatus AMM DMC-12-A-12-1004-00A-902A-A350-0, S/N: 3177S00312 and installed new tire P/N:	025-350-0, S/N: 6146S00232, referencing Parker
031. Referencing	Domestad I.A and might main (4) wh	and bearing ours D/N: 24720 and installed (4) new cut	os P/N: 214-13100. Removed left and right main (4)
PC-12 AMM section	wheel bearing cones P/N: 24780 and	installed (4) new cones P/N: 214-13200, referencing	Cleverand wheels and Brakes Civily Civilo 121 and
315 and	13830 referencing Goodrich CMM 3	-1501.	erhauled regulator P/N- 4D2095-141; S/N- N0178
AMM section	AMM section DMC-12-A-30-10-01-		
1.022; SN-	I certify that this Airframe has been condition and is approved for return t	inspected in accordance with a Pilatus 100 Hour Insto service. Pertinent details are on file at this facility u	pection and was determined to be in airworthy inder the work order referenced below.
21-10; SN- 1.024; NDK-6260	For Tempus Jets: WO# 3170	Ronald Gish, A&P 3650077	Page 3 of 3
221-12; SN-			
5-7D5221-13;			
, ,			

	Date	Aircraft Time		Maintenance	Type Black
	TEMPUSJETS	Registration #: N840	AG Total Aircraft Time: 14477.8	Total Aircraft Cycles: 8847	and Re
	I CIVIPOSSCI -	Hobbs: 4477.3	Total Engine Time: 13303.8	Total Engine Cycles: 10077 Total Propeller TSOH: 44.5	
		VCCS Hours: 802.3	Total Propeller Time: 2124.6 Work Order #: 3170	Date: 8/12/2016	
	Pilatus PC-12/45, S/N 296				
S	Aircraft Airworthiness Direc	tives and Service Bulletins	22 (245) Engine Mounting Frame Ultrason	nic Inspection of Swaged Tube Ends. No	
O C C C T to	<ul> <li>Complied with Pilatus Manda discrepancies found. See Ultra:         Aircraft Scheduled Maintena -Complied with 400 hour gene discrepancies noted.         Complied with 1 year VCCS Aircraft Maintenance Action - Removed co-pilots EHSI In Referencing Pilatus PC-12 Al     </li> </ul>	sonic Report by NDE Services ance and Inspections rator 2 brush inspection referencies cleaning/inspection referencies addicator P/N 066-03125-2500 MM section DMC-12-A-34-26	R2 (345) Engine Mounting Frame Ultrasons, Inc. dated 8/12/2016 placed in the aircraft meing Pilatus PC-12 AMM Section DMC-12 Enviro Systems CMM 21-00-23. No disconsistent and installed repaired Indicator In 19/20200A-920A-A. Operational check satistic and replaced DME select switch Asser MC-12-A-34-52-00-00A-903A-A. Operational check satistic and replaced DME select switch Asser MC-12-A-34-52-00-00A-903A-A. Operational check satistic and replaced DME select switch Asser MC-12-A-34-52-00-00A-903A-A. Operational check satistic sat	P/N- 066-03125-2500; SN U3153.	
Ci Ci Ci Ci Ti	<ul> <li>Complied with Pilatus Manda discrepancies found. See Ultra:         Aircraft Scheduled Maintena - Complied with 400 hour gene discrepancies noted.     </li> <li>Complied with 1 year VCCS Aircraft Maintenance Action - Removed co-pilots EHSI In Referencing Pilatus PC-12 Al - Replaced Bulbs PN- OL683 - 972.81.12.526. Referencing F</li> </ul>	sonic Report by NDE Services and Inspections rator 2 brush inspection referencing cleaning/inspection referencing dicator P/N 066-03125-2500; MM section DMC-12-A-34-269 on Pilots ADHRS select swith the select selection of the section DMC-12 and section DMC-13 and is a select select in the section of the	g Enviro Systems CMM 21-00-23. No disc SN-3481 and installed repaired indicator lands and replaced DME select switch Asser	crepancies noted.  P/N- 066-03125-2500; SN U3153.  Efactory.  mbly PN-973.32.19.315 and ional check satisfactory.  ation Administration and the	

# AIDCDAFT LOG

		AIRCR	AFT LOG			
Dete	Aircraft	ł Time	Recorder		Main	tenance
Date	This Date	Total	Reading		Maiii	rendice
TE	MPUSJETS	Registration #: Hobbs  Engine TSO	s: 4554.3	l Fotal Aircraft Time: Total Engine Time: otal Propeller Time:	: 13380.3	Total Aircraft Cycles: 8 Total Engine Cycles: Total Propeller TSOH:
Airer -Re	us PC-12/45, S/N 296  raft Maintenance Actions emoved engine PN PT6A- Aircraft was inspected in a	-67B; SN PCE-PR0132	ent Regulations of	the Foderal Assisting	296 for ST(	C# SA02266LA.
For '	Tempus Jets:	Re		icht details are on me	at this facili	ition and the manufacturer's ap ity under the work order refere
WO	O# C3308	Ronald C	). Gish CRS#	3TPR073R		
Total to Carry Forw	ward					
			1			

TEMPUSJET

Registration #: N840AG Hobbs: 4554.3

Total Aircraft Time: 14554.3 Total Engine Time: New Total Propeller Time: New Work Order #: C3308

Total Aircraft Cycles: 8876 **Total Engine Cycles: Total Propeller TSOH:** Date: 06/05/2017

craft Cycles: 8876 ngine Cycles: 10106

eller TSOH: 0.0

acturer's approved rder referenced

PC-12/45, S/N 296

-Performed an Annual Inspection using the Pilatus PC-12/45 checklist and FAR 43 Appendix D.

VCCS Hours: 818.5

-Airworthiness Directive compliance checked through Revision 2017-11.

-Serviced aircraft oxygen referencing Pilatus PC-12 AMM Section DMC-12-A-12-10-05-00A-902A-A.

-Complied with continued airworthiness inspection requirements for installed equipment as required.

Aircraft Airworthiness Directives and Service Bulletins

-Complied with Pilatus flap control system current surges by performing wing flap actuator backlash check referencing Pilatus PC-12 AMM Section DMC-12-A-27-50-03-00A-313A-A and AD 2001-25-10 with results as follows:

	P/N	S/N	Previous Backlash	Current Backlash	Total Hours	Total Lndgs
Rt Otbd	978.73.20.309	0128		.009	3975.9	2512
Rt Inbd	978.73.20.309	1730	range in the second	.010	12389.4	6308
Lt Otbd	978.73.20.309	0291		.009	3975.9	2512
t Inbd	978.73.20.309	0733		.012	3975.9	2512

Aircraft total landings 8876. Recurring inspection due each 1000 hours or annual inspection. Next inspection due at 15554.3 hours or 06/2018.

-Complied with AD 2016-26-08 Par. (f)(6) MLG Attachment bolts inspection by removal and inspection of MLG attach bolts. Provided operator with latest copy of Pilatus PC-12/45 Chapter 4 Limitations.

-Complied with Pilatus PC-12 SB57-006 (295) Part 1. Part 2 was accomplished on the L/H forward flap support shim, R/H forward flap support shim, both R/H middle aft flap support shims, and both R/H outboard aft flap support shims. Referencing SB 57-006 instructions.

Aircraft Scheduled Maintenance and Inspections

-Complied with 6-month application of Age Master to surface deicers referencing Pilatus PC-12 AMM Section DMC-12-A-05-10-20-00A-281A-A.

-Complied with 12-month lubrication of main and nose wheel bearings referencing Pilatus PC-12 AMM Section DMC-12-A-12-20-06-00A-902A-A.

-Complied with 12-month corrosion and preventative compound condition inspection referencing Pilatus PC-12 AMM Section DMC-12-A-20-40-00-00A-901A-A. No discrepancies noted.

-Complied with 1 year VCCS cleaning/inspection referencing Enviro Systems CMM 21-00-23. No discrepancies noted.

-Complied with 1 year/1000-hour autopilot clutch torque check referencing Pilatus PC-12 AMM Section DMC-12-A-22-10-00-00A-313A-A. No discrepancies noted.

Page 1 of 8

AIRFRAME (Continued)

-Complied with 6-month/600-hour lead acid battery capacity test for main and secondary batteries referencing Pilatus PC-12 AMM Section 1997 A and Concorde CMM 24-30-71. Both batteries failed initial capacity test. Performed conditioning at the conditioning of the co -Complied with 6-month/600-hour lead acid battery capacity test for main and secondary batteries failed initial capacity test. Performed conditioning charge DMC-12-A-24-30-07-00A-920A-A and Concorde CMM 24-30-71. Both batteries failed initial capacity test. Performed conditioning charge that the capacity and secondary battery S/N:40539000 tests good at 90% capacity and secondary battery S/N:40539000 tests good at 90% capacity. DMC-12-A-24-30-07-00A-920A-A and Concorde CMM 24-30-71. Both batteries land secondary battery S/N:40539000 tests good at 90% capacity and secondary battery S/N:40539000 tests good at 90% capacity. Net

apacity test due 3 months/ 300 nours.
-Complied with 200-hour starter/generator brush check referencing Pilatus PC-12 AMM Section DMC-12-A-24-30-01-00A-313A-A No discrepancies noted. o discrepancies noted.
-Complied with 1-year fire extinguisher contents check referencing Pilatus PC-12 AMM Section DMC-12-A-26-20-00-00A-040A-A. No

discrepancies noted.

-Complied with 1 year/3000-hour horizontal stabilizer trim runaway aural warning functional test referencing Pilatus PC-12 AMM Section DMC-12-A-27-40-00-00A-903A-A. Functional test satisfactory.

-Complied with 1 year/150-hour flap actuator lubrication service referencing Pilatus PC-12 AMM Section

DMC-12-A-27-50-00-00A-902A-A.

-Complied with 1 year/150-hour inboard flap drive arm in-situ inspection/check referencing Pilatus PC-12 AMM Section DMC-12-A-27-51-00-00A-313A-A. No discrepancies noted.

-Complied with 1 year/2000-hour MLG axle and bushing inspection referencing Pilatus PC-12 AMM Section DMC-12-A-32-10-00-00A-313A-A. No discrepancies noted.

-Complied with 1 year crew oxygen mask operational test and cleaning referencing Zodiac Aerospace MC10 Series Operating and Maintenance Instructions 4NUT0045A. Operational test satisfactory. -Complied with 1 year/500-hour engine torque and stick pusher torque transducer electrical connectors cleaning referencing Pilatus PC-12

AMM Section DMC-12-A-71-00-03-00A-250A-A.

-Complied with 1 year/3000-hour propeller feathering micro switch functional tests referencing Pilatus PC-12 AMM Section DMC-12-A-76-10-02-00A-903A-A. Functional test satisfactory.

-Complied with 150-hour elevator cable tension inspection referencing Pilatus PC-12 AMM Section DMC-12-A-27-30-00-00A-903A-A.

-Complied with 150-hour rudder cable tension inspection referencing Pilatus PC-12 AMM Section DMC-12-A-27-20-00-00A-903A-A. -Complied with 1 year Main landing gear shock absorber top and bottom attachment bolts and nuts examination referencing Pilatus PC-12 AMM DMC-12-A-32-10-00-00A-310A-A. No defects noted.

-Complied with 6-year main landing gear leg forward attachment bolt and rear attachment bolt and nut referencing Pilatus PC-12 AMM section DMC-12-A-32-10-01-00A-920A-A.

-Previous compliance of 12 year seat belt overhaul at seat recovering and visually verified by data tags on 6 executive seats dated 07/2015,2 jump seats dated 05/2017, 2 crew seats dated 07/2010 (crew seats not recovered) see interior 8130-3 from Centennial Aircraft Services CRS#

Aircraft Maintenance Action -Complied with 6-year Main AMM DMC-12-A-32-10-00--Complied with 200-hour s DMC-12-A-12-20-07-00A-9 -Complied with 2-year AF -Complied with 2-year ger -Complied with 1-year EI

-Remove interior and inst Interiors dated 29/OCT/201 -Removed radome P/N: see certificate of conforma -Removed strobe light s

Performed operational/fur -Installed new chafe str self-adhesive film P/N 91 -Removed left wing tir

16/May/2017. Reinstalle DMC-12-A-57-33-00-0 section DMC-12-A-23--Removed damaged 1

form8130-3 from Strain DMC-12-A-55-20-01--Removed damaged

8130-3 from Straight ] DMC-12-A-55-20-01 -Removed upper V S/N:310-29751 seale -Removed the NL(

x's 3, 941.14.11.220 932.35.17.160, 932.

## Registration No.

M Section g charge on ity. Next

A.

A. No

12

Complied with 6-year Main landing gear actuator top and bottom attachment bolts and nuts corrosion inspection referencing Pilatus PC-12 Aircraft Maintenance Actions AMM DMC-12-A-32-10-00-00A-310A-A and DMC-12-A-32-30-01-00A-920A-A.

Complied with 200-hour servicing of flap up and down limit switches referencing Pilatus PC-12 AMM section

DMC-12-A-12-20-07-00A-902A-A no defects noted.

-Complied with 2-year AHRS #1 and #2 calibration swing referencing Pilatus PC-12 AMM Section DMC-12-A-34-25-00-00A-903A-A. -Complied with 2-year generator 1 ground point inspection referencing Pilatus PC-12 AMM Section DMC-12-A-24-30-00-00A-901A-A. -Complied with 1-year ELT inspection referencing FAR 91.207 (d).

-Remove interior and install refurbished interior from WO2825/PO15-02421 (N269PB MSN-269) see 8130-3's from Centennial Aircraft

Interiors dated 29/OCT/2015 and 06/NOV/2015. Referencing Pilatus PC-12 AMM section -Removed radome P/N: 4206-100-V1, S/N: 186 and installed new radome P/N: 4206-150, S/N: 552 from Saint-gobain Performance Plastics

see certificate of conformance dated 11/18/2016. Referencing Pilatus PC-12 AMM section DMC-12-A-34-41-02-00A-920A-A. -Removed strobe light switch P/N 973.61.42.510; S/N 9924. Installed new strobe light switch P/N 973.61.42.510; S/N 1330 as required.

Performed operational/functional check referencing Pilatus PC-12 AMM section DMC-12-A-33-40-00-00A-903A-A.

-Installed new chafe strips P/N'S 557.24.12.317, 557.24.12.318, 557.24.12.319, 557.24.12.320, 557.24.12.321, 557.24.12.322, using

self-adhesive film P/N 917.40.67.001 on LH main gear bay.

-Removed left wing tip P/N 571.10.12.041 sent out for repair, see form 8130-3 tag from Straight Flight Inc.CRS#OMKR399L dated 16/May/2017. Reinstalled repaired left wingtip P/N: 571.10.12.041, referencing Pilatus PC-12 AMM section DMC-12-A-57-33-00-00A-920A-A. Installed new static dischargers on left wing tip P/N: 984.78.81.406 referencing the Pilatus PC-12 AMM section DMC-12-A-23-60-01-00A-920B-A.

-Removed damaged left elevator P/N 555.20.12.039N; S/N 203. Reinstalled repaired left elevator P/N 555.20.12.039N; S/N 203 see form8130-3 from Straight Flight Inc. CRS# OMKR399L dated 26/May/2017 referencing Pilatus PC-12 AMM section

-Removed damaged right elevator P/N 555.20.12.040N; S/N 203. Reinstalled repaired right elevator P/N 555.20.12.040N; S/N 203 see form DMC-12-A-55-20-01-00A-920A-A. 8130-3 from Straight Flight Inc. CRS#OMKR399L dated 26/May/2017 referencing Pilatus PC-12 AMM section

DMC-12-A-55-20-01-00A-920A-A.

-Removed upper VHF1 COMM antenna P/N:984.81.10.203 S/N: 6114. Installed new upper VHF1 COMM antenna P/N:984.81.10.203 S/N:310-29751 sealed with PR1422B-2 and PR1764. Referencing Pilatus PC-12 AMM section DMC-12-A-23-12-02-00A-920A-A. -Removed the NLG steering yoke bolts and bushings. Installed new bushings P/N's 941.14.11.209 x's 2, 941.14.11.218 x's 2, 941.14.11.222 x's 3, 941.14.11.220, 941.22.56.053 x's 2, 941.22.57.053 x's 2, 941.14.11.216, 941.22.57.057 x's 2 and bolts P/N's 932.35.17.178, 932.35.17.160, 932.35.14.280, 932.35.14.268 referencing Pilatus PC-12 AMM section DMC-12-A-20-50-04-00A-901A-A.

Page 3 of 8

#### Aircraft Maintenance Actions

-Repaired damage shielding on LH WOW switch. Found corrosion on cannon plug, replaced cannon plug with new P/N 971.75.16.500 and strain relief P/N 971.74.98.376 referencing Pilatus PC-12 AMM section DMC-12-A-32-60-12-00A-920A-A operational check satisfactory.

-Removed right inboard fuel sump valve P/N 115.55.07.209 and plate seal P/N AS3209-116 and replaced with new valve P/N 115.55.07.208 and plate seal P/N AS3209-116 referencing Pilatus PC-12 AMM section DMC 12-A-28-10-02-00A-920A-A leak and operational check normal.

-Removed left outboard fuel sump valve P/N 115.55.07.209 and plate seal P/N AS3209-116 and replaced with new valve P/N 115.55.07.209 and plate seal P/N AS3209-116 referencing Pilatus PC-12 AMM section DMC 12-A-28-10-02-00A-920A-A leak and operational check normal.

-Removed damaged rivets on L/H wing lower side outboard of MLG gear door. Installed New rivets wet, P/N CR3214-5-3,-4,-6,-7 and NAS1097AD 5-8, 5-10 as required, referencing Pilatus PC-12 SRM DMC-12-A-57-00-00-00A-663A-A.

-Removed and replaced two new washer's P/N 530.24.12.110 and sealing cord P/N 530.24.12.090 on both right and left engine inlet de-ice lip pipe assemblies, referencing the Pilatus PC-12 AMM section DMC-12-A-78-10-01-00A-904B-A, DMC-12-A-78-10-01-00A-904C-A and DMC-12-A-78-10-01-00A-920A-A. Operational check satisfactory.

-Removed broken condition lever knob P/N 944.31.01.112 and replaced with new condition lever knob P/N 944.31.01.112 as necessary.

-Removed engine driven fuel pump P/N RG9570R1/M S/N B4489. Reinstalled overhauled engine driven fuel pump P/N RG9570R1/M S/N B4489 see form 8130-3 from Ametek B&S Aircraft Parts & Accessories CRS#NE2R028L dated 25/APR/2017 placed in aircraft records, referencing Pilatus PC-12 AMM section DMC-12-A-28-20-03-00A-920A-A.

-Installed new hydraulic nitrogen pressure placard P/N: 511.21.12.049 on the left belly panel referencing Pilatus PC-12 AMM section DMC-12-A-11-00-00-00A-901A-A.

-Installed pilot side curtain stop P/N: 944.41.00.002 referencing Pilatus PC-12 AMM section DMC-12-A-25-10-03-00A-920A-A.

-Removed worn P3 insulation blankets P/N's; 959.90.21.122 and 959.90.21.123 installed new P/N's; 959.90.21.122 and 959.90.21.123 referencing Pilatus PC-12 AMM section DMC-12-A-71-00-02-00A-920A-A.

-Complied with 3,500-hour engine oil cooler overhaul by removing P/N 8180-2 S/N T0195 and reinstalling overhauled oil cooler P/N 8180-S/N T0195 referencing Pilatus PC-12 AMM Section DMC-12-A-79-20-02-00A-920A-A. See Form 8130-3 from Pacific Oil Cooler Service Inc. CRS#RF3R813L dated 25APR17 placed in the aircraft records. Leak checks satisfactory.

-Removed and replaced Gas Strut P/N 552.10.12.339 for passenger/crew door referencing Pilatus PC-12 AMM section DMC-12-A-52-10-01-00A-920A-A.

carry rorwara

Page 4 of 8

P71.75.16.500 and eck satisfactory.
P/N 115.55.07.209 tional check

2/N 115.55.07.209 ional check

,-4,-6,-7 and

gine inlet de-ice 0A-904C-A and

s necessary. 9570R1/M S/N

1 section

N-A. 0.21.123

ler P/N 8180-2 ler Service

e 4 of 8

Aircraft Maintenance Actions

Installed new NLG tire P/N 021-327-0, S/N 6230S0027 with new O-ring P/N 959.56.01.650. Cleaned, inspected, and serviced the wheel bearings referencing Goodrich Corporation CMM 3-1501 Section 32-47-72. 3rd tire change NDI inspection was performed on NLG wheel assembly P/N 3-1501 S/N 0294. See maintenance release from NDE Services CRS# FS6R546N dated 03/27/2017 placed in aircraft records. -Performed in-service wear limit check on left and right flap support arms. Replaced bushings and axles on left and right flap support arms PN's 527.52.12.160, 941.22.57.102, 941.22.57.103 and 557.52.12.133 referencing Pilatus PC-12 AMM Section DMC-12-A-57-50-02-00A-904A-A.

-Removed and replaced left and right MLG pivot pin safety hardware Bolts P/N: 932.19.21.120, washer's P/N 938.77.11.114 and Nuts P/N: MS21042-4 referencing Pilatus PC12 AMM section DMC-12-A-32-10-00-00A-313A-A.

-Removed magnetic compass P/N C2350-L4-M23-5B; S/N AT-215 and installed new magnetic compass P/N 999.98.80.103; S/N AT-1575 referencing Pilatus PC-12 AMM section DMC-12-A-34-21-01-00A-920A-A.

-Repaired fuselage belly skin corrosion damage between frames 25 and 26 and frame 25 skin flange, stringers 17-18. Referencing Pilatus document # RM-12-001000 signed by Pilatus Office of Airworthiness Othmar Ziorjen Director. See form 337 form from Tempus Jets dated 06/05/2017 placed in aircraft records.

-Repaired impact damage at frames 26 and 29. Referencing Pilatus document # RM-12-001000 signed by Pilatus Office of Airworthiness Othmar Ziorjen Director. No further defects noted.

-Removed emergency power supply P/N-501-1712-02, S/N-2526. Installed new emergency power supply P/N-501-1712-02, S/N-81486 referencing Pilatus PC-12 AMM section DMC-12-A-24-52-51-00A-920A-A. Performed 1-year capacity check referencing L3 Avionics Systems CMM section 24-30-07. Functional test satisfactory.

-Adjusted aileron cable tension to manufactures specification referencing Pilatus PC-12 AMM Section DMC-12-A-27-10-00-00A-903A-A.

-Adjusted rudder and rudder autopilot cable tension to manufactures specifications referencing Pilatus PC-12 AMM Section DMC-12-A-27-20-00-00A-903A-A.

-Adjusted elevator, stick pusher, and elevator autopilot cable tension to manufactures specifications referencing Pilatus PC-12 AMM Section DMC-12-A-27-30-00-00A-903A-A.

-Removed aileron trim actuator P/N: 978.73.18.132, S/N: 66 and installed new aileron trim actuator P/N: 978.73.18.138, S/N: 1326 referencing Pilatus PC-12 AMM section DMC-12-A27-15-01-00A-920A-A. Operational test satisfactory.

-Removed and replaced rudder stop cushion P/N 555.30.12.218 as required referencing Pilatus PC-12 AMM section DMC-12-A-27-20-00-00A-903A-A.

-Adjusted rudder trim travels to manufactures specifications referencing Pilatus PC-12 AMM section DMC-12-A-27-25-00-00A-903A-A. Functional test checks satisfactory.

- Removed and replaced rudder autopilot cable turn buckle barrel P/N 941.93.41.613 referencing Pilatus PC-12 AMM section DMC-12-A-27-20-02-00A-920A-A.

- Removed and replaced elevator autopilot cable turnbuckle barrel P/N 941.93.41.613 referencing Pilatus PC-12 AMM section DMC-12-A-27-30-02-00A-920A-A.

#### Aircraft Maintenance Actions

-Removed the left wing inboard surface de-ice boot P/N P27-7D5221-09 S/N NDC0900. Installed new deice boot P/N: P27-7D5221-09 S/N NDC0900. Installed new deice boot P -Removed the left wing inboard surface de-ice boot F/IN F27-7D5221-09; Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich Corporation CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-920A-Sn NDT6610, referencing the Goodrich CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-Sn NDT6610, referencing the Goodrich CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-Sn NDT6610, referencing the Goodrich CMM 30-10-70 and the Pilatus PC-12 AMM Section DMC-12-A-30-14-01-00A-Sn NDT6610, referencing the PC-12 AMM Section DMC-12-A-30-14-01-00A-Sn NDT6610, referencing th Perational check satisfactory.
-Removed LH AOA vane P/N: 975.44.21.423; S/N: 1216. Installed repaired LH AOA vane P/N: 975.44.21.423 S/N: 1421 see 8130-3 from

Rosemont Aerospace CRS# RJLR391K dated 11MAR2017 placed in aircraft records, referencing Pilatus PC-12 AMM section

DMC-12-A-22-20-02-00A-920A-A

MC-12-A-22-20-02-00A-920A-A.
-Removed RH AOA vane P/N: 975.44.21.424; S/N:1033. Installed repaired RH AOA vane P/N: 975.44.21.424 S/N: 0905 see 8130-3 from

Rosemont Aerospace CRS# RJLR391K dated 23MAR2017 placed in aircraft records, referencing Pilatus PC-12 AMM section DMC-12-A-22-20-02-00A-920A-A

-Removed and installed new autopilot servo capstan cover P/N 047-02350-0001 referencing Pilatus PC-12 AMM section

DMC-12-A-22-10-00-00A-313A-A.

-Removed ADF antenna P/N:071-1234-00 S/N: KA44B-A-85354 and ADF doubler plate P/N: 553.14.12.513, Installed new ADF antenna P/N 071-1234-00 S/N: KA44B-A94880 and new ADF doubler plate P/N: 553.14.12.513 referencing Pilatus PC-12 AMM section

-Installed new chafe strips P/N's 557.24.12.321, 557.24.12.322, 557.24.12.320 using adhesive film P/N 917.40.67.001 on right main gear door bay.

-Installed one new passenger seat#7 oxygen mask P/N: 957.12.10.211 referencing Pilatus PC-12 AMM section DMC-12-A-35-20-03-00A-920A-A.

-Removed forward inboard roller and bushing from the Pilots crew seat. Replaced with new bushing P/N NAS75-5-024 and new forward roller P/N 959.30.01.217 referencing IAI Golan Industries MM 25-10-99. Operational check satisfactory. -Removed leaking landing gear selector valve P/N 960.30.01.273; S/N 0612AB and installed overhauled landing gear selector valve P/N

960.30.01.273; S/N 077ABC referencing Pilatus PC-12 AMM section DMC-12-A-32-30-03-00A-920A-A. Functional and leak check

02099 32-10-05.

-Removed broken towing bolt on right MLG and replaced with new P/N 532.10.12.106 bolt referencing Pilatus CMM document number:

-Removed serviceable HF Controller P/N: 071-1274-01, S/N: 5100, HF Power AMP P/N: 064-1017-00 S/N: 2684, HF Receiver/Exciter P/N:

985.99.11.915 S/N: 4945, HF Antenna P/N: D/G 5ARM300-1CN-3 S/N:0000 HF Amplifier Rack P/N: Unknown. At this time and date,

DMC-12-A-52-10-01-00A-920A-A

DMC-12-A-32-30-00-00A-901A-A.

-Removed and replaced passenger door aft suspension cable P/N:552.10.12.329 referencing Pilatus PC-12 AMM section

-Removed and replaced right MLG up stop plate P/N 557.24.12.075 referencing Pilatus PC-12 AMM section

-Removed the NLG torqu 932.35.14.003, 938.07.68.3 tube found the NLG spring PC-12 AMM section DMC -Removed right main lan and nut P/N: 938.08.71.21

Aircraft Maintenance Action

-Cleaned and sealed Gen 1 -Removed and replace L/I

-Replaced right MLG ut 938.77.11.124 and Nut P/

-Installed new; washer l DMC-12-A-32-30-01-00. -Removed LH MLG sh in upper fwd and lower i

-Removed RH MLG sl in upper fwd and lower i -Replaced damaged at

-Removed and replace AMM section DMC-12 -Comply with Finnof

installation of new Prat AMM sections DMC-337 and placed in airc

-Removed worn insi AMM section DMC-1 -Repaired left wing AMM section DMC-

D5221-09; S/N: IA-920A-A.

: 8130-3 from

130-3 from

antenna

in gear

rward

: P/N

nber:

iter P/N:

Aircraft Maintenance Actions

-Cleaned and sealed Gen 1 grounding point referencing Pilatus PC-12 AMM section DMC-12-A-24-30-00-00A-901A-A.

-Removed and replace L/H outboard engine cowling hinge half P/N 571.10.12.181 with P/N 939.31.89.103 blind rivets.

-Removed the NLG torque tube and found the two bolts and nuts worn beyond serviceable limits, replaced with new bolts and nuts PN 932.35.14.003, 938.07.68.304 referencing Pilatus PC-12 AMM section DMC-12-A-32-50-03-00A-920A-A. While removing NLG torque tube found the NLG spring strut LUG to be damaged, removed damaged lug and replaced with new lug P/N 532.50.12.052 referencing Pilatus PC-12 AMM section DMC-12-A-32-50-02-00A-920A-A. Operational checks satisfactory.

-Removed right main landing gear actuator lower attaching hardware and installed new bolt P/N: 532.10.12.218, washer P/N: 938.77.11.129 and nut P/N: 938.08.71.212 referencing the Pilatus PC-12 AMM section DMC-12-A-32-30-01-00A-920A-A.

-Replaced right MLG upper actuator bolt P/N: 532.34.12.062 and washer P/N: 938.77.11.124 with new bolt P/N: 532.34.12.062, washer P/N: 938.77.11.124 and Nut P/N: MS17825-9 referencing Pilatus PC-12 AMM section DMC-12-A-32-30-01-00A-920A-A.

-Installed new; washer P/N 938.77.11.124 and nut P/N MS17825-9 on left MLG upper actuator bolt referencing Pilatus PC-12 AMM section

DMC-12-A-32-30-01-00A-920A-A.

-Removed LH MLG shock absorber upper fwd and lower in board bushings P/N: 532.10.12.124. Installed new bushings P/N: 532.10.12.124 in upper fwd and lower in board positions referencing Pilatus PC-12 AMM section DMC-12-A-20-50-04-00A-901A-A.

-Removed RH MLG shock absorber upper fwd and lower in board bushings P/N: 532.10.12.124. Installed new bushings P/N: 532.10.12.124

in upper fwd and lower in board positions referencing Pilatus PC-12 AMM section DMC-12-A-20-50-04-00A-901A-A.

-Replaced damaged aft left isolator mount at cargo door panel 22TZ with new P/N: 944.81.18.201.

-Removed and replaced worn bushings PN 941.14.11.266 and 552.10.12.353 on passenger/crew door hand rail referencing Pilatus PC-12 AMM section DMC-12-A-52-10-01-00A-920A-A and DMC-12-A-20-50-04-00A-901A-A.

-Comply with Finnoff Aviation STC # SA02266LA removal of serviceable Pratt & Whitney PT6A-67B, S/N PCE-PR0132engine and installation of new Pratt & Whitney PT6A-67P engine, S/N PCE-RY0776. Referencing STC# SA02266LA instructions and Pilatus PC-12 AMM sections DMC-12-A-71-00-01-00A-920A-A, DMC-12-A-71-00-02-00A-920A-A and DMC-12-A-71-00-00-00A-903A-A. Completed 337 and placed in aircraft records.

-Removed worn insulation blanket for P2.5 bleed air line P/N: 959.90.21.121 installed new P/N: 959.90.21.121 referencing Pilatus PC-12 AMM section DMC-12-A-71-00-02-00A-920A-A.

-Repaired left wing inboard fuel tank at panels 51FB and 51EB and rivets at leading edge sealed with sealant referencing Pilatus PC-12 AMM section DMC-12-A-28-10-00-00A-904A-A. No leaks noted.

#### AIDCDAFT LOG

#### Aircraft Maintenance Actions

-Removed belly drain seals P/N-553.14.12.601 and replaced with new P/N-553.14.12.601.

-Removed beily drain seals P/N-333.14.12.001 and installed new bonding strap PN: 523.60.09.071 referencing Pilatus PC-12 AMM Section DMC-12-A-32-10-01-00A-920A-A. -Removed two damaged bonding straps at right inboard flap support and replaced with new P/N 527.52.12.138 and P/N 523.60.09.077

referencing Pilatus PC-12 AMM section DMC-12-A-57-50-02-00A-904A-A

-Removed #1 AHRS LCR-92 P/N-124210-2022; S/N-1468 and installed repaired AHRS LCR-92 P/N- 124210-2022; S/N-1216 referencing

Pilatus PC-12 AMM section DMC-12-A-34-25-01-00A-920A-A. Performed AHRS calibration procedures on #1 and #2 AHRS referencing

Pilatus PC-12 AMM section DMC-12-A-34-25-00-00A-903A-A. See EASA Form 1 dated 09NOV2016 by Northrop Grumman LITEF GmbH placed in aircraft records. Operational checks satisfactory.

-Removed bleed air venturi on ECS shut off valve and installed new P/N- 521.41.12.073 with new seals P/N 946.94.11.109 referencing Pilatus PC-12 AMM section DMC-12-A-21-40-05-00A-920A-A. No leaks noted.

-Complied with 1 year ELT inspection referencing FAR 91.207 (d). BATTERY ONE JAN. 12018 W -Removed the auto pilot control panel P/N 065-0086-17, S/N 1962 installed modified auto pilot control panel P/N 065-0086-17 S/N 2032 se

8130-3 form from Honeywell International Inc. Date 25/Mar/2017.

-Installation of Dual USB Charging Port P/N-6430102-3; S/N- A17-10140 at co-pilots side wall see log entry from Duncan Aviation

WO-#58ANA dated June 7, 2017 placed in aircraft log books.

-Removed Hartzell 4 blade prop P/N HC-E4A-3D S/N KX680 referencing Pilatus PC-12 AMM section DMC-12-A-61-10-01-00A-920A-A

Installed new MT 5 blade propeller P/N MTV-27-1-N-C-F-R(P)/CFR260-65A S/N 170160 referencing MT propeller Operation and Installation Manual E-1082 section 61-00-83 and STC # SA02742NY. See EASA form 1 dated 1MAY17 placed in the aircraft records.

Updated POH to reflect MT propeller operation. Completed 337 and placed in aircraft records. -Complied with weight and balance of aircraft after STC's, interior and repairs as required referencing Pilatus PC=12 AMM section DMC-12-A-08-10-00-00A-901A-A

-Performed aircraft test flight as per engine STC see flight checklist in aircraft documents on file under WO-3308. No defect noted at this

-Complied with continued airworthiness inspections airborne data communicator ICA, cockpit display panel ICA, GPS/Iridium antenna ICA, circuit breaker checks ICA, as required no defects noted at this time.

The airframe identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and approved for return to service. Pertinent details of the repair are on file at this facility under the work order referenced below.

For Tempus Jets: WO# C3308

Ronald C. Gish

CRS# 3TPR073R

and Remarks



FAA Certified Repair Station DY1-916.3K 7775 S. Peoria Street F7 | Englewood, CO 9012

DESCRIPTION ITEM PART NUMBER HEADLINER Remove the original

WORK PERFORMED ITEM DESCRIPTION - PIN

WORK COMPLETED:

1-0005003 1-0005004 1-0004003 1-0004004 1-0004009 1-0005003

1-0005003

AIR BALL NOZZLE LIGHT TRIMPING GASPER TRIMPIN ELECTROPLATE

DESCRIPTION

LIGHT FLANGE

LIGHT BALL

AIR FLANGE

ELECTROPLATE

SERVICEABLE The item(s) identified above were refurbished and in

All materials used to affect this refurbishment meet

AC.43.13-18 Dated: Sept 8, 1989, change .. Standard :

Page 8 of

## and Remarks

# **Signature**

Centennial Aircraft Interiors

**TEMPUS JETS** 

12250 E CONTROL TOWER ROAD

ENGLEWOOD, CO 80112

303-799-6130

Mike Shrader

Nancie Bagdon

mshrader@tempusiets.com

RETURN TO SERVICE

WORK ORDER

3737

AC# AC MAKE:

N840AG PILATUS

AC MODEL: AC SEPIAL:

PC-12 296

PURCHASE ORDE PO17-00816

FAA Certified Repair Station DYHRISIK

7775 S. Peoria Street F7 | Englewood, CO 8012

DESCRIPTION

nbagdon@tempusiets.com

MATERIAL

PADDING

VENDOR STYLE TAPIS ULTRALEATHER

CL CELL

PIN ULFR5805 SKAPC.125

COLOR EPIMINE BEIGE

WORK PERFORMED: ITEM DESCRIPTION - PIN

ITEM PART NUMBER

Remove the original headliner material, strip, prep and recover with new padding and ultraleather

HEADLINER

DESCRIPTION

MATERIAL

10

VENDOR STYLE

SKANDIA

PIN

COLOR

ELECTROPLATE HEADLINER HARDWARE

SIGNATURE

32597 Antique Rose

WORK COMPLETED:

Process, electroplated, inspected and test for compliance with Signature Plating Quality Assurance PLATING

Manual and Process Spec. ABIPL1 Rev A - Re-install same as removed.

1-0005003 LIGHT FLANGE LIGHT BALL 1-0005004 1-0004003 AIR FLANGE

AIR BALL 1-0004004 1-0004009 NOZZLE

LIGHT TRIMRING 1-0005003 1-0005003

GASPER TRIMPING

**ELECTROPLATE SEAT DRAWER LATCHES** 

SERVICEABLE

The item(s) identified above were refurbished and inspected in accordance with current Federal Aviation Agency Figurations and was found airworthy for return to service. All materials used to affect this refurbishment meet or exceed 14 CFR Part 25.853(a) Appendix F Part 1(a) (ii) (Amendment 25 - 83). All work performed in accordance to the control of the AC 43 T3-TB Dated: Sept 8, 1989, change . Standard practices to were used to accomplish refurbishment to the above illums


Return to Service By:

Jeanne Sharopack, Repairman

FAA Repair Station: DYHR613K

Aircro	Aircraft Time			AL.				
This Date	Total	Reading			Mai	intenanc	e	
mad (A		TEMPUS JETS	RETURN	TO SERVICE		and the first of the first of the second		
Centennial A	forcraft	12260 E CONTROL TOWER ROAD ENGLEWOOD, CO 80112 303-799-6130 Mike Shrader				WORK ORDER  A/C #:  A/C MAKE:  A/C MODEL:	N840AG PILATUS PC-12	
Centennial P Suterio FAA Certified Repoir Statio 7775 S. Peoria Street F7	n DYHR163K	mshrader@tempusiets.com  Nancie Bagdon  nbagdon@tempusiets.com				A/C SERIAL: PURCHASE ORDI	296	
303.649.9296 Office jeannesharpnack@aol.co								
EM DESCRIPTION - P/N  3  WORK PERFORMED:	WORK TO BE PERFORMED  CARPET, AFT - 8 SEAT CONFIGURAT  Measure, cut and bind for a 8 seat  CUT, BIND, FIT, CHECK & INSPECT		MATERIAL CARPET PADDING	VENDOR RED ROCKS SKANDIA	STYLE MATRIX CLOSED CELL	<b>!</b> !!	COLOR CARDIGAN BEIGE	
EM DESCRIPTION - P/N	WORK TO BE PERFORMED	A compared to the second second	MATERIAL	VENDOR	STYLE	P/N	COLOR	
4 WORK PERFORMED:	Make pattern, cut and sew FABRICATE, CHECK & INSPECT	ED LOGO	LEATHER	M&G	APOLLO		ATHENS	
All materials used to affect	this refurbishment meet or exceed 14 C	The state of the s	) (Attendment 2:	5 - 83) All work	airworthy for re performed in ac	turn to service. cordance with		
			V					

	and Remarks						Sign	ature	Certificate
-	Centennial A  Pateries  FAA Certified Repair Station  7775 S. Peor is Street F7   E  503 648 5236 Office	DYNR163X	TEMPUS JETS  12260 E CONTROL TOWER ROA ENGLEWOOD, CO 9D112 505-789-6130 Mike Shrader mshrader & tempus jeta.com Nancie Bagdon nbagdon@tempus jeta.com	RETURN D	TO SERVICE		WORK ORDER A/C # A/C MAKE: A/C MODEL A/C SERIAL: PURCHASE OR	3737 NS4CAG PILATUS PC-12 295 DER: PO17-00816	
	ITEM PART MUNICER  1 959.30.01.521 959.30.01.522 WORK PERFORMED:  TEM DESCRIPTION - P/N 2 3122-1-011-8044 PRELIMBRARY INSPECTION: IN PROGRESS INSPECTION: WORK PERFORMED:	DESCRIPTION JUMP SEATS - SEAT FRAME PAS JUMP SEATS - SEAT FRAME PAS Removed old leather cover. M same as removed with new lea FIT, CHECK AND INSPECT  WORK TO BE PERFORMED 3 PT RESTRAINT ASSEMBLIES (C Completed by C&M Marine Au Need, New Web Slide (AMSOS) ReWebbed & Overhauledin acc Webbing Flammability Require	senger, STANDARD  ske pattern, cut, sew and recover  ther  TY 2) - C&M MARINE AVIATION SERVICE  intion Services,  54-1) and Cover, Lower DBS (AM50481)  ordance with CMMADD Dec. 20.		VENDOR M&G SKANDIA SKANDIA SKANDIA VENDOR C&M ODER (AM504816-) e drawing DATED	SEW HOOK	P/N DAX47 SABLK1.00L SABLK1.00H	COLOR ATHENS GREEN BLACX BLACX COLOR MATCH	
<u>-</u>	SERVICEABLE The item(s) identified above All materials used to affect to AC.48.18-18 Dated: Sept 8, 1	were refurbished and inspected in	n accordance with current Federal Avia 14 CFR Part 25 853(a) Appendix F Part to were used to accomplish refurbishn Return to Service By.	ition Agenty Regult  1 (a) (ii) (Apendment to the active it  Jeanne Sharp ac FAA Repair Stat	ck. Repairman No	Q.	y for return to si d in accordance	rvice, with	



June 7, 2017	and Remark	cs	Signature	Certificate No.
ion A.	DUNCAN	N840AG Tempus Aircraft	PC-12/45 296	16 June 2017
80112	repair. Reinstalled both of S/N 23425743. Config vo 00356-08.	erification and ops check good IAW Coness Directives apply.	GNS430 P/N 011-01060-00 S/N 23425743 S530 P/N 011-01064-00 S/N 23822865, and Garmin GNS 500W Series IM 190-00357-08 rn to service. Pertinent details of these insp	and Garmin GNS 400W 190- bections are on file under Work
	Signed: CRS # JG7D076J	Phone: 303-649-1790	Total Time:	Total Landings:



N840AG Tempus Aircraft Sales and Service

Pilatus PC-12/45 S/N: 296

June 20, 20

7.773 S. P. 303 649 Jeannesh

	ay Systems FD200CPU-7 IM, US airworthiness directives ap	Systems Cabin Moving Map Distems Cabin Moving Map Distems Cabin Moving Map Distems of the Capacitan Capaci	are as good configuration	and ops effect performe
The above d	escribed repair or maintenance	e is approved for return to service	. A detailed record is on f	ile under Work Order #5
- Signed: For Dunçar	Aviation CRS # JG7D076J	DUNCAN QI 1473 Phone: 303-649-1790	for Duncan Avionics Total Time:	s; Englewood, CO 80112 Total Landings:
- Par (ma) Ambar (				
1				
otal to				

11003) 00001016 Inned IA

#594LA

12

# and Remarks

# Signature



FAA Centified Repair Station DYHR163K 77795 Peor a Street F7 | Englewood, CO 80112 509 649 9296 Office comestar prack@aol.com

**TEMPUS JETS** 12260 E CONTROL TOWER ROAD ENGLEWOOD, CO B0112

303-799-6130 Mike Shrader mshrader@tempusjets.com

Director of Maintenance Kevin Fenske Kfenske@tempusjets.com 920.342.8729

Nancie Bagdon nbagdon@tempusjets.com

Parts

Kevin Fenske Kfenske@tempusjets.com 920.342.8729 Customer Support and Service Manager DIRECT 303.784.7504

Ron Gish rgish@tempusjets.com Chief Inspector DIRECT 303.784.7537 CELL 720.373.0017 **RETURN TO SERVICE** 

W.O.

3770 N840AG A/C# PILATUS

A/C MAKE: A/C MODEL:

PC-12 296

A/C SERIAL: P.O. PO17-

REQUIRED DATE Jun 20 2017 START DATE Jun 19 2017

			VENDOR	STYLE	P/N	COLOR
TEM DESCRIPTION - P/N	WORK TO BE PERFORMED	MATERIAL	CONTRACTOR OF THE PROPERTY OF	RESIDENCE OF THE PROPERTY OF THE PERSON OF T	SERVED STATES AND STATES OF STATES OF SERVED	THE ASSESSMENT OF THE PARTY OF
•	CARPET MAT - Entry way	CARPET	RED ROCKS	MATRIX	RRC-3925	CARDIGAN
WYDEK PERFORMED:	Measure, cut and bind for entryway custom fit	CARPET	RED ROCKS	MATRIX	SERGING THREAD	CARDIGAN

#### SERVICEABLE

The item(s) identified above were refurbished and inspected in accordance with current Federal Aviation Agency Regulations and was found an worthy for return to service. All work performed in accordance with All materials used to affect this refurbishment meet or exceed 14 CFR Part 25.853(a) Appendix F Part 1 (a) (ii) mendment 25 - 83 AC.43.13-18 Dated: Sept 8, 1989, change. Standard practices to were used to accomplish refurbishment to the adove items

Return to Service By:

Jeanne Sharprock, Repairman FAA Repair Statten: DYHR613K

Brought Forward  TEMPUS JETS  12260 E CONTROL TOWER ROAD  ENGLIWOOD, CO 80112  MAC RETURN TO SERVICE  12360 E CONTROL TOWER ROAD  ENGLIWOOD, CO 80112  MAC RETURN TO SERVICE  12360 E CONTROL TOWER ROAD  ENGLIWOOD, CO 80112  MAC RETURN TO SERVICE  SOS-789-6130  Miles Shrader mshrader@tempusjets.com  AC MAKE  MIRE Shrader mshrader@tempusjets.com  AC MAKE  MIRE Shrader mshrader@tempusjets.com  AC MAKE  PO  TO 1755 S. Peoria Street F7   Engliewbod. CO 80112  TEMP  PART MUMBER  1 PID 1020-0-05  DESCRIPTION  TEMP  TABLE (DITY S) - Remove existing leather insert. Recover w/ new leathe LEATHER  Removed existing leather, strip, clean and prep. Recover new panel with leather. Recovered same as transvered sitting leather, strip, clean and prep. Recover new panel with leather.  TIEMP  PART NUMBER  TIEMP  PART NUMBER  DESCRIPTION  SMALL DRINK RAIL - Remove existing leather insert. Recover w/ new leather LEATHER  MAG ATHENS  TO 200ATC  ACMINISTRAL VENDOR STYLE  PIN  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  AMM REST - PILOT SEAT (Ot 1) - FABRICATE SAME AS THE SAMPLE  LEATHER  MAG ATHENS  TO 200ATC  TO 200ATC  TO 200ATC  TO	ate	Aircraft T	ime	AFT LOG					
Forward  TEMPUS JETS  CENTENCIONAL  12260 E CONTROL TOWER ROAD  ENGLEWOOD, CO 80112  SOS-79-99-10  Miles Shrader mahrader@tempusjets.com  AC & MARCHAL  POSTA  FAA Certified Repoir Station DYNEISSX  Miles Shrader mahrader@tempusjets.com  AC & MARCHAL  AC	Th	is Date	Total						
Certify that the item(s) identified above were refurbished and inspected in accordance with Signature Plating Quality insurance Manual and Process Spec. ABIPLI All materials used to affect this refurbishment meet or exceed 14 CFR Part 25.853(a) Appendix F Part 1 (a) (ii) (Amendment 25 - 83). All work performed in accordance with AC-43.13-18 Dated: Sept 8, 1989, change. Standard practices to were used to accomplish refurbishment to the above items    Jeanne Sharpnack, Rogarman No.388591     FAA Repair Station of Na619K	Brough	FAA Certified Repair S. 7775 S. Peoria Street  TIEM PART NUMBER 1 PID 1020-406 CORRECTIVE AC TIEM PART NUMBER 3 PID 1020-404 CORRECTIVE AC TIEM PART NUMBER 5 PID PC12-SUI-20 CORRECTIVE ACI (certify that the item(s)	Total  Strictors  Stri	TEMPUS JETS  12260 E CONTROI ENGLEWOOD, CO 303-799-6130 Milke Shrader mash Director of Mainte Director of Mainte Director of Mainte Control Englewood, CO 303-799-6130 Milke Shrader mash Director of Mainte Control Eather, strip, clean and prep. Recover ne L. Remove existing leather insert. Recover Leather, strip, clean and prep. Recover ne Leather, strip, clean and prep. Recove	MATERIAL / new leathe LEATHER ew panel with leather. ew panel with leather. w/ new leather Recov MATERIAL er w/ new leather Recov MATERIAL er w/ new leather MATERIAL w/ new leather w/ new leather MATERIAL er w/ new leather MATERIAL er w panel with leather. MATERIAL ARM REST SHEETN MATERIAL BUE ROSE th Signature Plating Quality the Federal Aviation Rency Re the 1 (a) (ii) (Amendment 25 - 8 ment to the above items wrman No. 3835991	VENDOR M&G VENDOR M&G VENDOR M&G  VENDOR M&G  VENDOR M&G  AETAL FABRICATE VENDOR SIGNATURE Insurence Mani	RETURN 1 W.O. A/C #. A/C MAKE: A/C MODEL A/C SERIAL: P.O. STYLE ATHENS MOVED STYLE ATHENS STYLE ATHENS STYLE ATHENS D BY STRAIGHT STYLE JOB STRAIGHT STYLE ATHENS ATHENS ATHENS D BY STRAIGHT STYLE ATHENS D BY STRAIGHT STYLE ATHENS D BY STRAIGHT	70 SERVICE  3770  N840Ag PILATUS PC-12 296 PO17-01178  P/N 7020ATCP-FT  P/N 7020ATCP-FT  P/N 7020ATCP-FT  P/N 7020ATCP-FT  FLIGHT FAA CR5 NO P/M 32597	COLOR CHOC PUDDIN COLOR CHOC PUDDIN CHOC PUDDIN COLOR COLOR COLOR MKR3596L COLOR

Pilatu:


Aircra -Rer 14JUN -Rer 13JUN -Res 8130-DMC -Res AMM -Re refere

RUA
-Ins
Place
-Re
-Ins
-Re
-Co
Form
time
Th

main

belo For '

WO:



Donistation No.

TEMPUSJETS

Registration #: N840AG

Hobbs: 4556.3

**VCCS Hours:** 

Total Aircraft Time: 14556.3

Total Engine Time: 2.0

Total Propeller Time: 2.0

Work Order #: C3419

Total Aircraft Cycles: 8879

Total Engine Cycles: 3

Total Propeller TSOH:

Date: 06/21/2017

Pilatus PC-12/45, S/N 296

#### Aircraft Maintenance Actions

-Removed GNS430 PN 011-01060-00, SN 23425743 and repaired see 8130-3 from Garmin International CRS# G6XR582Y dated 14JUN2017. Duncan re-installed GNS430 after repair CRS# JG7D076J WO#58JFA see log book entry placed in aircraft records.

-Removed GNS530 PN 011-01064-00, SN 23822865 and repaired see 8130-3 from Garmin International CRS# G6XR582Y dated 13JUN2017. Duncan re-installed GNS530 after repair CRS# JG7D076J WO#58JFA see log book entry placed in aircraft records.

-Removed CAWS display unit P/N 972.81.32.012 S/N 8208. Replaced CAWS display unit with repaired P/N 972.81.32.012 S/N 9213 see 8130-3 from Pilatus Business Aircraft CRS# ZP8R849Y dated 15FEB2017. Referencing Pilatus PC-12 AMM section DMC-12-A-31-50-02-00A-920A-A.

-Removed faded placards as per the customer request and installed new placards as required by the POH section 2 referencing Pilatus PC-12 AMM section DMC-12-A-11-00-00-00A-901A-A. No further defects noted.

-Removed overhead control panel P/N PMPP 6200 S/N 015and installed inspected overhead control panel P/N PMPP 6200 S/N 042 referencing Pilatus PC-12 AMM DMC-12-A-31-10-00-00A-901B-A. Operational check normal. Power management panel inspected by RUAG Aerospace Services GmbH see EASA Form 1 - Issue 2 dated 30AUG2013 put in aircraft records.

-Installed three re-covered original table assemblies see 8130-3 from Centennial Aircraft Interiors CRS# DYHR163K dated 20JUN2017. Placed in aircraft records

-Removed Prop speed placard on instrument panel per MT prop STC. See section 9 of the POH.

-Installed new co-pilot armrest P/N: 959.30.01.226 referencing IAI Golan Industries CMM 25-10-99.

-Replaced forward and aft Seatbelt / No smoking lenses with new lenses P/N 1202-006-005. Operational test good.

RUCK

-Complied with Pilatus AD 2016-18-05, per Pilatus SB 71-009(345), Ultrasonic Inspection of Swaged Tube Ends. See Maintenance Release Form from NDE Services, INC dated 06/16/2017 CRS# FS6R546N. No defects noted. Next inspection due 31DEC2017 or 5156.3 Hobbs time.

The Aircraft was repaired in accordance with current Regulations of the Federal Aviation Administration and the manufacturer's approved maintenance instructions, and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.

For Tempus Jets:

Ronald C. Gish

CRS# 3TPR073R

WO# C3419

**	Recorder	ift Time	Aircraft Time			
Reading	Reading	Total	This Date	Date		
ation IIC	tion IIC	Vernon Avia	Tranghi>	ate: 6-21-		
		PO Box		HM: 4557		
NM 87499	NM 87499	Farmington, I	n#: N840AG	egistratio		
			azžie	Stanfred Y		
	- Lychelle i lite (see on passe					
ed to the work performed.	ed to the work perfor	e manual. Limite	azzie	Stanfred Y A&P31038		

Pilatus PC-12/45, S/N 296  Aircraft Maintenance Actions -Removed and replaced Prop deice timer with repaired assembly P/N: 4E3163-2 S/N: U031 (ref. AMETEK B&S 8130 No. 113551, W. BEL100902, dated 05/11/2017) referencing Pilatus PC-12 AMM DMC-12-A-30-60-01-00A-920A-A. Operational check normalRemoved and replaced airfoil deice pressure regulator with overhauled assembly P/N: 4D2095-141 S/N: N061490 (ref. AMETEK B& 8130 No. 77404, W/O No. BHY100051, dated 10/20/2017) referencing Pilatus PC-12 AMM DMC-12-A-30-10-01-00A-920A-A. Operat check normalRemoved and installed new baggage net assembly P/N: 525.25.12.043 referencing Pilatus PC-12 AMM DMC-12-A-25-23-01-00A-92-Removed and replaced L/H outboard fuel drain valve assembly PN: 115.55.07.209 referencing Pilatus PC-12 AMM Section DMC-12-A-28-10-02-00A-920A-A. No Leaks detected at this timeCleaned and inspected suspected corrosion areas in left and right wing wheel wells, flap cables and lower flap pully attachment hardwin No corrosion found at this time.  The Aircraft was repaired in accordance with current Regulations of the Federal Aviation Administration and the manufacturer's approved.	, TEMPUSJETS	Registration #: N840AG Hobbs: 4562.0	Total Aircraft Time: 14562.0 Total Engine Time:	Total Aircraft Cycles: 88 Total Engine Cycles:
Aircraft Maintenance Actions -Removed and replaced Prop deice timer with repaired assembly P/N: 4E3163-2 S/N: U031 (ref. AMETEK B&S 8130 No. 113551, W/BEL100902, dated 05/11/2017) referencing Pilatus PC-12 AMM DMC-12-A-30-60-01-00A-920A-A. Operational check normalRemoved and replaced airfoil deice pressure regulator with overhauled assembly P/N: 4D2095-141 S/N: N061490 (ref. AMETEK B& 8130 No. 77404, W/O No. BHY100051, dated 10/20/2017) referencing Pilatus PC-12 AMM DMC-12-A-30-10-01-00A-920A-A. Operat check normalRemoved and installed new baggage net assembly P/N: 525.25.12.043 referencing Pilatus PC-12 AMM DMC-12-A-25-23-01-00A-92 -Removed and replaced L/H outboard fuel drain valve assembly PN: 115.55.07.209 referencing Pilatus PC-12 AMM Section DMC-12-A-28-10-02-00A-920A-A. No Leaks detected at this timeCleaned and inspected suspected corrosion areas in left and right wing wheel wells, flap cables and lower flap pully attachment hardway No corrosion found at this time.  The Aircraft was repaired in accordance with current Regulations of the Federal Aviation Administration and the manufacturer's approve maintenance instructions, and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.  For Tempus Jets:		VCCS Hours:		Total Propeller TSOH: Date: 06/30/201
-Removed and replaced Prop deice timer with repaired assembly P/N: 4E3163-2 S/N: U031 (ref. AMETEK B&S 8130 No. 113551, W/BEL100902, dated 05/11/2017) referencing Pilatus PC-12 AMM DMC-12-A-30-60-01-00A-920A-A. Operational check normal.  -Removed and replaced airfoil deice pressure regulator with overhauled assembly P/N: 4D2095-141 S/N: N061490 (ref. AMETEK B& 8130 No. 77404, W/O No. BHY100051, dated 10/20/2017) referencing Pilatus PC-12 AMM DMC-12-A-30-10-01-00A-920A-A. Operat check normal.  -Removed and installed new baggage net assembly P/N: 525.25.12.043 referencing Pilatus PC-12 AMM DMC-12-A-25-23-01-00A-92  -Removed and replaced L/H outboard fuel drain valve assembly PN: 115.55.07.209 referencing Pilatus PC-12 AMM Section DMC-12-A-28-10-02-00A-920A-A. No Leaks detected at this time.  -Cleaned and inspected suspected corrosion areas in left and right wing wheel wells, flap cables and lower flap pully attachment hardway No corrosion found at this time.  The Aircraft was repaired in accordance with current Regulations of the Federal Aviation Administration and the manufacturer's approve maintenance instructions, and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.	Pilatus PC-12/45, S/N 296			
maintenance instructions, and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.  For Tempus Jets:	-Removed and replaced Prop deice the BEL100902, dated 05/11/2017) reference -Removed and replaced airfoil deice 8130 No. 77404, W/O No. BHY10005 check normal.  -Removed and installed new baggage -Removed and replaced L/H outboard DMC-12-A-28-10-02-00A-920A-A. No -Cleaned and inspected suspected corrections.	pressure regulator with overhal, dated 10/20/2017) reference net assembly P/N: 525.25.12 fuel drain valve assembly P/D Leaks detected at this time.	MC-12-A-30-60-01-00A-920A-A. Opnauled assembly P/N: 4D2095-141 S/Ning Pilatus PC-12 AMM DMC-12-A-2.043 referencing Pilatus PC-12 AMNN: 115.55.07.209 referencing Pilatus	perational check normal. N: N061490 (ref. AMETEK B&-30-10-01-00A-920A-A. Operat I DMC-12-A-25-23-01-00A-92 PC-12 AMM Section
For Tempus Jets:	The Aircraft was repaired in accordance	with current Regulations of t	the Federal Aviation Administration a	and the manufacturer's approved
	below.	11/17		
	For Tempus Jets:	- MANY		Zee Van State on Language and the second second second second
		Randy Vetter Jr., A&P 2744	1696	

DUNCAN

**N840AG Vernon Aviation LLC** 

Pilatus PC-12/45 296

July 19, 201

Pi

Maintenance

Removed Pilot's and Copilot's Honeywell SG465 Symbol Generators (PN: 066-04021-1111, SN: Pilot 4009, Copilot 4686) for upgrade Installed "tested" rental Pilot's Honeywell SG465 Symbol Generator (PN: 066-04021-1116, SN: 4369, Copilot 5289) and "modified" rental Pilot's Honeywell Consister (PN: 066-04021-1116, SN: 5289) in accordance with Honeywell Installed "tested" rental Pilot's Honeywell SG465 Symbol Generator (PN: 066-04021-1116, SN: 5289) in accordance with Honeywell STC The affected systems were configured IAW Duncan Aviation document 170719002. The affected systems were ground function

Honeywell Master Drawing List, Installation of the Alternate Part Number Symbol Generator in a PILATUS PC-12, PC-12/45, and Garmin Installation Bulletin 0903, revision A. NCTE: The Honeywell Master Drawing List took precedence over any discrepancies found between the Honeywell Master Drawing

Placed a new Honeywell EFIS 40/50 Pilot's Guide, document number 006-08701-0000, revision 16, dated 8/10, in the aircraft.

Updated the aircraft \_quipment List to reflect these alterations. No Changes to the aircraft Weight and Balance.

The above described repair or maintenance is approved for return to service. A detailed record is on file under Work Order #5AQVA. CRS # JG7D076J for Duncan Avionics; Englewood, CO 80112 Total Time: Total Landings:

Total to **Carry Forward** 

NOONE

	Remarks		Signature	Cartificata No.
-ified* ell STC	TEMPUSJE	Registration #: N840AG Hobbs: 4582.3 VCCS Hours:	Total Aircraft Time: 14582.3 Total Engine Time: N/A Total Propeller Time: N/A Work Order #: C3449	Total Aircraft Cycles: Total Engine Cycles: N/A Total Propeller TSOH: Date: 07/20/2017
unction	Pilatus PC-12/45, S/N 296			
5, and	Aircraft Maintenance Action	ns	erencing Pilatus PC-12 AMM section I aired ADRS #1 P/N 124210-2022; S/N	DMC-12-A-22-20-00-00A-903A
	-Removed AHRS #1 P/N124 Northrup Grumman CRS# DE Performed ADRS #1 and #2 ca	145.0114 dated 01/AUG/2016. Referencing Pilatus Pondure followed by a flap functional test	encing Pilatus PC-12 AMM section DN	MC-12-A-34-25-01-00A-920A-7 -00-00A-903A-A.
awing	-Removed AHRS #1 P/N124 Northrup Grumman CRS# DE Performed ADRS #1 and #2 ca -Performed the flap set proce DMC-12-A-27-50-00-00A-903 The Aircraft was repaired in acc maintenance instructions, and is	145.0114 dated 01/AUG/2016. Referentiation swing referencing Pilatus Pour followed by a flap functional test BB-A. No discrepancies noted.	. D'I + - DC 12 AMM cection DM	MC-12-A-34-25-01-00A-920A-2 -00-00A-903A-A.
rawing VA.	-Removed AHRS #1 P/N124 Northrup Grumman CRS# DE Performed ADRS #1 and #2 ca -Performed the flap set proce DMC-12-A-27-50-00-00A-903 The Aircraft was repaired in acc maintenance instructions, and is below.  For Tempus Jets:	145.0114 dated 01/AUG/2016. Refere alibration swing referencing Pilatus Podure followed by a flap functional tests. No discrepancies noted.  cordance with current Regulations of approved for return to service. Perting	encing Pilatus PC-12 AMM section DNC-12 AMM section DMC-12-A-34-25 at referencing Pilatus PC-12 AMM section Pilatus PC-12 AMM section Pilatus PC-12 AMM section Federal Aviation Administration and the details are on file at this facility under the section of the	MC-12-A-34-25-01-00A-920A-7 -00-00A-903A-A.
rawing	-Removed AHRS #1 P/N124 Northrup Grumman CRS# DE Performed ADRS #1 and #2 ca -Performed the flap set proce DMC-12-A-27-50-00-00A-903 The Aircraft was repaired in acc maintenance instructions, and is below.	A10-2022, S/N 1210 and instants A10-2022, S/N 1210 and instants A145.0114 dated 01/AUG/2016. Refere alibration swing referencing Pilatus Pour and Pilatus Pour	encing Pilatus PC-12 AMM section DNC-12 AMM section DMC-12-A-34-25 of referencing Pilatus PC-12 AMM section Pilatus PC-12 AMM section the Federal Aviation Administration and the details are on file at this facility under the property of t	MC-12-A-34-25-01-00A-920A-2 -00-00A-903A-A.

TEMPUSJETS	VCCS Hours: N/A	Total Propeller Time: N/A  Needing Work Order #: A3-		/A
Pilatus PC-12/45, S/N 296	10/14/2	and the second s	and the second s	17 emoved rental Pile emoved ren
DMC-12-A-30-60-00-00A-903A -Complied with flap up and do DMC-12-A-27-50-00-00A-903A The Aircraft was inspected and/	A-A. No discrepancies noted a own limit switch servicing and A-A. No discrepancies noted for renaired in accordance wit	d performed flap functional check reat this time.  h current Regulations of the Federal	eferencing Pilatus PC-12 AMM Sectio	n stalled Modification is talled Modification in affected system affected system is the state of
	alot	A management of the second sec	<u> </u>	pdated the aircra
For Tempus Jets:	- Alth	Sp		ne above describ
				spected by: _/
Total to Carry Forward				


craft Cycles: 8903					Y
THE CYCIES. NIVA	DUNCAN AVIATION	N840AG	Pilatus PC-12/45		August 04, 2017
Her ISOH: NIA	DUNTION	Vernon Aviation LLC	296		Certificate No.
Date: 07/26/2017		d Copilot's Honeywell SG465 Sym and Copilot's Honeywell SG465 S	hal Canarator (DN): 066 040	21 1116 CN: Dilat 126	Conilet E290\
	ed rental Pilot S at	d Copilot's Honeywell SG465 Sym and Copilot's Honeywell SG465 S are configured IAW Duncan Aviat	bol Generator (PN: 066-040	04004 4444 CN: Pilot 430	9, Copilot 5289).
-	Removed "Modified" Pilot's	and Copilot's Honeywell SG465 S	symbol Generators (PN: 066-	-04021-1111, SN: Pilot	4686, Copilot 4009)
ection	Bacieu System				
AMM Section	The allocation according in according to acc	ordance with the following docume	nata Bart Number Symbol G	enerator in a PII ATLIS	PC-12 PC-12/45 and
Limit Section	Honeywell Master Di	umber 159-08329-0001, revision A	, dated 12/16/2008.	ienerator in a l'ibrioc	7, 6, 12, 16, 12, 16, 4, 4,
and the	carmin Installation B	ulletin 0903, revision A.			annual Master Proving
facility under the	NOTE: The Honeywell	viaster Drawing List took preceder	nce over any discrepancies	found between the Hor	neywell Master Drawing
	· A Fauin	mont List to reflect these alteration	ns. No Changes to the aircra	aft Weight and Balance	•
	Updated the allorant Equip	or maintenance is approved for r	eturn to service A detailed	record is on file under	Work Order #5AQVA.
	The above described repair	or maintenance is approved for i	Clarif to Scration. 71 actained		
	1/7	DUNCAN		an Avionics; Englew	ood, CO 80112
	Inspected by:	/Wa W 1336	Total Time:	Tot	al Landings:
	CRS # JG7D076J		gladica mentangan kanangan pada salah s		
	11				
	4				
100	The second second	And the second of the second o			
	Jan All			and the state of t	
Part of the second of the seco					
		A Part of the second			

DUNCAN	N840AG Tempus Aircraft		us PC-12/45 5/N: 296	August 4, 2017	TEMPL
Removed existing Navig Database Card IAW Ber	gation Database Card ndix/King KMD 540 II	from customer's KMD 54 M. No defects noted at this	40 Multifunction Display time.	and installed updated Navigation	Pilatus PC-12/
KMD 540 Multifunction	n Display (PN: 066-04	035-0101, SN: KMD540-8	3873).		Aircraft Main -Complied w
		: PN: 071-00161-0203, SN : PN: 071-00161-0201, SN			VAPOR CYCL Pilatus PC-12 A -Removed w emergency wir
No current US airworth	niness directives apply.				The Aircraft w maintenance in below.
The above described #5CBNA. Signed:	repair or maintenance	is approved for return to  DUNCAN QI 1473		cord is on file under Work Order nics; Englewood, CO 80112	For Tempus Je WO# C3449
For Duncap Aviation	CRS # JG7D076J	Phone: 303-649-1790		Total Landings:	
					1///
Total to					4
Carry Forward	man regional de mandales.	nteri siyota Tuur ahasis			

August 4, 2017		Registration #: N840AG	Total Aircraft Time: 14582.3	Total Aircraft Cycles: N/A
updated Navigation	TEMPUSJETS	Hobbs: 4582 3	Total Engine Time: N/A Total Propeller Time: N/A Work Order #: C3449	Total Engine Cycles: N/A Total Propeller TSOH: Date: 07/20/2017
APR-2014 UG-2017	VAPOR CYCLE COMPRESSOR Pilatus PC-12 AMM Section DMC	MOTOR DRIVE BELT. Belt -12-B-21-50-01-00A-903A-A.n oly P/N: 525.24.12.099, S/N: 230	ONING - COMPRESSOR / CONDEN was not within limits, performed the book of defects noted. Operational check sates 322 and installed new window shade -CM-00-00-00-1.	elt adjustment procedure reference isfactory.
ider Work Order O 80112	The Aircraft was repaired in accord maintenance instructions, and is applelow.  For Tempus Jets:  WO# C3449	proved for return to service. Per	of the Federal Aviation Administration tinent details are on file at this facility TRS# 3TPR073R	and the manufacturer's approved under the work order referenced
-				

	aft Time	Recorder	Maint	anance
* This Date	Registration #: N840 Hobbs: 4652 VCCS Hours: 884.2	.2 Total Eng		Total Aircraft Cycles: 8960 Total Engine Cycles: 84 Total Propeller TSOH: ate: 09/15/2017
12/45, S/N 296 Performed a 100 Hour Inspection of the complete complication of the complete complication of the complete complication of the complete complication of the complete comp	alice cliccked directly	Section DMC-12-A.	12-10-05-00A-902A-A.	ection
craft Scheduled Maintenance Complied with 1 year/150-hour C-12-A-27-50-00-00A-902A-A Removed and re-installed #1 lea formed 3-month capacity check Removed and installed #2 lead a formed 3-month capacity check Complied with 200 hour/12 mon IC-12-A-12-20-07-00A-902A-A Complied with 5-year duct over	and Inspections I flap actuator lubrication s A. Indicate a service of the servic	service referencing P. 000 referencing Pilat M section 24-30-71. 5 referencing Pilatus M section 24-30-71. It switches servicing	latus PC-12 AMM Section us PC-12 AMM section 12 Next capacity check due: I PC-12 AMM section 12-A Next capacity check due: I according to Pilatus PC-12 Pilatus PC-12 AMM Section	n 2-A-24-30-07-00A-920A-A. Dec 2017. A-24-30-07-00A-920A-A. Dec 2017. 2 AMM Section

**Carry Forward** 



Registration #: N840AG

Hobbs: 4676.2

VCCS Hours: 0.40

Total Aircraft Time: 4676.2

Total Engine Time: N/A

Total Propeller Time: N/A

Work Order #: A3513

Total Aircraft Cycles: Notal Engine Cycles: Notal Propeller TSOH: N

Date: 10/05/20

Pilatus PC-12/45 S/N 296

### Aircraft Maintenance Actions

TEMPUSJETS

Removed old VCCS PN: 959.90.22.102 SN: 793 and installed new VCCS PN: 959.90.22.140 SN: 2055 referencing Pilatus PC-12 AMM Section DMC-12-A-21-50-01-00A-920B-A. Operational checks normal.

The Aircraft was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and the manufacturer's approved maintenance instructions, and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.

For Tempus Aircraft Sales & Service:

WO# A3513

Ashely Baumgartner A/P 3681560

# **Bode Aviation**

1260 W Navajo ST Hanger 6, Farmington NM 87401


**Airframe** 



10/16/2017 N840AG a/c hrs 14685.1

AD 2017-16-01 Ameri-King ELT N/A affected equipment not installed Aircraft has ARTEX 406 ELT installed. AD 2017-18-12 Aerospace PBE oxygen mask N/A affected equipment not installed.


Terrell Grimes 3465915 A&P IA




Ch. 12-A-34-11-20-00A-001

12-A-34-14-00-00A

The



ate	Bode Aviation  1260 W Navajo ST Hanger 6, Farmington N	NM 87401	Airframe	BODE
	11/28/2017 N840AG a/c hrs 14730.3 Performed 6 month inspection of ICA Airb ICA Circuit Breaker in accordance with sup Aircraft is approved for return to service.  Terrell Grimes 3465915 A&P IA	oorne Position Doplement ICA080	ata Communicator, ICA ( 13-1 Para. 601, A & B. N	Cockpit Display Panel a o discrepancies found.
	Bode Aviation  1260 W Navajo ST Hanger 6, Farmington NM	1 87401	Airframe	BÖDE
_   1	12/14/2017 N840AG a/c hrs 14744.3 Removed battery #1 s/n 40539000 perform 40904128in #1 (aft) position. Removed batters alled p/n RG-380E/44 s/n 40906050 in installation. Next capacity checks due 12/20	ned capacity che tery #2 s/n 4053 #2 (fwd) positio	38995, performed capacit n. Both batteries showed	cy check, battery faile l over 25.8 volts befo



### Aircraft Maintenance Actions

- Serviced hydraulic system referencing Pilatus PC-12 AMM section 12-A-29-00-00A-902B-A. Performed the Extension and retraction functional tests of the landing gear referencing Pilatus PC-12 AMM section 12-A-32-30-00-00A-903A-A. Functional test checks good. While landing gear was retracting, did note the right main landing gear actuator is seeping hydraulic fluid. No action required at this time, recommend continuing evaluation.
- Adjusted passenger seat # 1&3 swivel mechanism referencing Goodrich Aerospace CMM 25-20-07. Operational check good.
- Adjusted passenger seat # 3&4 recline mechanism referencing Goodrich Aerospace CMM 25-20-07. Operational check good. - Installed new cotter pin P/N 968.20.12.319 on the L/H aft latch on panel 43AL referencing Pilatus PC-12 AMM section
- 12-A-71-10-00-00A-903A-A. Operational check good.

I certify that this Aircraft has been inspected in accordance with a Pilatus 100 Hour Inspection and was determined to be in airworthy condition and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.

For Tempus Jets: WO#C3577

Aircraft Maintenance Actions

- Serviced hydraulic system referencing Pilatus PC-12 AMM section 12-A-29-00-00A-902B-A. Performed the Extension and retraction functional tests of the landing gear referencing Pilatus PC-12 AMM section 12-A-32-30-00-00A-903A-A. Functional test checks good. While landing gear was retracting, did note the right main landing gear actuator is seeping hydraulic fluid. No action required at this time reco



Reg. #: Make:

**N840AG PILATUS**  Date: Model: **December 18, 2017** 

S/N:

296

Customer:

**Tempus Aircraft** 

TT:

14753.3

PC-12

. Comp No disc

Comp

12-A-2 . Comp

- Comp

Performed new battery change Issued 8130-3 for this work.

Tested and inspected ELT IAW ARTEX C406-N Series ELT Description, Operation, Installation and Maintenance Manual Doc. No. 570-5060 Rev. K Dated Dec 01/14 and found it to be in compliance with FAR Part 91.207 paragraph (d).

ELT: ARTEX C406-N. PN: 453-5060, SN: 05304. Hex I.D.: ADC6498C28DE2B1. Battery: PN: 452-0133 Rev. AB, SN: 376115-020. Exp. Date: FEB/2023.

Inspected the Artex C406-N ELT system in this Aircraft according to applicable Aircraft and ELT manufacturer's instructions and applicable FAA guidance and found that it meets the requirements of section 91.207(d).

The above described repair or maintenance is approved for return to service. A detailed record is on file under Work Order #

- 5MFDA.

Signed:

Duncan QI 1224

For Duncan Aviation Repair Station JG7D076J Phone: 303-649-1790

# Registration No.\_

TEMPUSJETS

Registration #: N840AG

Hobbs: 4853.7

VCCS Hours: 12.3

Total Aircraft Time: 14853.7 Total Engine Time: 299.4

Total Propeller Time: 299.4

Work Order #: C3634

Total Aircraft Cycles: 9112 Total Engine Cycles: 232

Total Propeller TSOH:

Date: 02/22/2018

PC-12/45, S/N 296

ile

end

PC-12/45, 5/14 200

-Performed a 100 Hour Inspection using the Pilatus PC-12/45 100-hour checklist. Airworthiness Directive compliance checked through Revision 2018-04.

Serviced aircraft oxygen referencing Pilatus PC-12 AMM Section 12-A-12-10-05-00A-902A-A.

Complied with continued airworthiness inspection requirements for installed equipment as required.

-Complied with 6-month application of Age Master to surface deicers referencing Pilatus PC-12 AMM Section 12-A-05-10-20-00A-281A-A.

# Aircraft Airworthiness Directives and Service Bulletins

-Found AD 2017-04-06 United Instruments Altimeters is Not Applicable by Model # installed in Pilot and Co-pilot Altimeter positions. This AD is not applicable at this time and date.

-Found AD 2018-03-04 Rosemont Aerospace repaired pitot tubes are not applicable by model and serial number installed on left and right wings. This AD is not applicable at this time and date.

#### Aircraft Scheduled Maintenance and Inspections

- Complied with 200-hour generator #2 brush check referencing Pilatus PC-12 AMM Section 12-A-24-30-01-00A-313A-A. No discrepancies noted.

-Complied with 1 year/150-hour flap actuator lubrication service referencing Pilatus PC-12 AMM Section 12-A-27-50-00-00A-902A-A.

- Complied with 1000 hour starter/generator overhaul by removing P/N- 23085-030; S/N-P1009 and installing overhauled starter generator P/N- 23085-030; S/N-99357. See FAA Form 8130-3 from AMETEK B&S Aircraft Parts & Accessories CRS# NE2R028L dated 09/JUL/2015 placed in the aircraft records. Referencing Pilatus PC-12 AMM Section 12-A-24-30-01-00A-920A-A.

- Complied with 150 hour / Annual inboard flap drive arm in-situ inspection/check referencing Pilatus PC-12 AMM Section 12-B-27-51-00-00A-313A-A. No discrepancies noted.

- The affected parts, P/N: 945.02.02.201 and P/N: 945.02.02.202 that require the 2000-hour flap drive shaft lubrication are not installed. Flap drive shaft cable P/N: 945.02.02.205 and P/N: 945.02.02.206 are installed. This time compliance is no longer APPLICABLE for this aircraft. Reference Pilatus PC-12 AMM section 12-A-05-10-20-00A-281A-A and parts installed on aircraft.

- Complied with 200 hr./12 months flap up and down limit switches servicing according to Pilatus PC-12 AMM Section 12-A-12-20-07-00A-902A-A.

Page 1 of 2

#### Aircraft Maintenance Actions

-Removed copilots EHSI, EFIS screen P/N: 066-03125-2500, S/N: 2374 from aircraft and installed REPAIRED EFIS unit P/N-066-03125-2500; S/N- 2680 from Honeywell International Inc.; Certificate No. PR2R093L; Dated 22/DEC/2017, referencing the Pilatus AMM section 12-A-34-26-02-00A-920A-A. Operational check satisfactory.

- Customer report: Check cabin window shades for operation, several might not be working as they should. To be complied with at annual

inspection.

-Replaced 5 light bulbs total P/N: OL6839 from Pilot and Co-pilot AHRS switches referencing Pilatus PC-12 AMM section 12-A-31-11-01-00A-920A-A.

All the above work complied with in accordance with owner operators 135 GMM.

Aircreft Time

I certify that this Aircraft has been inspected in accordance with a Pilatus 100 Hour Inspection and was determined to be in airworthy condition and is approved for return to service. Pertinent details are on file at this facility under the work order referenced below.

For Tempus Jets:

WO# C3634

Rulan

Ronald C. Gish

CRS#3TPR073R

Page 2 of 2

# **Bode Aviation**

1260 W Navajo ST Hanger 6, Farmington NM 87401

**Airframe** 

4/20/2018 N840AG Hobbs 4938.2

Checked aft seat belt light, found broken wire at lamp. Re-soldered wire. Ops check was good.

Approved for return to service.

Terrell Grimes 3465915 A&P

**Carry Forward** 



Registration No. OK3-18-5310 W/O#: 4952.2 Hobbs: No. Pilatus 14952.2 Make: Total Time: PC-12/45 AMM Model: 9183 Landings: 296 S/N: Freon Hobbs: 22.5 N840AG Reg #: 1980 Airport Rd. Hangar A Heber City, UT 84032 nual Teertify that this Aircraft has been inspected in accordance with a 100-Hour Inspection using PC-12 AMM 12-A-05-20-10-00A-- 281A-A and was determined to be in airworthy condition. Complied with the following Chapter 4/5 Special Inspection Items: Inboard Flap Drive Arms In-situ Inspection / Check IAW AMM 12-A-27-51-00-00A-313A-A. LH & RH Inboard & Outboard Flap Actuators Lubrication IAW AMM 12-A-27-50-00-00A-902A-A. Ice / Rain Protection Airfoil Deicers Treatment by cleaning / applying a surface coating of Age Master No. 1 to all Airfoil Deicers. - Complied with the following Instructions for Continued Airworthiness (ICA) Inspections: Airborne Position Data Communicator (ICA) Inspection IAW Manufacturer's Instructions. No faults found. Cockpit Display Panel (ICA) Inspection IAW Manufacturer's Instructions. No faults found. Check Circuit Breaker (ICA) Manufacturer's Instructions. No faults found. Addressed the following Discrepancies: Lamps in AFT Fasten Seatbelt / No Smoking Light replaced with new P/N: 1202-300. Bled & Serviced LH & RH Brake Systems as needed IAW AMM. Serviced the Hydraulic System Reservoir with Fluid & Dry Nitrogen IAW AMM 12-A-29-00-00A-902A-A. Serviced the Oxygen System IAW AMM 12-A-35-00-00-00A-902A-A. AFT Switch Guard Bar on Center Pedestal tightened as needed. Serviced the Hydraulic Accumulator with Nitrogen IAW AMM 12-A-29-10-02-00A-901A-A as needed. #5 Cabin Window Shade Repaired as needed using replacement Kit P/N: 950.10.00.091. Rheostat Knob on Copilot's Map Light Assembly replaced with new P/N: 944.34.17.111. Lower Static Wick on Rudder replaced with new P/N: 984.78.81.406. The Aircraft, Airframe, Aircraft Engine, Propeller, or Appliance identified above was repaired and inspected by OK3Air CRS W77R917Y in accordance with current Federal Aviation Regulations and was Approved for return to service. Pertinent Details are on file under this work order.

Date: 5/1/18

Authorized Inspector:

Fodd Hopkinson

	Aircraft	Time Recorder				
Date	This Date	Total Reading		Maintenance		
	Brought —>					
					And the second	
	E BUSINESS OF AVIATION*	Cutter Aviation Phoenix 2802 E Old Tower Road Phoenix, Arizona 85034 FAA Repair Station No, EKGR571D	I	Phone: 602-273-1237 Fax: 602-267-7806		
egistration	N840AG	4.0	Work Order	02M-10781		
odel	PC-12/45	Airframe	Tach	N/A		
erial No	296	Log Rook Enter	Hour meter	N/A		
Aircraft TT	14,976.90	Log Book Entry	Landings	2004		

Removed and replaced cargo door handle micro switch arm P/N 973.30.24.202, ops check good, in accordance with the Pilatus PC-12/45 AMM 12-A-52-70-04-00A-920B-A.

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details are on file at this repair station.

Signature

Kevin Reedy

Landings

9206

W/O#: Make: Model: S/N: Reg#:

MLG Hin

Main / No

LH & RH

Propeller Vapor Cy

Outflow /

Cabin Po

### Registration No.

OK3AIR

1980 Airport Rd. Hangar A Heber City, UT 84032

Hobbs: 5002.5 Total Time: 15002.5

Landings: 9230 Freon Hobbs: 33.9

I certify that this aircraft has been inspected in accordance with an Annual Inspection using the Pilatus AMM 12-A-05-20-20-00A-281A-A and was determined to be in airworthy condition.

Complied with FAR 91.207(d) by ELT Inspection / Function test - No faults found. Battery due: 02/2023.

Accomplished an Aircraft Avionics Inspection / Operational Check IAW applicable sections of the PC-12 AMM and

Manufacturer's Maintenance / Operational Instructions. All applicable checks were satisfactory.

Complied with the following Instructions for Continued Airworthiness (ICA) Inspections:

GPS / Iridium Combination Antenna (ICA) IAW Manufacturer's Instructions. No faults found.

ISAT-100 Back-up Battery P/N:PS-1212 removed. Installed new Battery P/N: ISAT-100-BAT, S/N: 18031410 IAW Skytrac

ISAT-100 Battery Replacement Manual DOC0945 (Current Revision).

OK3-18-5334

Pilatus

296

PC-12/45

N840AG

W/O#:

Make:

S/N:

Model:

Reg #:

Complied with the following Chapter 4/5 Special Inspection Items:

Internal / External Aircraft Corrosion Inspection IAW AMM 12-A-20-40-00-00A-901A-A.

- Auto Flight Servo Mount Clutches Inspection / Check IAW AMM 12-A-22-10-00-00A-313A-A.

Cockpit Fire Extinguisher Contents Check IAW manufacturer's instructions.

Horizontal Stabilizer Trim Runaway Aural Warning Functional Test IAW AMM 12-A-27-40-00-00A-903A-A.

Inboard Flap Drive Arms In-situ Inspection / Check IAW AMM 12-A-27-51-00-00A-313A-A.

Emergency Power Supply removed, capacity checked, and re-installed IAW AMM 12-A-24-52-51-00A-920A-A & CMM.

Ice / Rain Protection Airfoil Deicers Treatment by cleaning / applying a surface coating of Age Master No. 1 to all Airfoil Deicers.

LH & RH Inboard & Outboard Flap Actuators Lubrication IAW AMM 12-A-27-50-00-00A-902A-A.

Aileron Control System Bearings Lubrication IAW AMM 12-A-27-10-00-00A-901A-A.

LH & RH Flap Up / Down Limit Switches Servicing IAW AMM 12-A-12-20-07-00A-902A-A.

MLG Hinge Pin & Bushes Inspection / Check IAW AMM 12-A-32-10-00-00A-313A-A. Dimensions within limits.

— Main / Nose Wheel Bearing Lubrication IAW AMM 12-A-12-20-06-00A-902A-A.

LH & RH MLG Shock Absorber Top and Bottom Attach Bolt & Nut Inspections IAW AMM 12-A-32-10-00-00A-310A-A.


Propeller Feathering Micro-Switches Test IAW AMM 12-A-76-10-02-00A-903A-A.


Vapor Cycle Compressor Condenser Module Cleaning IAW Enviro Systems, Inc. CMM 21-00-23.


Outflow / Safety Valve Removal / Cleaning IAW AMM 12-A-21-30-01-00A-250A-A.

= Cabin Positive Pressure Relief Functional Test IAW AMM 12-A-21-30-00-00A-903A-A.

(Continued on Next Page)







and Remarks



Certificate No.

CRS: W77R917Y HEBER CITY, UT 84032

**N840AG** 

	STATIC SYS #1 TEST ALT: 2	3,000	STATIC SYS #2 TE	ST ALT: 23,000	STATIC	SYS #3 TEST ALT: N/	<u>A</u>
	STATIC STORT TECT	MAKE	MODEL	P/N	<u>S/N</u>	TESTED ALT	
	ALTIMETER #1	Bendix / King		066-03062-0010	4040	35,000	
	ADC/ENCODER #1			066-03062-0010	4040	35,000	
-	ALTIMETER #2	United	N/A	5035P-P50	29639	35,000	
	ADC/ENCODER #2		N/A	5035P-P50	29639	35,000	
-	ALTIMETER #3	N/A	N/A	N/A	N/A	N/A	-
	TRANSPONDER #1	Garmin	GTX 345	011-03302-00	3EG020868	N/A	
_	TRANSPONDER #2			066-01141-0201	30303	<u>N/A</u>	
	THE HADE OF THE BETT III						

Tests & Inspections Performed in Accordance with FAR 43, Appendix E to Comply with FAR 91.411 X; Appendix F to Comply with FAR 91.413 X. Pertinent Details Are on File at This Repair Station Under W/O#: OK3-18-5334.

Date: 7/01/18

isher

are

Authorized Individual:

Podd Hopkinson

· V		Aircra	ft Time	Recorder		aintenance
	Date	This Date	Total	Reading		difference
	Leading the Bu	Siness of Aviation	Ph	302 Old Tower Road oenix Arizona 85034 oair Station No. EKGR571D		602-267-4070 Phone 602-267-4030 FAX
	Model	PC-12/45	A i wa wa	ft Maintanana	Work Order No	o. <b>02A-10882</b>
7990	Serial No.	296	Aircra	ft Maintenanc	e Hour Meter	5009.7
	Registration	N840AG		Record	Aircraft Total T	Time
	Page	1 of 1			Landings	
	Coan an     Co     F.  The aircraft an	anual, Chapters 12-A-3 omplied with 24 month d FAR Part 43 Append d Part 43 Appendix E v omplied with 24 month #1 and #2 Transponder	certification of pitot slix E. Pilot and co-pilot worksheet for certific certification of transpers are approved for refield above was repaire	A and 12-A-34-14-00-00 static system to an altituot altimeters are approve ation results.  Sonder system in accordance to the service of the	oA-903A-A.  de of 35,000 feet in acced for return to service  ance with FAR 91.413  ce Cutter Form 401 for	eral aviation regulations and is
	Signed	-	- Mug		Kevin Reedy	Date: July 24, 2018 _
			FAA	Repair Station No. EKGR571D	The state of the s	
	al to rry Forward					

Signature	BODE
Airframe	TAIN!
1)2t2 Communicates ICA C	kpit Display Panel and discrepancies found.
ı	Data Communicator, ICA Coc 3013-1 Para. 601, A & B. No c

Leading the Business of Aviation

2802 Old Tower Road Phoenix Arizona 85034 FAA Repair Station No. EKGR571D

Dasardar

602-267-4070 Phone 602-267-4030 FAX

Model Serial No.

Registration

296

**N840AG** 

PC-12/45

Page 1 of 1 Aircraft Maintenance Record

Work Order No. Hour Meter Aircraft Total Time Landings

02M-11057 5101.0

- Performed No.1 battery capacity check, battery passes. Performed recharge of battery and reinstalled into aircraft. Operational check good. Work performed reference Concorde Battery Doc. # 5-0171 (CMM 24-30-71). PC-12 MM 24-00-
- Performed No.2 battery capacity check, battery passes. Performed recharge of battery and reinstalled into aircraft. Operational check good. Work performed reference Concorde Battery Doc. # 5-0171 (CMM 24-30-71). PC-12 MM 24-00-
- Applied a surface coating of age master to airfoil deicers. Reference Goodrich CMM 31-00-23.
- Cleaned air conditioning compressor condenser module IAW CMM subtask 21-00-23-10-001.
- Inspected and cleaned passenger O2 masks IAW 12-A-35-20-00-00A-313A-A.
- Removed and replaced nose landing gear torque tube. Installed new torque tube part number 532.50.12.064. Reference 12-
- Performed operational test of OAT system, ops check good. Performed continuity check of OAT wiring, no faults found. Referencing the Pilatus PC-12/45 AMM 12-A-34-12-00-00A-040A-A.
- NO. 1 Propeller Inspection Tear-Down not Applicable Propellers, used in unlimited competition and / or airshow aerobatic flying (auto rotation maneuvers with high engine power and high propeller speed, for examples: flat spins, snap rolls, knife edge spins, etc.), must get a tear-down inspection every 1/3 of the TBO (hours or months). This aircraft does not do aerobatic flying.
- Checked No. 1 Engine ignition exciter for installation and condition IAW 12-A-74-10-01-00A-920A-A.
- Performed No. 1 Engine oil sample and sent out for analysis.
- Performed fuel pump corrosion inspection on No. 1 Engine. Found no discrepancies. Work performed referencing Pratt

THE STATE OF THE S		component identified abo to service with respect to	ve was repaired and insp the work performed. Per	ected in accordance v tinent details are on fi	vith current federal aviati le at this repair station.	on regulations and is
Malled imp aircraft 30-71). PC-12 MM 24-0.	Signed:	(N	FAA Repair Station	No. EKGR571D	Date:	<u> 11/9/18</u>
1/16						
ed into aircraft. 71). PC-12 MM 24-10.						
24-00 24-00 V						
F -						
064. Reference 12.						
neterence 12.						
no faults found						
airshow -						
at spins, snap						
- I	Section 2 198					

#### AIDCD AET LOC



Carry Forward

2802 Old Tower Road

Leading the Busin	ness of Aviation	Phoenix Arizona 85034 FAA Repair Station No. EKGR571D		602-267-4070 Phone 602-267-4030 FAX
Model	PILATUS PC-12/45	A1 C/ BE 1 /	Work Order No.	02M-11092
Serial No.	296	Aircraft Maintenance	Hour Meter	5116.6
Registration	N840AG	Record	Aircraft Total Time	15116.6
Page	1 of 1	rtooora	Landings	9319
Insp to s 00- • Pile Ins arm - A-:	pected NLG up and down loswitches, function check god- 00A-903A-A.  ot reports Landing gear hand pected RH MLG weight on m, no faults found, function 32-60-12-00A-920A-A.  Ind for component identified a return to service with respect	red light comes on intermittently in cruise whock proximity switches and checked rigging, and, referencing the Pilatus PC-12/45 AMM 12 dle will not unlock after takeoff.  wheel switch and rigging no faults found. Insucheck good, referencing the Pilatus PC-12/45 and the pilatus PC-12/45 are on the work performed. Pertinent details are on the switch and inspected in accordance to the work performed. Pertinent details are on the switch and inspected in accordance to the work performed.	no defects noted. Cleaned 2-A-71-00-03-00A-250A pected landing gear hand AMM 12-A-32-30-05-00	d electrical connectors -A, and 12-A-32-20- le lock solenoid and 0A-920A-A, and 12- ion regulations and is
		FAA Repair Station No. EKGR571D		
Total to				

1260 W Navajo ST Hai 04/19/2019 N840AG A	noon & Commington AINA			BC
04/19/2019 N840AG A		87401	Airframe	
Performed 6 month in	rspection of ICA Airborr ordance with supplemen	ne Position I ot ICA08013-	Data Communicator, IC 1 Para. A & B. No disc	CA Cockpit Display crepancies found.
Ferrell Grimes 3465915	A&P Grade	In		
DUNCAN Reg. #:	N840AG	Date:	May 02, 2019	
DUNCAN Reg. #:  Make:	N840AG PILATUS AIRCRAFT LTD	Date: Model:	May 02, 2019 PC-12	S/N:

A detailed record is on file under Work Order # 6P2QA. Signed:

DUNCAN QI 1224

For Duncan Aviation Repair Station JG7D076J Phone: 303-649-1790

Model	PILATUS PC-12/45	Total Repaired	Work Order No.	. 14MN-134
Serial No.	296	Aircraft Maintenance	Hour Meter	5200.5
Registration	N840AG	Record	Aircraft Total Time	15200.5
Page	1 of 2	Record	Landings	9374
		ead acid battery #2 capacity test for main	71 /11 / 2/ 20 71 Main bo	ttery tests good at O'
apacity. Next 30-10/79 - Co 13A-A and Go 79-00/80 - Per ue 15300.5FH <b>A.D. 2019-07</b> -	capacity test due 15800.5Flompleted 6 month Agemas oodrich CMM 30-10-31. form engine oil sample as I.	2-A-24-30-07-00A-920A-A and Concorde C H or 11/30/2019. ter de-ice boot treatment referencing Pilate required referencing Pratt and Whitney EMI TEF GmbH LCR-100 Attitude and Heading	us PC-12 AMM section M 72-00-00 and SIL-GE	12-A-30-10-00-00A N-153. Next sample
apacity. Next 30-10/79 - Co 13A-A and Go 79-00/80 - Per	capacity test due 15800.5Flompleted 6 month Agemas oodrich CMM 30-10-31. form engine oil sample as I.	H or 11/30/2019.  ter de-ice boot treatment referencing Pilate  required referencing Pratt and Whitney EMI	us PC-12 AMM section M 72-00-00 and SIL-GE	12-A-30-10-00-00A N-153. Next sample
eapacity. Next 30-10/79 - Co 13A-A and Go 79-00/80 - Per lue 15300.5FH <b>A.D. 2019-07</b> - nstalled LCR-9	capacity test due 15800.5Flompleted 6 month Agemas oodrich CMM 30-10-31. form engine oil sample as I.	H or 11/30/2019.  ter de-ice boot treatment referencing Pilate  required referencing Pratt and Whitney EMI	us PC-12 AMM section M 72-00-00 and SIL-GE	12-A-30-10-00-00A N-153. Next sample not applicable by P



# 12180 E. Control Tower Road Englewood, CO 80112

303-799-4539 FAX

303-799-9999 Phone

<u>Discrepancies</u> Removed NLG left and right drag link assemblies removed and replaced lower link assembly with new PN 532.20.12.135 and Removed NLG left and right drag link assemblies removed and replaced lower link assembly with new PN 532.20.12.135 and Removed NLG left and right drag link assemblies removed. Referencing Pilatus PC-12 AMM section 12-A-32-20-05-00A-920A-A, 12-A-32-20-06-00A-920A-A and 12-A-32-30-00-00A-903A-A.  Cleaned and lubricated seal referencing Pilatus PC-12 AMM section 12-A-52-30-03-00A-920A-A.  Removed Left brake PN 30-244, SN 1087 and installed overhauled assembly PN 30-244. SN 2134 referencing Parker Cleveland CMM CM30-244 and Pilatus PC-12 AMM section 12-A-32-40-03-00A-920B-A. See 8130-3 from Parker Hannifin Aircraft Wheel and Brake CRS# QPWR872L dated 16/APR/2019 placed in aircraft records.
The aircraft and lor component identified above was repaired and inspected in accordance with current CFR Title 14 Part 91.409 (f) (3) and is approved for return to service with respect to the work performed. Pertinent details are on file under Work Order 14MN- 134.

Signed: Relul Con	Ronald C Gish A/P 3650077	_ Date:	06/MAY/2019
		-	
			1

DUNCAN Reg. #:	N730NG	Date:	August 09, 2019	
Make:	PILATUS AIRCRAFT LTD	Model:	PC-12/47E	Aircraft S/N: 17
Customer:	<b>Cutter Aviation</b>	TT:	222.5	Landings: 11
Performed the 24 month certifications inspections, ADC, standby altimed CFR Part 91.411, and the ATC to performed an found to comply with Performed tests Task 34-11/82, Maintenance Manual chapter 12.  1/2 ADC P/N:065-00188-5.  Standby Altimeter: P/N:926.  #1 Transponder P/N:066-0.  #2 Transponder P/N:066-0.  The ADC was tested to 35,  The standby altimeter was.  The #1/2 transponders we.  The #1/2 encoder data con.  The #1/2 static pressure sy.  The above described repair or maintenance of the pressure sy.	eter, and automatic programs are tested and automatic progra	ressure altitudes aspection requived as Appendice at the	e reporting system testired by Title 14 CFR Paris E and F. Table 7 of the Pilatus Ped Inspection Requires  Let on 08/09/19.  08/09/19.	art 91.413 have been
Signed:		66		47 1127
For Du	ncan Aviation Repair	Station JG7D	0076J Phone: 303-649	9-1790
Total to Carry Forward				

Leading to Model Corial No.			trol Tower Road d, CO 80112			303-799-4	999 Phone 539 FAX
41-41	the Business of Aviation		107.0122	VC	CS Hobbs: 82.4	4.	P. Comment
1 1000	PILATUS PC-12/45			Wor	k Order No.	14MN- 17	73
Model	296	Aircraft Ma	aintenanc	Hou	Meter	5230.3	
Serial No.		Por	ord	Aircr	aft Total Time	15230.3	
Model Serial No. Registration Page					0.1.1	9392	
600 FH/1: 018A-A in Performe: This aircra 12-A-05-20 00-00/45 - 901A-A. 22-10/60 - 00A-313A-/ 24-50/70 - Pilatus PC- JG7D076J 0 24-30/228 - 12-A-24-30- 26-20/24 - 1 27-40/1 - 30 AMM 12-A-2 27-50/76 - 1	at this aircraft has been in Market M	3 Appendix D, and was ed Inspection and Main to the revised PC-12 miles of the referencing Pilated 12 Month Emerge POA-920A-A and L3 Color aircraft records. The remail power operation of the referencing Pital stabilizer trim runs of 12 Months flap actual pomplied with re-occurring Pital stabilizer trim runs of 12 Months flap actual pomplied with re-occurring Pital stabilizer trim runs of 12 Months flap actual pomplied with re-occurring Pital stabilizer trim runs of 12 Months flap actual pomplied with re-occurring Pital stabilizer trim runs of 12 Months flap actual process of the revised PC-12 miles of the re	determined to ntenance: aintenance: aintenance pole of clutch torque tus PC-12 AMP ency power summunications all test reference pole away aural watter backlashing AD 2001-10	be in an ain licy, per Pilat ction referen ue check ret M section 12 upply capac CMM 24-30- ncing Pilatus amm 12-A-26 arning syste	vorthy condition tus PC-12 Servering Pilatus P	vice Letter 20 C-12 AMM 1 us PC-12 AM 0A-313A-A. S-855 S/N 8 -3 from Dunc 2-A-24-30-00 0A-A. test reference	00, PC-1 2-A-20-4 IM 12-A 1486. R can Avia 0-00A-9

Continued on page 2



12180 E. Control Tower Road Englewood, CO 80112

Aircraft Maintenance Record Continued from Page 1

303-799-9999 Phone 303-799-4539 FAX

27-50/437 - 600FH/12 Month Inboard flap drive arm in-situ inspection and check referencing Pilatus PC-12 AMM 12-A-27-51-28-10/146 - 300FH/12 Month Fuel sample from each drain valve and examined for water referencing Pilatus PC-12 AMM 12-A-05-

32-10/80 - 12 Month Main and Nose wheel bearing lubrication referencing Pilatus PC-12 AMM 12-A-12-20-06-00A-902A-A. 32-10/60 - 12 Month Main landing gear hinge pin and bushes inspection and check referencing Pilatus PC-12 AMM 12-A-32-

32-10/162 - 600FH/12 Month Main landing gear lubrication referencing Pilatus PC-12 AMM 12-A-12-20-04-00A-902A-A. 32-10/102 - 000FH/12 Month Main landing gear shock absorber top and bottom attachment bolts and nuts examination

referencing Pilatus PC-12 AMM 12-A-32-10-00-00A-310A-A. 32-20/266 - Nose landing Gear spring strut P/N 532.20.12.249 is installed in aircraft. Inspection not required.

32-20/200 - Nose landing Ocal Spring State of Section 2012 120/200 - Nose landing gear actuator fuselage attachment fitting examination referencing Pilatus PC-12 AMM 12-A-05-40--00-00A-000B-A.

24-30/62 - 24 Month Generator 1 & 2 and Battery 1 & 2 ground point examination corrosion protective layer referencing

Pilatus PC-12 AMM 12-A-24-30-00-00A-901A-A. 34-21/84 - 24 Month Standby magnetic compass calibration referencing Pilatus PC-12 AMM 12-A-34-21-00-00A-903A-A. New

compass card installed. 21-50/433 - 12 Month Vapor cycle compressor module cleaning and inspection referencing Enviro Systems CMM 21-00-23.

34-25/85 - 24 MO AHRS #1/#2 check swing. Referencing Pilatus PC-12 AMM 12-A-34-25-00-00A-903A-A. 56-11/332 - 120 month inspection/check of cockpit side windows referencing PC-12 AMM 12-A-56-11-02-00A-313A-A, no

defects noted at this time. - 25-20/295 - Verify passenger seat belt MFG date for overhaul verification. CAMP Due 07/31/2019. Verified passenger seat belt MFG

date 07/2015 next compliance due 07/31/2027. 25-60/231 - Performed 1 Year ELT inspection referencing FAR 91.207 (d). ELT P/N 453-5060, S/N 05304. Battery Exp Date

02/2023.

Continued on page 3 Carry Forward

Removed and replaced | Comment on page 4

30391288-5362 after flow and k

records. Referen

710031 - 400FH

in aircraft records 12 month Engine

and Pratt and Whit 76-10/117 - Perfoi

A-76-10-02-00A-90 Discrepancies

Removed and repla

AMM 12-A-34-12-0C

Removed and replace

Removed and replace

PC-12 AMM 12-A-32. in aircraft records.

Removed and replac referencing Pilatus PC

Removed and replace

Removed broken pass 35-20-03-00A-920A-A

Removed and replaced

Adjusted flap up limit sw Removed and replaced

12.A.32-30-00-00A-901A

00A-040A-A

901A-A

901A-A.

- Page 2

303-789-9599 Prone TUE PC-12 AMM 12AD

Pilatus PC-12 AMM 124

-12-20-06-00A-902A-A Platus PC-12 AMM 124

!-20-04-00A-902AA bolts and nuts examp

quired. ation referencing Plaus

on protective layer referen

2-A-34-21-00-00A-9034.1

viro Systems CMM 21-00-2 903A-A

12-A-56-11-02-00A-31344

Verified passenger seated

60. S/N 05304. Battery Eq.



12180 E. Control Tower Road Englewood, CO 80112

Aircraft Maintenance Record

303-799-9999 Phone 303-799-4539 FAX

Continued from Page 2

731015 - 400FH Fuel nozzle inspection and check. Removed Fuel flow divider P/N; 26130-2 and 13 fuel nozzle adapters P/N: 30391288-5362. ETT: 676.0 ETC: 512. Installed Fuel flow divider P/N: 3119856-01 and 13 fuel nozzle adapters P/N: 3119855-01 after flow and leak check performed by Dallas Airmotive, see 8130-3 dated 12 July, 2019. CRS# YRR4491L placed in aircraft records. Referencing Pratt & Whitney PT6A-67P, 3038336 chapter 73-11-05.

710031 - 400FH Borescope Inspection completed by Dallas Airmotive CRS# YRRR491L see log entry dated 12/JUL/2019 placed in aircraft records.

12 month Engine compressor and CT wheel wash and rinse referencing Pilatus PC-12 AMM section 12-A-71-00-00-00A-250A-A and Pratt and Whitney EMM 3038336 section 71-00-00.

76-10/117 - Performed 3000FH/12 Month Propeller feathering microswitch functional test referencing Pilatus PC-12 AMM 12-A-76-10-02-00A-903A-A. Discrepancies

Removed and replaced OAT temperature bulb P/N: MS28034-3 with new OAT temperature bulb P/N: MS28034-3. Reference PC-12 AMM 12-A-34-12-00-00A-040A-A, PC-12 WM 34-12-00, and PC-12 WM 77-40-10.

Removed and replaced drain fluid bottle power pack O-ring P/N 946.91.29.902 referencing Pilatus PC-12 AMM 12-A-29-00-00-00A-901A-A.

Removed and replaced shimmy dampener 532.20.12.215. S/N off: AM098, repaired S/N on: IL323 PTT: unknown referencing Pilatus PC-12 AMM 12-A-32-50-01-00A-920A-A. See form 8130-3 from Pilatus Business Aircraft CRS# ZP8R849Ydated 09 Jul 2019 placed in aircraft records.

Removed and replaced nose gear torque links bushings P/N 532.20.12.172 and 532.20.12.192, and pins P/N 532.20.12.159 referencing Pilatus PC-12 CMM section 32-20-05.

Removed and replaced steering collar swivel joint and steering collar bushings/hardware referencing PC-12 AMM 12-A-32-50-00-00A-040A-A.

Removed broken passenger oxygen mask new passenger oxygen mask P/N: 535.21.12.141 referencing Pilatus PC-12 AMM 12-A-35-20-03-00A-920A-A.

Removed and replaced left and right wing fuel cap O-rings P/N MS29513-232 Referencing Pilatus PC-12 AMM 12-A-28-00-00A-

Adjusted flap up limit switch referencing Pilatus PC-12 AMM 12-A-27-50-07-00A-903B-A.

Removed and replaced L/H MLG up stop bumper and spacer P/N 557.24.12.075 and 557.24.12.209 referencing Pilatus PC-12 AMM 12-A-32-30-00-00A-901A-A.

Removed and replaced Propeller beta ring carbon block P/N A3026 with new. Referencing Pilatus PC-12 AMM 12-A-61-20-02-00A-

Page 3 Continued on page 4



12180 E. Control Tower Road Englewood, CO 80112

## Aircraft Maintenance Record

Continued from Page 3

303-799-9999 Phone 303-799-4539 FAX

Installed "CWS" placard on pilot control wheel. Referencing Pilatus PC-12 AMM section 12-A-11-00-00-00A-901A-A Removed and replaced emergency exit door seal with new P/N 552.20.12.126 as required referencing Pilatus PC-12 AMM 12-A-52. 20-01-00A-920A-A.

Right outboard lower wing surface has dents. Pilatus Position: The reported dents along with the associated blend outs of the scratches have been assessed to be structurally and aerodynamically acceptable to leave as is for the time-limited period of 100 hours (Current Hours 15230.3).Performed dye penetrant inspection as per NTO TM-12-006512, dated 05/AUG/19, for 100 hour flight recommendation. Repair due at ACTT: 15330.3.

Cleaned and applied corrosion protection sealant to Gen #2 ground point referencing PC-12 AMM 12-A-24-30-00-00A-901A-A Cleaned and applied corrosion protection sealant to Battery #1/#2 ground point referencing PC-12 AMM 12-A-24-30-00-00A-901A-A

Removed worn engine cowling rubber seals and replaced with new referencing Pilatus PC-12 AMM 12-A-71-10-01-00A-920A-A Installed cargo door placard P/N: 511.34.12.290 referencing Pilatus PC-12 AMM 12-A-11-00-00-00A-901A-A

Installed "Max Freight Load" placards P/N 511.34.12.147 on the forward and aft cargo door frames. Referencing Pilatus PC-12 AMM 12-A-11-00-00-00A-901A-A.

Installed new Tire pressure placards on MLG P/N 511.23.12.021 as required referencing Pilatus PC-12 12-A-11-00-00-00A-901A-A Repaired lower cowling plenum as per Class 1 RM 11192 instruction referencing Pilatus PC-12 SRM 12-A-54-10-04-00A-664A-A Removed and replaced hardware for R/H flap center and outboard support arms with new. Installed shim 0,5 mm and shim 0,3 mm on center R/H flap support arm. No shim were required on the R/H outboard support arm. Referencing Pilatus SB 57-006.

Removed and replaced stick pusher circuit breaker collar P/N 944.87.12.004 as required.

Right aileron lower skin dented, installed Repaired R/H Aileron P/N 557.60.12.058, S/N 3451S Referencing Pilatus PC-12 AMM 12-A-57-60-01-00A-920A-A, Performed travel check 29.6 degrees up and 10.4 degrees down referencing Pilatus PC12 AMM 12-A-27-15-00-00A-903A-A. FAA FORM 8130-3 from CRS OMKR399L Dated 31 JUL 2019 Painting and static balance of control surface.

Removed and replaced both main tires referencing Parker/Cleveland CMM CM40-424. P/N on/off: 025-350-0. S/N's off: 6146S00232. 6145S00207. Installed Right tire SN: 8092S00354, Left SN: 8155S00297, see EASA Form 1 dated 17 April, 2018 in aircraft records. See EASA Form 1 dated 11 June, 2018 in aircraft records.

Removed standby attitude indicator 5040035922, S/N 504003592225215 routed to Duncan Aviation for repair. Installed standby attitude indicator 5040035922, S/N 504003592225215 referencing PC-12 AMM 12-A-34-23-20-00A-903A-A. Performed operational test referencing 12-A-34-23-21-00A-920A-A. See FAA form 8130-3 from Duncan Aviation CRS# JGVR194F under work order 6UNWA, dated 07/24/2019.

Page 4 Continued on page 5 AD research and co Complied with Pila Complied with Pila Installed shim 0.5 Referencing Pilatu complied with Pila complied with Pil See maintenance due 15830.3 hou

23-70/07 - Perfc 00357-65 and St The aircraft ide approved for re

Signed:

Model


Serial No. Registration

Removed volt

S/N: 175, refe The aircraft i approved for 188.

Signec

Page 1



**Bode Aviation Airframe** 1260 W Navajo ST Hanger 6, Farmington NM 87401 Performed 6 month inspection of Airborne Position Data Communicator, Cockpit Display and ICA Circuit 10/8/2019 N840AG A/C hrs 15257.5 breaker in accordance with supplement ICA 08013-1 Para. A & B. No discrepancies found. Approved for return to service. Batt Replaced 7/1/18 Terrell Grimes 3465915 A&P Total to Carry Forward

Serial No. Registration Page  De-fueled and sumped aircraft. Reference Pilatus PC-12 AMM 12-A-12-10-01-00A-902A-A. Removed right outboard wing deice boot P/N P27-7D5221-12, S/N NBD3670, and installed new rig 7D5221-24, S/N NEU6170. Function check good. Reference Pilatus SB 30-012, referencing the Pil 00A-920A-A, and Goodrich CMM 30-10-07.  Removed right aileron to facilitate skin replacement. Reinstalled referencing Pilatus PC-12 AMM 12-referencing Pilatus PC-12 AMM 12-A-20-20-01-00A-040A-A Table 2.  Removed the right wing lower outboard skin from rib 16 to 20. Installed a new right wing lower out 5572012544. Reference PC-12/45 SRM 12-A-51-70-05-00A-663A-A.  Refueled for leak check of right wing fuel tank. Leak check good. Reference Pilatus PC-12 AMM 12-Paint lower right wing skin performed by PDR Services, inspected paint. Reference Pilatus PC-12/45 Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 And aircraft and /or component identified above was repaired and inspected in accordance with current federal aviation.	F	Pho	02 Old Tower Forenix Arizona 8 Bair Station No.	5034				602-267-4070 Pho 602-267-4030 FAX
Registration Page  Page  Registration Page  Reference Pilatus PC-12 AMM 12-A-12-10-01-00A-902A-A.  Removed right outboard wing deice boot P/N P27-7D5221-12, S/N NBD3670, and installed new right 7D5221-24, S/N NEU6170. Function check good. Reference Pilatus SB 30-012, referencing the Pil 00A-920A-A, and Goodrich CMM 30-10-07.  Removed right aileron to facilitate skin replacement. Reinstalled referencing Pilatus PC-12 AMM 12-referencing Pilatus PC-12 AMM 12-A-20-20-01-00A-040A-A Table 2.  Removed the right wing lower outboard skin from rib 16 to 20. Installed a new right wing lower out 5572012544. Reference PC-12/45 SRM 12-A-51-70-05-00A-663A-A.  Refueled for leak check of right wing fuel tank. Leak check good. Reference Pilatus PC-12 AMM 12-Paint lower right wing skin performed by PDR Services, inspected paint. Reference Pilatus PC-12/45.	A:		C4 N/I -14		W	Work Order No.		02M-11712
<ul> <li>De-fueled and sumped aircraft. Reference Pilatus PC-12 AMM 12-A-12-10-01-00A-902A-A.</li> <li>Removed right outboard wing deice boot P/N P27-7D5221-12, S/N NBD3670, and installed new rig 7D5221-24, S/N NEU6170. Function check good. Reference Pilatus SB 30-012, referencing the Pil 00A-920A-A, and Goodrich CMM 30-10-07.</li> <li>Removed right aileron to facilitate skin replacement. Reinstalled referencing Pilatus PC-12 AMM 12-referencing Pilatus PC-12 AMM 12-A-20-20-01-00A-040A-A Table 2.</li> <li>Removed the right wing lower outboard skin from rib 16 to 20. Installed a new right wing lower out 5572012544. Reference PC-12/45 SRM 12-A-51-70-05-00A-663A-A.</li> <li>Refueled for leak check of right wing fuel tank. Leak check good. Reference Pilatus PC-12 AMM 12-Paint lower right wing skin performed by PDR Services, inspected paint. Reference Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Reference Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Reference Pilatus PC-12/45 A Reference Pilatus PC-12/45 A Reference Pilatus PC-12/45 A Reference PILATUS PROPERTOR PROPERTOR PROPE</li></ul>	Aircraft Maintenance		Ho	our Meter		5322.8		
<ul> <li>De-fueled and sumped aircraft. Reference Pilatus PC-12 AMM 12-A-12-10-01-00A-902A-A.</li> <li>Removed right outboard wing deice boot P/N P27-7D5221-12, S/N NBD3670, and installed new rig 7D5221-24, S/N NEU6170. Function check good. Reference Pilatus SB 30-012, referencing the Pil 00A-920A-A, and Goodrich CMM 30-10-07.</li> <li>Removed right aileron to facilitate skin replacement. Reinstalled referencing Pilatus PC-12 AMM 12-referencing Pilatus PC-12 AMM 12-A-20-20-01-00A-040A-A Table 2.</li> <li>Removed the right wing lower outboard skin from rib 16 to 20. Installed a new right wing lower out 5572012544. Reference PC-12/45 SRM 12-A-51-70-05-00A-663A-A.</li> <li>Refueled for leak check of right wing fuel tank. Leak check good. Reference Pilatus PC-12 AMM 12-Paint lower right wing skin performed by PDR Services, inspected paint. Reference Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 A</li> </ul>	Record	Ai	craft Total Time	)	15,322.8			
<ul> <li>Removed right outboard wing deice boot P/N P27-7D5221-12, S/N NBD3670, and installed new rig 7D5221-24, S/N NEU6170. Function check good. Reference Pilatus SB 30-012, referencing the Pil 00A-920A-A, and Goodrich CMM 30-10-07.</li> <li>Removed right aileron to facilitate skin replacement. Reinstalled referencing Pilatus PC-12 AMM 12 referencing Pilatus PC-12 AMM 12-A-20-20-01-00A-040A-A Table 2.</li> <li>Removed the right wing lower outboard skin from rib 16 to 20. Installed a new right wing lower out 5572012544. Reference PC-12/45 SRM 12-A-51-70-05-00A-663A-A.</li> <li>Refueled for leak check of right wing fuel tank. Leak check good. Reference Pilatus PC-12 AMM 12-Paint lower right wing skin performed by PDR Services, inspected paint. Reference Pilatus PC-12/4 Replaced right aileron inboard seal with new P/N 557.60.12.227, referencing the Pilatus PC-12/45 Ame aircraft and /or component identified above was repaired and inspected in accordance with current federal aviation.</li> </ul>					La	ndings		9472
Signed: Kevin Red FAA Repair Station No. EKGR571D	DDD.	/0-0: ak ch	5-00A-663A-A neck good. Ref	led a new righ a. erence Pilatus	PC-12 A1	MM 12-A-12-10	-01-00A	A-902A-A



Cutter Aviation Phoenix 2802 E Old Tower Road Phoenix, Arizona 85034 FAA Repair Station No, EKGR571D

Phone: 602-273-1237

Fax: 602-267-7806

Registration	N840AG	
Model	PC-12/45	
Serial No	296	
Aircraft TT	15,323.00	

## Airframe Log Book Entry

Work Order	02M-11795	
Tach	N/A	
Hour meter	5,323.00	
Landings	9473	1

Swapped LH and RH inbd flap actuators P/N 978.73.20.309, S/N now installed at LH inbd 1730 and RH inbd 0733. Removed LH flap assy P/N 557.50.12.003, S/N 251, and installed new LH flap assy P/N 557.50.12.003, S/N 1531S. LH flap assy painted by PDR services, inspected paint and no defects noted. Performed flap actuator and flap zero set. Performed flap functional test, function check good. Install new inner mark placard P/N 511.24.12.046, and outer mark placard P/N 511.24.12.047, Placard strip P/N 511.24.12.024, and 3 Do Not Push placards P/N 511.21.12.038-BLACK, referencing the Pilatus PC-12/45 AMM 12-A-57-50-01-00A-920A-A, 12-A-27-50-03-00A-920A-A, 12-A-27-50-03-00A-903A-A, 12-A-27-50-00-00A-903A-A, and 12-A-11-20-01-00A-901A-A

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details are on file at this repair station.

Signature

Kevin Reedy

Performed the adjustment test or t Dated 5-17-2019, No defects noted

Removed intermittent SA-360D Servo actuator P/N 501-1684-04 S/N 1185. Installed "New" Stick Pusher Servo P/N 501-1684-04 S/N 81313. Performed the Functional test of the Stick pusher system IAW Pilatus AMM 02049 dated 5/17/2019 chapter 12-A-22-20-00-00A-903A-A.

The aircraft and for component identified above was repaired and inspected in accordance with current federal aviation regulations and is approved for return to service with respect to the work performed. Pertinent details are on file at this repair station.

Kevin Reedy

Date: Jan 1

FAA Repair Station No. EKGR571D



2802 Old Tower Road Phoenix Arizona 85034 FAA Repair Station No. EKGR571D

602-267-4070 Phone 602-267-4030 FAX

Model PC-12/45 Serial No. 296 Registration **N840AG** Page 1 of 1

**Aircraft Maintenance** Record

Work Order No. 02M-11712 Hour Meter 5322.8 Aircraft Total Time 15,322.8 Landings 9472

### Special Inspection Items

- Removed Concorde batteries P/N RG-380E/44 S/N 40904128 and P/N RG-380E/44 S/N 40906050 for capacity check referencing Concorde RG Series Main Aircraft Battery CMM 5-0171. S/N 40906050 passed at 100% and reinstalled in the #1 position. S/N 40904128 passed at 90% and reinstalled in the #2 position. Installed referencing Pilatus PC-12 AMM 12-A-24-30-07-00A-920A-A.
- Complied with 6-month application of AgeMaster to airfoil deicers, referencing the Good rich CMM 30-10-07.
- Performed engine oil sample and sent out for analysis.

#### Discrepancies

- Began functional test on propeller de-ice and found amber "DEICE" light would stay on and green "PROP DEICE" light would flash with OAT simulators set to -21G and aircraft in air mode. Inspected wiring harness to OAT connectors and found broken wire on airframe side of connector to L/H OAT. Repaired broken wire and performed functional test. Functional test good. No further discrepancies noted. Work
- Reset the key backlighting from photocell to 28 vdc. All work performed IAW Garmin GTX 3XX manual 190-00734-10 Rev. 13 dated
- Performed the adjustment/ test of the Altitude Preselector and KEA altimeter, IAW Pilatus AMM 12-A34-14-00-00A-903A-A Rev. 29 Dated 5-17-2019. No defects noted.
- Removed intermittent SA-360D Servo actuator P/N 501-1684-04 S/N 1185. Installed "New" Stick Pusher Servo P/N 501-1684-04 S/N 81313. Performed the Functional test of the Stick pusher system IAW Pilatus AMM 02049 dated 5/17/2019 chapter 12-A-22-20-00-00A-903A-A.

The aircraft and /or component identified above was repaired and inspected in accordance with current federal aviation regulations and is approved for return to service with respect to the work performed. Pertinent details are on file at this repair station.

Kevin Reedy

Date: Jan 15, 2020

FAA Repair Station No. EKGR571D

12180 E Control Tower Rd Englewood, C0 80112  303-799-9999 P 303-7	none	THE RESERVE OF THE PARTY OF THE	12180 E. Control Tower Road	150 G Hebbs: 150 G 303-799-4	539 FAX
Model PilATUS PC-12/45 296 N840AG Registration Page 1 of 1 Scheduled Inspections Compiled with 6 month inspection of the Airborne Position Data Communicator (237001), cockpit display (2370 and circuit breaker (237011), referencing supplement ICA 08013-1, Para A&B. No defects noted at this time.  Removed pitch trim actuator S/N: 1016 and installed overhauled actuator S/N: 2180 referencing Pilatus PC-12 AMM 127-40-01-00A-920A-A. Ops checks good. See EASA Form 1 dated 11 Dec. 2019 in aircraft record.  AAA, and AAA, and Cleaned LH AHRS indicator light socket, installed 2 new indicator bulbs, P/N 972-73.19.106, in LH AHRS indicator referencing Pilatus PC-12 AMM 12-A-57-00-00-00A-901A-A. Cleaned LH AHRS indicator light socket, installed 2 new indicator bulbs, P/N 972-73.19.106, in LH AHRS indicator referencing Pilatus PC-12 AMM 12-A-31-11-01-00A-920A-A. Ops check good at this time.  The work performed on the aircraft identified above has been performed satisfactorly and inspected in accord. with current projectures and recofunity and inspected in the Manufactures Maintenance Manual. Pertine details are on file under WO14MM-308.  Signed:  Signed:  Signed:  Gina lacolino AP 3026433  Date: 05 MAR 2020	Fax: 602-273-1237	Leading the Business of Aviation	Englewood, CO 8011	Rd	303-799-9999 Phone 303-799-4539 FAX
Complied with 6 month inspection of the Airborne Position Data Communicator (23701), cockpit display (2370 and circuit breaker (237011), referencing supplement ICA 08013-1, Para A&B. No defects noted at this time.  Airframe Maintenance Item Removed pitch trim actuator S/N: 1016 and installed overhauled actuator S/N: 2180 referencing Pilatus PC-12 AMM 12-4-01-00A-920A-A. Ops checks good. See EASA Form 1 dated 11 Dec. 2019 in aircraft records.  Installed trim strip P/N 557.50.12.172 on L/H flap assy. Referencing Pilatus PC-12 AMM 12-A-57-00-00-00A-901A-A.  Cleaned LH AHRS indicator light socket, installed 2 new indicator bulbs, P/N 972.73.19.106, in LH AHRS indicator referencing Pilatus PC-12 AMM 12-A-31-11-01-00A-920A-A. Ops check good at this time.  The work performed on the aircraft identified above has been performed satisfactorily and inspected in according to the month of the Airborn Position Position of the Airborn Position of the Airborn Position of the Airborn Position Position of the Airborn Position Position Position of the Airborn Position of the Airborn Position Position Position Po	02M-11795 N/A	Serial No. 296 Registration N840AG Page 1 of 1	Aircraft Mainte Record	nance Hour Meter	5328.30
ulations and is approved for return	3. Removed assy painted inctional test. Placard AMM A-A, and ral Aviation Regulations of station.  Date 2/28/2020	Complied with 6 mont and circuit breaker (23 Airframe Maintenance Removed pitch trim act 27-40-01-00A-920A-A. Installed trim strip P/N 5 Cleaned LH AHRS indice referencing Pilatus PC-The work performed owith current procedure details are on file und	th inspection of the Airborne Position Data 37011), referencing supplement ICA 08013-e Item tuator S/N: 1016 and installed overhauled ac Ops checks good. See EASA Form 1 dated 557.50.12.172 on L/H flap assy. Referencing icator light socket, installed 2 new indicator be 12 AMM 12-A-31-11-01-00A-920A-A. Ops con the aircraft identified above has been pres and recommended practices specified iter WO 14MM-308.	1, Para A&B. No defects noted at the tuator S/N; 2180 referencing Pilatus 11 Dec. 2019 in aircraft records. Pilatus PC-12 AMM 12-A-57-00-00 rulbs, P/N 972.73.19.106, in LH AHF heck good at this time. Derformed satisfactorily and insperint the Manufactures Maintenance I	nis time. SPC-12 AMM 12-A- D-00A-901A-A. RS indicator Sected in accordance Manual. Pertinent
Date: _Jan 15, 2020	ulations and is approved for return				
	Date:Jan 15, 2020				

		Aircra	ft Time	Recorder		
Date	Thi	is Date	Total	Reading	Mainter	nance
	Brough					
	Torwar					
	DUNCAN -		NO 40 A G	Deter	lasha 9, 2020	
		eg. #:	N840AG	Date:	July 8, 2020 PC-12/45	
		lake	Pilatus	Model	PC-17/45	A i
						, morall olla.
nspection #1 Alt End	24 month system(s) as required coder PN:	ustomer h 91.411/91 tests and ii I by 14 CFR 066-03062	Cutter Aviation. 1.413 certification. 1.413 required 1.413 have 1.413 have 1.413 have	n TT: The altimeter sys	15374.40 stem(s). static system(s 91.411 and the ATC tra and found to comply wit	Landings: 9497 s), and automatic pressure
nspection #1 Alt End #2 Alt End #1 Transp #2 Transp The above 85,000 fee	d 24 month system(s) as required coder PN: coder PN: conder PN conder PN e listed equet on 7/8/	ustomer h 91.411/91 tests and it l by 14 CFR 066-03062 5035P-P.5 : 011-0330 : 066-0114 uipment, alt 2020.	Cutter Aviation 1.413 certification. Inspections required Part 91.413 have 2-0010 SN: 3947 0 SN: 29639 02-00 SN: 3EG0206 11-0201 SN: 30303 titude reporting sys	n TT: The altimeter system of the system of	15374.40 stem(s). static system(s) 91.411 and the ATC trained found to comply with	Landings: 9497 s), and automatic pressure nsponder system(s) tests th 14 CFR 43, Appendices  ft static system(s) were
nspection #1 Alt End #2 Alt End #1 Transp #2 Transp The above 85,000 fee	24 month system(s) is required coder PN: coder PN: coder PN conder PN conder PN e listed equet on 7/8/2 e described	ustomer h 91.411/91 tests and in l by 14 CFR 066-03062 5035P-P.5 : 011-0330 : 066-0114 uipment, ali 2020. d repair or i	Cutter Aviation 1.413 certification. Inspections required Part 91.413 have 2-0010 SN: 3947 0 SN: 29639 02-00 SN: 3EG0206 11-0201 SN: 30303 titude reporting sys	n TT: The altimeter system of the system of	15374.40 stem(s). static system(s) 91.411 and the ATC tra and found to comply with espondence, and aircraft to service. A detailed re	Landings: 9497 s), and automatic pressure nsponder system(s) tests th 14 CFR 43, Appendices  ft static system(s) were
nspection #1 Alt End #2 Alt End #1 Transp #2 Transp The above The above	d 24 month system(s) as required coder PN: coder PN: conder PN conder PN e listed equet on 7/8/	ustomer h 91.411/91 tests and in l by 14 CFR 066-03062 5035P-P.5 : 011-0330 : 066-0114 uipment, all 2020. d repair or in	Cutter Aviation 1.413 certification. Inspections required 2-0010 SN: 3947 0 SN: 29639 02-00 SN: 3EG0200 41-0201 SN: 30303 titude reporting systemaintenance is approximately	n TT: The altimeter system of the system of	atem(s). static system(s) 91.411 and the ATC trained found to comply with espondence, and aircraft to service. A detailed response	Landings: 9497 s), and automatic pressure nsponder system(s) tests th 14 CFR 43, Appendices  ft static system(s) were to
nspection #1 Alt End #2 Alt End #1 Transp #2 Transp The above The above	24 month system(s) is required coder PN: coder PN: coder PN conder PN conder PN e listed equet on 7/8/2 e described	ustomer h 91.411/91 tests and in l by 14 CFR 066-03062 5035P-P.5 : 011-0330 : 066-0114 uipment, all 2020. d repair or in	Cutter Aviation 1.413 certification. Inspections required 2-0010 SN: 3947 0 SN: 29639 02-00 SN: 3EG0200 41-0201 SN: 30303 titude reporting systemaintenance is approximately	n TT: The altimeter system of the system of	15374.40 stem(s). static system(s) 91.411 and the ATC tra and found to comply with espondence, and aircraft to service. A detailed re	Landings: 9497 s), and automatic pressure nsponder system(s) tests th 14 CFR 43, Appendices  ft static system(s) were to

SEII I		Englewood, CO 80112	VCCS Hobbs: 150.6	300,100,100
Leading the Busine	PILATUS PC-12/45	15-11-11-11-11-11-11-11-11-11-11-11-11-1	Work Order No.	14MN-355
Model	PILATOST G 12.10	Aircraft Maintenance	Hour Meter	5374.4
Serial No.	296		Aircraft Total Time	15374.4
penistration	N840AG	Record		9497
Registration Page  I certify that the 600 FH/12 Mo 20-00A-018A-A Airworthiness I Performed the 00-00/45A-B - A -20-40-00-00A 05-40-01-06A A 21-30/46 - Com A-21-30-01-00A 21-30/47 - Com A-21-30/49 - Com 21-30/49 - Com 21-30/49 - Com 21-30/43 - Com 21-30/43 - Com 21-30/43 - Com 21-30/43 - Com 21-30/40 - Com 21-30/40 - Com 21-30/340 -	is aircraft has been inspired, and 1200FH/12 Mainspection guide and Foirective compliance cheefollowing Scheduled Complied with 12 Month-901A-A. Complied with 24 month/3 A-903A-A. Inplied with 3000FH/24 A-250A-A. Inplied with 60 Month Complied with 60 Month Complied with 60 Month Complied with 12 Month Complied with 12 Month Complied with 12 Month Complied with 600 Hour/MM Section 12-A-24-30.00FH/6 MO. 600FH/6 MO. 600FH/6 Month Lead MC-12-A-24-30-07-00A-16 MO. Folied with 12 Month Ed. 3 dated: 18 AUG 2020.00	ected in accordance with Pilatus AMM (Ionths Annual Inspection in accordance AR 43 Appendix D, and was determined ecked through Revision 2020-17.  Inspection and Maintenance: Aircraft External Corrosion and Corros  FH/24 Month Inspection per checklis  000 hour cabin positive pressure relimentation outflow valve at the cabin altitude switch functional test, recabin differential pressure switch functional test, recabin diffe	ion Protection Inspection, referencing Pilatus And Institute and safety valve check and referencing Pilatus Allow and the safety Test P/N RG-380I A-30-71. Main battery and safety tests of the safety	- 300 FH, 300 FH/12 Months, tus PC-12/45 AMM 12-A-05-20-condition.  ion, referencing Pilatus AMM 12-AMM 12-A-05-40-01-05A-000B-st, referencing Pilatus AMM 12-ck, referencing Pilatus AMM 12-ck, referencing Pilatus AMM 12-A-21-30-07-00A-903A-A. Ing Pilatus AMM 12-A-21-30-08-encing Pilatus AMM 12-A-21-40-Systems CMM 21-00-23.  MM 12-A-22-10-00-00A-313A-A. E/44, S/N 40906050 referencing tests good at 90% capacity. Next 24128 referencing Pilatus PC-12 good at 91% capacity. Next capancan Aviation CRS# JG7D076J, 81486, referencing Pilatus AMM
Pilatus AMM	Ch. 25-63-11. Battery	Exp Date 02/2023.	atus DC 12 ANANA 12-4	1-26-20-00-00A-040A-A.
20/24 - Comp	lied with 12 Month Fi	Exp Date 02/2023.  re extinguisher check referencing Pil	atus PC-12 Alviivi 12-7	Continued on page 2
				Continued on page 2



AD and Service Bulletins:

Discrepancies

12180 E. Control Tower Road Englewood, CO 80112

**Aircraft Maintenance** Record

303-799-9999 Phone

-Replaced 4ea bulbs PN 1044-06 in the pilot and copilot CB panels, referencing Pilatus AMM Ch. 33-10-01.

All work performed referencing Pilatus AMM Ch. 28-10-00. Leak check good at this time.

-Installed Pilot seat pan web repair kit SPC41990-901, referencing Pilatus Doc. SPC41990-901

Pilatus PC12 AMM sections 12-A-52-10-01-00A-920A-A and 12-A-52-30-01-00A-920A-A.

-Installed new bush R/H side NLG towing attachment P/N: 532.20.12.191, referencing Pilatus CMM section 32-20-05.

-Installed new bonding wire for NLG P/N 523.60.09.077, referencing Pilatus AMM 12-A-32-20-01-00A-920A-A. -Replaced oil cooler door strut rod P/N 571.10.12.353, referencing Pilatus AMM 12-A-79-20-02-00A-920A-A.

-Replaced NLG wheel bearings and races with new P/N 13830 and P/N 13889 Referencing CMM CM40-423.

-Replaced Brake drive keys on L/H and R/H MLG wheel assemblies P/N 959.56.01.520, referencing CMM CM40-424.

or indications were found during the ultrasonic testing per required after this initial inspection as long as no indications were noted. Three re-occurring inspection have been performed on this engine frame

Discrepancies
-Replaced all 8 window shades with new window shade repair kits P/N: 950.10.00.091, referencing Pilatus AMM 12-A-25-22-03-004

-Removed inop bulbs from multiple cockpit push buttons annunciators and installed new lamps PN 6839, referencing Pilatus AMM Ch

-Removed over voltage protection device P/N 988.21.16.104, S/N EMCA 006350 from external power receptacle. Installed new over

-Removed and replaced Crew/Passenger door stair shock strut. P/N: 552.10.12.534. Replaced loose rivets for door bracket

-Left bottom wing skin seam is leaking fuel by the main landing gear door. Found a leak on the main spar rivet row where the sealant

was cut. Cleaned area and installed new sealant. Installed all panels removed with new O-rings PN 557.20.12.190 & 557.32.09.035

-Removed deteriorated sealant, from the RH and LH cockpit windows, and replaced with new sealant, referencing Pilatus AMM 12-A-

-Installed numerous new cargo and passenger door nylon button and sleeves P/N 944.48.70.003 and 944.48.70.105, referencing

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is

approved for return to service with respect to the work performed. Pertinent details are on file under Work Order 14MN-355.

Godfrey Higgs III AP/IA 3391984

Continued from Page 3

Data.

24 AUG 2020

303-799-4539 FAX

27.00/71 - Complied with 4800FH/60 Pidus AMM 12-A-21-UU-UU-UUA-3131 27-40/1 - Complied with 3000FH/12 2740/1 - COMPINED WILL SUUUFHI ANN 12-A-27-40-00-00A-903A-A.

27-51-00 Complied with the 1200

1 AD-UU-UU-Performed 6 Month ap

A 32-10/81 - Performed the 12 Mc

32-10/436 - Complied with th

referencing Pilatus PC-12 AMN

35-10/7 - Complied with 60 1 C15020219 to include overha

(Large bottle). Hydrostatically

in aircraft records. Bottle MF

57-00199 - Complied with 1

12-A-57-00-00-00A-313A-A

Complied with 12 month

00-00A-250A-A and Pratt

76-10/117 - Complied W

12-A-76-10-02-00A-903A

237001 - Complied with 237003 - Complied with

237007 - Performed vi

00357-65 and Suppl 237011 - ICA - Che Complied with the

B159206 and a n€

Aerospace CRS#

and Goodrich CMM 30-10-31. 32-10/80 - Complied with 12 Mo

A32-10-00-00A-313A-A

00-00B-720A-A.

AD 1974-08-09 R3 - Inspect lavatory waste receptacles. Is not applicable.

Pilatus Mandatory SB 71-009 R02 - Engine Mounting Frame 12 month Ultrasonic Inspection of Swaged Tube Ends. Upon loglogy

Pilatus Mandatory SB 71-009 R02 - Engine Mounting Frame 12 month Ultrasonic Inspection of Swaged Tube Ends. Upon loglogy

Pilatus Mandatory SB 71-009 R02 - Engine Mounting Frame 12 month Ultrasonic Inspection of Swaged Tube Ends. Upon loglogy Pilatus Mandatory SB 71-009 R02 - Engine Mounting Frame 12 month. Services at ACTT: 14477.8 Hrs. Upon initial compliance no defect research found this bulletin to have been initially complied with on 08/12/2016 at ACTT: 14477.8 Hrs. Upon initial compliance no defect required the compliance of the co

ANN 12-7-2 Complied with 600FH/1

### 12180 E. Control Tower Road Englewood, CO 80112

All Clait manicon Record

סווטוו בבבב-מם-ווטווס

303-799-4539 FAX

Continued from Page 1

27-00/71 - Complied with 4800FH/60 Month Flight control cable, auto pilot and pusher cable inspection and check, referencing

Pilatus AMM 12-A-27-00-00-00A-313A-A pilatus AMM 12-7-2, with 3000FH/12 Month Horizontal stabilizer trim runaway aural warning functional test, referencing Pilatus

AMM 12-A-27-40-00-00A-903A-A. AMM 12-A-21-30 Somplied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check, referencing Pilatus AMM 12-A-27-50/437 - Complied with 600FH/12 Month Inboard flap drive arm in-situ inspection and check in the complex of the

27-51-00-007 with the 1200FH/48 Month Fuel low level warning system functional test, referencing Pilatus AMM 12-A-28-

30-10/79 - Performed 6 Month application of AgeMaster to surface deicers, referencing Pilatus AMM 12-A-05-10-20-00A-281A-A and Goodrich CMM 30-10-31. and Good Complied with 12 Month Main and Nose wheel bearing lubrication, referencing Pilatus AMM 12-A-12-20-06-00A-902A-

A. 32-10/81 - Performed the 12 Month Main landing gear hinge pin and bushes inspection and check, referencing Pilatus AMM 12-

32-10/436 - Complied with the 12 Month MLG Shock absorber top and bottom attachment bolts and nuts examination, A-32-10-00-00A-313A-A.

referencing Pilatus PC-12 AMM 12-A-32-10-00-00A-310A-A. 35-10/7 - Complied with 60 Month Oxygen bottle hydrostatic test. Removed and reinstalled oxygen bottle P/N 895-06077, S/N C15020219 to include overhauled regulator P/N: 803213-03, S/N: C14110170, referencing Pilatus AMM 12-A-35-10-01-00A-920B-A

(Large bottle). Hydrostatically tested by HRD Aero Systems, Inc. CRS: YN2R325L See FAA form 8130-3, dated 15/JUL/2020 placed in aircraft records. Bottle MFG Date 12/2014, Expires 12/2029. 57-00/99 - Complied with 10 year/11,000 hour left and right wing/fuselage attach fitting inspection, referencing Pilatus AMM 12-A-57-00-00-00A-313A-A, 12-A-57-00-00A-520A-A, 12-A-57-00-00A-720A-A, 12-A-57-00-00B-520A-A, and 12-A-57-00-

Complied with 12 month Engine compressor and CT wheel wash and rinse referencing Pilatus PC-12 AMM section 12-A-71-00-

00-00A-250A-A and Pratt and Whitney EMM 3038336 section 71-00-00. 76-10/117 - Complied with 3000FH/12 Month Propeller feathering microswitch functional test referencing Pilatus PC-12 AMM \_\_\_\_

237001 - Complied with ICA for Airborne position data communicator, referencing supplement ICA 08013-1. No defects noted. 237003 - Complied with ICA of Cockpit display pane, referencing, supplement ICA 08013-1. No defects noted.

237007 - Performed visual 12 month inspection GPS/Iridium combination antenna ICA document number 190-00356-65, 190-

00357-65 and Supplement ICA08013-1 for GPS installation and antennas as required. 237011 - ICA - Check circuit breaker, referencing supplement ICA 08013-1. No defects noted.

3159206 and a new mask PN MC10-06-125 SN 82785 referencing Pilatus AMM CH. 35-00-00. Mask SN B159206 was overhauled by Semco =

Complied with the Zodiac Aerospace Crew Masks 6 year overhaul. Installed and function tested overhauled mask PN MC10-06-125 SN

lerospace CRS# 5CIR425B see FAA Form 8130-3 dated: 05/AUG/2020 for details. Continued on page 3 age 2

12180 E. Control Tower Road 303-799-9999 Phone =PILATUS= Englewood, CO 80112 303-799-4539 FAX Work Order No. 14MN-308 PILATUS PC-12/45 Aircraft Maintenance Model Hour Meter 5328.30 296 Serial No. Aircraft Total Time Record 15328.30 **N840AG** Registration 1 of 1 Page Scheduled Inspections Scheduled inspections

Scheduled inspections

Complied with 6 month inspection of the Airborne Position Data Communicator (237001), cockpit display (237003). and circuit breaker (237011), referencing supplement ICA 08013-1, Para A&B. No defects noted at this time. 24-30/69 - Complied with Lead acid battery capacity test for main battery RG-380E/44, S/N 40906050, referencing Pilatus AMM 12-A-24-30-07-00A-920A-A and Concorde CMM 24-30-71. Main battery tests good at 100% capacity. Next capacity test due 15928.3FH/07/21/2021. 24-30/69 - Complied with Lead acid battery #2 capacity test P/N RG-380E/44, S/N 40904128, referencing Pilatus AMM 12-A-24-30-07-00A-920A-A and Concorde CMM 24-30-71. Main battery tests good at 100% capacity. Next capacity test due 15928.3FH/07/21/2021. 30-10/79 - Performed 6 Month application of AgeMaster to surface deicers referencing Pilatus AMM 12-A-05-10-20-00A-281A-A and Goodrich CMM 30-10-31. Discrepancies Addressed: Removed Inboard upper wing boot pressure switch P/N: 973.81.14.312 and installed new pressure switch P/N: 973.81.14.312, referencing PC-12 AMM 12-A-30-10-04-00A-920A-A. Removed TB204 and installed new terminal block P/N: 971.42.31.706, referencing PC-12 WDM 971.42.31.706. Airworthiness Directives or Service Bulletins: Researched AD 2020-21-23 Pilatus Aircraft Ltd. Found AD to not be applicable to this aircraft due to aircraft MSN 296 and that the horizontal stabilizer rear attachment bolts P/N 555.10.12.139 were not replaced between July 24, 2018 and the issue date of SB 55-004 Mar 29/19. No further action is required at this time. Researched AD 2020-22-05 Pilatus Aircraft Ltd. Found AD to not be applicable to this aircraft due to aircraft MSN 296. No further action is required at this time. Complied with Pilatus Optional SB 30-014, Ref 375, dated Feb 26/18, Ice and Rain Protection - Airfoil De-Ice System -Introduction of a Wiring Modification to Support Replacement of a New Airfoil De-Ice System Timer. Referencing Para. 3 Accomplishment instructions, Removed Timer P/N: 9598901014, S/N: UO217, BOD: 20 DEC 99 TSN: 15443.0, AFL: 9544. Installed new Timer P/N: 959.89.01.043, S/N: UA115, using kit P/N: 5000.50.12.363. The work performed on the aircraft identified above has been performed satisfactorily and inspected in accordance with current procedures and recommended practices specified in the Manufactures Maintenance Manual. Pertinent details are on file under WO 14W-473.


For Cutter Aviation FAA CRS# CUTR877D

Gina lacolino

Date:

22 JAN 2021

Signed:



# **Bode Aviation**

1260 W Navajo ST Hanger 6, Farmington NM 87401 **Airframe** 3/12/2021 N840AG A/C hrs 15482.6

3/12/2021 N840AG A/C hrs 15482.6

					-
				7	
		SEL			
	1/01				
			-		

> CUIL	<b>7&gt;</b>	12180 E. Control Tower Road Englewood, CO 80112		<b>EPILATUSE</b>
PILATUS PC-12/45			Hobbs Meter	5662.7
Model	296	Airframe Maintenance	Aircraft Total Time	15662.7
Serial No.	N840AG	Record	Landings	9679
Registration Work Order No.  14M-1015  AD / SB: Blweekly Ads checked thru 2023-24  AD / SB: Blweekly Ads checked thru 2023-24			vccs	167.9
Complied with Pilatus Complied with Pilatus Complied with Pilatus Complied with Due Pil Complied with Pilatus windshields installed. Inspections Complied N	AD 2023-12-17, Cracks in the Love AD 2023-09-12, Insufficient group AD 2023-10-02, Radio altimeter a latus AD 2021-24-01, Detect and a SB 30-017, Ice and rain protect with:	que limiter improvements IAW Pilatus PC-1 wer main Spar Connection of the Horizonta and of the VCCS compressor / condenser, N, anomalies that undetected by the automatic address any looseness or damage to the strain windshield de-ice system modification.	I Stab, revised ALS para (g) 'A due to MS/N. on or pilot, N/A by categorake, N/A due to equipment of the temperature sense tion checklists IAW Pilatus	(1). NFA required.  y. t not installed. or wiring. N/A due to P/N and  PC-12 AMM 12-A-05-20-00-00/
A. I certify that this airc 10-00/45 - Complied with 1-50/433 - Complied with 4-30/69 - Complied with 100A-A and CMM. Batter 1-30/69 - Complied with 10A-A and CMM. Batter	th 3 month corrosion prevention vith 12 month vapor cycle compro th 600 HR/6 month #1 lead acid b ry 95%, next check due in 6 month th 600 HR/6 month #2 lead acid bo ry 92%, next due in 6 months.	wash IAW Pilatus PC-12 AMM 12-A-12-20- essor condenser module clean IAW Pilatus pattery capacitance check P/N RG-380E/44 s ths. attery capacitance check P/N RG-380E/44 s	01-00A-902A-A. PC-12 CMM 21-00-23. S/N 70022096 IAW Pilatus S/N 41277915 IAW Pilatus	PC-12 AMM 12-A-24-30-07-00
A. I certify that this airc 00-00/45 - Complied with 21-50/433 — Complied with 24-30/69 - Complied with 20A-A and CMM. Batter 4-30/69 - Complied with 20A-A and CMM. Batter	th 3 month corrosion prevention vith 12 month vapor cycle compro th 600 HR/6 month #1 lead acid b ry 95%, next check due in 6 month th 600 HR/6 month #2 lead acid bo ry 92%, next due in 6 months.	wash IAW Pilatus PC-12 AMM 12-A-12-20- essor condenser module clean IAW Pilatus pattery capacitance check P/N RG-380E/44 s ths.	01-00A-902A-A. PC-12 CMM 21-00-23. S/N 70022096 IAW Pilatus S/N 41277915 IAW Pilatus	PC-12 AMM 12-A-24-30-07-00/
A. I certify that this airc 00-00/45 - Complied with 21-50/433 - Complied with 4-30/69 - Complied with 20A-A and CMM. Batter 4-30/69 - Complied with 20A-A and CMM. Batter	th 3 month corrosion prevention with 12 month vapor cycle compro th 600 HR/6 month #1 lead acid b ry 95%, next check due in 6 month th 600 HR/6 month #2 lead acid ba ry 92%, next due in 6 months. th 12 months emergency power so	wash IAW Pilatus PC-12 AMM 12-A-12-20- essor condenser module clean IAW Pilatus pattery capacitance check P/N RG-380E/44 s ths. attery capacitance check P/N RG-380E/44 s upply remove and capacitance check P/N 5	01-00A-902A-A. PC-12 CMM 21-00-23. S/N 70022096 IAW Pilatus S/N 41277915 IAW Pilatus 01-1712-02 S/N 81486.  ed Next Page Date:	PC-12 AMM 12-A-24-30-07-00

### AIRCRAFT LOG

>CUTTER	<b>&gt;</b>	12180 E. Control Tower Road Englewood, CO 80112		<b>EPILATUS</b>
Model	PILATUS PC-12/45		Hobbs Meter	5662.7
Serial No.	296	Airframe Maintenance	Aircraft Total Time	15662.7
Registration	N840AG	Record	Landings	9679
Work Order No	14M-1015	acement due 2/2023. Removed ACR 406 old	vccs	167.9
26-20/24 - Complied 27-40/1 - Complied 00A-903A-A. 27-50/30 - Complied flap actuator P/N 9 S/N 0146 IAW Pilat 27-50/76 - Complied 27-50/437 - Complied 32-10/436 - Complied 32-10/436 - Complied 32-10/436 - Complied 34-11/82 - Complied 34-11/83 - Complied 35-11/83 - Complied 36-11/83 - Complied 37-11/83 - Complied 38-11/83 - Complied 39-11/83 - C	ed with 12 month ELT inspection of with 12 months fire extinguished with 3000 FH or 12 months horized with 5,000FH/7,000 Landing flat 78.73.20.309 S/N 0104, removed us AMM 12-A-27-50-03-00A-920A with 2,400 FH/3,200 LDG/24 miled with 600 FH or 12 months inbody with 12 month main landing gelied with 1200FH/12 month main landing gelied with 24 months pitot and states R Part 43, Appendix D, E and F IAVed with 24 Months Altimeter, Chependix E and F. #1 Encoding Altimeted with 24 Months Transponder of Williams AMM 12-A-34-54-01-00 and with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are set of the second with 6 Months Airfoil desicers are second with 6 Months Airfoil desic	p actuator overhaul. Removed L/H outbd fl R/H inbd flap actuator P/N 978.73.20.309 in A-A. Performed flap adjustment and function flap actuators backlash check IAW Pitcoard flap drive arms in-situ inspection/checker hinge pin and bushes inspection and checker hinge pin and bushes inspection and bottom is systems. Leak check and tested system is W Pilatus AMM 12-A-34-11-20-00A-903A-A eck calibration from 1,000ft to 35,000ft as the property of the pince of the pin	runaway aural warning syst lap actuator P/N 978.73.20. S/N 0291 and installed over onal test IAW Pilatus AMM 1 ilatus AMM 12-A-27-50-03- ck IAW Pilatus AMM 12-A-2 eck IAW Pilatus AMM 12-A-2 eck IAW Pilatus AMM 12-A- m attachment bolts and nu to 20,000ft as required by 1 A. required by 14 CFR 91.411 Standard Altimeter P/N 50: 413 (a) and found the Trans a. Transponder #1 Garmin G	309 S/N 0733 and Installed overhauled chauled flap actuator P/N 978.73.20.309 12-A-27-50-00-00A-903B-A. 27-51-00-00A-313A-A. 232-10-00-00A-313A-A. 232-10-00-00A-313A-A. 24 cFR 91.411 (a) (1) and found system to a (a)(1) and found Altimeter to comply with 35P-P50 S/N 29639. Sponder system to comply with 14 CFR Part 5TX 345 P/N 011-03302-00 S/N 3EG020868.
	Signed:		Continued Next Page	Date: 1 DEC 2023

»CUTTER		12180 E. Control Tower Road Englewood, CO 80112		EPILATUS F	
PILATUS PC-12/45			Hobbs Meter	5662.7	
Model	296	Airframe Maintenance	Aircraft Total Time	15662.7	
Serial No.	N840AG	Record	Landings	9679	
Registration Work Order No.	14M-1015		vccs	167.9	
Removed relay CB K-2. Aviation DWG no. 0201 Replaced passenger sea Removed autopilot com A. Replaced caution light be Secured Generator 1 Ind Removed Gen 1 indicator	-81501.  t 2 oxygen connector P/N 957.1  puter P/N 065-0064-15 S/N 237  ulb IAW Pilatus AMM 12-A-31-1  ication cover IAW Pilatus AMM  P/N VEI 6300 S/N 175 and inst.  W Pilatus PC-12 AMM 12-A-71-	12-A-25-10-03-00A-920A-A. alled new indicator P/N 975.50.84.910 S/N 00-00-00A-903D-A. -00-00-00A-903H-A.	N 1205 IAW Pilatus AMM 1 -00A-920A. 065-0064-15 S/N:2976 IAW	Pilatus AMM 12-A-22-10-01-00A-9	
djusted engine torque la djusted overspeed gover eplaced damaged chafe to placed navigation light a placed propeller de-ice la placed recline push butta viced left and right main viced hydraulic brake flu iced O2 system IAW Pili	rape on left and right engine consissembly P/N 972.87.87.206 IAV brush block P/N 3E2042-4 IAW on cable assembly P/N 959.30.0 gear shocks IAW Pilatus AMM id IAW Pilatus AMM and IAW Pilatus AMM 12-A-12-10-05-00A-5	-A-71-00-00-00A-903L-A. wl doors. N 12-A-33-43-04-00A-920A-A. Pilatus PC-12 AMM 12-A-30-60-02-00A-92 D1.712 IAW Goodrich CMM 25-20-07. 12-A-32-10-00-00A-902A-A. D-02-00A-902A-A.			
Adjusted engine torque la djusted overspeed gover eplaced damaged chafe to eplaced navigation light a eplaced propeller de-ice la placed recline push buttoviced left and right main viced hydraulic brake fluction of the place o	rape on left and right engine consistently P/N 972.87.87.206 IAV prush block P/N 3E2042-4 IAW on cable assembly P/N 959.30.0 gear shocks IAW Pilatus AMM id IAW Pilatus AMM 12-A-12-10 atus AMM 12-A-12-10 atu	-A-71-00-00-00A-903L-A. wl doors. N 12-A-33-43-04-00A-920A-A. Pilatus PC-12 AMM 12-A-30-60-02-00A-92 D1.712 IAW Goodrich CMM 25-20-07. 12-A-32-10-00-00A-902A-A. 0-02-00A-902A-A.	s required IAW Pilatus AMI		
djusted engine torque la djusted overspeed gover eplaced damaged chafe to placed propeller de-ice la placed recline push butto viced left and right main viced hydraulic brake flut iced O2 system IAW Pilloved corrosion from lef	rape on left and right engine consistently P/N 972.87.87.206 IAV prush block P/N 3E2042-4 IAW on cable assembly P/N 959.30.0 gear shocks IAW Pilatus AMM id IAW Pilatus AMM 12-A-12-10 atus AMM 12-A-12-10 atu	I-A-71-00-00-00A-903L-A. WI doors. W 12-A-33-43-04-00A-920A-A. Pilatus PC-12 AMM 12-A-30-60-02-00A-92 D1.712 IAW Goodrich CMM 25-20-07. 12-A-32-10-00-00A-902A-A. D-02-00A-902A-A. B02A-A. Bocket and applied corrosion protectant as and right pitot tube mount bracket referen	s required IAW Pilatus AMN cing Pilatus AMM 12-B-20-		

### **AIRCRAFT LOG**

SCHIER .	>	12180 E. Control Tower Road Englewood, CO 80112		EPILATUS F	
Model	PILATUS PC-12/45		Hobbs Meter	5662.7	
Serial No.	296	Airframe Maintenance	Aircraft Total Time	15662.7	
Registration	N840AG	Record	Landings	9679	
Work Order No.	14M-1015		vccs	167.9	
Resealed left wing fur Replaced left and right Remove left wing fur Replaced water sepan Replaced hydraulic produced static drain Replaced static drain Replaced emergency Replaced striker plate Adjusted pitch servo Replaced left main gradjusted passenger of Replaced left main gradjusted passenger of Removed left main was linstalled wheel assy Removed right main Installed wheel assy Removed nose wheel	I probe and installed probe P/N rator filter P/N: 4935C120 IAW owerpack filter P/N 960.30.02.  line cable tie support P/N 971. exit door trim hardware IAW 1 es P/Ns 553.18.12.298 / 553.1 clutch IAW Pilatus AMM 12-A-eta ring carbon block P/N A30. ear WOW switch bonding strap door Forward/Aft support cable wheel assembly. Removed tire IAW Pilatus AMM 12-A-32-40-wheel assembly. Removed tire IAW Pilatus AMM 12-A-32-40-el assembly. Removed tire IAW Pilatus AMM 12-A-32-40-el assembly. Removed tire IAW Pilatus AMM 12-A-32-40-el assembly. Removed tire P/N IAW Pilatus AMM 12-A-32-40-el assembly. Removed tire IAW Pilatus AMM 12-A-32-40-el assembly. Removed tire P/N IAW Pilatus AMM 12-A-32-40-el assembly.	M 12-A-28-10-00-00A-313A-A. 946.91.27.446 IAW Pilatus AMM 12-A-28-I PFP20-1 S/N 202 IAW AMM 12-A-28-40-0 Pilatus PC-12 AMM 12-A-21-40-02-00A-90 101, reset delta "p" indicator and perform 32.18.114 in empennage IAW Pilatus AMI 12-A-52-20-00-00A-920A-A. 8.12.483 and hardware IAW 12-A-52-10-0 22-10-00-00A-313A-A. 26 IAW Pilatus AMM 12-A-61-20-02-00A-9 20 P/N 532.62.12.014 IAW Pilatus AMM 12 es IAW Pilatus AMM 12-A-52-10-01-00A-9 P/N 025-350-0 S/N 8092S00354 and insta 01-00A-920A-A. 26 P/N 025-350-0 S/N 8155S00297 and ins 01-00A-920A-A. 37 O21-327-0 P/N S/N 6230S0027 and ins	01-00A-920B-A. 04A-A. ed functional test IAW Pilat M 12-A20-50-02-00A-901A- 07-00A-920A-AA-32-10-00-00A-313A-A. 920A-A. illed tire P/N 025-350-0 S/N talled tire P/N 021-327-0 S	A. I 219ST00286 IAW Cleveland CMM 40-424. /N 2196T00267 IAW Cleveland CMM 40-424. IS/N 1349T00175 IAW Cleveland CMM 40-42	
	igned:		Continued Next Page	Date: 1 DEC 2023	
3	igneu.	For Cutter Aviation FAA CRS		DUIC. 1000 2023	

	Keç	gistration No		
and Remo	arks		Signature	Certificate No
» CUTTER	>	12180 E. Control Tower Road Englewood, CO 80112		EPILATUSE
odel	PILATUS PC-12/45		Hobbs Meter	5662.7
rial No.	296	Airframe Maintenance	Aircraft Total Time	15662.7
gistration	N840AG	Record	Landings	9679
. a Jar No	14M-1015	AN3-5A, AN960-10 and 938.09.14.303 IAW	VCCS	167.9
A-920A-A. placed power pac	k hydraulic drain bottle P/N 960. er system P/N TSFPC12E-3084-13	.273 S/N 0077ABC and installed new valve 30.01.199 IAW 12-A-29-10-01-00A-920A-A. L5-PL IAW Tannis Manual TNF3084 Rev. E JU and prop low pitch micro switch P/N 973.10	JN-05-2020.	
laced oil cooler h	oses P/N 940.26.28.007 IAW 12-	-A-79-20-02-00A-920A-A. 475-7-575 IAW Pilatus AMM 12-A-77-40-03		2-A-71-00-02-00A-320A-A.
placed upper aft on placed fire loop clap placed propeller re placed nut plate o	owl center beam P/N 571.10.12. amp P/N 526.11.12.052 on right eversing hardware P/N 3009087, n the upper right side of the vert	162 IAW Pilatus AMM 12-A-71-10-00-00A-9 exhaust flange IAW AMM 12-A-78-10-01-00, 3013165, 3011554, 968.20.11.326, 301316 cical stabilizer IAW Pilatus IPC 12-A-55-30-00 NK and installed controller P/N 071-01439-3	920A-A. 0A920A-A. 56 and MS9358-09 IAW Prat 0-020-941A-A.	
Si	gned:	Cor	ntinued Next Page Date	: _ 1 DEC 2023
	4	For Cutter Aviation FAA CRS# CUT	R877D	

## AIRCRAFT LOG

LACACI ME BLEMES OF ANA	nor	12180 E. Control Tower Road Englewood, CO 80112	il.	EPILATUS#
Model	PILATUS PC-12/45	Airframe Maintenance Record	Hobbs Meter	5662.7
Serial No.	296		Aircraft Total Time Landings VCCS	15662.7
Registration	N840AG			9679
Work Order No.	P/N RG-380E/44 S/N 40904128 and ar position indication light bulbs P/N			
referencing Pilatus S The airframe identif respect to the work	B 77-001. W&B change negligible.	rted by PWC. Removed Inlet pressure transfucers, pulled and collared circuit breaker #5 ected in accordance with current Federal and file under Work Order 14MN-1015.	Aviation Regulations and is	card for switch on instrument pa
		For Cutter Aviation FAA CRS# CUTR87	770	
		For Cutter Aviation FAA CRS# CUTR87	770	