

ENGINE MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 18282413 N413CS

ENGINE MODEL AND SERIAL TO - 540-ABIAS L-36360-48E

D5518-3-13

INSTRUCTIONS

This record should be completed and maintained in accordance with FAA Federal Aviation Regulations 43.9, 43.11 and 91.173 and/or other prevailing government regulations.

NOTE: Record Service Bulletins and Airworthiness Directives in the back of this record as well as the Airframe Maintenance Record.

Copyright © 1993





DATE	TOTAL T	IME ICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER

New Reciprocating Engine Certificate

This is to certify that the engine as described hereinafter has been manufactured and ground operation tested as prescribed by Lycoming specification and Federal Aviation Regulations. All applicable Federal Aviation Airworthiness Directives applicable Lycoming Service Publications have been complied with at time of manufacture. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Part Number:

ENPL-RT10597

Serial Number L-36360-48E

Engine Model

IO-540-AB1A5

Work Order

AR617186

Total Time

0 New

Form 777C Rev 05/13

Production Certificate #3 652 Oliver Street Williamsport, PA 17701 U.S.A Lycoming Engines is a division of Avco Corporation

-			MAINTENANCE RECORD		
DATE	TOTAL IN SER HOURS	VICE	DESCRIPTION OF THE WORK PERFORMED		AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
			A/C Serial # A/C Unit # A/C Registration # Date City ID Tetal A/C Hours Total A/C Landings 18282413 82413 N413CS Feb. 17, 2016 IDP 3.2 3	Total Engine HRS	Prop Hrs 3.2
			Engine Model 10-540-AB1A5 Serial Number L-36350-48E has been installed on aircraft S/N 18282413 With TTAF 3,2 TTSN was 3,2 Tris engine serviced with 11 qts Phillips Aviation Oil Type M 20W50 and Champion CH48110-1 filter. Work Performed by CESSNA AIRCRAFT COMPANY Certificate No PC-4 Date Feb. 17, 2016 I certify that the above staged maniferpance and in respection was performed in accordance with the current regulations of the Federal Aviation Administration Work inspected by Robert R. Evans Certificate No PC-4 Date Feb. 17, 2016 Personert details of this maintenance are on file at our facility under the above Work/Service Order Number as applicable.		
				h	
	-				
			MAINTENANCE RECORD		•
DATE	TOTAL IN SER	VICE	CESSNA 182T N413CS S/N 18282413 5-3-2016 INV# 9181 TACH TIME-21.4 CHANGED OIL AND FILTER, USED FILTER OPENED AND INSPECTED, FOUND SATISFACTORY. SERVICED WITH 9 QTS OF PHILLIPS 20W50 XC. GROUND RUNUPS PERFORMED, LEAK AND FUNCTION CHECKS SATISFACTORY. ADJUSTED IDLE MIXTURE SETTING TO DECREASE RICH CONDITION. END KACY BAWLINGS A&P 3791541 DAVID MPAGE A&P 3130153		AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

MAINTENANCE RECORD TOTAL TIME DATE AUTHORIZED SIGNATURE, IN SERVICE **CERTIFICATE TYPE** 76 HOURS 10THS & NUMBER CESSNA 182T N413CS S/N 18282413 10-26-2016 INV# 9621 TACH TIME-52.8 CHANGED OIL AND FILTER, USED FILTER OPENED AND INSPECTED, FOUND SATISFACTORY, SERVICED WITH 9 QTS OF PHILLIPS 20W50XC, INSTALLED A NEW CH48110-1 FILTER. GROUND RUNUPS AND LEAK CHECKS SATISFACTORY. --END--ERIC NOFTZ A&P 3047803 DATE TOTAL SIGNATURE, IN SEI ATE TYPE HOURS **Engine Maintenance Record** MBER 3 Cessna Blvd. **Reechcraft** Hawker Wichita, KS 67215 CRS# X07R071Y EASA.145.5122 TEXTRON AVIATION 25 Jan 2017 N413CS Date Registration No. Model 182T Total Time Tach 66.5 Ser. No. 18282413 **Total Time Hobbs** 73.0 Performed an Annual/100 hour inspection. Cessna inspection time intervals completed A,AX,B,C,D,F,O,P,R,S,W,X. C/W AD 2011-26-04 Lycoming fuel injection lines and clamp inspection. Inspected per Lycoming SB342G by visual inspection. Due at 166.5 hours R&R CHT probe p/n 32DKWUE006F0126 due to red X. Ops check ok. Adjusted magneto timing to 23 degrees BTDC. Drained oil, cut filter and inspected. Installed new CH48110-1 filter and refilled with 9 qts of Phillips X/C 20W-50. Cylinder compressor results are #1 79/80 #2 78/80 #3 79/80 #4 78/80 #5 78/80 #6 79/80. No leakage at valves noted. I certify that this power plant was repaired and inspected in accordance with the manufactures inspection program required by FAR 91.409 (f) (3) and Cessna 182 Series Maintenance Manual Rev. 20 1-Sept-2016, and Lycoming IO-540 series Operator's manual p/n 60297-10, 4th edition dated June 2006, and current FAA regulations and is approved for return to service. Inspections: 100 hour engine inspection / Cessna 182 inspection intervals Authorized Signature Ezra R. Olson for

Textron Aviation Repair Station X07R071Y

D	Engine Log Book Entry, by Yis Lycoming Complied with single engine oil change, with sa no defects noted. Installed new CH48110-1 filts check OK. Complied with 50 Hr. inspection iten clamp inspection, no defects noted. I CERTIFY THAT THE ABOVE STATED MAINTEN/WITH THE CURRENT REGULATION OF THE FEDI IDENTIFIED ABOVE IS PRESENTLY AIRWORTHY Engine Log Book Entry, by Yis Lycoming AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRW ORTHINESS APPROVAL TAG Textron Aviation Inc. (PC4) Textron Aviation In										
DATE	HC		Engine Log		Authority C	ountry od States	AUTHOR FAA Fo	IZED RELEA	SE CE	RTIFICATE ROVAL TAG	10
		no defects	noted. Installed	d new CH48110-1 filte			1 Cessna Bly	n Aviation Inc. d, Wichita, KS 6	7215	-	Number:
	+								20101753	Contract to the Contract	
					12 Remarks:		AUTH				New
		WITH THE	CURRENT REGI	JLATION OF THE FEDI				PO#: 0	01633		
			O SERVICE.	SENTLY AIRWORTHY	Approved a	levign data and at	we were manufactured in co e in a condition for safe ope secified in Block 12.	nformaty to: 144	DIACER 43	9 Return to Service Others infex otherwise specified in Blo- sed in Block 12 was accomplished if Regulations, part G and in res	regulation specifically Block 12 k 12, the week identified in Block d in accomiance with Tale 14, specific to that work, the items are
		P.O. Bo	d By Yingling a x 9248, Wich	ita, KS 67277	Marie		Lauber	13c Approva' Authoriza PC4		14b. Authorized Signature	14c. Approval Certificine No.
		1000000	CRS #YN8R621 e 316-943-3240		MARILYN	K. FARB		13e. Date (dd swmm))); 02/ldar/2(User/Installer Respon	017	4d Name (Typod or Printed)	14e Date (dd/mmns))))yr
			ffery A. Eckhard	it fafrif 21	It is important to and Where the user instal	erstand that the eviler performs work	Austence of this document al	one does not automatically con-	at to a direct	to install the aircraft engine pro-	peller article.
					in Block I, at is essent country specified in I Statements in Blocks accordance with the n FAA Form 8130-3 (0)	tail that the user's flock I 13a and 14a do is attental regulation 3-14)	notaller ensures that his her of constitute installation cer is by the user installer befor	airworthiness authority accepts tification. In all cases, aircraft in the aircraft may be flown.	uners authority aircraft engine	different than the airworthiness a (s) propeller(s) article(s) from th ords must contain an installation	peller article, unthority of the country specified e airs orthiness authority of the certification issued in NNN, 0052-00-012-9005
				1				ž.			
			÷							4	
DATE	To	OTAL TIME		MAINTE	NANCE R	ECOR	D				
DATE	IN	JRS 10THS		DESCRIPTION OF	THE WORK I	PERFOR	RMED	3		CERTIFIC	SIGNATURE, CATE TYPE MBER
			Elman and a sec	Red Cloud Avial 12021 N Hw Seminole, OK 405-382-21	y 99 74868						
		Reg # N413	BCS					TTAF: 171	.1		
	t	Date: 05/14/ IO-540-AB1 Serial # L-30	/2018 A5				T	ach Time: 171 TSNEW: 171			
		checks were	as follows: Cyl 1	ction IAW Lycoming and Cess 78/80, Cyl 2 74/80, Cyl 3 77/8	80, Cyl 4 76/8	30, Cyl 5	78/80, Cyl 6	79/80. Cleane			30
		found and leaks found Lycoming a	replaced with new . New and recurr nd Cessna Mainte ction and has bee	spark plugs upon reinstallation w Tempest AA48110-1, filled wing AD's checked and compli- enance Manuals, and FAR 43 an determined to be in airworth	vith 9 qts Phil ed with. All v 3 Appendix D	llips 20V vork don . This e	V50. Engine le in accordar ngine has co	ground run, no nce with currer mpleted an 100	nt O		
		ė.	0.8				-4 D !				
							ott D. Lee P 3728276	afor			
						0	will				
		ata 80 B B									

MAINTENANCE RECORD

DATE	1 <u>I</u> HC		Engin	e Log Bool	k Entry, by Yinglin Lycoming IO-5		n for: N413CS C L-36360-48E	Cessna 1828	2413	GNATUI E TYPE ER
		no defects check OK	noted.	nstalled new	change, with sample. CH48110-1 filter and . inspection items, no ted.	serviced w	ith 9 qts Phillips 20W	50 X/C. Groun	nd run and leak	
	-	WITH THE	CURREN D ABOVE	T REGULATION	ATED MAINTENANCE A DN OF THE FEDERAL A LY AIRWORTHY WITH	AVIATION A	DMINISTRATION, AND	THE ARTICLE	AIRCRAFT	
0.1		P.O. Bo FAA Phor Signature	ox 9248, CRS #YI ne 316-9	ngling Aviati Wichita, KS N8R621Y 43-3246 Eckhardt		-	Date Completed Work Order # Hobbs Hours Tach Time Aircraft Total Time		-21-2017 19259 116.9 106.8 106.8	
					1.2					0 14 0 14 2000,
						•				
					MAINTEN	ANCE RE	CORD			
DATE	IN	OTAL TIME SERVICE JRS 10THS			DESCRIPTION OF TH			/	AUTHORIZED : CERTIFICA & NUM	TE TYPE
		3		v 90	Red Cloud Aviation 12021 N Hwy Seminole, OK 7 405-382-218	99 '4868				
		Reg # N41 Date: 05/14 IO-540-AB1 Serial # L-3	⊮2018 IA5				Tach	TTAF: 171.1 Time: 171.1 NEW: 171.1		
		checks were Gapped, Te found and leaks found Lycoming a	e as follow ested, and replaced I. New ar and Cessr	s: Cyl 1 78/80, rotated spark p with new Temp d recurring AD na Maintenance	W Lycoming and Cessn Cyl 2 74/80, Cyl 3 77/80 olugs upon reinstallation est AA48110-1, filled with the checked and complied Manuals, and FAR 43 Amined to be in airworthy	D, Cyl 4 76/80 Drained oil th 9 qts Philli d with. All wo Appendix D.	 Cyl 5 78/80, Cyl 6 79/8 checked filter for debrips 20W50. Engine groups done in accordance to This engine has completed. 	30. Cleaned, s, no debris and run, no with current ated an 100		
	_	F 6=		2	* *		Scott D. Lee A/P 3728276	m		

ENGINE LOG ENTRY Mesquite Aircraft Sales & Services 1350 Airport Blvd. Mesquite, Texas 75181 Aircraft Reg. N413CS AFSN: 18282413 DATE: 05/31/2019 HOBBS: 235.1 **TACH 214.4** ENG. Manuf. LYCOMING ENG Model-I.O.-540-AB1A5 ENG S/N L-36360-48E ETSN-214.4 Complied with 100 hour inspection on Lycoming Engine Model I.O.-540-AB1A5 S/N L-36360-48E IAW Title 14 CFR part 43, Complied with Airworthiness Directive research on Engine. Current through 2019-10. Complied with A.D. 2015-19-07 External Fuel injector lines and associated clamps by visual inspection. No defects noted at this time. Next due 335.1. Engine compression check results as follows #1: 77/80, #2: 78/80, #3: 74/80, #4: 77/80, #5: 77/80, #6: 77/80. Drained oil and removed oil filter, inspected filter for ferrous metal, none noted. Serviced engine with 9 quarts Phillips 20W-50 X/C and installed new filter P/N CH48110-1 filter. Secured and safetied as required. Leak check good. Provided oil sample to AOA for analysis and forward Owner/Operator test results. See Lab report # 44150207995 for details. Continue service and retest at next oil change interval to establish trend. Cleaned, gapped and tested engine spark plugs. Reinstalled and torqued as required. Tighten all retaining screws on each engine rocker box cover as required. Installed missing hardware on right AFT section of engine baffling as required. Removed dirt dobber nests from engine compartment as required. NOTE- Steven Adams A&P/I.A 2713403 also performed maintenance. I certify this aircraft, engine and/or component identified above was repaired and/or inspected in accordance with current F.A.A. regulations and was determined to be in airworthy condition and approved for Return to Service with respect to work performed. Martin J. Sisk A&P/ I.A. 2820585 Dated: May 31, 2019 Signed MAINTENANCE RECORD AUTHORIZED SIGNATURE, TOTAL TIME DESCRIPTION OF THE WORK PERFORMED CERTIFICATE TYPE IN SERVICE & NUMBER HOURS 10THS West Valley Flying Club DATE 10/22/2019 West Valley Flying Club REG # N413CS 12/13/2019 TACH 273 REG # N413CS 1901 Embarcadero Rd. Ste. 100, Palo Alto. Ca 94303 (650)856-2030 273 TACH 297 1901 Embarcadero Rd. Ste. 100. Palo Alto, Ca 94303 (650)856-2030 297 Engine Entry: COMPLETED 100 HOUR INSPECTION OF THE ENGINE USING THE CESSNA 182
MAINTENANCE MANUAL 100 CHECKLIST AS A GUIDE DRAIN OIL AND SERVICE
ENGINE WITH 9 OTS OF AEROSHELL 15W50 OIL REMOVED AND REPLACED OIL
FILTER WITH NEW P/N CH48110-1. CUT OPEN OLD FILTER NO EXCESSIVE CONTAMINANTS FOUND REMOVED AND REPLACED 6 SPARK PLUGS BE IN AIRWORTHY CONDITION AND RETURN TO SERVICE

DATE

Engine Entry:

COMPLETED 50 HOUR INSPECTION OF THE ENGINE USING THE CESSNA 182 MAINTENANCE MANUAL 50 HOUR CHECKLIST AS A GUIDE DRAIN OIL AND SERVICED WITH 9 QTS OF 15W50 AERUSHELL OIL REMOVED AND REPLACED OIL FILTER WITH NEW P/N CH48110-1 CUT OPEN OLD FILTER NO EXCESSIVE CONTAMINANTS FOUND I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH THE 50 HOUR INSPECTION AND WAS DETERMINED TO

P/N REM40E. COMPLIED WITH AD2015-19-07 FUEL LINE INSPECTION PERFORMED POST INSPECTION ENGINE RUN UP MAG CHECK GOOD, SYSTEM CHECK GOOD, NO LEAKS FOUND. THIS AIRCRAFT IS IN AN AIRWORTHY CONDITION AND RETURNED TO SERVICE

JASPER SARDALLA A&P /IA 3287387

JASPER SARDALLA A&P/IA 3287387

		MAINTENA	ANCE RECORD	
DATE	TOTAL TIME IN SERVICE HOURS 10THS		E WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
Connect System. With respendence	S LYCOMING, II 66.7 Reiff Preheater, Standar or - Straight, Installed (7) sect to the work performed are on file with Sierra A	Engine - page 1 of 1 SIERRA A E R O 6 Truckee Alport Rd, Hangar #1 - Truckee, CA 96161 - 530-359-8751 O-540-AB1A5, S/N: L-36360-48E January 17, 2020 of System, per Reiff Installation instructions. Installed (1) TNC 101 - Adel Clamp, Installed (1) SL6 - Reiff Preheater Standard ed, this engine is approved for return to service. Details of work Aero LLC under work order: WO_2081.	1901 Embarcadero Rd Ste 100. Palo Alto. Ca 94303 (650)856-203 Engine Entry: COMPLETED 50 HOUR INSPECTION OF THE ENGINE MAINTENANCE MANUAL 50 HOUR CHECKLIST AS A SERVICED WITH 9 QTS OF 15W50 AEROSHELL OILE OILE FILTER WITH NEW PIN CH48110-1. CUT OPEN O CONTAMINANTS FOUND COMPLIED WITH AD2015-1 INSPECTION I CERTIFY THAT THIS AIRCRAFT HAS I ACCORDANCE WITH THE 50 HOUR INSPECTION AN IN AIRWORTHY CONDITION AND RETURN TO SERVI	ETT 361 E USING THE CESSNA 182 GUIDE. DRAIN OIL AND REMOVED AND REPLACED LD FILTER NO EXCESSIVE 9-07 FUEL INSPECTION LINE BEEN INSPECTED IN
			JASPER SARDA	ALLA A&P /IA 3287387
		MAINTENA	NCE RECORD	
DATE	TOTAL TIME IN SERVICE HOURS 10THS	DESCRIPTION OF THE	WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
1901 Embarcad Engine Ent DRAIN OIL A AND REPLAC	ND SERVICED WITH 9 O IED OIL FILTER WITH N VE CONTAMINANTS FO SS PIN REM40E	TACH: 395	Sierra Aero LLC - 10356 Truckee Airport Rd. Harrow F1 - Truckee, C N413CS Tach: 447.5 1. Complied with AD 15-19-07 by inspection of fuel lines and 2. Removed and inspected 6 spark plugs, reinstalled with ne 1 - Spark plug gasket. 3. Performed oil change; drained oil and removed filter. Cut ancies noted. Installed (7) Aeroshell - 15W50 Oil, Installed 4. Obtained oil sample and sent to Blackstone for analysis. 5. Ran engine, leak check good. —END—. With respect to the work performed, this engine is approved for performed are on file with Sierra Aero LLC under work order: W Jeffrey Fay A&P 2679315	clamps, no discrepancies noted. w gaskets. Installed (6) AN4027- filter and inspected, no discrep- (1) AA48110 - Tempest Oil Filter.

7 7 3

			MA	INTENANCI	E RECORD	
DAT	TOTAL TIME IN SERVICE HOURS 10	E OTHS	DESCRIPTIO	N OF THE WO	RK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
8/19	1/20652	1	Orained oil, replaced o 8 97. W1007lus, Soft 17 3521052	Will:	& oilfilter.	
9/16	12681	' 6	Drained oil, replaced 39T. Aeroshell w10071 WAD 2015-19-07-1	oil Filt. lus, safe Fuel Lia	er. CHY8110-1, added Tred dvaixix Filter, 45 inslection	Willia & Mans 200 AP 3521052
9/15/2	725 3	5 i	Drained engine oil, re 39T. W1007Lusoiz, Sat	Placedo Fried oil	il filter MCH4840-1900a filter, closeddiain	William EMWoldle A17352105-2
12/1	120 772	Į.	Drained engins oil Added 891, Wico Plu 2015-19-07 Fuelline	Perlace S-sufi	d oil filter PINCH48/10 ied = ilter-c/WAD - No defects Noted	Willia Ellonsta A173521052

. 5	¥1		\$ -			
					5	
			MAI!	NTENANCE	RECORD	
wo: WO_2	542	SIE	RR N	OF THE WOR	RK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
P H	teplaced alternator with	new. Insta	Hungar #1 - Trudee, CA 96161 - 530-359-8751 S.N: L-36360-48E HOBBS: 841.8 November 11, 2020 Alled (1) ASG12000-3-PMA - Alternator, S/N: Ingine is approved for return to service. Details ero LC under work order: WO_2542.		Sierra Aero LLC - 10358 Truckee Airport Rd, Hangar #1 - Truc N413CS LYCOMING, IO-540-AB1A5, S/N: L-36: HOBBS: 884.9 TACH: 784.9 TSN: 784 1. Performed annual inspection per Sierra Aero LLC sion check: 1). 76, 2). 76, 3). 63, 4). 76, 5). 70, 6	160-48E January 14, 2021 9
Taylor (Good A&P 3529105 wo: WO_2620		SIERRA Engine - pag	pe 1 of 1	- Spark plug gasket. 2. Drained oil and removed filter. Cut filter and in cles noted. Obtained oil sample and sent to Blac Blackstone - Oil Sample, Installed (1) AA48110 Phillips - 20W50 Oil. 3. Ran engine, leak check good.	kstone for analysis. Installed (1)
1	N413CS Lycon HOBBS: 884.9	ning IO-540 TA	— A F R O— Alee Airport Rd, Hangar #1 - Truckee, CA 96161 - 530-359-8751 D-AB1A5, S/N: L-36360-48E January 14, 20 CH: 784.9	021	Researched AD's; see attached AD Compliance Repot been inspected IAW a 100 HR/ANNUAL inspection a airworthy condition on this date. –END- Details of work Aero LLC under work order: WO_2620. Bryan Whitfield IA 2549302	nd was determined to be in an
ή'	Removed cylind tor Aviation in F MM. Installed (2 SHROUD TUBE Replaced spark Removed Slick	ler #6 PN: Palo Alto for PA77611 LOCKPLA plugs with magnetos onents, Inc SB3-80B p	new. Installed (12) UREM38E - Spark plug. PN6351, SN: 15060588 & 15060589. Sent to Air to disassemble, clean, inspect & CW 500 Hoter W086750 & W086751. Re-installed magnetos	rcraft	Gryan Millurgu IA 2545302	V
t-	With respect to the wo of work performed are Bryan Whitfield A&P 2	on file with	ed, this engine is approved for return to service. Do Sierra Aero LLC under work order: WO_2620.	etails		

1	ro: WO_2683 Engine - page 1 of 1	IN				
D/	SIERRA	EV	wo: WO_2741	SIERRA	Engine - page 1 of 1	JRE,
$\triangle \vdash$	Sierra Aero LLC - 10256 Trudee Airport Rs. Hangar #1 - Trudee, CA 96161 - 530-359-8751 N413CS	1_	-	Sierra Aero LLC - 10956 Truckee Airport Rd, Hangar #1 - Truckee, CA	96161 - 530-359-8751	
	HOBBS: 904.4 TACH: 804.4		HOBBS: 9	Lycoming IO-540-AB1A5, S/N: L-36360-488.5	18E March 9, 2021	
	 Performed oil change; drained oil and removed filter. Cut filter and inspected, no discrepancies noted. Installed (8) Aeroshell - 15W50 Oil, Installed (1) AA48110 - 		1. Perfor	med oil change: draight and all hem	Cut filter and inspected no	
	Tempest Oil Filter. 2. Obtained oil sample and sent to Blackstone for analysis. Installed (1) Blackstone		Tempe	est Oil Filter.	Oil, Installed (1) AA48110 -	
-	- Oil Sample. 3. Ran engine, leak check good. –END–.		 Obtair Ran e 	ned oil sample and sent to Blackstone for analysi angine, leak check good. —END—.	s.	
- I w	the secret to the work performed, this engine is approved for return to service. Details		With respect	to the work part	Or return to sensice. Details	
of	work performed are on file with Sierra Aero LLC under work order: WO_2683.	11.1	or work perio	ormed are on file with Sierra Aero LLC under wor	k order: WO_2741.	
B	ryan Whitfield A&P 2549302	1-1	Taylor Good	A&P 3529105		
	WARNING					J j
	 When installing drive gear or driver onto magneto, torque nut provide 	ded to	·	wo: WO_2806		ingine - page 1 of 1
-	120 to 180 inch lbs.Use only the installation hardware provided.			SIEF	RR M	
h	 Secure nut with appropriate cotter pin. 			Sierra Aero LLC - 10356 Truckee Airport Rd, H	angar #1 - Truckee, CA 96161 - 530-359-875	1
1	FAA-PMA Approved			N413CS Lycoming IO-540-AB1A5, HOBBS: 1010.6 TACH: 897.6		il 22, 2021
P	This magneto was manufactured from all new components in accordance with	II216A I		 Replaced LH magneto with new. Inst S/N: 21021589, Installed (2) LW12681 Adjusted RH magneto timing. 	- Magneto Gasket.	gneto 6351,
	the Champion/Slick L-1318 Document in the F-1100 Master Service Manual. For L Magnetos, see L-1500 Manual.	ASAR*		Performed check run, no discrepancies		
	Enter magneto model, serial number, and date of installation, and attach this tag to engine t	logbool	k —	With respect to the work performed, this engit of work performed are on file with Sterra Aero	ne is approved for return to sen LLC under work order: WO_2	vice. Details 806.
	1.251			Bryan Whitfield A&P 2549302		
	Magneto Model No. 210 21589			5,611,111,101,111		
	Magneto Serial No.	000000	-			
	Dale of Installation 1/22/2021					
	and the same of th	1				
		NAN	ICE REC	ORD	AUTHORIZED SIGN	ATURE,
DATE	TOTAL TIME IN SERVICE HOURS 10THS	THE	WORK PER	FORMED	CERTIFICATE T	YPE
wo: W	D_2802 Engine - page 1 of 1	Г	wo: WO_2894	her	Engine - page 1 of 1	
	SIERRA		Sie	SIERRA — A F R O— erra Aero LLC - 10356 Truckee Airport Rd, Hangar #1 - Truckee, CA 9616		
	Sierra Aero LLC - 10356 Truckee Airport Rd, Hangar #1 - Truckee, CA 96161 - 530-359-8751	-	N413CS HOBBS: 1055.	Lycoming IO-540-AB1A5, S/N: L-36360-48E .3 TACH: 935.8	June 02, 2021	
	BBS: 1010.3 TACH: 897.4		1. Performed	d oil change; drained oil and removed filter. Cut	filter and inspected, no	
1.	Performed oil change; drained oil and removed filter. Cut filter and inspected, no discrepancies noted. Installed (7) Aeroshell - 15W50 Oil, Installed (1) AA48110 -		Tempest (oil Filter.	Installed (1) AA48110 -	
	Tempest Oil Filter. Obtained oil sample and sent to Blackstone for analysis. Installed (1) Blackstone	-	- Oil Samp		nstalled (1) Blackstone	
1 2	- Oil Sample.	١,		ne, leak check goodEND-,		
4.	Complied with AD 15-19-07 by inspection of fuel lines and clamps, no discrepancies noted.	ő	f work performe	the work performed, this engine is approved for re ed are on file with Sierra Aero LLC under work or	eturn to service. Details der: WO_2894.	
With	respect to the work performed, this engine is approved for return to service. Details	N	faximilian Ilizan	OV A&P 3925219	ZARAV .	
of wo	rk performed are on file with Sierra Aero LLC under work order: WO_2802.					
Taylo	r Good A&P 3529105					
-	+ + +					
					1	
					1	

ATE	TOTAL TIME IN SERVICE HOURS 10THS	DESCRIPTION OF			E RECORD RK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
1. I	Siema Aero LLC - 10356 Truc CS LYCOMING, IO- BS: 1097.3 TACH: 97. Performed annual inspectic sion check: 1). 67, 2). 70, Spark plug gasket. Drained oil and removed folias noted. Obtained oil sa Slackstone - Oil Sample, Iv- hillips - 20W50 Oil. Ran engine, leak check goor creded AD's; see attached of rspected IAW a 100 HR/	on per Sierra Aero LLC Inspection Checklist. Compres- 3). 60, 4). 70, 5). 70, 6). 70/80. Installed (12) M-674 - iilter. Cut filter and inspected medium, no discrepan- imple and sent to Blackstone for analysis. Installed (1) installed (1) AA48110 - Tempest Oil Filter, Installed (8) and Compliance Report. I certify that this ENGINE has ANNUAL inspection and was determined to be in an END- Details of work performed are on file with Sierra	Witt are	1. Re h resp on file	SIERRA Sierra Aero LLC - 10356 Truckee Airport Rd, Hangar #1 - Ti	ilter. Cut filter and inspected, no NSO Oil , Installed (1) AA48110 - nalysis. byed for return to service. Details er work order: WO_3027. Engine - page 1 of 1 Engine - page 1 of 1 BE October 13, 2021 installed P/N 86317 - EGT Probe.
1500	dUI:					
		MAINTE	1AN	NCE	RECORD	
TE	TOTAL TIME IN SERVICE HOURS 10THS	DESCRIPTION OF		WOF	RK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
Wir of v	413CS LycomIng IO OBBS: 1277.6 TACH: 1. Performed oil change; no discrepancies notec AA48110 - Tempest Oil 2. Obtained oil sample an 3. Ran engine, leak check 4. Complied with AD 15-1 cies noted. h respect to the work perfc	d sent to Blackstone for analysis. good. 9-07 by inspection of fuel lines and clamps, no discrepan- ermed, this engine is approved for return to service. Details with Sierra Aero LLC under work order: WO_3101. Engine : page 1 of 1		W	Sierra Aero LLC - 10356 Truckee Airport Rd, Hanger #1 - Truck N413CS Lycoming IO-540-AB1A5, S/N: L-36360-48E HOBBS: 1263.6 TACH: 1121.3 1. Performed oil change; drained oil and removed filter. no discrepancies noted. Installed (7) P/N Aeroshell - AA48110 - Tempest Oil Filter. 2. Obtained oil sample and sent to Blackstone for analysis Oil Sample. 3. Ran engine, leak check good. —END ith respect to the work performed, this engine is approved for work performed are on file with Sierra Aero LLC under work yan Whitfield A&P 2549302	December 21, 2021 Cut filter and inspected, 15W50 Oil , Installed P/N Blackstone or return to service. Details
	Sarra Asro II C	SIERRA — A E R O —			SIERRA A E R O Signa Agro LLC - 10756 Truckee Agrood Rd Unique 81 - To	du CARRIE

N413CS TEXTRON AVIATION INC, 182T, S/N: 18282413 February 01, 2022 HOBBS: 1323.7 TACH: 1176.0 TSN: 1176.0

Complied with AD 15-19-07 by inspection of fuel injector lines and clamps, no discrepancies noted.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Sierra Aero LLC under work order: WO_3242.

Maximilian Ilizarov A&P 3925219

Max Il EARON

N413CS Lycoming IO-540-AB1A5, S/N: L-36360-48E HOBBS: 1323.7 TACH: 1176.0

2. Obtained oil sample and sent to Blackstone for analysis.

3. Ran engine, leak check good. -END-.

Maximilian Ilizarov A&P 3925219 _

 Performed oil change; drained oil and removed filter. Cut filter and inspected, no discrepancies noted. Installed (7) P/N Aeroshell - 15W50 Oil, Installed P/N AA48110 - Tempest Oil Filter.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Sierra Aero LLC under work order: WO_3242.

February 01, 2022

Il: ZABOV

3. Form Tracking Number: ATF H-U101181		5. Work Order/Contract/Invoice Number: M032670	Serial Number: 11. Status/Work:	H-U101181 NEW			yo		14a. 🗆: 14: CFR 43.9. Return 10: Service 💛 . Other: regulation specified in:Block:12	dess otherwise specified in Block 12, the work identified in Block 11	and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	nature: 14c. Approval/Certificate. No:	r: Printed); 14e.: Date (dd/mmm/yyyy);		User/Installer Responsibilities
T FACE CE	FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	VTGOMERY, AL 361	9. Quantity: 10.	1 H	PMA/		13.5		14a. 🗆 14 CFR 43.9	Certifies that un	and described in B Federal Regulation return to service.	No.: 146. Authorized Signature	14d. Name (Typed or Printed):		User/Installer Responsibilities
HODIZED BEI FASE CERTIFICATE	FAA Form 8130-3, AIF	2900 SELMA HWY., MONTGOMERY, AL 36108	Part Number:	ASG12000-3-PMA	?. Remarks: AIRWORTHINESS APPROVAL- PARTS.FOR PMA ELIGIBILITY SEE WWW.HARTZELL.AERO/PMA/	• ")			actured in conformity to:	lition for safe operation.	lock 12.	13c.Approval/Authorization No.: ODA-100082-CE	13e. Date (dd/mmm/yyyy):	15-Oct-2020	User/Instal
AT17	AOI	OGIES, 2	8.	ASGL	R PMA ELIGIB				were manufa	l are in a conc	specified in B	\cap			
1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		4. Organization Name and Address: HARTZELL ENGINE TECHNOLOGIES,	7. Description:	ALTERNATOR **** END ****	ks: IINESS APPROVAL- PARTS.FO				13a. Certifies the items identified above were manufactured in conformity to:	Approved design data and are in a condition for safe operation.	Non-approved design data specified in Block 12.	13b. Authorized Signature:	43d. Name (Typed or Printed):	James Murphy	
1. Approving Authori FAA/	:	4. Organizat HARTZEL	6. Item:	1 /	12. Remarks: AIRWORTHIN	-			13a. Certific	⊠		13b. Author	13d. Name (s L	

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA Form 8130-3 (02-14)

NSN: 0052-00-012-9005

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block I, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

L/H WAG

FAA/UNITED STATES 4. Organization Name and Address:	CERT FAA Form 8130-3, Ai	CERTIFICATE		
2	FAA Form 8130-3, Ai			86750
		8130-3, Airworthiness Approval Tag		
	Aircraft Electrical Components, Inc. (CRS# S7HR883J) Nevada Repair Center 2482 Progress Drive Redding, CA 96001	RS# S7HR883J)	5. Work Order/Cont	5. Work Order/Contract/ Invoice Number: CUST PO: 0317
6. Item 7. Description:	8. Part Number:	9.Quantity:	10. Serial Number:	11. Status/Work:
Magneto	6351	-	15060588	Repaired
Certifies the items identfied above were manufactured in conformity Approved design data and are in a condition safe for operation Non-approved design data specified in Block 12.	ere manufactured in conformity to: ndition safe for operation n Block 12.	14a. [X] 14 CFR 43.9 Return to Service Certifies that unless otherwise specified described in Block 12 was accomplishe Regulations, Part 43 and in respect to	a. [X] 14 CFR 43.9 Return to Service [] Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to service.	pecified in Block 12. tified in Block 11 and 14, Code of Federal vroved for return to service.
13b. Authorized Signature: 13c Not Applicable	13c. Approval Authorization No.: Not Applicable	14b. Authorized Signature:	14c. Approval/Certificate Number: S7HR883J	ficate Number:
13d. Name (Typed or Printed): 13e Not Applicable	13e. Date (dd/mmm/yyyy): Not Applicable	14d. Name (Typed or Printed:) Carl E. Schutte	14e. Date (dd/mmm/yyyy): 22/Dec/2020	, , , , , , , , , , , , , , , , , , , ,
	User/Installer Responsibilities	usibilities		

It is important to understand that the existance of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in Block 1, it is essential that the user/installer ensure that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER

DATE	CUSTOMER PO#	WORK ORD	ER#	
12/22/20	0317	86750		
Mfr: Slick	Desc.: Magneto	Part No.: 6351	Serial No.: 15060588	Work Order No.: 86750

Received Magneto for 500 Hour Inspection:

1 ea P/N 6351 S/N 15060588

Disassemble, clean and inspect. Noted both rivets loose on impulse coupling – fails per SB2-19A. C/W 500 Hour Inspection per Section 3.3 of Manufacturer Manual L-1363G, Rev G dated Oct 30 2017 and SB2-80-C. Distributor block reconditioned. Parts replaced as listed. Magneto assembled, internally timed and tested.

The following parts have been replaced in this unit:

I ea A-13081

Contact & Cam Kit

1 ea AM-3215

Carbon Brush

In addition to 500 Hour Inspection the following was required:

1 ea M-3333

Impulse Coupling

AD / SB STATUS:

AD 81-16-05 Coil - N/A MAG MOD #

SB1-80-A Soft Rivets (447, 600, 4200 & 6200) AD 80-06-05 - N/A MAG MOD #

SB2-80-C Maintenance Schedule (400/600, 4000/6000, 4200/6200, 4300/6300) - 500 HOUR INSPECTION

SB3-80-B Broken Flanges, All Magnetos - SUPPLY COPY TO CUSTOMER

SB1-83-A Index Plate - IN COMPLIANCE

SB1-86-C Impulse Coupling Inspection - C/W INSPECTION; INSTALLED NEW IMPULSE COUPLING DOM 11-20-20

SB1-88-A / AD 88-25-04 Insp Models 6220 & 6224 Pressurized - N/A MAG MOD #

SB1-88-B / AD 88-25-04 Insp Models 6300 Pressurized - N/A MAG MOD #

SB2-88-A Bearing Inspection (4200) - N/A MAG MOD #

SB3-88-A Bearing Inspection (6200) - N/A MAG MOD #

SB1-89-B Maintenance Schedule (Single Ignition Sys) - N/A APPLICATION

SB1-95 Replacement (4000 & 4100) - N/A MAG MOD #

SB1-98-A / AD 99-04-04 Impulse Coupling Inspection (6200 & 6300) ea 250 Hrs. - C/W, INSTALLED NEW M-3333 11-20-20

SB1-00C / AD 2011-26-07 (Some 6300) Impulse Pin - N/A MAG MOD #

SB1-07 Insp Mag Driver / Torque Requirements (4309, 4310) - N/A MAG MOD #

SB2-07 Insp Mag Driver / Torque Requirements (Lasar) - N/A MAG MOD #

SB3-07 Impulse Coupling Assy (Some 4300) - N/A MAG MOD #

SB2-08B Contact Cam 4300/6300 & Lasar - C/W INSPECTION INSTALLED NEW, PMA MFR, NFA

SB3-08B Carbon Brush or Dist Block 4300/6300 & Lasar - C/W INSPECTION INSTALLED NEW, PMA MFR

SB1-12 Defective Contacts (M3081 Contact Kits) - N/A, INSTALLED NEW, PMA CONTACTS

SB-009 Tempest Contacts - N/A DATE CODE; A-13081 11-2-20

SB1-15A Distributor Gear Assy (4 Cyl) - N/A MAG MOD #

SB03-7A IO240 Series Mag Drive Gear (4309, 4310) - N/A MAG MOD #

SL 1-17 Drive End Nut Torque (Impulse) - C/W

SB1-19 Impulse Coupling Stop Pin - N/A MAG SERIAL #

SB2-19A Impulse Coupling - C/W, INSTALLED NEW IMPULSE COUPLING; M-3333 MFR DATE 11-20-20

2482 Progress Drive Redding, CA 96001-3235 (530) 221-4397 (530) 221-0660 fax Repair Station #S7HR883J The aircraft component identified above was repaired and Inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service.

FAA REPAIR STATION NO. S7HR883J

Inspector:

PH MAG.

1. App	1. Approving Civil Aviation	2.	AUTHORIZ	HORIZED RELEASE	ASE		3. Form Tracking Number:	ıber:	
₹	Authority/Country:		CERTI	CERTIFICATE			~	86751	
	FAA/UNITED STATES	6	FAA Form 8130-3, Airworthiness Approval Tag	worthiness App	roval Tag				
4. Orga	4. Organization Name and Address:	Aircraft Electrical Com Nevada Repair Center 2482 Progress Drive Redding, CA 96001	Aircraft Electrical Components, Inc. (CRS# S7HR883J) Nevada Repair Center 2482 Progress Drive Redding, CA 96001	(S# S7HR883J)		เก๋	5. Work Order/Contract/ Invoice Number: CUST PO: 0317	ontract/Invoice Number: CUST PO: 0317	
6. Item	7. Description:		8. Part Number:	6	9.Quantity:	10. Serial Number:	ımber:	11. Status/Work:	
-	Magneto		6351		-	· ·	15060589	Repaired	
12. Remarks: Performed Full details	12. Remarks: Performed 500 Hour Inspection in accordance with Manufa Full details of work carried out per Work Order No 86751	in accordance v er Work Order h	12. Remarks: Performed 500 Hour Inspection in accordance with Manufacturer Manual L-1363G, Rev G dated Oct 30 2017 and SB2-80-C. Full details of work carried out per Work Order No 86751 attached.	1363G, Rev G date	ed Oct 30 2	2017 and Sf	B2-80-C.		
13a. C.	Certifies the items identfied above were manufactured in conformity to: Approved design data and are in a condition safe for operation Non-approved design data specified in Block 12.	ve were manufacti n a condition safe fc ified in Block 12.	ured in conformity to: or operation	14a. [X] 14 CFR 43.9 Return to Service Certifies that unless otherwise specified described in Block 12 was accomplish Regulations, Part 43 and in respect to	Return to Se sotherwise sp 12 was accom 3 and in respective	ervice [] (Decified in Bloc oblished in according to that work or the work or that work or that work or that work or the work	a. [X] 14 CFR 43.9 Return to Service [] Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to se	a. [X] 14 CFR 43.9 Return to Service [] Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to service.	
13b. A	13b. Authorized Signature: Not Applicable	13c. Approval Autho Not Applicable	13c. Approval Authorization No.: Not Applicable	14b. Authorized Signature:	nature:	14	14c. Approval/Certificate Number: S7HR883J	ate Number:	
13d. N	13d. Name (Typed or Printed): Not Applicable	13e. Date (dd/mmm/yyyy): Not Applicable	ommíyyyy): cable	14d. Name (Typed or Printed:) Carl E. Schutte	r Printed:)	-	14e. Date (dd/mmm/yyyy): 22/Dec/2020		

User/Installer Responsibilities

It is important to understand that the existance of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an Aiworthiness Authority of the country specified in Block 1, it is essential that the user/installer ensure that his/her Aiworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Aiworthiness Authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER

DATE	CUSTOMER PO#	WORK ORD	ER#	
12/22/20	0317	86751		
Mfr: Slick	Desc · Magneto	Part No.: 6351	Serial No.: 15060589	Work Order No.: 86751

Received Magneto for 500 Hour Inspection:

1 ea P/N 6351 S/N 15060589

Disassemble, clean and inspect. Noted both rivets loose on impulse coupling - fails per SB2-19A. C/W 500 Hour Inspection per Section 3.3 of Manufacturer Manual L-1363G, Rev G dated Oct 30 2017 and SB2-80-C. Distributor block reconditioned. Parts replaced as listed. Magneto assembled, internally timed and tested.

The following parts have been replaced in this unit:

1 ea A-13081

Contact & Cam Kit

1 ea AM-3215

Carbon Brush

In addition to 500 Hour Inspection the following was required:

1 ea M-3333

Impulse Coupling

AD / SB STATUS:

AD 81-16-05 Coil - N/A MAG MOD #

SB1-80-A Soft Rivets (447, 600, 4200 & 6200) AD 80-06-05 - N/A MAG MOD #

SB2-80-C Maintenance Schedule (400/600, 4000/6000, 4200/6200, 4300/6300) - 500 HOUR INSPECTION

SB3-80-B Broken Flanges, All Magnetos - SUPPLY COPY TO CUSTOMER

SB1-83-A Index Plate - IN COMPLIANCE

SB1-86-C Impulse Coupling Inspection - C/W INSPECTION; INSTALLED NEW IMPULSE COUPLING DOM 11-20-20

SB1-88-A / AD 88-25-04 Insp Models 6220 & 6224 Pressurized - N/A MAG MOD #

SB1-88-B / AD 88-25-04 Insp Models 6300 Pressurized - N/A MAG MOD #

SB2-88-A Bearing Inspection (4200) - N/A MAG MOD #

SB3-88-A Bearing Inspection (6200) - N/A MAG MOD #

SB1-89-B Maintenance Schedule (Single Ignition Sys) - N/A APPLICATION

SB1-95 Replacement (4000 & 4100) - N/A MAG MOD #

SB1-98-A / AD 99-04-04 Impulse Coupling Inspection (6200 & 6300) ea 250 Hrs. - C/W, INSTALLED NEW M-3333 11-20-20

SB1-00C / AD 2011-26-07 (Some 6300) Impulse Pin - N/A MAG MOD #

SB1-07 Insp Mag Driver / Torque Requirements (4309, 4310) - N/A MAG MOD #

SB2-07 Insp Mag Driver / Torque Requirements (Lasar) - N/A MAG MOD #

SB3-07 Impulse Coupling Assy (Some 4300) - N/A MAG MOD #

SB2-08B Contact Cam 4300/6300 & Lasar - C/W INSPECTION INSTALLED NEW, PMA MFR, NFA

SB3-08B Carbon Brush or Dist Block 4300/6300 & Lasar - C/W INSPECTION INSTALLED NEW, PMA MFR

SB1-12 Defective Contacts (M3081 Contact Kits) - N/A, INSTALLED NEW, PMA CONTACTS

SB-009 Tempest Contacts - N/A DATE CODE; A-13081 11-3-20

SB1-15A Distributor Gear Assy (4 Cyl) - N/A MAG MOD #

SB03-7A IO240 Series Mag Drive Gear (4309, 4310) - N/A MAG MOD #

SL 1-17 Drive End Nut Torque (Impulse) - C/W

SB1-19 Impulse Coupling Stop Pin - N/A MAG SERIAL #

SB2-19A Impulse Coupling - C/W, INSTALLED NEW IMPULSE COUPLING; M-3333 MFR DATE 11-20-20

2482 Progress Drive Redding, CA 96001-3235 (530) 221-4397 (530) 221-0660 fax Repair Station #S7HR883J

The aircraft component identified above was repaired and Inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service.

FAA REPAIR STATION NO. S7HR883J

Inspector:

Airworthiness Directive Compliance Report

Date of Report: 07/16/2021

Tail Number: N413CS

Prepared For:

Manufacturer/ Model: Textron (Cessna) 182T

Single / Left Engine: Lycoming IO-540-AB1A5

Right Engine:

Single / Left Propeller: McCauley B3D36C431

Right Propeller:

Notes:



Prepared By:

Bryan Whitfield Sierra Aero LLC 10356 Truckee Airport Rd, Hangar #1 Truckee, CA 96161 530-359-5751

Preparer's Signature

The AD Tocloox - Assembled By Zock Aviation, Inc.

Make Model

Textron (Cessna) 182T

Airframe Hours: Tach: 973.4

Misc:

Engine: Lycoming IO-540-AB1A5

Propeller: McCauley B3D36C431

Tail # N413CS

Serial # 182-82413

Airworthiness Directi Compliance Rep

S/N: I-36360-48E

S/N: 150645

Hours: Hours:

AD#	Category	Subject		Amend #	Eff Date	Rec	Remarks
Date/Hours	Compliance	Novt Duo	1 Marca	6			

Bryan Whitfield

Bryan Whitfield

Bryan Whitfield

Bryan Whitfield

Bryan Whitfield

	AD# Date/Hours Co	Category	Subject Next Due	Name	Amend #	Eff Date	Rec	Remarks	STREET AND		
	Airframe:	Textron (Ce	ssna) 182T		- gratero	OUTER		- A	Class men sa	100	(4-0)
_	04-15-18	Airframe	KAP 140 Autopilot					-			
100	MATERIAL SECTION	ATE OF STREET	TOUR 140 Autoprior	Bryan Whitfield	39-13752	09/12/04		N/A by Serial No.	the state of the best of	By habaki	Prepatter
	05-05-53 R1	Airframe	Flight Control System Pro			234330217	100 1 14 11 17 21	E. Christinian Street		A1074	Virginity for the same
			riigik Control System Fit	Bryan Whitfield	39-14021	03/21/05		N/A by Serial No.			
	05-13-10	Airframe	Incorrect Circuit Breakers		39-14147	2549302IA				*	
			moored Circuit Digardis	Bryan Whitfield	39-14147	08/09/05		N/A by Serial No.	atom sine	- Approxis	nor slige a
	07-05-10	Airframe	Crew Seat Back Cylinder		39-14971	2549302IA 04/11/07					2 0114
				Bryan Whitfield	39-149/1	2549302IA		N/A by Serial No.		*2011/11/19	84-1-04
1	07-08-03	Airframe	Fuel Hose Connections	Diffun triminolo	39-15020	05/02/07		NA L. C. LIN	~		
W	<u> </u>			Bryan Whitfield	33-13020	2549302IA		N/A by Serial No.	. /		
	08-02-18	Airframe	BRS Parachute System F		39-15348	02/28/08		N/A by Data			
			and Retaining Screws	The opening copport	03-10540	02/20/00		N/A by Date			
				Bryan Whitfield		2549302IA					
	08-05-09	Airframe	Seat Base/ Back Attach B	Brackets	39-15403	04/08/08		N/A by Serial No.			
				Bryan Whitfield		2549302IA		El			
	08-10-02	Airframe	Alternate Static Air Source	e Selector Valve	39-15508	05/12/08		N/A by Serial No.			
				Bryan Whitfield		2549302IA					
	08-26-10	Airframe	Alternate Static Air Source	e Selector Valve	39-15776	01/05/09		N/A by Date			
	40.44.44			Bryan Whitfield		2549302IA		5+ 540-54-44-44-45-45-45-55			
	13-11-11	Airframe	Engine Oil Pressure Switch	ch	39-17471	08/01/13	Yes	N/A by Serial No.			
				Bryan Whitfield		2549302IA					
	Engine: Lu		40 40445							1 DOMESTIC	Wall of the Sa
_	Engine. Ly	coming IO-5	4U-AB1A5					JE .			
	63-14-03	Engine	Oil Pump Drive Shaft	to recommended (Preside	583	07/06/63	Yes*	N/A by Engine Ma	nufacture Date		The Control
				Bryan Whitfield		2549302IA					
	66-20-04	Engine	Oil Filter Adapter Gasket		39-277	08/27/66		N/A by Engine Ma	nufacture Date		
				Bryan Whitfield		2549302IA					
	75-08-09	Engine	Oil Pump Drive Shaft and	Impeller	39-3013	08/18/77		N/A by Engine Ma	nufacture Date		
				Bryan Whitfield		2549302IA					
	75-09-15	Engine	Bendix Fuel Injector Flow	Divider Cover Gasket	39-2187	04/30/75		N/A by Engine Ma	nufacture Date		
				Bryan Whitfield		2549302IA					
	78-23-10	Engine	Bendix RSA Series Fuel In	njector Bellows Seal	39-3333	11/07/78		N/A by Engine Ma	nufacture Date		
				Bryan Whitfield		2549302IA					
	79-04-05	Engine	Bendix RSA Series Fuel In	njectors Diaphragm	39-3570	09/26/79		N/A by Engine Ma	nufacture Date		
				Bryan Whitfield		2549302IA					
	92-12-05	Engine	Piston Pin Failure		39-8265	07/10/92		N/A by Engine Ma	nufacture Date		
				Bryan Whitfield		2549302IA				0	
	93-11-11	Engine	Diaphragm Fuel Pumps O	verhauled (by AAI)	39-8584	06/21/93		N/A by Engine Ma	nufacture Date		
1				Bryan Whitfield		2549302IA					
	96-09-10	Engine	Oil Pump Impeller Failure		39-9586	07/15/96		N/A by Engine Mar	nufacture Date		
				Bryan Whitfield		2549302IA					
	96-23-03	Engine	High Pressure Fuel Pump		39-9826	12/17/96		N/A by Engine Mar	nufacture Date		
				Bryan Whitfield		2549302IA					
	98-17-11	Engine	Crankshafts Installed by N		39-10713	10/19/98		N/A by Engine Mar	nufacture Date		
			110000000000000000000000000000000000000	Bryan Whitfield		2549302IA					
	02-19-03	Engine	Crankshaft Failure		39-12883	09/20/02		N/A by Engine Mar	nufacture Date		
				Bryan Whitfield		2549302IA					
	03-14-03	Engine	Rotary Fuel Pump Leaks	we constitute that the second	39-13222	08/14/03	Yes*	N/A by Engine Mar	nufacture Date		
				Bryan Whitfield		2549302IA					
	04-05-24	Engine	Crankshaft Gear Retaining		39-13519	03/30/04		N/A by Engine Mar	nufacture Date		
				Bryan Whitfield		2549302IA					1 1 to 3 to 3 to 6 to 6 to 6 to 6 to 6 to 6
	04-10-14	Engine	Crankshaft Gear Retaining		39-13644	06/25/04		N/A by Engine Mar	nufacture Date		
				Royan Whitfield		254020214					

2549302IA

2549302IA

2549302IA

2549302IA

2549302IA

Yes*

N/A by Engine Manufacture Date

10/21/05

07/11/06

05/07/07

02/09/09

39-14276

39-14632

39-15005

39-15793



05-19-11

06-12-07

07-04-19 R1

09-02-03

Engine

Engine

Engine

Engine

Crankshaft Failures

ECi Cylinder Assemblies

Superior Air Parts Cylinder Assemblies

RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket

09-26-12 25:	Engine, own	ECI Cracked Cylinder Assemblies Bryan Whitfield	39-16151	02/04/10 Yes 2549302IA	N/A by Engine Manufacture Date
12-03-06	Engine	AVStar Fuel Servo Diaphragm Bryan Whitfield	39-16947	02/24/12 2549302IA	N/A by Engine Manufacture Date
12-19-01	Engine	Crankshaft Replacement Bryan Whitfield	39-17196	10/24/12 2549302IA	N/A by Engine Manufacture Date
15-19-07 07/16/2021 @	Engine Tach: 973.4	Fuel Injector Fuel Lines and Clamps Due @ Tach: 1083.4, or Bryan Whitfield whenever fuel injector lines/clamps disconnected, moved or loosened and/or every annual	39-18269	11/03/15 Yes	07/16/2021 @ Tach: 973.4 - C/W by inspection of fuel lines and clamps discrepancies notes. Due every 110 hrs. or whenever fuel injector lines/clamps disconnected, moved or loosened.
17-16-11	Engine	Connecting Rod Failure Bryan Whitfield	39-18988	08/15/17 2549302IA	N/A by Serial No.
Propeller:	McCauley B	3D36C431	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	er (Mercula Fillator Photosocia)	Supplemental and the desired and the annual state of the second of the s
	THE RESERVE OF THE PARTY OF THE			20147105	MA have an along and smed by Couthern Colifornia Propoller
05-14-11	Propeller	Southern California Propeller Serviced Propeller Bryan Whitfield	rs 39-14188	08/17/05 2549302IA	N/A by no services performed by Southern California Propeller
05-14-11	Propeller -	Bryan Whitfield	s 39-14188		N/A by no services penormed by Southern California Properlet
05-14-11		Bryan Whitfield			desirent mentera te appui pari a procesa de catalogo

English to the goldens of the shifter

endj. (3