

2478 Wilcox Road • Stockton, CA 95215 (800) 749-PROP • (209) 982-4000 • Fax (209) 982-1240 FAA Aproved Repair Station No. UD7R333Y

Propeller Logbook

Propeller Maintenance Record

Propeller Make_	McCauley	Position
Propeller Model_	10160 DTM 7557M1	Aircraft Manufacturer Cessna
Propeller S/N	730079	Aircraft Model 17210
Blade Design		S/N 17268677
Blade S/N's		Registration N733ZK
No. 1		
No. 2		Pitch Range
No. 3		1 Item Range
No. 4		High/Feather
No. 5		Start Lock
		Low
No. 6		


N733ZK 12-19-2014 Tach:7812.4 SPOH:142.3

This propeller has been inspected in accordance with annual inspection per FAR 43 Appendix "D"

Removed and replaced front Bulkhead spinner P/N U0550321-4 with serviceable used unit. Torqued propeller and re safety wired IAW Cessna M.M.

I certify that this propeller has been, inspected per annual and was found to be in airworthy conditions and is approved to return to service IA #2802232 ALLI

escription of all operations pertaining to Airworthiness Dir ice Doucuments, Overhaul, Major or Minor Repair, and In



		• • • •	
6			
PROP MODEL: DTM7557 PROP S/N: 730079	Rossi Aircraft, Inc.	DATE: 4/17/2015 A/C TSN: 7839.5 PROP TT: 0	Directives,
REG. NO: N733zk WORK ORDER: 2258	Repair Station No. ZRSR378L 1903 Embarcadero Rd Palo Alto, CA 94303	TACH: 7839.5	Inspections.
	Phone: 650-493-3326		
Prop Entries			The Part of the Pa
Propeller removed and or	verhauled by Sullivan Prop. Details of OH on file with	Sullivan WO#9898. Front and rear bulkneads	
roplaced with new because	verhauled by Sullivan Prop. Details of OH on file with se of cracks. Installed repainted spinner Performed	a dynamic propeller palatice. Add 132 granis s.	
replaced with new because weight to Stan to a final re	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered in accordance.	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer	
replaced with new because weight to Stan to a final re	se of cracks. Installed repainted spinner Performed	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer	
replaced with new because weight to Stan to a final re	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered in accordance.	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer	
replaced with new because weight to Stan For Rim De 5 i.p.s to a final re Model 192A Manual No. A Authorizing Signature:	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered in accordance.	tered on propeller to correct the dynamic balance from the with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 2268 on file.	
replaced with new because weight to Stan For Rim De 5 i.p.s to a final re Model 192A Manual No. A Authorizing Signature:	The location of static balance weights has been altered by Alberto Rossi A & P No. 3402723. Work Performed in accordance weights has been altered by Alberto Rossi A & P No. 3402723. Work Performed in accordance weights have been altered by Alberto Rossi A & P No. 3402723. Work P No. 3402723.	tered on propeller to correct the dynamic balance from the with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 2268 on file.	
replaced with new because weight to Standard Inc. Inc. sto a final removed in p.s. to a final remove in p.s. to a final removed in p.s. to a final remove in p.s. to a fi	se of cracks. Installed repainted spinner Performed to the location of static balance weights has been altered in judgments. In p.s. All work performed in accordance AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other less on N733zk was repaired and inspected in accordance with the location of t	tered on propeller to correct the dynamic balance from the with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. The rotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered in accordance (AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other (Is) on N733zk was repaired and inspected in accordance with service. Pertinent details of the repair are on file at this respective.	tered on propeller to correct the dynamic balance from the with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015.	
replaced with new because weight to Standard Inc. Inc. sto a final removed in p.s. to a final remove in p.s. to a final removed in p.s. to a final remove in p.s. to a fi	se of cracks. Installed repainted spinner Performed to the location of static balance weights has been altered in accordance (AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other (as) on N733zk was repaired and inspected in accordance with service. Pertinent details of the repair are on file at this results of the repair are on file at this results.	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015. Work Order: 2258	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered in accordance (AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other (Is) on N733zk was repaired and inspected in accordance with service. Pertinent details of the repair are on file at this respective.	tered on propeller to correct the dynamic balance from the with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015.	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed to the location of static balance weights has been altered in accordance along of i.p.s. All work performed in accordance along the location of	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015. Work Order: 2258	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed to the location of static balance weights has been altered in accordance along of i.p.s. All work performed in accordance along the location of	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015. Work Order: 2258	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered and in accordance (AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other (as) on N733zk was repaired and inspected in accordance with service. Pertinent details of the repair are on file at this results of the repair are on file at this results. Certified Repair Station No. ZRSR378L	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015. Work Order: 2258	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered and in accordance (AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other (as) on N733zk was repaired and inspected in accordance with service. Pertinent details of the repair are on file at this results of the repair are on file at this results. Certified Repair Station No. ZRSR378L	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015. Work Order: 2258	
replaced with new because weight to Signature i.p.s to a final removed in the second s	se of cracks. Installed repainted spinner Performed The location of static balance weights has been altered and in accordance (AW9511-1 by Alberto Rossi A & P No. 3402723. Work added weights must be removed if propeller or other (as) on N733zk was repaired and inspected in accordance with service. Pertinent details of the repair are on file at this results of the repair are on file at this results. Certified Repair Station No. ZRSR378L	tered on propeller to correct the dynamic balance from e with Chadwick-Helmuth Co., Inc Spectrum Analyzer rk order No. 268 on file. Trotating mass is altered or changed. The current FARs rules of the Federal Aviation Regulations and repair station under Work Order No. 2258, Dated 4/17/2015. Work Order: 2258	



SUBURBAN AIR

CORPORATION

21599 Skywest Drive Hayward, California 94541 (510) 780-0428

PROPELLER ENTRY

ectives. spections.

JOB: 3417 AIRCRAFT: N733ZK TACH: 8033.4 TSOH: 193.9


MODEL: 1C160/DTM7557M1 S/N: 730079

DATE: 1-7-2016

Inspected propeller. No defects noted at this time. Verified AD's current through AD 2005-14-11. -----END-----

I certify that this propeller has been inspected in accordance with FAR 43 Appendix D (Annual Inspection) and has been determined to be in an airworthy condition.

Scott D Franges A&P 3393208 IA



1903 Embarcadero Road, Palo Alto, CA 94303

650-494-6516 www.advantage-ariation.com

WO: 3255 Aircraft: N733ZK Tach: 8049.3 Date: 17 February 2016


s/n 730079 Model: McCauley 1C160/0TM 75557M1

Propeller Entry

Removed propeller to facilitate crankshaft seal removal. After replacing crankshaft seal, reinstalled prop, torqued prop bolts and safety wired. Ground ran engine, leak check good, no defects noted at this time. - END

This Propeller is approved for return to service only for the work performed and stated above in this entry.

Charles Harvie A&P 3517275



TSI Craft 1903 Embarcadero Road,





Palo-Alto CA 94303, 650-494-6516

Date: 3 November 2016 TSN: TSO: 523.1 Aircraft: N733ZK Tach: 231.3

Model: McCauley 1C160/DTM7557M1 S/N: 730079

Propeller Entry

Completed Annual Inspection. Inspected propeller hub, prop blades, and spinner assy. Found spinner bulkhead cracked. Replaced with new, p/n 0552231.1. Reinstalled prop, torque bolts and safety wired. - END

I certify that this propeller has been inspected in accordance with FAR 43 Appendix D (Annual Inspection) and has been determined to be in an airworthy condition.

James Allen A/P / IA 559294160

www.advantage-ariation.com

Reechcraft 1903 Embarcadero Road,



650-494-6516 Palo Alto, Calif., 94303

Date: 17 March 2017 Aircraft: N733ZK Tach: 359.7 TSO: 651.5 TTP: Model: McCauley 1C160/DTM7557M1

Propeller Entry


Inspected propeller blades, hub, and spinner assembly. Found spinner forward bulkhead cracked, replaced with new, p/n 0552231-1. Reinstalled prop with new washers, p/n A1638-11. Torqued and

safetywired prop bolts. No other defects noted. - END I certify that this propeller has been inspected in accordance with FAR 43 Appendix D (100 hour inspection)

and has been determined to be in an aipworthy condition.

James Allen A/P 559294160

www.advantage-aviation.com



N737ZK

SERVICEABLE

PROPELLER

Unit Name

MCCAULEY

Manufacturer

1C160/DTM7557 M1

730079

Model

Serial

The propeller or appliance identified above was repaired/overhauled and inspected in accordance with the 730720

overhaul manual and current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under:

ADVANTAGE AVIATION

Owner Name

Work Order Number

Date



SULLIVAN PROPELLER SPECIALISTS 2156 American Avenue Hayward, CA 94545 tel: 510.782.0920 fax: 510.264.9162



Palo Alto, Calif., 94303 650-494-6516

Date: 8 August 2017 TTP: (unknown) TSO: 0.2 S/N: 730079 IcCauley 1C160/DTM7557M1

Propeller Entry

ection and repair (stone, wind abrasion, and peeling paint). Reinstalled eller Specialists, Hayward, Calif. FAARS#S5UR963J, under W/O# 10709, neads with new, p/n 0550321-4 and p/n 0550321-12. Reinstalled prop with d safetywired prop bolts. Engine ground run and flight test good. - END eturn to service only for the work performed and stated in this entry.

www.advantage-ariation.com



Palo-Alto-CA 94303, 650-494-6516

Date: 22 December 2017 TSO: 34.0 TSN: (unkown) ach: 453.6 McCauley 1C160/DTM7557M1 S/N: 730079

Propeller Entry

ed propeller hub, prop blades, and spinner assy. No defects found. - END spected in accordance with FAR 43 Appendix D (Annual Inspection) an

www.advantage-arietion.co




Palo-Alto- CA 94303, 650-494-6516

570.2 TSO: 150.6 TSN: (unknown at this time) Date: 2 November 2018 Cauley 1C160/DTM7557M1 S/N: 730079

Propeller Entry

ropeller hub, prop blades, and spinner assy. No defects found cted in accordance with FAR 43 Appendix D (Annual Inspection) and condition.

www.advantage-aviation.com



46	7/24/2019 Tach: 670.6 SPOH: 250.8	book Entry			N733ZK 1C160/DTM7557 s/n 730079	Date
	per an ANNUAL and	es Maintenance Manual & FAR 43, Apply this Propeller has been inspected per anceend	k painted blades. I	9-13. Dressed &	checked thru Issue 201	
-	A 7/24/2019	Chris Camph 3568328 IA				
		0 8/25/20				
			Cro;			

A