

**BEN'S MOTORWORKS**

4119 W Commonwealth Ave, Hangar D28, Fullerton, CA 92833  
714-396-6090

# INVOICE

**BILL TO**

WWJ Corp  
Edd Lombard  
3 Widefield Blvd  
Colorado Springs, Co  
80911 USA  
Tach 3469.06

**INVOICE # 1056****DATE 08/16/2017****DUE DATE 08/16/2017****SHIP DATE**

08/16/2017

**N NUMBER**

N 624 P

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	Hourly Service	Trouble shoot charging system, Remove cowling, Remove generator and regulator for testing and repair, Reinstall regulator and generator after repair. Test and reinstall cowling	3	85.00	255.00
					0.00
		Customer paid Aero Accessories directly			0.00

**PAYMENT**

255.00

**BALANCE DUE****\$0.00**

**BEN'S MOTORWORKS**

4119 W Commonwealth Ave, Hangar D26, Fullerton, CA 92833  
714-396-6090

**INVOICE****BILL TO**

WWJ Corp  
Edd Lombard  
3 Widefield Blvd  
Colorado Springs, Co  
80911 USA  
Tach 3469.06

**INVOICE # 1428****DATE 08/30/2018****DUE DATE 08/30/2018****SHIP DATE**

08/30/2018

**NUMBER**

1624/P

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	Annual Comanche	Annual Comanche	1	1,300.00	1,300.00
	AD 2012-17-06	AD 2012-17-06 Install Australian Kit	1	1,800.00	1,800.00
	Hourly Service	Replace interior brake hoses, Bleed and flush brakes, after hose replacement	1.25	90.00	112.50
	Hourly Service	Repair Broken ground on LH magneto P lead, Trouble shoot engine not turning off. Clean and lubricate the inside of the switch.	2	90.00	180.00
	Hourly Service	Replace engine hoses and the interior brake hoses	3	90.00	270.00
	Hourly Service	Replace all 4 rubber engine mounts	4	90.00	360.00
	Hourly Service	Service all 3 struts with fluid and air	0.75	90.00	67.50
	Hourly Service	replace seat belts	0.50	90.00	45.00
	Hourly Service	spray corrosion x in the empennage where water	0.25	90.00	22.50

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		had been leaking on to the stringers and ribs it was starting to corrode			
	Hourly Service	Replace broken hose clamp on the carb heat ducting and re riveted the duct.	0.50	90.00	45.00
	Hourly Service	Replace LH steering boot with new	1	90.00	90.00
					0.00
	CH48110-1	CH48110-1 oil filter	1	32.00	32.00T
	BA-3205	BA-3201 Air Filter	2	16.95	33.90T
	AEROP100W Plus	100W AeroShell oil	10	8.83	88.30T
	J-3804-20	J-3804-20 Lord Rubber engine mount	4	199.48	797.92T
	21378-00	21378-00 Steering boot	1	75.00	75.00T
	Seat belts	Seat Belts	2	95.00	190.00T
	AE3663231E0083	AE3663231E0083 hose	1	54.74	54.74T
	AE3663231E0104	AE3663231E0104 hose	1	59.98	59.98T
	AE3663161B0075	AE3663161B0075 Hose	1	80.40	80.40T
	AE3663161G0227	AE3663161G0227 Hose	2	118.51	237.02T
	AE3663162G0143	AE3663162G0143 Hose	1	135.90	135.90T
	AE3663161H0484	AE3663161H0484 Hose	1	246.46	246.46T
	AE3663161H0492	AE3663161H0492 Hose	1	250.26	250.26T
	359-2D0082	359-2D0082 Hose	1	48.96	48.96T
					0.00
	Shipping	Shipping hoses both ways	1	30.00	30.00
	Shipping	mounts and boots	1	15.00	15.00
SUBTOTAL					6,668.34
TAX (7.75%)					186.47
TOTAL					6,854.81
PAYMENT					6,854.81
BALANCE DUE					\$0.00



**BEN'S MOTORWORKS**

4119 W Commonwealth Ave, Hangar D28, Fullerton, CA 92833  
714-396-6090

**INVOICE****BILL TO**

WWJ Corp  
Edd Lombard  
3 Widefield Blvd  
Colorado Springs, Co  
80911 USA  
Tach 3469.06

**INVOICE # 1860****DATE 12/09/2019****DUE DATE 12/09/2019****SHIP DATE**

12/09/2019

**N NUMBER**

N 624 P

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	<b>Annual Comanche</b>	Annual Comanche	1	1,300.00	1,300.00
	<b>Hourly Service</b>	Replace the battery, Install battery charger interface kit in the baggage compartment.	1	90.00	90.00
	<b>Hourly Service</b>	Replace the ignition switch assembly with new ACS switch	1	90.00	90.00
	<b>Hourly Service</b>	CW AD 77-13-21 bungee replacement, Service the struts with air and fluid	3	90.00	270.00
	<b>Hourly Service</b>	Dress the propeller	0.25	90.00	22.50
	<b>Hourly Service</b>	Tighten #6 oil return coupling, Stop drill several cracks in the baffling in the engine compartment,	0.50	90.00	45.00
	<b>Hourly Service</b>	Adjust the rudder cable tensions	0.75	90.00	67.50
	<b>Hourly Service</b>	Replace the shimmy Dampener bracket and eye bolt, replace the Nose gear door actuator arm eye bolt and clevis	1	90.00	90.00

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
					0.00
					0.00
					0.00
	<b>AEROP100W Plus</b>	100W AeroShell oil	3	8.83	26.49T
	<b>402-032</b>	402-032 Eye bolt	1	8.95	8.95T
	<b>11601-003</b>	11601-003 Shimmy Dampener Eye Bolt	1	89.99	89.99T
	<b>W21709-000M&amp;L</b>	W21709-000M&L Shimmy Dampener Bracket	1	35.99	35.99T
	<b>21831-003</b>	21831-003 Bushing, Shimmy Damper	1	51.42	51.42T
	<b>Shipping</b>	Shipping Piper parts listed above	1	16.88	16.88
	<b>128CEC1-AA-S5</b>	128CEC1-AA-S5 Battery charger, Approved for aircraft	1	229.90	229.90T
	<b>BM-AIK2A</b>	BM-AIK2A Battery interface kit	1	65.95	65.95T
	<b>RG-35AXC</b>	RG-35AXC	1	363.83	363.83T
	<b>A-510-2</b>	A-510-2 Ignition Switch	1	187.75	187.75T
	<b>451-359</b>	8097 Landing Gear Bungee Cord	2	89.07	178.14T
	<b>BA-3205</b>	BA-3201 Air Filter	1	16.95	16.95T
<b>SUBTOTAL</b>					3,247.24
<b>TAX (7.75%)</b>					97.29
<b>TOTAL</b>					3,344.53
<b>PAYMENT</b>					3,344.53
<b>BALANCE DUE</b>					<b>\$0.00</b>

**BEN'S MOTORWORKS**

4119 W Commonwealth Ave, Hangar D28, Fullerton, CA 92833  
714-396-6090

**INVOICE****BILL TO**

Edd Lombard

WWJ Corp

3 Widefield Blvd

Co

Tach 3469.06

Colorado Springs, CO

80911

USA

**INVOICE # 2449****DATE 09/07/2021****DUE DATE 10/01/2021****TERMS Due on receipt****N NUMBER**

N6244P

**TACH TIME**

3488.7

**PAID**

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	Annual Comanche	Annual Comanche	1	1,300.00	1,300.00
	CH48110-1	CH48110-1 oil filter	1	34.93	34.93T
	BA-3205	BA-3201 Air Filter	1	22.06	22.06T
	Spark plug gasket	M674 Spark plug gasket	12	0.42	5.04T
	AEROP100W Plus	100W AeroShell oil	11	9.99	109.89T
	91.207D ELT Test,	FAR 91.207D Elt Inspection, Replace battery pack with new. New Due date is Aug 2023	1	100.00	100.00
	BP-1010	BP-1010 ELT battery	1	45.99	45.99T
	Hourly Service	The stall warning circuit breaker keeps popping. We also noticed the Warning light is falling out of the instrument panel. I suspect that when the light is put back into place the breaker will stop popping.	0.50	100.00	50.00
	Hourly Service	Adjust the idle and and	0.25	100.00	25.00



DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		mixture settings. The idle is too high and there is no rise when you pull the mixture back.			
	Hourly Service	Dress the propeller	0.25	100.00	25.00
	Hourly Service	replace the bushings in both RH and LH Lower torque links then Line hone. Reassemble with new hardware.	1.50	100.00	150.00
	W20737-002	W20737-002 Torque link bushing	12	19.95	239.40T
	Hourly Service	reseal the RH strut assembly. the wiper seal is coming apart	1.50	100.00	150.00
	Strut kit Piper	Strut kit Piper	1	32.95	32.95T
	5606	5606 Hydraulic fluid	0.25	37.72	9.43T
	Hourly Service	Replace the nose gear steering rollers with new. yours are excessively worn. The book calls out .010 clearance. you have approx. .187 clearance.	0.75	100.00	75.00
	14175-113	14175-113 Nose gear steering bushing	2	89.65	179.30T
	Hourly Service	Reseal the hand brake. there is fluid all down the inside of the belly and we can see fluid dripping from it.	1	100.00	100.00
	MS28775-211	MS28775-211 O ring	1	2.99	2.99T
	MS28775-113	MS28775-113 O ring	1	1.25	1.25T
	MS28775-012	MS28775-012 O ring	1	1.25	1.25T
	MS28775-010	MS28775-010 O ring	1	1.20	1.20T
	Hourly Service	Replace the nose gear Retract arm bushings and bolts	1	100.00	100.00
	14843-018	14843-018 nose gear drag link bushing.	7	21.60	151.20T
	22066-000	22066-000 Close tolerance pivot bolt	2	45.00	90.00T
	Hourly Service	Replace both LH and RH drag link brace bushings and pins	6	100.00	600.00
	20737-005	20737-005 Side stud bushings	2	43.75	87.50T
	20737-006	20737-006 Side stud bushing	2	29.11	58.22T
	487-596	487-596 Side stud. new	2	328.80	657.60T

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		style			
	14843-030	14843-030 Bushing side stud	2	57.06	114.12T
	14843-016	14843-016 Drag link bushing	8	11.99	95.92T
	Hourly Service	Replace 1 landing gear drag link bushing/rod end bolt. Parts are discontinued and we are looking for more.	2	100.00	200.00
	Misc Hardware	AN8-34 bolt	1	12.95	12.95T
	Hourly Service	Aileron, flap and rudder system pullies are in pretty rough shape. replace	10	100.00	1,000.00
	41001-008	41001-008 Pulley	20	72.00	1,440.00T
	41001-003	41001-00 Pulley3	1	72.00	72.00T
	Hourly Service	Air box shaft bushings are getting loose. and several craks in the	2	100.00	200.00
	Misc expense	Send the air box out for rebuilding. It went to Joe Rogg. and air box specialist. This was out cost from him, No mark up	1	950.00	950.00T
	Shipping	Shipping	1	45.00	45.00
	Hourly Service	The wind screen is cracked and crazed bad. We have squawked it a few times and it is getting worse. You need to have it replaced ASAP. We would suggest Foothill Aviation for this. They are at Cable airport. (defer)	0	100.00	0.00
	Shipping	Shipping,Piper parts	1	45.93	45.93
	Hourly Service	Replace the nose gear upper housing with serviceable unit. we found yours to be cracked after we washed and degreased your gear with the steam cleaner.	3	100.00	300.00
	21715-000	Piper PA25 Nose Gear Housing. .Serviceable	1	390.00	390.00T
	IFR Pitot static check	IFR Pitot Static Check, Precise Pitot Static	1	350.00	350.00
	Hourly Service	Leach check the aircraft. Replaced all flexible pitot static lines and couplers. Replaced the Air speed indicator with overhauled	7	100.00	700.00



DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		unit. (invoiced from Precise pitot static, My cost)			
08/08/20	misc parts	Replacement airspeed indicator. Yours was not repairable. My cost from Global tech in Huntington Beach ca	1	612.18	612.18
SUBTOTAL					10,933.30
TAX (7.75%)					419.85
TOTAL					11,353.15
PAYMENT					11,353.15
BALANCE DUE					\$0.00



4119 W Commonwealth Ave, Hangar D28, Fullerton, CA 92833  
714-396-6090



## INVOICE

### BILL TO

Edd Lombard  
WWJ Corp  
3 Widefield Blvd  
Co  
Tach 3469.06  
Colorado Springs, CO 80911  
USA

N NUMBER  
N6244P

TACH TIME  
3493.9

INVOICE  
DATE  
TERMS  
DUE DATE

3351  
11/14/2023  
Due on receipt  
12/01/2023

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Annual Comanche	Annual Comanche	1	1,300.00	1,300.00
100W SAE 50	Aeroshell 100W	10	12.99	129.90T
AA48110-2 Oil Filter	TEMPEST AA48110-2 OIL FILTER	1	45.99	45.99T
AOA kit	AOA kit, oil analysis	1	24.99	24.99T
Spark plug gasket	M674 Spark plug gasket	12	0.75	9.00T
BA-3205	BA-3205 Air Filter	1	16.95	16.95T
05-01019	electric fuel pump gasket	1	12.99	12.99T
751-858	751-858 Gasket, Old style fuel pump.	1	35.00	35.00T
Shipping	shipping for the 751-858 gasket. The part is discontinued from Piper and had to come from a parts Wearhouse.	1	15.95	15.95
Hourly Service	Replace the ignition switch because the key had been lost.	1	120.00	120.00
A-510-2	A-510-2 Ignition Switch. KEY CODE 097	1	198.26	198.26T
91.207D ELT Test,	FAR 91.207D Elt Inspection	1	120.00	120.00
BP-1010	BP-1010 ELT battery New Due Date 12-2025	1	52.87	52.87T
AD 77-13-21 par b	AD 77-13-21 par b Piper landing bungee replacement	2	120.00	240.00
451-359	8097 Landing Gear Bungee Cord	2	89.07	178.14T
Hourly Service	Replace worn out cowl latch hinge pins. 1 was broken and 3 were worn almost to failure.	0.50	120.00	60.00
AN392-25	CLEVIS PIN	6	0.72	4.32T
MS24665-132	MS24665-132 Cotter pin	6	0.20	1.20T

Hourly Service	Stop drill several cracks in the cowling	0.25	120.00	30.00
Hourly Service	Adjust the elevator trim cable tension.	1	120.00	120.00
Hourly Service	Service the struts with fluid and air	2	120.00	240.00
5606	5606 Hydraulic fluid 1 gallon.	1	50.00	50.00T
Hourly Service	Install missing Diode for the starter solenoid.	0.75	120.00	90.00
Hourly Service	Tighten hardware for the torque links.	0.75	120.00	90.00
Hourly Service	Trouble shoot the engine making an intermittent tapping noise once the engine is running. Found the noise to be coming from Cylinder 1. with the stethoscope we could hear the noise from the exhaust valve lifter. Check the valve guide for freedom of movement. Test run the engine again. After fixing the loudest noise a lesser noise was heard from the #2 intake. Remove the #2 intake valve lifter and replace with new. Test run. The engine is no longer making the noise.	4.50	120.00	540.00
SL75906	SL75906. Valve cover gasket.	2	2.75	5.50T
15B21319	15B21319 Hydraulic Tappet Socket.	2	29.98	59.96T
SL78290	SL78290 PLUNGER ASS Y	2	101.92	203.84T
Detail	Color sand and buff the paint. Wash and wax the plane.	1	475.00	475.00
Hourly Service	R/R the front windscreen	7.50	130.00	975.00
misc parts	1 piece aircraft windshield. This was more or less a custom part. This aircraft originally came with a 2 piece windscreen. The original maker isn't around anymore. The one we thought would work was not the correct size. We had to have the original one duplicated. My cost was \$800.00	1	800.00	800.00T
IFR Pitot Static	IFR Pitot Static, Fix Leaks, Replace the encoder.	1	450.00	450.00T
misc parts	Encoder	0	0.00	0.00T

We have a new shipping address  
Ben's Motorworks  
2271 W Malvern Ave #384  
Fullerton Ca 92833

SUBTOTAL	6,694.86
TAX (7.75%)	176.62
TOTAL	6,871.48
PAYMENT	4,549.60

**BALANCE DUE \$2,321.88**

Pay invoice