

Damage history:

Gear up landing 2004, fully repaired; wind shear incident 2010 resulted in a hard landing, right MLG failure, & prop strike. Fully repaired by Beegles Aviation, Greeley Colorado.

Prop replaced. Engine tear-down & inspection performed by Western Skyways, Montrose Colorado.

All repairs were performed meticulously (e.g. -new landing gear spacers, washers, & other hardware replaced. Even though the right MLG was not damaged during the hard landing, both right and left MLG struts replaced and non-destructively inspected prior installation).

No gear extension problems since repaired.

(Details of all repairs documented in Airframe and Engine log books)