Scaplane Prop

5/10: 799714



EAST COAST PROPELLER SERVICE INC.

PROPELLER LOGBOOK

PROPELLER MAINTENANCE RECORD

LEFT ENGINE	RIGHT ENGINE
Hub Model	Hub Model
Blade Design 90DcA-10	Blade Design
Diameter	Diameter
Hub Ser. No	Hub Ser. No.
Blade Ser. Nos.	Blade Ser. Nos.
No. 1 PB119296	No. 1
No. 2 PB 119317	No. 2
No. 3	to to excite No. 3
No. 4	No. 4
No. 5	No. 5
PITCH RANGE	PITCH RANGE
High Low 11.3°	
Feather Reverse	Feather Reverse
Governor Model	HINTON HOLD HELD NOT HOLD NOT HOLD HELD HELD HELD HELD HELD HELD HELD HE

SERVICEABLE

CUSTOMER Lake Shore Aviation
MFG Mc Cauley
COMPONENT 2A34C2O3-C / 90 DCA-10
REMARKS Complete Overhaul, inspected, due penetrated magna
fluxed blades refinished assembled tested oil-filled reset
angles, checked track and Static balanced.
ANGLES AT 30" STA. LO: 11.3° HI: 24.8° FEA

RE MA MOI

1С то ве **ЈЕ**Б

> RE MA MO

JEI

EAST COAST PROPELLER SERVICE INC.

2079 Main Street Lititz, PA 17543 #E65R064Y

Blade 5/w: PB119294 PB119317

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

RIGHT ENGINE

	TACH	DESCRIPTION OF WORK	SIGNATURE
DATE	IIME	McCaulan Propeller Model 2A34	C203-C Made Design Market C203-C
5-11		McCauley Propeller Model 22439	Diameter 4 d. L
		5/2799714 was overhauled t	NIS CIAIT.
		See Yellow tag for details	2 44 2 - 10
		SEC LECTIONS THE SELECTION OF THE SECOND SEC	DIBUG DEL MOS
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		When Der Folf
	Total Barrey	MAINTENANCE RELEASE	No 2 I DITIZITE
		The component identified above was repaired	
	- W.P.	and inspected in A.W. regulations of the FAA	No. 3
		and was found ainworthy for return to service	No 4
		at this agency under work	The state of the
		10 4 ER-8514	
	SUWA	R IDDIS.	W PITCH RANGES
	1/ 1/ 20	I STORAT PER TH	ER SER
7		20, MAIN STRILL	1901597
-	POVENT	UTITZ DA 17543	9797
		LITTZ, PATON#	E65R064Y IsboM ronisvoo

REG#	N66003
MAKE	McCauley
MODEL	2A34C2O3-C
S/N	799714



LAKESHORE AVIATION MANITOWOC COUNTY AIRPORT 1815 FREEDOM WAY MANITOWOC, WI 54220 (920)-682-0043

ATE	4/21/2011	
TACH	2411	
SPOH	0	
31 O11 F		

THIS PROPELLER WAS INSTALLED ON AIRCRAFT N66003 CESSNA R172K S/N R1723000. RUN UP AND LEAK CHECK OK.

JEREMY TROUSIL

A&P 391849627 IA

REG#	N66003
MAKE	MCCAULEY
MODEL	2A34C2O3-C
S/N	799714



LAKESHORE AVIATION MANITOWOC COUNTY AIRPORT 1815 FREEDOM WAY MANITOWOC, WI 54220 (920)-682-0043

4/21/2011 DATE 2411 TACH 0 **TSPOH**

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY.

JEREMY TROUSIL

A&P 391849627 IA

REG#	N66003
MAKE	McCauley
MODEL	2A34C2O3-C
S/N	799714



LAKESHORE AVIATION MANITOWOC COUNTY AIRPORT 1815 FREEDOM WAY MANITOWOC, WI 54220 (920)-682-0043

8/1/2011 DATE 2460 TACH 49 **TSPOH**

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO

BE AIRWORTHY.

JEREMY TROUSIL

A&P 391849627 IA

MAINTENANCE RELEASE	4/2011 2560
Make McCauley	149
Model 2 A 34 (203-C	INED TO
Serial No. <u>799714</u>	627 IA
The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found airworthy for return to service for work performed. Pertinent details of therepair are on file at this agency under Work Order No. <u>ER. 9305</u> and complies with Airworthiness Directives and Service Bulletins listed here.	1/13/2012 2582 171
RESET Angles Chark Track & STATIC Balancello	d leak check
Manual No. mpc200R2 SPmooR	2/2012 2642
Total Time Brought forward Total Time Since O/H Brought forward	231
Date 4-9-12 Signed Signed	9627 IA
EAST COAST PROPELLER SERVICE INC.	Section of the second

REG#	N66003
MAKE	McCauley
MODEL	2A34C203-C
S/N	799714



LAKESHORE AVIATION MANITOWOC COUNTY AIRPORT 1815 FREEDOM WAY MANITOWOC, WI 54220 (920)-682-0043

DATE	11/21/2013
Tach	2717
TSMOH	306
	Hy the wall - W

I certify that this propeller has been inspected in accordance with a 100 hour inspection per FAR 43 App D and was determined to be airworthy.

Jeremy Trousil

A&P 391849627 IA

Alice of the	111.0		
N66003 4/	11/15	Tac H2766	
Icentify	That	this proper has been IN	Spected with it
100 hr =	spection	per for 43 app D and -	لاه ل
Frank A	thouti	- END-	
Frank	2 Kost		
5-	9-2016	TACH 2777	
The state of the s	and the second lives of	I CERTIFY THAT THIS PROPELLER	HXS BABN WSPACEN
		N ACCORDANCE WITH X 100 HOUR	
		APPENDIX D. AND FOUND AIRWORT	
		J.M Adlot Agr3320693	44

McCauley 2A34C203-C S/N 799714

LB Aero Services Inc 5101 Auburn St Hangar I-2 Rockford, IL 61107

11-07-2016 Tach 2850.4 Hobbs 1543.8 SPOH 439.4

Removed propeller to return N66003, a Cessna R172K, S/N R1723000, to landplane configuration.

Timothy M Gallagher A&P 3320693 IA

McCauley
2A34C203-C
S/N 799714

LB Aero Services Inc
5105 Auburn St Hangar I-2
Rockford, IL 61107

Tach 2889.4
SPOH 478.4

Installed propeller to return N66003 to seaplane configuration. Operation checks normal with no leaks noted.

Timethy M Gallagher A&P 3320693 IA

McCauley 2A34C203-C S/N 799714 LB Aero Services Inc 5105 Auburn St Hangar I-2 Rockford, IL 61107 06-01-2019 Tach 2889.4 SPOH 478.4

I certify that this propeller has been inspected in accordance with the scope and detail of McCauley Propeller Systems maintenance program for 100 hour inspections, and has been found to be in an airworthy condition.

Timothy M Gallagher A 3320693 IA

Airworthy Aviation LLC.	N66003 (Cessna R172k)
N6185 Resource Drive	July 1, 2020
Sheboygan Falls, WI 53085	s/n R1723000
920-467-8611	2895.25 Tach
Complied with Annual inspection IAV	V FAR 43.appx.D
	V FAR 43.appx.D spected in accordance with a Annual /100 to be in airworthy condition at this time.

McCauley 2A34C203-C S/N 799714

LB Aero Services Inc 5105 Auburn St Hangar I-2 Rockford, IL 61107

08-01-2021 Tach 2908.0 SPOH 497.0

I certify that this propeller has to Propeller Systems maintenance	peen inspected in ac	ccordance with the scope nour inspections, and has	and detail of McCauley been found to be in an
Propeller Systems maintenance airworthy condition.	1111	Mon	

Timothy M Gallagher A&F 3320693 IA

and the second second	producting the	to All Carried Balling	
The second secon			
6 1 1 1 1 1 1 1			
	A LONG TO SERVICE		
1		Y .	AT A L
		The second secon	

Hildt Aviation Bennington, LLC - 1563 Walloomsac Rd - Bennington, VT 05201 - 866-649-5296

N66003 January 22, 2024 SINCE OVERHAUL TACH: 2953.0 (TACH): 542.0

TENANCE DATA AS A GUIDE. CHECKED ADS SEE LISTING FOR DETAILS. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE IN AIRWORTHY CONDITION. With respect to the work performed, the propeller and/or component(s) was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and is approved for return to service. Details of work performed are on file with Hildt Aviation Bennington, LLC under work order: 2023-

COMPLIED WITH ANNUAL INSPECTION PER FAR 43 APPENDIX D USING MANUFACTURERS MAIN-

JAMIE HILDENBRANDT A&P IA 3039160

023.

Propeller - page 1 of 1