



**MEMPHIS
PROPELLER
SERVICE, INC.**

LOG BOOK

PROPELLER MAINTENANCE RECORD

Position FRONT

PITCH RANGE

Propeller Model 3A32C76-S-M-R

High/Feather

Propeller S/N 722075

Start Lock

Blade Design

Low

Blade S/N's

Reverse

No. 1 F75856YS

No. 2 K76403YS

Aircraft Manufacturer

No. 3 R1179YSC

Aircraft Model BEACH

No. 4

S/N CE-431

No. 5

Registration N1070W

No. 6

Spinner Assembly Part No.

THIS PROPELLER/COMPONENT HAS

~~BEEN OVERHAULED~~/REPAIRED AS

PER MAINTENANCE RELEASE TAG

UNDER WORK ORDER NO. 21921

DATED 05/04/2017

FOR: 3A32C76-S-M-R S/N 727075

MEMPHIS PROPELLER SERVICE, INC

OLIVE BRANCH, MISSISSIPPI

FAA C.R.S. # PI4R441M

BY: Tyler Williams

Tyler Williams, Inspector

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	N1070W Tach: 1430.9 05/03/21	TSIRAN: 319.3	Dressed blades. I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition. Rushing Aviation 703 Airport Rd. Marks, MS 38646
			Kevin Rushing IA3412822
	N1070W Old Tach: 1444.8 06/08/21	New Tach: 0.0 TSIRAM: 338.8	Installed new tachometer PN# D1-112-5025. Operation normal. Rushing Aviation 703 Airport Rd. Marks, MS 38646
			Kevin Rushing IA3412822

N1070W

Tach: 117.9

TSIRAN: 456.1

05/13/22

Dressed blades.

I certify that this Propeller has been inspected in accordance with
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation

703 Airport Rd.

Marks, MS 38646

Kevin Rushing

IA3412822

N1070W

Tach: 220.2

TSIRAN: 558.4

05/23/23

Dressed blades.

I certify that this Propeller has been inspected in accordance with
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation

703 Airport Rd.

Marks, MS 38646

Kevin Rushing

IA3412822