McCAULEY™

PROPELLER LOGBOOK

McCauley Propeller Warranty Policy

Dear Customer,

Congratulations on the purchase of your new McCauley propeller. Engineered with the customer in mind, it is designed to provide years of reliable and trouble-free service.

Scheduled maintenance or servicing of your McCauley propeller should be accomplished at your nearest McCauley Approved Service Station.

For location of the McCauley Approved Service Station nearest you, please call 1-316-831-4021 and ask for Product Support.

NOTE

Having work performed at a facility other than a McCauley Approved Service Station may void your warranty.

USE OF LOGBOOK

1. Proper maintenance of this logbook is the owner's responsibility. It is an important record designed for the owner's information and protection.

2. If the propeller is sold or installed on another aircraft, the logbook should be transferred with the propeller.

3. It is recommended that maintenance release tags and work orders be attached inside the back cover of this book. If a copy of the work order is not available, the repair station and work order numbers should be referenced in the logbook entry.

4. All Airworthiness Directives, Service Bulletins, and Service Letters have been complied with at the time of production.

CONTENTS

Installation History	3
Service History	4
AD's, Service Bulletins	11
Maintenance Release Tags	13

Owner Name ANGELO PETROPOLIS

Address 2032 TOWN AND COUNTRY DR.

SIERRA VISTA, AZ 85635-4947

Propeller Model B2D34C207-B

Blade Model G-78TCA-0

Hub Serial No. 071546

Blade Serial No. 1 ABI26227

2 ABI26228

3

4

INS

Date	Aircraft M
NOV 14 2007	THIS PROP
	NEW AT McC
	INSPECTED A
	ON THIS DAY

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
NOV 14 2007	THIS PROPELLER WAS MANUFACTURED	
	NEW AT McCAULEY PROPELLER SYSTEMS	1021
	INSPECTED AND FOUND TO BE AIRWORTHY	
	ON THIS DATE.	

MAINTENANCE & SERVICE HISTORY

Beegles
Aircraft Service, Inc.
Quality Service Since 1946

GREELEY, CO
REPAIR STATION BX4R092M
(970) 353-9200

02-27-08 Hobbs 230.20 Tach 4014.40 N52878 sn 177RG1297

Installed new McCauley propeller Model # B2D34C207-B/G-78TCA-0 sn 071546, Torqued and saftied as required.

This aircraft was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.
LIMITED TO THE WORK PERFORMED
Pertinent details on file at Beegles Aircraft Service, Inc., Greeley, CO.
Work Order # 10,799 CRS BX4R092M

Signed _____

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTEN

Date	Total Propeller Time	T Since
06/23/2008 Tach: 4052.5 Inspected propeller for security of at Darrell R. Noble IA526177036		
08/01/2008		

07/12/2009 Tach: 4152.4

Inspected propeller for security of atta and leaks as part of annual aircraft

inspection and found to be in an airwo

Darrell R. Noble IA526177036

~~07/12/2009 Tach: 4152.4 TSN: 339.4 STOH:~~

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
08/01/2008			Dressed & painted prop	Darrell R Noble
				A&P 526177036

06/23/2008 Tach: 4052.5
Inspected propeller for security of attachment, leaks and bolt torque.
Darrell R Noble
Darrell R. Noble IA526177036

07/12/2009 Tach: 4152.4

Inspected propeller for security of attachment, blade condition and leaks as part of annual aircraft

inspection and found to be in an airworthy condition.
Darrell R Noble
Darrell R. Noble IA526177036

Factory Service Bulletins On Pages 11 & 12

~~07/12/2009 Tach: 4152.4 TSN: 339.4 STOH: 1an~~

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
7-27-09		TACH 4163.0	DYNAMIC BALANCE PERFORMED	
			BY WARNER PROPELLER.	
			Starting imbalance at .16	
			And after DYNAMIC BALANCE	
			imbalance was slightly above	
			.1 Reinstalled cowling.	AP3787872495

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTEN

Date	Total Propeller Time	Sinc

7-27-09 Dynamicall
N52878. Dy
.6ips to .
4163.0

Warner Propeller & Go
FAA CRS W59R659N

08/05/2010 Tach: 4304.8
Inspected propeller for securi
torque.
Darrell R. Noble IA52617703

Note: Enter Compliance W

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
7-27-09			Dynamically balance propeller on N52878. Dynamic balance from .6ips to .1ips. Current Tach 4163.0	
			Warner Propeller & Governor Co., LLC FAA CRS W59R659N	
			08/05/2010 Tach: 4304.8 Inspected propeller for security of attachment, leaks and bolt torque. Darrell R. Noble IA526177036	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Sierra Vista Aviation Services, LLC
4535 Via Viento
Sierra Vista, AZ 85635
520-22-1759
svas@cox.net

N52878 Cessna 177RG S/N 177RG1297
McCauley B2D34C207-B SN 071546

09/24/2011 Tach: 4393.6

Propeller inspected for blade condition and security of attachment No leaks noted at this time. A.D. biweeklies checked thru this date.

I CERTIFY THAT THIS PROPELLER HAS BEENINSPECTED DURING AN **ANNUAL/100 HR** INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.

Darrell R. Noble IA3513071

Sierra Vista Aviation Services, LLC
4535 Via Viento
Sierra Vista, AZ 85635
520-22-1759
svas@cox.net

N52878 Cessna 177RG S/N 177RG1297
McCauley B2D34C207-B SN 071546

09/01/2012 Tach: 4443.7

Propeller inspected for blade condition and security of attachment No leaks noted at this time. A.D. biweeklies checked thru this date.

I CERTIFY THAT THIS PROPELLER HAS BEENINSPECTED DURING AN **ANNUAL/100 HR** INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.

Darrell R. Noble IA3513071

MAINTEN

Date	Total Propeller Time	Sinc

FEB 2
Repair
WO# 9

Brooke
Warner
FAA CR

Note: Enter Compliance With

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers

FEB 24 2013 TTSN 462.5 TSO N/A
Repair and static balance. Refer to
WO# 9659 and 8130-3 # 31959 for details.

Brooke Warner
Warner Propeller Tucson, AZ
FAA CRS# W59R659N

Warner
PROPELLER & GOVERNOR CO
TUCSON

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SEF

Date	Total Propeller Time	Time Since Overhaul	Descripti
02/27/2013 Tach: 4477.0 Installed propeller after repair by Warner Propeller and Governor of Tucson, AZ. Torqued and safetied mounting bolts. Engine run shows no leaks. Darrell R. Noble Darrell R. Noble A&P3513071			
10/16/2014 Tach : 4563.4 Inspected propeller for security of attachment, leaks and blade condition. Darrell R. Noble Darrell R. Noble IA3513071			

Note: Enter Compliance With All Applicable FAA A.D. & F

Sierra Vista Aviation Services, LLC
4535 Via Viento
Sierra Vista, AZ 85635
520-22-1759
svas@cox.net

N52878 Cessna 177RG S/N 177RG1297
McCauley B2D34C207-B SN 071546

09/19/2013 Tach & TTIS: 4508.7 TTIS: 494.3

Propeller inspected for blade condition and security of attachment
No leaks noted at this time. A.D. biweeklies checked thru this date.

I CERTIFY THAT THIS PROPELLER HAS BEENINSPECTED DURING AN **ANNUAL/100 HR** INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.
Darrell R. Noble
Darrell R. Noble IA3513071

Sierra Vista Aviation Se
4535 Via Vien
Sierra Vista, AZ 8
520-22-1759
svas@cox.ne

N52878 Cessna 177RG S/N 177R
McCauley B2D34C207-B SN 0715

12/12/2015 Tach : 4637 TT

Propeller inspected for blade conditio
Attachment for annual inspection. No
A.D. biweeklies checked thru this dat

I CERTIFY THAT THIS PROPELLER HA
DURING AN **ANNUAL/100 HR** INSI
DETERMINED TO BE IN AN AIRWORT

Darrell R. Noble IA3513071

Sierra Vista Aviation Services, LLC
4535 Via Viento
Sierra Vista, AZ 85635
520-22-1759
svas@cox.net

N52878 Cessna 177RG S/N 177RG1297
McCauley B2D34C207-B SN 071546

12/12/2015 Tach : 4637 TT: 622.6

Propeller inspected for blade condition and security of Attachment for annual inspection. No leaks noted at this time. A.D. biweeklies checked thru this date.

I CERTIFY THAT THIS PROPELLER HAS BEENINSPECTED DURING AN **ANNUAL/100 HR** INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.

Darrell R. Noble IA3513071

ECTIVE AND SERVICE BULLETIN/ MPLIANCE RECORD

A.D./Bulletin/Letter Number	Authorized Signatures Repairman and Station
01/16/2017 Tach : 4730 Inspected propeller for security of attachment, leaks and blade condition. Darrell R. Noble IA3513071	

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number	Authorized Signatures Repairman and Station Certificate Numbers
N52878 **Cessna 177RG** **McCauley B2D34C207B** Inspected propeller for security of attachment, leaks and blade condition. Darrell R. Noble IA3513071			**01/28/2018** **Tach : 4814.9 TTIS: 800.5** **S/N 071546**	
N52878 **Cessna 177RG** **McCauley B2D34C207B** Inspected propeller for security of attachment, leaks and blade condition. Darrell R. Noble IA3513071			02/23 ~~03/01~~/2019 **Tach : 4887.1 TTIS: 872.7** **S/N 071546**	
N52878 **Cessna 177RG** **McCauley B2D34C207B** Propeller removed for installation of alternator belt P/N S-1597-1-37.5. Reinstalled using new MS28775-228 o-ring. Inspected propeller for security of attachment, leaks and blade condition. Darrell R. Noble IA3513071			**03/26/2020** **Tach : 4955.7 TTIS: 941.3** **S/N 071546**	

N52878 04/10/2021
Tach : 5013.7 TTIS: 999
McCauley B2D34C207B
Inspected propeller for s
Darrell R. Noble IA35130

N52878
Cessna 177RG
McCauley B2D34C207
Inspected propeller f
Darrell R. Noble IA351

N52878
Cessna 177RG
McCauley B2D34
Inspected propel
Darrell R. Noble I

	Authorized Signatures Repairman and Station Certificate Numbers
018 0.5 546	
2/23 01/2019 TTIS: 872.7 S/N 071546	
03/26/2020 Tach : 4955.7 TTIS: 941.3 S/N 071546 775-228 o-ring. Inspected	

N52878 04/10/2021 Cessna 177RG
Tach : 5013.7 TTIS: 999
McCauley B2D34C207B S/N 071546
Inspected propeller for security of attachment, leaks and blade condition.
Darrell R. Noble IA3513071

N52878
Cessna 177RG
McCauley B2D34C207B
05 ~~04~~/06/2022
Tach : 5135.6 TTIS: 1120.9
S/N 071546
Inspected propeller, spinner bulkhead and spinner for security of attachment, leaks and blade condition.
Darrell R. Noble IA3513071

N52878
Cessna 177RG
McCauley B2D34C207B
05/22/2023
Tach : 5257.8 TTIS: 1243.1
S/N 071546
Inspected propeller, spinner bulkhead and spinner for security of attachment, leaks and blade condition.
Darrell R. Noble IA3513071

Approving National Aviation Authority/Country: FAA/UNITED STATES	**AUTHORIZED RELEASE CERTIFICATE** FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG	3. System Tracking Ref. No. **07-3998**
4. Organization Name and Address. **McCauley Propeller Systems** **4800 Cargo Drive** **Columbus, Ga 31907**	Production Certificate 3CE	5. Work Order. Contract. Or Invoice Number SS62047

6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	Propeller Assembly	B2D34C207/78TCA-0 P2074392-01	N/A	1	071546	NEW

13. Remarks:

The above mentioned propeller assembly was found to meet type design requirements on Nov 14, 2007
"AIRWORTHINESS APPROVAL-PROPELLER. FOR DOMESTIC SHIPMENTS ONLY."

14. Certifies the item identified above were manufactured in conformity to:

- ☑ Approved design data and are in a condition for safe operation
- ☐ Non-approved design data specified in Block 13

☐ 14 CFR 42.9 Return to Service ☐ Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:	16. Approval/Authorization No.: DMIR410251-CE	20. Authorized Signature:	21. Certificate Number:
17. Name *(Typed or Printed)*: Mel Tolle	18. Date (m/d/y): Nov 14, 2007	22. Name *(Typed or Printed)*:	23. Date:

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs works in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

McCauley Propeller Systems
4800 Cargo Drive
Columbus, Ga 31907

PROPELLER ASSEMBLY, INSPECTION AND AIRWORTHINESS DETERMINATION REPORT

PROPELLER MODEL NUMBER 3 2D34C207-B/G-78 TCA-0 **SERIAL NUMBER** 0715-46

PROPELLER PART NUMBER P2074392-01

BLADE SERIAL NUMBERS AB126227 (No. 1) AB126228 (No. 2) N/A (No. 3) N/A (No. 4) N/A (No. 5) N/A (No. 6)

ALL ANGLES SET AT 30 INCH STATION

ANGLES				BLADE NUMBER					
POSITION	SPECIFIED	TOLERANCE ±	ACTUAL	1	2	3	4	5	6
REVERSE	—	—		—	—				
LOW OR PICK UP	12.9°	± .2°		12.8°	12.9°				
LATCH OR START LOCK	—	—		—	—				
HIGH OR FEATHER	27.5°	± 1.0°		27.2°	27.4°				

Blade Radii Checked: DL (Initial) Blade Track Checked: DL (Initial) Blade Shake Checked: DL (Initial) Blade Torque Checked: DL (Initial)

Internal Check/s: Snap Rings, Screws Torqued, Etc.: DL (Initial/s) Functional Check: DL (Initial)

Propeller Balanced with Blades Set at: Low By: Dennis Long Date: 11-14-07

Propeller Pressure Checked: DL (Initial) Propeller Oil Filled: N/A (Amount) N/A (Initial) 11-14-07 (Date)

This Propeller Has Been Assembled Per Assembly Drawing No. E-4392 Change: E-11688 Date: 4-11-01

And Contains Parts Fabricated Per Parts List No.: 4393 Change: B-11017 Date: 4-27-98

Assembler Name: Dennis Long Dennis Long **Date:** 11-14-07

I Certify that this Propeller Conforms to the Above Listed Specifications and is Airworthy as Approved Under FAA

T.C. No. P. 7EA. & P.C. No 3

Inspector Name: Rebecca Stewart Rebecca Stewart **Date:** 11/14/07

QC-110
Revised: 6/12/98

WARNER PROPELLER & GOVERNOR CO.

5102 S. Country Club Rd., Tucson, Az. 85706 FAA CRS # W59R659N

WORK ORDER

9659

CUSTOMER INFORMATION

BILLING		SHIPPING	
Name	Angelo A. Petropolis	Name	Will Call
Address	2032 Town & Country Drive	Address	N/A
City/State/Zip	Sierra Vista, AZ 85635	City/State/Zip	N/A
Contact person	Angelo or Darrell	Phone	520-249-8001
Date Recieved	2/18/13	Date promised	N/A

AIRCRAFT INFORMATION

A/C model: Cessna 177RG — Engine M/N: IO-360-A1B6D

A/C Serial: 177RG1297 — N#: 52878 — Engine S/N: N/A

COMPONENT INFORMATION

Item: Propeller — Manufacturer: McCauley — Model #: B2D34C207B

Serial #: 071546 — Part #: N/A — TTSN: 462.5 — TTSO: N/A

Reason for repair: rock damage to leading edge of both blades at approximately station 33

Work to be performed: Rework leading edges of both blades, penetrant inspect reworked area, repaint and static balance.

Note: damage is field repairable. Owner requested work to be performed by repair station to preserve blade life and appearance

The customer authorizes the above repairs to be made to the above components

Customer signature _____

REQUIRED DOCUMENTS

☐ New logbook ☒ Maintenance release ☐ CofA ☐ 337 ☐ Origin ☐ Other _____

MAINTENANCE INFORMATION

Inspection results: defective as reported

Additional work required: None, repairable within requested work scope

Parts installed: 1ea 1633-11

Work performed: Dress leading edges. Dimensional and penetrant inspect reworked areas. Scuff sand, alodine and repaint blades. Install new mounting oring, functional test and static balance.

S/B, S/L, A/D compliances: None

Maintenance release issued: 8130-3 — Number: 31959 — Date issued: 2/24/13

Attatchments to this work order: MM20, MM20-1(2pgs),8130-3

FORM MM-19 (8/96)

1. Approving National Aviation Authority/Country: FAA/United States	2. **AUTHORIZED RELEASE CERTIFICATE** FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 31959

4. Organization Name and Address:	5. **Work Order/Contract/Invoice Number:**
Warner Propeller and Governor Co. L.L.C. 5102 S. Country Club Rd. Tucson, AZ 85706 FAA CRS W59R659N	9659

6. Item:	7. **Description:**	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	Propeller	B2D34C207B	N/A	1	071546	Repaired

13. Remarks: RETURN TO SERVICE

Repaired using McCauley manual MPC200 revision 1 dated February/2008. Refer to work order listed in block 5 for details.

14. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
- ☐ Non-approved design data specified in Block 13.

19. ☒ **14 CFR 43.9 Return to Service** ☐ **Other regulation specified in Block 13**

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:	16. Approval/Authorization No.:	20. Authorized Signature:	21. Approval/Certificate No.: W59R659N
17. Name (Typed or Printed):	18. Date (m/d/y):	22. Name (Typed or Printed): Brooke J. Warner	23. Date (m/d/y): Feb 24, 2013

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA Form 8130-3 (6-01) *Installer must cross-check eligibility with applicable technical data. NSN: 0052-00-012-9005

STANDARD LIMITED WARRANTY
FOR McCAULEY PROPELLER SYSTEMS

McCauley Propeller Systems, a division of Cessna Aircraft Company, Wichita, Kansas U.S.A. ("McCAULEY"), expressly warrants new and remanufactured products produced and sold by McCauley to be free from defects in material and workmanship under normal use and service for a period of thirty-six (36) months after delivery to the original retail purchaser or until the expiration of the maximum hours of use or calendar limits for overhaul published by McCauley for the subject product, whichever occurs first.

McCauley's obligation under this limited warranty is **limited to repairing or replacing**, at its option, any propeller, propeller parts, governor or governor parts determined by McCauley to have been defective and which is properly returned by the owner, with a written statement describing the alleged defect, to any McCauley Authorized Service Center authorized to service the individual McCauley product. The repair or replacement of defective parts will be made without charge to the owner for parts, or labor for removal and installation, except export/import duties, and/or sales or use taxes, if any, which are solely the owner's responsibility. A part replaced pursuant to this limited warranty will be warranted by McCauley under the same terms as the original part for the remainder of the applicable warranty period of the original part. This limited warranty is not intended to and does not cover the costs of normal maintenance or overhaul.

In addition, McCauley will **repair or replace**, at its option, any propeller, propeller parts, governor, or governor parts requiring replacement due to manufacturing defect if found at or before the first recommended overhaul interval as described in McCauley published service information. This first overhaul coverage does **not** include labor, standard overhaul replacement parts, parts repairable via published service information (re-plating, painting, etc.), other costs associated with the propeller or governor overhaul, or export/import duties, and/or sales or use taxes, nor does it apply to defects found after McCauley published overhaul hour or calendar limits. The provisions of this limited warranty do not apply to: any McCauley parts which have been subject to misuse, negligence or accident or which have been repaired or altered in any way so as, in the judgment of McCauley, to adversely affect their performance, stability or reliability; to normal maintenance services (such as cleaning, mechanical adjustments and maintenance inspections); to the replacement of service items made in connection with normal maintenance, to normal deterioration of soft trim and appearance items (such as paint and rubber-like items) due to wear and exposure, to propellers, governors or parts found defective beyond the McCauley recommended overhaul period; or to parts which have been improperly installed by entities other than McCauley and/or McCauley Authorized Service Centers

The McCauley limited warranty is void on any new or remanufactured product installed, without McCauley's prior written approval, on a non-type certificated engine, or an any engine which has received an overhaul or modification which is not approved by the engine manufacturer and that results in a change to the vibratory environment of the engine such as, but not limited to, an alteration of horsepower, operating RPM, crankshaft damper configuration, compression ratio, magneto timing, camshaft design, or any other overhaul or modification not expressly approved by the original engine manufacturer.

To the extent allowed by applicable law, THIS WARRANTY IS EXPRESSLY IN LIEU OF ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED IN FACT OR BY LAW, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. THE REMEDIES OF REPAIR OR REPLACEMENT SET FORTH HEREIN ARE THE ONLY REMEDIES UNDER THIS WARRANTY. McCAULEY DISCLAIMS ANY OBLIGATION OR LIABILITY, WHETHER IN CONTRACT OR IN TORT, INCLUDING LOSS OF USE OF THE PRODUCT WARRANTED, LOSS OF TIME, INCONVENIENCE, LOSS OF PROFITS, COMMERCIAL LOSS OR ANY OTHER DIRECT, CONSEQUENTIAL, SPECIAL OR INCIDENTAL DAMAGES. THIS WARRANTY IS IN LIEU OF ANY OBLIGATION OR LIABILITY ON THE PART OF McCAULEY TO ANYONE OF ANY NATURE WHATSOEVER by reason of the manufacture, sale, lease or use of the warranted products and McCauley neither assumes nor authorizes anyone to assume for it any other obligation or liability in connection with such warranted products. The United Nations convention on Contracts for the International Sale of Goods, 1980, and any successor thereto, is expressly excluded from this warranty.

ISSUED 12/03/00 D-7564 FILE:C:\SJ\A16\MCCAULEY\PUBLICATIONS\CARDS\D-7564 WARR REG 2001

MPC-10
NOVEMBER 2001