MAKE: Cirrus
MODEL: SR20
S/N: 1407
REG. NO: 2706E
WORK ORDER: 00619

Kim Davidson Aviation, Inc.

2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 9/13/2005
A/C TSN: 115.0
HOBBS: 115

Airframe Entries

C/W SB 2x-61-02 R1 by checking torque on prop spinner bolt. Checks good at this time.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 9/13/2005 SIGNED: Work Order: 00619

Printed by EBis 3 (datcomedia.com)

1 of 1

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

PROP MODEL: BHC-J2YF-1BF
PROP S/N: EF406B
REG. NO: 2706E
WORK ORDER: 00963

Kim Davidson Aviation, Inc.
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 3/24/2006
A/C TSN: 216.2
PROP TT: 216.2
HOBBS: 216.2

Prop Entries

I certify that this propeller has been inspected in accordance with an ANNUAL inspection I.A.W. Cirrus Checklist and has been determined to be in AIRWORTHY CONDITION.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 3/24/2006 SIGNED: Work Order: 00963

Printed by EBis 3 (datcomedia.com)

1 of 1

MAKE: Cirrus
MODEL: SR20
S/N: 1497
REG. NO: 2706E
WORK ORDER: 01589

Kim Davidson Aviation, Inc.
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 8/23/2006
A/C TSN: 350.8
HOBBS: 350.8

Airframe Entries

I certify that this propeller has been inspected in accordance with with a 100hr inspection I.A.W. Cirrus Checklist and has been determined to be in AIRWORTHY CONDITION.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 8/23/2006 SIGNED: Work Order: 01589

Printed by EBis 3 (datcomedia.com)

1 of 1

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

PROP MODEL:
BHC-J2YF-1BF
PROP S/N: EF406B
REG. NO: 2706E
WORK ORDER: 10563

Kim Davidson Aviation, Inc.
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 4/10/2007
A/C TSN: 454.5
PROP TT: 454.5
HOBBS: 454.5

Prop Entries

I certify that this propeller has been inspected in accordance with with an ANNUAL inspection I.A.W. Cirrus Checklist and has been determined to be in AIRWORTHY CONDITION.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 4/10/2007 SIGNED Work Order: 10563

Printed by EBis 3 (datcomedia.com)

1 of 1

PROP MODEL:
BHC-J2YF-1BF
PROP S/N: EF406B
REG. NO: 2706E
WORK ORDER: 11490

Kim Davidson Aviation, Inc.
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 4/4/2008
A/C TSN: 714.2
PROP TT: 714.2
HOBBS: 714.2

Prop Entries

I certify that this propeller has been inspected in accordance with with an ANNUAL inspection I.A.W. Cirrus Checklist and has been determined to be in AIRWORTHY CONDITION.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 4/4/2008 SIGNED Work Order: 11490

Printed by EBis 3 (datcomedia.com)

1 of 1

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

PROP MODEL:
BHC-J2YF-1BF
PROP S/N: EF406B
REG. NO: 2706E
WORK ORDER: 12649

Kim Davidson Aviation, Inc.
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 7/7/2009
A/C TSN: 920.5
PROP TT: 920.5
HOBBS: 920.5

Prop Entries

I certify that this propeller has been inspected in accordance with with an ANNUAL inspection I.A.W. Cirrus Checklist and has been determined to be in AIRWORTHY CONDITION.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE

DATE: 7/7/2009 SIGNED: Work Order: 12649

Printed by EBis 3 (datcomedia.com)

1 of 1

PROP MODEL:
BHC-J2YF-1BF
PROP S/N: EF406B
REG. NO: 2706E
WORK ORDER: 15713

Kim Davidson Aviation, Inc.
2701 Airport Avenue
Santa Monica, CA 90405
Phone: (Maint 310-391-6293) (Avionics 310-391-0692)

DATE: 9/4/2012
A/C TSN: 1666.6
PROP TT: 1666.6
HOBBS: 1666.6

Prop Entries

I certify that this propeller has been inspected in accordance with an ANNUAL inspection I.A.W. Cirrus Checklist and has been determined to be in AIRWORTHY CONDITION.

Maintenance Release

The aircraft, airframe, engine, propeller, or appliance identified above was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Administration and is APPROVED FOR RETURN TO SERVICE.

DATE: 9/4/2012 SIGNED: Work Order: 15713

Printed by EBis 3 (datcomedia.com)

1 of 1

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
11-8-13			18444	I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service. Samuel Barnes A+P 4264442 4
12-19-14			19061	I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service. Samuel Barnes A+P 4264442 4

9-22-15 H.M 1930.1

SERVICEABLE PART

MANUFACTURER Hartzell

PART NAME Propeller

MODEL BHC-J2YF-1BF

PART NO.

SERIAL NO. EF4413

REMARKS: Disassembled and repaired greases 1200 CW S/N 348. Passivated, greased, painted tips and blades. Old Dwg. # F7694 4) K14835 5) K14837.

ACCOMPLISHED BY Chad Smith

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 2115 Date 10 Sept 15

Signed [illegible] Signature of Authorized Representative

FOR: H & H PROPELLER SERVICE
Burlington Municipal Airport
Burlington, NC 27215

F.A.A. REPAIR STATION NO. PS4R451M;

Date	Propeller TSN	Propeller TSO	A/C Hrs Tach	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
3-1-16			1935.5	I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service. Samuel Barnes
				A&P 2426444 24 IA

6-14-17	Tach		1961.6	I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service.
				Samuel Barnes
				A&P 2426444 24 IA
3-12-19	Tach		1974.6	I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service.
				John E. Carter 402065620 IA

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			1988.7	I certify that this prop has been inspected in
6-25-2020				accordance with a 100 hr annual inspection it is
				approved for return to service.
				John E. Coulter 402065620 IA

AVIATION PROPELLERS, INC.

PROPELLER LOG BOOK ENTRY STICKER

August 20, 2020 propeller assembly serial number EF406B was overhauled IAW Hartzell Propeller manuals: 113B-R46, 133C-R39, 159-R72, 165A-R25 (TR-034) and 202A. AD notes: N/A. Service Bulletins: SB-136RI and SB-374R1 C/W. Factory new parts kit and cylinder installed. All mandatory replacement parts were removed and replaced with factory new parts. Propeller was lubricated with NYCO GN3058 grease and shipped assembled with bulkhead installed. A copy of the work order issued. Original FAA Form 8130-3 and propeller log book entry sticker issued. Propeller assembly model number, component serial numbers and times are:

Propeller model number BHC-J2YF-1BF/F7694	TTSN: Not Provided	TSO: 0.0
#1 Blade serial number K14835	TTSN: Not Provided	TSO: 0.0
#2 Blade serial number K14837	TTSN: Not Provided	TSO: 0.0

Work accomplished by Aviation Propellers, Inc., 12970 Port Said Road, Opa Locka, Florida, 33054, Repair Station ME4R359M, under API Work Order Number 45701A.

Jason H. Gato
Chief Inspector

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
7/14/21		0032		COMPLETED 100 HR/ANNUAL INSPECTION IAW CIRRUS
				SR20 SERVICE MANUAL. AND HARTZELL PROPELLER.
				VISUAL INSPECTION OF PROPELLER BLADES FOR NICKS
				AND DENTS. INSPECT PROP NUTS AND BOLTS.
				CHECK SAFETY WIRE.
				I CERTIFY THAT THIS PROPELLER WAS INSPECTED
				IN ACCORDANCE WITH AN ANNUAL INSPECTION
				AND WAS DETERMINED TO BE IN AIRWORTHY
				CONDITION. P.F. COMPTON A/P 3618 4660
				GEORGE R. LEE A/P 1968610 IA.

Seven Rivers Aviation
129 Airport Rd
Georgetown, SC 29440
Phone 843-527-7516

◇ Propeller ◇ N2706E ◇ Hartzell ◇ BHC-2JYF-1BF ◇ S/N: EF406B◇

◇ Hobbs: 2051.5 ◇ Engine Hobbs: 52.0 ◇

Date: 3/15/2022

1. Removed Spinner and Replaced UHMW Tape on forward Spinner Bulkhead, Verified Fit and Reinstalled. Referenced Hartzell Manual 127 CH61-16-27-S and Figure 6-20.

✈END✈

Justin Eshleman
3302761 AP

E&E AVIATION LLC.
WWW.EEAVIATIONMX.COM
DATE:8/3/2022 N2706E HOBBS/TTAF:2122.4
COMPLETED ANNUAL INSPECTION I/A/W FAR43 APPENDIX D:
I CERTIFY THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND FOUND AIRWORTHY FOR RETURN TO SERVICE

SIGNED _____ RAYMOND VILLALBA
A&P-103623209-IA

ss Directives,
and Inspections.

E&E AVIATION LLC.
WWW.EEAVIATIONMX.COM
DATE:1/6/2023 N2706E HOBBS/TTAF:2222.9
COMPLETED 100HR INSPECTION I/A/W FAR43 APPENDIX D:
I CERTIFY THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH A 100HR INSPECTION AND FOUND AIRWORTHY FOR RETURN TO SERVICE

SIGNED_____RAYMOND VILLALBA
A&P-103623209-IA

E&E AVIATION LLC.
WWW.EEAVIATIONMX.COM
DATE:6/1/2023 N2706E HOBBS/TTAF:2326.4
COMPLETED 100HR INSPECTION I/A/W FAR43 APPENDIX D:
I CERTIFY THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH A 100HR INSPECTION AND FOUND AIRWORTHY FOR RETURN TO SERVICE

SIGNED_____RAYMOND VILLALBA
A&P-103623209-IA

E&E AVIATION LLC.
WWW.EEAVIATIONMX.COM
DATE:10/23/2023 N2706E HOBBS/TTAF:2350.0 ENGINE HOBBS:348.6
COMPLETED ANNUAL INSPECTION I/A/W FAR43 APPENDIX D:
I CERTIFY THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND FOUND AIRWORTHY FOR RETURN TO SERVICE

SIGNED_____RAYMOND VILLALBA
A&P-103623209-IA

E&E AVIATION LLC.
WWW.EEAVIATIONMX.COM
DATE:2/7/2024 N2706E HOBBS/TTAF:2449.0 ENGINE HOBBS:448.2
COMPLETED 100HR INSPECTION I/A/W FAR43 APPENDIX D:
I CERTIFY THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH A 100HR INSPECTION AND FOUND AIRWORTHY FOR RETURN TO SERVICE

SIGNED_____RAYMOND VILLALBA
A&P-103623209-IA