

N4222J

# PROPELLER LOGBOOK

PROPELLER MAKE Sensenich

PROPELLER MODEL M74Dm-0-58

PROPELLER S/N K5826

LOGBOOK # 1

N4222J

**SERVICEABLE**Propeller Sensenich

UNIT NAME

MFG. NAME

M74DM-0-58

K5826

MODEL OR TYPE

SERIAL No.

The propeller or appliance identified above was ~~repaired~~ overhauled and inspected in accordance with the SRM 580 overhaul manual and current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under:

West Valley Aircraft Services

OWNER

8064

WORK ORDER #

DATE

11/23/2010

SIGNED

SULLIVAN PROPELLER SPECIALISTS

2156 AMERICAN AVENUE

HAYWARD, CA 94545

510.782.0920 • FAX 510.264.9162

F.A.A. REPAIR STATION #S5UR963J

SPS-106

**PROPELLER MAINTENANCE RECORD**

Position \_\_\_\_\_

PITCH RANGE

Propeller Model Sensenich

High/Feather \_\_\_\_\_

Propeller S/N K 5826

Start Lock \_\_\_\_\_

Blade Design \_\_\_\_\_

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 \_\_\_\_\_

Aircraft Manufacturer Piper

No. 2 \_\_\_\_\_

Aircraft Model PA28-140

No. 3 \_\_\_\_\_

S/N 28-22570




No. 4 \_\_\_\_\_

Registration N4222J

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	N4222J Sensenich M74DM-0-58 Serial No. K5826		 West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B. Palo Alto, CA 94303 Tel. (650) 565-0063
			3/1/2011 Tach: 5781.5 TSOH: 0
			<b>Propeller Entry:</b> Inspected spinner and backing plates. Reinstalled propeller in accordance with the PA28-140 maintenance manual following overhaul by Sullivan Propeller Specialist FAA Repair Station #S5UR963J under work order # 8064.
			 Kevin R. Pinger A&P IA 3236526
	N4222J Sensenich M74DM-0-58 Serial No. K5826		 West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B. Palo Alto, CA 94303 Tel. (650) 565-0063
			3/1/2011 Tach: 5781.5 TSOH: 0
			<b>Propeller Entry:</b> Completed <b>Annual Inspection</b> of the propeller using the Piper PA28-140 maintenance manual 100 hour checklist as a guide. Airworthiness Directives current through AD2011-05. This propeller is airworthy.
			Kevin R. Pinger A&P IA 3236526



I CERTIFY THAT THIS PROPELLER HAS BEEN  
INSPECTED IAW ANNUAL INSPECTION AND WAS  
DETERMINED TO BE IN AIRWORTHY CONDITION.

SIGNED: David Vickers DATE: 5-15-12  
David Vickers, IA 3161731

TTIS: 5798.28 TSMO: 16.78 REG # N4222J

145 JOHN GLENN DR CONCORD, CA 925-676-2100

PROP MODEL  
PROP S/N  
REG. NO. N4222J  
WORK ORDER  
5908-04-2012



#### Sterling Aviation

145 John Glenn Drive  
Concord, CA 94520  
Phone: 925-676-2100

DATE: 5/15/2012  
A/C TSN: 5798.28  
PROP TT: 5798.28  
TSPOH: 16.78  
TACH: 5798.28

#### Prop Entries

Propeller 100 hour inspection for 2012 airworthiness recertification complied with using Sterling's checklist and FAR 43 appendix D. Propeller ground operation after inspection and servicing was normal.

DATE: 5/15/2012

SIGNED: David Vickers 1 of 1  
A&P 3161731

Work Order: 5908-04-2012

Printed by EBis 3 (datcomedia.com)


D



145 John Glenn Drive  
Concord, CA 94520  
Phone: 925-676-2100

DATE: 9/27/2012  
A/C TSN: ~~5855-82~~  
PROP TT: ~~5855-82~~  
TSPOH: 74.32  
TACH: ~~5855-82~~

Directives,  
Inspections.

Propeller 100 hour inspection for 2012 airworthiness recertification complied with using Sterling's checklist and FAR 43 appendix D. Propeller ground operation after inspection and servicing was normal.

DATE: 9/27/2012

**SIGNED**

David Vikner REP 3161731

Work Order: 6007-09-2012

Printed by EBis 3 (datcomedia.com)



145 John Glenn Drive  
Concord, CA 94520  
Phone: 925-676-2100

DATE: 4/29/2013  
A/C TSN: 5986 2  
PROP TT 5986 2  
TSPOH 204.7  
TACH: 5986.2

Propeller 100 hour inspection for 2013 airworthiness recertification complied with using Sterling's checklist and FAR 43 appendix D. Propeller ground operation after inspection and servicing was normal.

DATE: 4/29/2013

**SIGNED**

Jan 2000 ADP 316123

Work Order: 6169-05-2013

Printed by EBis 3 (datcomedia.com)



145 John Glenn Drive  
Concord, CA 94520  
Phone: 925-676-2100

DATE: 5/15/2013  
A/C TSN: 6008 59  
PROP TT: 6008 59  
TSPOH 227 09  
TACH: 6008 59

Propeller 100 hour inspection for 2013 airworthiness recertification complied with using Sterling's checklist and FAR 43 appendix D. Propeller ground operation after inspection and servicing was normal.

DATE: 5/15/2013

**SIGNED:**

David Vickers AP 3161731

Work Order: 6169-05-2013

Printed by EBis 3 (datcomedia.com)

TTIS: 6008.59 TSMO: 227.09 REG # N40025

145 JOHN GLENN DR CONCORD,CA 925-676-2100





**I CERTIFY THAT THIS PROPELLER HAS BEEN  
INSPECTED IAW ANNUAL INSPECTION AND WAS  
DETERMINED TO BE IN AIRWORTHY CONDITION.**


SIGNED: David Vickers

DATE: 5-15-13

David Vickers, IA 3161731



Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	<b>BOWLES AVIATION LTD., Marysville, CA</b>		
	916-439-3052		
	11/08/2017 Tach: 6138.67		
	Cleaned, inspected, and dressed propeller.		
	I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.		
	END		
	Thomas M. Bowles A&P 3293707 		
	<b>BOWLES AVIATION LTD., Marysville, CA</b>		
	916-439-3052		
	12/20/2018 Tach: 6148.24		
	Cleaned, inspected, and dressed propeller.		
	I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.		
	END		
	Thomas M. Bowles A&P 3293707 		

	<b>BOWLES AVIATION LTD., Marysville, CA</b>		
	916-439-3052		
	01/18/2020 Tach: 6151.84		
	Cleaned, inspected, and dressed propeller.		
	I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.		
	END		
	Thomas M. Bowles A&P 3293707 		
2022	TSN: Unk.	100 Hour/Annual Inspection - Inspected Propeller, Spinner & Backing Plate - No Defects Noted.	
Dec. 1	TSO: 288.6	I certify that this Propeller has been inspected IAW FAR 43 App. D and found to be in a safe condition for operation.	
		L. Bradley ATP 3083894	