N734MK #3




The Standard AIRCRAFT LOG

ASA-SA-2

Aircraft Record General Information Cessna C172N Manufacturer Model 17268959 Registration Number 11734m/2 **Date of Manufacture Engine(s) currently installed:** 0-320-H2AD Serial RL-6231-76T Lycoming Model Manufacturer Manufacturer Serial Model Propeller(s) currently installed:

Manufacturer	McCauley	Mode	1060/DT	m7557	
HUB Model	Seria	al	Ser	ial	
Blade Model	Seria	al	Serial	Serial	
Blade Model	Seria	al	Serial	Serial	

Cessna 172 Serial No. 17268959



10/1/2011 Tach: 3487

TTA: 3487

Airframe Entry

Completed a **Annual Inspection** of the airframe using the Cessna 172 100 hour MM checklist as a guide. **Inspected ELT in accordance with FAR 91.207 (d)**, battery replacement due DEC/2011. Complied with **AD2011-10-09** seat track and roller inspection, okay, NID Tach 3587. Complied with **AD2001-23-03**, map post light inspection, okay, due next Annual. Complied with **SEB 96-2** seat belt friction test and shoulder harness inspection. Replaced vacuum relief filter p/n ARB3-5-1. Replaced induction air filter p/n BA48103. Inspected the flaps and flight controls and pullies. Lubricated aircraft in accordance with the Cessna Maintenance Manual lubrication schedule. Inspected the muffler and exhaust risers. Cleaned the gascolator. Serviced the battery. Serviced the brake reservoirs. Checked interior and exterior lights. This aircraft is airworthy.

Kevin R. Pinger A&P 3236526 IA

Reg. No. N734MK Cessna 172N Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 11/25/2011 Tach: 3536

TTA: 3536

Aircraft Entry:

Completed the **50 Hour Inspection** of the airframe using the Cessna 172 maintenance manual 50 hour checklist as a guide. Checked engine controls, alternator and bracket, induction system, and muffler, okay. Inspected interior and exterior lights. Inspected brake linings and serviced tires. Cleaned belly. Taxi tested aircraft, run up and indication check normal.

//m //m

Kevin R. Pinger A&P/IA 3236526

EAR	Reg. No. N734MK	ont and Halman Information	12/30/2011 Tach: 3566
O	Cessna 172N Serial No. 17268959	West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063	TTA: 3566
	EIT :- accordance with FAR	73, next battery replacement due FEB/2014. Test 91.207 (d). Installed and set to ARM.	
	G	Carrie L. Ferg	ruson A&P/IA 2806332
	N734MK Cessna 172	West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063	1/28/2012 Tach: 3587 ATT: 3587
	Serial No. 17268959 Airframe Entry	Tel. (650) 565-0063	7111. 3307
	interior and exterior lights. Installed the induction air filter. Inspected with new gasket. Inspected the	-2 seat belt friction test and shoulder harness inspect pected the tires and brakes. Serviced the shimmy day d the flaps and flight controls. Cleaned the gascolate muffler and exhaust risers. Inspected the motor mounts. This aircraft is returned to service.	mpener. Inspected or and re-safetied
	up, power, and indication check		inger A&P 3236526 IA
	1		

-

-

YEAR 20 Date	TOT TIM SER	Reg. No. N734MK Cessna 172N Serial No. 17268959 West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 9430 Tel. (650) 565-0063	3/7/2012 Tach: 3644 TTA: 3644
		Completed the 50 Hour Inspection of the airframe using the Cessna 172 nd checklist as a guide. Checked the engine controls, alternator and bracket, in muffler, okay. Inspected interior and exterior lights. Inspected brake linings 066-30026 (qty 2) and serviced tires. Cleaned the belly. Taxi tested the airc check normal. This aircraft is returned to service.	duction system, and s, replaced left linings p/n
		N734MK Cessna 172 Serial No. 17268959 West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 9430 Tel. (650) 565-0063	4/21/2012 Tach: 3687 ATT: 3687
		Airframe Entry Completed a 100 Hour Inspection of the airframe using the Cessna 172 MM 100 hour checkle AD2011-10-09 seat track and seat inspection NID Tach 3787. Complied with SEB 96-2 seat harness inspection. Checked the interior and exterior lights. Inspected the tires and brakes. Re 314-0. Replaced the L/H brake disk P/N 164-30615-1. Checked the shimmy dampener. Service nitrogen. Removed the carb heat box & repaired it. Installed the box & rigged the carb heat car muffler with a spare serviceable unit & 4 P/N 77611 no blow gaskets, removed the muffler she cracks were found Inspected the induction air filter -okay for service Inspected the flaps and gascolator. Inspected the motor mount. Wiped the belly & cleaned the gear. Performed run up. Taxied the aircraft to condition the brake disk IAW Cleveland instructions. This aircraft is return.	belt friction test and shoulder eplaced the L/H main tire P/N 072-ed the front strut with 5606 & ble. Removed & replaced the roud & inspected the muffler -no I flight controls. Cleaned the power, and indication check.

Market S.

YEAR 20_

DATE

N734MK Cessna 172 Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 5/2/2012 Tach: 3705.8

ATT: 3705.8

ber of htries.)

ations

Airframe Entry

Replaced vacuum pump with overhauled unit p/n AA3215CC s/n 848102.

In Mal

Kevin R. Pinger A&P 3236526 IA

N734MK Cessna 172N Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 5/11/2012 ACTT: 3717.6 TACH: 3717.6

Airframe Entry:

Replaced right tire p/n 072-314-0 due to flat spot. Inspected brake linings, repacked the wheel bearings and torqued the wheels in accordance with the Cessna Maintenance Manual. Tightened muffler clamp.

IM IME

Kevin Pinger A&P 3236526 IA

Reg. No. N734MK Cessna 172N Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 5/25/2012 Tach: 3740.8

TTA: 3740.8

Aircraft Entry:

Completed the 50 Hour Inspection of the airframe using the Cessna 172 maintenance manual 50 hour checklist as a guide. Checked the engine controls, alternator and bracket, induction system, and muffler, okay. Inspected interior and exterior lights. Inspected brake linings and serviced the tires. Performed, run up, leak, and indication check, normal. This aircraft is returned to service.


Mollen

Kevin R. Pinger A&P/IA 3236526

N734MK Cessna 172 Serial No. 17268959 Airframe Entry

YEAR

DATE



6/30/2012 Tach: 3787 ATT: 3787

ons · of ies.)

Completed a 100 Hour Inspection of the airframe using the Cessna 172 maintenance manual 100 hour checklist as a guide. Complied with AD2011-10-09 seat track and seat inspection NID Tach 3887. Complied with SEB 96-2 seat belt friction test and shoulder harness inspection. Checked the interior and exterior lights. Inspected the tires and brakes. Replaced the nose tire. Replaced the right brake disk p/n 164-30615-1 and bearing race. Checked the shimmy dampener. Inspected the flaps and flight controls. Inspected the motor mount. Serviced the battery. Wiped the belly and cleaned the leading edges. Performed run up, power, and indication check. Taxied the aircraft to condition the brake disk in accordance with Cleveland instructions. This aircraft is returned to service.

Kevin R. Pinger A&P 3236526 IA

Reg. No. N734MK Cessna 172N Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063

8/14/2012 Tach: 3839.3

TTA: 3839.3

Aircraft Entry:

Completed the 50 Hour Inspection of the airframe using the Cessna 172 maintenance manual 50 hour checklist as a guide. Checked the engine controls, alternator and bracket, induction system, and muffler, okay. Inspected interior and exterior lights. Replaced Whelen FAA/PMA LED landing light with new p/n 01-0790623-10 s/n 1065 due to crack in the lens. Inspected brake linings and serviced the tires. Serviced the nose strut with nitrogen. Performed, run up, leak, and indication check, normal. This aircraft is returned to service.

Carrie L. Ferguson A&P/IA 2806332

YEAR 20 DATE	Reg. No. N734MK Cessna 172N Serial No. 17268959 West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 Airframe Entry: Parking Brake Deactivated by the cable. Placarded parking brake handle "INOI accordance with FAR 91.213 (d)(3)(ii). Carrie L. Fe.	8/29/2012 Tach: 3854.5 TTA: 3854.5 PERATIVE" in	ber of ntries,
	N734MK Cessna 172 Serial No. 17268959 Airframe Entry Performed Annual Inspection of the airframe using the Cessna 172 maintenance in checklist as a guide. Tested ELT in accordance with FAR 91.207 (d), battery represented with AD2011-10-09 seat track and seat inspection, okay, NII Complied with SEB 96-2 seat belt friction test and shoulder harness inspection. Cland exterior lights. Inspected the tires and brakes. Inspected the cables and pulleys controls points, attachment, and lubricated. Checked the shimmy dampener and ton the flaps and flight controls. Inspected the motor mount. Serviced the battery. Performance of the controls of the power, and indication check. I certify I have inspected this aircraft in accordance with Inspection and found it to be in an airworthy condition. This aircraft is returned to the service of the controls. The power is returned to the service of the controls. This aircraft is returned to the service of the controls of the controls. This aircraft is returned to the service of the controls. This aircraft is returned to the service of the controls of the controls. This aircraft is returned to the service of the controls of the controls. This aircraft is returned to the service of the controls of the controls. This aircraft is returned to the controls of the controls of the controls of the controls. The controls of the cont	D Tach 3987. hecked the interior . Inspected the rque links. Inspected ormed run up, with an Annual	
	I certify that the ATC Trans Inspections required by FA performed IAW FAR 43 Ap Date 13NOV12 Signed 5 houth Northcoast Service	R 91.413 were	

YEAR 20 DATE	Reg. No. N734MK Cessna 172N Serial No. 17268959 Airframe Entry:	West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 Tol. 10/12/2012 Tach: 3887 TTA: 3887	ons
		ke Deactivated by the cable. Parking brake handle is placarded rdance with FAR 91.213 (d)(3)(ii).	
		Carrie L. Ferguson A&P 2806332 L	1
		West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 witch and fuel line in accordance with AD2001-23-03, switch insulator is ad, next inspection due 10/2013. Carrie L. Ferguson A&P 2806332 LA	
	Reg. No. N734MK Cessna 172N Serial No. 17268959 Aircraft Entry: Serviced the shimmy damper	West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063 Tener with hydraulic fluid. Serviced the nose strut with nitrogen. Carrie L. Ferguson A&P/LA 2806332	

YEAR 20

DATE

Reg. No. N734MK Cessna 172N Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063

1/1/2013 Tach: 3937

TTA: 3937

er o

ries

Aircraft Entry:

Completed the 50 Hour Inspection of the airframe using the Cessna 172 maintenance manual 50 hour checklist as a guide. Checked the engine controls, alternator and bracket, induction system, and muffler, okay. Inspected interior and exterior lights. Inspected brake linings and serviced the tires. Serviced the nose strut with nitrogen. Performed, run up, leak, and indication check, normal. This aircraft is returned to service. Con CF

Carrie L. Ferguson A&P/IA 2806332

N734MK Cessna 172N Serial No. 17268959




West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303

3/14/2013 ACTT: 3952 TACH: 3952

Airframe Entry:

Replaced left tire p/n 072-314-0 due to flat spot. Replaced brake linings p/n 066-30026, repacked the wheel bearings and torqued the wheels in accordance with the Cessna Maintenance Manual.



Carrie L. Ferguson A&P 2806332 IA

N734MK Cessna 172N Serial No. 17268959



West Valley Aircraft Services, LLC. Embarcadero Rd. Hangar B, Palo Alto, CA 94303 Tel. (650) 565-0063

11/6/2013 Tach: 3957.3 TTA: 3957.3

Airframe Entry:

Installed pilot secondary seat stop kit p/n SK210-174B in accordance with Cessna SEB07-5 Rev. 4. Post installation inspection and operational check, good. Instructions for Continued Airworthiness incorporated into aircraft records. Installation to be inspected at each 100 Hour/Annual Inspection in accordance with the ICA.

Kevin R. Pinger A&P/IA 3236526

Zip Code

I certify that the ATC Transponder Tests & Inspections required by FAR 91.413 were performed IAW FAR 43 App. F. Date 19 May 16 Time 395766 Signed Northcoast Services crs WR3R955L	Description of Inspections, Tests, Entries must be endorsed with Name, Ration Technician or Repair Facility. (See back page 1)	nd and Certificate Number of
N734MK	RO WORKS dba	06/17/2017 Tach: 3981.2
Serial No. 17268959 Embaro	cadero Rd. Hangar B, Palo Alto, CA 94303 50) 565-0063	TTA: 3981.2
Airframe Entry:		
Replaced the induction air filter p/n BA in place, next inspection due next Annu housing inspection, all parameters within Inspected the wheel group, serviced the pulleys Stripped and treated metal as Cessna 172 lubrication schedule Cleathe fuel finger screen and cleaned and in Cleaned the firewall Inspected the metal as the firewall Inspected the metal as the firewall	cordance with FAR 91.207 (d), battery replace 6108 Complied with AD2001-23-03 map postal Inspection Complied with AD2011-10-09, in tolerance, next inspection due in 100 Hours/A tires with air Inspected and lubricated all flight required and painted Lubricated the aircraft is used and inspected the gascolator Drained the aspected, no contaminates found, reinstalled and otor mount Inspected the exhaust Replaced current through bi-weekly revision 2017-12, no ormal	st light inspection, insulator seat track, roller, pin, and annual (<i>Tach 4081.2</i>) ht controls, cables, and in accordance with the carburetor bowl, removed I secured with new gasket
I certify that this aircraft has been inspectairworthy condition.	cted in accordance with an Annual Inspection a	and was determined to be in
	Kevi	n R. Pinger A&P 3236526 IA

YEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Test Entries must be endorsed with Name, Ra Technician or Benair Facility (See back	ating and Cortificate Ni.
#1-Manf. Date 6	transponder tests and this date and found asponder. Naveo Model /6 //8 Signate AVIONICS, INC	el ATIS ature	o S/N#	12321 FB6R529N	pages for other specific entries
Ce	734MK essna 172 rial No. 1726895	9		readero Rd. Hangar One, Palo Alto, CA 94303	6/2/2018 TACH: 4005.5 TTA: 4005.5
A	irframe Entry				
th		as been in		ircraft in accordance with FAR Part 43 Applecordance with an Annual Inspection and Kevin R. F	

EAR D ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.
Ces	34MK ssna 172 ial No. 172689	59		6/2/2018 TACH: 4005.5 TTA: 4005.5 TTA: 4005.5
Ai	rframe Entry			
		-1	100 T	I am an American de Trade (105) Danis and construction
p/1	n J7444-14 (q CSK 172-1F, s	ty 5). Replaced w	laced induction ith hyraulic fl	Hours or Annual (next due Tach 4105). Replaced cowl mounts in air filter p/n BA6108. Resealed the nose strut kit p/n uid and nitrogen. Replaced baggage panel p/n 0515012-3-532. The bi-weekly revision 2018-12.
p/1	n J7444-14 (q CSK 172-1F, s	ty 5). Replaced w	laced induction ith hyraulic fl	n air filter p/n BA6108. Resealed the nose strut kit p/n uid and nitrogen. Replaced baggage panel p/n 0515012-3-532.

YEAR 20 DATE	RECO TACH TIME	N734MK Cessna 172 Serial No. 17268959 1901 Airframe Entry	Embarcadero Rd. Executive Hangar One. Palo Alto CA 94303	5/25/2019 ch: 4018.3 'A: 4018.3
		Performed Annual Inspecti ELT in accordance with FAI switch and fuel line in accordance. Annual. Complied with AD2 Annual (next due Tach 4118. Directives current through by	on of the aircraft in accordance with FAR Part 43 Appendix D. Test R 91.207 (d), battery replacement due JUL/2020 . Inspected map pedance with AD2001-23-03 , no defects found, next inspection due 2011-10-09 seat track and seat inspection, okay, recurs every 100 F <i>3 or Annual</i>). Replaced induction air filter p/n BA6108. Airworthis-weekly revision 2019-11. I test flew this aircraft, all parameters meen inspected in accordance with an Annual Inspection and was by condition. **Kevin R. Pinger A&P 32**	ost light next Hours or iness normal. I
		Beacon-AD3A AxisRudder	Model: tailBear P/N: UAV-1 UAVIONI 560 Berne Road Columbia Falls MT 59912 Www.uAvionix.com Office: 1-844-827-2372 Certificate of Conformance	002183-001
		SERIAL NUMBER:	I hereby certify that the product/s enclosed herewith, manufact uAvionix Corporation, have been inspected and found to in full accordance with the specifications of: TSO-C154c B1S, TSO-C145e Beta 1 INCOMP, TSO-C8 and TSO-C30c Type III. By: Country of Origin: U.S.A. Date: UAV-100304:	be

Palo

Alto

74303

Model

			TOTAL	Description of Ins	pections,	Tests, Repairs and A	Alteration
/EAR	RECORDING	TODAY'S				418(2020 Tach: 4024-9	cific entri
N734MF			AERO	WORKS als	to CA 94303	Tach: 4024-9 TTA: 4024-9	
Cessna 1	72 o. 17268959	1901 Emb	arcadero Rd. E	executive Hangar One, Palo Alt Tel. (650) 565-0063	10, 0117 1011	1 40 24-1	
				Tel. (050) 5 05			
	ne Entry			Avioniy t	ailBeacon as	sembly, part number	
Replace	ed existing O	EM tail pos	sition light a	ssembly with uAvionix t atest revision of tailBeac aft FAA Form 337 on fi	con STC Inst	allation Manual UAV-	
				aft. FAA Form 337 on fi			
100251	4-001. HIStan	icu suppres		3			
		1/9	10/		Kevin R	. Pinger A&P 3236526 IA	
	Company	- (,				
			Mc	odel: tailBeacon TSO Installation	Kit		
		6		P/N: UAV-1003202-	-001		
		ani			1700		
	uAV	OHIL	MT 50012				
560	Berne Road Co v.uAvionix.com	lumbia Falls Office: 1-844-8	M1 59912 327-2372				
	T. C.	Certifica	te of Conf	formance			
		that the proc	duct/s enclose	ed herewith, manufactured b	у		
	Autoniy (Cornoration	nave been ins	specied and lound to be			
	ir	full accorda	ance with the s	specifications of.			
	1	1.	30-0300 1110	J			
-	1/2			9 25-14			
By:		C.A.		Date: UAV-1003264-001 (Rev A)		
Cou	untry of Origin: U	.S.A.			1		
					7		

EAR 0	REI TAI TIN	N734MK Cessna 172 Serial No. 17268959 DERO WORKS d.b.a. 1901 Embarcadero Rd. Executive Hangar One, Palo Alto, CA 9430 Tel. (650) 565-0063	7/3/202 Tach: 40 2 9 TTA: 40 2 9
		Airframe Entry	
		Removed and reinstalled propeller following re-conditioning. Replaced altern 376. Replaced the right tire and tube. Replaced ELT antenna. Replaced one Co and replaced aft right baggage panel, painted to match. Painted baggage door baggage door seal. Serviced the nose strut with air.	DM/NAV antenna. Fit
		Kevin.	R. Pinger A&P 3236526 L
		N734MK	
		Cessna 172 AERO WORKS also	7/3/2020
		Serial No. 17268959 1901 Embarcadero Rd. Executive Hangar One, Palo Alto, CA 9430. Tel. (650) 565-0063	Tach: 4028 TTA: 4028
		Airframe Entry	
		Performed Annual Inspection of the aircraft in accordance with FAR Part 43	Annendiy D. Donland
		ELT battery p/n BS2173, tested ELT in accordance with FAR 91.207 (d), batter	ry replacement next due
		MAR/2022. Inspected map post light switch and fuel line in accordance with	D2001-23-03 no
		defects found, next inspection due next Annual. Complied with AD2011-10-09	seat track and seat
		inspection, okay, recurs every 100 Hours or Annual. Replaced induction air file	er p/n BA6108.
		Airworthiness Directives current through bi-weekly revision 2020-14. I test fle parameters normal. I certify that this aircraft has been inspected in accordance	w this aircraft, all
		Inspection and was determined to be in airworthy condition.	with an Annual
			R. Pinger A&P 3236526 IA
			10.1 11/2011 1021 3230320 111

ns of es.)

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Re Entries must be endorsed with Name, Rating Technician or Repair Facility. (See back page	and Certificate Null
Cess Seri	44MK sna 172 al No. 17268959 frame Entry:	9 1901	Embarcadero Ro	d. Executive Hangar One, Palo Alto, CA 94303 Tel. (650) 565-0063	7/25/2021 Tach: 4031 TTA: 4031
noct	light ewitch	and fuel li	ne in accordat	battery replacement next due MAR/2022. Inspence with AD2001-23-03, no defects found. Continue defects found. Perplaced induction air f	inplied with
BA6	5108 Airwort	hiness Dir nspected i	rectives curren	ction, no defects found. Replaced induction air f int through bi-weekly revision 2021-14. I certify with an Annual Inspection and was determine Kevin R. Pinger	y that this

hs

tions, Tests, Repairs and Alterations with Name, Rating and Certificate Number of y. (See back pages for other specific entries.) 7/25/2021 Tach: 4031 CA 94303 TTA: 4031 Part 43 Appendix D. Tested MAR/2022, Inspected map lefects found. Complied with ced induction air filter p/n 2021-14. Lecrtify that this and was determined to be in Kevin R. Pinger A&P 3236526 L1 g Livermore, CA Phone 925-449-5904 lifted Repair Station #QJAR856X including data correspondence, required by § 91.413, at to comply with 14 CFR Part 43, Appendix E and F. N 734114 21100 Date 5/4/2022

EAR 0 ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Entries must be endorsed with Name, Rating and Cert Technician or Repair Facility, (See back pages for other	ificate Number of
			37	PERO WORKS d.b., mbarcadero Rd. Executive Hangar One, Palo Alto, CA 94303 Tel. (650) 565-0063	5/18/2022 Tach: 4039 TTA: 4039
				w BP-1020. Tested ELT in accordance with FAR 91.20 023 . Replaced sump drain.	7 (d) . battery zer A&P 3236526 IA
			139	mbarcadero Rd. Executive Hangar One, Palo Alto, CA 94303 Tel. (650) 565-0063	6/7/2022 Tach: 4039.0 TTA: 4039.0
	This a	ircraft has		ed and has been found safe for the intended flight in acc	ordance with
		- / I	1	Kevin R. Ping	ger A&P 3236526 IA

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.
	N734MK Cessna 172 Serial No. 1726895 Airframe Entry:	9 1901		7/25/2021 Tach: 4031 Tel. (650) 565-0063 7/25/2021 Tach: 4031 TTA: 4031
	ELT in accordance post light switch a AD2011-10-09 se BA6108. Airworth	e with FA and fuel li- at track an hiness Dir aspected i	R 91.207 (d), ne in accordant nd seat inspectectives current	battery replacement next due MAR/2022. Inspected map ace with AD2001-23-03, no defects found. Complied with tion, no defects found. Replaced induction air filter p/n at through bi-weekly revision 2021-14. I certify that this with an Annual Inspection and was determined to be in Kevin R. Pinger A&P 3236526 LA
				Precision Static Testing Livermore, CA Phone 925-449-5904 FAA Certified Repair Station #QJAR856X I certify that transponder tests, including data correspondence, required by § 91.413, have been performed and found to comply with 14 CFR Part 43, Appendix E and F. Time: 4979.1 W/O# 21100 N 734714 Inspected by Date 5/4/2022

YEAR 20 Date

YE SO	YEAR 20 Date	RECORDING Tach Time	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		N734MK Cessna 172 Serial No. 17268959	68959	D 1901 Embarcad	### (6/20/2022 1901 Embarcadero Rd, Executive Hangar One, Palo Alto, CA94303 Tech. 4039,4 Tel. (650) 565-0063
		Airframe Entry:	try:		
		Replaced co- with new FA. serviceable (u magneto. Rep	pilot's inbo A/PMA p/ indrilled).	oard seat rail n K1754001- Replaced #2 1 tab actuator	Replaced co-pilot's inboard seat rail with new FAA/PMA p/n MC0511243-4. Replaced the exhaust with new FAA/PMA p/n K1754001-23. Replaced exhaust hardware. Replaced #4 exhaust header with serviceable (undrilled). Replaced #2 exhaust clamp with serviceable. Repaired ground wire to the magneto. Replaced trim tab actuator hardware. I test flew this aircraft, all parameters appeared normal.
				M	Kevin R. Pinger :1&P 3236526 L.1
)	
-	1, 2022	4041.3			Annaal inspection
					from al inspection completed 1. A. w. Cessna
			Main	. Mamo	Maint. Manual . elvercod + lubed all fight control.
			choe	God Corb	cheeted cololes, colole Teurism & Subsea Pulleys. choesed
			il ho	AME. C	all lights. cleanned + Packed whose Bearings. Cheekerd
			6-1	1.4 W . F.	ELT 1.4 W. FAR 91(207)d Olay. Maxi-Battery obange
	i.		Jue (B NO. 2	due @ NO. 2023. Waspeated post lite swittent fuel
			عصنا	I.A.W. A	Lines 1. A. W. A D. 2001-23-03. alcay. C(W. AID, 2011-10-09
			Seal	Tracks	Seal Tracks + seal - Roller - Oray. Replaced industron

Repairs and Alterations g and Certificate Number of jes for other specific entries.)

6/20/2022 Tach: 4039.4 TTA: 4039.4

placed the exhaust t exhaust header with ound wire to the iters appeared normal.

Pinger .1&P 3236526 L1

soften charge igen contrat. -1w. A.D. 2011-10-09 ed Pulley &. cheeklood pleved 1. A.w. Cessma Replaced widuction

							\$5°	9/2/2022 VARH: 4067-0							YEAR RECORDING 20 TACH DATE TIME	
							EN: 21 80-2	ACH: 4067.		COVE	Anny	-	Sups dem.	our of	RDING TODAY'S	
	umit.	CHACKE	e raus	P 10 /	80X3010	Replace	all. P	1		equalition.	al wis	1 cert	6 X.	التمر دا	TOTAL TIME IN SERVICE	
100 5 CE 130 PM		charked Prop. spinner with Wed Servicable	Circuit Porenker P 1910 1648-809-000 (New) Replaced	PINO VIIIO SINO. BOLOOS (NEW). Replayed 60 ANP	80X30101 - 175 (MGW) Replaced Over voltage Sousor	Replaced vollage Regulator PINO DGR6-1 SMO	all. P170 10-1050A 5/10. H. WOSI809. (75%)	Replaced allewalls with Plane Power	B. XX	Joen and and Marie and Mar	Annual mispections was found to be in our morting in	I certify whi his Ale had been inspected 1. A.w.		our Deller. chances fuel frien. Press. leave checked Bulliust	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	Total Density and Alterations

									1117 2022 4093.2	YEAR R 20 222 T	
									4093-4	RECORDING TACH TIME .	CONTRACTOR OF THE PERSON NAMED IN
								Z =1		TODAY'S FLIGHT	THE REAL PROPERTY.
								10. FQ1	- Re	TOTAL TIME IN SERVICE	
							W. W.	KIT NO. FOT KI - LT. LO OK TO TO THE DOWN TO TO	1	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	Tests, Repairs and Alterations

YEAR 20 DATE