

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL HC-C34R-1RF

PROPELLER S/N 154345A

### PROPELLER MAINTENANCE RECORD

Position \_\_\_\_\_

PITCH RANGE

Propeller Model \_\_\_\_\_

High/Feather \_\_\_\_\_

Propeller S/N \_\_\_\_\_

Start Lock \_\_\_\_\_

Blade Design \_\_\_\_\_

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 \_\_\_\_\_

No. 2 \_\_\_\_\_

Aircraft Manufacturer Mooney

No. 3 \_\_\_\_\_

Aircraft Model M20C

No. 4 \_\_\_\_\_

S/N \_\_\_\_\_

No. 5 \_\_\_\_\_

Registration N 9670 M

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
8-24-99		0.0	2470.8	Installed this propeller on mooney m20c N9670M
11-08-2000		95.7	2566.5	Inspected propeller. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. William Montgomery ATP 324481720 IA
12-20-01	TACH 2627.7			Annual inspection completed. Inspected Hub, blades and spruce assembly, Lubricated and dressed blades. List of recurring A/Ds in aircraft log.
	TT 156.9			Date 12-20-01 Total Time 156.9 I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Details on file at Sun Western Flyers FAA approved repair station EK1R572D WO # R 2121 Signed [Signature]

2-4-03	TACH 2688.1			Annual Inspection completed. Dressed Blade LEADING EDGES. Inspected Blades spruce hub + Lugs. List of Recurring A/Ds in Aircraft Log.
	TT 217.3			Date 2-4-03 Total Time 217.3 I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Details on file at Sun Western Flyers, FAA approved repair station EK1R572D WO # R228874 / 22888 Signed B. Dan

PROP MODEL:  
HC-C3YR-1RF  
PROP SN: DY4345A  
REG NO: N9670M  
WORK ORDER: 110



Don Maxwell Aviation Services, Inc.  
P.O. Box 884  
Gladewater, Texas 75647  
Phone: 903-845-5844

DATE: 4/16/2004  
A/C TSN: 2748.9  
PROP TT: 278.1  
TACH: 2748.9

**Prop Entries**

(51) Inspect Hub & Blades for Damage & Leaks. Greased prop hub.

I certify this prop has been inspected in accordance with a 100 hr. inspection and found in an airworthy condition.

DATE: 4/16/2004

SIGNED: [Signature]

Work Order: 110

Printed by EBIS 3 (datcomedia.com)

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date Propeller TSN TSO A/C Hrs

PROP MODEL: HC-C3YR-1RF  
PROP S/N: DY4345A  
REG. NO: N9670M  
WORK ORDER: 362-04-2005

Don Maxwell Aviation Services, Inc.

P. O. Box 884  
Gladewater, Texas 75647-6200  
Phone: 903-845-5844

DATE: 4/16/2005  
A/C TSN: 2820.1  
PROP TT: 349.3  
TSPOH: 349.3  
TACH: 2820.1

Prop Entries

(4) Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall spinner.

I certify this prop has been inspected in accordance with a 100 hr. inspection and found in an airworthy condition. Don Maxwell A&P 1784050

DATE: 4/16/2005

SIGNED: *D. P. Myrbel*

Work Order: 362-04-2005

Printed by EBis 3 (datcomedia.com)

PROP MODEL: HC-C3YR-1RF  
PROP S/N: DY4345A  
REG. NO: N9670M  
WORK ORDER: 599-04-2006

Don Maxwell Aviation Services, Inc.

390 Central Road - East Texas Regional Airport  
Longview, Texas 75603  
Phone: 903-643-9902

DATE: 4/8/2006  
A/C TSN: 2842.2  
PROP TT: 371.4  
TACH: 2842.2

Prop Entries

(4) Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall spinner.

I certify this prop has been inspected in accordance with a 100 hr. inspection and found in an airworthy condition. Don Maxwell A&P 1784050

DATE: 4/8/2006

SIGNED: *D. P. Myrbel*

Work Order: 599-04-2006

Printed by EBis 3 (datcomedia.com)

PROP MODEL: HC-C3YR-1RF  
PROP S/N: DY4345A  
REG. NO: N9670M  
WORK ORDER: 811-04-2007



Don Maxwell Aviation Services, Inc.

390 Central Road - East Texas Regional Airport  
Longview, Texas 75603  
Phone: 903-643-9902

DATE: 4/27/2007  
A/C TSN: 2866.2  
PROP TT: 395.4  
TACH: 2866.2

Prop Entries

(4) Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall spinner.... (13) AD2006-18-15 Failure of the Prop Hub not applicable, 3 blade prop installed.

I certify this prop has been inspected in accordance with a 100 hr. inspection and found in an airworthy condition. Don Maxwell A&P 1784050

DATE: 4/27/2007

SIGNED: *D. P. Myrbel*

Work Order: 811-04-2007

Printed by EBis 3 (datcomedia.com)

Date 9/21-2010 Time in Service 951.7 hours

I certify that this aircraft and/or engine

has been inspected I/AW a Annual

inspection and was determined to be

in airworthy condition.

*9023-2010 Tach 2922.50*

