

ASA-SA-1

Aircraft Record General Information  Manufacturer  Serial 28-7305264  Date of Manufacture		Model PA 28 - 18 Registration Number	
Engine(s) currently installed:  Manufacturer  Manufacturer  Propeller(s) currently installed:	Model	360-A4A	Serial <u>L-294/9-36A</u> Serial
Manufacturer Sensenich  HUB Model  Blade Model	M Serial	odel 76 EM855 2920 K	-0-60 Serial
Blade Model	Serial	Serial	Serial
	Archald S		

YEAR 20	RECORDING TACH	TODAY'S FLIGHT	MAKE: PIPER	Fo	othill Aircraft Sales & Serv	ice, Inc.
DATE	TIME		MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15702-08-2015	174 Upl	pair Station No. AJ4R052M 9 W 13Th St and, CA 91786 one: 909-985-1977	
File			Airframe Entries			
			(1) COMPLIED WITH 50 H FLUID, TIRE PRESSURE	HOUR INSPECT S, AND OVERAI	ION. CHECKED FLIGHT LL CONDITION. GROUN	CONTROL OPERAT D RUN, SYSTEMS C
			Maintenance Release I certify that the AIRCRAFT 16 current FARs rules of the Fede repair are on file at this repair s	ral Aviation Regula	d/ repaired in accordance with tions and was found Airworth Order No. 15702-08-2015, D.	y for return to service. P
			DATE: 8/27/2015	SIGNED:	106/	/ Wor
				Joe Caliva Certified Repair	Station No. AJ4R052M	Printed by E

DATE: 8/27/2015 A/C TSN: 3757.7 TACH: 3757.7

ATIONS, BRAKE CHECK GOOD.

naintenance manual and Pertinent details of the

/ork Order: 15702-08-2015

EBis 3 (datcomedia.com)

EAR	RECORDING						
ATE	TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15874-12-2015		Repair Station No. AJ4R052M 1749 W 13Th SI Upland, CA 91786 Phone: 909-985-1977	, Inc.	DATE: 12/11/2015 A/C TSN: 3914-65 TACH: 3914-65	hnician or
		Airframe Entries					
		SECTION III INSPECTION FUNCTIONAL CHECK.  12/10/2015 (4) INSTAINSTRUCTIONS. FORM	ON CHECKLIST ELT BATTERY LLED NEW SU M 337 ON FILE	IIS AIRFRAME IAW FAR 43 AP T AS A GUIDE. C/W FAR 91.20 EXPIRATION DATE 12/2018. J JN VISORS P/N:- RPF-300-2. IA (5) INSTALLED NEW TAIL O OORDINATOR P/N:-1394T100-7	7 D ELT INSPECTION ADS CHECKED THREAW STC SA00072SE CONE, TOP AND BO	ON AND ROUGH E INSTALLATION OTTOM (8)	
		the manufactures maintenar	ice manual and cu	on 16484 was repaired and inspecte urrent FARs rules of the Federal Avia epair are on file at this repair station	ation Regulations and wounder Work Order No. 1	as found Airworthy	
		DATE. 12/11/2015	Joe Caliva	Carlon No. A IABOSOM		s 3 (datcomedia com)	
			Certified Rep	pair Station No. AJ4R052M			
1/3/							
2				1 of 1			

PATE	RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N. 28-7305264 REG. NO: 16484 WORK ORDER: 15915-01-2016	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	ce, Inc.	DATE: 1/6/2016 A/C TSN: 3959.8 TACH: 3959.8	nician or
		Airframe Entries				A LANGE
		(1) COMPLIED WITH 50 FLUID, TIRE PRESSUR REPLACED CABIN HEA	O HOUR INSPECTION. CHECKED FLIGHT ORES, AND OVERALL CONDITION. GROUND AT DUCT WITH NEW.	CONTROL OPERATIONS, BE RUN, SYSTEMS CHECK G	RAKE 00D (3)	
		current i Arts rules of the Fe	16484 was inspected/ repaired in accordance with t deral Aviation Regulations and was found Airworthy ir station under Work Order No. 15915-01-2016, Dat	for return to convice Destinant de	manual and etails of the	
		DATE: 1/6/2016			5915.01.2016	
			SIGNED: Question No. AJ4R052M		5915-01-2016 comedia.com)	
			SIGNED: Ques Byars  Christopher Byars	Work Order; 15	5915-01-2016 comedia.com)	
			SIGNED: Ques Byars  Christopher Byars	Work Order; 15	5915-01-2016 comedia.com)	
			SIGNED: Ques Byars  Christopher Byars	Work Order; 15	5915-01-2016 comedia.com)	
			SIGNED: Ques Byars  Christopher Byars	Work Order; 15	5915-01-2016 comedia.com)	

YEAR 20 DATE	RECORD TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15958-02-2016	Foothill Aircraft Sales & Service, Ind Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 2/5/2016 A/C FSN: 4012.2 TACH: 4012.2	echnician or
		Airframe Entries			
		FUNCTIONAL CHECK. ELT BA 02//2016 (7) REPLACED RIC INSPECTED, AND SERVICED TORQUE LINK SHIMS WITH N (11) REPLACE O-RINGS IN PA FIREWALL TO VACUUM VALV  Maintenance Release I certify that the aircraft and/or composite manufactures maintenance manufor return to service. Pertinent details Dated 2/5/2016.	NON THIS AIRFRAME IAW FAR 43 APPENECKLIST AS A GUIDE. C/W FAR 91.207 DATTERY EXPIRATION DATE 12/2018. ADSOLUTE AND AIR MAIN TIRE WITH NEW AIR HAWK 6.0 WHEEL BEARINGS (9) REPLACED LE IEW (10) C/W AD 75-04-02 BY REMOVING BRAKE CYLINDER (13) REPLACED. (14) REPLACED VAC REG FILTER VALUE OF THE PROPERTY OF THE	ELT INSPECTION AND CHECKED THROUGH DOX6, 6PLY TIRE. CLEANED, FT MAIN UPPER AND LOWER NG SEATS AND INSPECTING CED HOSE AND CLAMP FROM VITH NEW.	
		010	Caliva Para V Cala	Work Order: 15958-02-2016	
		Cert	ifjed Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

YEAR 20 DATE	RECORD TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15976-02-2016	Foothill Aircraft Sales & Servi  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	ce, Inc. DATE: 2/16/2016 A/C TSN: 4017 TACH: 4017	chnician or
		Airframe Entries			
		(1) REPLACED AFT T MAINTENANCE MAN	RIM CABLE, BARREL, GEAR SHAFT, BUSHI UAL.	NGS, RE-RIGGED, PER	
		FARS rules of the Federal	T 16484 was repaired in accordance with the manufa Aviation Regulations and was found Airworthy for retu n under Work Order No. 15976-02-2016, Dated 2/16/2	in to service Pertinent details of the repair are	
		DATE: 2/16/2016	SIGNED: / M. M.	Work Order: 15976-02-2016	
			Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

A CONTRACTOR OF THE PARTY OF TH

EAR 0 ATE	TAI		Foothill Aircraft Sales & Service, Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	Inc. DATE: 3/2/2016 A/C TSN: 4060.48 TACH: 4060.48	r of Technician or
		Airframe Entries (1) COMPLIED WITH FLUID, TIRE PRESSU	50 HOUR INSPECTION. CHECKED FLIGHT CO JRES, AND OVERALL CONDITION. GROUND R	NTROL OPERATIONS, BRAKE UN, SYSTEMS CHECK GOOD.	
			FT 16484 was inspected/ repaired in accordance with the Federal Aviation Regulations and was found Airworthy for pair station under Work Order No. 16011-03-2016, Dated		
		DATE: 3/2/2016	SIGNED: Orus Segue	Work Order: 16011-03-2016	
			Christopher Byars Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

PECORD TACH TIME  MODEL PA:28-180 MODEL PA:28-						
(1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK SATISFACTORY. REPLACED CARB AIR SCREEN (7) TIGHTENED AND SAFTYED STEERING CLEVIS PIN (8) R&R L/H BRAKE LININGS WITH NEW.  Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16112-05-2016, Dated 5/16/2016.  DATE: 5/16/2016  SIGNED  Work Order: 16112-05-2016	20	TACH	MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER:	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786	A/C TSN: 4173.37	echnician or
FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK SATISFACTORY. REPLACED CARB AIR SCREEN (7) TIGHTENED AND SAFTYED STEERING CLEVIS PIN (8) R&R L/H BRAKE LININGS WITH NEW.  Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16112-05-2016, Dated 5/16/2016.  DATE: 5/16/2016  SIGNED  Work Order: 16112-05-2016			Airframe Entries			
I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16112-05-2016, Dated 5/16/2016.  DATE: 5/16/2016 SIGNED Work Order: 16112-05-2016  Michael Kearney			SATISFACTORY, REF	JRES, AND OVERALL CONDITION. GROUND PLACED CARB AIR SCREEN (7) TIGHTEN	O RIIN SYSTEMS CHECK	
Wichael Kearney			I certify that the AIRCRAF current FARs rules of the repair are on file at this re	pair station under Work Order No. 16112-05-2016, Da	ated 5/16/2016.	
				Michael Kearney  Certified Repair Station No. A MR052M		
				The Aban Cost of the Cost of t		
1 of 1				1 of 1		

RECORDING TODA	Y'S TOTAL Description of I	namastiana Tasta Da	and Alla	rations
MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16133-05-2016	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	Service, Inc.	DATE: 5/27/2016 A/C TSN: 4189 TACH: 4189	umber of Technician or
Airframe Entries				
(1) REMOVED AND FILLED RESERVOIR	REPLACED ALL 'O' RINGS IN L/H MASTER, FUNCTIONS CHECK SATISFACTORY.	ER BRAKE CYLINDER, BLED	BRAKES, AND	
FARS rules of the Federa	FT 16484 was repaired in accordance with the ral Aviation Regulations and was found Airworthy f	or return to service Pertinent detail	I and current	
DATE: 5/27/2016	on under Work Order No. 16133-05-2016, Dated	5/27/2016.	er: 16133-05-2016	
	MANIA	5/27/2016.	er: 16133-05-2016	
	SIGNED Michael Kearney	5/27/2016. 	er: 16133-05-2016	
	SIGNED Michael Kearney	5/27/2016. 	er: 16133-05-2016	
	SIGNED Michael Kearney	5/27/2016. 	er: 16133-05-2016	
	SIGNED Michael Kearney	5/27/2016. 	er: 16133-05-2016	

YEAR 20 DATE	RECC TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16061-04-2016	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 4/11/2016 A/C TSN: 4111.19 TACH: 4111.19	of Technician or
N. S. C.		Airframe Entries (1) C/W ANNUAL INSPECTION	ON ON THIS AIRFRAME IAW FAR 43 APPENDIX D	USING PIPER M.M.	
		04/11/2016 (4) REPLACED LIGHT AND CHECKED. NO P REPLACED THROTTLE AND	HECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSATTERY EXPIRATION DATE 12/2018. ADS CHEC PILOT PUSH TO TALK WITH NEW (5) REMOVE PROBLEMS FOUND (6) CLEANED AND SEALED MIXTURE PLACARD WITH NEW (9) REMOVED NEW TUBE. CLEANED, INSPECTED AND GREASY SATISFACTORY	KED THROUGH ED STALL WARNING ALL WINDOWS (7)	
		Maintenance Release I certify that the aircraft and/or comp the manufactures maintenance man for return to service. Pertinent detail Dated 4/11/2016.	ponent(s) on 16484 was repaired and inspected in accordance and current FARs rules of the Federal Aviation Regulation is of the repair are on file at this repair station under Work C	ce with a Annual inspection per ons and was found Airworthy Order No. 16061-04-2016,	
		Chi	ristopher Byars rtified Repair Station No. AJ4R052M  Print	Work Order: 16061-04-2016 ed by EBis 3 (datcomedia.com)	
			1 of 1		

R RECORDII TACH TIME	MAKE: PIPER MODEL: PA-28-18C S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16075-04-2016	Foothill Aircraft Sales & Service Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	ee, Inc. DATE: 4/14/2016 A/C TSN: 4111.19 TACH: 4111.19	inician or
	Airframe Entries			
	(2) REPLACED VOLT VOLTAGE PROTECT	AGE REGULATOR WITH NEW ZEFTRONICS	VOLTAGE REGULATOR WITH OVER	
	FARs rules of the Federa	T 16484 was repaired in accordance with the manufact I Aviation Regulations and was found Airworthy for return under Work Order No. 16075-04-2016, Dated 4/14/20 SIGNED:	n to service. Pertinent details of the repair are	
		Mike Hartman Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	

YEAR 20 DATE	RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16156-06-2016	Foothill Aircraft Sales & S  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 6/10/2016 A/C TSN: 4210.38 TACH: 4210.38	nicia
		REPLACED BOTH BR	PECTION ON THIS AIRFRAME IAW FAR A TION CHECKLIST AS A GUIDE. ADS CHE TAKE DISC AND BRAKE LININGS WITH N CED BOTH MAIN STRUTS WITH N2.	43 APPENDIX D USING PIPER M.M. CKED (5) CW AD 99-24-10 (6) NEW (11) TIGHTENED VACUUM INTAKE	
		Maintenance Release I certify that the aircraft and the manufactures maintena for return to service. Pertine Dated 6/10/2016.	d/or component(s) on 16484 was repaired and ins	pected in accordance with a Annual inspection per al Aviation Regulations and was found Airworthy tation under Work Order No. 16156-06-2016,	
		DATE: 6/10/2016	Michael Kearney Certified Repair Station No. AJ4R052M	Work Order: 16156-06-2016 Printed by EBis 3 (datcomedia.com)	
			1 of 1		

1	10 m				
YEAR 20 DATE	RECORD TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16214-07-2016	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 7/18/2016 A/C TSN: 4265.54 TACH: 4265.54	echnician or
		Airframe Entries			
		FLUID, TIRE PRESSU	50 HOUR INSPECTION. CHECKED FLIGHT COURSES, AND OVERALL CONDITION. GROUND F 3) INSTALLED TWO NEW BUSHINGS ON BOT	RUN, SYSTEMS CHECK	
		current FARs rules of the	T 16484 was inspected/ repaired in accordance with the Federal Aviation Regulations and was found Airworthy for pair station under Work Order No. 16214-07-2016, Date	or return to service. Pertinent details of the ad 7/18/2016.	
		DATE: 7/18/2016	SIGNED: Sheravan Kun	Work Order: 16214-07-2016	
			Shravan Poulu Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16237-08-2016	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 8/4/2016 A/C TSN: 4294.33 TACH: 4294.33	Number of Technician of
Airframe Entries	DUALII DIDEOTIONAL OVER		
Maintenance Release I certify that the AIRCRA FARs rules of the Federa	RHAUL DIRECTIONAL GYRO MODEL 4000C P/N  FT 16484 was repaired in accordance with the manufactor in Aviation Regulations and was found Airworthy for return on under Work Order No. 16237-08-2016. Dated 8/4/2016.	oures maintenance manual and current	
DATE: 8/4/2016	SIGNED: Showay Kum		
-	Shravan Poulu Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
	1 of 1		

YEAR 20 DATE	RECORDIN TACH TIME	PROP MODEL: 76EM8S5-0-60 PROP S/N: 12920K REG. NO: 16484 WORK ORDER: 16262-08-2016	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	e, Inc.	DATE: 8/24/2016 A/C TSN: 4311.68 PROP TT: 1667.02 TACH: 4311.68	hnician or
	-10-11	Prop Entries	AR MOREOTION ON THE T			
		M.M SECTION III INSF	HR INSPECTION ON THIS PROPELLER IAW F PECTION CHECKLIST AS A GUIDE. ADS CHEC	AR 43 APPENDIX D U CKED THROUGH 08/2	ISING PIPER 0/2016.	
		Maintenance Release I certify that the PROPELL maintenance manual and of Pertinent details of the repo	ER on 16484 was inspected in accordance with an 100 current FARs rules of the Federal Aviation Regulations a air are on file at this repair station under Work Order No	Phr./Annual inspection per and was found Airworthy for 16262-08-2016, Dated 8	the manufactoures or return to service. /24/2016.	
		DATE: 8/24/2016	SIGNED: Christopher Ryars		ler: 16262-08-2016	
			Christopher Byars Certified Repair Station No. AJ4R052M		(datcomedia.com)	
			1 of 1			

and the second of the second o

YEAR 20 DATE	RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16346-09-2016	Foothill Aircraft Sales & Service Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 9/27/2016 A/C TSN: 4361.5 TACH: 4361.5	hnician or
		FLUID, TIRE PRESSUR	0 HOUR INSPECTION. CHECKED FLIGHT C RES, AND OVERALL CONDITION. GROUND REPLACED LEFT MAIN TIRE WITH NEW A/H	RUN, SYSTEMS CHECK	
		current FARs rules of the Fe	16484 was inspected/ repaired in accordance with tederal Aviation Regulations and was found Airworthy air station under Work Order No. 16346-09-2016, Date SIGNED:	for return to service. Pertinent details of the	
			Christopher Byars Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M	DATE: 11/30/2016 A/C TSN: 4411.07 TACH: 4411.07	ions
S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16445-11-2016	1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977		nber of Technician o
Airframe Entries			
SECTION III INSPECTION CHECKED THROUGH 11/ RETENTION MECHANISM SATISFACTORY.NEXT DU INSPECTION OF THE PUI VALVES.DETERMINE FUN	TION ON THIS AIRFRAME IAW FAR 43 APPENDIX D IN CHECKLIST AS A GUIDE. ELT BATTERY EXPIRATION/30/2016 (4) C/W AD 75-24-02 REAR LEG QUICK DISTRICTION IAW PIPER SL-763. DETERMINE FUNDE IN 100HRS OR ANNUAL WHICHEVER COMES FIR SH-PULL CABLE, VACUUM LINES, AND SADDLE FIT NCTIONALLY SATISFACTORY (7) INSTALLED A NEW TIGHTENED RIGHT SUN VISOR.	SCONNECT SEAT CTIONALLY (ST (5) C/W AD99-24-10 TINGS, AND SHUTTLE	
the manufactures maintenance	component(s) on 16484 was repaired and inspected in accordant manual and current FARs rules of the Federal Aviation Regulation details of the repair are on file at this repair station under Work (	ions and was found Airworthy	
DATE: 11/30/2016	SIGNED: Sheravan Humah	Work Order: 16445-11-2016	
		nted by EBis 3 (datcomedia.com)	
	1 of 1		

YEAR 20 DATE	RECO'TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16499-12-2016	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 12/29/2016 A/C TSN: 4430.4 TACH: 4430.4	of Toobalai
		Airframe Entries (1) INSTALLED OVERHAU	LED HEADING INDICATOR P/N IU262-00	05-20, S/N 46602E.	
		on file at this repair station under DATE: 12/29/2016	SIGNED: Christopher Byars	Work Order: 16499-12-2016	
			Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	

1 of 1

E. MAKE: PIPER MODEL: PA-28-180 ) S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16520-01-2017	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977		DATE: 1/23/2017 A/C TSN: 4441.23 TACH: 4441.23	Alterations cate Number of Technici
Airframe Entries  (1) REPLACED FOR P/N68488-002.	RWARD STABILIZER TRIM CABLE P/N 62	2701-111 AND INDICATOR PO	OINTER	
	al Aviation Depolation 1 to 1 to 1	manufactoures maintenance manufactoures	and different	
on file at this repair stat	on under Work Order No. 16520-01-2017, Dated	for return to service. Pertinent del 1/23/2017.	tails of the repair are	
- or me at this repair state	on under Work Order No. 16526-01-2017, Dated	for return to service. Pertinent del	tails of the repair are	
on me at this repair state	on under Work Order No. 16520-01-2017, Dated  SIGNED:  Joe Caliva	for return to service. Pertinent del	tails of the repair are	
- State at this repair state	on under Work Order No. 16520-01-2017, Dated  SIGNED:  Joe Caliva	for return to service. Pertinent del	tails of the repair are	

YEAR 20 DATE		RECORI TACH TIME	DING	TODAY'S
	-			
	-			

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16583-02-2017



## Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 2/24/2017 A/C TSN: 4454.7 TACH: 4454.7

## Airframe Entries

(1) REMOVED AND RESEALED LOWER NOSE STRUT. SERVICED WITH NITROGEN AND FLUID. R & R TWO LINK BOLTS WITH NEW.

Maintenance Release

I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16583-02-2017. Dated 2/24/2017.

DATE: 2/24/2017

SIGNED:

Mike Hartman Certified Repair Station No. AJ4R052M Work Order: 16583-02-2017

Printed by EBis 3 (datcomedia.com)

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16610-03-2017



SIGNED:

## Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977

DATE: 3/8/2017 A/C TSN: 4472.98 TACH: 4472.98 nd Alterations rtificate Number of Technician or

tries.)

### Airframe Entries

(1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK SATISFACTORY.... (3) REPLACED RIGHT MAIN TIRE WITH NEW A/H 6.00X6 6 PLY TIRE. SERVICED WHEEL BEARINGS.

### Maintenance Release

I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16610-03-2017, Dated 3/8/2017.

DATE: 3/8/2017

Christopher Byars

Work Order: 16610-03-2017

Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia com)

EAR 0 ATE	RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16815-07-2017	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 7/10/2017 A/C TSN: 4561 TACH: 4561	lician or
		Airframe Entries			
		(1) COMPLIED WI ADJUSTED IDLE	TH 50 HOUR INSPECTION (3) REPLACED O-RII MIXTURE.	NGS ON PRIMER PLUNGER,	
		FARs rules of the Fed	RAFT 16484 was repaired in accordance with the manufactorial Aviation Regulations and was found Airworthy for return ation under Work Order No. 16815-07-2017, Dated 7/10/2013	to service. Pertinent details of the repair are	
			Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia com)	
				Printed by EBis 3 (datcomedia com)	
				Printed by EBis 3 (datcomedia com)	
				Printed by EBis 3 (datcomedia com)	

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16661-04-2017



# Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 5/18/2017 A/C TSN: 4509.9 TACH: 4509.9

## Airframe Entries

(1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE 12/2018. ADs CHECKED THROUGH 05/17/2017. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA3.... (4) INSTALLED OVERHAULED · 0-360-A4A, S/N RL-34094-36E. NEW AVSTAR CARBURETOR P/N 61C26046. S/N AV22747371.LYCOMING FUEL PUMP P/N LW-15472 S/N RC33163666. SLICK IGNITION HARNESSES LEFT- P/N 67P20429, RIGHT- P/N67P20428. SLICK MAGNETOS LEFT-P/N 66GC25SFNN, S/N 17010069, RIGHT-P/N 66GP-OSANN, S/N 17010674.ENGINE MOUNTS P/N J-9613-40. ENGINE WAS RUN UP AND ADJUSTED IN ACCORDANCE WITH LYCOMING SERVICE INSTRUCTION NO. 10427C. ALL WORK DONE IN ACCORDANCE WITH PIPER M.M. SECTION VIII.... (5) REPLACED FRONT LEFT PILOT'S WINDOW AND FRONT RIGHT DOOR WINDOW WITH NEW IN ACCORDANCE WITH STC SA00047NY .... (6) REMOVED CORROSION FROM FORE SECTION OF BATTERY TRAY .... (7) REPLACED LEFT FORE GEAR FAIRING BRACKET WITH NEW .... (8) REPLACED PARKING BRAKE MASTER WITH SERVICEABLE UNIT.... (9) C/W AD 75-24-02, REAR SEAT INSPECTION.... (10) OVERHAULED BRAKE CALIPER WITH NEW PACKING .... (11) REPLACED LEFT BRAKE LININGS WITH NEW .... (12) INSTALLED PROPAFTER OVERHAUL BY JOHNSON PROPELLER SERVICE. M/N 76EM855-0-60, S/N 120920K... (13) REPLACED OIL COOLER WITH NEW. P/N 8000075, S/N 10428-409.... (14) REPLACED THROTTLE AND MIXTURE CONTROL CABLES WITH NEW .... (15) INSTALLED ITEMS AFTER REPAIRED BY UPHOLSTERY SHOP... (17) REPLACED WINDSHIELD WITH NEW L.P. AERO PLASTICS WINDSHIELD. ALL WORK DONE IN ACCORDANCE WITH L.P. AERO INSTALLATION INSTRUCTIONS

#### Maintenance Release

I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16661-04-2017, Dated 5/18/2017.

	5.)			
				LA F
			1319 C	Kei
THE P				
	0000	BUB.	1961	VIII
1				
3000		9		34

and Alterations

DATE: EMBIONAZ

CICNICD

Work Order 16661-04-2017

YEAR 20	RECO TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16905-08-2017	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 8/25/2017 A/C TSN: 4604.3 TACH: 4604.3	f Technician or
DATE	Tiwit	Airframe Entries			
		M.M. SECTION III I FUNCTIONAL CHE 08/2017 (4) C/W INSPECTION IAW OR ANNUAL WHIC LEAK CHECK GOO P/N 966-10500 (7 MICHELIN. REMON CHECKED-DETER ANNUAL INSPECT 09/01/2018 (12) (12)	INUAL INSPECTION ON THIS AIRFRAME IAW FAR INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91 CK. ELT BATTERY EXPIRATION DATE 12/2018. AE AD 75-24-02 REAR LEG QUICK DISCONNECT SEA PIPER SL-763. DETERMINE FUNCTIONALLY SATISTICHEVER COMES FIRST (5) INSTALLED NEW PITCOD (6) REMOVED AND REPLACED RH MAIN WH) R&R LH MAIN TIRE WITH NEW AIRHAWK 6.00X6 (ZED, CLEANED, INSPECTED, GREASED, REINSTAMINE FUNCTIONALLY SATISFACTORY (10) R&R ION PERFORMED BY CHUCK'S FIRE EXTINGUISH C/W AD 2017-14-04 OIL COOLER HOSES, INSTALLE ENGINE ENTRY 05/18/2017. VISUAL INSPECTION	.207 D ELT INSPECTION AND DS CHECKED THROUGH AT RETENTION MECHANISM DFACTORY.NEXT DUE IN 100HRS DT TUBE, HEAT SYSTEM AND EEL BRAKE LININGS WITH NEW 6PLY WITH NEW TUBE AIRSTOP LLED THE BEARINGS.OPS FIRE EXTINGUISHER AFTER ER SERVICE CO. NEXT DUE BY	
	th fo	e manuactures manner	ad/or component(s) on 16484 was repaired and inspected in a nance manual and current FARs rules of the Federal Aviation Finent details of the repair are on file at this repair station under SIGNED:  Shravan Poulu Certified Repair Station No. AJ4R052M	Regulations and was found Airworthy Work Order No. 16905-08-2017,	

R RECORDING	TODAY FLIGH	MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 10/3/2017 A/C TSN: 4640.3 TACH: 4640.3
TIME		S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 16961-10-2017	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786	TACH: 4040.
			Phone: 909-985-1977	
		Airframe Entries (1) C/W AD76-07-	-12R1 BY INSTALLING NEW BENDIX IGNITION SWIT	TCH. TEST NEXT DUE 4740.3
		FARs rules of the Fe	se CRAFT 16484 was repaired in accordance with the manufactor deral Aviation Regulations and was found Airworthy for return to station under Work Order No. 16961-10-2017, Dated 10/3/2017.	service. Pertinent details of the repair an
			0 1 1	
		DATE: 10/3/2017	SIGNED: mile Shuto	
		DATE: 10/3/2017	= 001	Work Order: 16961-10-201
		DATE: 10/3/2017	SIGNED: Mike Bluto	Work Order: 16961-10-201
		DATE: 10/3/2017	SIGNED: Mike Bluto	Work Order: 16961-10-201
		DATE: 10/3/2017	SIGNED: Mike Bluto	Work Order: 16961-10-201
		DATE: 10/3/2017	SIGNED: Mike Bluto	Work Order: 16961-10-2017 Printed by EBis 3 (datcomedia.com
		DATE: 10/3/2017	SIGNED: Mike Bluto	Work Order: 16961-10-2017

YEAR 20 DATE	RECORDIN TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG, NO: 16484 WORK ORDER: 16981-10-2017	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 10/12/2017 A/C TSN: 4649.32 TACH: 4649.32	chnician or
			H 50 HR ON THIS AIRCRAFT BY USING FOOTHILL IIDE.	AIRCRAFT CHECKLIST AND	
		Current I ANS Tules Of the	AFT 16484 was inspected/ repaired in accordance with the new Federal Aviation Regulations and was found Airworthy for response testion under World Order.	above to annulus David Little Co.	
		DATE: 10/12/2017	epair station under Work Order No. 16981-10-2017, Dated 1 SIGNED: Showard Kumoh	0/12/2017. Work Order: 16981-10-2017	
			Shravan Poullu Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

1.55

Ilterations YEA DATE: 10/17/2017 Foothill Aircraft Sales & Service, Inc. MAKE: PIPER ate Number of Technician or A/C TSN: 4652.2 MODEL: PA-28-180 TACH: 4652.2 S/N: 28-7305264 Repair Station No. AJ4R052M REG. NO: 16484 1749 W 13Th St WORK ORDER: Upland, CA 91786 16984-10-2017 Phone: 909-985-1977 Airframe Entries (1) REPLACED VACUUM PUMP WITH NEW, P/N 10-00609, S/N QCX319. Maintenance Release I certify that the ENGINE in 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16984-10-2017, Dated 10/17/2017. Work Order: 16984-10-2017 DATE: 10/17/2017 SIGNED: Christopher Byars Printed by EBis 3 (datcomedia.com) Certified Repair Station No. AJ4R052M 1 of 1

EAR 0	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician Repair Facility. (See back pages for other specific entries.)
LO	3 ID# 2599 0	cs 7000 7-August- -7305264	Merrill Ave 2017 WO# PIPER	Box 20 Hangar A-240 Chino, CA 91710 VZKR081Y 7811 AC TT 2050.9 PA-28-180 TACH 2050.9 Pg 1 / 1
Remo	ved from airc	raft: GTX	× 327	
Inst	alled in airc	raft: GTX	x 345	
PERF	ORMED ATC TRA	NSPONDER	TEST AND I	NSPECTION. UNIT FOUND TO COMPLY WITH FAR 91.413 AND APPENDIX F
Perf	ormed on Mod	lel: GTX	345 Serial	#: 3EG005286.
For	more informat	ion, see	FAA form 3	37. Dated 08/05/17
VZKR	081Y Mark Kr	ueger		

Iterations DATE: 11/2/2017 Foothill Aircraft Sales & Service, Inc. MAKE: PIPER A/C TSN: 4668.8 ate Number of Technician or MODEL: PA-28-180 TACH: 4668.8 Repair Station No. AJ4R052M S/N: 28-7305264 REG. NO: 16484 1749 W 13Th St WORK ORDER: Upland, CA 91786 17026-10-2017 Phone: 909-985-1977 Airframe Entries (1) REPLACED ATTITUDE GYRO WITH OVERHAULED UNIT, P/N 5000E-852D66, S/N X48823F, IN ACCORDANCE WITH PIPER M.M. CH.12 P. 10-31. Maintenance Release I certify that the AIRCRAFT 15484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17026-10-2017, Dated 11/2/2017. Work Order: 17026-10-2017 SIGNED: DATE: 11/2/2017 Printed by EBis 3 (datcomedia.com) Christopher Byars Certified Repair Station No. AJ4R052M 1 of 1

YEAR 20 DATE	REC TACI TIMI	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17088-12-2017  MAKE: PIPER Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	of Technician o
		(1) C/W 100HR/ ANNUAL INSPECTION ON THIS AIRFRAME IAW 14 CFR PART 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ELT BATTERY EXPIRATION DATE 12/2018. R&R INDUCTION AIR FILTER WITH NEW P/N:- BA-3. ALL ADS CHECKED THROUGH 12/2017 (7) C/W AD 76-07-12R1 BENDIX IGNITION SWITCH BY OPS CHECKED, NO DEFECTS NOTED AT THIS TIME. NEXT INSP DUE IN 100 HRS (8) C/W AD 2017-14-04 OIL COOLER HOSES VISUAL INSP-NO DEFECTS NOTED AT THIS TIME.NEXT INSP DUE IN 100HRS (9) C/W AD 75-24-02 REAR LEG QUICK DISCONNECT. NO DEFECTS NOTED AT THIS TIME.NEXT INSP DUE IN 100HRS (10) AD 99-24-10 VACUUM SYSTEM NOT APPLICABLE IAW PRECISE FLIGHT INSTALLATION REPORT NO.08072  SHUTTLE VALVE S/N:- 15060 (11) R&R VACUUM MAIN FILTER WITH NEW P/N:- AAD9-18-1. NEXT DUE AT 5301.0 (12) R&R VACUUM GARTER FILTER WITH NEW P/N:- ARB3-5-1. NEXT DUE AT 5001.0	
		Maintenance Release I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17088-12-2017,  DATE: 12/20/2017  SIGNED: Substituting Work Order: 17088-12-2017	
		Shravan Poulu Certified Repair Station No. AJ4R052M  Work Order: 17088-12-2017  Printed by EBis 3 (datcomedia.com)	

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		#1 TRAIN I CERTIFY AND WET PILOTS A STANDEY Maintend I certify if	Entries TY THAT THE ATC TR APPENDIX F. SPONDER THAT THE ALTIMETE RE FOUND TO COM LT. TO: 18, 0 C ALT. TO: 18, 0 C TO ALT. TO:	os inspected in accordance with the manufactures maintenance manual and current FAR rules of and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair

DATE: 5/1/2018 YEAL Foothill Aircraft Sales & Service, inc. **Iterations** A/C TSN: 4798.25 MAKE: PIPER MODEL: PA-28-180 TACH: 4798.25 20 Repair Station No. AJ4R052M te Number of Technician or S/N: 28-7305264 1749 W 13Th St REG. NO: 16484 DATE Upland, CA 91786 WORK ORDER: Phone: 909-985-1977 17304-04-2018 Airframe Entries (1) C/W 100HR/ ANNUAL INSPECTION ON THIS AIRFRAME IAW 14 CFR PART 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ELT BATTERY EXPIRATION DATE 12/2018. ALL ADs CHECKED THROUGH 04/2018.... (4) C/W AD 75-24-02 FOR REAR SEATS.... (5) C/W AD 76-07-12R1 FOR BENDIX IGNITION.... (6) C/W AD 2017-14-04 FOR OIL COOLER HOSES.... (11) REPLACED 4 BOLTS, WASHERS, NUTS, ON LOWER PORTION OF LEFT MAIN GEAR STRUT.... (12) ADJUSTED VAC REG TO 5 INCHES OF MERCURY. Maintenance Release I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17304-04-2018, Dated 5/1/2018 DATE: 5/1/2018 SIGNED: Work Order: 17304-04-2018 Christopher Byars Printed by EBis 3 (datcomedia.com) Certified Repair Station No. AJ4R052M 1 of 1

YEAR 20 DATE	Ri Ti	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17390-06-2018	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	p, Inc. DATE: 6/19/2018 A/C TSN: 4855.06 TACH: 4855.06	er of Technician or
		Airframe Entries			
		TIRE AND SERVICED	50 HOUR INSPECTION (3) CHANGED TIRE WHEEL BEARINGS (4) CHANGED WITH N KE LININGS WITH NEW	WITH NEW 600X6 6 PLY AIRHAWK EW 600X6 6PLY AIRHAWK TIRE (5)	
		current FARs rules of the F	T 16484 was inspected/ repaired in accordance with the Federal Aviation Regulations and was found Airworthy foair station under Work Order No. 17390-06-2018, Date SIGNED:	or return to service. Pertinent details of the ed 6/19/2018.	
		DATE: 6/19/2018	SIGNED:	Work Order: 17390-06-2018	
_				D: 1 1 ED: 0 (determedia)	
			Shravan Poulu Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
				Printed by EBis 3 (datcomedia.com)	
				Printed by EBis 3 (datcomedia.com)	
				Printed by EBis 3 (datcomedia.com)	
				Printed by EBis 3 (datcomedia.com)	
				Printed by EBis 3 (datcomedia.com)	

YEAR 20DATE	RECORDING TACH TIME	FLIG	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17422-07-2018	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 7/15/2018 A/C TSN: 4896.61 TACH: 4896.61
			Airframe Entries	TION ON THIS AIRFRAME IAW FAR 43 APPENI	
			07/19/2018. REPLACED ALLANDING GEARS AND GEMI-450 SEC 3.4. NEW BAT NITROGEN (11) INSTALL GOOD. REMOVED LH SEASB1245A 1-10. ADJ CABLE	CHECKLIST AS A GUIDE. C/W FAR 91.207 D ET BATTERY EXPIRATION DATE 12/2018. ADS COR INDUCTION FILTER WITH NEW P/N BA-3 REASE (6) R & R RH TIRE WITH NEW (7) ETERIES EXP 07-2019 (ONE YEAR) (10) SERVED NO STEP PLACARDS ON RH FLAP (13) OF WAITING PARTS (16) C/W AD2013-02-13 ETENSION. DUE AGAIN 6896.0 OR 07-2025 (176-07-12R1 BENDIX IGN SWITCH BY TEST.	HECKED THROUGH (5) CLEAN BOTH MAIN T TESTED PER 91.207(d) AND ICED MAIN STRUTS WITH C/W AD 75-24-02. RH SEAT LEV TURNBARRELS PER
			Maintenance Release I certify that the aircraft and/or of the manufactures maintenance of for return to service. Pertinent of Dated 7/15/2018.	omponent(s) on 16484 was repaired and inspected in accommand and current FARs rules of the Federal Aviation Reletails of the repair are on file at this repair station under SIGNED:	ordance with a Annual inspection per gulations and was found Airworthy Vork Order No. 17422-07-2018,
			A STATE OF THE PARTY OF THE PAR		VVOEV   17400: 17400 07 0040

DATE: 8/29/2018 YEAR itions Foothill Aircraft Sales & Service, Inc. MAKE: PIPER A/C TSN: 4945.99 MODEL: PA-28-180 Repair Station No. AJ4R052M TACH: 4945.99 imber of Technician or S/N: 28-7305264 1749 W 13Th St REG. NO: 16484 DATE Upland, CA 91786 WORK ORDER: Phone: 909-985-1977 17498-08-2018 Airframe Entries (1) COMPLIED WITH 50 HOUR INSPECTION.... (3) ADDED NITROGEN NOSE STRUT Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17498-08-2018, Dated 8/29/2018. relavas Kurnos Work Order: 17498-08-2018 DATE: 8/29/2018 Printed by EBis 3 (datcomedia.com) Shravan Poulu Certified Repair Station No. AJ4R052M Advantage Aviation, Inc. 7000 Merrill Ave. Box 20 Hangar A-240 Chino, CA 91710 VZKR081Y LOG ID# 2872 14-August-2018 WO# 8152 AC TT 2326.3 S/N 28-7305264 Pq 1/1 N16484 PIPER PA-28-180 TACH 2326.3 Removed from aircraft: Directional Gyro Installed in aircraft: G5 HSI System, Trutrak Vizion autopilot system. For more information, see FAA form 337. Dated 08/14/18 Mark Krueger

AR	RECORF						Technician o
E	TACH	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17547-10-2018	Rel 174 Upl	pothill Aircraft Sales & Serv pair Station No. AJ4R052M 49 W 13Th St land, CA 91786 one: 909-985-1977	ice, Inc.	DATE: 10/3/2018 A/C TSN: 4992.65 TACH: 4992.65	Teermonante
		Airframe Entries					
		SECTION III INSPECTI FUNCTIONAL CHECK. 10/03/2018. REPLACEI ON BOTH LEFT AND R TIGHTENED HARDWA NEW AN3-11A BOLT O WITH NEW (13) STO INSTALLED ESCUTCH BY INSTALLATION AND	ON CHECKLIST AS ELT BATTERY EX DAIR INDUCTION SIGHT LANDING G RE AT CABIN DOO N UPPER RUDDE OP-DRILLED CRAC EON AT CABIN DO DADJUSTMENT O	AIRFRAME IAW FAR 43 / S A GUIDE. C/W FAR 91. (PIRATION DATE 07/2019) FILTER WITH NEW P/N EAR UPPER STRUT FAI OR LOCK (11) INSTALI R HINGE (12) REPLACTOR INTERIOR HANDLE OF SEAT CLIP. CHECKED N-UP. OPS CHECK GOO	207 D ELT INSPECTION ADS CHECKED THR BA-3 (9) INSTALLED RINGS (10) LUBED ALED NEW BEARING PARTIES AT COMPLIED WITH ADDITION OF THE ADD	ON AND OUGH O FAIRING CLIP AND /N: 452-387 AND ABIN DOOR SILICON (15)	
		Maintenance Release I certify that the aircraft and, the manufactures maintenar for return to service. Pertine Dated 10/3/2018.  DATE: 10/3/2018	for component(s) on 1s nce manual and currer ent details of the repail	6484 was repaired and inspect nt FARs Jules of the Federal A ir are on file at this repair stat	on under Work Order No. 1	annual inspection per as found Airworthy 7547-10-2018, Order: 17547-10-2018	
			Abraham Abel	Ny		3 (datcomedia.com)	
			Certified Repair	Station No. AJ4R052M	Timed by EBI	o (datcomedia.com)	
	I BUILDING			1 of 1			

YEAR MAKE: PIPER Foothill Aircraft Sales & Service, Inc. lions MODEL: PA-28-180 DATE: 11/27/2018 S/N: 28-7305264 nber of Technician or A/C TSN: 5087.3 Repair Station No. AJ4R052M DATE REG. NO: 16484 1749 W 13Th St TACH: 5087.3 WORK ORDER: Upland, CA 91786 17630-11-2018 Phone: 909-985-1977 Airframe Entries (1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE 12/2018. ADs CHECKED THROUGH 11/26/2018. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-3.... (13) INSTALLED NEW STRAP AT BAGGAGE DOOR .... (14) INSTALLED NEW CO DETECTOR .... (15) REPLACED BROKEN COWL LATCH WITH NEW... (16) INSTALLED NEW WING WALK ON WING AND STEP. Maintenance Release I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Ayiation/Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station upder Work Order No. 17630-11-2018, DATE: 11/27/2018 SIGNED: Work Order: 17630-11-2018 Abraham Abel Printed by EBis 3 (datcomedia.com) Certified Repair Station No. AJ4R052M 1 of 1

YEAR 20 DATE	RECORD TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG, NO: 16484 WORK ORDER: 17649-12-2018	Foothiil Aircraft Sales & Service, I Repair Station No. AJ4R052M 1749 W 131h St Upland, CA 91786 Phone: 909-985-1977	DATE: 12/4/2018 A/C TSN: 5087.3 TACH: 5087.3	echnician
		Airframe Entries (1) REMOVED NOSE	STRUT, DISASSEMBLED AND CLEANED. ASSE	MBLED WITH NEW PACKINGS	
		Maintenance Release	T 16484 was repaired in accordance with the manufactour Aviation Regulations and was round Airworthy for return to under Work Order No 17849-12-2018, Dated 12/47678.  SIGNED:  Abraham Abel	res maintenance manual and current service. Pertinent details of the repair are  Work Order: 17649-12-2018	
			Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

YEAR MAKE: PIPER Foothill Aircraft Sales & Service, Inc. ions DATE: 12/28/2018 MODEL: PA-28-180 20 A/C TSN: 5133.6 nber of Technician or S/N: 28-7305264 Repair Station No. AJ4R052M TACH: 5133.6 REG. NO: 16484 1749 W 13Th St DATE WORK ORDER: Upland, CA 91786 17687-12-2018 Phone: 909-985-1977 Airframe Entries (1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK GOOD .... (3) REPAIRED CO PILOT PUSH TO TALK... (4) DRESSED PROP LEADING EDGES AND PAINTED BLADE FACES .... (5) TIGHTENED HARDWARE AT RIGHT AND LEFT VISORS. Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17687-12-2018, Dated 12/28/2018. DATE: 12/28/2018 SIGNED: Work Order: 17687-12-2018 Abraham Abel Printed by EBis 3 (datcomedia.com) Certified Repair Station No. AJ4R052M 1 of 1

YEAR 20 DATE	RECORDIN TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17707-01-2019	Foothill Aircraft Sales & Se  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	Prvice, Inc. DATE: 4/9/20 A/C TSN: 5143 TACH: 5143	.97 hnician o
		S/N:- 17010096 RH P/N:- 2 MINERAL OIL. ENGINE GI INSTALLED NEW McCAUI PER STC SA779NE. SEE	STALLED THE SAME ENGINE LYCOMI OP STRIKE INSPECTION PERFORMEI - 10874. INSTALLED SAME STARTER 8 4370 S/N:- 17010674, SEE FORM 8130- ROUND RUN IAW LYCOMING SI 14270 LEY PROPELLER MODEL 1A170/BMS7 FORM 337	ALTERNATOR. LH MAG P/N:- 4373	
		DATE: 4/9/2019	SIGNED/// Jun ///	Work Order: 17707-01-2019	
			Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

AR RECORDII TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17899-06-2019	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 6/9/2019 A/C TSN: 5184.45 TACH: 5184.45	chnician or
	FUNCTIONAL CHECK. ELT BATTER REPLACED AIR INDUCTION FILTER SELECTOR HANDLE AND SECURE OUTBOARD FLAP GAP SEAL AND S BARREL NUT (7) C/W AD 76-07-12 INSTRUCTION. NO DISCREPANCIE CHECKED GOOD PER FAR 91.207( SECURED PILOT AND COPILOT CA	THIS AIRFRAME IAW FAR 43 APPENDIX D US ST AS A GUIDE. C/W FAR 91.207 D ELT INSPEY EXPIRATION DATE 07/2019. ADS CHECKER WITH NEW P/N BA-3 (4) INSTALLED SCR. D (5) REMOVED AND REPLACED ONE LOSECURED (6) LUBED LUGGAGE DOOR LOSECURED (6) LUBED LUGGAGE DOOR LOSE NOTED (8) ELT STATIC AND INERTIAL SENTED STATIC AND INERTIAL SENTED (11) REMOVED AND REPLACED RIV (12) COMPLIED WITH AD 75-24-02. AFT SECTION.	PECTION AND D THROUGH 06/2019. REW AT FUEL POSE RIVNUT AT LEFT DCK AND TIGHTENED N SWITCH PER AD SWITCHES OPS KE LINE (10)	
		on 16484 was repaired and inspected in accordance workers and the Federal Aviation Regulations repair are on file at this repair station under Work Order		

YEAR	RECORD	MAKE: PIPER Foothill Aircraft Sales & Service, Inc. DATE: 6/17/2019  A/C TSN: 5192.58	
DATE	TACH	MARE: PIPE MODEL: PA-25-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17915-36-2019  TACH: 5192.58  Repair Station No. AJ4R052M  1749 W 13Th St  Upland, CA 91786  Phone: 909-985-1977	echnician or
		Airframe Entries  (1) R&R LH MAIN TIRE WITH AIRHAWK 6.00X6 6PLY AND EXISTING TUBE. REMOVED, INSPECTED AND REINSTALLED THE BEARINGS. DETERMINE FUNCTIONALLY SATISFACTORY.	
		Maintenance Release I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17915-06-2019, Dated 6/17/2019.	
		DATE: 6/17/2019 SIGNED: Showard Jumos Work Order: 17915-06-2019	
		Shravan Poulu Certified Repair Station No. AJ4R052M  Printed by EBis 3 (datcomedia.com)	
		1 of 1	

-

YEAR 20 DATE	RECORDIN TACH TIME	Maintenance Release I certify that the AIRCRAF FARs rules of the Federal	Foothill Aircraft Sales & Service Repair Station No. AJ4R052M 1749 W 137h St Upland, CA 91786 Phone: 909-985-1977  OIL DOOR ASSY. IN UPPER COWLING P/N 9  T 16484 was repaired in accordance with the manufact Aviation Regulations and was found Airworthy for return under Work Order No. 17970-07-2019, Dated 7/18/20	A/C TSN: 5218.31 TACH: 5218.31	chnician or
		DATE: 7/18/2019	SIGNED: Mil Abyth	19. Work Order: 17970-07-2019	
			Mike Hartman Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia com)	
			1 of 1		

YEAR 20	RECOR! TACH TIME	MAKE: PIPER MODEL: PA-28-180		Foothill Aircraft Sales & Service Repair Station No. AJ4R052M	ce, Inc.	DATE: 7/23/2019 A/C TSN: 5230.5	Technician or	
DATE		S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17977-07-2019		1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977		TACH: 5230.5		
		Airframe Entries						
		(1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK GOOD (3) R&R LH & RH BRAKE LININGS WITH NEW P/N:066-10500.						
		Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the						
		repair are on file at this repair station under Work Order No. 17977-07-2019, Dated 7/23/2019.						
		DATE: 7/23/2019	SIGNED:	mile Mint	Work Ord	der: 17977-07-2019		
			Mike Hartman	n pair Station No. AJ4R052M	THE RESIDENCE OF THE PARTY OF T	3 (datcomedia.com)		
				out ofation No. AJ4R052M				
				1 of 1				

TE	RECOR TACH TIME	07-31-2020. ELT TES  Maintenance Release I certify that the AIRCRA	01 PER MI-450 SEC 3.4. NEW BATTERIES EXP	A/C TSN: 5236.4 TACH: 5236.4  O7-2020 M4  P G7-2030 (ONE YEAR) NEXT DUE  stoures maintenance manual and current	Technician or
		on file at this repair station  DATE: 7/31/2019	SIGNED: Amb Mark	19. Work Order: 17991-07-2019	
			Mike Hartman Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

EAR O ATE	RECOF TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 17991-07-2019	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	ce, Inc.  DATE: 8/1/2019 A/C T'SN: 5236.4 TACH: 5236.4	f Technician o
		Airframe Entries (2) R&R RH MAIN TIR AND REINSTALLED	RE WITH AIRHAWK 6.00X6 6PLY AND EXISTIN THE BEARINGS. DETERMINE FUNCTIONALL	NG TUBE. REMOVED, INSPECTED Y SATISFACTORY.	
		raks rules of the Federal	T 16484 was repaired in accordance with the manufa Aviation Regulations and was found Airworthy for return n under Work Order No. 17991 77-2019, Dated 8/1/201	n to service Portinget details afther	
		DATE: 8/1/2019	SIGNED: SIGNED	Work Order: 17991-07-2019	
			Emmanuel Méndoza-Cuevas Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18042-09-2019	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	e, Inc.  DATE: 9/6/2019 A/C TSN: 5283.5 TACH: 5283.5	inician or
	Airframe Entries			
	SECTION III INSPECT FUNCTIONAL CHECT REPLACED AIR INDU BENDIX IGNITION SI	PECTION ON THIS AIRFRAME IAW FAR 43 AI TION CHECKLIST AS A GUIDE. C/W FAR 91.2 K. ELT BATTERY EXPIRATION DATE 07/2019. JCTION FILTER WITH NEW P/N BA-3 (4) CO WITCH. NO DISCREPANCIES NOTED (5) CO SECURED VACUUM LINE FROM I/C MANIFOLI ANCIES NOTED.	07 D ELT INSPECTION AND ADs CHECKED THROUGH 09/2019. DMPLIED WITH AD 76-07-12R1 DMPLIED WITH AD 24-10 STANDBY	
	the manufactures mainte	nd/or component(s) on 16484 was repaired and inspect nance manual and current FARs rules of the Federal Av tinent details of the repair are on the at this repair station SIGNED:	iation Regulations and was found Airworthy	
		Ralph Gouda Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
		1 of 1		

YEAR 20 DATE	TOTAL TIME IN SERVICE	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18135-11-2019	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 11/4/2019 A/C TSN: 5331.11 TACH: 5331.1)
		Airframe Entries		
		(1) COMPLIED WITH FLUID, TIRE PRESS	H 50 HOUR INSPECTION. CHECKED FLIGHT CO CURES, AND OVERALL CONDITION. GROUND F	ONTROL OPERATIONS, BRAKE RUN, SYSTEMS CHECK GOOD.
		Maintenance Release		
		current FARs rules of the repair are on file at this ru	FT 16484 was inspected/ repaired in accordance with the Federal Aviation Regulations and was found Airworthy to epair station under Work Order No. 18135-11-2019, Dated	e manufactoures maintenance manual and or return to service. Pertinent details of the d 11/4/2019.
		DATE: 11/4/2019	SIGNED: /// Whore /////	Work Order: 18135-11-2019
			Abraham Abel Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)
	1			
			1 of 1	

	1 10 1	MAKE: PIPER	Foothill Aircraft Sales & Service,	Inc. DATE: 1/7/20	
	1 3	MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484	Repair Station No. AJ4R052M 1749 W 13Th St	A/C TSN: 5383, TACH: 5383.	
	100	WORK ORDER: 18236-01-2020	Upland, CA 91786 Phone: 909-985-1977		
77		Airframe Entries			
		SECTION III INSPECTION FUNCTIONAL CHECK. E INDUCTION FILTER WIT 79071-000 AND BUMPER SHAFT (9) C/W AD 75-2 NEXT INSP DUE IN 100H	CTION ON THIS AIRFRAME IAW FAR 43 APP N CHECKLIST AS A GUIDE. C/W FAR 91.207 LT BATTERY EXPIRATION DATE 7/2020. AD H NEW P/N. BA-3 (5) REPLACED NOSE G R P/N 452-947 WITH NEW (7) REPLACED B R4-02 REAR LEG QUICK DISCONNECT. NO RS (10) C/W AD 76-07-12R1 BENDIX IGNI AW BENDIX S/B 583. NO DEFECTS NOTED	D ELT INSPECTION AND S CHECKED. REPLACED AIR EAR BUMPER BLOCK P/N BOTH O-RINGS ON PRIMER DEFECTS NOTED AT THIS TIME. TION SWITCHES BY	
		the manufactures maintenance	component(s) on 16484 was repaired and inspected e manual and current FARs rules of the Federal Aviate details of the repair are on file at this repair station under the state of the repair are on the state of the state	ion Regulations and was found Ainvorthy	
			Abraham Abel Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com	n)
46.8 20.0			1 of 1		

The same of the sa			
oothill Arcraft Sales & Service, Inc. epair Station No. AJ4RO52M 749 W. 13th St. Upland, CA 91786, 09 985-1977	TESTED AS REQUIRED BY F  Mance manual and current alls of the report of e on file  Milliad Ponts Same	MODEL: PA-28-180 A/C TS	E: 5/7/2020 SN: 5431.68 CH: 5431.68
180 REQUIRED BY FAR 9	#2 TRANSPONDER GEOUIPMENT HAVE BEEN KE. #1 ENCODER TO: #2 ENCODER TO: #2 ENCODER TO: #2 ENCODER TO: #2 ENCODER TO: #3 ENCODER TO: #4 ENCODER TO: #4 ENCODER TO: #5 ENCODER TO: #6 ENTINENT del Michael Harturan Cen	FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK GOOD INSTALLED NEW LAP BELT AND SHOULDER HARNESS AT BOTH PILOT AND CO-PILOT POSITION.  (4) INSTALLED SERVICEABLE HARDWARE AT TAIL NAVILIGHT AND SECURED. (6) INSTALLED	D (3) ONS D NEW EC 3.4.
MODEL PA28- WORK ORDER 1822	ND ALTITUDE REPORTIN WITH FAR 43. APPENDIN FT. FT. FT. FT.	Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manucurrent FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details repair are on file at this repair station under Work Order No. 18380-05-2020, Dated 5/7/2020.  DATE: 5/7/2020 SIGNED: Work Order: 18380	s of the
G# PIPEL G# MIGY84  Train Linties CERRITY THAT THE ATC TRANS	TH FAR APPENDIX F  TRANSPONDER  ERTHY I HAT THE ALTIMETER AND DIVINE FOUND TO COMPLY  DIS ALL TO:  ND3Y ALL TO:  ND3Y ALL TO:  Inter Guice Release  thy short the AIRCRAFT - was instruct the AIRCRAFT - was instructed to the AIRCRAFT	Abraham Abel Certified Repair Station No. AJ4R052M  Printed by EBis 3 (datcome	1991

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18441-06-2020

## Foothill Aircraft Sales & Service, Inc.

DATE: 7/1/2020 A/C TSN: 5481.86 TACH: 5481.86

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977

### Airframe Entries

(1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING PIPER M.M.

SECTION III INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE 03/2024. ADs CHECKED. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-3.... (7) ROTATED LEFT TIRE, CLEANED AND GREASED BEARINGS.... (8) REPLACED ALL BRAKE LININGS WITH NEW P/N... (9) C/W AD 75-24-02 REAR LEG QUICK DISCONNECT. NO DEFECTS NOTED AT THIS TIME. NEXT INSP DUE IN 100HRS.... (10) C/W AD 76-07-12R1 BENDIX IGNITION SWITCHES BY OPERATIONAL CHECK IAW BENDIX S/B 583. NO DEFECTS NOTED AT THIS TIME. NEXT INSPECTION DUE IN 100 HRS.

### Maintenance Release

I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18441-06-2020, Dated 7/1/2020.

DATE: 7/1/2020

SIGNED:

Work Order: 18441-06-2020

Abraham Abel

Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

YEAR 20 DATE	AD NUMBER	TOTAL TIME II SERVIC	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18509-09-2020	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	ervice, Inc.
			Airframe Entries		
			FLUID, TIRE PRESS REPLACED BOTH N	H 50 HOUR INSPECTION. CHECKED FLIGH SURES, AND OVERALL CONDITION. GROU MAIN TIRES WITH NEW 600 X 6 6PLY AIR H EMOVED ENGINE PRIMER CONTROL. CLE	ND RUN, SYSTEMS IAWK TIRES, CLEAN
			current FARS rules of the	FT 16484 was inspected/ repaired in accordance verse Federal Aviation Regulations and was found Airwo epair station under Work Order No. 18509-09-2020	rthy for return to service
			DATE: 9/3/2020	SIGNED:	My/ w
	The general		314	Abraham Abel Certified Repair Station No. AJ4R052M	Printed by

DATE: 9/3/2020 A/C TSN: 5534.02 TACH: 5534.02

ATIONS, BRAKE CHECK GOOD.... (3) NED AND GREASED INSTALLED. OPS

maintenance manual and Pertinent details of the

Vork Order: 18509-09-2020

y EBis 3 (datcomedia.com)

EAR	AD NUMBEI	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484	Foothill Aircraft Sales & Service, I Repair Station No. AJ4R052M 1749 W 13Th St	DATE: 10/30/2020 A/C TSN: 5577.27 TACH: 5577.27	
ATE		WORK ORDER: 18586-10-2020	Upland, CA 91786 Phone: 909-985-1977		92
		Airframe Entries			
		FUNCTIONAL CHECK. ELT BAT INDUCTION FILTER WITH NEW GOOD (6) REPLACED RIGHT AT LEFT WHEEL. REPACKED WITH NEW (9) COMPLIED W.	ON THIS AIRFRAME IAW FAR 43 APPE CKLIST AS A GUIDE. C/W FAR 91.207 I ITERY EXPIRATION DATE 03/2024. AD V P/N BA-3 (5) REPLACED BULB AT I I WING FUEL SUMP VALVE WITH NEW WHEEL BEARINGS (8) REPLACED B //ITH AD 75-24-02. CORRECT SEAT REI	D ELT INSPECTION AND S CHECKED. REPLACED AIR LEFT NAV LIGHT. OPS CHECKED V (7) REPLACED BRAKE DISC BRAKE LININGS AT LEFT WHEEL	
		The state of the s	T DUE AT 5677.27HRS TACH TIME (1 07-12R1 INSTRUCTION. NEXT DUE AT	(A) ICAUTICAL OLAUTEAL	MARKET
		Maintenance Release I certify that the aircraft and/or compor the manufactures maintenance manua for return to service. Pertinent details Dated 10/30/2020.	nent(s) on 16484 was repaired and inspected in al and current FARs rules of the Federal Aviation of the repair are on file at this repair station und	accordance with a Annual inspection per	
		DATE: 10/30/2020 SIGN	N W IVV	Work Order: 18586-10-2020	
		Abrat Certif	nam Abel Tied Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 10 1	000000000000000000000000000000000000000	

YEAR TOTA TIME SERV	Manufacturers' M Chronological Listing	Manufacturers' Mandatory Service Bulletins Chronological Listing and Method of Compliance			
	Maintenance Release I certify that the AIRCRAF FARs rules of the Federal	Foothill Aircraft Sales & Service, Inc.  Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977  RCRAFT BATTERY CONCORD P/N RG-35AXC (3) CYCLED. OPS CHECKED GOOD.  T 16484 was repaired in accordance with the manufactoures Aviation Regulations and was found Airworthy for return to sen under Work Order No. 18619-11-2020, Date 12/14/2020.  SIGNED:  Abraham Abel Certified Repair Station No. AJ4R052M	LUBED ALL TRIM SYSTEM		

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18736-03-2021

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 3/11/2021 A/C TSN: 5676.3 TACH: 5676.3

# Airframe Entries

(1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK, ELT BATTERY EXPIRATION DATE 03/2024, ADs CHECKED, REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-3.... (4) C/W AD 2020-24-05 BY VISUAL INSPECTION OF WING SPARS PER AD INSTRUCTION. NO DISCREPANCIES NOTED. NEXT DUE ON OR BEFORE APRIL 1, 2028.... (5) AD 2020-26-16 WING SPAR EDDY CURRENT INSPECTION DUE AT 5000 FACTORED HOURS. THIS IS INSPECTION #36. FACTORED HOURS IS 3722. RECALCULATION DUE AGAIN AT EACH 100 HOUR OR ANNUAL INSP.... (6) C/W AD 75-24-02 BY OPERATIONAL INSPECTION, RELEASE PRESSURE CHECKED GOOD PER AD INSTRUCTION. NEXT DUE AT 577.3 HRS TACH TIME.... (7) IGNITION SWITCH OPS CHECKED GOOD PER AD 76-07-12 INSTRUCTION. NEXT DUE AT 5776.3 HRS. TACH TIME.... (8) ADJUSTED CLAMP AT CARB HEAT SHROUD SCAT TUBE TO DETER CHAFING.... (9) DRESSED PROP LEADING EDGES .... (10) REPLACED INTAKE FILTER WITH NEW .... (11) REPAIRED CRACK AT CARB HEAT SHROUD AND INSTALLED .... (12) REPLACED VACUUM REGULATOR FILTER WITH NEW.... (13) ADJUSTED THRESHOLD PLATE AT CABIN DOOR FOR CORRECT CLOSURE.... (15) REPLACED SPINDLE, SPACERS, SPINDLE PLUGS, WHEEL, AND TIRE AT NOSE WHEEL ASSEMBLY .... (16) REPLACED LEFT BUSHING AND LOCK RING AT BOTTOM COWL

Maintenance Release

I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18736-03-2021, Dated 3/11/2021.

DATE: 3/11/2021

SIGNED

Work Order: 18736-03-2021

Abraham Abel Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

ional Equipment tional Equipment quired—Exchanged for Optional quired—Exchanged for Optional

ional Equipment tional Equipment quired—Exchanged for Optional quired—Exchanged for Optional

ional Equipment tional Equipment quired—Exchanged for Optional quired—Exchanged for Optional

ional Equipment tional Equipment quired—Exchanged for Optional quired—Exchanged for Optional

ional Equipment tional Equipment juired—Exchanged for Optional quired—Exchanged for Optional

ional Equipment tional Equipment quired—Exchanged for Optional quired—Exchanged for Optional

YEAR 20\_\_\_

DATE

YEAR

DATE

20

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18850-05-2021



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 5/5/2021 A/C TSN: 5722.34 TACH: 5722.34

Airframe Entries

(1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK GOOD.... (4) INSTALLED NEW COVERS AT RIGHT AND LEFT SHOULDER HARNESS REELS.... (5) INSTALLED NEW CAPACITY PLACARD AT RIGHT AND LEFT FUEL FILL CAPS.

Maintenance Release

I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18850-05-2021, Dated 12021

DATE: 5/5/2021

SIGNED:

Abraham Abel Certified Repair Station No. AJ4R052M Work Order: 18850-05-2021

Printed by EBis 3 (datcomedia.com)

otional Equipment
ptional Equipment
equired—Exchanged for Op
equired—Exchanged for Op

otional Equipment
ptional Equipment
equired—Exchanged for Op
equired—Exchanged for Op

ptional Equipment
ptional Equipment
equired—Exchanged for Optional
equired—Exchanged for Optional
equired—Exchanged for Optional
equired—Exchanged for Optional
equipment

ptional Equipment ptional Equipment ∋quired—Exchanged for Opt lequired—Exchanged for Op

ptional Equipment
)ptional Equipment
equired—Exchanged for Opt
lequired—Exchanged for Op

ptional Equipment
)ptional Equipment
equired—Exchanged for Opti
Required—Exchanged for Opti

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18932-06-2021



# Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977

DATE: 7/1/2021 A/C TSN: 5768.95 TACH: 5768.95

## Airframe Entries

(2) INSTALLED RECAP TIRE AND NEW TUBE LH SIDE. PACKED BEARINGS... (3) R & R LH BAKE LININGS WITH NEW.

I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18932-06-2021, Dated 7/1/2021.

DATE: 7/1/2021

SIGNED:

Work Order: 18932-06-2021

Mike Hartman Certified Repair Station No. AJ4R052M Printed by EBis 3 (datcomedia.com)

Notes

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 18945-07-2021



# Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 7/8/2021 A/C TSN: 5772.79 TACH: 5772.79

## Airframe Entries

(1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-3.... (4) CW AD 2017-16-01 BY REPLACEMENT OF BATTERIES, AND INSPECTION OF ALL WIRING AND SYSTEM COMPONENTS. NO DISCREPANCIES NOTED. NEXT DUE AT ANNUAL.... (6) C/W AD 2017-16-01 PER MI-450 SEC 3.4. NEW BATTERIES EXP 07-2022 (ONE YEAR) ELT TESTED PER 91.207(d) AD DUE AGAIN 07/2022... (7) ADJUSTED LOCKING TANGS AT AFT FOR CORRECT RELEASE PRESSURE PER AD 75-24-02 INSTRUCTION. OPS CHECKED GOOD. NEXT DUE AT 5872.79 HRS TACH TIME.... (8) IGNITION SWITCH OPS CHECKED GOOD PER AD 76-07-12 INSTRUCTION. NEXT DUE AT 5872.79 HRS TACH TIME.... (9) C/W AD 2020-26-16 WING SPAR EDDY CURRENT INSPECTION DUE AT 5000 FACTORED HOURS. THIS IS INSPECTION #37. FACTORED HOURS IS 3821. RECALCULATION DUE AGAIN AT EACH 100 HOUR OR ANNUAL INSP.

#### Maintenance Release

I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18945-07-2021, Dated 7/8/2021

DATE: 7/8/2021

SIGNED:

Work Order: 18945-07-2021

Abraham Abel

Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

