

MCCAULEY™

**PROPELLER
OPERATOR'S
MANUAL
&
LOG**



**MPC-10, MPC-11, MPC-12,
MPC-13, MPC-14, MPC-15,
CMM500-1**



1. Approving Civil Aviation
Authority/Country

2

McCauley Warranty Registration
Cessna Warranty Administration
PO Box 7704
Dept. 767
Wichita, KS 67277-7704

ED
30-3,

14a

14b, A

14d, N

ler
ute e

ess e
n the

inter


[illegible]

PAGE NUMBER

[illegible]

PROPELLER LOG

PAGE NUMBER


Date		Total Time		Aircraft	
				<p>PROP MODEL: 1A170/BMS7660M1 PROP S/N: ALK23022 REG. NO: 16484 WORK ORDER: 17707-01-2019</p>	<p>Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13TH ST Upland, CA 91786 Phone: 909-955-1977</p>
				<p>DATE: 4/9/2019 A/C TSN: 5143.97 PROP TT: 0.01 TACH: 5143.97</p>	
				<p>Prop Entries</p> <p>(6) INSTALLED NEW McCauley Propeller Model 1A170/BMS7660M1 Serial Number ALK23022 PER STC SA779NE. SEE FORM 337</p>	
				<p>Maintenance Release</p> <p>I certify that the PROPELLER on 16484 was inspected / repaired in accordance with the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17707-01-2019, Dated 4/9/2019.</p>	
				<p>DATE: 4/9/2019</p>	<p>SIGNED: </p> <p>Abraham Abel Certified Repair Station No. AJ4R052M</p>
				<p>Work Order: 17707-01-2019</p> <p>Printed by EBis 3 (datcomedia.com)</p>	
				<p>1 of 1</p>	

PROPELLER ASSEMBLY LOG

PROPELLER ASSEMBLY LOG					
PAGE NUMBER _____					
Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature Certificate Number
			PROP MODEL: 1A170/BMS7660M1 PROP S/N: ALK23022 REG NO- 16484 WORK ORDER: 17699-06-2019 	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-955-1977	DATE: 6/9/2019 A/C TSN: 5184.45 PROP TT: 40.48 TACH: 5184.45
			Prop Entries		
			(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER M.M. SECTION III INSPECTED BY _____		

PROPELLER ASSEMBLY LOG

NUMBER _____

Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
		<p>PROP MODEL: 1A170/BMS7600M1 PROP S/N: AUK23022 REG. NO: 16484 WORK ORDER: 17899-06-2019</p> <p></p> <p>Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91766 Phone: 909-985-1977</p> <p>DATE: 6/9/2019 A/C TSN: 5184.45 PROP TT: 40.48 TACH: 5184.45</p> <p>Prop Entries (3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED THROUGH 06/2019</p> <p>Maintenance Release I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr/Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17899-06-2019, Dated 6/9/2019.</p> <p>DATE: 6/9/2019 SIGNED:  Abraham Abel Certified Repair Station No. AJ4R052M</p> <p>Work Order: 17899-06-2019 Printed by EBis 3 (datcomedia.com)</p>		

rendered, suspended, revised, or determination date as otherwise established by the
Federal Aviation Administration.

PROPELLER LOG

PROPELLER ASSEMBLY LOG

NUMBER

Total
Time

PROP MODEL:
1A170BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
18236-01-2020

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-985-1977

DATE: 1/7/2020
A/C TSN: 5383.31
PROP TT: 239.34
TACH: 5383.31

Signature &
Certificate
Number

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER
M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18236-01-2020, Dated 1/7/2020.

DATE: 1/7/2020

SIGNED:

Work Order: 18236-01-2020

Ralph Gouda
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
18441-06-2020

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-985-1977

DATE: 7/1/2020
A/C TSN: 5481.86
PROP TT: 337.69
TACH: 5481.86

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER
M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED... (4) DRESS PROP BLADES.

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18441-06-2020, Dated 7/1/2020.

DATE: 7/1/2020

SIGNED:

Work Order: 18441-06-2020

Abraham Abdel
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

DATE: 7/8/2021

SIGNED:

Abraham Abdel
Certified Repair Station No. AJ4R052M

Maintenance Release
I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18565-07-2021, Dated 7/8/2021.

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED... (5) PROPELLER LEADING EDGES.

PROP MODEL:
1A170BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
18945-07-2021

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-985-1977

DATE: 3/1/2021

SIGNED:

Abraham Abdel
Certified Repair Station No. AJ4R052M

Maintenance Release
I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18732-03-2021, Dated 3/1/2021.

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED

PROP MODEL:
1A170BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
18732-03-2021

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-985-1977

DATE: 10/30/2020

SIGNED:

Abraham Abdel
Certified Repair Station No. AJ4R052M

Maintenance Release
I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18732-03-2021, Dated 10/30/2020.

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED

PROP MODEL:
1A170BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
18732-03-2021

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-985-1977

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO.: 16484
WORK ORDER:
18586-10-2020



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-965-1977

DATE: 10/30/2020
A/C TSN: 557.27
PROP TT: 33.3
TACH: 55 7.27

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18586-10-2020, Dated 10/30/2020.

DATE: 10/30/2020

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 18586-10-2020

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO.: 16484
WORK ORDER:
18736-03-2021

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-965-1977

DATE: 3/11/2021
A/C TSN: 5676.3
PROP TT: 532.33
TACH: 5676.3

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18736-03-2021, Dated 3/11/2021.

DATE: 3/11/2021

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 18736-03-2021

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO.: 16484
WORK ORDER:
18945-07-2021



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-965-1977

DATE: 7/8/2021
A/C TSN: 5772.79
PROP TT: 628.82
TACH: 5772.79

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED... (5) FILED AND FEATHERED PROPELLER LEADING EDGES.

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18945-07-2021, Dated 7/8/2021.

DATE: 7/8/2021

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 18945-07-2021

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
19073-10-2021



Foothill Aircraft Sales & Service, Inc.
Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-965-1977

DATE: 10/7/2021
A/C TSN: 5869.53
PROP TT: 725.56
TACH: 5869.53

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER
M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19073-10-2021, Dated 10/7/2021.

DATE: 10/7/2021

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 19073-10-2021

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
19247-01-2022



Foothill Aircraft Sales & Service, Inc.
Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-965-1977

DATE: 2/2/2022
A/C TSN: 5908.2
PROP TT: 824.23
TACH: 5908.2

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER
M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19247-01-2022, Dated 2/2/2022.

DATE: 2/2/2022

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 19247-01-2022

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
19381-05-2022



Foothill Aircraft Sales & Service, Inc.
Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-965-1977

DATE: 5/13/2022
A/C TSN: 6062.05
PROP TT: 918.08
TACH: 6062.05

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER
M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19381-05-2022, Dated 5/13/2022.

DATE: 5/13/2022

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 19381-05-2022

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
19476-07-2022



Foothill Aircraft Sales & Service, Inc.
Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-965-1977

DATE: 7/19/2022
A/C TSN: 6161.92
PROP TT: 1017.95
TACH: 6161.92

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED... (9) DRESSED AND PAINTED PROPELLER BLADES.

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19476-07-2022, Dated 7/19/2022.

DATE: 7/19/2022

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 19476-07-2022

Printed by EBis 3 (datamedia.com)

1 of 1

Allez à avery.ca/gabarits
Utilisez le Gabarit Avery 5168

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
19583-09-2022



Foothill Aircraft Sales & Service, Inc.
Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-965-1977

DATE: 11/30/2022
A/C TSN: 6260.18
PROP TT: 1110.21
TACH: 6260.18

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr./Annual inspection per the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19583-09-2022, Dated 11/30/2022.

DATE: 11/30/2022

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 19583-09-2022

Printed by EBis 3 (datamedia.com)

1 of 1

Allez à avery.ca/gabarits
Utilisez le Gabarit Avery 5168

TrueBlock[®] Shipping Labels
Completely covers everything underneath

5168

AVERY

PROP MODEL:
1A170/BMS7660M1
PROP S/N: ALK23022
REG. NO: 16484
WORK ORDER:
20001-06-2023



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13TH ST
Upland, CA 91786
Phone: 909-985-1977

DATE: 6/29/2023
A/C TSN: 6365.42
PROP TT: 1221.45
TACH: 6365.42

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PIPER
M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED... (5) DRESSED PROPELLER
LEADING EDGES.

Maintenance Release

I certify that the PROPELLER on 16484 was inspected in accordance with an 100hr Annual inspection per the manufactures
maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service.
Pertinent details of the repair are on file at this repair station under Work Order No. 20001-06-2023, Dated 6/29/2023.

DATE: 6/29/2023

SIGNED:

Abraham Abel
Certified Repair Station No. AJ4R052M

Work Order: 20001-06-2023

Printed by EBis 3 (dalcomedia.com)

GENUINE / AUTHEN



