

[illegible]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

REG NO N7152D **CHANDLER AVIATION INC** DATE 02/01/16
 MODEL Tripacer CHANDLER MUNICIPAL WO# 53028
 S/N 22-5016 CHANDLER, AZ HOBBS XXXXX
 ENG MOD XXXXX (480) 732-9118 TACH XXXXX
 ENG S/N XXXXXX TOTAL XXXXX

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE  AUTH. NO. 2037335 A&P

Bleed brakes with MIL 5606. Replace vent cable. Replace (3) fuel drains. Clean primer nozzles, install new o-rings and reinstall primer control.

END

[illegible]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations <small>Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)</small>
				Mesquite Avionics LLC 1725 E. Ryan #8 Chandler, AZ 85249 Removed KT76 and KX170B, and installed GTX327 and SL40 interfaced with the existing Encoder Per Garmin Installation manual , GTX IM and AC43-13-1B. All tests are Satisfactory. W&B Changer is Negligible. FAA Certificate # 3473353 A&P B. Thayer May 16, 2016

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations <small>Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)</small>										
				Mesquite Avionics LLC 1725 E. Ryan #8 Chandler, AZ 85249 CRS# Q5KR301B										
				<table border="1"> <thead> <tr> <th>Reg.#</th> <th>A/C Make</th> <th>Model</th> <th>S/N</th> <th>Tach/hobb</th> </tr> </thead> <tbody> <tr> <td>N7152D</td> <td>Piper</td> <td>PA22</td> <td>2020</td> <td>515</td> </tr> </tbody> </table> <p>I certify that the transponder tests, including data correspondence, required by § 91.413, have been performed and found to comply with 14 CFR part 43, appendix F.</p> <p>Date <u>05/16/16</u> Work performed by <u>[Signature]</u> Inspected by <u>[Signature]</u> Work Order # <u>0515</u></p>	Reg.#	A/C Make	Model	S/N	Tach/hobb	N7152D	Piper	PA22	2020	515
Reg.#	A/C Make	Model	S/N	Tach/hobb										
N7152D	Piper	PA22	2020	515										

YEAR	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations		
				Entries must be entered with Name, Rating and Certificate Number of Technician or		
				CHANDLER AIR SERVICE		
				1675 E. RYAN RD.		
				CHANDLER, AZ. 85286		
152D	MODEL: PA-22-150	SN: 22-5016	TACH: 526.7	AFTT: 2360.9	NOTE: TT corrected based on TACH change 1/20/1992	
COMING	MODEL: 0-320	SN: L-6282-27	TSMOH: 495.2	ETT: 2360.9	NOTE: TT & TSMOH corrected based on TACH change 1/20/1992	
ENSENICH	MODEL: 74DM5674	SN: 17758	PTSO: 0.0			

FAR 91.207(d) COMPLIED WITH BY VISUAL & OPERATIONAL INSPECTION OF ELT & BATTERY. BATTERY EXPIRES 7/2017

AD 57-22-01, Inflight Fires, Inspected Per Para 3, 4, & SB 161a. Next Due @ TACH: 627

AD 60-10-08, Fuel Selector Valve, Operational Check & Visual Inspection Completed. Next Due @ TACH: 627

AD 68-05-01, Exhaust Muffler, Inspected Per Para (b) & SB342C. Next Due @ TACH: 627

AD 74-17-04, Fabric Failure, Inspected Per Para 2. Next Due @ TACH: 627

AD 2015-08-04, Wing Lift Struts & Forks, Inspected Struts Per Para (h)(1) & Piper MSB 528D. Next Inspection of Struts Due 8/2018.

New Forks Previously Installed @ TACH: 293. Next Inspection of Forks Per (j)(1) & (k)(1) Due @ TACH: 793

NEW FILTER, RA-D9-18-1, INSTALLED INSTRUMENT AIR INLET ASSEMBLY

SERVICEABLE ATTITUDE GYRO, JH6500A, SN 16663752P, REPAIRED BY KEYSTONE INSTRUMENTS,

WO# 16-0201, INSTALLED WITH NEW HOSE NIPPLES, AN840-6D, & HOSE, 306-6

NEW CATCH, 52745-000, INSTALLED LEFT CABIN DOOR STOP ASSEMBLY

NEW BRAKE DISCS, RA164-02601, INSTALLED LEFT & RIGHT WHEEL ASSEMBLIES

NEW BRAKE LININGS, RA66-105, INSTALLED LEFT & RIGHT BRAKE CALIPER ASSEMBLIES

NEW O-RINGS, MS28775-224, INSTALLED LEFT & RIGHT BRAKE CALIPER PISTONS

NEW BRAKE HOSE ASSEMBLIES, U15216-000, INSTALLED BETWEEN FUSELAGE & LEFT/RIGHT GEAR STRUT LINES

NEW GASKET, U60750-006, INSTALLED LEFT FUEL TANK CAP

NEW GASKET, CA462-049, INSTALLED MAIN FUEL GASCOLATER ASSEMBLY

NEW SWITCH, AN3021-2, INSTALLED IN LANDING LIGHT CIRCUIT

MINOR WELD REPAIR TAILBEACON BRACKET. REPAIR INSPECTED, NEW TAIL BEACON, 01-0770509-00, INSTALLED VERTICAL FIN

NEW GASKET, W1283, INSTALLED LEFT NAV LIGHT ASSEMBLY

CORROSION REMOVED. BOX PAINTED WITH ACID PROOF PAINT, NEW DRAIN TUBE & COVER WING NUT, AN350-1032, INSTALLED BATTERY BOX COVER. NEW TERMINAL NIPPLE, MS25171-3S, INSTALLED POSITIVE BATTERY TERMINAL. NEW TERMINAL NIPPLES, MS25171-1S, -2S, INSTALLED GENERATOR & STARTER TERMINALS. NEW TERMINAL NIPPLES, MS25171-1S, INSTALLED LEFT/RIGHT MAGNETO "P" LEAD TERMINALS. NEW FILTER, BA-4108, INSTALLED INDUCTION AIR BOX ASSEMBLY. NEW HOSE ASSEMBLIES, 624000-8D0420 & 624000-8D0460, INSTALLED OIL COOLER ASSEMBLY. NEW FITTING, AN823-6D, INSTALLED CARBURETOR FUEL INLET PORT. NEW HOSE ASSEMBLY, 350-6-0091, INSTALLED BETWEEN GASCOLATER ASSEMBLY & CARBURETOR FUEL INLET. NEW CLAMPS, MS21919-WDG16, INSTALLED LOWER COWL Baffle ASSEMBLY. MINOR WELD REPAIR LOWER FUSELAGE STIFFENERS AFT OF MAIN GEAR. REPAIR INSPECTED. MINOR FABRIC REPAIR & PAINT COMPLETED FUSELAGE BELLY AREA, LEFT GEAR LEG FAIRING, RIGHT WING, LOWER AFT SECTION. MINOR SHEET METAL REPAIR LOWER ENGINE COWL, RIGHT BOTTOM AREA, LEFT UPPER GEAR FAIRING, LEFT & RIGHT BOTTOM GEAR COVERS, LOWER FUSELAGE COVER, & COWLING NOSE BOWL AFT OF SPINNER. OPERATIONAL & LEAK CHECKS COMPLETED.

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MAINTENANCE COMPLETED IN ACCORDANCE WITH PIPER & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE ADS CHECKED THROUGH ATP REVISION 8/16/2016

Ricky Will
RICKY WILL, A&P 3028383 IA

8/19/2016

SHOP ORDER 16-4137

CHANDLER AIR SERVICE
1675 E. RYAN RD
CHANDLER, AZ 85286

AIRFRAME LOG ENTRY

N7152D MODEL: PA-22-150 SN: 22-5016 TACH: 535.3




NEW CONCORD BATTERY RG-35A, SN 40816540, INSTALLED. NEW AUXILIARY POWER PLUG, 11-00500, WIRE, MIL-W-22759/16-4, & CLAMPS, MS21919-WDG16, INSTALLED ADJACENT TO BATTERY BOX. NEW GASKETS, AN 900-16, INSTALLED BRAKE RESERVIOR CAPS. MAINTENANCE COMPLETED PER PA22 MAINTENANCE MANUAL & AC 43.13-1B

Edward Magbitang
EDWARD MAGBITANG, A&P 2611566

10/8/2016

SHOP ORDER 16-4222

[illegible]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				<p style="text-align: right;">FAA-PMA (PQ2393NM)</p> <p style="text-align: center; font-size: 2em;">Y130RS</p> <div style="border: 1px solid black; padding: 10px; margin: 10px;">  <p>Rosen P/N: R1710000-034 Description: NSA TUBE 5/8" PACER SYSTEM Customer P/N: N/A Model: PACER Insp:  Date: <u>JUL 21 2016</u> Rosen Code: P,S SERIAL No: M167511 </p> </div>



5047 E. Roadrunner Drive, Mesa, AZ 85215
Ph. (480) 832-1330 Fax (480) 832-1186

Make	Model	Serial Number	Tail Number
Piper	PA-22-150	22-5016	N7152D

The following interior refurbishment items were completed on the aircraft with materials conforming to CFR 23.853(a) and Arizona Aircraft Interior Designs approved processes.

<u>Description</u>	<u>Part Number</u>	<u>Material Description</u>
Seats	2041P/74 N/A	Douglass Grey Honeycomb Fabric GBS Eclipse Zodiac Grey Vinyl
Sidepanels	2041P/74 N/A	Douglass Grey Honeycomb Fabric GBS Eclipse Zodiac Grey Vinyl
Carpet	AC7315/548 N/A	Douglass Seal Nylon Carpet Skandia .250" Carpet Pad
Headliner	5815	Tapis Polar UltraLeather
Sound Reduction	SX-1000	Soundex Product

All work was performed in accordance with aircraft Maintenance Manual, Illustrated Parts Catalog, AC 43.13-18, AC4.13-2B and current FAA Regulations. It was found to be airworthy for return to service. Pertinent details are on file at this repair station under work Order.

Inspected by:

Date Inspected 10/04/2016



Work Order: 17378

ARIZONA AIRCRAFT INTERIOR DESIGN, INC.

FAA REPAIR STATION NO. LG3R656L

[illegible]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				<p> Date: <u>8/29/16</u> TTAF: _____ Hrs: <u>530 22</u> Aircraft N#: _____ Removed 7512-12V or -24V incandescent position lamps and replaced with PSA's P7512-14V or -28V RED and GREEN LED position lamps. Form, Fit and Function are the same. Per the Manufacture's tests and the requirements of <u>CAR -- 3; SAE/AS 8037REV B; RTCA DO 160REV C</u>; for Coordinates, Brightness, Color, EMC, EMI, Thermals, and Vibration for Airborne Equipment are met. Owner preventative maintenance per FAR43.3(g), .17(C) & APX(A). <u>Continue in Service.</u> Signed: <u>[Signature]</u> Certificate #: _____ NOTE: This may be signed by any <u>Private Pilot or greater if he/she is owner operator of the aircraft; 14CFR43 appendix A, (c)(17) and 14CFR43.7(f) or of course any airframe mechanic.</u> LED Batch #'s: _____ Invoice #: _____ </p>
12/10/16		547.18		<p> Changed oil & Filter <u>[Signature]</u> </p>

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations <small>Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)</small>
07/01/17		587.03		Charged Oil - Used 7qts shell 100 plus 3693811 Changed Filter Tempest AA48108-2 3693811 Scott Hansen
				DESERT RAT AVIATION 32424 W BUD RD MARICOPA AZ 85138
				
				DATE: 6.14.2017, REG: N7152D, TACH: 590.02
				AIRFRAME WORK PERFORMED:
				1. Replaced steering arm packing @ firewall, LT & RT.
				2. Sealed all firewall gaps.
				3. Adjusted cabin hear cable.
				4. Adjusted cabin air cable.
				END
				ANDREW ESTES A&P/IA 2828023 

[illegible]

CHANDLER AIR SERVICE
1675 E. RYAN RD.
CHANDLER, AZ. 85286

N7152D MODEL: PA-22-150 SN: 22-5016 TACH: 600.3 AFTT: 2434.5

NEW BATTERY, BP-1045, INSTALLED ELT SYSTEM

VISUAL & OPERATIONAL INSPECTION OF ELT & BATTERY COMPLIED WITH PER FAR 91.207(d). BATTERY EXPIRES 10/2019

AD 57-22-01, Inflight Fires, Inspected Per Para 3, 4, & SB 161a. Next Due @ TACH: 700

AD 60-10-08, Fuel Selector Valve, Operational Check & Visual Inspection Completed. Next Due @ TACH: 700

AD 64-05-04, Upper Main Oleo Bearings, New Upper Bearing, 452-419, Washer Seal, 85012-072 & Boot, 14087-000, Lower Bearing, 452-332, Installed.

Recurring Removal & Inspection Requirement Terminated Per Para (f)

AD 68-05-01, Exhaust Muffler, Inspected Per Para (b) & SB342C. Next Due @ TACH: 700

AD 74-17-04, Fabric Failure, Inspected Per Para 2. Next Due @ TACH: 700

NEW CLEVIS PIN, MS20392-3C41, INSTALLED CO-PILOT SECONDARY SEAT STOP ASSEMBLY

NEW WIPER STRIP, 187-625, BACKUP RING, 494-025, O-RINGS, MS28775-222, -224, SNAP RING, 484-720, & SERVICEABLE BUMPER BRACKET,

79071-000, INSTALLED NOSE STRUT ASSEMBLY. STRUT SERVICED WITH MIL-H-5606 & NITROGEN

NEW RACES, 13836-20629, & BEARINGS, 13889-20629, INSTALLED NOSE WHEEL ASSEMBLY

NEW AXLE ROD, 13089-000, INSTALLED NOSE GEAR FORK ASSEMBLY

NEW BUSHINGS, 452-766, BOLTS, AN5-30, -32, INSTALLED NOSE STRUT TORQUE LINK ASSEMBLY

NEW RACES, 13836-20629, & BEARINGS, 13889-20629, INSTALLED LEFT & RIGHT WHEEL ASSEMBLIES, OUTBOARD POSITIONS

NEW FILTER, BA-4108, INSTALLED INDUCTION AIR BOX ASSEMBLY

NEW CLAMP, MS21919-DG2, INSTALLED PRIMER LINE ASSEMBLY, REAR OF ENGINE SUMP

NEW CLAMPS, MS21919-DG5, INSTALLED MANIFOLD PRESSURE LINE

NEW SCREWS, SL-STD1925, INSTALLED #2 & 4 CYLINDER BAFFLE ASSEMBLIES

MINOR WELD REPAIR MUFFLER BRACE & SHROUD. REPAIRS INSPECTED, BRACE & SHROUD INSTALLED

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MAINTENANCE COMPLETED IN ACCORDANCE WITH PIPER & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE ADS CHECKED THROUGH ATP REVISION 9/6/2017


BRIAN L. WILSON, A&P 497728418 IA

9/6/2017

SHOP ORDER 17-4486

[illegible]

[illegible]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	---

DESERT RAT AVIATION
32424 W BUD RD
MARICOPA AZ 85138



DATE: 11.15.2017, REG: N7152D, TACH: 630.00

AIRFRAME WORK PERFORMED:

1. Installed new UMA #T19-801-1E1 Tachometer & T1A9-X Mag pickup.
2. Installed new Alcor #46156 CHT/EGT gauge, Alcor #42535 CHT Sender Probe, Alcor #86255 EGT Probe Type K.
3. Negligible weight & balance change.

END

ANDREW ESTES A&P/IA 2828023

[illegible]

[illegible]

CHANDLER AIR SERVICE
1675 E. RYAN RD.
CHANDLER, AZ 85286

N7152D MODEL: PA-22-150 SN: 22-5016 TACH: 673.1 AFTT: 2507.3

VISUAL & OPERATIONAL INSPECTION OF ELT & BATTERY COMPLIED WITH PER FAR 91.207(d) BATTERY EXPIRES 10/2019

AD 57-22-01, Inflight Fires, Inspected Per Para 3, 4, & SB 161a. Next Due @ TACH: 773

AD 60-10-08, Fuel Selector Valve, Operational Check & Visual Inspection Completed. Next Due @ TACH: 773

AD 68-05-01, Exhaust Muffler, Inspected Per Para (b) & SB342C. Next Due @ TACH: 773

AD 74-17-04, Fabric Failure, Inspected Per Para 2. Next Due @ TACH: 773

NEW FILTER, RA-D9-18-1, INSTALLED INSTRUMENT AIR INLET ASSEMBLY

NEW GASKETS, U80122-048, INSTALLED LEFT & RIGHT FUEL TANK FILLER NECKS

NEW GASKET, 462-021, INSTALLED LEFT FUEL TANK SENDING UNIT

NEW FUEL SUPPLY HOSES, MIL-DTL-6000D 3/8, INSTALLED LEFT & RIGHT FUEL TANKS

NEW INNER TUBE, MICHELIN 092-500-0, & WHEEL ASSEMBLY, 40-76B, INSTALLED NOSE GEAR WHEEL/TIRE ASSEMBLY

NEW HOSE ASSEMBLY, 624000-8D0322, INSTALLED ON RIGHT SIDE OF OIL COOLER ASSEMBLY

NEW CLAMPS, MS21919-DG12, INSTALLED ON ENGINE OIL BREATHER LINE

NEW SWIVEL ASSEMBLY, U70371, INSTALLED ON CARB HEAT CONTROL BOX

NEW FILTER, BA-4108, INSTALLED IN INDUCTION AIR BOX ASSEMBLY

NEW O-RING, 41x2MM, INSTALLED ON MAIN FUEL STRAINER ASSEMBLY


RUDDER PEDAL ASSEMBLIES REMOVED TO PERMIT ENGINE MOUNT REMOVAL. ENGINE & ENGINE MOUNT REMOVED FOR REPAIR. SERVICEABLE MOUNT, REPAIRED BY AERO FABRICATORS, WO# 72688, INSTALLED WITH NEW BOLTS, AN6-35A, AN6-24A, NUTS, MS21045-6 (MOUNT TO FIREWALL SUPPORTS). ENGINE INSTALLED WITH NEW BOLTS, AN8-44, BUSHINGS, 71032, WASHERS, STD619, & NUTS, AN310-8 (ENGINE TO MOUNT). RUDDER PEDAL ASSEMBLIES INSTALLED WITH NEW HARDWARE AS REQUIRED.

MINOR SHEET METAL REPAIR COMPLETED CABIN HEAT SHROUD (DOUBLER & FLUSH PATCH ON BOTTOM, DOUBLER ON TOP)

NEW SHROUD, U12742-004, SN 131809, INSTALLED ON MUFFLER ASSEMBLY

MINOR WELD REPAIR COMPLETED EXHAUST SYSTEM TAILPIPE (McNEILLY) REPAIR INSPECTED & TAILPIPE INSTALLED

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MAINTENANCE COMPLETED IN ACCORDANCE WITH PA22 & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE ADS CHECKED THROUGH ATP REVISION DATED 2/15/2019



DOMENICO BUFFO A&P 3491335 IA

2/15/2019

SHOP ORDER 18-4800

[illegible]

YEAR
20
DATE

DESERT RAT AVIATION
32424 W BUD RD.
MARICOPA AZ. 85138



DATE: 4.29.2021, REG: N7157D, TACH: 744.5, TT: _____

ENGINE WORK PERFORMED:

1. Removed spark plugs, cleaned, inspected & reinstalled.
2. Performed compression test #1- 77/80, #2- 75/80, #3- 74/80, and #4- 75/80.
3. Changed oil filter Champion CH48108-1.
4. Changed oil 8 qts Aeroshell W100 SAE 50.
5. Check timing found ok.
6. Tightened up loose dip stick housing.
7. Tightened vacuum hose clamp.
8. Installed missing bolt on exhaust clamp.
9. Checked fuel screens in carburetor.
10. Washed engine with mineral spirits.
11. Test run engine found ok.

END

I certify that this engine has been inspected in accordance with annual inspection and was determined to be in airworthy condition.

ANDREW ESTES 2828023 A&P / IA

YEAR

20

DATE

DESERT RAT AVIATION
32424 W BUD RD.
MARICOPA AZ 85138



DATE: 4.29.2021, REG: N7157D, TACH: 744.5, TT: _____

AIRFRAME WORK PERFORMED:

1. Inspected all pulleys, cables and control surfaces and lubed.
2. Removed all fuel screens, cleaned, inspected and reinstalled.
3. ELT ops check IA W 207.d found to be in compliance with 207.d, ELT Battery due 02/2023.
4. Repaired holes in fabric and touched p paint in numerous places.
5. Removed RT & LT main gear and nose gear for cleaning and inspecting wheel bearings, services wheel bearings and reinstall.
6. Removed positive battery cable and installed new one.
7. Removed parking brake valve repaired and reinstalled.
8. Performed AD 57-22-01 inspected per para 3, 4, SB161a next due 844.5.
9. Performed AD 60-10-08 fuel selector valve operational check and visual inspection next due 844.5.
10. Performed AD 68-05-01 exhaust muffler inspected per para (b) SB342C next due 844.5.
11. Performed AD 74-17-04 fabric failures inspect per para 2 next due 844.5.

END

I certify that this airframe has been inspected in accordance with annual inspection and was determined to be in airworthy condition.

ANDREW ESTES 2828023 A&P/ IA

Airworthy Aviation, LLC

N7152D Make: Piper Model: PA22-150 S/N 2020

02-MAR-2023 Tach: 782.9 TTAF: 2618.1

Removed inspection panels and interior as required for inspection. Inspected aircraft per Piper Service Manual and applicable AD's. Repaired minor tear in the RH elevator per AC43-13-2B and touched up paint to match. Drained LH fuel tank and replaced the fuel drain valve. Replaced all three tires

New fuel drain valve CAV-180 installed

New ELT battery BP-1045 installed

New Condor 8.00-6 main tires installed

New Condor 6.00-6 nose tire installed

AD 57-22-01, inflight fires, Inspected per PARA 3,4, & SB161A. Next due tach time 883.9

AD 60-10-08, Fuel Selector, operational check and visual inspection completed. Next due Tach time 883.9

AD 74-14-04, Fabric Failures, inspected per para 2, next due Tach time 883.9

AD 2015-08-04, Wing lift struts and forks, inspected struts per para (h)(1) and Piper MSB 528D. Next due 3/2025

Inspected forks per para (j)(1) & (k)(1). Next due tach time 1282.9

All ADs checked through bi-weekly 2023-05. See AD compliance worksheet in the aircraft records.

Replaced ELT battery tested ELT per FAR 91.207 paragraph D. ELT battery is due replacement Jan-2025.

I certify that this aircraft has been inspected in accordance with an annual inspection in accordance with FAR Part 43, appendix D, and manufacturers maintenance manuals and found to be in airworthy condition at this time.

Theodore Hawkins 3880925 A&P/IA

