

for PIPE
MANUAL 107-Q-1
HARTZELL PROPELLER, INC.

out

DN 1655

'S

Installation
Operation
Service

"Compact"
HC-F (2)
12Y:
Fe




Current

NEW ENGLAND PROPELLER SERVICE, INC.


Propeller Logbook

ES
This Manual Will Be Periodic

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
 Advanced AeroWorks 131 Liberator Lane Indiana Pa 15701 814-312-3853 Make: American Champion Model: 8KCAB Tail: N5043G S/N: 50379 Hours: AC: 1974.08 TT: 1974.08 EngTT: TT-1974.08 TSMOH-589.08 PropTT: TT-1974.08 TSMOH-153.78 Hobbs: 2318.8 Misc: I certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition. Signed:  Name: Paul West Cert: A&P 2723731 IA Date: 09/08/2022			

N5043G AMERICAN CHAMPION 8KCAB S/N: 503-79 ACTTIS: 1978.27 TACH: 1978.27 NOVEMBER 15, 2023
 PROPELLER: HARTZELL HC-C2YR-4CF/FC7666A-2 TTIS: 1978.27 TSMOH: 157.97
 REMOVED SPINNER. VISUALLY INSPECTED HUB, PLATES, AND BLADE ROOTS; NO DEFECTS NOTED. LUBRICATED BEARINGS USING
 AEROSHELL 5 GREASE. VERIFIED BLADE TRACKING; WITHIN LIMITS. REINSTALLED SPINNER.


 JOHNNIE B. SMITH AP214769163