

in a - to

1

a sta

. .

PIPER AIRCRAFT CORPORATION

General Offices at Lock Haven, Pennsylvania U. S. A.

N8088B

Aircraft Registration Number

Part No. 230715

AIRCRAFT DESCRIPTION

Registration No8	F088B
lodel: PA. 32. 300	Popular Name: Cherokee Six 300
orial No.: 32. 7940250	Type Certificate No.: <u>A350</u>
see WEIGHT AN	ID BALANCE
ngine Manufacturer: Lycomicg riginal Engine Model: IO. 540. Kilo 5-	Propeller Manufacturer: <u>Hartzell</u> Original Propeller Model: <u>HC-C3YK-RBF</u> CH35605 B
rial Numbers: Single L - 19680 - 48A	Hub or Serial Number: Single
Left	Left
Right	Right
	Blade Numbers
	Left Right <u>E3388/</u> <u>D98420</u>

COMPLIANCE WITH FAA AIRWORTHINESS DIRECTIVES

COMPLIANCE WITH FAA AIRWORTHINESS DIRECTIVES

	1				Repeat AD:	*	8-17-99		
A. D. No. ond Date	Method of Compliance (See Log for Details)	Time on Aircraft	Date of Compliance	Signature and Certificate No.	A. D. No. and Date	Method of Campliance (See Log for Details)	Time on Aircroft	Date of Compliance	Signature and Certificate No.
AD 80-14-01	Tank Vent Mod Kit fintatles	1286.76	9-18-80	V Vargh Atrize 33 24	#96-12-07	Bendix impulse imp due in 43 hr, Next ail change	1823	5-6-93	ea- 500 hr
AD 80-24-03	Replaced ammeter washers			NVanger A+P17633 > 4	\$90-02-23	Propeller the practions	1823.	8-11-49	
AD 83-22-04	Bendix fuel injector serve	565.83	1-19-84	V Vanch. 5A1762374	\$78-23-01	Buel drain dool hapt	1823	8-11-99	71
AID 77-12-06	OVERHAULED PROP	609.3	15 DEC 89 115EPT84	L. BIBLE ANPIPOSTTI	× 13-02-05	Guel injector lines and	1823	2011-99	К
A/D 90-02-23	PROP INSPECTION			. "	99-05-09	Purglater ais fitter installe	1823	•	8-19-99
A1092-12-05	PISTON BN NIA AS PER	DATE			*96-12-07	Remard Magnete DOT9310F C/W IAW MS6645, CPOK	R 1914,	9-22-00 ea. 50 m	
A1096-10-03	Plan Busting & Clevis Coltin paphonalle By S. Bible 6-17-94	1401.6	6-17-94	L. Bible	*90-02-234	propeller Hub Cracks	Nº 111	9-22.00 950 hr	
A1091-14-22	NA. at O.H on after prop				+93-02-05	Che y wel injusto lines	1914	9-22-00	
					* 78-23-01	CW Guel dramchaning	1914	9-22-00 da 100 hr	
								F	
						•			1

COMPLIANCE WITH MANUFACTURER'S SERVICE BULLETINS AND LETTERS

Bulletin or Letter No.	Subject and Remarks	Time on Aircraft	Date of Compliance	Signature and Certificate No.
R5-68 58646A	Injector regulator stem erimped by Bendig Kep Jast took Vent nod Hit	2.34	8-23-19	SHA XX-14-64
5B 646A	fast touch vant nad Kit	286.76	9-18-80	Dep1763374
dimit it	Contraction of the second s			-

· ...

Registration No. 18088B

Date	Aircraf	t Time	Recorder				
Duie	This Date	Total	Reading	Maintenance	and Remarks	Signature	Certificate N
	Brought Forward		I HAVE INSPE	CTED THIS AIRCRAFT AND ISSUED			
			A STANDAR	AIRWORTHINESS CERTIFICATE	The ATC Transponder Tesis and Inspections required by FAR 91.177 were performed this date and found to comply with		
			DATEDA	PER 21,2/3.	FAR 43, Appendix F. ATC Transponder:		
		/	fammer	- Francia FAA DOA SO-1	1. Make KINg Model KIT 78A SIN7444		
		0	THE ALTIN	ATTER AND STATIC SYSTEM	2. Make Model S/N	FAR 91.52.	Battery re-
			HAVE BEE	I DEPENDENT FAR PART 91. 170	Details of this inspection are on file at this facility under S/NZ9.402050 Date 8-9-79	placement da $12 - 28 =$	
		2	HAVE BEEN	TESTED TO 20 00 FT.		D. O. A. I Piper Airci	No. 50-1
			SIGNED	TESTED TO 20,00 - FT. 5-11-79 (R) 14 - FT. mmi A Lengin DATE AUG 2 2 1979	VERO BEACH, FLORIDA		an corp.
			THE ALITON				
2 2 1979	2.34		PERFORMENT	91.36 HAVE BEEN	5		
al To ry Forward		2.34	DATE 5-9-79	SIGNED Simming Flankin			

Registration No._

Certificate No.

A+P1763374

and was de

min

263324

Dete	Aircro	Ift Time	Recorder	Maintenance		Signature
Date	This Date	Total	Reading	Mainienance	and Remarks	Signatore
	Brought Forward				Jan 10, 1980 Low Line 162.57	aired tires,
Oct 30, 19	29 Low,	Rime 110	. O Rep	laced seals in mose .	brake reservoir, serviced b	
		1 .	1 1 1	Plash tube.	fin strobe flash tube. Pepe	
				dose relay and	on right aileron. aired right	
/	1 1		1	tipy this aircraft	. Rincent V. Vac	
1 1		1 1		nce with a 100		
	A 1		1 1	round to be in	april - 14, 1980 Tac Time 20	0.4 Replaced
	4	A	An	+ 9. Vaughn	left + one right brake bining pas	
			A+P126	/	right brake. I certify this one	1 1 1
					in accordance with a 100 How insp	
Total To Carry Forward					to be in direvorthy condition. Hincu	

Date	Aircraft	Time	Recorder	Maintenance	and Remarks
Date	This Date	Total	Reading	Mamendace	
	Brought Forward				July 1
-25-80	Tostine	122.35	Remove	d both main year legs.	filled
und rep	laced sea	le in a	trut co	ngear strut fairings. icent V. Vaugh MP183324	
erviced,	struto. K	place &	oth mai	ingen strut fairings.	
Replaced	both m	ain tir	es, Va	icent V. Vaugh AtP183324	august:
'					leaking
-					dartif
					accordo
					determin
Total To Carry Forward					

Registration No. Certificate No. Signature 10, 1980 Tar Time 262.37 dired tires, braken, serviced battery. Vincent V. A+P1263324 28, 1980 Tactime 275.0 Tightened botts in helquartity transmitter left into tout has been inspec es ancraft 1 nce with a 100 Hour inspection and was red to be in airworthy condition Vincent V. Val A+P1263374

AIRCRAFT LOG Registration No.__ **Aircraft Time** Recorder Date Signature Certificate No. Mointenance and Remarks Reading This Date Total Nov 21, 1980 Tac Time 312.96 Replaced Vacuum Pump, Vincent V. Vaugh IA 1763374 Brought Forward 8-28-80 TRUG 275.0 I GERTIFY THIS ALACRAFT WAS INSPECTED IN A COORDANCE WITH AN ANNAL for 9, 1981 Tac Time 326 dued three INTRECTION AND WAS DETAMINED TO BE ARWIRIS filled brake con serviced battery, checked lights, Vincent V. Vaugh Atp 1763374 Frend & Clabours , A 1785235 9-18-80 Tar Time 286.76 C/W Riper 58 646 A Sontalled fuel tank Vent modification pit # 764-011 V. April 7, 1981 Tax Time 338. 47 IW Sp 50.24.03 By replacing ammeter terminal post washers. Vincent V. Vaugh Atp/ 763374 Vincent V. Vaugh AtP1763374 Total Ta **Corry Forward**

Registration No.

Aircraft Time Recorder Date Maintenance Reading Certificate No. This Date Total and Remarks Signature The ATC transponder tests and inspections required Brought 23 June 81 by FAR 91 177 were performed this date and found to Forward Sept 1, 1981 Tac Time 378.29 Replaced boost FAR 43, Appandin F. COMON Mote KUSS Model KIDSA Mort 1, 7444 switch. Replaced Make NAA Model Spring 12 Pertinent details are on file at this paency under Date 9-1-81 TT 378.29 W.O. # 14818 Date 23 June Stigner A Jugo I certify that this aircraft Capital Auomics, Inc was inspected in accordance with a Taliahaesee, FL 32304 Certificate #707-37 Change inspection and was the second found to be airworthy. Vincent V. Vaugh TA1263374 June 25, 1881 Tor 358.62 Replaced ELT Battery. Expiration date & certify the altimeter and static system august 1982, 1100 18, 1981 Tou Time 397.0 Replaced air conditioner tests required by FAR 91. 170 have been performed. The door on belly. Replaced with nose strut fairings attempter was tested to 20,000 ft on 6-25-81. on Coulins. Vancent V. Vanst LA1763374 Total To ATP1763374 Carry Forward

Date	Aircra	ft Time	Recorder	
Date	This Date	Total	Reading	Maintenanc
	Brought Forward			
stember	1, 1982	Tac Time	454.88	Replaced expired ELT
ttey. &	lew expir	ation do	te fan	Replaced expired ELT 1984.
	Date 9-1	· 82 TT_	454.88	
		t this dinc		
	annue found to be	inspec	tion and was	
			~ JAII	63374
		V. Vaugh	L IAI	63374

Registration No. Certificate No. and Remarks Signature april 4, 1983 Tac Time 502.0 dired times, revoiced brake reservoir, serviced battery Replaced right now light bulb. Vincent V. Vaughn ASP 1763. augh ASP 1763374

-

-

Date	Aircra	ft Time	Recorder	
Date	This Date	Total	Reading	Maintenance
	Brought Forward			
Totoler	12, 1983	Tac Tu	ne 546.	5 Replaced nose time.
				C/W Bendix AD 78-09-07 R.
faspected	left mo	gaeto i	ripulse	coupling, OK (no impulse
on right		Date 10-12		
	-	1 certify that I	his aire	raft
		was inspected	in accorda	hee with a
		found to be a	rworthy.	
		Vincent	V. Vaug	hn +14/165374
Total To Carry Forward				

	Registration No		
and Remarks		Signature	Certificate No.
1) Oct 83	I certify that the sto	tie peussine	cyster,
	each attimeter instru	iment and li	ich
	automatic presure al		*
	test and inspections a		
	has been performed.	Static pressure	e system
	was tested on 17 oct 83	. The altimet	n ares
	feated to 20,000' on	17 00+83. Th	e
*	Automatic pressure a	ltitude repo	inting
	system was firsted to	20,000 m	17 Oct 83.
	the figle capital	Automes, Inc.	
-	> Tallahas:		-37

1

Registration No. ELT Battery date 12-28-85

Ry

Engine

565.83

rear

598.9

p. En-My

epared

loo.

KEPLADED

alle

June

Fucks

Signature

WAD 83-22-04

seed man

BOTH

and Remarks

Bendy

IRES.

resta

Certificate No.

tery

gear

run up and

VIAIN

					-
Date	Aircraf	Time	Recorder	Maintenance	
Dale	This Date	Total	Reading	maintenance	-
	Brought Forward	THE ATC L	Insponder Lists	and inspections required	
		COMPLY WIT	n FAR 43, Appe	78A Seriel 110 7444	6
		Make_JJ/	Model	Serial No.	6
	Port	nent details are	on file at this	agency under	_
	w.d.:	# 2726 Dat	·17 0083	Capital Avionico, Inc.	4
				Tallahassee, Fl. 22304 Certificate #707-37	_0
	1				
					le le
					-
					-
tal To Irry Forward					6

Registration No._

Certificate No.

BELT

-

Dete	Aircraft	t Time	Recorder			1
Date	This Date	Total	Reading	Maintenance	and Remarks	Signature
11SEPT84	Brought Forward	TACH 6	09.3 (/W A/D 77-12-06	I certify this <u>AIRFRAME</u> has been inspected in	
	By PRO	PELLER	OUER H	AUL - SERVICEABLE	accordance with a <u>MWUMPU</u> inspection and was found to be in an airworthy condition.	
	TAG B	BACK OF	F LOG,	REPLACED BOTH	Tach Time 609.3 Total Time 609.3 Date / 4 Sept 1984	
	BRAKE	DISK P	VN 164	23, SERVICED ALL	Rochney J. Hailley	
	STRUTS	WITH	5606	+ NITROGEN, REPACKED	RODNEY J. HAILEY IA 2184891	
	WHEEL	BRCS.	I CER	TIFY THIS ACFT	29 APR85 TACH 649.6 REPLACED 1	AL TERNATOR,
	HAS \$	BEEN 1	NSPECTE	D I/A/M 100 AR	PIN 452-823 & BATTERY.	they Ablo
	INSPECTIC	on &	WAS	DETERMINED TO	AdP1908771	11-
	BE IN	AIRI	NORTHY	CONDITION	AIRBORNE, VERY OFTEN WILL PHA	SE INTO
	Talk	ABI	6 A	KP190877/	IT'S EXCHANGE PROGRAM-BRAND N AT NO COST PENALTY TO YOU, OU CUSTOMER THE INIT IN THIS CA	R
Total To Carry Forward					CUSTOMER, THE UNIT IN THIS CA A <u>NEW</u> ACCESSORY.	RTON IS
				i k		

	11 A					
Date		ft Time	Recorder	Maintenance		
2	This Date	Total	Reading			
105EPT85	Brought Forward	TACH 69	2.5 R	PLACED BOTH		
•	WINDSHIELD	s - OB	STAB.	TRIM HINGES -		
	BOTH CA.	BIN Do	OR SER	15, SERVICED AIR		
	CONDITIONE	ER, REI	NOUED	PROP & REWSTALLED		
	AFTER	RESEALED	BY	ATLANITA PROPELLER.		
	I CERT	FY THI	5 Ac.	FT HAS BELEN		
	INSPECTED	1/A/W	100 HR	INSPECTION & WAS		
	DETERMAIN	0 70	BE	N AIRWORTHY CONDITION		
	Tally	Bill	AXPIQO	877/		
	V / 1					
Total To Carry Forward						

Registration No		
and Remarks	Signature	Certificate No
I certify this <u>AIRFRAME</u> has been inspected in accordance with a <u>AUNUAL</u> inspection and was found to be in an airworthy condition.		
Tach Time <u>692.5</u> Total Time <u>692.5</u> Date <u>10 Sept 85</u> Rorthey I Lailer		
ROCNEY J. HAILEY IA 2184891		
х х		

Date	1 5 1	ft Time	Recorder	Maintenance
Dule	his Date	Total	Reading	Multiendice
28 JAN 86	Brought Erward	TOTAL TI	NE 729.7	REMOVED & REPLACED
	D.G AF	TER REPA	K BY	AA-LST, RESEALED RIN
	WHEEL E	RAKE CY.	INDER,	REPLACED ALL BRAKE
	LININGS,	SERAMCE	D ALL	STRUTS WITH HYD
	FRUID +	NITROGEN	, REPL	ACED VACUUM PRESS SW
	REPLACED	ELT	BATTER	Y, REPAIRED BORTOM
	CONV. G	BOTTOM	MOUNT.	I CENTIFY THIS
	ACFT 1	AS BEEN	INSPL	CTED IJAIN ANNUAL
	INSPECTION	+ WA	S DET	ERMINED TO BE
	IN AIRV	VOKTHY	CONDITION	Jally BHL
Total To			ANDIA	AT

Registration No	` `	
and Remarks	Signature	Certificate No.
24 MAR 86 TACH 751.1 C/W 5/B 811	BY INSTALL	IN G
AMMETER KIT 765186 Jally	Bill ANPIPO	577/
16 APR 86 TACH 758.3 REPLACED AL	TERNAJAR L	ELT
P/N 452-823 + PULLY P/N 99072-0	og tal ABill A	XP1908771
9MAN86 TACH 763.0 CAN BENDI	SERU. BOL	LETIN
NO 464A & 623A DATE 9/1982	REVISED 81	1984
BY REPLACEMENT OF IMPULSE CO		
Jally Bill Ad P1908771		
	REPLACEMENT	ANNETER
Jally Bill ALPIROB771		

Aircraft Time Recorder Date Maintenance Reading This Dote Total Brought REPAIRED 7. JULY86 TACH 808. 4 Forward RIH MAIN WHEEL PAINT MOUNT. NELDEM PANT PAINTED OUTSIDE ALP 1908771 NOTATE MAIN TIRES Vally 1 4. SEPT 86 86-1 NOTE AID PICIN BY 811 A. Ad P1908771 SIR Mer 19 JAN87 840.0 KEPLACED # 2 + #3 ENHAUST ACH MUFFLERS N/EW AB1000 EX GASHETS, WITH KEPLACED BRAKE LININGS, KEPLACED RIH BOTH ONE TUBE, REPLACED MAIN TIRES N AIR HILTER Totol To Carry Forward

Registration No. Certificate No. Signature and Remarks ACFT HAS INSPECTED FRTIFY THIS BEEN AIN INSPECTION DETERMINED WAS ANNDAL TO AIRWORTHY CONDITION DE 1908771 898.3 FIBERGLASS. 30 TAN INSIDE PLATE REPLACED WHEEK OWL BRAKE KEPLACED 65148-001 LININGS. FRIFY HAS DEEN 1415 INSPECTED ANINUAL ALIV INSPECTION WAS DETEKMINED AIRINORTHY ONDITION. 10

Dette	Aircra	ft Time	Recorder	
Date	This Date	Total	Reading	Maintenance
5 FER 89	Brought Forward	TACH 96	7.7	CLEANED & TREATED
	BATTERY	Box.	REPL	CED ELT BATTER
	REPLACE	O BR	AKE 1	ININGS. I CERTIF
	THIS	ACFT	HAS	BEEN INSPECTED
	1/A/W	ANNUA	L IN.	SPECTION & INAS
	PETERMI		to	BE IN AIRINDATHY
	CONDITION		un AR	le APPI908771AI
			11-	

and Remarks	-	Signature	Certificate No.
15 DEC 89 PROP O/H BY	ATKANTA	PROPERIER	INC
BRAKE LININGS REPLACES	NOSE	STROT +	NOSE
PAINT FAIRINGS REPLACED.	I CEM	TIFY THE	<u> </u>
ACET HAS BEEN INSPEC	CTED VA	IN ANNUAL	
INSPECTION & INAS DET.	RMARED	TO BE	111
AIRINORTHY CONDITION J	day ASI	L AtPI908	771 AI
27 FEB 90 TACH 1124.57	REPEACED	BOTH	MAIN
TIRES & TUBES Jally AB	the AXF	1908771	
. / 1/			
	ι		
	*		

A NOT N

Aircraft Time Recorder Maintenance Date Reading This Date Total Brought REPLACED 1186.6 Oct90 Forword ALTERNATOR BOLB MOONT. POLLEY ANDING LIGHT AJ P1908 771 23 MARCH NEPLACED 196 SIDE OW IACH AIR SERVICED COND. TINO LBS HOSE FREON STRUTS DERVICED WITH 33 NITROGEN. HYD FIUID MAY INSPECTI AS DEEN CERTIFY INSPECTION WAS ANNUAL AIRWORTHY ETERMINED BE n IN 17 P1908771 AT ONDITION

SFEB91 HOBBS: 1363.8 7 1 11 2 I certify that the static pressure system, each altimeter Certificate No. Signature Instrument, and each automatic pressure altitude reporting system test and inspections required by FAR 11.411 has been performed. X WSGARRISON The ATC transponder tests and inspections required by FAR 91.413 were performed this date and found tr SFEB91 HOBBS: 1363.8 comply with FAR 43, Appendix F. Make KING Model KT76 Aberial No.47050 Make_____Model_____Serial No_____ 1. The static pressure system was tested on 8FFB91 2. The altimeter(s), instrument(s) was/were tested to ZC CCC ft. on BEEB91 3. The automatic pressure altitude reporting system was tested to 20000 ft. on 814. 5 Signature NBCINRIUSON Certified Repair Station #707-37 . Performent dotails are on file at this agency under W.O. #10566 Date 8 FEIS signed NOCAR MON 1991 Capital Avionics, Inc. Tallahassee, Fl. \$2304 Certificate #707-37 NS4R-399M

4. . . . AIRCRAFT LOG ---4 . A . . "M Aircraft Time Recorder Date Maintenance Reading This Dote Total Braught Farward + TACH CABLE 18 Nov 91 TACH 1206.4 INSTALLED #763961V REROUTING KIT 1/A/W #78821 FACTORY REPLACED DRAW ING FUEL A PUMP LW 1547 AXP 1908771 ally REPLACEMENT P/1 38462-02 NOTE : ABLE -Total Ta Carry Farward

Registration No					
and Remarks	Signature	Certificate Na.			
4 MAY 92 TACH 1216.0. REPLACED	NOSE TIRE	& TURE			
RIH BRAKE LININGS REPLACED,					
COMPRESSOR OIL & SERVICED AIR					
FIBERGLASS REPAIR R/H 1/B WHE	EL FAIRING	COUER,			
INSTALLED NOSE STRUT KIT. I					
ACET HAS BEEN INSPECTED 1	12/W ANNUS	12 .			
INSPECTION & WAS DETERMINE	TO TO BE				
IN AIRWORTHY CONDITION ally A	IL AXPIGOST	ILAL			
~ 16					
x					

Aircraft Time Recorder Date Maintenance Reading This Dote Total Brought Forward 1366 KEPLACED ELEU TIRMA MAY93 END BRG (BINDING), REPLACED #42 #6 ROD + #345 EXHAUST STACK MOFFLER BL 349370-4 1 21100 UAC PUMP LIH MAG REPAIRED LEANS AIR COND. REPLACED. WELDED WHEEL FAIRING NOT. RIH PAINT TOUCH UP - INHEEL FAIRINGS, WING LEADING CERTIFY EDGE & STAB. THIS ACFT 1/A/N BEEN IN SPECTED ANNUNI WAS INAS DETERMINED IN ALKNOWNY INSPECTION Total To ONDITION Tally Bill ASPIROSTTIAE Carry Forward

Registration No._ Certificate No. and Remarks Signature REPLACED BATTERY G-35 W/ACID 200793 A& P1908771 7 JAN 94 1425.0, LNSTALLED HOSE KIT. ANPIGORTTI

Date	Aircro	oft Time	Recorder	Maintenance
Date	This Date	Total	Reading	Mainfenance
17 JON 94	Brought Forward	1401.6	REPLA	ED CABIN DOOR (R/H)
	DOOR L	ATCH 1	Por B;	AN-26 WELDING, ALL BRAKE
	LININGS	REPLACE	D, IN:	TALLED DOUBLER BOTTON
	CONK	MOUNT,	INSTALL	D AN23-11 CIEDIS BOIT
	+ BUSHI	V6 63900	-174	ON FLAP HANDLE,
	ELT BI	TTERY	REPLACE	FIBERGLASS REPAIRS
	WHEEL	PANT.	T CERTI	FY THIS ACFT HAS
	BEEN	INSPECTED	IAK	N ANNUAL INSPECTION
	+ INAS	DETERMY	NED	TO BE IN AIRINDATHY
	CONDITION.	Sally	1Ble	AXP1908771 AT
Total To Carry Forward				

and Remarks			Sign	ature	Certificate No.
1 JUN 95	TT 1462.6 I	CENTIFY	THIS	ACFT	HAS
BEEN	INSPECTED . 1/A/W	ANNUAL	INSP	SCTION	×
Was	DETERMINED TO	BE IN	I AI	RINORTHY	CONDITION,
_	July ABill 1	Ad PI905771	AT		
12 APR 76	TT 1498.8 C/4	A/D 99	-26-13	BY	INSPECTION
OF HOSES	(NOTE HOSE KIT	INSTALLED	-94 1425 h	(185):	
	MAIN TIRES FL				PLACED
ALL BRA	RE LININGS, RESEALE	D MAIN	STRUTS	ELT A	NTENNA
REPLACED	CERTIFY THIS ACFT	HAS BEEN	INSP	ECTED 1	1/A/W
	ECTION & WAS DETERMINE	N			1
CONDITION.	1 112.0.				

Registration No._

	Aircro	ft Time	Recorder	N	
Date	This Date	Total	Reading		Maintenance
26 APA 96	Braught Forward	1502.3	REPLAC	ED REAR	CABIN
	DOOR	WINDOW	P/N 4	P940 Jaly AB	26 ANP1908771
1/196	1530.7	INSTALL	NOLTH	TAR MI LORA	N, ANTENNA,
11				337 FORM + N	
-		OPS CHECK	O.K. Ank	CLAFT RACAMPED	"LORAN-C
				I.F. R. " ARCCAF	2
- and		RETURN	TO SERV	ice. Alist lau	Jut Aspansions
				AL AL	
Total To					

Registration No		-
and Remarks	Signature	Certificate N
Decatur-Athens Aero Services PRYOR FIELD AIRPORT REPAIR STATION D75R275N REQUIREMENTS OF FAR 23.1325, FAR91.217, FAR91.411, and FAR 91.413 have been accomplished as follows on 91.413 have been accompliance the follows on 91.414 have been accompliance the follows on 91.415 have been follows on 91.416 have been correspondence check to 91.417 have been correspondence check to 91.417 have been correspondence check to 91.417 haveen correspondence check to		

......

1 . . . AIRCRAFT LOG ----Registration No. Aircraft Time Recorder Maintenance Date Reading and Remarks Certificate No. Signature This Date Total Brought Forward completed this date IAW FAR 1638 4-6-97 100hr inspection opened inep. panels check pulley, Caller 43 appendix D hinges I moving ports, greated landing AD list in back of fullcramps laber this Say beep. retarged links, place all on jacket gen sissons + 5606 fluid + nitioga to 5" extrucion. secured shuts with all what bearings, checked brakes + uleels cleaned of repacked + replaced Opings seale in brake aylinder on piston Cleaned brake assig's Replaced Vac system + Van vilief fitters, Pylaced ELT Battery New replacement date - July 1999 CENTIFY THAT THIS AIRCRAFT HAS BEEN, DISPECTED IN ACCORDANCE WITH A 1920 I WENTIFY THAT THIS AIMCHAFT HAS GEEN INSPECICE ST TO A NO WAS DET PLUNED TO BE M ACCORDANCE WITH A ALCONDA L INSPECTION IN THY CONDITION ILL AD. NOTES MA WAS REIESHINED IS BE IN ALEWORTHY CONDITION Voncen liter NO 18 30934 C/W AD 90-02-23 Propeller Hub Crocks Each 50 la T.1.5. Edward T. Smble anna 6-6-97 Tatal To IA 280065 6 JUNE 97 **Corry Forward**

-

Date	Aircraf	t Time	Recorder	
Date	This Date	Total	Reading	Maintenance
12-10-9	7 Brought Forward	1675.		Replaced, alternates
			1	Belt. Venon autin
6-2-0	8 Jack-	1695		100 h mapution CW
this	dato 1A4	FAR 4	3 appen	lix D remared, cleaned
and s	inputed a	huls, b	upes, +	time, repubed allabe
B		A A		a, Control kinges ,
red end	l bearings of	bellas	ubs,	serviced of changed butter
			5	SPECTED IN ACCORDANCE WITH A 100 Mars
e service un assorb	THE WITH A ADDA	WACHESTERS) P	ARMORTHY CONDITION: ALL A.D. NOTES
AND MAR S		MARINE LAND	Venn.	1110 fin AND NO 18 50 954
	AZEDOCE		AP "	

Registration No. 4 -1 -2 and Remarks Signature Certificate No. 744.2 10-19-98 - Jach. 1 sar lonon 11-12-98 Replace Vertical fing strabe New piper part. Venonla mon las 4 .

007-25-2001 Registration No.___ AIRCRAFT LOG New ELT BATT REPLACE DATE 1999 gemarks ELT Remard for Marint. Aircraft Time Certificate No. Signature Recorder Date Maintenance Reading This Date Total 8-17 Jack- 1823.57 110 hr inspection completed Brought Forward **Decatur-Athens Aero Services** this date IAW FAR43 appendix D PRYOR FIELD AIRPORT removed wheels, checked wheels, **REPAIR STATION D75R275N** REQUIREMENTS OF FAR 23.1325, FAR91.217, FAR91.411, and FAR 91.413 have been accomplished as follows on ACYCIS & times, cleaned + reparked retuel bearings. (a) Transponder Manufacturer King Model KT7LA Serial number 47050 removed, serviced + Charged balling, lubed controls. Transponder certified IAW FAR 43 APPENDIX F. (b) Altimeter Manufacturer Kollsuren Model 6 NILLO Serial Number 41098KID NARCO AVIONICS INC. led brake resurion, smoothedprop nicks, Altimeter certified to 20,000 feet IAW FAR 43 APPENDIX F (c) Performed correspondence check to 10,000 SERVICE TAG (d) STATIC SYSTEM CERTIFIED AS PERFAR 23.1325. SIGNED Dominic Hospiel 23 MODEL # CUTIO 5N 74822 DISTECTED IN ACCORDANCE WITH A 100 ha BRATIFY THAT THIS AINCRAFT BAS SHEN INVECTOR DATE 5-13-11 INCIECTION AND WAS DETERMINED TO BE ACCORDANCE WITH A ANNUAL INSPECTION THROUGH 15599 CW. WOR 344500 HA WAS BETERMINED TO BE IN ALRWORTHY COMPLICATION. Venier listin ALY HO 1830934 Roward T. Smbly DETACH AND AFFIX DATE 8-17-99 Total To 1A 280065 17AUG99 TO LOGBOOK Carry Forward

Date	Aircraf	Aircraft Time		Maintenand	
Duie	This Date	Intal	Reading		
-30-	Brought Forward	ton	7 1860	Remove non s in bottom strut flindt nitrigen Vennon tust	trut
	-	- replace	e seal	in bottom strut	1
	ser	the w	th 5600	fluidt nitrogen.	/
				Venon tust	in
					*
-	A F				
	•	÷.			1946
tal To rry Forward		4			

N8088B Registration No._ Certificate No. and Remarks Signature -26-00 Jotal Jack - 1914,75 100 m inspection Conjulited IAW FAR 43 appendix D insp. plates & tail come faring, ables & label mouning parts, checked wheels leaned + repached all wheel beings, replaced brake timings. Caling door seal, + -we Uset fin farings B DESERV THAT THIS RINGSAFT BAS SEEN INSPECTOR PIEPECTED IN ACCORDANCE WITH A 1000 A ACCORDANCE WITH A PANUAL INSPECTION INSPECTION AND WAS DETERMINED TO BE AND WAS DETERMINED TO DE IN ANEWARTEY CONDITION REARWORTHY CONDITION ALL A.D. NOTH THROWOH 2000-19 CW luchings NO 1830934 14280065 26 SEA 2000 9-26-0

AIRCRAFT LOG NUN ELT Rattery Replace in to " Aircraft Time Recorder 2001 Maintenance Reading Total This Date Brought 100 have inspection IAW FAR 43 Forword 10-10-01 I with checked all + stell warmin uched all wheel rearings. shuts to proper extension mplated Contrig geon Assonst lubed Controls - CERTIPY THAT THIS AIECRAPT HAS SEEN PASPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WIS ETERMINED TO BE THROUGH 2001-20CIW. Un ust 18A NO 454840045 > CERTIFY THAT THIS AIRCRAFT HAS BEEN MSPECTED IN ACCORDANCE WITH A 100 MA INSPECTION AND WAS DETERMINED TO BE DATE 10 -10-IN AIRWORTHY CONDITION, ALL A.D. NOTES THROUGH 2001+20 C.W. fluitures NO 1830 Total To 10-10-0 Carry Forward

Certificate No. ature **Decatur Athens Aero Service** Pryor Field - Highway 31 Athens-Decatur, Alabama 35601 FAA Repair Station #D75R275N Class 1 & II The requirements of FAR's 23.1325, 91.217, 91.411 and 91.413 has been accomplished on Date: 10/15/01, as follows on: (a) Transponder manufacturer: KING Model: KTIGA , Serial number: 17050 Transponder certified I.A.W. FAR 43 appendix E. (b) Altimeter manufacturer: Kollsman Model: 67/1810 , Serial number: 41109 Altimeter certified to: 10K. Feet I.A.W. FAR 43 appendix F. -'c) Performed correspondence check on altitude encoder Manufacturer: Newco, Model: AASOO Serial number: 19576, To: 20 K. feet. d) Static system certified as per. FAR 23.1325. Signed: Hume Horsey

AIRCRAFT LOG

	Aircraft Time		Recorder	Matataa		
Date Lec /	This Date	Total	Reading	Maintenance		
DEC. 8	Brought Forword +	1931.2	1931.2	INSTALES NEW RG.		
				ALL EVECTRICAL		
IOMAY OZ	TOTAL TIM	E 1947.6	REPLA	CEP VOLTAGE REGULATOR		
		P/N UN	200A	ally Abile At P1908771		
17MAYOR	TT 195	6.9 A	EPLACED	WACUUNA PUMP		
			Halley.	1Bile AdP1908771		
		4	///			
Total To Carry Forward						

Registration No. Certificate No. and Remarks Signature DARS W.O. AXC BATTERY S/N 426914 . CHECKE #04892 423249241 ASP. 14 Systems VW A/D'S 2001-23-08 JULY 02 TIME 1974.6 TOTAL + 2002-09-08 HARTZELL REPLACEMENT RE HUB ATLANTA PROPELLER WO 17102. Chu AD 95-26-13 BY REPLACEMENT COOLER OIL 124 FOOI - 8CR0210 - 260-284, A/D 99.05.09 BY REPLACEMENT AIR 78-23-01 FILTER, OPERATION Door, FUEL DRAIN COVER INSPECTION 93-02-05 FUEL INJECTOR LINES.

Date	Aircraft Time		Recorder	Maintenana		
Date 2	This Date	Total	Reading	Maintenance		
	Brought Forward	REPLACED	FOLLO	WING PARTS - MAIN		
	/			AIR STOP TUBES,		
NOTE !	INSIDE A	DAIN LAND	UNG GEA	R)- 484-769 QUAD SEAL		
VAN 91207	63314-00	RING, G	3307-0	0 RING, 486-188 SCRAPEA.		
D) OP CK	AIR CON	p Hoses	PIN 56	6-228 + 63904-092,		
	AIR FIL	ER Coul	R 3801	7.008, LIH STAB. TIP		
	63584.	010, ALT	+ COMP.	BELTS 73965-009 + 73965-010,		
	ALTER NA	TOR ALY	6522 - R- 1	E, FOWARD MUFFLER 0004,		
	L/H EX		1	ALL EXHAUST GASKETS		
	77611, R	H BOTTOM	WINC B	OLT COVER 63942-001		
Total To Carry Forward		4EA ENG	INE MOO	NTS J3804-40,		

Registration No. Certificate No. and Remarks Signature SIDE FROM EXHAUST LORR OSSION RIM REMOVED DELLY REAR OF AIR COND. DOOR TRACK BACK USING. STEAL BRUSH - METAL STAIN LESS REP ETCH # 79-ALODINE # 1201 - REPLACED REAR RIH HAT SECTIONS PIN 68609-001- 68612-000- 62554-000 - PRIME & PAINT AREA. ALL REPAIRS FIBER GLASS WHEEL COVERS - PRIME & PAINT. BY BOB'S AUTO + MARINE WO 80558 UPHOLSTERY REPLACED 1/A/W FAR 25.853(A) APP F STATE MENT OF FLAMM ABILTY LOG FOLDER. 1 GENTIFY THIS ACAT HAS BEEN MISPECTEN WAS DETERMINET TOBE IN AIRWORTHY INSPECTION UALN ANNUAL Jally A Bill AVP 1908 TTI AT LONDITION

Date	Aircra	ft Time	Recorder	Maintenance
Dale	This Date	Total	Reading	Maimenunce
4 Nov 0.3	Brought Forward	TOTAL TIM	= 2095	8 REPLACED ALL BRAKE
	LININGS	66 - 105 ,	REPLACE	D FLT BATTERY (NOU 05)
	W/ ELT C	PERATIONAL	CK F	AR 91.207(D) C/IN A/D
	78-23.01	BY OPEN	ATIONAL	CK FUEL DRAIN COVER,
	C/W NO	93.02.05	BY INSI	PECTION FUEL LINES - NOTE
	ALL FUEL	LINES	REPLACED	W/ NEW CLAMPS THIS
	DATE @	ENG OF	H- SEE	ENG LOG FOR DETAILS.
MAN PRESS/	FUEL FLOW	O/H BY M	LAYLOR IN	STRUMENT SERV. INLIGICE 3662
	TGERDFY	THIS ACFT	NAS E	BEEN INSPECTED I/A/W ANNUAL
	INSPECTION	WAS DETO	MALINED	TO BE IN AIR WORTHY
Tatal To Carry Farward		CONDITION.	11	BRE AXP 1908771 AI

May 18, 2004 N8088B Removed King KMA-20 Audio Panel s/n 26142, KR-86 ADF Receiver s/n 28868, KX-175B Nav/Com s/n 42482, KN-75 Glideslope Receiver s/n 10545, KN-72 Vor/Loc Converter s/n 16061, PM1000II Intercom s/n VN-07759, and KA-42A Loop Signature Certificate No. Antenna. Installed Garmin GNS-530 GPS/Nav/Com s/n 78410894, GMA-340 Audio Panel s/n 96269140, GDL-49 Datalink s/n 39803872, GA-56 GPS Antenna s/n 59093231 and AV-14 Datalink antenna. Installed placard stating "GPS approved VFR use only". Revised aircraft weight and balance. AVIONICS INT DATED Executive Beechcraft inc 10 Richards Rd. •Kansas City, Missouri 64116•Phone (816) 842-8484 This constitutes an official maintenance record per FAR 43.9 & 43.11. AIRFRAME S/N: 32-7940250 Reg. No. Date Tach NSOSSB 6/18/2004 2182.2 1. Installed new engine oil cooler Aero-Classics, Inc. Huron Ohio part number 8000074 serial/batch number 1041170 thru 1041199. 2. Removed oil temperature gauge face and adjusted needle to relieve hysteresis error. 3. Ground operational checks checked satisfactory at this time, leak checked and no leaks noted at this time.

Pertinent details are on file at this repair station under work order 51-27344. File name: 5127344MO Inspector Signature EXECUTIVE BEECHCRWFT, INC - MKC • FAA certified repair station AKGR142C

Date

Total To

Carry Forward




GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

N8088B 12-14-04 TACH:2243.07 TTA: 2243.07 Completed an annual inspection in accordance with FAR 43 appendix D supplemented by piper pa-32-300 checklist. Cleaned and lubricated all wheel bearings. Lubricated aircraft per checklist. ELT removed for repair. Replaced tail Nav. lamp GE1777. Resealed left and right brake cylinders. Replaced right brake linings. Replaced instrument air regulator filter B3-5-1. Cleaned battery box. Complied with AD78-23-01 by operational check of fuel drain cover; satisfactory. Oil cooler hoses inspected per AD95-26-13; satisfactory. Complied with AD2002-26-01 by inspection of fuel injector fuel lines; satisfactory. I certify this aircraft has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. Timothy K. Stroman IA 466594753

tenand	0
renun	





Registration No.__

N8088B 1-10-05 Reinstalled ELT after repair. Timothy K. Stroman A&P466594753

1-21/6

NARCO AVIONICS INC. 903-643-0980 NARCO AVIONICS INC. SERVICE TAG MODEL # <u>£1710</u> S/N <u>74 82 2</u> DATE <u>12/31/6 4</u>



W.O.# 30827

DETACH AND AFFIX

TO LOGBOOK

ertificate No.

Registration No._



Total To Carry Forward

GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

N8088B 2-9-05

Re-sealed nose gear and serviced with 5606 and nitrogen. Timothy K. Stroman A&P466594753

Varet KE

GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980 Certificate No

 N8088B 9-23-05 TACH: 2369.7
Replaced main tires with new Goodyear Flight Custom IIIs.
Timothy K. Stroman A&P466594753

Took la

tenance



N8088B

Total To Carry Forward GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

Completed an annual inspection using Piper PA32-300 checklist.

AD2002-26-01 fuel injector lines inspection satisfactory. AD84-26-02

replaced paper induction air filter. Due replacement each 500 hours

and inspected each 100 hours and annual. AD76-07-12R1 functional

test of ignition switch satisfactory. Replaced cracked hose in manifold

pressure line. Replaced o'rings in both brake calipers and re-lined

left brake. Functional test of ELT in accordance with FAR91.207(d)

Cleaned and lubricated wheel bearings. Replaced nose wheel bearings and races. AD2005-19-11 does not apply due to crank S/N and not replaced after 3-1-99. AD2005-14-11 not applicable as prop has not been repaired or serviced by Southern California Propeller Service. AD78-23-01 functional test of fuel drain cover satisfactory. AD95-26-13 oil cooler hoses inspection satisfactory.

12-22-05


TACH: 2384.6 TTA: 2384.6



Maintenance

satisfactory. Battery due 2-07. Replaced instrument air filter and regulator filter. Tensioned to spec. rudder, stabilizer and aileron cables. Replaced rivets in belly longeron 2nd inboard from right. I certify this aircraft has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. Timothy K. Stroman IA466594753


- to they bla





GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980





TACH: 2469.5

Serviced, charged and installed new G-35 battery S/N G02295047. Replaced left wing fuel tank fuel transfer couplings and vent couplings between inboard and outboard tanks. Repaired cowling at right forward latch pin. re-sealed nose strut. Timothy K. Stroman A&P466594753

Certificate No.



Date

GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

N8088B 5-3-07 TACH: 2514.52 TTA: 2514.52

Completed an annual inspection using Piper PA32-300 checklist. Cleaned and lubricated all wheel bearings. Replaced all brake linings and both brake discs. Bled and serviced brake system. Replaced forward and aft cabin door seals and aft baggage door seals. Replaced bent bolts in steering stops. Inspected cabin heat exchangers (mufflers) for cracks and found none. Complied with **AD78-23-01** fuel drain cover inspection; satisfactory. Complied with **AD78-23-01** fuel drain cover inspection; satisfactory. Complied with **AD76-07-12R1** ignition switch; satisfactory. Repaired lower cowl mount hole and left wheel cover. **AD84-26-02** replacement of induction air filter due at TTA: 2884.6. 100-hour/annual inspection of filter; satisfactory. Functional test of ELT in accordance with FAR91.207.(d); satisfactory. Battery replaced and next due 5-09.

I certify this aircraft has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. Timothy K. Stroman

IA466594753

Total To Carry Forwa

	ature	Certificate No
IAW FAR 91.411 The altimeter make Kollon		
Model 671K-10 and S/N 41109		
Tested to 20 K ft. and found to comply with		
FAR 43 App. E see W.O. 4301		
Inspected by Date 5-14-07		
Sparrow Aviorets Inc. FAA CRS XXYR919L		
3211 C.R.384 Tyler Texas 75708 1-800-416-8548		
Encoder Pitot Heat Static		
IAW FAR 91.413 The transponder make Kidg		
Model KT76A and S/N 47050		
Was tested and inspected and found to comply with FAR 43 App. F see W.O ₂ 430 i		
Inspected by Chillen Date 5-14-07		
Sparrow Avionics Inc. FAA CRS XXYR919L 3211 C.R.384 Tyler Texas 75708 1-800-416-8548		

and

intenance




Date

GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

N8088B 6-13-07 TACH: 2524.52 Installed new left magneto P/N 10-349370-4R. Replaced starter with overhauled unit P/N MZ4222R. Heli-coiled starter mount threads. Replaced nose strut guad seal and filled.

Byron C. Williams A&P2021731





GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0280

N8088B12-21-07TACH: 2950.0Replaced both brake caliper assemblies with new P/N 030-06500.Bled and serviced system. Function test good.

Byron C. Williams — A&P2021731

Total To Carry Forw Byten C. William

lintenance

and Rem

GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

Registration No.



artificate No.

TACH: 2630.69 TTA: 2630.69 N8088B 5-30-08 Completed an annual inspection in accordance with Piper PA32-300 checklist. Cleaned and lubricated all wheel bearings. Replaced LH wing bolt fairing/cover. Functional test of ELT in accordance with FAR91.207(d); satisfactory. Battery due 5-09. Replaced right aileron aft rod end bearing with new P/N 452-334. Replaced ring terminals at A/C blower circuit breaker. Replaced all stabilizer trim hinges and pins with new parts. Replaced nose tire 600x6x6ply. Replaced both upper and lower tail cone fairings P/Ns LSM-600-101-3 and -4. Painted both. Repaired cowl cracking at forward RH lower attachment and replaced both bushings. Patched small hole in lower LH cowl area. Replaced nut plate at lower R/H cowl. Repaired cracks in fiberglass wheel pants. Complied with AD78-23-01 fuel drain cover; satisfactory. Complied with AD95-26-13 oil cooler hose inspection; satisfactory. Complied with AD2002-26-01 inspection of fuel

Continued on next page

Byun C. Willi

injection lines; satisfactory. Complied with **AD76-07-12R1** ignition switch functional test; satisfactory. Complied with **AD84-26-02** by 100hour/annual inspection of induction air filter; satisfactory. Replace filter at TTA: 2884.6. Replaced elbow and spacer from induction air duct to injector body P/Ns 69232-006 and 69231-000. Replaced landing light. Resealed nose gear shock strut and serviced to spec. I certify this aircraft has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.

Byron C. Williams IA2021731 /

Maintenance

Registration No.



Certificate No.



To v Forward GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980



ance

N8088B 3-15-10 TACH: 2637.04 TTA: 2637.04 Completed an annual inspection in accordance with Piper PA32-300 checklist. Cleaned and lubricated all wheel bearings. Replaced ELT battery. Next due 4-2012. Functional test of ELT in accordance with FAR91.207(d); satisfactory. Replaced main battery with new Gill G-35 S/N G02482001. Replaced vacuum regulator filter. Replaced elevator trim cable P/N 62701-042 in accordance with PA32-300 Manual. Rigged to spec. Replaced landing light bulb. Complied with AD78-23-01 by inspection and function test of fuel drain door; satisfactory. Complied with AD95-26-13 by replacement of oil cooler hoses P/Ns 124F001-8CR0210, 124F001-8CR0260, 124F001-8CR0284. Complied with AD2008-14-07 by inspection for conformance with proper support of engine fuel injector lines; satisfactory. Complied with AD76-07-12R1 by satisfactory functional test of magneto switch. I certify this aircraft has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. Timothy K. Stroman/IA3390266 75

Registration No._ Certificate No. GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980 N8088B 1-17-11 TACH: 2637.04 Re-sealed all toe brake actuators with new o'rings. Bled both main gear brake systems. Function check good. Greg Burnett A&P3367653



intenance

GREGG AIRCRAFT SERVICES, INC. EAST TEXAS REGIONAL AIRPORT 155 DOVEL ROAD LONGVIEW, TX 75603 903-643-0980

•

TTA: 2641.66 TACH: 2641.66 N8088B 7-1-11 Completed an annual inspection in accordance with Piper PA32-300 checklist. Cleaned and lubricated all wheel bearings. ELT battery next due 4-2012. Functional test of ELT in accordance with FAR91.207(d); satisfactory. Replaced main battery with new Gill G-35 S/N G02558652. Complied with AD78-23-01 by inspection and function test of fuel drain door; satisfactory. Complied with AD2008-14-07 by inspection for conformance with proper support of engine fuel injector lines; satisfactory. Complied with AD76-07-12R1 by satisfactory functional test of magneto switch. Complied with AD2010-15-10. Both control wheel shaft universal joints meet requirements of SB1197B. Evacuated A/C system and charged with 2 lbs. R-12. Function check of A/C system good. Cleaned corrosion from battery box and treated with Corrosion X. Airframe controls lubricated.

I certify this aircraft has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.

Timothy K. Stroman ? IA3390266

al To

Registration No. and Remarks Signature Certificate No. September 30, 2011 N8088B Removed GDL-49 s/n 39803872, M1 Loran s/n 15097, AV-14 s/n 1202, K1-266 s/n 1182 and KN-65A s/n 23467. Installed AirGizmos Panel Dock. Performed compass swing. Aircraft to be reweighed. AVIONICS UNLIMITED FAA CRS# VUER010Y

Date: 10-22-2011	Aircraft # N8088B Airframe	Serial # 32-7940250		e: 11-4-2011 h: 2680.38	Aircraft # N8088B Airframe Total Time: 2680.38	Serial # 32-7940250 SMOH: N/A
Tach: 2677.24	Total Time: 2677.24	SMOH: N/A	Rep	place right door window	v with new part.	
Prepared By: H. L. Wils Certification # 3182068	son			pared By: H. L. Wilson tification # 31820581A		
Date: 8-4-2011	Aircraft # N8088B Airframe	Serial # 32-7940250				
Tach: 2645.40	Total Time: 2645.40	SMOH: N/A				
Replace A/C compressor	r, replace filter/drier, clean expansion valve,	, evacuate and charge system.				

Aircraft Time Recorder Maintenance This Date Total Reading Maintenance	and General Avionics, Inc. FAA CRS#Y4XR461Y Certifica
This Date Total Reading	
Date: 8-9-2012 Aircraft # N8088B Airframe Serial # 32-7940250 Tach: 2734.15 Total Time: 2734.15 SMOH: N/A Remove inspection covers, lube hinges and rod ends, clean and pack wheel bearings, replace main tires, lube gear, replace tail nav bulb, service A/C system, replace ELT battery and test per 91-207D, expires 9-2014, service brakes and battery, C/W AD 78-23-01 by inspection, next due 2834.15, C/W AD 95-26-13 by inspection, next due 2834.15, C/W AD 95-26-13 by inspected IAW an annual inspection and found to be airworthy. Repeare Boy H AIC HOSES IN EMBLY MEML, CHARGE System, of PERATEDIN OK.	West Houston Airport 18000 Groeschke Road, Hangar 1-E, Houston, Texas 77084 Model: <u>PIPER PA32-300 Reg: N808813</u> S/N: <u>30 - 7940350</u> W/O: <u>IO 703</u> In accordance with FAR 91.413, this ATC transponder has been tested and inspected and found to comply with appendices E and F of FAR part 43. UNIT: <u>KT75A</u> S/N: <u>47050</u> In accordance with FAR 91.411, each static pressure system, each eltimeter instrument and each automatic pressure altitude reporting system has been tested and inspected and found to comply with appendices E and F of FAR part 43. ALT: <u>671K-10</u> ALT: <u>N/A</u> Performed a FAR 91.217 data correspondence test. Signed: <u>Date:</u> Signed: <u>Date:</u> Network Disspectred in Accordance with respect to the fax holds approved for Retruer to Service with respect to the work Described and found to comply with appendices E and F of FAR part 43.

		AIRCRAFT LOG		Registration No			
	1 Bros Forv	Calkins Aero Service Inc. West Houston Airport 18000 Groeschke Rd. Houston, TX 77084 Date:8/19/2013 N8088B TACH/TTAF:2821.45 ANNUAL INSPECTION INSTALLED NEW BEARING AND RACE ON R/H WHEEL INSTALLED NEW EVAPORATOR COVER C/W AD 2013-02-13 FLIGHT CONTROLS BY VISUAL INSPECTION-DUE	Maintenance	and Remarks	Calkins Acro Service Inc. West Houston Airport 18000 Groeschke Rd. Houston, TX 77084 Date:8/20/2014 N8088B TACH/TTAF:2940.30 ANNUAL INSPECTION INSTALLED NEW ELT BATTERY INSTALLED NEW ELT BATTERY INSTALLED NEW CENTER MUFFLER P/N K67517-00 INSTALLED NEW R/H FUEL TANK INTERCONNECT HOSES INSTALLED NEW L/H & R/H BRAKE CALIFER HOSES	ature	Certificate No.
		C/W AD 78-23-01 FUEL DRAIN BY VISUAL INSPECTION DUE AGAIN BY TACH:2921.45 C/W AD 78-23-01 FUEL DRAIN BY VISUAL INSPECTION DUE AGAIN BY TACH:2921.45 C/W AD 76-07-12 R1 IGNITION SWITCH BY OPERATIONAL CHECKS-DUE AGAIN BY TACH:757.6 Drained all sumps, cleaned and repacked wheel bearings. Serviced battery, brakes, shock struts, and tires, lubricated gear fittings and controls. Tested ELT per 91.207 (d)-BATTERY EXPIRES 9/2014 I certify that this aircraft has been inspected in accordance with An annual Inspection and was determined to be in an airworthy condition. Calkins Aero Service Inc. FAA Certified Repair Station No. GK2R849K signed WO#22453			C/W AD 78-23-01 FUEL DRAIN LEVER BY VISUAL INSPECTION-D AGAIN BY TACH:3040.3 C/W AD 76-07-12 RI IGNITION SWITCH BY OPERATIONAL CHECKS-D AGAIN BY TACH:3040.3 Drained all sumps, cleaned and repacked wheel hearings. Serviced battery, brakes, shock struts, and tires, hubricated gear fittings and controls. Tested ELT per 91.207 (d)-BATTERY EXPIRES 10/2016 I certify that this alreraft has been inspected in accordance with An annual Inspection and was determined to be in an airworthy condition. Calkins Acro Service Inc. FAA Certified Definir Station No. GK2R849K signed WO#23819		
Total Ta Carry Farward				9-10-14 TAC Tested El Miccraft	Ch: 2946.30 - I restalled New Ther 91.207 (0). All Ops Che Airworthy For repurn to se		ANDENNA O.K

Aircroft Time Recorder Date Maintenance Reading Total This Date Brought 78. AUG 9 Forward ACH ACUOM REPLACE -94 PRESS SW POMP REPLACED. 456-615 DRATOR)EH CHARGEN SYSTEMA. SID OND. Window Allops dects of the 12-2-14 FAA CERTIFIED REFAIR STATION NO. OK2R8498. Total To Carry Forward

Certificate No. ature and Rema Calking Aero Service Inc. West Houston Airport 18000 Groeschke Rd. Houston, TX 77084 Date:8/27/2015 N8088B TACH/TTAF:3013.85 ANNUAL INSPECTION INSTALLED NEW L/H NAV LIGHT BULB INSTALLED ALL NEW FUEL CAP GASKETS **RELINED R/H & L/H BRAKES** INSTALLED NEW R/H TIRE TUBE INSTALLED NEW R/H FWD EXHAUST STACK P/N K38137-05 C/W SB 1242 RUDDER PEDAL TUBES BY VISUAL INSPECTION C/W AD 78-23-01 FUEL DRAIN LEVER BY VISUAL INSPECTION-DUE AGAIN BY TACH:3113.85 C/W AD 76-07-12 R1 IGNITION SWITCH BY OPERATIONAL CHECKS-DUE AGAIN BY TACH:3113.85 Drained all sumps, cleaned and repacked wheel bearings. Serviced battery, brakes, shock struts, and tires, lubricated gear fittings and controls. Tested ELT per 91.207 (d)-BATTERY EXPIRES 10/2016 I certify that this aircraft has been inspected in accordance with An annual Inspection and was determined to be in an airworthy condition. Calkins Aero Service Inc. FAA Certified Repair Station No. GK2R849K signed 2 WO#25089

Registration No.