| DATE | N319CS TA ENGINE S/N: L-142 PERFORMED A 100 HOUR AND FILTER CHANGED. (CH48110-1. REPLACED A #3 76 #4 75 #5 78 #6 7 (g) (1) (i-iii) & (g) (2) (i-iii) IN FLANGE NUTS & SUBMITTE 2015-19-07 FUEL INJECTIC OVERHAUL OR LOOSENIN I CERTIFY THIS ENGINE H. | I INSPECTION IN ACCORDANCE WITH FAR 4: COMPLIED WITH SB 480E OIL, OIL FILTER AN LL SPARK PLUGS WITH NEW P/N: RHB37E. CH7/80. REPLACED CRANKSHAFT SEAL P/N: LYACORDANCE WITH LYCOMING SB 627. DS URVEY. NEXT INSPECTION PER (g)(1) IS DID LINE INSPECTION IN ACCORDANCE WITH LYCOMING SD 627. DS LINE INSPECTION IN ACCORDANCE WITH GOF CLAMPS. AD'S CHECKED THROUGH 2: AS BEEN INSPECTED IN ACCORDANCE WITH PERTINENT DETAILS OF THE REPAIRS ARE ON | 18 FAA CRS 453.5 DATE 7/5/20 3 WITH REFERENCE TO CESSNA MAIN D SUCTION SCREEN INSPECTION. SI ECKED MAGNETO TO ENGINE TIMIN N-15628. COMPLIED WITH AD 2017- FOUND NO CRACKING OF EX. PIPE: JE AT TACH 425.8 AND (g)(2) IS DUE H LYCOMING SB 342G, NEXT INSPECTION 1017-14. | VNFR171L 17 W.O. SV5165 ITENANCE MANUAL 206HMM20. O ERVICED WITH PHILLIPS 20W50 ANI G. COMPRESSION TEST: #1 77 #2 7 11-10 EXHAUST INSPECTION, PARA S OR LEAKAGE, TORQUE CHECK O AT TACH 501.8. COMPLIED WITH AI CTION DUE BY TACH 511.8, ENGIN | 66 6. F D E |
|------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| ė. | - J . | 10 | | | _ |
| | | G. | | | |
| | | 1 P | tar 8 . | | |
| | | | 9 | | |
| , | 0 | | | | |
| | 6304 N 9/8/2017 Tach Hours: 454 | Cedar Ave Lubbock, TX 79403 N319CS Cessna T206H, S/ 6 :: Aircraft TT: 454.6 :: #1 Engine TT | 806-747-5101 Fax: 806-76 N- T20609219 | 7-8000 Engine 1 Logbook | O SIGNATURE, CATE TYPE MBER |
| | installed a new fi engine, re-install Oil sample taken C/W Slick Magne 15090317, right s | nd run. Removed cowling as required. Dra lter p/n: CH48110-1, and serviced engine ed cowling, ground run ops and leak che paper work filled out and mailed to lab. eto 500 hour overhaul. Removed magnet s/n: 15090328 and installed left s/n: 1603 check normal. -10 (6-28-2017) 25 hour Exhaust system | ained oil, removed filter, inspected with 10 quarts Phillips XC 20w-5 ck ok. os, p/n: 66LC35SDNP, model: 63 1023 and right s/n: 17060221. Ra | 50 oil. Washed | |
| | | Signed | Chad R. Burns AP2829180 | | |
| Date: Dec Make: Lyc Performed removed fii AA48110-2 - 50 oil. Was leak check | edar Ave., Lubbock, T 18, 2017 N#: 319CS coming Model: TIO- ground run. Removed Iter, inspected filter mo 2, and serviced engine shed engine, re-installa- ok. | TX 79403 Tach & Engine TT time: 590.0 540-AJ1A S/N: L-14227-61E d cowling as required. Drained oil, edia, installed a new filter p/n: with 11 quarts Phillips X/C 20W- ed cowling, ground run ops and ed out and mailed to Aviation | | | |