

DATE



# VAN BORTEL AIRCRAFT INC™

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

**N319CS TACH & TOTAL 1118.0 H.M. 1233.9 DATE 2/17/2020 W.O. SV6085**

AIRCRAFT S/N: T20609219 ENGINE S/N: L-14227-61E PROPELLER S/N: 150866  
 PERFORMED AN ANNUAL INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 206HMM20. COMPLETED THE ONE YEAR ESSENTIAL & CROSS FEED DIODE TEST (246101), STANDBY BATTERY CAPACITY TEST & RECHARGE (243005) & AMSAFE RESTRAINTS DIAGNOSTIC TEST (351102). COMPLETED THE TWO YEAR ACU OVERVOLT TEST (346003). COMPLETED ICA INSPECTIONS FOR AEROCET CARGO POD, KNOTS2U FLAP GAP SEALS, KELLY A/C SYSTEM, MICRO VG's & FLINT WINGTIPS. ELT INSPECTED & TESTED ELT PER FAR 91.207(d). ELT BATTERY EXPIRES 8/2021. CLEANED AND GREASED ALL WHEEL BEARINGS. REPLACED RIGHT BRAKE CALIPER PISTON ORINGS P/N: MS28775-222 AND SERVICED BRAKE SYSTEM. REPLACED VACUUM REGULATOR FILTER P/N: B3-5-1. INSPECTED VACUUM PUMP PER TEMPEST SB-008 AND FOUND VANE WEAR EXCESSIVE. REMOVED PUMP P/N: AA3225CC S/N: 09W924 AND INSTALLED NEW PUMP P/N: AA3225CC S/N: OBE620. REMOVED ALTERNATOR P/N: ASG12000-3R-PMA S/N: H-R080757 AND INSTALLED OVERHAULED ALTERNATOR P/N: ASG12000-3R-PMA S/N: H-T110385. REPLACED UPPER PEDESTAL LIGHT BULB P/N: 1829. REPLACED INDUCTION AIR FILTER WITH NEW P/N: P197268, NEXT FILTER REPLACEMENT PER **AD 84-26-02** IS DUE AT TOTAL TIME 1618.0. COMPLIED WITH SEL-21-03 KELLT AIR CONDITIONER CONTROLLER COVER BY INSTALLING COVER P/N: AC-01995 IN ACCORDANCE WITH KELLY DOCUMENT NC-19-009. SEL-74-06 SLICK MAGNETO INSPECTION DOES NOT APPLY BY S/N'S OF MAGNETOS. SEL-61-01 PROPELLER GOVERNOR INSPECTION DOES NOT APPLY BY GOVERNOR S/N: 150520. AD'S CHECKED THROUGH 2020-04.

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

  
PAUL PARK, CHIEF INSPECTOR

 SIGNATURE,  
 TYPE  
 ER

## LUBBOCK AERO

6304 N. Cedar Ave., Lubbock, TX 79403 806-747-5101  
 Date: July 24, 2019 N#: 319CS Tach: 1071.2 Hobbs: 1184.0  
 Make: Cessna Model: T206H S/N: T20609219  
 Replaced main aircraft battery with Gill, p/n: G-242, s/n: G03024901.  
 Serviced with acid and top charged.  
 Resealed left brake caliper, bled brakes and replaced master  
 cylinder vented cap.  
 Replaced right brake linings.

  
Anthony Cruse 3539124 A&P

DATE



# VAN BORTEL AIRCRAFT INC™

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

**N319CS TACH & TOTAL 1395.5 H.M. 1531.4 DATE 4/19/2021 W.O. SV10042**

AIRCRAFT S/N: T20609219 ENGINE S/N: L-14227-61E PROPELLER S/N: 150866  
 PERFORMED AN ANNUAL INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 206HMM21. COMPLETED THE ONE YEAR ESSENTIAL & CROSS FEED DIODE TEST (246101), STANDBY BATTERY CAPACITY TEST & RECHARGE (243005) & AMSAFE RESTRAINTS DIAGNOSTIC TEST (251102). COMPLETED ICA INSPECTIONS FOR FLINT WING TIPS, KELLY A/C SYSTEM, MICRO VG's, AEROCET CARGO POD & KNOTS2U FLAP GAP SEALS. REPLACED ELT BATTERY P/N: 455-0012 S/N: 390559-010, EXPIRATION DATE 6/2028. ELT INSPECTED & TESTED ELT PER FAR 91.207(d). CLEANED & GREASED ALL WHEEL BEARINGS. REPLACED INDUCTION AIR FILTER WITH NEW P/N: P197268, NEXT FILTER REPLACEMENT PER **AD 84-26-02** IS DUE AT TOTAL TIME 1895.5. REPLACED VACUUM CENTRAL FILTER P/N: AAD9-18-1 & REGULATOR FILTER P/N: B3-5-1. REPLACED ALTERNATOR WITH OVERHAULED P/N: 9910592-3RX S/N: H-T110388. REPLACED ALTERNATOR BELT WITH NEW P/N: 435K4-E. SERVICED, CHARGED & INSTALLED NEW AIRCRAFT BATTERY P/N: G-242 S/N: G03111611. REMOVED LEFT & RIGHT STROBE LIGHT POWER SUPPLIES & FLASH TUBES. INSTALLED NEW PMA LED STROBE LIGHT FLASHER UNITS P/N: 01-077198-17 & LIGHT HEAD ASSEMBLIES P/N: 01-0771987-00, WEIGHT CHANGE NEGLIGIBLE. REMOVED OXYGEN BOTTLE P/N: 804882-34 S/N: 33931 & SENT TO DFW FIRE EQUIPMENT DALLAS TX. (DOT TEST FACILITY) FOR HYDROTEST. REINSTALLED BOTTLE AND SERVICED SYSTEM. INSTALLED REIFF ENGINE PREHEAT SYSTEM MODEL: TXPL6. WEIGHT & BALANCE REVISED. REPLACED #2 & #4 EGT PROBES P/N: 86317. REPLACED ENGINE SIDE BAFFLE PLUGS P/N: CM2692-48J1S. SEL-61-01 (**AD 2020-19-06**) PROPELLER GOVERNOR IDLER GEAR BEARING INSPECTION DOES NOT APPLY BY GOV. S/N: 150520 & AFFECTED PART HAS NOT BEEN INSTALLED. AD'S CHECKED THROUGH 2021-09.

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

  
PAUL PARK, CHIEF INSPECTOR

 SIGNATURE,  
 TYPE