

DATE

Reassembled aircraft: Reinstalled horizontal stabilizer and vertical fin. Reinstalled rudder and LH & RH elevators. Rigged elevator trim system. Performed operational check to flight control systems. Reinstalled aft tailcone systems. Reinstalled aft baggage interior.

SIGNATURE,  
DATE TYPE  
NUMBER

This aircraft was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Except as stated above, no other work, inspection, corrective action or determination of airworthiness has been completed at this time, limited to work performed.

Pertinent details on file at Beegles Aircraft Service LLC, Greeley, CO.  
Work Order # 13,297 CRS# BX4R092M

Signed



Date

6/23/23

Tach

1640.1

N

31965

Performed operational flight in accordance with FAR 91.407 Paragraph (b).

Signed



DATE



SIGNATURE,  
DATE TYPE  
NUMBER

635 AIRPORT ROAD • WELD COUNTY AIRPORT • GREELEY, COLORADO 80631

08-25-2023 Tach 1507.40 AFTT 1507.40 N319CS sn T20609219

Repaired airplane: Adjusted aft cargo door. Replaced LH & RH stabilizer tips pn (2) GF1232012-1. Replaced LH & RH elevator tips pn's K1234640-1 and K1234640-2. Performed static balance check after painting. Replaced LH & RH lower strut cuffs pn's SA-1227010-1 and SA-1227010-2. Painting: Painted RH rear window trim. Painted LH & RH lower strut cuffs, stabilizer, and elevator tips to match.

This aircraft was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Except as stated above, no other work, inspection, corrective action or determination of airworthiness has been completed at this time, limited to work performed.

Pertinent details on file at Beegles Aircraft Service LLC, Greeley, CO.  
Work Order # 13,297 CRS# BX4R092M

Signed

