

mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MTE - 1198
Juni 2005

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Sept 2006	00:00	-	Manufactured	<i>[Signature]</i>

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12.

MAINTENANCE & SERVICE HISTORY

Air Associates of Kansas

7-24-2007 N699CT

Note: this propeller installed on Cessna N699CT S/N 21062554 on 7-19-2007 with a Tach time of 2511.00 and ACTT of 3931.6. By Roy Fellows A&P IA 275643582 working for Flight Resource, LLC of Benton Kansas. The next overhaul (1800hr/72 months) is required by ACTT 5731.6 or (current Tach 4311.0) or 7-2012 WCF per MT-Propeller Service Bulletin 1A.D.

Steve Mooney 489507862A&P *[Signature]*

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12.

MAINTENANCE &

Air Associates of Kansas

1-24-2008, Tach: 2568.3 TT: 57.3

Inspected propeller in accordance with FAR 43, appendix D, C/W AD 2006-05-05 and AD 2007-26-13 by visually inspecting propeller blade for damaged or defective sheath. No defects noted at this time. Next due Tach: 2668.3 or 1-2009. I certify that this propeller has been inspected in accordance with an 100HR inspection and was determined to be in airworthy condition.

Evan M Sustarich
Evan M Sustarich 574880658 IA

25 Feb 2010 N699CT TACH 2896.5 TTPROP 385.5
Perform Annual Inspection IAW Cessna Service Manual.
No defects noted in prop hub or prop blades. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Freddie W. McCall, Jr.
Freddie W. McCall, Jr. A&P 2735421 IA

4 Feb 09 N699CT TACH 2724.2 TT 213.2
Inspected prop IAW FAR 43 Appendix D, C/W AD 2006-05-05 and AD 2007-26-13 by visual inspection of propeller blades. No defects were detected. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Freddie W. McCall, Jr.
Freddie W. McCall, Jr. A&P 2735421 IA

1
Perform annual inspection in accordance with Cessna Service Manual. All ADs current thru 2011-02. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Freddie W. McCall, Jr.
Freddie W. McCall, Jr. A&P 2735421 IA

SERVICE HISTORY

Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers

3-14-12	N699CT	TACH 3085.0			
PMA and governor removed for overhaul					
<i>Freddie W. McCall, Jr.</i>					
A&P 2735421 IA					

August 28, 2012. HUB: MTV-9-D. SN: 06948. TT: 3085.0.
TSO: 0.00. Overhauled propeller, painted and statically balanced in accordance with MT-Propeller Manual: E-220. All other current service information and Airworthiness Directives complied with as of this date. An Airworthiness Directive may apply to the installation of the propeller described hereon. The installer is responsible for ensuring complete compliance with any applicable installation Airworthiness Directive.


Maintenance Release (Complete Overhaul)
The aircraft (propeller, or appliance identified above was overhauled and inspected in accordance with Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order Number 12-7653.

Signed: *Freddie W. McCall, Jr.* for AIR PROP SPECIALISTS,
INC. Certificate Number 1X4R274M, 3671 Industrial Park Drive,
Marianna, FL 32446

NOTE: Enter Compliance With All Applicable FAA A


22OCT12 N699CT TACH 3085.0 TTSNEW 574
TSPOH 00.0

Install Overhauled Propeller on N699CT in accordance with Cessna Service Manual. Return propeller to normal service.


Freddie W. McCall, Jr. A&P 2735421 IA


22OCT12 N699CT TACH 3085.0 TSNEW 574
TSPOH 00.0

Perform annual inspection in accordance with Cessna Service Manual. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.


Freddie W. McCall, Jr. A&P 2735421 IA

22Nov13 N699CT TACH 4576.23 TSNEW 645.53
TSPOH 71.53

Perform annual inspection in accordance with Cessna Service Manual. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.


Freddie W. McCall, Jr. A&P 2735421 IA

22Nov13 N699CT TACH 4576.23 TSNEW 645.53
TSPOH 71.53

Perform annual inspection in accordance with Cessna Service Manual. All ADs current thru 2014-10B. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.


Freddie W. McCall, Jr. A&P 2735421 IA

