



#### PROPELLER MAINTENANCE RECORD Hub Model 3A32 C76-5-MR Blade Design <u>582NB-2</u> Diameter <u>80"</u> Blade Ser. Nos.\_\_\_\_ No. 1 \_ K 63733Y5 No. 2 K 6389045 No. 3 K 6385345 PITCH RANGE High \_\_ 29.6 Low \_\_ 13.3



Tri-County Propellers Inc. Work Order #11165 Date 12/30/91 Propeller [X] Governor [ ] Model No 3A32C76-S-M/582NB-2 Serial No. 761236 Overhauled [X] Repaired [ ] Repitch [ ] Blade Replacement [ ] Resealed [ ] Service Manual No. 720415 Service Letters Thru 1991-2 Service Bulletins Thru 150 AD's None currently apply. Re-Occuring [ ] Next Overhaul Due (hours) 1500 Date 12-30-96 Remarks: Overhauled propeller per McCauley service manual 720415. IBO is 1500 hours or 5 years, whichever occurs first. Repair Station # FRGR545N Cert No. PR2349185	DATE TACH		SIGNATURE
Serial No. 761236 Overhauled [X] Repaired [] Repitch []  Blade Replacement [] Resealed [] Service Manual No. 720415  Service Letters Thru 1991-2  Service Bulletins Thru 150  AD's None currently apply. Re-Occuring []  Next Overhaul Due (hours) 1500 Date 12-30-96  Remarks: Overhauled propeller per McCauley service manual 720415.  IBO is 1500 hours or 5 years, whichever occurs first.  Repair Station # FRGR545N Cert No. PR2349185			
Repair Station # FR6R545N Cert No. PR2349185 5, 1992 This froge for entally on N 37539		Serial No. 761236 Overhauled [X] Repaired E Blade Replacement [ ] Resealed [ ] Service Manual Service Letters Thru 1991-2 Service Bulletins Thru 150 AD's None currently apply. Next Overhaul Due (hours) 1500	82NB-2  1 Repitch [ ]  No. 720415  Re-Occuring [ ]
	5,1992	Repair Station # FRER545N Cert No. PR2349185	



The state of the s				
ATURE	DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		8-08-01	NIA PU MOD	
	4-3600-	12-13-17	N/A MOD	
	(A)	83-13-06	N/4 MO	
	- Inshe	95-24-05	RT NIA MOD	
	_ (4)114			
<u></u>				
5				
9				
		•		
				STATE OF THE PARTY



SLADE DWG. NO.	DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIV SERVICE BULLETINS, SERVICE LETTERS & MINOR ADJUSTMENTS	ES,	
TACH TIME	DESCRIPTION OF WORK	SIGNATURE	_
I.	(18 Jul 32 / 4)	A STATIONE	2/24/99
1/h	PROPELLERS/N 76/236 HAS	BEEN OVERHAULED	2/24/99
1 /00 N	MANUAL NO. 720415	THE FOLLOWING	
002 1/8	ADDITIONAL SERVICE INFORMATION HAS BEEN	ACCOMPLISHED:	
N	HUB MODIFIED TO OIL FILLED	CONFIGURATION	
	JANW S.L. NO. 1992-7.	Constitution and the Constitution of the Const	
	PERTINENT DETAILS ON FILE UNDER W.O.	4042	
	JORDAN PROPELLER SERVICE IN	C. CRS#EK2R797K	
	SIGNED Sang Gord	an	
Fel	MECHANIC MAKING INSTALLATION MUST	CANTAR 43.9.	
			-



DATE	TACH TIME	DESCRIPTION OF WORK		SIGNATUR	E
2/24/99	4601,40	installed grop on Beech V-3	5	N. Fedel	44.5
		N37538, SIN D-8393 IN		1449	
- 422-42		accordance with beech bonanza	Series		
		Maintenance Manaal-			
		Paht Call A+P 1798	666 1 A	15156	20-15
		STETSON Aviation INC.			1
		PANALLE			,
		19.32/c			
		W. S.			



DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
10-2-02	5054.4	NO AD'S Arthis time - looke inspection	SIGNATURE  Republication STA
10-21-3	5114.1	Blodes LROSSES - No dy hertspites	167 She 191 Vally 8+1
		LOOKE INSO Camp Paul determinent	Jun / Bulen 14 1554636
-21-05	5156.47	to be in an AIRE ORTHY LAND THOR	
		HAS BEEN INSPECTED IN ACCORDANCE	
5.0		WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	
Konneth		TACH TIME 5156 47	1
602-55	unichance	1. Sekur 263080161A	
002 00	3 3043	SIGNATURE AMP NUMBER	



2006 DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
2-7-06	5192.86	Picture Pictur	614-18 8197.69
<u> </u>		I CERTIFY THAT THIS AIRCRAFT, BOOKS	
		HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND	
		WAS DETERMINED TO BE IN AIRWORTHY CONDITION:	1 3625 1235 138
		TACH TIME 5192 06	tu by
	5	100H TOTAL THE 591.46 DATE 2-7-06	
		SIGNATURE ASPINATOR	Pool.
2007		2002.20	9-09 5,214 20
1-2-07	5197.42	I CERTIFY THAT THIS AIRCRAFT, CORPANCE	
		HAS BEEN INSPECTED INSPECTION AND	
	83	WAS DETERMINED TO BE IN AIRWORTHY	
	QT.	CONDITION 5197.42	
	SMO	H TOTAL TIME 596.02 DATE 1-2-07  X. Jelant 26308016 IA	
		X Secut 2630301617	



2008							1000	20
DATE	TACH TIME		DESCRIPTION OF	WORK		SIGNATU	RE	DA
1-14-08	5/97.69		CERTIFY THAT THIS AS BEEN INSPECTE	U IM WELLING HINDAR		8.1918	30-65	2-15
-	aintenance	a A	MAS DETERMINED TO	BE IN AIRWORTH	0			
602-5	58-53 <b>45</b>	T	OTAL TIME 596.2	9 DATE 1-15	-08			
		w	SIGNATURE	26308016 ARP NUMBER	IA			20
2009		ext)		LAT THIS AIRCRA	PROPE	ler		3-2
2-9-09	5214.20		LIAC DEEM H	urperted in ac	COKDANCE		2007	
Ke	nneth F.	ekut	WIHA AN WAS DETER COMBITION	MINED TO BE IN	ALTO CAPALA	F. 1613	10-2-07	
Airci	raft Mainte	nance	TACH TACH TIME	5214,2 612.80 DA	2-9-0	99		
6	102-558-5	143	X-Je	ent 20	308016 P NUMBER	IA		_
- 1		erra	SIGNAT	UKE	. HC	11/2		



2010	TACH		2100
DATE	TIME	DESCRIPTION OF WORK	SIGNATURE
- 2-15-10	5226.67	I CERTIFY THAT THIS AIRCRAFT, DEGR	
		HAS BEEN INSPECTED IN ACCORDANCE	and good cooper & with
-		WILH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY	Kennem F. lekut
		CONDITION.	Aircraft Maintenance
		TACH TIME 5226.67	POO EEO EQAE
	SMO	628 23 7-16 10	<del>007-500-20-8</del>
-		1 1 Later 26308016JA	
2011		SIGNATURE A&P NAMBER	
3-21-11	5238.70	PROR	llez
		HAS BEEN INSPECTED IN ACCORDANCE	
		WIMA ANNUAL INSPECTION AN	
		WAS DETERMINED TO BE IN AIRWORTH	iv
		CONDITION.	
		TACH TIME 5238.70	
		SMOH TOTAL TIME 637,30 DATE 3-21	
		K-Labert 263080	A LOI
		SIGNATURE ASPIRANCE	



DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-1-12	5242,60	CERTIFY THAT THIS AIRCRAFT CHOICE	16-10 SOOL 676
		WITH A ANNUAL INSPECTION AND	Kenneth F. Telar
		WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	Aircraft Maintenance
		TACH TIME 5242,60	602-558-5345
	SMOH	TOTAL TIME 641.20 DATE 4-1-12	HOM S
		SIGNATURE AMP NUMBER	

Date 21August2013 N3753Q 1967 Beech V-35 Airframe Serial # D-8393 Tach and Total Time 5261.9 Propeller: McCauley Model 3A32C76-S-MR Serial # 761236 Propeller Time Since Overhaul 660.5 See Airworthiness Directive lists for complete AD compliance information.---END---

I certify this propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition.

Bradley R. Power A&P3407465IA



# DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS TACH DESCRIPTION OF WORK SIGNATURE DATE 5277.8 irworthy



DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
9/1/17	5280	Inspect Prop + f	lound .
		Enery of the Box	200789737 I.A.
9/2/18	5280,2	I CERTIFY THAT I	HAVE INSPECIEL
		AIRWORTHY AT This	TITO DE
/ 2.01		A/P 300387737I	
1-7-21	528 <b>5.9</b>	Inspected propeller Tayou	Defects noted.
		Fuproil & Callet 39	82337 AUSTA.

