



The Standard

ENGINE LOG

ASA-SE-2

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

VALLEY AIRCRAFT SERVICES

615 AIRPORT ROAD

SUITE 107

WINCHESTER, VA 22602

DATE:10/14/22 N# 1833D MODEL: IO-520-BB S/N: 274580-R TT: 1623.85 TSMOH: 0.0

ENGINE WAS DISASSEMBLED, CLEANED, AND INSPECTED AT THIS TIME. ALL PARTS WERE EITHER MAGNAFLUXED, ZYGLOED, OR VISUALLY INSPECTED AND MEASURED FOR SPECIFICATIONS. ASSEMBLED ENGINE WITH REPAIRED CASE P/N C/N655434/5 S/N M/NR04HA571 FROM CRANKCASE SERVICES, INC. INSTALLED NEW MAIN BEARINGS P/N SA646592-A1, NEW CONNECTING ROD BEARINGS P/N SA642398. INSTALLED CAMSHAFT P/N 629726-AB. INSTALLED (6) HYDRAULIC UNITS P/N SA646277 AND (6) HYDRAULIC UNITS P/N SA626488. INSTALLED NEW CYLINDER KITS P/N SA52006-A20P AND TORQUED. INSTALLED NEW SLICK MAGNETO P/N ES6310 S/N K-K09053 AND P/N ES6310 S/N K-K10012 WITH NEW HARNESS P/N KA12381. INSTALLED OVERHAULED STARTER ADAPTER P/N 642087-A68 S/N QAA86609 FROM QUALITY AIRCRAFT ACCESSORIES, INC. INSTALLED OVERHAULED FUEL PUMP P/N FT-B8.5/1-632818-11 S/N K178820BR FROM GREAT PLANES FUEL METERING, INC. ENGINE WAS ASSEMBLED WITH NEW GASKETS AND SEALS WITH GASKET SET P/N SA632429-A3. ALL WORK PERFORMED IN REFERENCE TO MANUFACTURERS MAINTENANCE MANUAL.

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED WAS REPAIRED AND / OR INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED.


THOMAS SCHWIETZ A&P 2677708

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	---


February 7, 2023 N1833D Continental IO-520-BB – SN: 274580-R-TT

Tach: 3149.85 TTSN: 1623.85 TSMOH: 0.00

1. Performed **100 Hour Inspection** IAW Scope and Detail of FAR 43 Appendix D.
2. Inspected all accessories and hardware for security and serviceability.
3. Adjusted idle and mixture settings as needed for correct fuel flow.
4. Adjusted for proper manifold pressure.
5. Post maintenance turn performed satisfactory with no leaks noted at this time.

Aero Services of Winchester, Inc.
615 Airport Road Suite 107
Winchester, VA 22602
540-665-0193

I certify that this ENGINE has been
inspected in accordance with a 100 Hour
inspection and determined to be in
airworthy condition.


Charlie Schoenduby A&P 3152411 IA

using JetGlo Express Matterhorn White CM0840103. Secondary color painted with PPG Red 708970. Stripe painted with PPG Tan 208260. Replaced hardware as needed. Performed ops check of flight controls and all lighting, in working condition. All work done IAW Beechcraft maintenance manual. Return to Service. **END.**

Mechanic: Bryce Jordan Gray

Certificate #: A&P 3720939

Signature: Bryce J Gray

July 4, 2023 N1833D Beech F33A S/N: CE-952 Continental IO-520-BB – SN: 274580-R-TT
Tach: 3155.8

1. Performed Mid Cycle oil service.
2. Changed oil and oil filter CH48109-1 and added 12 quarts Phillips 20w50x/c oil.
3. Post maintenance turn performed satisfactorily.

Aero Services of Winchester, Inc.
615 Airport Road Suite 107
Winchester, VA 22602
540-665-0193

Levi Jordan
Levi Jordan A&P 4044180