		TOTAL
PA	GE	NUMBER

	TOTAL	TAGE							
	TIME	TACH OR RECORDING	DESCRIPTION OF WORK PERFORMED						
DATE	IN SERVICE	METER TIME	SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK						
_	CHANDLER AIR SERVICE 1675 E RYAN RD								
3/6/2012	N5757D	MODEL: 35-	CHANDLER, AZ 85286  -C33 SN: CD-1092 TACH: 411.0						
		N GILL G-35, SN	G02534691, REMOVED FOR NOT MAINTAINING CHARGE. 5, SN G02694463, INSTALLED.						
OI LIWITION.	E OFFECTION CON	MPLETED.							
MAINTENANO	ECIFIC TO THIS	S AIRCRAFT INC	CE WITH BEECHCRAFT MAINTENANCE MANUAL. ADDITIONAL MAINTENANCE CLUDING PERSONS COMPLETING MAINTENANCE, ARE FILED IN AIRCRAFT STENANCE OFFICE UNDER SHOP ORDER 12-2327.						
MATHEW Mer	KENY, A&P 2797	711							
		- T-1 - 1-7	CHANDLER AIR SERVICE 1675 E. RYAN RD. CHANDLER, AZ 85286						
3/15/2012	N5757D	MODEL: 35-	C33 SN: CD-1092 TACH: 412.0						
TIGHTENED LO	DOSE SCREW	N TAILCONE FA	IRING & VERIFIED TIGHTNESS OF REMAINING SCREWS.						
NEW FLAP BU	BIN ENTRY STE MPER STOPS	PN 4088 INCTAL	RE-IINSTALLED STEP AFTER WELD REPAIR, PRIMING & PAINT. LED FOR LEFT & RIGHT FLAPS. ADJUSTED RIGGING PER SERVICE MANUAL.						
CLEANED & LU	JBRICATED AL	TERNATE AIR C	ONTROL CABLE & LEVER ASSEMBLY.						
OPERATIONAL	CHECKS COM	DIETED							
MAINTENANC	E RECORDS SE	IN ACCORDANC	E WITH BEECHCRAFT & OTHER APPLICABLE MAINTENANCE MANUALS. ADDITIONAL AIRCRAFT, INCLUDING PERSONS COMPLETING MAINTENANCE, ARE FILED IN						
AIRCRAFT MA	INTENANCE FI	LES LOCATED IN	I CAS MAINTENANCE OFFICE UNDER SHOP ORDER 12-2327.						
Math	& MEX	S							
MATHEW McK	ENY, A&P 2797	711							
	-								
3/20/2012		412.0	INSTALLED NEW LANDING GRAZ ENGRALENCY HAND CLAME						
7 / 7			COUEL. hyble 4+P 3628383						
4-27-12		421.6	RESEALED BOTH FUEL CARS. PANTER MEKING						
12/12		7	ARP 279771)						
			CHANDLER AIR SERVICE  1875 E. RYAN RD.  CHANDLER, AZ. 85286						
6/6/2012	N5757D	MODEL: 35-	-C33 SN: CD-1092 TACH: 423.4 AFTT: 6099.9						
HARTZELL	r000	MODEL: PHC-L	_3YF-1RF/F8468A-6R SN: FD415B PTSOH: 0000.0 PTT: 1365.1 834 BLADE # 3: J75832						
PROPELLER I	NSTALLED AFT ATIONAL CHEC	ER OVERHAUL CKS COMPLETED	BY WARNER PROPELLER, WO# 8642. D.						
MAINTENANC ADDITIONAL I FILED IN AIRC	E COMPLETED MAINTENANCE CRAFT MAINTEI	IN ACCORDANC	DE WITH BEECHCRAFT, CONTINENTAL, OTHER APPLICABLE MAINTENANCE MANUALS.  CIFIC TO THIS AIRCRAFT, INCLUDING PERSONS COMPLETING MAINTENANCE, ARE  ICATED IN CAS MAINTENANCE OFFICE UNDER SHOP ORDER 12-2401.						
Lywis									
RICKY WILL,	&P 3028383								
7-27-17	_	1432	REPAIRED RITATING BECCON. REV. Lacod 1 BUR						
, ~, ,	,		#70798-12. LUDA Gear MOTOR						
			GK For when Return to farvice  4 Daul Hupon A+P 565623722						
			L Daul Hupon A+A 565823722						

DESCRIPTION OF WORK PERFORMED TACH OR TOTAL RECORDING TIME SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK METER IN TIME DATE SERVICE TNSTALL NEW TOW PIN. 447,5 9-24-12 SEENCEABLE 14155 COVER NAV, SN 27606, REPARED BY 9/15/2012 448.1 AVIONILY OF LINTEAU AZ, WO SU INSTAURS. OPERATIONAL loguited A+P 3028387 CHECK COMPLETED, 9/25/2012 448.1 EGT INDICATOR IN OFERTIVE. GRUGE PLACALDED BER FAF 9/1405 (C+A) PLALALO DUE INSPECTION & NETT 100 HR / ANNUAL Ry Wing AVP 3028383 INGAGENON. 499.7 1-7-13 INSTALL NEW TUBE AND TIRE 5.00X5 ON NOSEWHEEL, NEW BEARING AND RACE ON STEM SIDE, REPACK BEARINGS. 1-4-13 499.7 Landing LIGHT INOR OH For 1= LIGHT FROM Horgen 8+ P585-129726

> CHANDLER AIR SERVICE 1675 E. RYAN RD. CHANDLER, AZ 85286

N5757D MODEL: 35-C33 SN: CD-1092 1/11/2013 TACH: AD 89-05-02, ELEVATOR CONTROL FITTINGS, INSPECTED PER Beech Service Bulletin No. 2242, Revision 1. 500.2 AFTT: 6176.7 AD 93-24-03, RUDDER SPAR CRACKS, INSPECTED PER Beech Service Bulletin No. 2333, Revision 1. AD 95-04-03, SPAR FRAME STRUCTURE, INSPECTED PER Beech Service Bulletin No. 2360.

AD 2007-08-08, LANDING GEAR UPLOCK ROLLERS, INSPECTED & LUBED PER Beech Service Instruction No. 0448-211, Rev. I. NEW BULB, 4313, INSTALLED IN LANDING LIGHT ASSEMBLY. OPERATIONAL CHECKS COMPLETED.

MAINTENANCE COMPLETED IN ACCORDANCE WITH BEECHCRAFT & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE ADS CHECKED THROUGH ATP REVISION DATED 1/9/2013. ADDITIONAL MAINTENANCE RECORDS SPECIFIC TO THIS AIRCRAFT, INCLUDING PERSONS COMPLETING MAINTENANCE, ARE FILED IN AIRCRAFT MAINTENANCE FILES LOCATED IN CAS MAINTENANGE OFFICE UNDER SHOP ORDER 13-2732.

LYNDEL P. HARPER, A&P 565623722

SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK

DATE

IN

SERVICE

CHANDLER AIR SERVICE 1675 F RYAN RD CHANDLER, AZ 85286

1/25/2013 N5757D MODEL: 35-C33 SN: CD-1092 NEW BATTERY, 2020-0, INSTALLED IN ELT ASSEMBLY. TACH: 507.2 AFTT: 6183.7

FAR 91.207(d) COMPLIED WITH BY VISUAL & OPERATIONAL INSPECTION OF ELT & BATTERY. ELT BATTERY EXPIRES 1/2015

NEW FILTER, RA-B3-5-1, INSTALLED ON VACUUM REGULATOR ASSEMBLY.

METER

TIME

NEW FILTER, RA-D9-18-1, INSTALLED ON INSTRUMENT AIR INLET ASSEMBLY.

NEW FILTER, BA-7112, INSTALLED IN AIR INDUCTION ASSEMBLY.

NEW BOLTS, AN24-32A, INSTALLED IN INBOARD ATTACH POINTS, LEFT & RIGHT FORWARD SEATS.

NEW O-RINGS, MS28775-222, INSTALLED IN LEFT & RIGHT BRAKE CALIPER ASSEMBLIES.

NEW LININGS, RA66-105, INSTALLED ON LEFT & RIGHT BRAKE CALIPER ASSEMBLIES.

NEW BRAKE DISCS, RA164-02504, INSTALLED ON LEFT & RIGHT WHEEL ASSEMBLIES. NEW GASKET, 35-921181, INSTALLED IN FUEL STRAINER ASSEMBLY.

MINOR SURFACE CORROSION REMOVED FROM BATTERY BOX. BOX PRIMED & PAINTED.

NEW OIL TEMPERATURE PROBE, 1512926, AND GASKET, AN900-10, INSTALLED. LEAK & OPERATIONAL CHECKS COMPLETED

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AN AIRWORTHY CONDITION. INSPECTION COMPLETED PER CHANDLER AIR SERVICE (CAS) INSPECTION CHECKLIST.

MAINTENANCE COMPLETED IN ACCORDANCE WITH BEECHCRAFT & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE ADS CHECKED THROUGH ATP REVISION DATED 1/23/2013. ADDITIONAL MAINTENANCE RECORDS SPECIFIC TO THIS AIRCRAFT, INCLUDING PERSONS COMPLETING MAINTENANCE, ARE FILED IN AIRCRAFT MAINTENANCE FILES LOCATED IN CAS

MAINTENANCE OFFICE UNDER SHOP ORDER 13-2749.

Ry Will

RICKY WILL, A&P 3028383 IA

7/3/13	585.2	nomoveD VAC PUMP P/N 216 CW, 5/H 1/AD 5792;
. ,		INSTALLED HOW VAC PUMP Ply 212Cov, 5/N 153551; CHE
		VAC & INGT. PICTER; OPS. CHECK COMPLETED:
		EDWARD MAGBITATING ASP 204/566

CHANDLER AIR SERVICE CHANDLER, AZ 85286

N5757D MODEL: 35-C33 SN: CD-1092 TACH: 601.7 AFTT: 6278.2 8/22/2013 FAR 91.207(d) COMPLIED WITH BY VISUAL & OPERATIONAL INSPECTION OF ELT & BATTERY. ELT BATTERY EXPIRES 1/2015

AD 89-05-02, ELEVATOR CONTROL FITTINGS, INSPECTED PER Beech Service Bulletin No. 2242, Revision 1.

AD 2007-08-08, LANDING GEAR UPLOCK ROLLERS, INSPECTED & LUBED PER Beech Service Instruction No. 0448-211, Rev. I. NEW FILTER, RA-B3-5-1, INSTALLED ON VACUUM REGULATOR ASSEMBLY

NEW TIRES, MICHELIN 072-314-0, LEFT, SN 3067S00073, & RIGHT, SN 3061S00080, INSTALLED ON MAIN WHEEL ASSEMBLIES

NEW GREASE FITTINGS (2), 3016, INSTALLED ON NOSE GEAR SCISSOR LINK ASSEMBLY

NEW GREASE F11 HINGS (2), RN35-825152, SPRING, RN100943ZE316G, ROD, RN35-825148, O-RINGS, MS28775-006, -012, & -115.

INSTALLED IN SHIMMY DAMPENER ASSEMBLY. DAMPENER SERVICED WITH MIL-H-5606

NEW SEALS, MS29513-339, INSTALLED ON LEFT & RIGHT FUEL TANK CAPS

NEW GASKET, 35-921181, INSTALLED IN FUEL STRAINER ASSEMBLY

NEW MUFFLER, K701-05, INSTALLED ON RIGHT EXHAUST ASSEMBLY

MINOR SHEET METAL REPAIRS COMPLETED TO RIGHT EXHAUST HANGAR BRACKET & CABIN HEAT SHUT-OFF VALVE HOUSING MINOR SHEET METAL REPAIRS SOME THE HOUSIN MINOR SURFACE CORROSION REMOVED FROM BATTERY BOX & LID. BOX & LID PRIMED & PAINTED WITH ACID PROOF PAINT MINOR FIBERGLASS REPAIR COMPLETED TO VERTICAL STABILATOR AIR SCOOP DRAIN FITTING

NEW CLAMP, QS200-44H INSTALLED ON SCOOP DUCT

NEW ANTI-SKID PAINT APPLIED TO WINGWALK AREA

PROPELLER GOVERNOR CONTROL CABLE, RE-POSITIONED UNDER INSTRUMENT PANEL TO PREVENT CHAFING #2 NAV INDICATOR MODEL KI208, SN 17816, REMOVED FOR REPAIR. RE-INSTALLED AFTER REPAIR BY FLITE INSTRUMENTS.

LEAK & OPERATIONAL CHECKS COMPLETED.

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AN AIRWORTHY CONDITION. INSPECTION COMPLETED PER CHANDLER AIR SERVICE (CAS) INSPECTION CHECKLIST. AN AIRWORTHY CONDITION. ING. EACH DATED STORY AND TONAL MAINTENANCE MAINTENANCE MANUALS. APPLICABLE MAINTENANCE COMPLETED IN ACCOUNTS APPLICABLE ADS CHECKED THROUGH ATP REVISION DATED 8/20/2013. ADDITIONAL MAINTENANCE RECORDS SPECIFIC TO THIS AIRCRAFT, ADS CHECKED THROUGH AT MAINTENANCE OFFICE UNDER SHOP ORDER 13-3039.

4 Will RICKY WILL, A&P 3028383 IA

N5757D AIRFRAME MAINTENANCE RECORD MODEL: 35-C33

SN: CD-1092

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK  INSTRUCTO NEW ALTERNATIVE BELT P/N 539547-31.19;				
11/30/18		459.8					
			1			BUSHING P/4 12502	
						OPS CHECK COM	
			EDWARD	MACIBI	TAMG	A+P24	11844
12/4/13		44-1	pemoveo	VACUM	n pump 101	1x 212cw, 5/H 153	551;
			INSTALLED	NEW OV	ETHAUL OF	C. PUMP PHY 212CO	w, slag
			154285;	1457AVIC	D NOW AT	T. ATTACH BOTT PI	MANS-
			/			UN V-9534-20 A	
						OPS CHECK COM,	
			EDWARD			A+P241	
DER 12,2013		664.3	REMOUED A	ALTIMET	TER PINS	934P-A56, SN	19182
	3					34-1, 5/N M44	
						MASP 334 1221-	
		ſ	Mesquite Avid		, , , , ,		ins
			1725 E. Ry Chandler, A	yan #8			
		T	CRS# Q5K				i i
	Reg			S/N	Tach/hobb		
	N575	70 Beech	35C	GD1092	2271		
	I certify	that the altimeter a	nd static system tes	ts required by 1	4 CFR § 91.411 and FAR 91.413, have		1
	been pe	rformed and found them Tested to 20	to comply with 14 (	CFR part 43, ap	pendixE& F.		
	Date	12/14/13	de de				1
	Wor	k performed by V	3 that	$\geq$		And the second s	
	Inspe	ected by B-	half	Work Ord	er # M 1179		
	- · · T				-		
25 2014		681.2 E	EMOUED G	-35 5/N G	02694463.	INSTALLED NEW E	- 35
		WOI.L S	1~602777	095 OF	CR GOOD TO	them Set 458 3341	221
4/2014		1013					
,, 4,7		681,3	NEW STAL	rel Soven	vois, 5-199	MAI, INSTALLED, OP	ERATION .
			CHACK CON	WIETED,	Turken	C/a 11+733412	2/
					,		
							. 1
	1						

3 N5757D AIRFRAME MAINTENANCE RECORD MODEL: 35-C33 SN: CD-1092

PAGE NUMBER 5

			514. CD-1072	
	TOTAL	TAGE		
	TIME	TACH OR RECORDING	DESCRIPTION OF WORK PERFORMED	
DATE	IN	METER		
	SERVICE	TIME	SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK	_
			CHANDLER AIR SERVICE 1675 E. RYAN RD.	
3/28/2014	N5757D	MODEL	CHANDLER, AZ 85286	-
FAR 91.207(d	COMPLIED W	MODEL: 35		-
AD 89-05-02,	ELEVATOR CO	NTPOL FITTING	A OPERATIONAL INSPECTION OF ELT & BATTERY. ELT BATTERY EXPIRES 1/2015  S, INSPECTED PER Beech Service Bulletin No. 2242, Revision 1.	
AU 2007-08-0	B I ANDING OF	- COLITINGS	>, INSPECTED PER Beech Service Bulletin No. 2242. Revision 1.	
				1
NEW FLASHE	RASSV 02 00	Table III	IN AIR BUX ASSEMBLY	
NEW BOLT, 3	5-825108 INCT	ALLES ON, & BULE	5, UZ-U350433-00, INSTALLED LOWER BEACON ASSY	
NEW GASKET	35-021101 IN	OTALL SE	AN ACTUATOR ROD	-
NEW DUCT.	SCEET12 INST	TALLED ON LEFT	EL STRAINER ASSEMBLY EXHAUST ASSEMBLY	
NEW TERMIN	AL NIPPLE MS	25174 40 10074	NMUFFLER SHROUD & CABIN HEAT CONTROL VALVE	
MINOR META	L REPAIR COM	PLETED TO LEF	LLED BATTERY CONTACTOR TERMINAL  T & RIGHT WING TIEDOWN RINGS (NEW BUSHINGS INSTALLED)PER AC 43.13-1B	-
MINOR CORR	OSION REMOV	(ED EDOM DATT	TO NOSE GEAR DOOR ACTUATOR GUIDE PIN PER AC 43.13-16	
	WITH CHE	CV2 COMPLEIF	J.	_
I CERTIFY TH	IIS AIRCRAFT I	HAS BEEN INSPE	CTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN	_
AN AIRWORT	HY CONDITION	I. INSPECTION C	COMPLETED PER CHANDLER AIR SERVICE (CAS) INSPECTION CHECKLIST.  DE WITH BEECHCRAFT & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE	
ADs CHECKE	D THROUGH A	TP REVISION DA	TED 3/25/2014. ADDITIONAL MAINTENANCE RECORDS SPECIFIC TO THIS AIRCRAFT,	_
INCLUDING P	ERSONS COM	PLETING MAINTE	NANCE ARE FILED IN AIRCRAFT MAINTENANCE FILES LOCATED IN CAS	
Ly Wa	E OFFICE UND	ER SHOP ORDE	R 14-3294	
RICKY WILL	≈ A&P 3028383 IA		ž.	_
6.3-14	753.8		INSTALL NEW 4313 LDG. LIGHT BULA DISCU, 600	0.
			10	
		-	Matthe S. Mary Ax P 2797711	_
			/	
7-13-14	761.3		INSTALLED NOW PIT SWITCH IN RIGHT YOKE, OPS (4 GOOD.	
1 13 19	1.01.		Bruce a Miles A& P 307 86 99	
		<del> </del>	13 mil (1 11 mil) 1 80 / 80 19	
			CHANDLER AIR SERVICE	
		9	1675 E. RYAN RD.	
-		MODEL: 35	CHANDLER, AZ 85286	
7/24/2014 ALTERNATO			ED COD INSPECTION/REPAIR ATTERNATOR INSPECTED & REDAIDED BY EAL CON	
AFRO, WO#	1354. ALTERNA	TOR RE-INSTAL	D D4224 INSTALLED	
_ NEW UPPER	, 4509 GLAT, a	MADI ETED		
OPERATION	AL CHECKS OF		OF MITTURESCUCPART & OTHER APPLICABLE MAINTENANCE MANUAL O	
ADDITIONAL	MAINTENANCI	E RECORDS SPE	CIFIC TO THIS AIRCRAFT, INCLUDING PERSONS COMPLETING MAINTENANCE, ES LOCATED IN CAS MAINTENANCE OFFICE UNDER SHOP ORDER 14-3414	
- ARE FILED	AIRCHAFT	9		
- Cont	THE ARE	2611566		
EDWARD MA	GEITANG, A&I			
			*	

## N5757D AIRFRAME MAINTENANCE RECORD

SN: CD-1092

PAGE NUMBER 6

-	
O	

	- 3
OG NUMBER	
OC MOINTER	

MODEL: 35-C33

			DESCRIPTION OF WORK PERFORMED
	TOTAL	TACH OR RECORDING	
	TIME	METER	SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK
DATE	SERVICE	TIME	CHANDLER AIR SERVICE
			1875 E RYAN RD CHANDLER, AZ 85286
		MODEL : 35-0	took TACIL 900 0 AFTT ATT
9/5/2014	N5757D	MODEL: 334	C33 SN: CD-1092 TACH: 800.0 AFT1: 6476.5 OPERATIONAL INSPECTION OF ELT & BATTERY. ELT BATTERY EXPIRES 1/2015 INSPECTED PER Beech Service Bulletin No. 2242, Revision 1.
FAR 91.207(d)	COMPLIED WIT	TROL FITTINGS	INSPECTED & LUBED PER Beech Service Instruction No. 0448-211, Rev. I.
AD 89-05-02, E	LEVATOR CON	R UPLOCK ROL	, INSPECTED PER Beech Service Builetin No. 2242, Revision 1.  LERS, INSPECTED & LUBED PER Beech Service Instruction No. 0448-211, Rev. 1.  REGULATOR ASSEMBLY
NICA EII TER	ZA-D9-10-1, IIVO	INCLED	BLOUT HALE NOSE WHEEL ASSEMBLY
EMERGENCY (	CABIN AIR SHU	TOPT CONTINUE	- VENT DUCT
NICIAL CLAMP (	35200-40H, INS	TALLED DET TO	TO OLEANED & MOTOR LIBRICATED
UPPER ROTAT	ING BEACON E	COMPLETED T	O #4 CYLINDER COOLING BAFFLE PER AC 43.13-1B
I FAK & OPERA	TIONAL CHEC	KS COMPLETED	
CERTIFY THIS	S AIRCRAFT HA	S BEEN INSPEC	TED IN ACCOUNT OF AIR SERVICE (CAS) INSPECTION CHECKLIST
AN AIRWORTH	IY CONDITION.	INSPECTION CO	AUTH RESCHORAFT & OTHER APPLICABLE MAINTENANCE MANUALS APPLICABLE
MAINTENANCE ADs CHECKED	THROUGH AT	P REVISION DAT	EWITH BEECHORIST A WAINTENANCE RECORDS SPECIFIC TO THIS AIRCRAFT,
WALLIDING DE	DECNIS COMP	FTING MAIN I CI	VANCE, AILE I ILLE III VIII OIL
MAINTENANCE	OFFICE UNDE	R SHOP ORDER	
RICKY WILL, A	&P 3028383 IA		
KIOKI WILL, I			CHANDLER AIR SERVICE 1675 E. RYAN RD.
			CHANDLER, AZ 85286
	9/19/201	14 N5757D	MODEL: 35-C33 SN: CD-1092 TACH: 806.1
			7, INSTALLED FLAP MOTOR. OPERATIONAL CHECKS COMPLETED.
	MAINTEN	ANCE COMPLET	ED IN ACCORDANCE WITH BEECHCRAFT & OTHER APPLICABLE  ADDITIONAL MAINTENANCE RECORDS SPECIFIC TO THIS
	AIRCRAF	T. INCLUDING PE	RSONS COMPLETING MAINTENANCE, ARE FILED IN AIRCRAFT
			CATED IN CAS MAINTENANCE OFFICE UNDER SHOP ORDER 14-3447
	Dene	a mil	an
	BRUCE A	WILSON A&P 30'	78699
	DAMESTON BOOK STORY		
1/28/205		862.0	NEW BATTERY POINTEL 2020 , INSTAUSED ELT GUSTEMA
1			PAL 91.207 (d) COMPLISO WITH BY VISUAL & OPERATIONAL
			ENSPECTION, BATTERY EXPIRES : 12017, LYWIN ATP 3028383
7/22/		222	
4/23/2019		872.1	NEW BULB INSTALLED UPPER LANDING LIGHT 4558,
			EPERATIONAL CHECK COMPLETED. By Wind AND 3028383
			7-9-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-
-11			
5/1/2015		891.0	GARMIN GNS 430, SN 9712 0114, REMOVED FOR INSPENDING
			REPAIR. SERVICENSIE GNS 430 REMOVED FROM N 25 922
			INSTAUSD. Roy W.SI A+P 30283803
5/21/2015	_	898.6	CARROLL COLLIS 12 PRODUCT
		- [916	GARMIN GNS430; SN 97120114, REDAILED BY GARMIN INTL,
			INSTAILED.

DATE

	6	4	_	
-6	6		à	
179	Ą	Ti.	y	
		w	-	

TOTAL TACH OR TIME RECORDING IN METER SERVICE TIME

## **DESCRIPTION OF WORK PERFORMED**

SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK

CHANDLER AIR SERVICE CHANDLER, AZ 85286

6/11/2015 N5757D TACH: 900.7 AFTT: 6577.2 MODEL: 35-C33 SN: CD-1092 FAR 91.207(d) COMPLIED WITH BY VISUAL & OPERATIONAL INSPECTION OF ELT & BATTERY. ELT BATTERY EXPIRES 1/2017

AD 89-05-02, ELEVATOR CONTROL FITTINGS, INSPECTED PER Beech Service Bulletin No. 2242, Revision 1. AD 2007-08-08, LANDING GEAR UPLOCK ROLLERS, INSPECTED & LUBED PER Beech Service Instruction No. 0448-211, Rev. I.

NEW FILTER, RA-B3-5-1, INSTALLED VACUUM REGULATOR ASSEMBLY

NEW GASKET, 35-921181, INSTALLED MAIN FUEL STRAINER ASSEMBLY NEW FUEL BOOST PUMP, 4140-00-7NVCJ, SN 1016, INSTALLED WITH NEW O-RINGS, MS29512-06, & DRAIN HOSE, MIL-DTL-6000D 1/4

NEW BEARING, YAG-04-E, INSTALLED NOSE GEAR RETRACTION CENTERING ASSEMBLY NOSE TIRE ROTATED ON WHEEL ASSEMBLY

NEW BELT, 539547-31.19, INSTALLED ALTERNATOR DRIVE ASSEMBLY NEW HOBBS HOUR METER PRESSURE SWITCH, 100450, INSTALLED LEFT FORWARD FIREWALL BELOW BRAKE RESERVOIR

NEW CLAMPS, MS21919-DG5 & -DG11, INSTALLED

MINOR WELD REPAIR COMPLETED TO CABIN ENTRANCE STEP PER AC 43.13-1B

MINOR WELD/SHEET METAL REPAIR COMPLETED TO BATTERY BOX PER AC 43.13-1B

LEAK & OPERATIONAL CHECKS COMPLETED.

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AN AIRWORTHY CONDITION. INSPECTION COMPLETED PER CHANDLER AIR SERVICE (CAS) INSPECTION CHECKLIST. MAINTENANCE COMPLETED IN ACCORDANCE WITH BEECHCRAFT & OTHER APPLICABLE MAINTENANCE MANUALS. APPLICABLE ADS CHECKED THROUGH ATP REVISION DATED 6/10/2015. ADDITIONAL MAINTENANCE RECORDS SPECIFIC TO THIS AIRCRAFT, INCLUDING PERSONS COMPLETING MAINTENANCE, ARE FILED IN AIRCRAFT MAINTENANCE FILES LOCATED IN CAS MAINTENANCE OFFICE UNDER SHOP ORDER 15-3727

RICKY WILL, A&P 3028383 IA

8/13/2015	918.0	NEW TOWBAL ATTACH PIN INSTALLED NOSE STRUT
		ASS4 MBLY. Ly Will AMP 3028383
0 AUG 2015	0918.0	SCAULCEASLE COMM ANTENNA, CI 138, S/N 8941, AND NEW NAVICOMM
		ANTENNA, 0-247930-0001, 5/N 164083, (NSTALLED, ORS CK 6080. Bruce Wilson And 3078699
(4 NOU 2015	951.4	1NSTALLES NEW TIRE P/N 072-314-0, RACE P/N 13836 BEARING P/N 13889 ON TEFT MAIN WHELL ASSY, NEW
		TIRE AN 072-312-0 S/N 5062500182 ON NOSE WHEEL  ASSY Two try on Life A&P 3341221
7000 2015	951.4	M37MLED NEW TOW PIN P/N RAGO- 8200291 IN BYOSE STRUT
7,000 70.0		ASSEMBLY. Tunky on Cha 4 & P 334/1221
1/21/2015	955.1	NEW OVERHALLED GEAR MOTOR PHY 35-380094, 5/H 2021; INSTANCED
		COMPLETED, EDWARD MAGBITANY NAPPLITE

## N5757D AIRFRAME MAINTENANCE RECORD MODEL: 35-C33

SN: CD-1092

PAC

GE	NUMBER	8

	TOTAL TIME	TACH OR RECORDING	DESCRIPTION OF WORK PERFORMED						
DATE	IN	METER TIME	SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK						
DATE	SERVICE		Mesquite Avionics LLC 1725 E. Ryan #8 Chandler, AZ 85249 CRS# Q5KR301B						
		Reg.#	A/C Make   Model   S/N   Tach/hobb						
		N 5757 D	Beech	35-633	CD-1092	2706	- Breen		
		I certify that the altimeter and static system tests required by 14 CFR § 91.411 and transponder tests, including data correspondence, required by FAR 91.413, have been performed and found to comply with 14 CFR part 43, appendix E &F.  System Tested to 2 C C O feet  Date Of O4/2 C/K  Work performed by S. Charles  Work Order # 1002							
4-26-16		965.3	TNS	TALLE	DUEN	6-35	BATTERY		
							/ /2		
					7	10000			
		9491128418							
9 11 2000	and the second com-			CHANDLER AIR S	ERVICE _				
		-		1675 E RYAN CHANDLER, AZ	85286 -				
N5757D N	ODEL: 35-C33	SN: CD-		ACH: 970.7	AFTT: 66	47.2			
VISITAL & OPE	RATIONAL IN	SPECTION OF EL	T & BATTER	Y COMPLIED	WITH PER FAR		T BATTERY EXPIRES 7/2018		
	HODED ADAD	NTROL FITTINGS CRACKS, Inspec	stad Dar Ree	ch Sarvica Rii	Hetin No. 2333. I	revision I.			
■ Nev	DW-1 Unner	Hinge, & DW-2, N 100, Rev. A, Date	1iddle Hinge.	Rudder Brac	ket Kits installed	in Accordance	With STC SA00044LA, Master		
AD AF A4 A2 C	DAD EDAME S	TRUCTURE Inci	nected Per Br	eech Service	Bulletin No. 2360	).	sin Kit		
AD 2007-08-08	LANDING GE	004-1-S, SN 260,	LLERS, Inspe	ected & Lubec	l Per Beech Serv	rice Instruction	No. 0448-211, Rev. I.		
NEW FILTER.	RA-B3-5-1, INS	TALLED VACUUN	/I REGULATO	OR ASSEMBLY					
NEW FILTER, I	RA-D9-18-1, IN: ARD FLOORBO	STALLED INSTRU	REPAIRED, N	EW FLOORBO	DARD & REPAIR	ED CARPET INS	TALLED FORWARD CABIN		
NEW FILTER I	3A-7112. INSTA	ALLED INDUCTIO	N AIR BOX A	SSEMBLY					
NEW RACE, 13	836. & BEARIN	4-0, SN 6012S000 NG, 13889, INSTA	LLED RIGHT	WHEEL ASSE	EMBLY, INBOAR	D POSITION			
NEW O-RING.	MS28775-222,	INSTALLED RIGH	IT BRAKE CA	LIPER PISTO	N				
<b>NEW O-RINGS</b>	MS28775-012	5109, INSTALLED 2, -223, -224, BEA	RING, 45-825	031, & SHIM,	35-820134, INST	ALLED NOSE GI	EAR STRUT ASSEMBLY		
NEW BEARING	S (2), 08125, &	RACE (1,RT), 08	231, INSTAL	LED NOSE W	HEEL ASSEMBL	Y			
NEW BOLT, AN	16-30A, INSTAL	LED RIGHT SIDE	NOSE WHEE	R V-BRACE A	SSEMBLY	CMOLI			
MINOR WELD MINOR WELD	REPAIR COMP	D TAXI LIGHT AS LETED BATTER' LETED LEFT MU CKS COMPLETEL	/ BOX PER A FFLER HEAT	.C 43.13-1B. E SHIELD PER	BOX INSPECTED AC 43.13-1B. S	), ACID-PROOF I HIELD INSPECT	PAINT APPLIED, BOX INSTALLED ED AND INSTALLED		
AIRWORTHY CO COMPLETED IN ATP REVISION MAINTENANCE	ONDITION. INSI ACCORDANCE DATED 7/20/201 , ARE FILED IN	PECTION COMPLIED WITH BEECHCR.  16. ADDITIONAL MAIRCRAFT MAINT	ETED PER CH AFT & OTHER MAINTENANCI	IANDLER AIR S R APPLICABLE E RECORDS S	SERVICE (CAS) II MAINTENANCE I PECIFIC TO THIS	NSPECTION CHE MANUALS. APPL SAIRCRAFT, INCI	DETERMINED TO BE IN AN CKLIST. MAINTENANCE ICABLE ADS CHECKED THROUGH LUDING PERSONS COMPLETING DER SHOP ORDER 16-4114		
BRIAN L. WILS	ON, A&P 4977	28418 IA			8/4/2016	s	HOP ORDER 16-4114		

8/4/2016

SHOP ORDER 16-4114

MODEL: 35-C33

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMANCE & CERTIFICATE TYPE/NUMBER OF PERSON	
	N5757D Butler Avionics		Date - November 22, 2016	TENTORMING WORK
			Station #TF2R185L	
	The aircraft and	or component iden	tified were repaired in accordance with current federal	
	are on file at the	and were found airw	tified were repaired in accordance with current federal orthy for return to service. Pertinent details of the repair	
		s agency,	of the repair	
	The GNS-430 w	vas upgraded to WA	AS at the factory. Upgraded the aircraft for WAAS C transponder and installed a new Garrie GTV 245	
				200
	There was negli	manufacturer specs gible weight change	C transponder and installed a new Garmin GTX-345 See Form 337's this date for additional information.	
			,	
	S:	4		
	Signature WO #MN01110	an LN	Repairman #2347550	
		· · · · · · · · · · · · · · · · · · ·		
				-
		, ,		
NI#	5757	<b>2</b> D		
N#-	5/5/	D	Date <i>  -23-16</i>	
Butl	er Avionics, Inc.		Station #TF2R185L	
			ied was repaired in accordance with current	
			d airworthy for return to service. Pertinent	
	///	are on file at this	- ·	
Sig	nature	Cory	Repairman #_ <i>22704SC</i>	
Hot	bs/Tach		W.O.# <u>M 506980</u>	
Acti	on: D	1 Kropes	6NS430 4 KMD24	
D.	Kemwed K	TROGATEN	5430 WIRING. Repaired	
Kep	-208 IMA	ing Rowsta	6 NS 436 + KMA24 5430 WIRING Repaired  Mal GNS 430, KIRRGA  BAForm 012	
110	A24 VKTZ	08.		
16 110			BA Form 012 ——————	
KIII.				et.
KIII.			The same of the sa	
,			# E7E1N	
			Registration # 5757D	
		I certify that t	he following transponder and altitude	
·		reporting sys	he following transponder and altitude tem was tested as required by FAR 91.413	
·		reporting sys	he following transponder and altitude tem was tested as required by FAR 91.413 structions in FAR 43 appendix F.	
	0	reporting sys as per the in	the following transponder and altitude stem was tested as required by FAR 91.413 structions in FAR 43 appendix F.  S/N 3EG 004138	
, , , , , , , , , , , , , , , , , , ,	<i>e</i>	reporting sys as per the in  Transponder	the following transponder and altitude stem was tested as required by FAR 91.413 structions in FAR 43 appendix F.  S/N 3EG 004138	

BA-Form-009

## N5757D AIRFRAME MAINTENANCE RECORD MODEL: 35-C33

SN: CD-1092

PAGE NUMBER 10

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME Aviator Air. 31	SIGNATURE & CER	TIFICATE TYPE/NUM	ORK PERFORMED BER OF PERSON PERFOR	MING WORK
DES Per Rep lubr C/M AD AD	ME: Beechcra SCRIPTION OF formed ANNUAL placed induction ricated airframe. V AD 89-05-02, eV V AD 2007-08-08 93-24-03, eff. 04 95-04-03, eff. 04 ave inspected to	aft WORK PERFORM inspection. Inspection. Inspection. Inspection. BA- Adjusted baggage off. 03/24/1989: Elo 3, eff. 05/25/2007: 1/21/1994: Rudder 4/07/1995: Forward	MODEL: 35-C33 MED: ACT cted and tested ELT in acc 7112. Gear doors rigged in door stop. evator control fittings. By vi Uplock rollers. By operatio Spar. TERMINATED by co d spar. Kit 36-4004-1-s inst cordance with an annual	T: 6704.7 cordance with FAR 91.20 accordance with Beech sual inspection per para anal check and servicing. prective action 8/4/2016 alled 8/4/2016. Inspectio	S/N: CD-1092  S/N: CD-1092  T/  7 (d). ELT battery next due: craft 33/35 shop manual. Segraph (b). Next due: T: 1128  Next due: T: 1128.2.	1078.2 ACH: 1929. 3 July 2018. erviced and
- DA	Dec	cember 8, 2017	7	SIGNATURE	36461 A&P/IA	33 IA
		Aviator Air 31	22 S. Great SW Park			
DES		WORK PERFORM	MODEL: 35-C33  IED: ACTT: 6 6 ply rated tire and 5.00 si		l: 1029.6 Hobbs:	D-1092 2794.7
DA		ember 11, 201	7	SIGNATURE	3640 A&P	,/33
_   wo.w	O_428		J&G Aviation - 817-881-	5182	Airframe - page 1 of 1	
Install found and in test el inboar outbor 08125 Install ON /B cover	n: 1047.6 led vacuum relingood conditionspected inside ectrically and red P/N: 13889-ard P/N: 13889-ed new ELT baseFORE NOV 2 (P/N: does not expected thirthy condition.	ief valve filter eletion. Iubricated per of inspection promanually. Installed per 20629 Installed per 20629 Installed attery P/N: 2020 (20). Bled LH-bratapply for this ite	pulleys. cleaned and greanels. Placed aircraft or and L- wheel cup inboard R- wheel cup out board I nose wheel cups P/N: (2020 battery pack for 30 ke and fill up reservoir wim) for KX-155.	eased mains and nose n jacks and performed P/N: 13836-20629. In P/N: 13836-20629. Ins 18231-20629, install n 1000-10 ELT)( MFG DA ith brake fluid P/N: MI	February 19, 2019 ents filter inspected and e landing gear. Opened I landing gear retraction stalled L- wheel bearing stalled R- wheel bearings ose wheel bearings p/n: TE: NOV 18. REPLACE L-h-5656. Installed lens e determined it to be in	

METER CURRENT	
N5757D	
ALTIMETER NO. 1	

_					0 02 10.2	FOR		LLI	_
		TOTAL	TAGE			ALTITUDE		ALTITUD	티
		TIME	TACH OR RECORDING	DESC	RIPTION OF WORK PERF			4.10	
	DATE	IN SERVICE	METER			500		490	4
		SERVICE	TIME	SIGNATURE & CERTIF	ICATE TYPE/NUMBER OF PERS	1,000		1900	_
-	wo: WO_68	38				1,500		1500	_
	-			er,	Airframe ·	2,000		1990	_
				J&G Aviation		3,000		3005	$\dashv$
-			J&G Aviation, LLC -	545 Winston Street · Grand Prairie, TX 7	5052 · 817-881-5182	4,000		4015	1
	N5757	)			April 3,			6031	
	Tach: 1	056.1	Ho	CH, 35-C33, S/N: CD-1092 bbs: 2827.7	,, <b>,</b> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	8,000		8e43	
4	1.Comple	eted annual ins	m = =1'			10,000	*****	1006	
	I - ITEDIAL	CEU VACIIIIM ro	linfrale stu	N: BAB3-5-1		12,000		1205	5
	4. Check	ed cable tare	iuei strainer.			14,000	*****	1405	0
-						16,000		1607	10
_	J C. Comp	nied with At 1	9-23-10 per per	paranh h inappartian of right	aileron flight control cable end	18,000		1808	
		Saicty Wile an	(1) INSPECTED WITH	agraph in inspection of right 10X magnification. wing P/N Bat-8850.		20,000		2009	15
-	0. 1 61101	med landing g	ear retraction te	st normal and emergency		22,000			-
_	9.ELT te	sted per 91.20	7 and confirmed	d proper operation and insta	allation. Battery replacement d	25,000			
		AD compliance	report for AD I	sting. I have inspected this	aircraft in accordance with an	30,000			_
-	inspection	on and have de	etermined that it	is in airworthy condition. De	etails of work performed are on	35,000		/	
_	J&G Avia	ation under wo	rk order WO 688	3.		40,000			
			٨	mm Was		45,000			
_	Jimmy V	Vilson A&P/IA	2152303	mywas		50,000			
-		Ι						V	
	_	1	1				PDG SERV	ICES	
	N575	57D	VIATOR A	3122 Great Southwest Parkwa	y Grand Prairie, TX 75052 (972)986 Inspected the ELT in accordance	CRS: G	49R038Y		
	Date:	: Aug 13, 2021 Ta	ecting the mounting	r the battery and performing a fund	ctional check. Found to be OK. Battery	WO #	224013	1	
			ander Inchaste	d the fire extinguisher and its mo	inting Replaced fear hav light build at	CHIAIE.	10-12-	12	
-		OV D	A for nous A F	'e through Riweekly 2021-16	Complied with AD 89-03-02 Elevator	WIIII VI	2		
					mplied with AD 19-23-10 per parag ling gear retraction test, normal and em				
	Leert	tify that this aircra	ft has been inspecte	d in accordance with a Annual ins	pection and was determined airworthy				
	Steve	e O'Brien IA 3397	7718	and					
			1		-				
		PDG Service	es + 670 Ferri	s Rd., Suite 104 + Lancast	er TX 75146				
_		<b>-</b>	DEC NETS		40.8				

The H altimeter, transponder & altitude reporting system has been inspected and found to comply with the requirements of FAR 91.411 & 91.413, to an altitude of 20,000 ft. Pertinent details of the certification are on file at this repair station under the work order # 22-1013, dated 613-22

GT× 345 5434 p 369004138 S/N Transponder P/N Altimeter R/N

Paul Gardner CRS G49R038Y

(Authorized Signature) 214-886-5894

10-12-22 (Date)

3122 Great Southwest Parkway Grand Prairie, TX 75052 (972)988-8609 Date: Oct 20, 2022 Tach: 1140.9 AcfiTT: 6817.3 Hobbs; 2929.9 Inspected the ELT in accordance with 14 CFR Date: Oct 20, 2022 1 acht. 1752/ 1861. 175 91.207(d) by inspecting the industrials are performing a state of the performance of the right wing fuel bladder, FIVE 2020-2, 18 of Control of State and S been inspected in accordance with a Annual inspection and was determined airworthy. Steve O'Brien IA 3397718

LOG NUMBER 3

(Beech) 3!

/01/2022 N

lours: 6817.

Continental IO-

Hartzr

eec

Security of

Engine Fuel

Engine Oil Air Oil Separa

Tachometer (

Screws in the System

Elevator Control

levator Trim Tab

ng Carry Through

Flex Shaft

ding Gear Uplock

t Aileron Flight Co e End Fittings

10-470-K

N5757D AIRFRAME MAINTENANCE RECORD SN: CD-1092 **MODEL: 35-C33** 

PAGE NUMBER 12

NS757D 2.1.1.157.6. Hobbs. 2951.9  Date: June 7. 2023. Tach: 1157.6. Hobbs. 2951.9  Installed new orngos on left side wheel brake pucks. cleaned and inspected caliper and reassembled, blead brakes and ops checked, ground taxi brake test good.  Steve O Brien A&P 3597718	DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED  SIGNATURE & CERTIFICATE TYPE/NUMBER OF PERSON PERFORMING WORK
	Date:	June 7, 2023, Tach installed new orings	h:1157.6 Hobbs: 295 s on left side wheel b xi brake test good.	51.9  brake pucks . cleaned and inspected caliper and reassembled , blead brakes and
	•			
				,