#### SAN DIEGO PROPELLER & ACCESSORIES, INC. 4-169646 SERVICEABLE PART BLADE MODEL NO 2 FB468A-4R MFG Hartzell BLADE SER NO. MODEL NO. HC-F2YR-1F E83413 E83410 SERIAL NO. \_CM638 ANGLE: LOW 16.25 IGH 33.6 FEATHER REV STA 30" ub Mc GOVERNOR RPM MIN\_\_\_\_\_MAX \_\_\_\_ ade [ REMARKS Propeller has been completely overhauled per service manual iame #113B. Blades inspected & compression rolled per SB #118C to comply ub S with AD 77-12-06. All pertinent SB's through #148 & SL's through #154 have been complied with. Propeller returned to "0" hours S.M.O.H. NOTE: Tachometer must be checked for accuracy to fully comply with AD 77-12-06. No No. 2 No. 3 No. 3

High

Feather\_

Governor Model

PITCH RANGE

Reverse

PITCH RANGE

Reverse

eather

Sovernor Model

DATE	TACH	DESCF	RIPTION OF WORK		SIGNATUR	RE
Date APR/			Date MAY 7.03 Total Time in Service		9.4	
I Certify this	Aidrente, Engine, Pro	peller have been	I Certify this Airtrame, inspected in Accordance	with a	100 HOUR	
Inspection as	nd was determined to	be in an Airworthy	Inspection and was det Condition per FAR Part	43 (d) and is	s Released Back to	
Service. Pert	inent details of this Insp under Work Order No.	ection are couffie at	Service. Pertinent details this Agency under Work			
Signature	Service Center, Inc.	tor.	Signature	nter, inc.	tor.	
	ra Valley Road #85		11700 W. Avra Valley Ro Marana, Arizona 85653	oad #85		
FAA CRS No			FAA CRS No. YXUROSS.			
MODEL	Piper PA28-236	Tucson	Aeroservice Center	DATE	7/28/2004	
S/N REG. NO.	28-8111050 N83334	11700 W. Avra Valley Rd. Marana, AZ 85653		W.O.# HOBBS	04-000470	
CYCLES		Maintenance D	Dept. FAA CRS # YXUR055J	TACH Total Tim	1501.4	
Eng. S/N	adlar component identified sh		ed in accordance with current fede		A STATE OF THE STA	moine
Date	7/28/2004 only fo	r the work accomplished. Pert	inent details of the reportant on fit	with this ager	N .	
Removed	propeller from O-540-J	• •	and installed on O-540-J3	C5D S/N 2	0893-40A.	Martin In
-		END				

Hub Model

Blade Design

Diameter

LEFT ENGINE

# PROPELLER MAINTENANCE RECORD

This component identified was repaired and inspected in accordance with current regulations of the Pederal Aviation Agency and is approved for return to service.

Pertinent details of this repair are on file at this repair station under W.O. 8383

Signed Date 7/31/86

San Diego Propellor & Accessories INC.

Repair Station #403-38

Repair Station #403-38
Giliespie Airport Plaza
8400 Magnolia Ave., Suite H
Santee, Calif. 92071

## DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DESCRIPTION OF WORK

SIGNATURE

TACH

DATE

***	WALE	44WE	CESCHIP I (OI	SIGNATURE	
-					
					The second second second
	N63334 PROP LOG ENTRY PIPER PA-28-2 LYCOMING O- Hartzell HC-F3	36 540-J3C5D	S/N 28-8111050 S/N L 20893-40C S/N CM 636	ACTT: 2181.8	Tucson Aeroservice Center 11700 W. Avra Valley Rd Marana, AZ 85653 CRS #YXU056J Hobbs: 1993.4 Tach: 1666.8
	This sirrraft an	id/or compor i is approved	pection per the Tucson Aerosei nent identified above was reput for return service. Pertinent de	aired inspected in accordi	ecklist and FAR 43, Appendix D. ance with current Federal Aviation le with this agency.
	DATE	-	/25/2006 Signed:	Jours	h

DATE	TACH	DESCRIPTION OF WORK	SIGNATUR
9/4/07 1 certify ( alreverthy	this propeller has been in condition	Propeller TT 2297.5 aspected in accordance with an annual inspection and Harlie D. Deckard A&P 1829705 1A	was determined to be in an
11/1 1 cer was	tify this propeller	Propeller TT 2334.5 has been inspected in accordance with a n an airworthy condition.  Harlie D Deckard  A&P 1829705 IA	n annual inspection

## DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
12/15/10	)	Propeller TT 2310.9	_
I certify	this propeller ha	s been inspected in accordance with an an	nual inspection and —
		n airworthy condition	no =
		Harlie D. Deckard A&P 1829705 IA	
1/6/12		Propeller TT 2350.7	
		as been inspected in accordance with a Pa as determined to be in an airworthy condi	
_		Harlie D. Deckard A&P 1829705 IA	
	<u> </u>		COLUMN TO THE CONTROL OF THE COLUMN TO THE C

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5/6/13		Propeller TT 2364.6	
I certify thi	s propeller has be	en inspected in accordance with an ann	ual inspection and
was determ	ined to be in an ai	irworthy condition Dockers	0
		Harlie D. Deckard	
		A&P 1829705 IA	
		en inspected in accordance with a Part d to be in an airworthy condition  Harlie D. Deckard  A&P 1829705 IA	43 Appendix D annual

		has been inspected in accordance with a ermined to be in an airworthy condition	16 Pie DD B.O
		4	Harlie D. Deckard
			A&P 1829705 IA
	5 4 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
-11-16	TACH 205	0,5, T.T. 2563,3, 75MOR	1063.3
	PERFORME	INSPECTIONS AND SERVICIA	C PER THE PIPER
		REPORT TABLLE 111-1, PAR	
August Shares (- )		IFY THAT THIS PROPELLER	The second of th
		DANCE WITH AN AMMAL I	
		VED TO BE IN AN AIRE	
entransación frantes de como d	$\bigcirc$	3245075 14	
	44 2085:1		

9/23/18, TACH ZIAGO, T.T. ZGGZ.4, TSMOH 1192.3

PERFORMED INSPECTIONS AND SERVICING PER THE PIPER

SM INSP. REPORT TABLE III-I, PARA A, PAGE IFIB

I CENTIFT THAT THIS PROPELLER HAS BEEN INSPECTED IN
ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS

DETERMINED TO BE IN AN AIRWORTHY CONDITION'

32450751A STOGSDILL

105/19 15/19 TACH 2249.4, TT 2762.0 TSANOH 1261.5 AD COMPLIANCE LOG PATED 9/15/19 15 CURRENT. PERFORMANCE INSPECTIONS AND SERVICING PER THE PIPER SM INSP. REPORT TABLE 111-1 , PARA A, PAGE IF18 --"I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANMAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION" 3245075 IA STOGSDILL

Propeller Manufacturer HARTZELL  Model HC-F2YR-IF  Hub Series # CM 638	Type	1- E83413
Date of Manufacture 1981		2- E33410
Make/Model Aircraft Installed On: Piper/PA38-336	Serial #	
N83334_		

UB	&	BLADE	INSPEC	TIONS,	REPAIRS	AND	ALTERA'	TIONS	N83334	4
		and the second s	ADAPOSA O A TAMBO							190000

2/16/2021 Tach 2276.3 TTProp. 2791.2 TSMOH 1288.4 N83334 Supervised Rick Witaker (owner/operator) During cleaning, servicing and minor maintenance. As

prescribed by the Piper PA-28-236 SM Sect. 12. AD compliance logs Dated 2/15/21 are current.

AP 3245075 Stogsdill

2/16/2021 Tach 2276.3 TTProp. 2791.2 TSMOH 1288.4 N83334 Performed Inspections per the Piper PA-28-236 SM Sect. 5. Periodic Inspection Check List pgs. 5-02 thru

5-05. "I Certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy Condition" 3245075 IA Stogsdill

3/08/2022 Tach 2297.0 TT Prop. 2811.9 TSMOH 1309.1 N83334 Performed Inspections per the Piper PA-28-236 SM Sect. 5. Periodic Inspection Check List pgs. 5-02 thru 5-05. "I Certify that this Propeller has been inspected in accordance with an Annual inspection and was

determined to be in an Airworthy Condition" 3245075 IA Stogsdill

# AIRCRAFT MAINTENANCE RECORDS

Owner Rick Whitaker Aircraft Registration N 83334 Manufacturer \_\_HARTZELL Model HC-F2YR-1F Serial No. CM 638 Position Blade 1 - E83413 Blade 2 - E83410

### AIRCRAFT MAINTENANCE RECORD

Page No. \_\_\_

Date

**Total Time** 

DESCRIPTION OF WORK PERFORMED
SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK

ALDDIED

### **PROPELLER LOG**

DATE: 05-24-2023

AIRCRAFT: Piper PA-28-236

ENGINE: Lycoming O-540-J3A5D

PROPELLER: Hartzell HC-F2YR-1F

PROPELLER LOG

REGISTRATION: N83334.

ICAO 52663135

TCD: 2A13

TACH: 2311

TTAF: 2826

S/N: L-20893-40AC

S/N: 28-8111050

TSMO: 810

TTE: 4910

S/N: CM638

TSMOH: 1323

TTP: 2826

Elapsed (adder) time since log entry dated 03-08-2022, = 14

### **INSPECTION/SERVICE:**

- Propeller serviced and inspected in accordance with the Hartzell Propeller Owners Manual 115N. Biweekly AD's checked Through 2023-11.

#### Scott Farris A&P 3692748I.A.

-			
- 1			
1			E CONTROL AND
41	Bull-state (state) project of the control of the co	Bullion and the second of the	Signature and the state of the
н			
н			
ч			
1		K i i i i i i i i i i i i i i i i i i i	
ч			
1	processor and the second of th	Brazilian	Exp. 25 (1997) Administration of the property
1	Balgariera que el ser el como de la como de la como del como del como de la c	grand the control of the transport of the control o	
- 1			
- 1			
1			
- 1			
1			has been also as the second of
1	Mineral Administration of the Committee	Send on the contract of the co	To a contract the supplied and the contract
1	But only	A compared to the compared property of the property of the compared to the com	2 8 CONTROL CO
1			
1			
1			
1			
п			
н	A CONTRACT OF THE PARTY OF THE	\$ midumous constant and a second constant an	\$ \$400,000 per section (1) \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
١ŀ	P. C. Commission of the Commis		
11	A Transport of the Control of the Co		
П			
ì			
н			
: 1			