

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL

HC-C2YR-1BFP / F7497

PROPELLER S/N

NS 2049B

LOGBOOK #

1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model HC-C24R-1BFP

Propeller S/N NS 2049B

Blade Design F 7497

Blade S/N's

No. 1 L 48011

No. 2 L 48012

No. 3 Ø

No. 4 Ø

No. 5 Ø

No. 6 Ø

Spinner Assembly Part No. Ø

PITCH RANGE

High/Feather 29.0°

Start Lock N/A

Low 14.8°

Reverse N/A

Aircraft Manufacturer Mooney

Aircraft Model M20C



S/N 20-1190

Registration N 6957V


Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
8/8/2014			UNBOXED prop VISUAL check OK <i>[Signature]</i>
8-21-14		Tach 778.7 AFT 26263	Installed propeller and spinner assy on Aircraft, ground engine run OK, per STC SA0249-A SA 02414CH-W -END- <i>[Signature]</i> AD IA 2201735
MODEL M20C SERIAL NO. 20-1190 REG NO. 6957v			DATE February 28, 2015 TACH 800.4 PROP TTSN 21.7
RROPELLER LOGBOOK INSERT			
DATE 2-28-15 SIGNED <i>[Signature]</i> 2201735 IA AP			

I certify that this Propeller has been inspected per Annual Inspection and has been found to be in airworthy condition.

-----END-----

ACFT Model:	Mooney M20C	GIBBS SERVICE CENTER	Date:	3-8-2016
Serial No.:	20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.:	16-064
Reg. No.:	N6957V	FAA Approved Repair Station VT3R931L	TPT:	277 120.4
Prop. Mfg.:	Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N:	NS2049B
SMOH:	277 120.4	Tach: 877.0	Airframe:	2724.18
Annual Inspection per Mooney M20 Series AMM and Gibbs Service Center form F-8. Dressed and painted blades. AD notes checked and are current 3-8-2016. ATP Navigator Content Revision: 3-4-2016.				
The aircraft and/or component identified above repaired/replaced and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 16-064				
Date:	3-8-2016	Signed:	<i>[Signature]</i> Jeff Runyon 	
ACFT Model:	Mooney M20C	GIBBS SERVICE CENTER	Date:	4-19-2017
Serial No.:	20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.:	17-068
Reg. No.:	N6957V	FAA Approved Repair Station VT3R931L		
Prop. Mfg.:	Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N:	NS2049B
TPT:	219.1	Tach: 976.1	Airframe:	2823.28
Annual inspection completed per the Mooney M20 series Service and Maintenance Manual and the Gibbs Service Center Engine Inspection Checklist E-9. Dressed and painted blades. Shimmed spinner bulkhead. AD notes checked and are current. ATP Aviation Hub Content Revision: 4-19-2017.				
The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 17-068				
Date:	4-19-2017	Signed:	<i>[Signature]</i> Jeff Runyon 	

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	ACFT Model: Mooney M20C	GIBBS SERVICE CENTER	Date: 9-20-2017
	Serial No.: 20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.: 17-289
	Reg. No.: N6957V	FAA Approved Repair Station VT3R931L	
	Prop. Mfr.: Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N: NS2049B
	TPT: 256.2	Tach: 1013.2	Airframe: 2860.38
	Balanced propeller with Micro Vibe balancer to .028 IPS.		
	The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 17-289		
	Date: 9-20-2017	Signed: <i>Wayne H.</i>	
	ACFT Model: Mooney M20C	GIBBS SERVICE CENTER	Date: 5-8-2018
	Serial No.: 20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.: 18-171
	Reg. No.: N6957V	FAA Approved Repair Station VT3R931L	
	Prop. Mfr.: Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N: NS2049B
	TPT: 316.0	Tach: 1072.6	Airframe: 2920.18
	Removed propeller for repair.		
	The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 18-171		
	Date: 5-8-2018	Signed: <i>Wayne H.</i>	

05-21 2018	316	N/A		 <p>AMERITECH INDUSTRIES DBA AMERICAN PROPELLER SERVICE REPAIR STATION NO. NO3R717L 20208 CHARLANNE DRIVE REDDING, CA 96002 USA</p>
				WORK ACCOMPLISHED <u>Reseal - Repair</u>
				MODEL NO. <u>HC-C2YR-1BFP</u>
				SERIAL NO. <u>NS2049B</u>
				THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER
				REPAIR ORDER # <u>22725-05-2018</u>
				DATED: <u>05-21-2018</u>
				SIGNED <i>Mike Crowell</i> MIKE CROWELL (AUTHORIZED INDIVIDUAL)
				FORM LB01

Date	P TSI	ACFT Model: Mooney M20C	GIBBS SERVICE CENTER	Date: 6-6-2018
		Serial No.: 20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.: 18-171
		Reg. No.: N6957V	FAA Approved Repair Station VT3R931L	
		Prop. Mfr.: Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N: NS2049B
		TPT: 315.6	Tach: 1072.6	Airframe: 2919.78
		Annual inspection completed per the Mooney M20 series Service and Maintenance Manual and the Gibbs Service Center Engine Inspection Checklist E-9. Installed propeller resealed/repared by CRS No. N03R717L. AD notes checked and are current. ATP Aviation Hub Content Revision: 6-6-2018.		
		The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 18-171		
		Date: 6-6-2018	Signed: <i>Wayne I. H.</i>	

Date	P TSI	ACFT Model: Mooney M20C	GIBBS SERVICE CENTER	Date: 7-8-2019
		Serial No.: 20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.: 19-259
		Reg. No.: N6957V	FAA Approved Repair Station VT3R931L	
		Prop. Mfr.: Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N: NS2049B
		TPT: 387.0	Tach: 1144.0	Airframe: 2991.18
		Annual inspection completed referencing Mooney M20 series Service and Maintenance Manual and the Gibbs Service Center Engine Inspection Checklist. Greased propeller hub with Aeroshell 6 grease. AD notes checked and are current. ATP Aviation Hub Content Revision: 7-8-2019		
		The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 19-259		
		Date: 7-8-2019	Signed: <i>Wayne I. H.</i>	

Date	P TSI	ACFT Model: Mooney M20C	GIBBS SERVICE CENTER	Date: 8-28-2020
		Serial No.: 20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.: 20-407
		Reg. No.: N6957V	FAA Approved Repair Station VT3R931L	
		Prop. Mfr.: Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N: NS2049B
		TPT: 456.8	Tach: 1213.8	Airframe: 3060.98
		Annual inspection completed referencing Mooney M20 series Service and Maintenance Manual and the Gibbs Service Center Engine Inspection Checklist. Greased propeller hub with Aeroshell 6 grease. AD notes checked and are current. ATP Aviation Hub Content Revision: 8-28-2020.		
		The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 20-407		
		Date: 8-28-2020	Signed: <i>Wayne I. H.</i>	

Date	P TSI	ACFT Model: Mooney M20C	GIBBS SERVICE CENTER	Date: 9-24-2021
		Serial No.: 20-1190	Montgomery Field, San Diego, CA 92123	W.O. No.: 21-352
		Reg. No.: N6957V	FAA Approved Repair Station VT3R931L	Tach: 1,285.0
		Prop. Mfr.: Hartzell	Prop. Model: HC-C2YR-1BFP/F7497	Prop. S/N: NS2049B
		Prop SMOH: 528.0	Prop TT: 528.0	Airframe: 3,132.18
		Annual inspection completed referencing Mooney M20 series Service and Maintenance Manual and the Gibbs Service Center Engine Inspection Checklist. Greased propeller hub with Aeroshell 6 grease. Installed spinner anti chafe tape. Removed from engine SN: L-20508-36A and installed on rebuilt engine SN: RL-32486-36E. AD notes checked and are current. ATP Aviation Hub Content Revision: 9-24-2021		
		The aircraft and/or component identified above repaired/replaced and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Pertinent details of the repair/replacement are on file at this agency under Order No. 21-352		
		Date: 9-24-2021	Signed: <i>Wayne I. H.</i>	

Page 4