			PROP	ELLER ASSEMBLY LOG	
PAGE	NUMBER	₹/_			
Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
1/26	16 0	SA32C4	106 - D	THIS PROPELLER WAS MANUFACTURED	63N
		S/	N 140558	NEW AT MCCAULEY PROPELLED SYSTEMS	1 (30)
				INSPECTED AND FOUND TO BE AIR-	
				WORTHY ON THIS DATE.	
	Reg. No. N3072W McCauley 3A32C406-D/G-8 Serial No. 140558 Propeller Entry: Installed new propeller in McCauley instructions.			2NDB-2 West Valley Aircraft Services, Inc. Embarcadero Rd. Hangar B. Palo Alto, CA 94 Tel. (650) 565-0063 neccordance with D'Shannon STC SA1166GL and Beech	110. (7.170)
			y instructions.	Kevin R. Pinge	er A&P 3236526 LA
	_				

-			-					
		Reg. 1	No. N3072W		THE ACCENA	DIAIUU		
PAGE	NU	McCa Serial	iuley 3A32C40 No. 140558	6-D/G-82NDB-2	 Embarcadero Rd. Hangar B. Pa 	<5 d.b.a. lo Alto, CA 94303	5/22/2017 TACH: 1439.50 TTA: 3733.42	
1	ĺ	Propo	eller Entry:	Embarcadero Rd. Hangar B. Palo Alto, CA 94303 Tel. (650) 565-0063 TTA: 3733.42 TTP: 0.00 speller has been inspected in accordance with an Annual Inspection and was an inairworthy condition. This propeller is returned to service.				
Date	-	I certi deterr	ify this propel nined to be in	ler has been insp airworthy condt	ected in accordance with a ion. This propeller is return	n Annual Inspection ned to service.	and was	ature & tificate mber
	 	-				Kevin R. Pina	om 1 P D 2227527 11	
				ļ		reim it. I mge	7 ARCT 5230320 IA	
	in a	n airwo	at this propelle orthy condition.	r has been inspecte A detailed record	tion Ave. suite 125, San Jo 2W Propeller Tach: ed in accordance with an Ann is on file under Work Order	1441.07 PTSN: 1.5 ual/100 Hour inspection # 34686		
						<u> </u>		-
				_ _		<u>.</u>		
		1			<u> </u>			

			PROP	ELLER ASSEMBLY LOG	
PAGE	NUMBER				
Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
	7/ 1/2020, Tach: 1562.54: I certify that I have inspected this propeller I/A/W an ANNUAL inspection guide. S/N140558. TTSN 123.04: I have determined this propeller to be in an airworthy condition on this date and Tach reading only. James A. Foley AP545849691IA				1



4990 Wing Way, Ste. C Paso Robles, CA 93446

N3072W, Beechcraft, Model: A-36, S/N: E-492, TACH: 1666.61, AFTT: 3966.53. Propeller: McCauley, Model: 3A32C406-D, S/N:140558. Work Performed: Annual Inspection IAW FAR 43 Appendix(D). Inspected propeller hub, blades, spinner and bulkhead blade knicks as necessary.

Checked all AD's to current TDATA 21-16.

All work performed IAW maintenance manual and FAA approved data. I certify that this propeller has been inspected in scope and detail of an Annual Inspection and has been determined to be in airworthy condition.

Date: 8-13-2021

Signed:

Javedan

IA #2688610

&

e



4990 Wing Way, Ste. C Paso Robles, CA 93446

N3072W, Beechcraft, Model: A-36, S/N: E-492, TACH: 1745.47. Propeller: McCauley, Model: 3A32C406-D, S/N:140558. Work Performed: Annual Inspection IAW FAR 43 Appendix(D). Inspected propeller hub, blades, spinner and bulkheads. Dressed blade knicks as necessary.

Checked all AD's to current TDATA 22-24.

All work performed IAW maintenance manual and FAA approved data. I certify that this propeller has been inspected in scope and detail of an Annual Inspection and has been determined to be in airworthy condition.

Date: 11-01-2022

Signed:

IA #2688610

PAGE	Propeller · page 1 of 2	\neg
AGE	Lucy's	-
	Lucy's Aviation LLC - 7000 Merrill Ave. B-320/ HNGR #7 - CHINO, CA 91710-9091 - 19093432512	-
	PTTSN: 313.4 McCauley , 3A32C406-D/G-82NBD-2, 5/N: 140558 January 05, 2024	·e
ate	I certify this Propeller has been inspected in accordance with an Annual Inspection and was found to be in Airworthy condition.	ate
	1. Removed and replaced spinner mounting screws and washers with P/N: A-1635-133 Screw (15) and A	er
	2. Installed shims on prop hub spinner with P/Ns B-3410-32 Shim (2) and B-3410-16 Shim (2). All airworthiness directives through 1/2004 have the same and the sa	_
	All airworthiness directives through 1/2024 have been checked for compliance and recurrence. Complied with 2007-08-04 2007-08-04 McCauley Propeller Systems. Installed Cockpit Placard for RPM Restriction IAW AD	*
	This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of work performed are on file with Lucy's	
	wo: WO_115 Propeller · page 2 of 2	-
	lacy's	
	Lucy's Aviation LLC · 7000 Merrill Ave. B-320/ HNGR #7 · CHINO, CA 91710-9091 · 19093432512	
_	Aviation LLC under work order: WO_115. I certify this aircraft has been inspected in accordance with an annual inspection, and a list of highly recommended items dated 12/19/2023, have been provided for the aircraft owner.	_
_	Lucy Holbrook A/P & IA 3741763 Lucy Harbrook	