(2) C/W ANNUAL/100 HR INSPECTION ON THIS ENGINE I.A. W FAR 43 APPENDIX D USING MOONEY M20F M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. CHANGED ENGINE OIL AND FILTER

WORK DONE IAW LYCOMING 10-360-A1A M.M. ADS CHECKED 06-2023.... (5) C/W AD 2015-19-07 FUEL ENGINE TIMING, CLEANED, REGAPPED AND CHECKED SPARK PLUGS. PERFORMED OK. COMPRESSION CHECK: 78-78-79/80. ENG WAS GROUND RUN AND LEAKED CHECKED OK. OIL SUMP SCREEN WERE CHECKED FOR CONTAMINATION. NONE FOUND. CHECKED MAG TO AND SERVICED WITH 8 QTS OF AEROSHELL W100 AND A NEW AA48110-2 FILTER. OLD FILTER AND

INJECTION LINES INSPECTION IAW LYCOMING S/B 342F. NO DEFECTS NOTED AT THIS TIME. NEXT

INSPECTION DUE IN 100 HRS OR NEXT ANNUAL WHICHEVER COMES FIRST

Engine Entries

MAKE: MOONEY MODEL: M20F S/N: 22-0073 REG. NO: 7164V WORK ORDER: 19895-04-2023 Airframe Entries

Upland, CA 91786 Phone: 909-985-1977

Repair Station No. AJ4R052M 1749 W 13Th St Foothill Aircraft Sales & Service, Inc.

DATE: 6/2/2023 A/C TSN: 3845.46 TACH: 3845.46

(9) RE-SECURE LOOSE WIRE ON RH STROBE LIGHT. OPS CHECKED GOOD.... (11) REPLACED ADF REAR ATTACH CABLE HARDWARE.... (12) INSTALLED ELECTRONICS INTERNATIONAL INC PRIMARY EGT/CHT INSTRUMENT P/N EC-1P S/N 288508 AND ASSOCIATED ACCESSORIES IAW ELECTRONICS INTERNATIONAL INC STC SA3862NM DATED APRIL 25, 1988, USING INSTALLATION INSTRUCTIONS No 110361 REV A AND II 111361. NO CHANGE IN WEIGHT AND BALANCE. SEE ATTACHED 337 FORM 06/2023. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-6305.... (6) C/W AD 76-07-12R1 BENDIX IGNITION SWITCHES BY OPERATIONAL CHECK IAW BENDIX S/B 583. NO DEFECTS NOTED AT THIS TIME. NEXT INSPECTION DUE IN 100 HRS.... (7) C/W AD 73-21-01 TO PREVENT CORROSION AND/OR MISRIGGING IN THE FLIGHT CONTROL AND LANDING GEAR SYSTEMS BY LUBRICATION.... (8) REPLACE LH AND RH FUEL CAP O-RINGS WITH P/N MS29513-338 AND MS29513-010 (QTY 2 ea)... (1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING MOONEY M20F M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE DEC 2024. ADS CHECKED THROUGH FOR DETAILS.

1 of 2

ENGINE MODEL: IO-360-A1A ENGINE S/N: L-13138-51A REG. NO: 7164V WORK ORDER: 19895-04-2023

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977

Foothill Aircraft Sales & Service, Inc.

DATE: 6/2/2023 A/C TSN: 3845.46 ENG TT: 458.83 TSMOH: 458.83 TACH: 3845.46

I certify that the Engine and/or component(s) on 7164V was repaired and inspected in accordance with a Annual/100HR. Inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No.

5168

9895-04-2023, Dated 6/2/2023.

Maintenance Release

DATE: 6/2/2023

Certified Repair Station No. AJ4R052M Adrian Arias

of 1

Work Order: 19895-04-2023

Printed by EBis 3 (datcomedia.com)



Maintenance Release
Loertify that the aircraft and/or component(s) on 7164V was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19895-04-2023, Dated 6/2/2023. DATE: 6/2/2023 Certified Repair Station No. AJ4R052M Adrian Arias SIGNED: 2 of 2 Printed by EBis 3 (datcomedia.com) Work Order: 19895-04-2023

PROP MODEL: HC-C2YK-1BF PROP S/N: CH32232A REG. NO: 7164V WORK ORDER: 19895-04-2023

Prop Entries

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977

Foothill Aircraft Sales & Service, Inc.

DATE: 6/2/2023 A/C TSN: 3845.46 PROP TT: 310.23 TSPOH: 310.23 TACH: 3845.46

Work Order: 19895-04-2023

Printed by EBis 3 (datcomedia.com)

DATE: 6/2/2023

SIGNED:

Certified Repair Station No. AJ4R052M

Maintenance Release
Icertify that the PROPELLER on 7164V was inspected in accordance with an 100hr./Annual inspection per the manufactoures
maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service.
Pertinent details of the repair are on file at this repair station under Work Order No. 19895-04-2023, Dated 6/2/2023.

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING MOONEY M20F M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED 06-2023.

1 of 1