



Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Summary](#)
[Prior Page](#)

N Number: 58TF

Last Action Date	2023-05-17		
Airworthiness Date	1980-06-16	Expiration Date	2030-05-31
Manufacturer_Name	BEECH	Model Name	58P
Registrant Name	KEITH ROBERT	Street	701 W LIVE OAK ST
Registrant City	AUSTIN	Registrant State	TX
Registrant Zip Code	787045007	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2023-05-17
Status	N-Number Assigned and Registered		
Serial Number	TJ-292	Aircraft Type	Fixed wing multi engine
Mode S Code	51672476	Year Mfr	1980
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	123
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer	CONT MOTOR		
Engine Model Name	TSIO-520 SER	Engine Type	Reciprocating
Engine Horsepower/Thrust	0	Fuel Consumed	0.00

----- History 1 -----

Last Action Date	2022-10-20		
Registrant Name	REGISTRATION PENDING	Street	1100 N GRAHAM ST STE A
Registrant City	CHARLOTTE	Registrant State	NC

Registrant Zip Code	282063045	Country	UNITED STATES
Region	Eastern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	
Status	Registration pending		
----- History 2 -----			
Last Action Date	2021-08-13		
Registrant Name	IVESTER DRYWALL & PAINTING INC	Street	201 FAIRSON AVE
Registrant City	SALISBURY	Registrant State	NC
Registrant Zip Code	281442521	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2021-08-13
Status	N-Number Assigned and Registered		

----- History 3 -----			
Last Action Date	2020-08-27		
Registrant Name	H & D AVIATION LC	Street	PO BOX 448
Registrant City	GREENVILLE	Registrant State	NC
Registrant Zip Code	278350448	Country	UNITED STATES
Region	Eastern	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2005-08-04
Status	N-Number Assigned and Registered		

----- History 4 -----			
Last Action Date	2017-08-09		
Registrant Name	H & D AVIATION LC	Street	PO BOX 448
Registrant City	GREENVILLE	Registrant State	NC
Registrant Zip Code	278350448	Country	UNITED STATES
Region	Eastern	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2005-08-04
Status	First Notice for Registration Renewal		

----- History 5 -----	
Last Action Date	2014-11-20

Registrant Name	H & D AVIATION LC	Street	PO BOX 448
Registrant City	GREENVILLE	Registrant State	NC
Registrant Zip Code	278350448	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2005-08-04
Status	First Notice for Registration Renewal		

----- History 6 -----

Last Action Date	2012-01-19		
Registrant Name	H & D AVIATION LC	Street	PO BOX 648
Registrant City	GREENVILLE	Registrant State	NC
Registrant Zip Code	278350648	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2005-08-04
Status	First Notice for Registration Renewal		

----- History 7 -----

Last Action Date	2008-11-19		
Registrant Name	H & D AVIATION LC	Street	PO BOX 648
Registrant City	GREENVILLE	Registrant State	NC
Registrant Zip Code	27835-0648	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2005-08-04
Status	First Notice for Re- Registration/Renewal		

----- History 8 -----

Last Action Date	2008-08-19		
Registrant Name	H & D AVIATION LC	Street	7610 US HIGHWAY 41 N
Registrant City	PALMETTO	Registrant State	FL
Registrant Zip Code	34221-9611	Country	UNITED STATES
Region	Southern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2005-08-04
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 9 -----

Last Action Date	2005-08-04		
Registrant Name	H & D AVIATION LC	Street	7610 US HIGHWAY 41 N
Registrant City	PALMETTO	Registrant State	FL
Registrant Zip Code	34221-9611	Country	UNITED STATES
Region	Southern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2005-08-04
Status	N-Number Assigned and Registered		

----- History 10 -----

Last Action Date	2004-03-01		
Registrant Name	PROCTOR DANNY	Street	#1 KNOTTY PINE PL
Registrant City	TEXARKANA	Registrant State	TX
Registrant Zip Code	75503	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2004-03-01
Status	N-Number Assigned and Registered		

----- History 11 -----

Last Action Date	2003-08-11		
Registrant Name	REGISTRATION PENDING	Street	PO BOX 1231
Registrant City	BIG SPRING	Registrant State	TX
Registrant Zip Code	79721-1231	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	
Status	Registration pending		

----- History 12 -----

Last Action Date	2000-10-17		
Registrant Name	PRICE CONSTRUCTION INC	Street	PO BOX 1231
Registrant City	BIG SPRING	Registrant State	TX
Registrant Zip Code	79721-1231	Country	UNITED STATES

Region	Southwestern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1994-05-12
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

----- FAA Accident/Incident 1 -----

Occurrence Date	1988-06-09	Aircraft Make	BEECH
Aircraft Model	58P	Damage	
Document Last Modified	2012-08-08		
Narrative	CLEARED TO LAND AND TOLD TO HOLD SHORT OF RUNWAY 22 DUE TO A DEPARTING B737. LOCKED BRAKES AND SKIDDED OFF RUNWAY.		

***** No NTBS Accidents Found *****

***** No NTBS Pre 1982 Accidents Found *****

----- SDR 1 -----

Date Of Report	1990-01-09	Operator Control Number	SW179071234
Date Of Occurrence	1989-12-14	Aircraft Registration	58TF
Aircraft Manufacturer	BEECH	Aircraft Group Code	58
Aircraft Manufacturer Model	58P	Aircraft Make Model Sequence	1152744
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type	G	Stage Of Operation	INSP/MAINT
Severity Factor	FREQUENT	Air Transport Association Code	Reciprocating Engine Cylinder Section
Precautionary Procedures	NONE	Nature Of Condition	OTHER
Segment	ENGINE	Descriptive Name Of Part	VALVE SPRING
Defective Location On Aircraft	NR 5 CYL EXH	Failed Part Condition	BROKEN
Part Total Time	0	Part Total Time Since Overhaul	1,229
Component Manufacturer		Component Manufacturer Model	
Component Manufacturer Number		Manufacturer Part Number	637837
Ata Code			
Remarks	LOW OIL PRESSURE RIGHT ENGINE. FOUND METAL IN OIL FILTER AND OIL PRESSURE RELIEF HOUSING. FOUND BROKEN VALVE SPRING, NR 5 CYLINDER EXHAUST. DRAINED SUMP		

THROUGH SCREEN WITH MAGNET, FOUND NO OTHER METAL. REPLACED BROKEN VALVE SPRING. INSPECTED OIL PUMP FOR DAMAGE, SLIGHT SCORING, POLISHED PUMP HOUSING, REASSEMBLED AND RETURNED TO SERVICE. RUNUP CHECK OK. INSPECTED OIL FILTER, NO MORE METAL FOUND. SUBMITTER RECOMMENDS 10 HOURS OF FLYING AND REINSPECT AS PER TCM TECH REP RECOMMENDATION.

[Custom Reports](#)

Copyright 2001 - 2024 AviationDB.com Corp. All Rights Reserved

[Legal](#)[Contact Us](#)