-			
7	1	THE .	
- 2		1	
ι,	7	ľ	
- 1	- 7	1	

Pegasus Aviation Service, LLC 5725 SW Plumley St. Corvallis, OR 97333

No.

Date: 02/07/2023

Total Time: __3190.2 ___ Tach Time _3190.2 ___ N#_N9637Q _ Serial#_17265721

On this date a 100 hour inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspection IAW FAR 91.207b was found satisfactory. ELT Battery replacement date is 05/2027. AD 11-10-09 Seats and seat rails inspection IAW AD Instructions 1-9. Removed all inspection panel, seats, interior and where needed. Lubricated all applicable rigging, controls, and flight control surface components IAW CSM lubrication chart. Reinstalled all inspection covers, upholstery and seats. Serviced main and nose wheel bearings with Mobil SHC100. Installed Peterson Aviation STC SA2601CE, placarded on cockpit panel and at both wing fuel fill ports. Pitch trim resecured, Installed Garmin G5 update 8.17 correcting Garmin pitch trim SB and updated IGRF Ops check and ground run is satisfactory at this time.

I certify that this Airframe has been inspected IAW an 100 Hour Inspection IAW FAR 43 appendix D as applicable and has been determined to be in airworthy condition at the time.

Signed:

A&P3055561



Pegasus Aviation Service, LLC 5725 SW Plumley St. Corvallis, OR 97333

Date: 04/18/2023

Total Time: 3287.9

Tach/Hobbs Time 3287.9 N9637Q

Serial# 17265721

On this date a 100 hour inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected and tested IAW FAR 91-207b and was found satisfactory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails patched were needed. Lubricated all rigging of pulleys, controls hinges and rigging IAW CSM lubrication chart. Reinstalled all inspection covers, upholstery and seats. Serviced Shimmy dampener, and blead brakes. Ops check and ground run satisfactory. I certify that this Aircraft has been inspected IAW an 100 Hour Inspection IAW FAR 43 appendix D as applicable and has been determined to be in airworthy condition at the time.

Signed:

A&P3055561



Pegasus Aviation Service, LLC 5725 SW Plumley St. Corvallis, OR 97333

Date: 06/05/2023

Total Time: 3368.0

Tach/Hobbs Time 3368.0 N9637Q

Serial# 17265721

On this date a 100 hour inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected and tested IAW FAR 91-207b and was found satisfactory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails patched were needed. Lubricated all rigging of pulleys, controls hinges and rigging IAW CSM lubrication chart. Reinstalled all inspection covers, upholstery and seats. Serviced Shimmy dampener, and blead brakes. Ops check and ground run satisfactory. I determined to be in airworthy condition at the time.

Signed:

A&P3055561

TOTAL—Carry forward to next page

TOTAL	TAGULOR		
1	TACH OR		
· ·		A STATE OF THE STA	707
	TOTAL Brought few		
2			
	Persons Avietica		
	regasus Aviation Se	ervice, LLC 5725 SW Plumley St. Corvallis, OR 97333	
Date: 07/10/2023		3327000	
Total Time: 3445.	7 Tach/Hobbs Time 3445		
	1 mic 3443		
On this date a 100	hour inspection was performe	ed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected	
inspection IAW ins	AR 91-207b and was found sa	ed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected atisfactory. ELT replacement date is May 31 st 2027. AD 11-10-09 Seats and seat rai inspected panels seats and interior were needed, found for unbelocated.	i
natched were need	ad I	inspected panels seats and interior were needed for AD 11-10-09 Seats and seat rai	ls
inspection covers, t	upholstery and seats. Replace	inspected panels seats and interior were needed, found torn upholstery, repaired and pulleys, controls hinges and rigging IAW CSM lubrication chart. Reinstalled all ed right main tire with Condor 6.00-6 and tube Apr. Cleanic CO.	
2	been determined to be in airw	worthy condition at the time.	
Signed:			
A&P3055561			
1 101 3033301			
94			
AND ASSESSMENT OF THE PARTY OF		_	
238			
238	Pegasus Aviation Serv	vice. LLC 5725 CW D	
Date: 08/13/2023	Pegasus Aviation Serv	rice, LLC 5725 SW Plumley St. Corvallis, OR 97333	
	Pegasus Aviation Serv	rice, LLC 5725 SW Plumley St. Corvallis, OR 97333	
Date: 08/13/2023 Total Time: 3544.9			
Total Time: 3544.9	Tach/Hobbs Time 3544.9	N9637Q Serial# 17265721	
Total Time: 3544.9 On this date a 100 hou and tested LAW FAR 0	Tach/Hobbs Time 3544.9	N9637Q Serial# 17265721	
Total Time: 3544.9 On this date a 100 hou and tested IAW FAR 9 inspection IAW in a second control of the seco	Tach/Hobbs Time 3544.9 r inspection was performed I/1-207b and was found satisfa	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT income actory. FLT replacements	
Total Time: 3544.9 On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction in the state of th	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
Total Time: 3544.9 On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction in the state of th	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
Total Time: 3544.9 On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction in the state of th	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed inspection covers, uphe ground run satisfactory, applicable and has been	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails elected panels seats and interior were needed, found torn upholstery, repaired and ght main tire with Conders 60s. CSM lubrication chart. Reinstalled all	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
Total Time: 3544.9 On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction in the state of th	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed, inspection covers, uphor ground run satisfactory, applicable and has been signed:	Tach/Hobbs Time 3544,9 r inspection was performed 1/ 11-207b and was found satisfa tions 1-9. Removed and inspe Lubricated all rigging of pull	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	
On this date a 100 hou and tested IAW FAR 9 inspection IAW instruction patched were needed. inspection covers, uphe ground run satisfactory, applicable and has been Signed: A&P3055561	Tach/Hobbs Time 3544.9 r inspection was performed I/1-207b and was found satisfations 1-9. Removed and insp. Lubricated all rigging of pull. Instead of pull. It certify that this Aircraft had determined to be in airworth	N9637Q Serial# 17265721 AW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected actory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails exected panels seats and interior were needed, found form upholstery.	

N9637Q

Signed: A&P3055561

SUB-TOTAL this page

TOTAL—Carry forward to next page

On this date a 100 hour inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected and tested IAW FAR 91-207b and was found satisfactory. ELT replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails inspection IAW instructions 1-9. Removed and inspected panels seats and interior were needed. Lubricated all rigging of pulleys, controls hinges and rigging IAW CSM lubrication chart. Reinstalled all inspection covers, upholstery and seats. Replaced right main inspected IAW a 100 Hour Inspection IAW FAR 43 appendix D as applicable and has been determined to be in airworthy condition at

Serial# 17265721

Total AC Hours: 3770.9



Pegasus Aviation Service, LLC 5725 SW Plumley St. Corvallis, OR 97333

Date: 11/08/2023

Total Time: 3770.9

Tach/Hobbs Time 3770.9

N9637Q

Serial# 17265721

On this date an Annual Inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual as a guide. ELT inspected and tested IAW FAR 91-207b and was found satisfactory. ELT replacement date is May 318 2027. AD 11-10-09 Seats and seat rails inspection IAW instructions I-9. Removed and inspected panels seats and interior were needed. Lubricated all rigging of pulleys, controls hinges and rigging IAW CSM lubrication chart. Reinstalled all inspection covers, upholstery and seats. Ops check and ground run satisfactory. I certify that this <u>Aircraft</u> has been inspected IAW an <u>Annual Inspection</u> IAW FAR 43 appendix D as applicable and has been determined to be in airworthy condition at the time.

Signed:

A&P3055561IA

Recurring ADs 11/08/2023 Airworthiness Directives: Compliance Report - Airframe

N-No.: N9637Q Make: Cessna Aircraft Co. (Textron 17265721 Serial: Aviation)

Model: 172M

Seat rail & seat rail holes; seat pin; seat rollers, etc.		Kevin Hester AP3055561			
AD 2011-10-09	Amdt. 39-16690	Issued: 05/13/11	Effective: 06/17/11	Recurring: Yes	Supersedes: 87-20-03 R2
Cracks in nose gear f	ork		Kevin Hester AP3055		
AD 71-22-02	Amdt. 39-1327	Issued: 1971	Effective: 11/09/71	Recurring: Yes	Supersedes.
Muffler assembly			Kevin Hester AP3055		Supersedes:
AD 69-15-03	Amdt. 39-798	Issued: 1969	Effective: 08/20/69	Recurring: Yes	Supersedes:
Stall warning system			Kevin Hester AP3055		Curemeden
AD 68-17-04	Amdt. 39-650	Issued: 1968	Effective: 09/07/68	Recurring: Yes	Supersedes:

Number of ADs: 4



N9637Q Tach: 3730.1 ACTT: 3730.1 SN:17265721 10/15/2023

On this date a 100 HR inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual or (CSM) D9072-4-13 Section 2 as a guide. Complied with Bi Weekly AD search. AD 11-10-09 seats and seat rails inspection IAW AD Instructions 1-9. ELT inspection IAW FAR 91.207 (d) no discrepancies. ELT Battery Replacement date is 05/2027. Removed inspection panels, seats, interior and applicable upholstery. Lubricated; rigging, controls, and flight control surface components IAW CSM Lubrication Chart. Reinstalled all inspection covers, upholstery and seats. Ops check and ground run is satisfactory at this time. With respect to the work performed, I certify this AIRCRAFT Has been inspected IAW 100HR inspection and was determined to be in Airworthy condition and approved for return to service.

OCT 14, 2023.

Zachary Maurice, AP4028825

SUB-TOTAL this page

TOTAL-Carry forward to next page

Page	No	

DATE

TOTAL TIME IN SERVICE TACH OR RECORDING METER TIME

DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK



Pegasus Aviation Service, LLC 5725 SW Plumley St. Corvallis, OR 97333

Date: 02/06/2024

Total Time: 3815.9

Tach/Hobbs Time 3815.9

N9637Q

Serial# 17265721

On this date an Annual Inspection was performed IAW FAR 43 Appendix D and Cessna Service Manual (CSM) as a guide. ELT inspected and tested IAW FAR 97-207b and was found satisfactory. ELT battery replacement date is May 31st 2027. AD 11-10-09 Seats and seat rails inspected IAW instructions 1-9. AD report attached to this log entry. Replaced left main tire, replaced all main brake lining with new 66-105, riveted and installed. Replaced missing screws in panels. Removed inspection panels and interior were needed and inspected aeras for corrosion and derbies, lubricated all rigging of pulleys control hinges and rigging IAW CSM lubrication chart. Reinstalled all inspection covers, upholstery and seats. Ops check and ground run found satisfactory. I certify that this Aircraft has been inspected IAW an Annual Inspection IAW FAR 43 appendix D as applicable and has been determined to be in airworthy condition at the time.

Cessna 172M N9637Q SN 17265721

			17265721		II AC Hours: 3815.9
AD 68-17-04	Amdt. 39-650	Issued: 1968	Effective: 09/07/68	Recurring: Yes	Supersedes:
Stall warning system			Kevin Hester AP305		Supersedes:
AD 69-15-03	Amdt. 39-798	Issued: 1969	Effective: 08/20/69	Recurring: Yes	0
Muffler assembly			Kevin Hester AP3058		Supersedes:
				ja	
AD 71-22-02	Amdt. 39-1327	Issued: 1971	Effective: 11/09/71	Recurring: Yes	Supersedes:
Cracks in nose gear fork		Kevin Hester AP3055561			
AD 76-04-03	Amdt. 39-2519	Issued: 1976	Effective: 02/26/76	Recurring: Yes	Supersedes:
ARC PA-500A actuators			Kevin Hester AP3055		oupoiscues.
AD 87-20-03 R2	Amdt. 39-6669	Issued: 1987	Effective: 09/24/90	Recurring: Yes	Cumanada
Superseded by 2011-10-09		Kevin Hester AP3055561 Supersedes:			
AD 2011-10-09	Amdt. 39-16690	Issued: 05/13/11	Effective: 06/17/11	Recurring: Yes	Supersedes: 87-20-03 R2
Seat rail & seat rail holes; seat pin; seat rollers, etc.		Kevin Hester AP3055	561	-	

SUB-TOTAL this page

TOTAL—Carry forward to next page