



ASA-SA-2

Registered Own	er Record			Notes
Name		Address		
City	State	From	То	
Name	****	Address		
City	State	From	То	
Name		Address		
City	State	From	То	Log Book #4
Name		Address		
City	State	From	To	opened 12-3-01 at 4010. hrs Total Time
Name		Address		- (# # 12
City	State	From	То	
Name		Address		
City	State	From	То	
Name		Address		
City	State	From	To	
Name		Address		
City	State	From	To	

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Nan	Tests, Repairs and Alterations ne, Rating and Certificate Number of back pages for other specific entries.)
2-3:01	4010.°		40/0.0	Removed oft fresh air blower attembly s/N 311B. Installed New blower KIT S/N 313.0ps	12:5:0	4014.3		404.3	Das Checked all I	ion # 7 of Beachciass poction Guid 7/N98349111 ghts. Serviced battery
				Checked good. MAINTENANCE RELEASE					Tirel and brake is induction are fitter a sumps.	and drained that
-				was repaired and inspected in accordance with the Faderal Aviation Regulations and is approved for return to service with respect to the work performed. Perforent details of the repair are on ble at this repair station. Work Order No. 10416			DET	ected II	ACCORDANCE WITH A INSPECTION AND HAS BEEN BE IN AIRWORTHY CONDITION. 1042	MAINTENANCE RELEASE The abcust and/or component identified above was repaired and inspected in accordance with the Federal Aviation Regulations and is approved for return to service with respect to the work performer. Performer details of the repair are on file at this repair station.
				Signed Authorized Individual Signature of Authorized Individual Authorized Authorized Individual Authorized Authorized Individual Suprise Authorized Autho			SIGN	HEON AIRCRAF	TOTAL TIME 40/4. 3 HOURS T SERVICES-REPAIR STATION YWBR797L TO Drive Bakersfield, CA 93308	Work Order No. 1042 Date 12-5-0/ Signed 14-0-15-0 individual Signatural of Authoritied individual RAYTHER ANT SERVICES No. WARRYIN, 1450 Boughton Drive, Bakerstrickt, CA. 93308

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must	on of Inspections, Tests, Repairs and Alterations t be endorsed with Name, Rating and Certificate Number of or Repair Facility. (See back pages for other specific entries.)
DATE			***********		
2-12-01	4039.5		4039.5	Completes	INSPECTION "8 OF RESCUCENFT CONTINUING
	BARESWA III JURES		• 100000000	CARE LNS	ESCHON GUIDE AL PE-367110. BPS EXECUTO ALL
		LIGHTS	Service	TIRES BI	TTELY FRENCE RESIVOIR. REPORMED 100 HOUR
785		LUBRO	1718× LA	VOING GEAR	OPERATION CHECKED NORMAL AND MANUEL
		SYSTER	15 INSOE	TED TAIL !	SECTION ELEVATOR + RUDACE. PERSONED FUEL
		Secen	L VALUE	WSPECTION.	C/W S.B. \$ 2693 DOOL HANDLE INSPECTION
					TEST OF BENOIX SWITCH , INSTALLED NEW
					IN UP AND TAKE CHECK GOOD.
				- 3	MAINTENANCE RELEASE
		1			
ICER	CTED IN	HIRFA	Charlet	WITH A	the skorart and inspected in accordance was repaired and inspected in accordance with the Foderal Aviation Regulations and the approved for return to service with respect
M	RMINED TO B	E IN AUGT.	DINGS PERSON	TION.	to the work performed. Perforent details of the repair are on file at this requir station.
	ORDER NO				Work Order No. 1027
DATE	12-12-01	TOTAL	ME4039.5	HOURS	Second (1) (Quality
SIGN	D N. CAL	1/6	DEDAID STATIO	VW00797	Signature of Authorized Individual Saytheom Arcraft Services No. YMERWIT.
RAYT	EON AIRCRAF	SERVICES	REPAIR STATIO	GASUS	1400 Boughton Orive Bakerstakt, CA 90308

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Na	, Tests, Repairs and Alterations ime, Rating and Certificate Number of a back pages for other specific entries.)
DATE			1	N N N N N N N N N N N N N N N N N N N	
20-01	4063.2		4063.2	Completed Inspect	ton 49 of Beacherast spection Guide PA98-3111
			.0	Continuina Care In	section Guide PA98-3671
				On Check of all 1.	ght Serviced hattery
				Tires and brake re.	
		ealistore.	-		VC. DOMESTIC STREET, CO. C.
	-			induction air filte	r and arained trust
				Sumpl	PARTICIPATE OF THE PROPERTY OF THE PARTY OF
					MAINTENANCE RELEASE
				S Aircraft HAS BEEN	The eineralt and/or component identified above was repaired and inspected in accordance
No.		INSE	ECTED/OIN		with the Federal Aviation Regulations and
		DETE	RMINED TO B	INSPECTION AND HAS BEEN	is approved for return to service with respect to the work performed. Pertinent details of the
ener :		1000	CORDER NO.	10474	repair are on tile at this repair station Work Order No. 10474
		DATE	0/2-20-0	TOTALTIME 4063.2 HOURS	Date 1/2-29-9/
BCC.			o Du		some Dur D Haut
(E) (E)	1			SERVICES REPAIR STATION YWBR797L	Signature of Authorized Individual
				Drive Bakersfield, CA 93306	RAYTHEON ARTCRAFT SERVICES No. WIDITATA. 1450 Bouchton Drive Bakarsfield, CA 93308
6					
		_	-	- 11	
					300
ATTACA CO.					

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Nan	Tests, Repairs and Alterations ne, Rating and Certificate Number of back pages for other specific entries.)
DATE				110 50.5	n/
-8-02	4097.9		4087.9	Completed Inspection	on #10 of Beechcraft
			7.0000000-3.00-4	Continuing Care In	spection Guido P/N983671
			Ops Che		ELT. Due Jan 2002.
			Setin	Armposition Service	ed battery, Tirey and
				eservoir. Inspected w	
				m. Replaced fuel C	V . / U.
	CH.		-1	1 1	Efor Cordition and
- 3////				tion. Run-up God To	0 1
3.0			1	1	
	7.00 CM		TIFYTHATTH	ACCORDANCE WITH A	MAINTENANCE RELEASE The alreadt and/or component identified above
		7	ECTEN/O	INSPECTION AND HAS BEEN	was repaired and inspected in accordance with the Federal Aviation Regulations and
		WOS	K ORDER NO.	10.5.39	is approved for return to service with respect to the work performed. Perfinent details of the
			D1-9-02	TOTALTIME 4097.9 HOURS	Work Order No
-		SIGH	ED Alyn	Detect	Date 8-02/
		RAY	HEON AIRCRAF 1450 Boughto	T SERVICES-REPAIR STATION YWBR797L In Drive Bakersfield, CA 93306	Signatus of Authopied Individual RAYTHEON AFRICRAFT SERVICES No. YWERTEN

YEAR:	RECO TACH TIME		TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE			1		15 TV 189/58 14 W
17-02	411	13.5		4113.5	
		热	<u> </u>		Continuing Care Inspection Guide PN98-X711.
		7 m = 3			Tes Checkler all light Replaced ELT Battery.
					Performed yearly inspection and functional check
FER		797			per MG instructions, Set in Arm position, New Day
SMITT		WBF		9	Date Feb 2004. Serviced betters Tirel and
ANS	1	188		e years	brake reservoir. Cleaned induction air filter
E S	20	る意			and drained feed samps.
ATOR	8	歌			MAINTENANCE RELEA
A Sept	-	Q 3			THAT THIS HIT COOL HAS BEEN The aircraft and/or component identified.
128	13	→	100000	INSPECT	INSPECTION AND HAS BEEN with the Federal Aviation Hegulation
50	-	53	-	DETERM	INED TO BE IN AIRWORTHY CONDITION. Is approved for return to service with re-
E Z		》是	I = J	WORKOR	RDER NO. 10565 repair ere on file at this repair station.
MERGEN		BRAYTHE		DATED_	17-02 TOTAL TIME 4/13.5 HOURS Date 1-17-02
E 8	S	있요		SIGNED_	Sup P. Heat signed New D. Feet
					AIRCRAFT SERVICES-REPAIR STATION YWBR7971. Signature of Authorized Individual Boughton Drive Bakersfield, CA 93308 RAYTHEON ARCRAFT SERVICES-No. WE

4		27				140	- 4	. autori	- A Banaire and Alterations
YEAR:	RECORDING	TODAYS	TOTAL	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Entries must be endorsed with Name, Rating and Certificate Number of	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
TEAL.	TACH	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Hating and Celumbur. Technician or Repair Facility. (See back pages for other specific entries.)	DATE				1117 at #1 1 Beedicialt
	TIME	0			2-1-02	41625		41625	Completed Inspection # of Beecheraft
DATE		-	wool	Completed Inspection #12 of Beach craft	2700	1180			of Talling (Ase bisection quite in
1-24-02	4138.	-	4/38.	Confleted Inspection Guide P/N98.36711D	1	-	1		la Al N / - II Fabr Serviced Daniely
				Continuing care they al books reservoir.	Ē	-	-	-	Tires and brake reservoir. Cleaned
	Das Che	sked at	& habite.	Serviced battery Tires and brake reservoir.			-	+	induction air filter and drained fuel
	of face	boh	Mulrica	Serviced battery, res and bearings Repland right The Reported all wheel bearings Repland right The Reported and wheel bearings Repland right	į.		-		
	PICICIA	D.	farmel 1	anding gear inspection and rigging. Landing					Sumps. MAINTENANCE RELEASE
	main li	12.121	DI 1. 0	wormed and married systems. Performed Cabin resembled central Cable Tensions, Replaced Pilots Co-pilots				- THAT I	The aircraft and or component of the aircraft
	gear of	eretion	checken	Checker Central Cable Tensions, Replaced Pilots Co-pilots Checker Central Cable Tensions, Replaced Pilots Co-pilots Cable Tensions of Cabin Leater			INS	PECTED!	IN ACCORDANCE WITH A wish-the Federal Aviation Frequencies with respect
	inTerie	1125	of crion	Cabin Leafer		+	T.	TERMINED TO	RE OU APPROPRIATE CONSTITUTION
	Center	Seat TI	ocks. 4	W BSL 0320 11 - 71 Ph. L C/WAD 97-14-15		-		ODDED N	10647 way order No. JUST
	muffle	C/ C/4	AD 76-0	Andles per S/B2693. Run-up and Taxi Check MAINTENANCE RELEASE MAINTENANCE RELEASE MAINTENANCE RELEASE MAINTENANCE RELEASE MAINTENANCE RELEASE MAINTENANCE RELEASE	1	-	DA	TEh 2-1-0	TOTAL TIME 4/62 HOURS Date
	in some Co	fel Cal	bin door	Andles per S/B2693. KONTENANCE RELEASE		-			the State of the s
	1	1	1 2 3				RA	YTHEON AIRCR	AT SERVICES-REPAIR STATION YWERTOTI. AT SERVICES-REPAIR STATION YWERTOTI. BAYTHEON ARCCAST SERVICES-No. TWESTON. 1450 Boughton Drive Bakersfield, CA 93308
	good	1 ICE	THEYTHATTH	MAS BEEN N ACCORDANCE WITH A Was repeired and inspected in accordance with the Federal Aviation Regulations and with the Federal Aviation Regulations and with the Federal Aviation Regulations and with the Federal Aviation Regulations of the				450 8009	
		1	W #12	the work continued. Personal continued in the work continued in th	-	1		37	
		DET	ERMINED TO	10578 ropair are on tall 10578		-			
		Wol	TE 1-24-0	2 TOTAL TIME 4/38. HOURS Date Date 1-24-02	<u> 4 — </u>	-	-	+	
		30,000	200	. I I Salar I I I I I I I I I I I I I I I I I I I	111				
		RAY		FT SERVICES-REPAIR STATION YWBR7ETL Signature of Authorized Howards Signature of Authorized Howar					THE THE PARTY OF T

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE	5	-	111005	Completed Inspection #2 of Beechcraft	2-14-02	4193.6		41921	Pare Pull War Tin Sames Late States
2-12-02	4189.5		4/89.5	Continuing Care Inspection Guid PN982711D ched all lights and ELT. Due Feb 2004.	9.7402	77.70.20		11116	Removes Right Wing Tip Stroke Light 5/N 849! And installed Stroke Light S/N 9238. Gerntional Check Good.
-			ā /	Continuing care Inspection Guide 1/1/3301110	§ ' ——			-	And installed STROKE LIFE SIN 4238.
			Ops Ch	cked all fights and ELI. Due Feb 2004.	-		1-		Gerntional Check Good.
			Setin	Arm position. Serviced patiery, lives and	<u> </u>		ļ	-	
			brake	reservoir. Cleaned industring air fitter. Performed					MAINTENANCE RELEASE The aircraft audior component identified above
			Sacrah	O che Le of nice alt Systems per inspection					was repaired and inspected in accordance with the Federal Aviation Requisitions and
-			ope and	Replaced instrument air filters on main precuration					is approved for return to service with respect to the work performed. Pertinant details of the
			quiae.	Al 355 5500 Up and Total Cabo bester					moving any on the at this movin station.
			system	C/w BSI 0558-412 pressure Tent of Cabin Leater					Work Order No. 22-04-10150
			Muffler	Checked emergency 4, to for condition and Run-up and The check good.			-		Signed Parts (dance
			Operation	. Kun-up and Thy, Check good.			-		Signature of Authorized Individual BAYTHEON AIRCRAFT SERVICES-No. YWSF797L
				MAINTENANCE RELEASE					1450 Boughton Orive Bakerstield, CA 93308
_			ECTED O	N ACCORDANCE WITH A was repaired and inspected in accordance					
		1	Veto#	INSPECTION AND HAS BEEN IN AIRWORTHY CONDITION. IN the work performed. Perfinent defails of the					
-		and the second	K ORDER NO.	10681 repair are on file at this repair station					
		DAT	02-12-0	2 TOTAL TIME #189.5 HOURS Page 2-12-02					
		SIGN	ED A	land, Heath Some Dun Heath			_		
100	27/10	RAY	HEON AIRCRAI	FY SERVICES REPAIR STATION YWERTET. Signature of Authorized Individual		L			
			1450 Bought	on Drive Bakersfield, CA 93308 RAYTHEON AIRCRAFT SERVICES4le, YMER/97/L 1450 Boughton Drive Bakersfield, CA 93308					

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Nar	, Tests, Repairs and Alterations me, Rating and Certificate Number of back pages for other specific entries.)
DATE	100				
2-26-02	4214.2		4214.2	Completed Inspect	
	000000000000000000000000000000000000000			Continuing Care Ins	pection Guide PN98-36711D
	1000			Das checked all light	
7				Tires and brake res	
				eir filter and dra	
	- 17		_	TIT FILLS CON CITE	arek the surges
1			TIFY THAT TH	S Aircraft HAS BEEN	MAINTENANCE RELEASE
1		0.0000000000000000000000000000000000000	ECTED IN	ACCORDANCE WITH A	The aircraft and/or component identified above was repaired and inspected in accordance
1000		PK	RMINED TO B	INSPECTION AND HAS BEEN IN AIRWORTHY CONDITION.	with the Federal Aviation Regulations and is approved for return to service with respect
Section 1			CORDER NO.	107/3	to the work performed. Pertinent details of the most are on file at this repair states.
-11-10-10-1				TOTAL TIME 4214.2 HOURS	Work Order No
7000		SIGN	7111	D. Lexts	Date 26-92
1480			BEON AIRCRAF	SERVICES REPAIR STATION YWBRTSTL	Signature of Authorized Index
1960			450 Boughto	n Drive Bakersfield, CA 93308	FORTREDS ARCRAFT SERVICES
350		S. Washington			1.30
1					
1					AND SECULAR SECULAR SECULAR SECULAR SECULAR SECULAR SECULAR SECURITIES SECURI
- 1			100		

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE	1			
3-1-02	4214.2		4214.2	Removed defeative aircraft battery SNG NEW 3937. Instelled New Gill G-242 battery Cleared battery box
B				S/NGO186 3937. Instelled New Gil
				G-242 battery Cleared battery box
				and Terminal ends. Run-up and
				ops Check good
				MAINTENANCE RELEASE
				The aircraft and/or component identified above was repaired and inspected in accordance
		i i		with the Federal Aviation Regulations and is approved for return to service with respect
		0 8		to the work performed. Pertinent details of the repair are on file at this repair station.
experience of the first of the				Date 13-2-07-1
				Signed Myn Attest
				Signature of Authorized Individual RAYTHEON ARCRAFT SERVICES No. YMERTYRIL
12.				1450 Boughton Drive Bultersfield, CA 93308
				THE REPORT OF THE PARTY OF THE
		1711		

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
3-4-02	4216.		4216.2	Removed defective lower oscillating beacon 5/N 6662. Installed repaired beacon ally 5/N 11545. ops Check Good.
				beacon 5/N 6662. Installed repaired
				beacen ally 5/N 11545. One Check
	697577700		-0.000	Cord
				/-
				MAINTENANCE RELEASE The aircraft and/or component identified above
				was repaired and inspected in accordance with the Federal Aviation Regulations and
		1		is approved for return to service with respect to the work performed. Pertinent details of the repair are, on the at this repair station.
				Work Order No. 1076.0
				Signed View Defects
				Signature of Authorized Individual ANTHEON AIRCRAFT SERVICES-No YMBRITA
	14 200			1-50 Boughton Orive Bakersfield, CA 90008
3				42
1				- 14°C
				1940 M 1970 C 19

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
mal 2002	4226.1		4226.1	Removed Loaner encodeing altimater & 2587 and
107.196 1				instaced united Introment overhauled altimeter %
-				26151. Ops and reak checked good.
	MAINTENA			THE STATIC DESCRIPTION AVAILABLE AND AVAILAB
W	e aiscraft and/or o as repaired and i	spected in	accordance	THE STATIC PRESSURE SYSTEM AND THE ALTHUME REPORTING EQUIPMENT WERE INSPECTED AND TESTED
ls ls	th the Federal A	in to service	with respect	I THE DATE AND FOUND TO COMPLY MITH EAD OF 44.
1 to	he work performe pair are on file at t	d. Portinant his repair sta	details of the tion.	HALTSN 6 TESTED TO 35 FEET PHALTSN TESTED TO FEET
	ork Order No. 22	94-10	380	ALTITUDE REPORTING EQUIPMENT SIN 26.151
	-12, MA			DATE 5- 000 200 WORK ORDER # 22-04-10-384
54	Signature of A		vidual	SIGNED RAYTHEON AIRCRAFT SERVICES-REPAIR STATION YWBR797L
	THEON AIRCRAI 50 Bougnton Div	T SERVICES-	io, YWBR797L	1450 BOUGHTON DRIVE, BAKERSFIELD, CA 93308
1				THE ATC TRANSPONDER S/N 16799
				WAS INSPECTED AND TESTED THIS DATE AND FOUND TO COMPLY WITH FAR 91.413
+	-	1	0.1	DATE 12-0-02 2002 WORK ORDER #28-69-1030-0
	10			1450 BOUGHTON DRIVE, BAKERSFIELD, CA 93308

YEAR:	RECORDING TACH TIME	TOBAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Nar	Tests, Repairs and Alterations ne, Rating and Certificate Number of back pages for other specific entries.)
DATE			in the second		DATE	L				
24.02	4289,0		4289.0		5-10-02	43/3.9		4313.9		on #70 Boodcraft
		202		Centinuing Care Inspection Guide 7/1/48-967/1D					Continuing Care Ins	pection Guide PN98-36711
			Das Che	sked all lights and ELT. Due Feb 2004.						ghte. Serviced battery
			Setin	Arm position. Serviced hattery, Tires and					Tires and brake is	/ / /
				reservoir Repacked all wheel bearings.	46				induction air fille	A 100 A
			Perform	el landing gear inspection and rigging.				1000000	sumps.	
				gear operation Checked Normal and manual					1. 14	MAINTENANCE RELEASE
				4. Checked emergency exit for condition and				ECTED -	ACCORDANCE WITH A	The alrerait and/or component identified above was repaired and inspected in accordance with the Federal Aviation Regulations and
			/ /	on. Run-up and Toxi Check good.			P	42 # /	INSPÉCTION AND HAS BEEN E IN AIRWORTHY CONDITION.	is approved for return to service with respect to the work performed. Pertinent details of the
			/	1 11	A STATE OF THE STA		WOR	CORDER NO.	11020	repair are on file at this repair station. Work Order No. //0.20
			RETER/ IN	ACCORDANCE WITH A The extract and/or component identified above		-		4.0	TOTAL TIME 43/3-9 HOURS	Dete 1 5-10-02
-		17	2H296	INSPECTION AND HAS BEEN was repaired and inspected in accordance with the Fedoral Avision Regulations and					SERVICES-REPAIR STATION YWBR717L	Signed Authorized Individual
			CORDER NO.	MOUS Between the result of the	-				n Drive Bakersfield, CA 93308	PAYTHEON ARCRAFT SERVICES No YWERNYA. 1450 Boughton Orive Bakersfield, CA 93308
***			42402	// A = // meneir are on like at this repair station			5- VP 125			THE DOOR OF STREET STREET
				Detects Date 4-2402					Latinize Co.	
				SERVICES-REPAIR STATION YWBR797L Signed Signatury of Autherized Individual			-		<u> </u>	
			contributed the c	GAYTHEON ARCRAFT SERVICESNIA, YWSR787L 1450 Boughton Drive Bakursfield, CA 93308		1				- CONTROL - CONT

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Entries must be endorsed with Nan Technician or Repair Facility. (See	ne, Rating and Certificate Nur	mber of	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Na	, Tests, Repairs and Alterations ime, Rating and Certificate Number of e back pages for other specific entries.)
DATE -/8-Q2	4239.3		4239.3	Completed Inspects Centinuing Care In	on # 4 of Beece section Guid WAS	Lengt.	DATE 4-4-02	4264.6		4264.6	Continuing Care	tion #5 of Beedwaft
	2.12	1050	rubir. F.	formed 100hr lubrices	From Replaced lef	t and					Tires and brake	ht. Serviced buttery, reservoir. Cleaned ir and drained fuel
		SysT	muffles	BSI 0558-412 visus DAY: C/W S/B2693 C	I inspection of Ca abin door hardle in	spection.			ICER	REYTHAY THE	Sumps. Aircraft HASBEEN	MAINTENANCE RELEASE The aircraft and/or component identified above was repeired and inspected in accordance
		Toxa	Check	1	MAINTENANCE REL				DETE	RMINED TO B	INSPECTION AND HAS BEEN EIN AIRWORTHY CONDITION.	water speared and inspected in according to which see Federal Aviation Regulations and is approved for return to service with respect to the work performed. Portivent details of the repair are on file at this repair station.
		INSP	ECTED /	INSPECTION AND HAS BEEN E IN AIRWORTHY CONDITION.	The einstand or component iden was repaired and inspected in an with the Federal Aviation Requi- te approved for return to service was to the work performed. Performed most are on file at this repeir state.	Jool 1			DATE SIGN RAYT	D DE	TOTAL TIME 426 4. HOURS SERVICES REPAIR STATION YWBR797L Drive Bakersfield, CA 93308	Signed Signed Signature of Authorized Individual BAYTHEOM AIRCRAFT SERVICES No. YWSITYPA
		DATE	ED Ale	TOTAL TIME 4239.3 HOURS	Work Order No. 1079 Date 3-1840 Signature of Authoritied Incir	et-				100 0009110		1450 Boughton Drive Bakersfield, CA 93308
		RAYT		SERVICES-REPAIR STATION YWBR7974.	SATTHEON ARCRAFT SERVICES H 1450 Boughton Orive Bakersheld,	r 2/L						

.

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)		RECORDING TACH TIME	TOBAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE /8-02	4387. ⁵	CERT ICEM	Checker from poor Noir. Le flag Checker Textor. IFYTHAT THIS CTER IN MINIED TO BE ORDERNO.	Completed Inspection #10 of Beecheraft Continuing are Inspection Guide 1898-1671 lad lightly and ELT. Due Feb 2004 Se Ition. Serviced pattury, Tires and brake Cleaned induction air filter. Inspected as and ailerand Replaced fuel Cap o-17 ched emergen by etits for Condition and Run-up and Toy; check good. MAINTENANCE RELEASE The aircraft and/or component identified above was repaired and inspected in accordance with the Federal Anaton Regulations and the work performed. Performed details of the maintenance of the trian to service with reapped to the work performed. Performed details of the maintenance of the trian of the service with reapped to the work performed. Performed details of the maintenance of the trian of the service with reapped to the work performed. Performed details of the maintenance of the service with reapped to the work performed. Performed details of the maintenance of the service with reapped to the work performed. Performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed performed details of the maintenance of the service with reapped to the work performed	DETT WOR DATE	44/3.9 TIFY THAT THIS TECTED IN 18 FMINED TO BE KORDER NO.	ACCOP INSP IN AIRWO	44/3.9 DANCE ECTION AND STATE HE	Technician or Repair Facility. (See back pages for other specific entries.) **Complete Tassection*** If of Resculption Continuing Char Tussection Guide Plane 367/10. **Des CHECKED ALL LIGHTS. SEMICED TIRES, BRITTERY, BEALED FULL SUMPS. **CHECKED ALL LIGHTS. SEMICED TIRES, BRITTERY, BEALED FULL SUMPS. **MAINTENANCE RELEASE** **MORRALE AND
		SIGNE	D RUGS	TOTAL TIME 4397.5 HOURS Oate Services-Repair STATION YWBR797L Drive Bakersfield, CA 93308 Services-Repair STATION YWBR797L Signature of Authorized Individual MAYTINGON AIRCRAFT SERVICES-No. INCREME. 1-50 Boughann Only Bakersfield, CA 93308					

						200					
YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with N	s, Tests, Repairs and Alterations ame, Rating and Certificate Number of se back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Nar	Tests, Repairs and Alterations me, Rating and Certificate Number of back pages for other specific entries.)
DATE						DATE					
5-24-02	4340.2		4340.2	Completed Inspectio	n #30 Beech graft	6-5-02	4362.		4362.	Completed Inspec	tion #9 of Beech cutt
		- G		Continuine Care Tiss	ection Guide PN 98-36711D.					Continuing Care In	spection Guil P/ 98-36911D
		Bas ch	edel a	U lights Berviced ba	they, Tires and brake					ops checked all lice	it . Serviced battery
2					cation Landing great					Tires and brake re	
		goera	tion che	ckel wormal sysTem	Inspected Tail section,	*				induction air fitter	
					558-412 visual inspection	£				Sumpl.	
		of Ca	bin Lea	for multiple ally. C/w	3/82693 Cabin door Landle					2 14	MAINTENANCE RELEASE
2					Switch Check C/W AD			INS	ECTED OC	N ACCORDANCE WITH A	The aircraft and/or component learning above was repaired and inspected in accordance
					air fitter. Next Due at		701	PET	CALL OF	INSPECTION AND HAS BEEN BE IN AIRWORTHY CONDITION.	with the Federal Aviation Regulations and is approved for return to service with respect
13	ts ==\\\		-	y and Taxi check go	0	- 100 r			K ORDER NO		to the work performed. Pertinent details of the repair are on file at this repair station.
				1 11- /	MAINTENANCE RELEASE					TOTAL TIME 4362 HOURS	Work Order No
				ACCORDANCE WITH A	Virusecraft and/or component identified above was repaired and inspected in accordance	*		SIGN	ED Sty	1) Heat	Signed My D. Heats
-		7	#e#8"	ACCORDANCE WITH A INSPECTION AND HAS BEEN	with the Federal Avision Regulation 2011 is approved for return to service with 3001		_	RAY	HEON AIRORA	T SERVICES-REPAIR STATION YWBR7971	Signature of Authorized Individual RAYTHEON ARCRAFT SERVICES No. 1998/1998.
		DETE	RMINED TO B	IN AIRWORTHY CONDITION.	to the work performed. Pertinent detail: 10th	36			1400 Bought	on Drive Bakersfield, CA 93308	1450 Boughton Orive Bakersfield, CA 93308
		11/25/30/30/2	ORDER NO.	11043	repair are on tile at this repair station						
-		DATE	5-24-02	TOTAL TIME 4340. HOURS	Work Order No. 1/04/		-				
		SIGNE	D. Deep	2 X/cots	Signed Man Ment	-	-				
	reunius			SERVICES-REPAIR STATION YWER797L	Signature of Authorized Individual	4	3.				
			450 Boughton	Drive Bakersfield, CA 93308	1450 Boughton Orive Bakersfeld, CA 64568						

YEAR:	RECORDING TACK TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Nan	Tests, Repairs and Alteration ne, Rating and Certificate Number of back pages for other specific entries	io.
DATE						_
3.6.02	4464.1		4464.	Completed Tropect	on #1 of Beech craf	1
			**************************************	Continuine Care In	spection Guido / N9836	7
				Das Cheled all lice	cht. Serviced batte	1
				tical well bake to	sorvoir. Cleanel	/
					ter and drained fu	
		-			an oracina	-
		2		Sumps.	MAINTENANCE RELEASE	
		ICE	TIEY THAT TH	S Air Creft HAS BEEN	The aircraft ancifor component identification about	**
			ECTED d IN	ACCORDANCE WITH A	was repaired and inspected in accordant with the Federal Aviation Regulations at	N.
		DET	RMINED TO E	INSPECTION AND HAS BEEN E IN AIRWORTHY CONDITION.	is approved for return to service (% 450) to the work performed. Pertinent	a
			K ORDER NO.	11286	repair are on the at this repair sold	
		0.755	08-6-90	TOTAL TIME 4464 HOURS	Work Order No. 7/296	-
		SIGN	1	Delleste	Stored Man 2 Verst	生
				SERVICES-REPAIR STATION YWBR797L	Signature of Authorized	-
		no.	1450 Boughte	n Drive Bakersfield, CA 93308	1450 Boughton Drive Bekers	1
				CO See Conservation Service with a contract of the Contract of	\$450 Bodghon Office General	~
				15		
-						
						-

ľ	Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	30-Sep-02	
		S/N:	E-2850	WORK ORDER:	22-04-11412	ì
	1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4488.8 hr	
	(661) 391-1177			TOTAL TIME:	4488.8 hr	

Date: 9-30-02	Signed: 4. Chulls	F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 04. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7-8-02	4423.0		4423.°	Removed defective preumatie pump S/N 2A4634. Installed New AA216CW		4438.8			Completed Inspection #12 of Beech craft Continuing Care Inspection Guid PN98-36711D
				replaced inlet and in line filters. Installed New pressure regulator Runup		TRITOIN	100	ohr liver	to Serviced bathery Tires and broke reservoir cation. Repacked all wheel bearings. Resealed uper Performed landing gear inspection and rigging
				and system ops checkgood.		inspect	ion C	heded w	similar manual systems. Herformed cabin interior
				The ancial and/or component is stalled above was repaired and inspected in accordance with the Federal Aviation Regulations and is approved for return to service with respect to the work performed. Perturent classis of the		door her	dies	er 5/132 Toxi	Muffler ally. C/W AD 97-14-15 inspected cabin 693. C/W AD 76-07-12 Bandix Switch check check good.
				repair are on tile at this repair station. Work Order No. 1203 Date Signed State State Signed State St		ICER	FYTHAT CTED	N ACCO	HAS BEEN THE AIRCRAFT THE AIRCRAFT AND HAS BEEN WAS repaired and inspected in accordance was repaired and inspected in accordance
				Signaturi/of Authorized Individuel R2YTHEON ARCHAFT SERVICES-No. YMSRIYIT. 1450 Boughton Drive Bakensleid, CA 93306	2005	WORK	7-/5-0	1/2	RTHY CONDITION. is approved for return to service with respect
						RAYTHE	ON AIRCR	T SERVICES R	EPAIR STATION YWBR797. Signatury of Authorized Individual RAYTHEON ARCRAFT SERVICES No. YWBR797. 1450 Bougracon Orive Balversteid, CA. 93308

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	10/16/02	_
Aircraft Services	S/N:	E-2850	WORK ORDER:	11474	
1450 Boughton Dr.	REG. NO:	N815LA	HOBBS:	4497.9	
Bakersfield, CA 93308 (661) 391-1177	1	######################################	TOTAL TIME:	4497.9	

F.A.A. A.R.S. #YWBR797L

Removed left and right elevators. Removed left and right elevator trim tab actuators. Disassembled, cleaned and inspected actuators. Installed new rod ends, pistons, bushings and bearings. Serviced and reinstalled. Reinstalled elevators using new bushings and hardware. Checked rigging and cable tensions. Operational check good.

AIRFRAME LOGBOOK INSERT

	Rayt	heon
3	Aircraft	Service

1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177

MODEL: Bonanza A-36 DATE: 11/20/02 S/N: E-2850 WORK ORDER: 11563

HOBBS: 4499.3 REG. NO: N815LA TOTAL TIME: 4499.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertingut details of the repair are on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Removed nose gear retract rod. Cleaned and inspected. Replaced all rod end bearings and reinstalled. Checked gear rigging. Landing gear operation checked normal system.

Raytheon Aircraft Services	MODEL: Bonanza A-36	DATE:	2/6/03
1450 Boughton Dr.	S/N: E-2850	WORK ORDER:	11720
Bakersfield, CA 93308	REG. NO: N815LA	HOBBS:	4513.1
(661) 391-1177	the state of the state of the	TOTAL TIME:	4513.1

1 1 1 1 1

Date: 2/6/03 Signed: My 2 F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed ELT yearly inspection and functional checks per manufactures instructions. Battery due date: Feb 2004. Set in the "Arm" position. Replaced instrument air filters on standby pneumatic system.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	4/14/03
	S/N:	E-2850	WORK ORDER:	11857
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4538.9
(661) 391-1177			TOTAL TIME:	4538 9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/14/03	Signed: My Heat	F.A.A. A.R.S. #YWBR797
	, ,,	- Contract of the contract of

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Replaced nose and left main tires. Replaced left brake linings. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. AD 2003-01-01 P/C/W 9/99 at 2139 hours total time per S/B 53-3341. Run-up and taxi check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	5/21/03	
Aircraft Services	S/N:	E-2850	WORK ORDER:	11942	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4559.2	
(661) 391-1177	NOT 1 - 101 - 10 - 1 - 1 - 1		TOTAL TIME:	4559.2	

Date: 5/21/03 Signed: Slyn Heat F.A.A. A.R.S. #YWBR797L

Removed defective 8-day clock S/N W80734. Installed overhauled clock S/N W80195. Set current time and checked for proper operation. Removed left inboard fuel quantity transmitter. Installed new transmitter using new gasket and insulating grommet. Leak and operational check good.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	5/27/03	
	S/N:	E-2850	WORK ORDER:	11955	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4564.3	
(661) 391-1177		1.50	TOTAL TIME:	4564.3	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/27/03 Signed: Heart F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	6/13/03	
	S/N:	E-2850	WORK ORDER:	12018	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4588.9	
(661) 391-1177		W. H. F	TOTAL TIME:	4588.9	

Signed: My O Heal F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2004. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced right main tire. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Ravi	heon
Ray!	Service

1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177

MODEL: Bonanza A-36 S/N: E-2850

REG. NO: N815LA

DATE: 6/18/03 WORK ORDER: 12037

HOBBS: 4591.1

TOTAL TIME: 4591.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Removed inoperative 8-day clock S/N W80195. Installed overhauled clock S/N W80734. Set current time. Operational check good.

	Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	07-03-03	- P
	The Company of the Co	S/N:	E-2850	WORK ORDER:	12096	2
	1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4614.0	
-	(661) 391-1177			TOTAL TIME:	4614.0	

Date: 7-3-03 Signed: 4. Challe F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	7/23/03
	S/N:	E-2850	WORK ORDER:	12119
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4638.5
(661) 391-1177			TOTAL TIME.	4630 #

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/23/03	Signed: My Heat	F.A.A. A.R.S.	#YWBR7971
---------------	-----------------	---------------	-----------

Completed Inspections #8 through #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights and ELT. Battery Due Date: Feb 2004. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Resealed right brake caliper, Replaced right brake disc and linings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Replaced fuel cap oring seals. Replaced instrument air filters on the main pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per Raytheon S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	8/5/03	- Origi
	S/N:	E-2850	WORK ORDER:	12171	A Street, St.
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4648.5	- 2
(661) 391-1177	1	and seems of	TOTAL TIME:	4648.5	1/4/48833
The aircraft and/or component identified approved for return to service with respect Date: 8/8/03 Signed		ed. Perjanent details of	the repair are on file at t	his Repair Star	tion,
Date: 8/8/05 Signed	- Myric	Hay	F.A.A. A.	R.S. #YWB	3R797L

Removed defective landing gear dynamic brake relay. Installed new relay. Operational check of landing gear-system good.

AIRFRAME LOGBOOK INSERT

	Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	9/8/03
1		S/N:	E-2850	WORK ORDER:	12249
	1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4664.2
	(661) 391-1177			TOTAL TIME:	4664.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/8/03 Signed: My X F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Raytheon	MODEL:	Bonanza A-36	DATE:	10/2/03	
Raytheon Aircraft Services	S/N:	E-2850	WORK ORDER:	12269	1 political
1450 Boughton Dr.	REG. NO:	** ** ** ** ** ** ** ** ** ** ** ** **	HOBBS:	4689.6	
Bakersfield, CA 93308 (661) 391-1177	KEG. NO.	1103000	TOTAL TIME:	4689.6	

Date: 10/2/03 Signed: Nym Heet F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beecheraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2004. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Replaced hinge halves and pin on right emergency exit window. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon	MODEL:	Bonanza A-36	DATE:	11/4/03
- Alleran Services	S/N:	E-2850	WORK ORDER:	12363
0 Boughton Dr. rsfield, CA 93308	REG. NO:	N815LA	HOBBS:	4706.0
661) 391-1177			TOTAL TIME:	4706.0
raft and/or component identified abo	ove was repaired as the work perform	nd inspected in accord ned. Perstnent details o	ance with Federal Aviation of the repair are on file at	on Regulations an

Removed defective landing gear retract motor S/N 11830. Installed new retract motor S/N 12355. Checked landing gear rigging and operation.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	11/11/03
	S/N:	E-2850	WORK ORDER:	12383
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4713.3
(661) 391-1177		_0,000000000000000000000000000000000000	TOTAL TIME:	4713.3

Date: 11/11/03 Signed: Signed: Acat F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	11/20/03	1500
Aircraft Services	S/N:	E-2850	WORK ORDER:	12344	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4724.7	
(661) 391-1177			TOTAL TIME:	4724.7	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Partinent details of the repair are on file at this Repair Station.

Date: 11/20/03 Signed: Alpho. Heat F.A.A. A.R.S. #YWBR797L

Replaced throttle control cable with new control P/N 36-380084-3. Adjusted rigging and checked gear warning and anti retraction settings.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	12/09/03
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	12449
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4738.7
(661) 391-1177	100000000000000000000000000000000000000		TOTAL TIME:	4738.7

Date: 12/9/03 Signed: Nyrs Heart F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Baytheon Aircraft Services	MODEL:	Вопапиа А-36	DATE:	12/29/03	
	S/N:	E-2850	WORK ORDER:	12472	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4762.5	
(661) 391-1177			TOTAL TIME:	4762.5	100

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/29/03 Signed: My D Hecks F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Replaced landing light. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	1/22/04	10000
	S/N:	E-2850	WORK ORDER:	12531	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4789.1	
(661) 391-1177	14 14 15	E1-3-121	TOTAL TIME:	4789.1	

Signed: Num W Head F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Replaced ELT battery and performed yearly inspection and functional checks per manufactures instructions. New Battery Due Date: Fcb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Replaced instrument air check valves. Removed fuel selector valve S/N 3680. Installed new fuel selector valve S/N 4757 using all new gaskets and seals. Removed fuel boost pump S/N 0115. Installed new fuel boost pump S/N 1056 with manufacture date of: Nov 11,2002. Operational and leak check good. Replaced co-pilot's shoulder harness assembly with repaired assembly. Installed new instrument air filters on the standby pneumatic system. Run-up and taxi check good.

EMERGENCY: LOGATOR (TRANSMITTER)	Т
Feb 2006	
SIGNED My Dett	
FOR RAYTHEON AIRCRAFT SERVICES- CRSYWBR 797L	

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	1/27/04
Aircraft Services	S/N:	E-2850	WORK ORDER:	12488
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4797.7
(661) 391-1177			TOTAL TIME:	4797.7
The aircraft and/or component identified al approved for return to service with respect Date: 1/27/04 Signed:		ed, Pertinent details o	of the repair are on file at	

Removed flashing beacon assembly. Replaced flasher unit, bulb and lens cover. Reinstalled beacon assembly. Operational check good.

	Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	2/6/04	
•		S/N:	E-2850	WORK ORDER:	12588	
	1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4813.7	
7	(661) 391-1177		v. rottorial de la constantial del constantial de la constantial d	TOTAL TIME:	4813.7	

Signed: Nums Hears F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Rayt	heon
Aircraft	Services

1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177

MODEL: Bonanza A-36

REG. NO: N815LA

S/N: E-2850

DATE: 2/11/04 WORK ORDER: 12595

HOBBS: 4820.4

TOTAL TIME: 4820.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed Pertingut details of the repair are on file at this Repair Station.

Signed: / Went Heats

F.A.A. A.R.S. #YWBR797L

Removed defective oil temperature/pressure indicator S/N 1129. Installed repaired indicator S/N 1397. Ground operational check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	2/27/04	
20 - 20 - 20 - 20 - 20 - 20 - 20 - 20 -	S/N:	E-2850	WORK ORDER:	12626	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4839.4	- 6
(661) 301-1177			TOTAL TIME:	4830 4	

ste: 2/27/04 Signed: Myn D. Heat F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. Performed 5 year wing bolt inspection. Installed new nuts and lubed torqued all wing attach bolts. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 84-26-02 Installed new induction air filter. Next due at 5339.4 hours total time. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	3/11/04	
	S/N:	E-2850	WORK ORDER:	12689	- 12
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4862.5	
(661) 391-1177			TOTAL TIME	1962 5	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/11/04 Signed: Lynd Heat F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

DATE:	30-Mar-04
VORK ORDER:	
HOBBS:	12.48
TOTAL TIME:	4886.8 hr
with Federal Aviat	tion Regulations and is
	at this Repair Station
_ F.A.A.	A.R.S. #YWBR7971
or S/M 166200 Look	and one checked good
Dr S/M 166200. Leak	k and ops checked good.
10799	
THIS DATE AND FO	DUND
WORK ORDER #	22-04-12720
1	
-	9
ES - CRS # YWBR7! RSFIELD, CA 93308	
ROFIELD, CA 33300	
	ERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	4/2/04
Aircraft Services 1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	12759
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4888.4
(661) 391-1177			TOTAL TIME:	4888.4

te: 4/2/04 Signed: New Hest F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Installed new landing gear dynamic brake relay. Installed new left brake caliper assembly with new brake linings. Landing gear operation checked normal system. Removed right flap assembly S/N E-2850. Installed repaired flap assembly S/N E-2649. Checked flap operation and rigging. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	4/16/04
	S/N:	E-2850	WORK ORDER:	12793
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4913.7
(661) 391-1177	1, -1	44	TOTAL TIME:	4913.7
The aircraft and/or component is approved for return to service w Date: 4//6/04 Sig		work performed/Pertin	ent details of the repair are	

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	5/10/04
	S/N:	E-2850	WORK ORDER:	12869
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4939.3
(661) 391-1177			TOTAL TIME:	4939.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

	Date: 5/10/04	Signed: Ny D.	Heats	F.A.A. A.R.S.	#YWBR797L
--	---------------	---------------	-------	---------------	-----------

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Replaced instrument air filters on the main pneumatic system. Re-torqued all wing attach bolts. Removed oil temp/press gauge S/N 1397. Installed overhauled gauge S/n 1375. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per Raytheon S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. Rum-up and taxi check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	5/24/04	
	S/N:	E-2850	WORK ORDER:	12911	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4964.4	
(661) 391-1177	100	1 Str.	TOTAL TIME:	4964 4	

Date: 5/24/04 Signed: My D. Heart F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Installed new shims in nose gear upper cap. Landing gear operation checked normal system.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	6/2/04	_
Aircraft Services	S/N:	E-2850	WORK ORDER:	12962	
1450 Boughton Dr.	REG. NO:	N815LA	HOBBS:	4984.0	
Bakersfield, CA 93308			TOTAL TIME	4084 0	

(661) 391-1177

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pyrtinent getails of the repair are on file at this Regular Station.

Date: 6/2/04 Signed: Dign D Heats F.A.A. A.R.S. #YWBR797L

Removed upper flashing beacon S/N 4480. Installed repaired beacon S/N 1449. Operational check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	6/3/04	1).
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	12968	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	4989.0	
(661) 391-1177	4-1	100-0	TOTAL TIME:	4989.0	

Date: 6/3/04 Signed: My D. Heat F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Replaced right brake linings. Resealed right brake caliper. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	06-14-04
	S/N:	E-2850	WORK ORDER:	12992
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5012.7
(661) 391-1177			TOTAL TIME:	5012.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

ate: 6/14/04	Signed: New D. Heart

F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	6/29/04	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	13018	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5039.8	
(661) 391-1177	1991 6 4 1000		TOTAL TIME:	5039.8	

Date: 6/29/04 Signed: My Defeats F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Replaced nose and right main tires. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	7/15/04	
	S/N:	E-2850	WORK ORDER:	13079	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5063.7	
(661) 391-1177			TOTAL TIME-	5863.7	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/15/04 Signed: Nyn Heart F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Raymeon	MODEL:	Bonanza A-36	DATE:	8/2/04
Aircraft Services	S/N:	E-2850	WORK ORDER:	13137
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5077.7
(661) 391-1177	111		TOTAL TIME:	5077.7
The aircraft and/or component identified above wapproved for return to service with respect to the Date: 9/2/04 Signed: 1	workperform		of the repair are on file at	

Removed defective right wing tip strobe light assembly S/N 9238. Installed repaired light assembly S/N 8913. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Raythenn	MODEL:	Bonanza A-36	DATE:	8/19/04	
Raytheon Aircraft Services		E-2850	WORK ORDER:		_
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5088.9	_
(661) 391-1177			TOTAL TIME.	5000 0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Pate: 8/19/04 Signed: Ny Jest F.A.A. A.R.S.	#YWBR797I	L
---	------------------	---

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Removed engine S/N 685901. Installed factory new engine S/N 687126. Propeller S/N 932354 was overhauled and reinstalled. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Drained fitel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed flap actuator and flex drive cable lubrications. Checked emergency exits for condition and operation. Installed new cabin heater muffler assembly. C/W AD 84-26-02 installed new induction air filter. Next due at 5588.9 hours total time. Run-up and taxi check good.

Mayrneon	MODEL:	Bonanza A-36	DATE:	8/23/04
Aircraft Services	S/N:	E-2850	WORK ORDER:	13185
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5094.5
(661) 391-1177	40.00		TOTAL TIME:	5094.5
The aircraft and/or component identified above approved for return to service with respect to the Date: 8/23/04 Signed:	vas repaired an	ed Pertinent details o	f the repair are on file at	n Regulations and is this Repair Station. R.S. #YWBR797L

Removed defective manifold pressure indicator S/N 2589. Installed Instruments Inc. overhauled indicator S/N 2432. Run-up and operational check good.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	8/30/04	1030
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	13202	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5115.0	
(661) 391-1177			TOTAL TIME:	5115.0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/30/04 Signed: Ny Deceto F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Run-up and taxi check good.

Rayfieon
Aircraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

WORK ORDER: 13266 HOBBS: 5138.7

DATE: 9/16/04

TOTAL TIME: 5138.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/16/04 Signed: Myord Heats

F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

	TODAYS TOTAL	Description	of Inspections, Te	ests, Repairs and Alte
Raytheon	MODEL:	Bonanza A-36	DATE:	10-08-04
Aircraft Services	S/N:	E-2850	WORK ORDER:	13348
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5,162.8 hrs.
(661) 391-1177			TOTAL TIME:	5,162.8 hrs.

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/8/04 Signed:

F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained-fuel sumps.



1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177

MODEL: Bonanza A-36 S/N: E-2850 REG. NO: N815LA

WORK ORDER: 13437

DATE: 11/4/04

HOBBS: 5181.8

TOTAL TIME: 5181.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Perfinent details of the repair are on file at this Repair Station.

Signed: Ulu D

F.A.A. A.R.S. #YWBR797L

Removed defective landing gear dynamic brake relay. Installed new relay P/N SM50D7. Checked landing gear operation and rigging. Operational check of landing gear system good.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	11/11/04	
	S/N:	E-2850	WORK ORDER:	13449	300
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5189.3	
(661) 391-1177			TOTAL TIME:	5189.3	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: UTITO	Date:	111	111	04
-------------	-------	-----	-----	----

Signed: Alund

F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

Raytheon Aircraft Services

1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177

S/N: E-2850

REG. NO: N815LA

MODEL: Bonanza A-36

DATE: 10/28/04

WORK ORDER: 13388

HOBBS: 5174.8

TOTAL TIME: 5174.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Removed defective attitude gyro S/N T8707A. Installed Mid-Continent Instruments West repaired attitude gyro S/N T8497A. Ground operational check good.

Raytheon Aircraft Services 1450 Boughton Dr.

Bakersfield, CA 93308

MODEL: Bonanza A-36 S/N: E-2850

DATE: 11/2/04

WORK ORDER: 13430

HOBBS: 5177.1

REG. NO: N815LA

TOTAL TIME: 5177.4

(661) 391-1177 The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Signed: Lun 6

F.A.A. A.R.S. #YWBR797L

Removed defective left outboard fuel quantity transmitter. Installed new transmitter P/N 96-380042-1, S/N 1477. Installed using new gasket and safety wire. Operational and leak check good.

AIRFRAME LOGBOOK INSERT

Raytheon	MODEL:	Bonanza A-36	DATE:	11/30/04
Rayffeon Aircraft Services	S/N:	E-2850	WORK ORDER:	13481
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5214.1
(661) 391-1177		10 V 10 20 20 10 10 10 10 10 10 10 10 10 10 10 10 10	TOTAL TIME:	5214.1
The aircraft and/or component	identified above wa	as repaired and inspects work performed. Pertin	ed in accordance with Feder ent details of the repair are	ral Aviation Regulations an on file at this Repair Static

Date: 11/30/04 Signed: Myn D. Heat F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

-					
	Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	1/11/05
	1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	13602
	Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5239.3
	(661) 391-1177			TOTAL TIME:	5239.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertiaent details of the repair are on file at this Repair Station.

Date: 1/11/05	Signed: My Heat	F.A.A. A.R.S. #YWBR7971

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Performed ELT yearly inspection and functional checks per manufactures instructions. Battery Duc Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Removed all brake master cylinders. Installed new master cylinders, pilots S/N 794FRA, 1522FRA co-pilot's S/N 888FRA, 1637FRA. Installed new parking brake vaive. Replaced upper and lower brake flex hoses on main gear. Replaced left brake linings. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Performed spar carry through structure inspection. Replaced instrument air filters on the standby pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per Raytheon S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	01-21-05	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	13649	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5264.7	C+151/4
(661) 391-1177		Committee of the same	TOTAL TIME.	22642	200

Date 1-21-05 Signed: 4. Causte F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services	MODEL:	Bonanza A-36	DATE:	2/14/05
	S/N:	E-2850	WORK ORDER:	13729
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	5289.0
(661) 391-1177			TOTAL TIME:	5289.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Pate: 2/4/05 Signed: Vyn O Heath F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

			The state of the s	7			Control of the Contro
YEAR:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance	YEAR:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance
//-05	97-14-15	Caro 3	T 10 Ton Ch des la 1/4 on 5/852 2/02 Pul	UNIE		1	1
1-05	77-14-13	5237.	Next Due at removal Myn Dekath 4WBATATL W/D 13602			- 4	*
						20000	
		-					
1005							
					100		25010000 400000
- 20 - 3	5						

The state of the s

Raytheon Aircraft Services 1450 Boughton Dr. Bakersfield, CA 93308

(661) 391-1177

MODEL: Bonanza A-36 S/N: E-2850

DATE: 3/14/05

WORK ORDER: 13816

HOBBS: 5314.2

TOTAL TIME: 5314.2

REG. NO: N815LA

F.A.A. A.R.S. #YWBR797L

This log book closed this time and date. Aircraft Total Time in Service 5314.2 hours.

YEAR:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance
DATE			
12402	97-14-15	4138.	Inspectal Gabin door handles per Raytheon 5/82693
			Due at Next removal. MynD. Heate YWBR797L 2/10578
5-24-02	84-26-02	4340.2	Installed New induction air filtyr. Next Due at
			4940.2 Total Time. Slyn D. Haut YWBR797L W/O 11043
7-15-02	97-14-15	4433.8	Inspected color downhardles per Ray Thea 5/82693
			Die at Next removal. My D. Heats /WZN797L w/215
4-14-03	2003-01-01	4538.9	P/C/W 9/99 @ 2/39 hrs total Time per 5/1353-3341
		111000000000000000000000000000000000000	My D feet YWBRATE W/011957
1-23-03	97-14-15	4638.5	Inspected Cabin door handles per 5/B 52.2693. R2 Due
Makan -		7.0	at west removed My D. Heats YWBATATL W/012/19
2-27-04	34-26-02	4339.4	Installed new induction air fitter. Het Due ut
		1115-517 5111	5339. 4 hours Total Time. March Heat YWARTHIL 1262
5-10-04	974445	4939.3	Inspected interior cabin door handles per 5/852-2693 R2
			Due at NEXT remove Alexand Health YWBRT971 w/012869
3-19-04	84-26-02	5088.9	Installed wew induction are fitter, Next Due at
	Šta		5588. 9 hrs Total Time New D. Hearty YWARTAIL W/0 13153

The Standard Aircraft Log SA-2

@ 1992-1999 Aviation Supplies & Academics, Inc.

ISBN 1-56027-117-5 ASA-SA-2

All rights reserved. Reproduction or use, without express permission, in any manner, is prohibited.

Published by Aviation Supplies & Academics, Inc. 7005 132nd Place SE Newcastle, WA 98059-3153

Printed in Canada





rcraft Record General Information	craft	ft Record	General	Information
-----------------------------------	-------	-----------	---------	-------------

21	
-56	
	MAISIA

Manufacturer Be	ech	Model A - 3 C		
Serial E-285	0	Registration Number	NO15LA	
Date of Manufacture	3/14/94		***	

Engine(s) currently installed:

Manufacturer	7CM	Model 20-550-13	Serial	
Manufacturer_		Model	Serial	

Propeller(s) currently installed:

Manufacturer	McCauley	Model	D3A32C409-C
HUB Model	/ Serial _	000000000	Serial
and the same of th			- Tolling

Blade Model Serial Serial Serial Blade Model Serial Serial . Serial