

100-111111



The Standard

AIRCRAFT LOG

BOOK #5

ASA-SA-2

Registered Owner Record

Name _____	Address _____
City _____ State _____	From _____ To _____
Name _____	Address _____
City _____ State _____	From _____ To _____
Name _____	Address _____
City _____ State _____	From _____ To _____
Name _____	Address _____
City _____ State _____	From _____ To _____
Name _____	Address _____
City _____ State _____	From _____ To _____
Name _____	Address _____
City _____ State _____	From _____ To _____
Name _____	Address _____
City _____ State _____	From _____ To _____

Notes

Log Book #5

opened 3-14-05 @ 5314.2 hrs Total Time



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 3/14/05

WORK ORDER: 13816

HOBBS: 5314.2

TOTAL TIME: 5314.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/14/05 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: BEECH A36

S/N: E-2850

REG. NO: N815LA

DATE: 29-Mar-05

WORK ORDER: 22-04-13810

HOBBS: 5320.2 hr

TOTAL TIME: 5320.2 hr

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 29-MAR-2005 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

The Directional Gyro, KG 102A S/N 36141, was overhauled by Honeywell International, Inc. and reinstalled this date. Ops checked good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 4/13/05

S/N: E-2850 WORK ORDER: 13890

REG. NO: N815LA HOBBS: 5339.8

TOTAL TIME: 5339.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/13/05 Signed: Myn D. Hest F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 5/12/05

S/N: E-2850 WORK ORDER: 13983

REG. NO: N815LA HOBBS: 5363.5

TOTAL TIME: 5363.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/12/05 Signed: Myn D. Hest F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 10/4/05
S/N: E-2850 WORK ORDER: 14328
REG. NO: N815LA HOBBS: 5388.7
TOTAL TIME: 5388.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/4/05 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Installed new G242 aircraft battery S/N G02143853. Replaced instrument air filters on the main pneumatic system. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: BEECH A-36 DATE: 10-07-05
S/N: E-2850 WORK ORDER: 14342
REG. NO: N815LA HOBBS: 5392.0
TOTAL TIME: 5392.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10-7-05 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed left wingtip strobe unit, serial number 9279 and installed repaired unit, serial number 8278. Operational check good. Removed panel mounted clock serial number W80734 and installed repaired clock, serial number W80713, operational check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 10/31/05
S/N: E-2850 WORK ORDER: 14390
REG. NO: N815LA HOBBS: 5414.5
TOTAL TIME: 5414.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/31/05 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 11/17/05
S/N: E-2850 WORK ORDER: 14446
REG. NO: N815LA HOBBS: 5438.3
TOTAL TIME: 5438.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/17/05 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. Replaced right fuel sump drain valve. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

DATE: 11/30/05

S/N: E-2850

WORK ORDER: 14463

REG. NO: N815LA

HOBBS: 5456.0

TOTAL TIME: 5456.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11-30-05

Signed:

F.A.A. A.R.S. #YWBR797L

Removed inoperative 8-day clock S/N W80713. Installed AeroSonic Corporation overhauled clock S/N W80534. Wound clock and set current time. Operational check good.



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

DATE: 12/5/05

S/N: E-2850

WORK ORDER: 14496

REG. NO: N815LA

HOBBS: 5464.0

TOTAL TIME: 5464.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/5/05

Signed:

F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced right brake linings and resealed brake caliper. Taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 12/16/05
S/N: E-2850 WORK ORDER: 14528
REG. NO: N815LA HOBBS: 5488.8
TOTAL TIME: 5488.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/16/05 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2006. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Replaced pilot's shoulder harness assembly with repaired unit. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 1/3/06
S/N: E-2850 WORK ORDER: 14591
REG. NO: N815LA HOBBS: 5514.0
TOTAL TIME: 5514.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/3/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced nose, left and right main tires. Landing gear operation checked normal system.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA
DATE: 1/16/06
WORK ORDER: 14621
HOBBS: 5538.1
TOTAL TIME: 5538.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/16/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Drained fuel sumps. Replaced ELT battery and performed yearly inspection and functional checks per manufactures instructions. Set in the "Arm" position. New Battery Due Date: Feb 2008. Performed 100 hour lubrication. Repacked all wheel bearings. Replaced left brake linings. Resealed and serviced nose strut. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Replaced instrument air filters on the standby pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per Raytheon S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 84-26-02 installed new induction air filter. Next due at 6038.1 hours total time. Run-up and taxi check good.

EMERGENCY LOCATOR TRANSMITTER
BATTERY TO BE REPLACED ON OR BEFORE
AIRFRAME LOGBOOK INSERT
Feb 2008
SIGNED [Signature]
RAYTHEON AIRCRAFT SERVICES, CRYVBR 797L



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA
DATE: 1/31/06
WORK ORDER: 14664
HOBBS: 5561.8
TOTAL TIME: 5561.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/31/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 2/13/06
S/N: E-2850 WORK ORDER: 14728
REG. NO: N815LA HOBBS: 5587.4
TOTAL TIME: 5587.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/13/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 2/23/06
S/N: E-2850 WORK ORDER: 14756
REG. NO: N815LA HOBBS: 5613.4
TOTAL TIME: 5613.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/23/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. C/W Raytheon S/B 76-3763 throttle warning/gear retraction cam inspection.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 3/13/06
S/N: E-2850 WORK ORDER: 14817
REG. NO: N815LA HOBBS: 5637.8
TOTAL TIME: 5637.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/13/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Replaced instrument air filters on the main pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 3/23/06
S/N: E-2850 WORK ORDER: 14842
REG. NO: N815LA HOBBS: 5663.2
TOTAL TIME: 5663.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/23/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Beech A36 DATE: 29-Mar-06
S/N: E-2850 WORK ORDER: 22-04-14861
REG. NO: N815LA HOBBS: 5674.2 hr
TOTAL TIME: 5674.2 hr

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station

Date: 29 MAR 2006 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

THE STATIC PRESSURE SYSTEM AND THE ALTITUDE
REPORTING EQUIPMENT WERE INSPECTED AND TESTED
THIS DATE AND FOUND TO COMPLY WITH FAR 91.411.

L.H. ALT. S/N: 26151 TESTED TO 35,000 FEET
R.H. ALT. S/N: ##### TESTED TO 35,000 FEET
ALTITUDE REPORTING EQUIPMENT S/N: 26151

DATE: 29-Mar-06 WORK ORDER #: 22-04-14861

SIGNED: [Signature]
RAYTHEON AIRCRAFT SERVICES - CRS # YWBR797L
1450 BOUGHTON DRIVE, BAKERSFIELD, CA 93308

THE ATC TRANSPONDER S/N: 10799
WAS INSPECTED AND TESTED THIS DATE AND FOUND
TO COMPLY WITH FAR 91.413.

DATE: 29-Mar-06 WORK ORDER #: 22-04-14861

SIGNED: [Signature]
RAYTHEON AIRCRAFT SERVICES - CRS # YWBR797L
1450 BOUGHTON DRIVE, BAKERSFIELD, CA 93308

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 4/7/06
S/N: E-2850 WORK ORDER: 14904
REG. NO: N815LA HOBBS: 5688.8
TOTAL TIME: 5688.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/7/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Replaced left and right brake linings. Replaced left brake disc. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 4/19/06
S/N: E-2850 WORK ORDER: 14939
REG. NO: N815LA HOBBS: 5712.1
TOTAL TIME: 5712.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/19/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 4/21/06
S/N: E-2850 WORK ORDER: 14949
REG. NO: N815LA HOBBS: 5718.8
TOTAL TIME: 5718.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/21/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed inoperative 8-day clock S/N W80534. Installed Aerosonic Corporation overhauled clock S/N W80713. Wound clock and set current time. Operational check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 5/3/06

WORK ORDER: 15001

HOBBS: 5738.6

TOTAL TIME: 5738.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/3/06

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 5/8/06

WORK ORDER: 15010

HOBBS: 5747.0

TOTAL TIME: 5747.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/8/06

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed inoperative 8-day clock S/N W80713. Installed Aerosonic Corporation overhauled clock S/N 841505. Wound clock and set current time. Operational check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 5/11/06
S/N: E-2850 WORK ORDER: 15027
REG. NO: N815LA HOBBS: 5763.6
TOTAL TIME: 5763.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/11/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 05-25-06
S/N: E-2850 WORK ORDER: 15064
REG. NO: N815LA HOBBS: 5787.2
TOTAL TIME: 5787.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5-25-06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: 2-08. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 6/7/06

WORK ORDER: 15128

HOBBS: 5815.3

TOTAL TIME: 5815.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/7/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 6/12/06

WORK ORDER: 15135

HOBBS: 5828.3

TOTAL TIME: 5828.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/12/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective strobe light power supply S/N 00098. Installed Whelen Engineering Co. Inc. rebuilt power supply S/N 02426. Removed right wing tip strobe light assembly S/N 8913. Installed repaired light assembly S/N 9238. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 7/10/06

WORK ORDER: 15232

HOBBS: 5886.2

TOTAL TIME: 5886.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/10/06

Signed: Nyrd D. Heath

F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 7/18/06

WORK ORDER: 15260

HOBBS: 5912.9

TOTAL TIME: 5912.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/18/06

Signed: Nyrd D. Heath

F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 6/16/06

WORK ORDER: 15138

HOBBS: 5838.8

TOTAL TIME: 5838.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/16/06

Signed:

F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per Raytheon S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 6/27/06

WORK ORDER: 15180

HOBBS: 5862.9

TOTAL TIME: 5862.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/27/06

Signed:

F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Beech A-36 DATE: 19-Jul-06
S/N: E-2850 WORK ORDER: 22-04-15263
REG. NO: N815LA HOBBS: 5912.9 hr
TOTAL TIME: 5912.9 hr

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 19-Jul-2006 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective attitude gyro S/N T8497A and installed Mid-Continent Instruments West repaired attitude gyro S/N T8287. Ops checked good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 7/28/06
S/N: E-2850 WORK ORDER: 15282
REG. NO: N815LA HOBBS: 5939.4
TOTAL TIME: 5939.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/28/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Removed attitude indicator S/N T8287. Installed overhauled indicator S/N T8664A. Removed pneumatic pump S/N N24449. Installed new AA3216CW pump S/N N38378. Cleaned lines and replaced inlet and inline filters. Installed new pneumatic pressure regulator. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 8/7/06

WORK ORDER: 15347

HOBBS: 5961.0

TOTAL TIME: 5961.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/7/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced left and right brake linings. Taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 8/16/06

WORK ORDER: 15371

HOBBS: 5989.3

TOTAL TIME: 5989.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/16/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Replaced right main tire. Removed landing gear actuator gearbox assembly S/N 10344. Installed repaired actuator S/N 8998 with new retract motor S/N 351. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Removed left and right flap actuator S/N 837-K-93 and 952-M-94. Installed overhauled actuator S/N 671-A-93 and 698-B-93A. Replaced right and left flap flex drive cables. Checked flap rigging. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 9/11/06
S/N: E-2850 WORK ORDER: 15452
REG. NO: N815LA HOBBS: 6038.3
TOTAL TIME: 6038.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/11/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Drained fuel sumps. Performed 100 hour lubrication. Replaced left main tire. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. Installed new bushings and hardware in left and right elevator trim tab horns. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 84-26-02 replaced induction air filter. Next due at 6538.3 hours total time. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 9/21/06
S/N: E-2850 WORK ORDER: 15490
REG. NO: N815LA HOBBS: 6061.9
TOTAL TIME: 6061.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/21/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 8/28/06

WORK ORDER: 15394

HOBBS: 6013.3

TOTAL TIME: 6013.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/29/06

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Beech A36

S/N: E-2850

REG. NO: N815LA

DATE: 08-Sep-06

WORK ORDER: 22-04-15453

HOBBS: 6034.6 hr

TOTAL TIME: 6034.6 hr

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 08 Sep 2006

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed attitude gyro S/N T8664A and installed Mid-Continent Instruments West overhauled gyro S/N T8497A. Ground checked good.

AIRFRAME LOGBOOK INSERT

YEAR:	RECORDING	TODAYS	TOTAL	Description of Inspections Tests
Raytheon Aircraft Services 1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177				MODEL: Bonanza A-36 S/N: E-2850 REG. NO: N815LA DATE: 10/24/06 WORK ORDER: 15612 HOBBS: 6113.9 TOTAL TIME: 6113.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10-24-06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon Aircraft Services 1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177	MODEL: Bonanza A-36 S/N: E-2850 REG. NO: N815LA	DATE: 11-03-06 WORK ORDER: 15631 HOBBS: 6137.5 TOTAL TIME: 6137.5
--	---	--

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11-3-06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Ops checked all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Installed new instrument air filters on standby system. Performed spar carry-through structure inspection. Repacked all wheel bearings. Installed new bolts and bushings on right and left landing gear retract braces. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per Raytheon S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 10/10/06
S/N: E-2850 WORK ORDER: 15574
REG. NO: N815LA HOBBS: 6081.9
TOTAL TIME: 6081.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/10/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective 8-day clock S/N 841505. Installed AeroSonic Corporation repaired clock S/N W80713. Wound clock and set current time. Operational check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 10/12/06
S/N: E-2850 WORK ORDER: 15579
REG. NO: N815LA HOBBS: 6088.5
TOTAL TIME: 6088.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/12/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 11/15/06
S/N: E-2850 WORK ORDER: 15687
REG. NO: N815LA HOBBS: 6164.3
TOTAL TIME: 6164.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/15/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 11/16/06
S/N: E-2850 WORK ORDER: 15690
REG. NO: N815LA HOBBS: 6164.8
TOTAL TIME: 6164.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/16/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed inoperative right wing tip strobe light assembly S/N 9238. Installed repaired light assembly S/N 8642. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

DATE: 11/29/06

S/N: E-2850

WORK ORDER: 15722

REG. NO: N815LA

HOBBS: 6188.4

TOTAL TIME: 6188.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/29/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Removed inoperative left wing tip strobe light assembly S/N 8278. Installed repaired strobe light assembly S/N 9279. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

DATE: 12/1/06

S/N: E-2850

WORK ORDER: 15758

REG. NO: N815LA

HOBBS: 6188.5

TOTAL TIME: 6188.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/1/06 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective landing gear dynamic brake relay. Installed new relay P/N SM50D7. Replaced nose tire. Checked landing gear rigging as required. Landing gear operation checked normal system.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 12/15/06
S/N: E-2850 WORK ORDER: 15797
REG. NO: N815LA HOBBS: 6213.5
TOTAL TIME: 6213.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/15/06 Signed: Myndy Heath F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 1/5/07
S/N: E-2850 WORK ORDER: 15874
REG. NO: N815LA HOBBS: 6238.3
TOTAL TIME: 6238.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/5/07 Signed: Myndy Heath F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Performed ELT yearly inspection and functional check per manufactures instructions. Set in the "Arm" position. Battery due date: Feb 2008. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Replaced instrument air filters on the main pneumatic system. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 1/23/07
S/N: E-2850 WORK ORDER: 15930
REG. NO: N815LA HOBBS: 6262.6
TOTAL TIME: 6262.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/23/07 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced left and right brake linings. Taxi check good.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 2/13/07
S/N: E-2850 WORK ORDER: 16004
REG. NO: N815LA HOBBS: 6286.2
TOTAL TIME: 6286.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/13/07 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Removed landing gear actuator assembly S/N 8998. Installed repaired actuator assembly S/N 14826 with new retract motor S/N 566. Replaced nose gear retract rod end bearings and plunger. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Approval/Certificate No:
YWBR797L
Date: 2/12/07

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36 DATE: 2/27/07
S/N: E-2850 WORK ORDER: 16058
REG. NO: N815LA HOBBS: 6312.6
TOTAL TIME: 6312.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/27/07 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Raytheon
Aircraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177


MODEL: Bonanza A-36 DATE: 03-12-07
S/N: E-2850 WORK ORDER: 16108
REG. NO: N815LA HOBBS: 6338.3
TOTAL TIME: 6338.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3-12-07 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W Raytheon S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 3/26/07

WORK ORDER: 16164

HOBBS: 6362.3

TOTAL TIME: 6362.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/26/07 Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 4/10/07

WORK ORDER: 16231

HOBBS: 6389.4

TOTAL TIME: 6389.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/10/07 Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Removed strobe light power supply S/N 02426. Installed new power supply S/N 02911. Replaced right exhaust manifold, cabin heater muffler assembly and tail pipe. Installed using new gaskets and hardware. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 4/23/07

1450 Boughton Dr.

S/N: E-2850WORK ORDER: 16266

Bakersfield, CA 93308

REG. NO: N815LAHOBBS: 6411.9

(661) 391-1177

TOTAL TIME: 6411.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/23/07 Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Removed lower oscillating beacon S/N 11545. Installed repaired beacon S/N 10377.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 5/4/07

1450 Boughton Dr.

S/N: E-2850WORK ORDER: 16328

Bakersfield, CA 93308

REG. NO: N815LAHOBBS: 6438.2

(661) 391-1177

TOTAL TIME: 6438.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/4/07 Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Replaced right main tire, brake disc and linings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection and installation of operating limitation placard. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 5/15/071450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177S/N: E-2850WORK ORDER: 16362REG. NO: N815LAHOBBS: 6462.9TOTAL TIME: 6462.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/15/07 Signed: *Myra D. Heats*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Removed aft fresh air vent blower assembly S/N 915B. Installed new blower assembly kit S/N 371.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 5/24/071450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177S/N: E-2850WORK ORDER: 16392REG. NO: N815LAHOBBS: 6487.9TOTAL TIME: 6487.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/24/07 Signed: *Myra D. Heats*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 6/7/07

WORK ORDER: 16463

HOBBS: 6514.8

TOTAL TIME: 6514.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/7/07 Signed: Myron D. Heath F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced left brake linings. Taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 6/14/07

WORK ORDER: 16493

HOBBS: 6534.8

TOTAL TIME: 6534.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/14/07 Signed: Myron D. Heath F.A.A. A.R.S. #YWBR797L

Removed defective pneumatic pump S/N N 38378. Installed new AA3216CW pump S/N N43642 using new gasket. Cleaned lines and replaced inlet and inline filters. Run-up and system operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 6/18/07

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 16495

REG. NO: N815LA


HOBBS: 6538.8

TOTAL TIME: 6538.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/19/07

Signed:



F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 84-26-02 replaced induction air filter. Next due at 7038.8 hours total time. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 6/26/07

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 16528

REG. NO: N815LA


HOBBS: 6563.4

TOTAL TIME: 6563.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/26/07

Signed:



F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 6/27/07

1450 Boughton Dr.

S/N: E-2850

WORK ORDER: 16529

Bakersfield, CA 93308

REG. NO: N815LA

HOBBS: 6563.4

(661) 391-1177

TOTAL TIME: 6563.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/27/07

Signed: *Myron D. Heath*

F.A.A. A.R.S. #YWBR797L

Removed left and right wing tip strobe light assemblies S/N 9279 and 8642. Installed repaired strobe light assemblies S/N 9332 and 9096. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 7/10/07

1450 Boughton Dr.

S/N: E-2850

WORK ORDER: 16591

Bakersfield, CA 93308

REG. NO: N815LA

HOBBS: 6588.5

(661) 391-1177

TOTAL TIME: 6588.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/10/07

Signed: *Myron D. Heath*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 7/13/07

1450 Boughton Dr.

S/N: E-2850

WORK ORDER: 16606

Bakersfield, CA 93308

REG. NO: N815LA

HOBBS: 6590.9


(661) 391-1177

TOTAL TIME: 6590.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/13/07

Signed:



F.A.A. A.R.S. #YWBR797L

Removed defective aircraft battery S/N G02143853. Serviced and installed new G242 battery S/N G02271677. Run-up and operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 7/20/07

1450 Boughton Dr.

S/N: E-2850

WORK ORDER: 16626

Bakersfield, CA 93308

REG. NO: N815LA

HOBBS: 6613.3


(661) 391-1177

TOTAL TIME: 6613.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/20/07

Signed:



F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced mixture control cable. Checked for proper rigging.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/1/07

S/N: E-2850

WORK ORDER: 16694

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

REG. NO: N815LA

HOBBS: 6639.3

TOTAL TIME: 6639.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/1/07 Signed: Nyrd. Hertz F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/14/07

S/N: E-2850

WORK ORDER: 16720

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

REG. NO: N815LA

HOBBS: 6663.1

TOTAL TIME: 6663.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/14/07 Signed: Nyrd. Hertz F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 8/28/07

WORK ORDER: 16749

HOBBS: 6688.3

TOTAL TIME: 6688.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/29/07 Signed: *[Signature]*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 9/12/07

WORK ORDER: 16823

HOBBS: 6712.7

TOTAL TIME: 6712.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/12/07 Signed: *[Signature]*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 9/17/07

1450 Boughton Dr.

S/N: E-2850

WORK ORDER: 16839

Bakersfield, CA 93308

REG. NO: N815LA

HOBBS: 6721.5

(661) 391-1177

TOTAL TIME: 6721.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/17/07

Signed:

F.A.A. A.R.S. #YWBR797L

Removed defective turn & bank indicator S/N 5151. Installed new turn & bank indicator P/N 1234T100-3TZ, S/N A06-11543. Ground operational check good.

AIRFRAME LOGBOOK INSERT

[illegible]

[illegible]

YEAR:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance
DATE			
1-16-06	84-26-02	5538. ¹	Installed new induction air filter. Next due at 6038. ¹ hrs Total Time Myn D. Harts YWBR797L w/o 14621
1-16-06	97-14-15	5538. ¹	Inspected interior cabin door handles per S/B 52-2693 Rev 2 Due at next removal Myn D. Harts YWBR797L w/o 14621
6/16/06	97-14-15	5838. ²	Inspected interior cabin door handles per S/B 52-2693 Rev 2 Due at next removal Myn D. Harts YWBR797L w/o 15133
9-11-06	84-26-02	6038. ³	Installed New induction Air filter. Next Due at 6538. ³ hrs Total Time Myn D. Harts YWBR797L w/o 15452
11-3-06	97-14-15	6137. ⁵	Inspected interior cabin door handles per S/B 52-2693 Rev 2 Due at next removal Myn D. Harts YWBR797L w/o 15631
5-4-07	97-14-15	6438. ²	Inspected interior door handles per S/B 52-2693 Rev 2 Due at next removal Myn D. Harts YWBR797L w/o 16328
5-4-07	2007-08-04	6438. ²	M ^c Cauley Inspected propeller and installed Limitation placard Myn D. Harts YWBR797L w/o 16238

1-16-06	84-26-02	5538. ¹	Installed new induction air filter. Next due at 6038. ¹ hrs Total Time <i>Myr D. Harts YWBR797L w/o 14621</i>
1-16-06	97-14-15	5538. ¹	Inspected interior cabin door handles per 51352-2693 Rev 2 Due at next removal <i>Myr D. Harts YWBR797L w/o 14621</i>
6/16/06	97-14-15	5838. ²	Inspected interior cabin door handles per 51352-2693 Rev 2 Due at next removal <i>Myr D. Harts YWBR797L w/o 15133</i>
9-11-06	84-26-02	6038. ³	Installed New induction Air filter. Next Due at 6538. ³ hrs Total Time <i>Myr D. Harts YWBR797L w/o 15452</i>
11-3-06	97-14-15	6137. ⁵	Inspected interior Cabin door handles per 51352-2693 Rev 2 Due at next removal <i>Myr D. Harts YWBR797L w/o 15631</i>
5-4-07	97-14-15	6438. ²	Inspected interior door handles per 51352-2693 Rev 2 Due at next removal <i>Myr D. Harts YWBR797L w/o 16328</i>
5-4-07	2007-08-04	6438. ²	McCaughey Inspected propeller and installed limitation placard <i>Myr D. Harts YWBR797L w/o 16238</i>