N815LA





ASA-SA-2

The Standard Aircraft Log SA-2

@ 1992 - 1999 Aviation Supplies & Academics, Inc.

ISBN 1-56027-117-5 ASA-SA-2

All rights reserved. Reproduction or use, without express permission, in any manner, is prohibited.

Published by Aviation Supplies & Academics, Inc. 7005 132nd Place SE Newcastle, WA 98059-3153

Printed in Canada





Aircraft Record General Information

Book	#	6

anulacturer BEECHCRAFT	-	Model 20NAA	ZA A:	36
Serial <u>E-2850</u>	Harris Harris	Registration Nu	ımber V	815 La
Date of Manufacture				
ingine(s) currently installed:				
Manufacturer	Model		Serial	
Aanufacturer	Model		Serial	
ropeller(s) currently installed	•			
Manufacturer		Model		
IUB Model	Serial		Serial	
Blade Model	Serial	Serial _		_ Serial
				Serial

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	09-28-07	
1450 Boughton Dr.	S/N:	E2850	WORK ORDER:	16857	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6739.6	
(661) 391-1177			TOTAL TIME:	6739.6	1
The aircraft and/or component id approved for return to service wi Date: 9-28-07 Signed	th respect to the w	ork performed. Pertin	ent details of the repair are	ral Aviation Regulations and is on file at this Repair Station. A. A.R.S. #YWBR797L	
	1				

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Installed new inlet and inline filters on standby instrument air system. Repacked all wheel bearings. Installed new nosegear steering idler pivot bushing. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/10/07
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	16923
Bakersfield, CA 93308 (661) 391-1177	REG. NO:	N815LA	HOBBS:	6756.0
0-20 1 3 W 1 1 1 2 S W 1 2 F W 1			TOTAL TIME:	6756.0
The state of the s				CONTROL OF THE RESERVE OF THE PARTY OF THE P

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed Fertinent details of the repair are on file at this Repair Station.

Date: 10/10/07 Signed: My Des

F.A.A. A.R.S. #YWBR7971.

Removed inoperative attitude indicator S/N T8497A. Installed Mid-Continent Instruments West repaired indicator S/N T8678A. Ground operational check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/11/07
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	16928
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6757.4
(661) 391-1177			TOTAL TIME:	6757.4
The aircraft and/or component iden approved for return to service with Date: 10/11/07 Signature 10/11/07	respect to the w		t details of the repair are on	

Removed inoperative right wing tip strobe light assembly S/N 9096. Installed repaired strobe light assembly S/N 8491. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/12/07
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	16934
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6763.8
(661) 391-1177			TOTAL TIME:	6763.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 19/2/07 Signed: Ny Heats

F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/15/07
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	16937
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6766.1
(661) 391-1177			TOTAL TIME:	6766.1
The aircraft and/or component iden approved for return to service with Date: _/0/15/07_ Sig	respect to the we		details of the repair are ou	

Removed defective left outboard fuel quantity transmitter. Installed new transmitter P/N 96-380042-1. Safetied attaching hardware. Leak and operational check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	11/9/07	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	16969	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6788.4	
(661) 391-1177			TOTAL TIME:	6788.4	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

1.1-1 11	\sim / /	
Date: 11/9/07 Signed: 1	you Heet	F.A.A. A.R.S. #YWBR7971

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Removed engine S/N 687126. Installed new engine S/N 690485. Performed operational check of all lights and ELT. Battery Due Date: Feb 2008. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Replaced nose tire. Landing gear operation checked normal system. Replaced throttle and propeller control cables. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler. C/W AD 84-26-02 installed new induction air filter. Next due at 7288.4 hours total time. C/W S/B 77-3304 installed tachometer stabilization resistor. Run-up and taxi check good.

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 12/5/07

1450 Boughton Dr. S/N: E-2850 WORK ORDER: 17118

Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 6813.2

(661) 391-1177 TOTAL TIME: 6813.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/5/07 Signed: Wyr F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

awker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	1/15/08	00
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17243	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6840.0	
(661) 391-1177			TOTAL TIME.	Z940.0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/15/08 Signed: My Harts F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Replaced ELT battery and performed yearly inspection and functional checks per manufactures instructions. Set in the "Arm" position. New Battery Due Date: June 2010. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Replaced left main tire. Replaced left and right brake linings. Landing gear operation checked normal system. Installed new instrument air filters on the main pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Runup and taxi check good.

EMERGENCY LOCATOR TRANSMITTER
BATTERY TO BE REPLACED ON OR BEFORE

June 2010

SIGNED Hands
FOR HANKER BEECHCRAFT SERVICES YWBR797L

lawker Beechcraft Services	MODEL:	Benanza A-36	DATE:	3/7/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17439
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6913.1
(661) 391-1177			TOTAL TIME:	6913.1
paperoved for return to service with Date: 3/7/08 Signed	: Algo	Hatt		A. A.R.S. #YWBR797L
Completed Inspection #7 operational check of all light drained fuel sumps.				

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Beech A36	DATE:	19 Mar 08
12.49	S/N:	E-2850	WORK ORDER:	22-04-17469
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6939.2
(661) 391-1177			TOTAL TIME:	6939.2
the aircraft and/or component identified above approved for return to service with respect to the Date: 3-19-08 Signed:	he work perfort	ned. Pertinent dejail:	of the repair are on file a	ion Regulations : t this Repair Sta

THIS DATE AND FOUND TO COMPLY WITH FAR 91.411.

L.H. ALT. S/N: 26151 TESTED TO 20,000 FEET

R.H. ALT. S.N: ##### TESTED TO 20,000 FEET ALTITUDE REPORTING EQUIPMENT SIN: 26151

DATE: 19-Mar-08

WORK ORDER #; 22-04-17469

1450 BOUGHTON DRIVE, BAKERSFIELD, CA 93308

TO COMPLY WITH FAR 91.413.

DATE: 19-Mar-08

WORK ORDER #: 22-04-17469

HAWKER BEECHCRAFT SERVICES - CRS # YWBR797L 1450 BOUGHTON DRIVE, BAKERSFIELD, CA 93308

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	2/5/08	-
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17324	- 10
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6864.8	777
(661) 391-1177			TOTAL TIME:	6864.8	10.00
The aircraft and/or component id approved for return to service with Date: 2/5/08 Signed	h respect to the	work performed. Pertin	cut details of the repair are	ral Aviation Regul on file at this Rep A. A.R.S. #YV	air Station

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	2/21/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17360
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6888.2
(661) 391-1177			TOTAL TIME.	£888.3

The nircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/21/08 Signed: Ny Defeats F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

Their Description Control	PIODES IN	Ullatica A-50	DAIL	3/13/00	S. A. H. L. VACCO
1450 Boughton Dr.	S/N: _E-	-2850	WORK ORDER:	17468	534 5 J.A
Bakersfield, CA 93308	REG. NO: N	815LA	HOBBS:	6939.2	P .
(661) 391-1177			TOTAL TIME:	6939.2	
The aircraft and/or component ide approved for return to service with	respect to the work	performed. Pertin	ed in accordance with Fede cent details of the repair are	ral Aviation Rep on file at this F	gulations and depair Station
Date: 3/19/08 Signed:	Myrz	Heats	F.A.	A. A.R.S. #Y	WBR797
Date: 3/19/08 Signed:					

MODEL . Passes 1 26

Howker Peacharoft Contings

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Replaced right main tire. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

H	awker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	3/26/08	
	1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17494	_
	Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	6962.0	_
	(661) 391-1177			TOTAL TIME	6962.0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/26/08 Signed: Alyn Detects F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

		DATE:	4/7/08
S/N:	E-2850	WORK ORDER:	17559
REG. NO:	N815LA	HOBBS:	6987.7
		TOTAL TIME:	6987.7
respect to the	vork perforgted. Pertin	ent details of the repair are	ral Aviation Regulations and is on file at this Repair Station. A. A.R.S. #YWBR797L
	REG. NO:	REG. NO: N815LA	REG. NO: N815LA HOBBS: TOTAL TIME: tifled above was repaired and inspected in accordance with Fede respect to the work perforgised. Pertinent details of the repair are

Sharper to the state belonging to be because of

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Replaced pilot's shoulder harness assembly with repaired assembly. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	4/21/08	
1450 Boughton Dr. Bakersfield, CA 93308	S/N:	E-2850	WORK ORDER:	17610	
(661) 391-1177	REG. NO:	N815LA	HOBBS:	7011.3	
			TOTAL TIME:	7011.3	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/21/08

Signed:

....

F.A.A. A.R.S. #YWBR797L

Removed defective attitude indicator S/N T8678A. Installed Mid-Continent Instruments West overhauled indicator S/N T8448A. Ground operational check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	4/21/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17611
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7013.8
(661) 391-1177			TOTAL TIME:	7013.8
The aircraft and/or component id approved for return to service with Date: 4/21/08 Signed	h respect to the	work performed. Pertin	ent details of the repair are	

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	5/2/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17646
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7039.3
(661) 391-1177			TOTAL TIME:	7039.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work purformed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/2/08 Signed: Up S Heats F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Performed spar carry through structure inspection. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

Hawker Beechcraft Services	MODEL: Bonanza A-3	6 DATE:	5/14/08
1450 Boughton Dr.	S/N: E-2850	WORK ORDER:	17722
Bakersfield, CA 93308 (661) 391-1177	REG. NO: N815LA	HOBBS:	7064.3
Service of the servic		TOTAL TIME:	7064.3
The aircraft and/or component ident approved for return to service with r Date: 5/14/08 Signed:	espect to the work performed. Pe	rtinent details of the repair are or	t file at this Repair Station.
	- Hand	F.A.A.	A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AURFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	05-28-08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17756
Bakersfield, CA 93308 (661) 391-1177	REG. NO:	N815LA	HOBBS:	7088.5
(001) 351-1177			TOTAL TIME:	7088.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

" /// / //	
Date: 5-28-08 Signed: A Carella	F.A.A. A.R.S. #YWBR7971
7	F.M.A. A.N.S. #1 W DK/9/1

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	6/9/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17817
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7114.0
(661) 391-1177			TOTAL TIME:	7114.0
The aircraft and/or component is approved for return to service w				
Date: <u>6/9/08</u> Signe				A. A.R.S. #YWBR797

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

1	lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	6/20/08
	1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17851
	Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7139.0
	(661) 391-1177			TOTAL TIME:	7139.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/20/08 Signed: New D. Sect

F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. Installed new instrument air filters on the main pneumatic system. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

			Donnaum 12-DO	DAIE:	110/00
	1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17929
56	Bakersfield, CA 93308 (661) 391-1177	REG. NO:	N815LA	HOBBS:	7164.5
				TOTAL TIME:	7164.5
	The aircraft and/or component ide approved for return to service wit	n respect to the	work performed. Pertin	ed in accordance with Fede ent details of the repair are	ral Aviation Regulations an e on file at this Repair Statio
	Date: 7/8/08 Signed	Dun	2 Heart	F.A.	A. A.R.S. #YWBR797

MODEL: Ronours A-36

Hawker Beechcraft Services

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services 1450 Boughton Dr. Bakersfield, CA 93308	MODEL:	Bonanza A-36	DATE:	07-11-08	
	S/N:	E-2850	WORK ORDER:	17937	
(661) 391-1177	REG. NO:	N815LA	HOBBS:	7169.1	
			TOTAL TIME:	7169.1	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7-11-08

Signed: D. Muffe

F.A.A. A.R.S. #YWBR797L

Removed left strobe flash unit s/n 9332. Installed repaired strobe flash unit s/n 8913. Operation check good.

Hawker Beechcraft Services	MODEL: Bonanza A-36	DATE:	7/18/08	Hav	wker Beechcraft Services	MODEL:	Bonanza A-36	DA
1450 Boughton Dr.	S/N: _E-2850	WORK ORDER:	17960		1450 Boughton Dr.			WORK ORDI
Bakersfield, CA 93308	REG. NO: N815LA	HOBBS:	7188.6		Bakersfield, CA 93308 (661) 391-1177	REG. NO:	-	HOB
(661) 391-1177		TOTAL TIME:	7188.6		(001) 391-1117	KEG. NO;	Noisla	
approved for return to service wi	lentified above was repaired and inspect the respect to the work performed. Performed is:	nent details of the repair ar		The s	aircraft and/or component ident oved for return to service with r e: 7/24/08 Sig	respect to the w		details of the repair as
Completed Inspection #6	of Beechcraft Continuing Care	Inspection Guide P/N	N 98-36711D. Perform		COLUMN TO SERVICE DE LA COLUMN	O Comment of the	ALCOHOLOGICA CHOOSES	Service Company of the party of

operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Replaced left and right brake linings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up. and taxi check good.

AIRFRAME LOGBOOK INSERT

7/24/08 17982 7204.2 ME: 7204.2

deral Aviation Regulations and is re on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Removed inoperative turn and bank indicator S/N A06-11543. Installed new turn and bank indicator P/N 1234T100-3TZ, S/N A08-10196. Ground operational check good.

lawker Beechcraft Services	MODEL:	Вонанга А-36	DATE:	7/29/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	17998
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7213.0
(661) 391-1177			TOTAL TIME:	7213.0
approved for return to service wit	h respect to the v	work performed. Pertin	7000000	
Date: 7/29/08 Signed	: Myn	Weat Pertin	7000000	A. A.R.S. #YWBR797L
Date: 7/29/08 Signed Completed Inspection #7 of	: Slyn	Heat	F.A./	A. A.R.S. #YWBR797L

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services 1450 Boughton Dr.	MODEL:	Bonanza'A-36	DATE:	8/6/08	- 53
Bakersfield, CA 93308	S/N:	E-2850	WORK ORDER:	18060	
(661) 391-1177	REG. NO:	N815LA	HOBBS:	7231.5	
			TOTAL TIME:	7231.5	570.00

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/6/08

Signed:

lend Heats

F.A.A. A.R.S. #YWBR797L

Removed defective tachometer transducer S/N 1720B. Installed new transducer P/N 102-389015-5, S/N 4944B using new gasket. Run-up, leak and operational check.

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	8/11/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18074
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7239.7
(661) 391-1177 The aircraft and/or component is			TOTAL TIME:	
Date: <u>8/11/08</u> Signed	1: News	Hat	F.A./	A. A.R.S. #YWBR797L
Completed Inspection #8 operational check of all lig drained fuel sumps. Perform tail section, elevator and massembly. C/W S/B 52-2693 functional check. C/W AI	hts. Serviced led 100 hour hu udder. C/W 1 3 Rev 2, inspec	battery, tires and b brication. Landing BSI 0558-412 perfo tion of interior cabi	prake reservoir. Clean gear operation checked ormed visual inspection door handles. C/W A	ed induction air filter and normal system. Inspected on of cabin heater muffler D 76-07-12 Bendin switch

induction air filter. Next due at 7739.7 hours total time. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

	Hawker Beechcraft Services 1450 Boughton Dr.	MODEL:	Bonanza A-36	DATE:	8/13/08	
	Bakersfield, CA 93308	S/N:	E-2850	WORK ORDER:	18083	
	(661) 391-1177	REG. NO:	N815LA	HOBBS:	7242.7	- Carrier and Ca
				TOTAL TIME:	7242.7	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and approved for return to service with respect to the work performed. Pertiaent details of the repair are on file at this Repair Station.

Date: 8/13/68

igned: Mens

F.A.A. A.R.S. #YWBR797

Removed defective tachometer indicator S/N 1834. Installed Mid-Continent Instruments West overhauled indicator S/N 1436. Ground operational check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	8/19/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18105
Bakersfield, CA 93308 (661) 391-1177	REG. NO:	N815LA	HOBBS:	7264.1
(The aircraft and/or component id			TOTAL TIME:	7264.1
Date: 8/19/08 Signed	Alyn	fect	F.A./	A. A.R.S. #YWBR797L
Completed Inspection #9	of Beechcraft	Continuing Care 1	nspection Guide P/N	98-36711D. Performed

AIRFRAMIE LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	8/27/08	
1450 Boughton Dr. Bakersfield, CA 93308			WORK ORDER:	The second secon	-
(661) 391-1177	REG. NO:	N815LA	HOBBS:	7288.5	

TOTAL TIME: 7288.5 The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/27/08 Signed: 14 F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE	9/5/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18194
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7314.9
(661) 391-1177			TOTAL TIME:	7314.9
The aircraft and/or component id- approved for return to service wit Date: 9/5/08 Signed		work performed. Perti	ent details of the repair are	en file at this Repair Station.
Date: 9/5/AC Signad	////	A VI	IP A	L. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Benanza A-36	DATE:	9/16/08	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18224	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7339.7	
(661) 391-1177			TOTAL TIME:	7339.7	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date:	9/16/08	Signed: Slyr Dotato	F.A.A.	A.R.S.	#YWBR797L
			L'arkerba f	Tolking.	# I TY DECITE

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Replaced nose and right main tires. Installed overhauled left main gear assembly. Serviced with fluid and nitrogen. Replaced left and right nose gear door aft hinges. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Installed new instrument air filters on the standby pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	9/23/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18257
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7362.3
(661) 391-1177			TOTAL TIME:	7362.3
The aircraft and/or component iden approved for return to service with Date: 9/23/08 Signed:	respect to the wo	rk peyformed. Pertinent	details of the repair are o	a file at this Repair Station. A.R.S. #YWBR797L
				-

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10-02-08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18317
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7388.6
(661) 391-1177			TOTAL TIME	#100 c

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

A //	a details of the repair are on life at this Repair Station
Date: 10:2-08 Signed: A. Muste	F.A.A. A.R.S. #YWBR797

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed landing gear retract motor brush inspection. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

wker Beechcraft Services	MODEL:	Bonanza A-36		10/10/08	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18353	300
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7411.8	
(661) 391-1177			TOTAL TIME:	7411.8	
The aircraft and/or component is approved for return to service w	ith respect to the	work performed. Pertin	ent details of the repair are	e on file at this Repair S	tation.
pproved for return to service w Date: 19/10/08 Signe	ith respect to the	work performed. Pertin	ent details of the repair are	e on file at this Repair St	tation.
approved for return to service w	ith respect to the	work performed. Pertin	ent details of the repair are	e on file at this Repair S	tation.
approved for return to service w	rith respect to the vide:	Heats	ent details of the repair are	e on file at this Repair Si	tation.

operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced right brake linings. Removed lower Grimes oscillating beacon S/N 10377. Installed Whelen Engineering Co, Inc. flashing anti-collision light assembly P/N 01-0790033-04, S/N 017906. See 337 form dated 10/10/08. Taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/16/08
1450 Boughton Dr. Bakersfield, CA 93308	S/N:	E-2850	WORK ORDER:	18373
(661) 391-1177	REG. NO:	N815LA	HOBBS:	7428.4
			TOTAL TIME:	7428.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Perfinent details of the repair are on file at this Repair Station.

Date: 10/16/08

Signed:

F.A.A. A.R.S. #YWBR797L

Removed aft fresh air vent blower assembly S/N 371. Installed new blower assembly P/N 36-4009-1 S, kit S/N 391. Operational check good.

wker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/17/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18378
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7432.6
(661) 391-1177			TOTAL TIME:	7432.6
The aircraft and/or component id approved for return to service wit Date: /0//7/08 Signed	h respect to the	work performed. Pertin	ent details of the repair ar	eral Aviation Regulations and i e on file at this Repair Station. A. A.R.S. #YWBR797L

Removed defective pneumatic pump S/N N43642. Installed new AA3216CW pump S/N N53606 using new gasket. Cleaned lines and replaced inlet and inline filters. Run-up and system operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL: Bonanza A-36	DATE:	10/21/08	
	S/N: E-2850	WORK ORDER:	18385	
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO: N815LA	HOBBS:	7440.0	
(661) 391-1177		TOTAL TIME:	7440.0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/21/08 Signed: My Acath F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	10/27/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18415
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7462.7
(661) 391-1177			TOTAL TIME:	7462.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 16/27/03 Signed: Nyv Steet F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAMIE LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	11/11/08
1450 Boughton Dr. Bakersfield, CA 93308		E-2850	WORK ORDER:	
(661) 391-1177	REG. NO:	N815LA	HOBBS:	7488.8
			TOTAL TIME	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Replaced left brake disc and linings. Resealed left brake caliper. Installed new nose gear retract rod boot. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	11/20/08	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18545	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7514.4	
(661) 391-1177			TOTAL TIME:	7514.4	
The aircraft and/or component ld approved for return to service wit Date: ///20/08 Signed	h respect to the	work performed. Pertin	ent details of the repair are	ral Aviation Regulations and is e on file at this Repair Station. A. A.R.S. #YWBR797L	

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

wker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	12/8/08
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18617
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7538.8
(661) 391-1177			TOTAL TIME:	7538.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 0/8/08 Signed: My Seate F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

		THE REAL PROPERTY AND ADDRESS OF THE PARTY O		Verience A
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18666
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7562.8
(661) 391-1177			TOTAL TIME:	7562.8
The aircraft and/or component id- approved for return to service wit Date: 12/20/08 Signed	h respect to the	work performed. Pertinent	details of the repair are	

DATE: 12/20/08

MODEL: Ronanza A.36

Hawker Beechcraft Services

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	1/5/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18732
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7579.0
(661) 391-1177			TOTAL TIME:	7579.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Avlation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Signed: Mars Acet

F.A.A. A.R.S. #YWBR797L

Removed defective attitude indicator S/N T8448A. Installed Mid-Continent Instruments West overhauled indicator S/N T8857A. Ground operational check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	1/8/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18744	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7588.5	
(661) 391-1177			TOTAL TIME.	7599 5	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/8/09 Signed: My Defeate F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Performed ELT yearly inspection and functional checks per manufactures instructions. Battery Due Date: Aug 2009. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	1/14/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18771	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7613.6	
(661) 391-1177			TOTAL TIME:	7613.6	

The aircraft ant/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Date: 1/14/09 Signed: Nyw D. Heart

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	1/24/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18798
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7637.3
(661) 391-1177			TOTAL TIME:	7637.6
The nircraft and/or component id approved for return to service with Date: 1/24/09 Signed	h respect to the	as repaired and inspects work performed. Pertin	ent details of the repair ar	ral Aviation Regulations and is on file at this Repair Station. A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. Replaced right aileron push-pull tube rod end bearings. Replaced right rear seat shoulder harness assembly with repaired assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. C/W AD 2008-13-17 replaced all affected circuit breaker toggle switches per S/B 24-3735. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	2/3/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18876
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7664.8
(661) 391-1177			TOTAL TIME:	7664.8
The aircraft and/or component ident approved for return to service with a Date: 2/3/09 Signed:	espect to the wo	rk performed. Pertinent	details of the repair are o	

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced left main tire. Landing gear operation checked normal system.

Hawker Beechcraft Services	MODEL	Bonanza A-36	DATE:	2/13/09	-
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18910	- 1 3d
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7686.8	
(661) 391-1177	*		TOTAL TIME:	7686.8	No.

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Perfinent details of the repair are on file at this Repair Station.

Date: 2/13/09 Signed: My O. Heatt F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	2/25/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	18945	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7712.8	
(661) 391-1177			TOTAL TIME:	7712.8	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work psylormod. Pertinent details of the repair are on file at this Repair Station.

Date: 2/25/09 Signed: My Le facto

F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and dramed fuel sumps.

wker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	3/11/09	100
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19009	- de
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7738.7	
(661) 391-1177 The aircraft and/or component is	The Editor State of the Control of t		TOTAL TIME:		

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-3671ID. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned fuel filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. Installed new instrument air filters on the main pneumatic system. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 installed new Bendix switch. C/W AD 2007-08-04 McCauley propeller inspection. C/W AD 84-26-02 installed new induction air filter. Next due at 8238.7 hours total time. Run-up and taxt check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	3/20/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19053	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7764.3	_
(661) 391-1177			TOTAL TIME.	2264.2	_

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/20/09 Signed: Myn Heart

F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced right main tire and brake disc. Replaced left and right brake linings. Run-up and taxi check good.

Hawker Beechcraft Services	MODEL:	Honanza A-30	DATE	4/1/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19095
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7789.5
(661) 391-1177			TOTAL TIME:	7789.5
The aircraft and/or component id approved for return to service with Date: 4/1/09 Signed	th respect to the	work performed. Pertin	ent details of the repair are	ral Aviation Regulations and is on file at this Repair Station. A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Duc Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	4/16/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19178	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7813.0	-,0.3
(661) 391-1177			TOTAL TIME.	7813.0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Date: 4/16/09 Signed: New Heart

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	4/28/09
Marine Lange	S/N:	E-2850	WORK ORDER:	19212
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7839.1
(661) 391-1177			TOTAL TIME:	7839.1
The aircraft and/or component is approved for return to service w	dentified above w ith respect to the	as repaired and inspect work performed. Pertin	ed in accordance with Fede ent details of the repair are	ral Aviation Regulations and is son file at this Repair Station.

Date: 4/29/09 Signed: Algor Heat F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Вопания А-36	DATE:	5/7/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19285
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7863.6
(661) 391-1177			TOTAL TIME:	7863.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/7/09 Signed: My Heath F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

ISMKGL Descrictary on Arces	THE COLUMN	Donance U. 20		
State Land	S/N:	E-2850	WORK ORDER:	19295
1450 Boughton Dr. Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7876.5
(661) 391-1177			TOTAL TIME:	7876.5
The aircraft and/or component iden approved for return to service with Date: 5/12/09 Si	respect to the w	repaired and inspected ork performed. Pertinen	t details of the repair are on	Aviation Regulations and is file at this Repair Station. A. A.R.S. #YWBR797
Removed defective manifold operational check good.	pressure indi	cator S/N 2432. In	stalled new indicator S/	N 4252. Ground run a

DATE: 5/12/09

AIRFRAME LOGBOOK INSERT

tawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	5/13/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19299
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7879.2
(661) 391-1177			TOTAL TIME:	7879.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed Pertinent details of the repair are on file at this Repair Station.

Date: 5/13/09 Signed: My Heat

F.A.A. A.R.S. #YWBR797L

Removed defective attitude indicator S/N T8857A. Installed Mid-Continent Instruments West overhauled indicator S/N T8567A. Ground operational check good.

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	5/18/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19314
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7888.0
(661) 391-1177			TOTAL TIME:	7888.0

Date: 5/18/09 Signed: Mund Healt F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and allerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	6/1/09
1450 Boughton Dr. Bakersfield, CA 93308 (661) 391-1177	S/N:	E-2850	WORK ORDER:	19395
	REG. NO:	N815LA	HOBBS:	7914.2
			TOTAL TIME:	7914.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

awker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	6/16/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19425	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7938.6	
(661) 391-1177		_	TOTAL TIME:	7938.6	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/16/09 Signed: Sly Host F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Replaced nose tire. Resealed right brake caliper. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Performed spar carry through structure inspection. Installed new flap motor and gearbox assembly S/N 1962A. Left and right flap actuators S/N 671-A-93 and S/N 698-B-93 were overhauled and reinstalled. Installed new left and right flap flex drive cables. Installed new instrument air filters on the standby pneumatic system. Removed turn & bank indicator S/N A08-10196. Installed overhauled indicator S/N A08-10238. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W s/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	6/26/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19484	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7964.5	
(661) 391-1177			moment meses		

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/24/09 Signed: Mun Heath F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AURTRAMIE LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-30	_ DATE:	6/29/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19492
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7967.1
(661) 391-1177			TOTAL TIME:	7967.1
e aircraft and/or component iden proved for return to service with	respect to the w	ork performed. Pertinent	n accordance with Federal details of the repair are on	Aviation Regulations and is file at this Repair Station,
te: 6/29/09 Si	ened: Me.	Dikak	F.A.	A. A.R.S. #YWBR7971

temoved inoperative turn and bank indicator S/N A08-10238. Installed Mid-Continent Instruments West verhauled indicator S/N C07-11637. Ground operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	7/2/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19542
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7979.9
(661) 391-1177			TOTAL TIME.	7070 0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/2/09 Signed: Mars. Heats F.A.A. A.R.S. #YWBR797L

Removed defective pneumatic pump S/N N53606. Installed new AA3216CW pump S/N N58435 using new gasket. Cleaned lines and replaced inlet and inline filters. Installed new annunciator light pressure switch. Runup and system operational check good. Removed inoperative #2 inverter S/N 2954. Installed inspected inverter S/N 2890. Ground operational check good.

		Dommara 10-00		112102
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19557
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	7987.8
(661) 391-1177			TOTAL TIME:	7987.8
The aircraft and/or component id approved for return to service wi				
Date: 7/9/09 Signed	: Dears	Heat	F.A.	A. A.R.S. #YWBR7971

MODEL . Beneves A 26

Hawker Beechgraft Services

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

awker Beechcraft Services	MODEL:	Вопания А-36	DATE:	7/20/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19594	178E2
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	8014.5)XW
(661) 391-1177			TOTAL TIME:	8014.5	5-330

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/20/09 Signed: My of feel F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced left main tire and brake linings. Landing gear operation checked normal system. Taxi check good.

Haw	ker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	7/28/09	
1450 Boughton Dr. Bakersfield, CA 93308	S/N:	E-2850	WORK ORDER:	19625	- 15	
	REG. NO:	N815LA	HOBBS:	8039.0		
	(661) 391-1177			TOTAL TIME:	8039.0	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/20/09 Signed: My Heats F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Removed aft fresh air blower assembly S/N 1070. Installed new blower kit P/N 36-4009-1 S, S/N 397-1098. C/W BSI 0558-412 installed new cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	8/10/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19705
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	8063.8
(661) 391-1177			TOTAL TIME:	8063.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 0/10/09 Signed: New Heatt F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

awker Beecho	raft Services	MODEL:	Bonanza A-36	DATE:	8/19/09	
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19737		
Bakersfield,	CA 93308	REG. NO:	N815LA	HOBBS:	8089.7	
(661) 39	1-1177			TOTAL TIME:	8089.7	

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/19/09 Signed: My Sheat F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	8/27/09	
- 1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19790	
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	8113.7	7,35
(661) 391-1177			TOTAL TIME:	8113.7	-

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/27/09 Signed: Nym Year F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

awker	Beechcraft Services	MODEL:	Bonanza A-36	DATE:	9/8/09
	1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19859
		REG. NO:	N815LA	HOBBS:	8139.1
				TOTAL TIME:	8139.1
					ral Aviation Regulations and is on file at this Repair Station.

Date: 9/8/09 Signed: Myn State F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Replaced right main tire. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services	MODEL:	Bonanza A-36	DATE:	9/17/09
1450 Boughton Dr.	S/N:	E-2850	WORK ORDER:	19901
Bakersfield, CA 93308	REG. NO:	N815LA	HOBBS:	8164.0
(661) 391-1177			TOTAL TIME:	8164.0
Data: 9/17/19 Si	mad: Al	und Arakt	- FA	A A D C #VIUDD707I

This Log Book Closed This Time and Date

Aircraft Total Time in Service 8164.0 hours