

N815LA



The Standard

AIRCRAFT LOG

BOOK #7

ASA-SA-2

The Standard Aircraft Log
SA-2

© 1991-2007 Aviation Supplies & Academics, Inc.

ASA-SA-2

ISBN 1-56027-117-5
978-1-56027-117-8

All rights reserved.
Reproduction or use, without express permission,
in any manner, is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE
Newcastle, WA 98059-3153
Website: www.asa2fly.com
Email: asa@asa2fly.com

Printed in China



PNR ASA-SA-2

ISBN 978-1-56027-117-8



9 781560 271178

5 1 2 9 5



Aircraft Record General Information

Book #7

Manufacturer Beech Model A-36
Serial E-2850 Registration Number N015LA
Date of Manufacture 3/14/94

Engine(s) currently installed:

Manufacturer TCM Model T0-550-B Serial _____
Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer McCawley Model D3A32C409-C
HUB Model _____ Serial _____ Serial _____
Blade Model _____ Serial _____ Serial _____ Serial _____
Blade Model _____ Serial _____ Serial _____ Serial _____

YEAR
20
DATE

lawker Beechcraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA

DATE: 9/18/09
WORK ORDER: 19902
HOBBS: 8164.0
TOTAL TIME: 8164.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/19/09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed inoperative turn and bank indicator S/N C07-11637. Installed Mid-Continent Instruments West repaired indicator S/N M05-10051. Ground operational check good.

AIRFRAME LOGBOOK INSERT

YEAR
20

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
EQUIPMENT

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility (See back pages for other specific entries)

lawker Beechcraft Services
1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Beech A36
S/N: E-2850
REG. NO: N815LA

DATE: 09/24/09
WORK ORDER: 19929
HOBBS: 8180.8
TOTAL TIME: 8180.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9-24-09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed turn and bank indicator s/n M05-10051 and installed repaired turn and bank indicator s/n A06-11547. Ground ops checked ok.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Beech A36 DATE: 09/25/09
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 19930
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8181.9
(661) 391-1177 TOTAL TIME: 8181.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9-25-09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed turn and bank indicator s/n A06-11547 and installed repaired turn and bank indicator s/n K07-11042.
Ground ops checked ok.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 9/29/09
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 19943
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8187.3
(661) 391-1177 TOTAL TIME: 8187.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/29/09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Replaced fuel cap o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 10/8/09
 1450 Boughton Dr. S/N: E-2850 WORK ORDER: 20024
 Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8214.2
 (661) 391-1177 TOTAL TIME: 8214.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/8/09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 10/26/09
 1450 Boughton Dr. S/N: E-2850 WORK ORDER: 20065
 Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8237.7
 (661) 391-1177 TOTAL TIME: 8237.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/26/09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Removed landing gear actuator gearbox assembly S/N 14826. Installed repaired actuator assembly S/N 10775 with serviceable retract motor S/N 624 with 40 hours time in service. Replaced nose gear retract rod end bearings and plunger. Installed new dynamic brake replay P/N SM50D7. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Installed all new wing attach hardware. Lubed torqued per manual. Installed new instrument air filters on the main pneumatic system. S/B 32-3990 N/A by purchase date of replacement part. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. C/W AD 84-26-02 installed new induction air filter. Next due at 8737.7 hours total time. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

AUTHORIZED RE-FAISSAGE
 FAA/UNITED STATES
 Authority/Country

YES
20
DATE

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 11-04-09

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20164

REG. NO: N815LA

HOBBS: 8264.5

TOTAL TIME: 8264.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11-4-09

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 11/9/09

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20184

REG. NO: N815LA

HOBBS: 8272.4

TOTAL TIME: 8272.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/9/09

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed defective aircraft battery S/N G02271677. Serviced and installed new G242 battery S/N G02431005. Cleaned battery box and terminal ends. Run-up and system operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 11/16/09

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20199

REG. NO: N815LA

HOBBS: 8289.3

TOTAL TIME: 8289.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/16/09 Signed: *Nyrd Heest*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 12/3/09

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20298

REG. NO: N815LA

HOBBS: 8313.0

TOTAL TIME: 8313.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/3/09 Signed: *Nyrd Heest*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced right brake linings. Taxi check good.

AIRFRAME LOGBOOK INSERT

YF

21 Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 12/17/09S/N: E-2850WORK ORDER: 203341450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177REG. NO: N815LAHOBBS: 8337.8TOTAL TIME: 8337.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/17/09 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Performed ELT yearly inspection and functional checks per manufactures instructions. Set in the "Arm" position. Battery Due Date June 2010. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT



lawker Beechcraft Services

MODEL: Bonanza A-36DATE: 12/29/09S/N: E-2850WORK ORDER: 203631450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177REG. NO: N815LAHOBBS: 8350.9TOTAL TIME: 8350.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with:

Date: 12/29/09

Removed defective fuel flo
S/N 1266. Ground operati

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: WFR00141933	
4. Organization Name and Address:  MID-CONTINENT INSTRUMENTS WEST 16320 STAGG ST VAN NUYS, CA 91406-1717 FAA CRS 01200611				5. Work Order/Contract/Invoice Number: WFR00141933		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Quantity:	11. Serial/Part Number:	12. Status/Work:
1	FUEL FLOP NO	10147 26 50-360-187	1	1	1266	REPAIRED
13. Remarks: THE WORK ORDER REFERENCED DESCRIBES THE ACTUAL WORK PERFORMED. ALL WORK WAS PERFORMED REF. MANUAL # 4013 9/05 The work specified in block 12713 except as otherwise specified was carried out in accordance with EASA Part 145 and in respect to that work the aircraft component is considered ready for release to service under EASA Approval Certificate Number EASA.145.AE24						
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				15. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in block 13, the work specified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
16. Authorized Signature: 		17. Approval/Authorization No.:		18. Authorized Signature: 		19. Approval Certificate No.: FAA CRS 01200611
20. Name (Typed or Printed): EDWARD GILLS		21. Date (Month):		22. Name (Typed or Printed): EDWARD GILLS		23. Date (MM/YY): 12/29/09
User/Installer Responsibility: It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component assembly. Where the user/installer performs work in accordance with the national regulations of an EASA/FAA authority different from the EASA/FAA authority of the country specified in Block 1, it is essential that the user/installer ensures that neither EASA/FAA accepts parts/component assemblies from the EASA/FAA authority of the country specified in Block 1.						
Statements in Blocks 14 and 15 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installed on certificate issued in accordance with the national regulations by the installation before the aircraft may be flown.						

YF
21 Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 12/17/09
D 1450 Boughton Dr. S/N: E-2850 WORK ORDER: 20334
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8337.8
(661) 391-1177 TOTAL TIME: 8337.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/17/09 Signed: Ney D. Heats F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711D. Performed operational checks of all lights. Performed ELT yearly inspection and functional checks per manufactures instructions. Set in the "Arm" position. Battery Due Date June 2010. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 12/29/09
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 20363
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8350.9
(661) 391-1177 TOTAL TIME: 8350.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/29/09 Signed: Ney D. Heats F.A.A. A.R.S. #YWBR797L

Removed defective fuel flow indicator S/N 1294. Installed Mid-Continent Instruments West repaired indicator S/N 1266. Ground operational check good.

AIRFRAME LOGBOOK INSERT

Y
2
B

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 1/4/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20412

REG. NO: N815LA

HOBBS: 8355.4

TOTAL TIME: 8355.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/4/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed defective fuel flow transducer S/N 79175. Installed new transducer P/N 102-389012-11, S/N 167584. Run-up, leak and operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 1/6/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20419

REG. NO: N815LA

HOBBS: 8362.2

TOTAL TIME: 8362.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/6/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

YF
 2 Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 1/28/10
 B 1450 Boughton Dr. S/N: E-2850 WORK ORDER: 20469
 Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8388.6
 (661) 391-1177 TOTAL TIME: 8388.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/28/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Removed shimmy damper. Installed new Lord shimmy damper P/N SE1076-1, S/N LK00286 per Lord STC SA00609DE. See 337 form dated 1/26/10. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Replaced pilot's shoulder harness with repaired assembly. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 02-11-10
 1450 Boughton Dr. S/N: E-2850 WORK ORDER: 20551
 Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8413.0
 (661) 391-1177 TOTAL TIME: 8413.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2-11-10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Installed new tire, brake disc, and brake linings on left main gear wheel. Landing gear cycle check good. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 2/23/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20586

REG. NO: N815LA

HOBBS: 8431.3

TOTAL TIME: 8431.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/23/10

Signed: Myron D. Healy

F.A.A. A.R.S. #YWBR797L

Removed defective attitude indicator S/N T8567A. Installed Mid-Continent Instruments West repaired indicator S/N T8565A. Ground operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 2/26/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20593

REG. NO: N815LA

HOBBS: 8437.1

TOTAL TIME: 8437.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/26/10

Signed: Myron D. Healy

F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: June 2010. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Y
2
D

Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 3/16/101450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177S/N: E-2850WORK ORDER: 20692REG. NO: N815LAHOBBS: 8464.2TOTAL TIME: 8464.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/16/10Signed: *Alvin D. Heath*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36DATE: 4/15/101450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177S/N: E-2850WORK ORDER: 20823REG. NO: N815LAHOBBS: 8488.9TOTAL TIME: 8488.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/15/10Signed: *Steve Casale*

F.A.A. A.R.S. #YWBR797L

THE STATIC PRESSURE SYSTEM AND THE ALTITUDE REPORTING EQUIPMENT WERE INSPECTED AND TESTED THIS DATE AND FOUND TO COMPLY WITH FAR 91.411.

THE ATC TRANSPONDER S/N: 10799 WAS INSPECTED AND TESTED THIS DATE AND FOUND TO COMPLY WITH FAR 91.413.

L.H. ALT. S/N: 26151

TESTED TO 20,000 FEET

R.H. ALT. S.N: #####

TESTED TO 20,000 FEET

ALTITUDE REPORTING EQUIPMENT S/N: 26151

AIRFRAME LOGBOOK INSERT

2 Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 4/16/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20734

REG. NO: N815LA

HOBBS: 8488.9

TOTAL TIME: 8488.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/16/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Removed engine S/N 690485. Installed factory new engine S/N 1001906. Propeller S/N 932354 was overhauled and reinstalled. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned fuel filter and drained fuel sumps. Inspected wings, flaps and ailerons. Inspected fuel cap and replaced o-ring seals. Checked emergency exits for condition and operation. Installed new standby pneumatic system filters and pump S/N 860681. Installed new throttle, mixture and propeller control cables. Installed new tachometer transducer S/N 123B. Installed repaired tachometer indicator S/N 3354. Installed new manifold pressure gauge S/N 615429. Installed new pilot's right brake master cylinder S/N 3716FRA. Installed new left muffler. C/W BSI 0558-412 performed pressure test and visual inspection on cabin heater muffler assembly. C/W AD 84-26-02 installed new induction air filter. Next due at 8988.9 hours total time. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 4/30/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20867

REG. NO: N815LA

HOBBS: 8514.2

TOTAL TIME: 8514.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/30/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 5/4/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20907

REG. NO: N815LA

HOBBS: 8514.8

TOTAL TIME: 8514.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/4/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed inoperative left wing tip strobe light assembly S/N 8913. Installed repaired strobe light assembly S/N 8916. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 5/14/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 20945

REG. NO: N815LA

HOBBS: 8538.3

TOTAL TIME: 8538.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/14/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Replaced ELT battery and performed yearly inspection and functional checks per manufactures instructions. New Battery Due Date: July 2012. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. Installed new instrument air filters on the main pneumatic system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 06-02-10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21026

REG. NO: N815LA

HOBBS: 8564.8

TOTAL TIME: 8564.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6-2-10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 6/16/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21058

REG. NO: N815LA

HOBBS: 8588.2

TOTAL TIME: 8588.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/16/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: July 2012. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Lawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 6/25/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21105

REG. NO: N815LA

HOBBS: 8612.1

TOTAL TIME: 8612.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/25/10 Signed: *Wyn D. Heath* F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Lawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 7/15/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21177

REG. NO: N815LA

HOBBS: 8632.1

TOTAL TIME: 8632.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/15/10 Signed: *Wyn D. Heath* F.A.A. A.R.S. #YWBR797L

Removed landing gear actuator gearbox assembly. Disassembled, cleaned and inspected all parts. Reassembled using all new o-rings, seals and bearings. Re-timed internally, lubricated and safetied. Reinstalled original motor S/N 624 with 435 hours time in service. Reinstalled in aircraft. Landing gear rigging and operation checked normal and manual systems.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 7/21/10

WORK ORDER: 21212

HOBBS: 8639.1

TOTAL TIME: 8639.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/21/10 Signed: *Myrd D. Heath* F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational checks of all lights and ELT. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Removed defective turn and bank indicator S/N K07-11042. Installed overhauled indicator S/N B06-10715. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36

S/N: E-2850

REG. NO: N815LA

DATE: 7/30/10

WORK ORDER: 21259

HOBBS: 8662.3

TOTAL TIME: 8662.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/30/10 Signed: *Myrd D. Heath* F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/5/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21311

REG. NO: N815LA

HOBBS: 8670.4

TOTAL TIME: 8670.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/5/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed defective turn and bank indicator S/N B06-10715. Installed Mid-Continent Instruments West overhauled indicator S/N M05-10267. Ground operational check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/13/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21333

REG. NO: N815LA

HOBBS: 8684.3

TOTAL TIME: 8684.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/13/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed defective left outboard fuel quantity transmitter. Installed new transmitter P/N 96-380042-1, S/N 2626 using new gasket. Operational and leak check good.

AIRFRAME LOGBOOK INSERT

2 Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 8/16/10
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 21330
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8687.4
(661) 391-1177 TOTAL TIME: 8687.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/16/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Replaced left and right brake linings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 8/17/10
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 21343
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8688.3
(661) 391-1177 TOTAL TIME: 8688.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/17/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective landing gear dynamic brake relay. Installed new relay P/N SM50D7. Operational and rigging check of landing gear system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/27/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21375

REG. NO: N815LA

HOBBS: 8713.3

TOTAL TIME: 8713.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/27/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 9/1/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21426

REG. NO: N815LA

HOBBS: 8722.7

TOTAL TIME: 8722.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/1/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective left outboard fuel quantity transmitter. Installed new transmitter P/N 96-380042-1, S/N 2649 using new gasket. Operational and leak check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 9/9/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21449

REG. NO: N815LA

HOBBS: 8734.4

TOTAL TIME: 8734.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/9/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed attitude indicator S/N T8565A. Installed Mid-Continent Instruments West overhauled indicator S/N T8869A. Ground operational check good.

AIRFRAME LOGBOOK INSERT

lawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 9/9/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21450

REG. NO: N815LA

HOBBS: 8734.4

TOTAL TIME: 8734.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/9/10

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed turn and bank indicator S/N M05-10267. Installed Mid-Continent Instruments West repaired indicator S/N F05-11254. Ground operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 9/10/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21453

REG. NO: N815LA

HOBBS: 8738.6

TOTAL TIME: 8738.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/10/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. Installed new right fuel sump drain valve. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 09-23-10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21498

REG. NO: N815LA

HOBBS: 8762.8

TOTAL TIME: 8762.8

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/23/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 10/13/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21572

REG. NO: N815LA

HOBBS: 8788.1

TOTAL TIME: 8788.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/13/10 Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Inspected fuel cap and replaced o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 10/26/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21613

REG. NO: N815LA

HOBBS: 8813.2

TOTAL TIME: 8813.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/26/10 Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Installed new forward cabin door interior handle and decal per AD 97-14-15.

AIRFRAME LOGBOOK INSERT

YE
20
BA
Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 11-09-10
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 21680
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8838.3
(661) 391-1177 TOTAL TIME: 8838.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/9/10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Performed spar carry-thru structure inspection. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection and pressure test of cabin heater muffler assembly. Installed repaired co-pilots shoulder harness and reel. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 11-19-10
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 21740
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 8863.7
(661) 391-1177 TOTAL TIME: 8863.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11-19-10 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 12/3/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21809

REG. NO: N815LA

HOBBS: 8882.3

TOTAL TIME: 8882.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/3/10

Signed: *Myron D. Heats*

F.A.A. A.R.S. #YWBR797L

Removed defective pneumatic pump S/N N58435. Installed new AA3216CW pump S/N I2807-03 using new gasket. Cleaned lines and replaced inlet and inline filters. Run-up and system operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 12/22/10

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21818

REG. NO: N815LA

HOBBS: 8889.3

TOTAL TIME: 8889.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/22/10

Signed: *Myron D. Heats*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: July 2012. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Checked emergency exits for condition and operation. Installed forward spar carry through structure repair kit P/N 36-4004-5 S, S/N 486 per kit installation instructions. Installed new forward spar cover assembly. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 1/6/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21933

REG. NO: N815LA

HOBBS: 8914.0

TOTAL TIME: 8914.0

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/6/11

Signed: *Myndy Heath*

F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 1/6/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 21929

REG. NO: N815LA

HOBBS: 8910.9

TOTAL TIME: 8910.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/6/11

Signed: *Myndy Heath*

F.A.A. A.R.S. #YWBR797L

Removed inoperative left wing strobe light assembly S/N 8916. Installed repaired strobe light assembly S/N 9381. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA

DATE: 1/18/11
WORK ORDER: 21967
HOBBS: 8938.5
TOTAL TIME: 8938.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/18/11 Signed: *Myrd. Heatt* F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational checks of all lights and ELT. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned fuel filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. C/W AD 84-26-02 installed new induction air filter. Next due at 9438.5 hours total time. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA

DATE: 1/28/11
WORK ORDER: 22000
HOBBS: 8959.5
TOTAL TIME: 8959.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/28/11 Signed: *Myrd. Heatt* F.A.A. A.R.S. #YWBR797L

Removed defective attitude indicator S/N T8869A. Installed Mid-Continent Instruments West overhauled indicator S/N T8707A. Ground operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 1/31/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22009

REG. NO: N815LA

HOBBS: 8964.4

TOTAL TIME: 8964.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 1/31/11 Signed: *Myrd Heath* F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced left main and nose tires. Replaced left and right brake linings. Landing gear operation checked normal system. Taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 2/10/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22066

REG. NO: N815LA

HOBBS: 8988.2

TOTAL TIME: 8988.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2/10/11 Signed: *Myrd Heath* F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Fitted, painted and installed new left nose gear door assembly P/N 35-410077-44. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Performed flap actuator and flex drive cable lubrication. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 02-28-11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22128

REG. NO: N815LA

HOBBS: 9014.7

TOTAL TIME: 9014.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 2-28-11

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 3/8/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22187

REG. NO: N815LA

HOBBS: 9029.1

TOTAL TIME: 9029.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/8/11

Signed: [Signature]

F.A.A. A.R.S. #YWBR797L

Removed fuel boost pump S/N 1056. Installed new boost pump P/N 4613-00-5, S/N 1593 with manufacture date of 07/16/09. Replaced o-ring seal on fittings. Operational and leak check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA

DATE: 3/14/11
WORK ORDER: 22196
HOBBS: 9038.6
TOTAL TIME: 9038.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/14/11 Signed: *Nyr D. Heath* F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. Installed new instrument air filters on the standby pneumatic system. Replaced pilot's shoulder harness with repaired assembly. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

MODEL: Bonanza A-36
S/N: E-2850
REG. NO: N815LA

DATE: 3/18/11
WORK ORDER: 22223
HOBBS: 9043.2
TOTAL TIME: 9043.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/18/11 Signed: *Nyr D. Heath* F.A.A. A.R.S. #YWBR797L

Removed inoperative right wingtip strobe light assembly S/N 8491. Installed repaired strobe light assembly S/N 8970. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 3/29/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22250

REG. NO: N815LA

HOBBS: 9061.7

TOTAL TIME: 9061.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 3/29/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 4/13/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22331

REG. NO: N815LA

HOBBS: 9087.9

TOTAL TIME: 9087.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/13/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Inspected fuel cap and replaced o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 4/26/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22361

REG. NO: N815LA

HOBBS: 9112.6

TOTAL TIME: 9112.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 4/26/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Replaced right main tire. Landing gear operation checked normal system. Taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 5/4/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22422

REG. NO: N815LA

HOBBS: 9127.1

TOTAL TIME: 9127.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/4/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective turn & bank indicator S/N F05-11254. Installed Mid-Continent Instruments West repaired indicator S/N E08-10780. Ground operational check good.

AIRFRAME LOGBOOK INSERT

2 Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 5/10/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22432

REG. NO: N815LA

HOBBS: 9139.6

TOTAL TIME: 9139.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/10/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #12 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Performed ELT yearly inspection and functional checks per manufactures instructions. Set in the "Arm" position. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Repacked all wheel bearings. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Performed cabin interior inspection. Checked control cable tensions. Inspected tail section, elevator and rudder. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 27-3459 inspection of flight control gust lock. C/W AD #97-14-15 inspected interior cabin door handles per S/B 52-2693 Rev 2. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 5/24/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22475

REG. NO: N815LA

HOBBS: 9163.7

TOTAL TIME: 9163.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/24/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #1 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 5/31/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22490

REG. NO: N815LA

HOBBS: 9167.2

TOTAL TIME: 9167.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 5/31/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective 8-day clock S/N W80713. Installed repaired clock S/N W80534. Wound clock and set current time. Removed defective tachometer indicator S/N 3354. Installed repaired indicator S/N 3755. Run-up and ground operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 6/1/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22534

REG. NO: N815LA

HOBBS: 9168.7

TOTAL TIME: 9168.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/1/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective tachometer transducer S/N 5123B. Installed new transducer P/N 102-389015-5, S/N 5242B using new gasket. Run-up and system operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 6/14/11
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 22557
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 9187.5
(661) 391-1177 TOTAL TIME: 9187.5

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/14/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #2 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: July 2012. Set in the "Arm" position. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed operational checks of aircraft systems per inspection guide. Installed new instrument air filters on the main pneumatic system. Installed new propeller governor control arm and rod end bearing. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 6/28/11
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 22599
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 9214.1
(661) 391-1177 TOTAL TIME: 9214.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 6/28/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #3 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 7/15/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22679

REG. NO: N815LA

HOBBS: 9238.6

TOTAL TIME: 9238.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 7/15/11

Signed: M. D. Heath

F.A.A. A.R.S. #YWBR797L

Completed Inspection #4 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational checks of all lights and ELT. Battery Due Date: July 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. C/W BSI 0558-412 performed pressure test and visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/8/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22788

REG. NO: N815LA

HOBBS: 9264.1

TOTAL TIME: 9264.1

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/8/11

Signed: M. D. Heath

F.A.A. A.R.S. #YWBR797L

Completed Inspection #5 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/15/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22803

REG. NO: N815LA

HOBBS: 9274.6

TOTAL TIME: 9274.6

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/15/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed inoperative fresh air blower assembly S/N 1098. Installed new blower kit assembly P/N 36-4009-1S, kit S/N 425-1136. Operational check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 8/23/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22819

REG. NO: N815LA

HOBBS: 9287.4

TOTAL TIME: 9287.4

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 8/23/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #6 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Repacked all wheel bearings. Replaced left and right brake linings. Replaced left main gear anti-ice boot. Performed landing gear inspection and rigging. Landing gear operation checked normal and manual systems. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 9/8/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22904

REG. NO: N815LA

HOBBS: 9314.9

TOTAL TIME: 9314.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9/8/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #7 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 09/27/2011

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 22936

REG. NO: N815LA

HOBBS: 9338.3

TOTAL TIME: 9338.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 9-27-11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #8 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights and ELT. Battery Due Date: Jul 2012. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Performed 100 hour lubrication. Landing gear operation checked normal system. Inspected tail section, elevator and rudder. Removed left and right elevator trim actuators and installed repaired elevator trim actuator S/N 21566-1 on left side, S/N 21566-2 on right side. Replaced right elevator hinge assembly. C/W BSI 0558-412 performed visual inspection of cabin heater muffler assembly. C/W S/B 52-2693 Rev 2, inspection of interior cabin door handles. C/W AD 76-07-12 Bendix switch functional check. C/W AD 2007-08-04 McCauley propeller inspection. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

FAA/UNITED STATES AUTHORIZED RELEASE
FAA FORM 8130-3, AIRWORTHINESS
Continuing Care Services

Y
2
E
Hawker Beechcraft Services MODEL: Bonanza A-36 DATE: 10/19/11
1450 Boughton Dr. S/N: E-2850 WORK ORDER: 23044
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 9364.3
(661) 391-1177 TOTAL TIME: 9364.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10/19/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Completed Inspection #9 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Y
2
B
Hawker Beechcraft Services MODEL: Bonanza A36 DATE: 10/27/11
1450 Boughton Dr. S/N: E2850 WORK ORDER: 22766
Bakersfield, CA 93308 REG. NO: N815LA HOBBS: 9376.2
(661) 391-1177 TOTAL TIME: 9376.2

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 10-27-11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective transponder KT 70 s/n 10799 and installed overhauled exchanged transponder KT 70 s/n 10669. Re-tested transponder system. Ground checked OK.

THE ATC TRANSPONDER S/N: 10669
WAS INSPECTED AND TESTED THIS DATE AND FOUND
TO COMPLY WITH FAR 91.413.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 11/2/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 23075

REG. NO: N815LA

HOBBS: 9388.9

TOTAL TIME: 9388.9

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/2/11

Signed: M. D. Heath

F.A.A. A.R.S. #YWBR797L

Completed Inspection #10 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps. Inspected wings, flaps and ailerons. Inspected fuel cap and replaced o-ring seals. Checked emergency exits for condition and operation. Run-up and taxi check good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 11/30/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 23209

REG. NO: N815LA

HOBBS: 9412.3

TOTAL TIME: 9412.3

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 11/30/11

Signed: M. D. Heath

F.A.A. A.R.S. #YWBR797L

Completed Inspection #11 of Beechcraft Continuing Care Inspection Guide P/N 98-36711J. Performed operational check of all lights. Serviced battery, tires and brake reservoir. Cleaned induction air filter and drained fuel sumps.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 12/5/11

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 23254

REG. NO: N815LA

HOBBS: 9416.7

TOTAL TIME: 9416.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/5/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed inoperative right wing strobe light assembly S/N 8970. Installed repaired strobe light assembly S/N 9259. Operational check of strobe light system good.

AIRFRAME LOGBOOK INSERT

Hawker Beechcraft Services

MODEL: Bonanza A-36

DATE: 12/12/2011

1450 Boughton Dr.
Bakersfield, CA 93308
(661) 391-1177

S/N: E-2850

WORK ORDER: 23270

REG. NO: N815LA

HOBBS: 9426.7

TOTAL TIME: 9426.7

The aircraft and/or component identified above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service with respect to the work performed. Pertinent details of the repair are on file at this Repair Station.

Date: 12/12/11 Signed: [Signature] F.A.A. A.R.S. #YWBR797L

Removed defective HSI S/N43358 and installed serviceable HSI S/N 82313. Removed defective turn and bank indicator S/N E-08-10780 and installed overhauled turn and bank indicator S/N A07-11563. Removed defective Vent blower S/N 1136 and installed new vent blower S/N 424-1167. Ground operational check all good.

AIRFRAME LOGBOOK INSERT

