THE OF AIRCRAFT MAINTENANCE MAINTENANCE RECORD RECORD SYSTEM

Left #2



ENGINE MAINTENANCE RECORDS

Custom Airmotive, Inc.
FAA REPAIR STATION #DC2R763K
AIRCRAFT ENGINE SERVICE
2702 N. SHERIDAN, BLDG. B
TULSA, OK 74115
(918) 836-6836
FAX (918) 836-9431



ENGINE MAINTENANCE RECORDS

Aircraft Registration No. NIAC

Engine Manufacturer Continental

Model TO - 550 - ELB

Serial No. A83380 - R

Date installed on aircraft

Time Between Overhauls (TBO) Hours

If used on multi-engine aircraft:

Right Left

Rear



(All applicable information must be filled in)

AEROTECH PUBLICATIONS INC.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK				
				TOTALS brought forward from previous page				
			HAULED TO MANUFACTURERS SPECIFICATIONS (test run time only)					
	TTTSMOH2.1 (test run time only) MODELIO-550-E (1) S/N283380-R							
	d above was repaired and inspected in accordance with and current Regulations of the Federal Aviation yed for return to service. Pertinent details of the repairs on under, med Wall. Lilling for							
	Custom Airmotive, Inc. 2702 North Sheridan Road (Bldg. B) Tulsa, OK 74115 U.S.A. Ph. 918-836-6836 Fax 918-836-9431 FAA Certified Repair Station DC2R763K							
	Fuel system, prop gov., tach gen., vac. pump, alternator, starter & magnetos were also overhauled (see maint. release). Ignition harness & spark plugs are new. This engine is equipped withFactory new genuine CMI P/N 658592A2 steel bore cylinders.							
	ModelIO-550-E S/N283380-R WO#24812 Total Time							
	A.D. # Method of compliance 86-13-04 N/A TO THESE NEW CYLINDERS.							
	88-03-06 1	N/A: HAS	ORIGINA	L SCREEN TYPE.				
	88-03-06 N/A; HAS ORIGINAL SCREEN TYPE. 91-19-03 "							
9	93-08-17 C/W BY USE OF CORRECT PICK-UP TUBE.							
9	93-10-02 N/A TO THESE NEW CYLINDERS MANUF. AUG 2015. 99-19-01 N/A TO THIS CRANKSHAFT S/N F279105N.							
	99-19-01 N 0-23-21 "	INDITAL I DIVIZIONA						
- 0	0-23-21 04-08-10 N	J/A TO TE	IESE CMI	CYLINDERS.				
0	7_04_19 N	I/A TO TH	IESE CMI	CYLINDERS.				
0	09-19-07 C/W BY INSPECTION (AFFECTED CYLINDERS NOT INSTALLED).							
1	0-11-04 N	I/A; AFFE	CTED P/N	LIFTERS NOT INSTALLED.				
1	2-03-06 N	/A; AFFE	CTED PA	RTS NOT INSTALLED.				
1	4-05-29 N/A TO THESE CMI CYLINDERS.							
S	Signed M	full o	lilter	for CRS# DC2R763K on_01 SEP 2015				
			S	UB-TOTALS this page				

P	ane	No	

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			Parket In the	TOTALS brought forward from previous page
wo: WO_000	9	_		
	West Houston A	Aero - 18000 Grosc	18000 Groschi	STON AERO Fingine L - page 1 of 1 Finding Parts Re Rd Hanger 3E Fuston, TX 77084 · 713-724-5002 · N/A#: -
N11AC HOBBS: 600		Continent SMOH: 39.2	al, IO-550-E, S/N	uston, TX 77084 · 713-724-5002 · N/A#: – l: 283380 July 14, 2023
1. Engine 2. Inspect 3. Change 4. Perform	T Annual Insperrun-up and comengine, nacelle oil & filter. Engine AD research.	ction - Work Perf pression check; group, & exhaus ine wash, run-up	all cylinders satis t system. Check . & leak check. S	
	te IA 3397518 _	//	NOSE B	brett
VALUE OF SECOND				
	3			
	*			
				SUB-TOTALS this page
				TOTALS-Carry forward to next page