LEFT

HARTZELL

Propeller Owner's Manual & Log Book

HARTZELL PROPELLER INC.

One Propeller Place Piqua, CH 45356-2634 U.S.A.

Hartzell Propeller Manual No. 115 N

PROPELLER MAINTENANCE RECORD



LEFT ENGINE

	del EHC -G3Y		
Blade De	esign FC 7463 E	13-47	
			reputa
Hub Ser.	No. FI 293 A		old
	r. Nos		OV.
			, mil
No. 2_	I 10927		No.
No. 3_	J 10926	я коле	
No. 4_	3/4 (4/2/4)		dpi
		RANGE	
High	18.80/19.00	Low 12.8°	
Feather_	92.9	Reverse	
Governor	Model wasqua	ro.	



Hartzell Propeller Manual No. 115 N



DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4/29/98	4916.8	HOBBS. INSTAll THIS PROJETIEROW	
		THE LEFT SINC OF BEECH 95.45	1
		Sho Te215 NIIAe. This new PRO	9
	•	Eller was InsTAlleDINACORDAN	2
		with Colemill STC. SAY3250.	
		AUD DRAW jug ACIGO RevisED Do	
		EMPRR 16 1981 AND INSTAN ATION	
		INSTRUCTIONS DATED APRILIZE 1970	
		INSTAll OVERHAULED GOVERNOR WOOD	ARO
		PIN BZIO438 5/W1104106// m JEESLERT	
		FOR SURPHAUL DRIAILS. I CERTIFY THE	
		ABOUT WORK IS AIRWORTHY FOR RETUR.	4
		TO SERVICE, WERK DONE By GIEMIL	
		ENTERPRISE Enc. Kulment A	217861



ABILENE AERO INC.	2850 AIRPOR ABILENE, TX	T BLVD. 79602 PROP TSMOH	81.9		
ATE: 12/02/1998 PROP S EG. N11AC AIRCRAFT HM/TAI		PROP TOTAL TIME WORK ORDER NO	51.9 3126	PERT	
certify that this aircraft/engine/comp spection and was determined to be SPECTED AND DRESSED BLADES INSPE ADE CLAMPS.	in airworthy cond	D BULKHEAD. SERVICED DO ROUGH S APPROVED FOR	mulus J RETURN TO SERVICE	DESCRIPTION OF	Manual No. 115
ABILENE AERO INC.	2850 AIF	RPORT BLVD.	ERO INC. GSTR469E	P	15
ABILLINE ALKO INO.		E, TX 79602		F	Z
		PROP TSMC	OH 228.9	9	
DATE: 01/13/2000 P	ROP S/N FJ290			OPER	
DATE: 01/13/2000 PI REG. N11AC AIRCRAFT H		PROP TOTAL TIM	ME 228.9	OPERATIONS	

Hartzell Propeller Manual No. 115 N

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
4-16-04		ProP	
7-16-07		r certify that this alverant tengine has been	
		inspected in accordance with an annual	
		intion and was determined to be III	
		simorthy condition. Total Time S.O.D.	
		Gigneri / Ch	
-		WO# 1357)	
		CALKINS AERO SERVICE INU.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		FAA Certified Repair Sta.	and the second
		No. GK2R849K	
		and the state of t	
4-16-05		/ certify that this aircraft/engine has been	
		Inspected in accordance with an annual	
		inspection and was determined to be in	and the second second
-		alworthy condition. Total Time \$6/9.4	
		Physical Spring Company of the Compa	
	Carlo and Section 1	CALKINS AERO SERVICE INC.	
		FAA Certified Repair Sta.	
		No. GK2R849k	
		Calking Aero Service Inc.	Contract Con
		West Houston Airport	
		18000 Groeschke Rd. Houston, TX 77084	-
		Date: 6-12-06 N11AC HOBBS/TTAF: 5682.0	
1		ANNUAL INSPECTION	
	Performed IA	W 14 CFR FAR 43 appendix 'D' and Calkins Aero checklist:	
	I cortify that	this PROP has been inspected in accordance with An annua	d
	Inspection a	nd was determined to be in an airworthy condition.	
	Calkins Aero	o Service Inc. ed Repair Station	
	No. GK2R84	19K signed	and the later of t
	WO#15155		
		Calkins Aero Service Inc.	
		West Houston Airport	
		19000 C	The state of the s

18000 Groeschke Rd.

Houston, TX 77084 Date:10-25-07 N11AC HOBBS/TTAF:5748.0

ANNUAL INSPECTION

Performed IAW 14 CFR FAR 43 appendix 'D' and Calkins Aero checklist: I certify that this PROP has been inspected in accordance with An annual Inspection and was determined to be in an airworthy condition. Calkins Aero Service Inc.

FAA Certified Repair Station No. GK2R849K

WO#16490

LH

LH

JAMES B. McMANUS 101 Piper lane Spicewood, Texas 78669 830 693 0408 shop JIMBO.MCM@GMAIL.COM Date Reg. Model

07-29-08

N11AC **BEECHCRAFT BARON 95A55**

T/C 215 S/N

Ac. Hrs. 5771.2

*PERFORMED A ANNUAL INSPECTION PER FAR 43 APDX D. AND MAINT. MANUAL AS GUIDELINE. DRESSED PROPELLER AND PAINTED. I CERTIFY THAT THIS PROPELLER HAS BEEN, INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

> Bherre JAMES B. McMANUS 455130849 I/A

JAMES B. McMANUS 101 Piper lane Spicewood, Texas 78669 830 693 0408 shop JIMBO.MCM@GMAIL.COM Date Reg.

08-04-09

N11AC

BEECHCRAFT BARON 95A55

Model T/C 215 S/N Ac. Hrs. 5834.6

*PERFORMED A ANNUAL INSPECTION PER FAR 43 APDX D. AND MAINT. MANUAL AS GUIDELINE. DRESSED PROPELLER AND PAINTED. I CERTIFY THAT THIS PROPELLER HAS BEEN, INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

Rus B. Willa JAMES B. McMANUS 455130849 I/A

JAMES B. McMANUS 101 Piper lane Spicewood, Texas 78669 830 693 0408 shop JIMBO.MCM@GMAIL.COM	Date Reg. Model S/N Ac. Hrs.	08-11-2010 LH N11AC BEECHCRAFT BARON M95A55 T/C 215 5887.0 HOBBS	3
*PERFORMED A ANNUAL INSPECTION P CERTIFY THAT THIS PROPELLER HAS BEI AND WAS DETERMINED TO BE IN AIRWOR	en, inspected in ac	AND MAINT, MANUAL AS GUIDELI CORDANCE WITH A ANNUAL INSPEC JAMES B. McMANUS 455130849 I/A	NE. I
		The second secon	
JAMES B. McMANUS 101 Piper lane Spicewood, Texas 78669 830 693 0408 shop JIMBO.MCM@GMAIL.COM	Date Manuf. Model S/N Ac. Hrs	EHC-G3YF-2UF FJ293A	

SIGNA

IES,

Certificated Repair Station No. EK2R79 PROPELLER S/N FJ293A HAS BE I/A/W Chadwick Helmuth Paper "Smooth Propeller".	EEN <u>BALANCED</u>		DATE	2
Dynamically Balanced To Less Than 0.03 ips.			TACH	Hai Mai Mai DESCI SERVICE
PERTINENT DETAILS ON FILE UNDER WORK ORDER SIGNED SOME L. JONES MECHANIC MAKING INSTALLATION ON A/C	DATE 05-22-12		DESCRIPTION	m = = = = =
			2	ESTA ZE
AMES B. McMANUS D1 Piper lane Dicewood, Texas 78669 B0 693 0408 shop BMBO.MCM@GMAIL.COM	Date Manuf. Model S/N Ac. Hrs.	11-01-2012 HARTZELL EHC-G3YF-2UF FJ293A 5967.8 HOBBS	LH	ALL OPERATIONS ATHINESS DIRECT SI PROP.

JUNE 22, 2015

W/O 17917



FLUSH ONLY HARTZELL PROPELLER. (DWG: EHC-G2YF-2UF) (SERIAL# FJ293A). I/A/W: HARTZELL MANUAL# 117D. Mechanic making installation must comply with FAR 43.9. Repair Station DM2R773K certifies this propeller is airworthy with respect to the work performed.

	Dean Antonia D.	and Harden Jan		UF
-	– San Antonio Pi	opellerService, Inc.		Ur
				1
-		The second secon		45
_	() ()	The second secon	The second secon	
			c	
	3 31	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	16.00	y 17 %
-	1000	The second secon		
<u> </u>		A Complete C		
_				
		100000000000000000000000000000000000000		
			D W	
wo: WO_0	1009	WEST HOUSTON AERO		age 1 o
		Aircraft Service and Parts 18000 Groschke Rd Hanger 3E		

	West Houston A	ero · 18000 Groschke Rd Ste 3E · Houston, TX 770		0000
N11AC	0.7	Hartzell, EHC-G3YF-2, S/N: FJ293A FSN: 1146.0	July 14	, 2023
HOBBS:	0002.0			
PROPELL	ER Annual Inspection - \	work Performed.	Performed AD research.	
		for condition and security, re-install spinner. F		termin
I certify tha	t this Propeller has been	n inspected IAW an Annual Inspection, per 14 ails on file at West Houston Aero/Inder work	order: WO_0009.	
to be in an	airworthy condition. Be-	Jan 6 Manat	1	
, Dia	cette IA 3397518	Jones & Maceto	>	
James Pla	Sette IA 3337 574			