

Date: 11/7/2017 AEROSTAR 601P HOBBS: 3589.1 TTAF: 3589.1

The entry is to verify that twelve (12) cylinders were repaired and installed on N701KE. Twelve (12) cylinders were repaired by Skyline Cylinders A&P 3336553 - see cylinder work performed information papers attached.

LH Engine IO540 S1A5 SN RL24677-48A with TSMOH: 914.1 cylinders installed on the engine and airframe by A&P 22374798. See WO 9523-27 3 Mar 2017.

RH Engine IO540 S1A5 SN L-13805-48A with TSMOH: 646.5 cylinders were installed on the engine and airframe by A&P 3812097. See WO 9523-27 3 Mar 2017.

Ronald Gatewood

A&P IA