### LYGOMING

## ENGINE LOG

SSP-1872-1



652 Oliver Street Williamsport, PA 17701 U.S.A. 570/323-6181

# ENGINE LOG AND MAINTENANCE RECORD

RECORD OF LYCOMING	TTO	0-540-AKIA	RL-8417-61
MAKE		MODEL	SERIAL
FROM <u>5/20</u>	20	то	20
DETAILING TIME FROM	0.0	то	
	HOURS		HOURS
SSP-1872-1	© 1994 by Textron Lycoming "All Rights Reserved"		October 1994

#### **Rebuilt Reciprocating Engine Certificate**

This is to certify that the engine as described hereinafter has been REBUILT in accordance with the applicable Lycoming specifications. It has been determined airworthy to return to service and is in a condition for safe operation. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Publications have been complied with. All accessories as part of the type certificate are new or newly rebuilt. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Part Number:

RENPL-10048

Serial Number

RL-8417-61A

Engine Model

TIO-540-AK1A

Work Order

HP606164

Total Time

0,0

Production Certificate #3

652 Oliver Street Williamsport, PA 17701 U.S.A Lycoming Engines is a division of Avco Corporation

Form 2481 Rev 05/13

CRANKCASE MN. KOI35

CRANKSHAFT SN. 4537940524

	T		ENGINE LOG	Se	rial No	
Date	Time Hrs Min		REPAIRS - ADJUSTMENTS - SERVICE - REMARK	:S	Signature	License Number
	0	0	ENGINE REI	301LV		
			ON 3/30/15	BY		
			LYCOMINGF	ACTORY	,	
			Page Total			
			Brought Forward All Re Certific Total to Date Certific	pair Data Must Bear tl cated Mechanic, and h cate Number MUST be	ne Endorsement of a is Rating and Shown.	

			ENGINE LO	) <b>G</b> Se	erial No	
Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - RE	MARKS	Signature	License Number
Date	Hrs	Min	REPAIRS - ADJUSTIMENTS - SERVICE - TIL	INATIO		
			+ 11	TUCTALI	1	
		<u> </u>	ENGINE -	L/15/07/1		
						_
	<u> </u>		01/1/20	60		
			0/1 // 300	10		
			011 5/21	7/10		
			014 0 120	1/15		
			•			
	1					
			Page Total	All Repair Data Must Bear	the Endorsement of	а
		<b> </b>	Brought Forward	Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		

Total to Date

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Time

Hrs

Min

Date

Serial No.

Signature

License Number

109(3) R (MN6361,81V 18010917),

72), FNEL PUMP (PN 62026032,

PN 46C 22924, SN H-REL 00 130),

(NO6084), PRESS CONTRE (PN 48B1270)

(PN.LW-14445-10, SN M-PSN00128)

MARKEN (MN. 680501, SN 199206)

Page Total

Brought Forward

Total to Date

Page Total

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

			ENGINE LO	G se	erial Noi	· · · · · · · · · · · · · · · · · · ·
Date	Ti Hrs	me Min	REPAIRS - ADJUSTMENTS - SERVICE - RE	MARKS	Signature	License Number
			NEW ALT BERY (PN 390)		1 - ' 1	Hetr
Newport	u N	eur,		-PO11752 Repair	0. 7. 10/1	م مؤ
NEW HOS	· .	X,	Text Run up found (OK) Co	The Suffelie	98-P39/1242	2179
5/22/15	0	0	Annual enspectors Comp	let M. Lube		
TACH	886	8	Engin & Core Controls. Cle	n Ful Strain	01	
			New oil Feltis (CH48110-1) a 50W oil. Replace Prinfelle	4 (P10-6150) Col	ud .	·.
			Funcion Compression		Nest	PACE
		`,.	Brought Forward Total to Date	All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST !	his Rating and	

			ENGINE LO	G Se	rial No.	
Date	Til Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - RE		•	License
5/2/16	0	0	#178/rn #78/2 #77/	#10/ T-201	Signature	Number
TAC	386	8	CW. AL 842602 612	1918/80 45 986	#6 16/FO	
•			AD 2811-26-04 (INSAU	Care An Fitte	) (Dul 1386)	(B)
			"I carly That whise To	exis har bee	h Hun 40 X	/
		• ;	in Accordance with an	Annel us	when and	
			war selement to be	in an Augus	My Cond	tera "
			- Ule	er Infla	84039114	THIA
		$\dashv$				
			Page Total			
		1	Brought Forward	All Repair Data Must Bear the	Endorsement of a	······································
				ertificated Mechanic, and hi ertificate Number MUST be		•

			ENGINE L	OG s	erial No	<del>-,</del>
Date	Date Tir		REPAIRS - ADJUSTMENTS - SERVICE -	REMARKS	Signature	License Number
ВО	LTS. TI	CL VIA		555M EIVE SOUTH IDA 34104 13031 TACH: 908.9 HOBBS:102 OG CONTAMINANTS FOUND. INS 50 AFROSHELL OIL TOROUS	TALLED NEW CH4811	
			Page Total			
			Brought Forward	All Repair Data Must Bear ( Certificated Mechanic, and	he Endorsement of a	
			Total to Date	Certificate Number MUST be Shown.		

**Brought Forward** Total to Date

Serial No. Time License Number Date Signature **REPAIRS - ADJUSTMENTS - SERVICE - REMARKS** Hrs Min 2 Page Total All Repair Data Must Bear the Endorsement of a WEKT Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

				ENGINE LO	OG	Serial No.	
Date	Tin	ne Min	REPAIRS - ADJU	STMENTS - SERVICE - R	EMARKS	Signature	License Number
1/15/16	59	4	uspetion	andwar be	temined tick	ean anteri	vorte
TARI	946	2	Constituer		T Cilmy HI A	9891524721	T.B.
					•	1	
					CENTER, INC.		
			•		04R655M N DRIVE SOUTH		
				NAPLES, FI	ORIDA 34104		
			<u>AIRCRAFT</u>		VO: 13319 TACH: 969.2 HO	BBS: 1,088.6	
·			NIONID OIL DEMON	ENGI B. IIO CRECTED OIL CLA CE	NE LOG HI TED INSTALLED NEW (	CH48110-1 OIL FILTER AND	)
	DRA	NED E	NUTTE O ORG OF ISW	SOM AND INSPECTED OIL F SOM FROSHFLL OIL ENGI	NE RUN UP C/W AND LEA	KED CHECKED GOOD.	
	SEKV	'ICEU		/			
			tople In	FOR NAPLES AIR CE	NTER CRS X04R655M		
		1	JOHN J. IRVINE				
			•				
		ı	Total to Date		Certificate Number MU	IST be Shown.	

Serial No.

South Delta Aviation

4248 S School Ave

Fayetteville AR 72701

Date: 2-10-2017

N53098

Tach: 1006.7

Hobbs: 1129.4

Total: 119.9

Performed a 100hr inspection on this date, changed oil with 9Qts AS-15/50 oil and replaced filter with a new CH4810-1 filter, the old filter was cut and inspected with no abnormalities found, compressions were, #1 76/80, #2 72/80, #3 74/80, #5 74/80, #6 72/80, the engine was ran for filter leak check with no leaks found and all functions normal.

I certify that this engine was inspected in accordance with a 100hr inspection and is approved for return to service on this date, Steven Duncan 431634174 IA Name Duncan.

	Page Total
_	Brought Forward
	Total to Date

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

CA	امند	No.
26	riai	INO.



#### DRTEL AIRCRAFT INC

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

N53098

**TACH 1023.5** 

**TOTAL 136.7** 

DATE 3/19/2018

W.O. SV5502

ENGINE S/N: RECOTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 1825MM20. OIL AND FILTER PERFORMED A 100 HOUR INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 1825MM20. OIL AND FILTER PROPERTY OF A 100 HOUR INSPECTION SERVICED WITH PHILLIPS 20W50 AND CH48110-1. SPARK PLUGS CHANGED COMPLIED WITH SETTED PRACTURE MAGNETOS. REPLACED GASKETS PANIS 42224 JW 12491 BEINGTALLED VACULTURE OF THE PROPERTY OF TH ENGINE S/N: RL-8417-61A CHANGED COMPLIED WITH 30 400E OIE, OIE FIELE AND SOCION SCREEN INSTECTION, SERVICED WITH PRILLIPS ZUWSU AND CHARTIU-T. SPARK PLUGS CIEANED AND TESTED. REMOVED MAGNETOS, REPLACED GASKETS P/N'S: 62224, LW-12681, REINSTALLED MAGNETOS AND TIMED TO ENGINE. COMPRESSION TEST: #1 76 #2 74 #3 75 #4 73 #5 76 #6 73/80. COMPLIED WITH AD 2015-19-07 FUEL INJECTION LINE INSPECTION IN ACCORDANCE WITH COMPRESSION TEST: #1 76 #2 74 #3 75 #4 73 #5 76 #6 73/80. COMPLIED WITH AD 2015-19-07 FUEL INJECTION LINE INSPECTION DUE BY TACK 132.5 ENCINE OMERESSION IEST # 170 # 274 # 000 # 000 # 000 # 000 ONLINE WITH AD 2015-19-07 FUEL INJECTION LINE INSPECTION IN ACCORDANCE WITH YEOMING SB: 342G, NEXT INSPECTION DUE BY TACH 1133.5, ENGINE OVERHAUL OR LOOSENING OF CLAMPS. AD 2017-16-11 CONNECTING ROD SPECIFIC PER LYCOMING SB 6328 DOES NOT APPLY BY ENGINE S/N. AD'S CHECKED THROUGH 2018-06. OF CLAMITS. AU 2017-16-11 CONNECTING ROD OFFICE THIS ENGINE S/N. AD'S CHECKED THROUGH 2018-06.

OFFICE THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY SHIPTION, PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

JOHN HOFFMAN, INSPECTOR

	1 11 11 11 11	(23,250)	
		Page Total	
		Brought Forward	
		Total to Date	
Part Control of the			

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.



#### VAN BORTEL AIRCRAFT INC™

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

N53098

**TACH 1096.0** H.M. 1228.3 DATE 11/6/2018 W.O. SV5712

ENGINE S/N: RL-8417-61A


OIL AND FILTER CHANGED. COMPLIED WITH SB 480F OIL, OIL FILTER AND SUCTION SCREEN INSPECTION. SERVICED WITH PHILLIPS 20W50 AND CH48110-1.

THE AIRCRAFT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK ABOVE, PERTINENT DETAILS OF THE REPAIRS ARE

ON FINE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

PAUL PARK, CHIEF INSPECTOR

 Page Total			All Repair Data Must Bear the Endorsement of a			
		Brought Forward		Certificated Mechanic, and his Rating a Certificate Number MUST be Shown.		
		Total to Date				





#### VAN BORTEL AIRCRAFT INC™

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

N53098

TACH 1108.9 TOTAL 222.1

DATE 12/19/2018 W.O. SV5749

se er

ENGINE S/N: RL-8417-61A		
PERFORMED A 100 HOUR INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE	CE TO CESSNA MAINTENAN	ICE MANUAL 182SMM20. OIL
AND FILTER CHANGED. COMPLIED WITH SB 480F OIL, OIL FILTER AND SUCTION SCRI	EEN INSPECTION, SERVICE	D WITH PHILLIPS 20W50 AND
CH48110-1. REPLACED ALL SPARK PLUGS WITH NEW P/N: RHB37E. MAGNETO TO ENGI	INE TIMING CHECKED, CO.	MPRESSION TEST: #1 77 #2 74
#3 75 #4 73 #5 77 #6 74/80. COMPLIED WITH AD 2015-19-07 FUEL INJECTION LINE INS	SPECTION IN ACCORDANC	E WITH LYCOMING SB 342G,
NEXT INSPECTION DUE BY TACH 1218.9, ENGINE OVERHAUL OR LOOSENING OF CLAM	APS. AD'S CHECKED THROU	JGH 2018-26.

I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION, PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

PAUL PARK, CHIEF INSPECTOR

Page Total	All Bonsis Date Must Bernell 5
Brought Forward	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and
Total to Date	Certificate Number MUST be Shown.

Serial No. License Signature Number

N53098

Hrs

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Tach: 1158.5

Time

Min

Date

Lycoming TIO-540-AKIA S/N RL-8417-61A

January 27, 2020 TTSMOH: 271.7

Performed a 100 hr inspection, removed engine cowls, drained oil, removed filter, cut, inspected, Per SB480F,(inspect screen / filter). Serviced with Phillips XC20W50, replaced AA48110-2 filter. Cleaned

Gapped all plugs, reinstalled .Compressions as follows #1 78 #2 76 #3 76 #4 75 #5 74 #6 76/80.

Tightened valve cover gasket screws. AD2015-19-07 insp fuel lines(SB342G) next due 1218.9

All AD's complied with at this time .Check AD listing.

I certify all work done in accordance with Cessna Maintenance Manuel and Federal Aviation Regulations Part 43 and is determined to be in Airworthy Condition,

HEND OF ENTRY-

Timothy S. Hart AP 3403977

January 27, 2020

N53098 Tach: 1158.5

Lycoming TIO-540-AKIA S/N RL-8417-61A

January 27, 2020 TTSMOH: 271.7

I certify this aircraft engine has been inspected IAW an annual inspection., and has been determined to be in airworthy condition.

Mark Robles AP2653131IA

				ENGINE	LOG	Serial No.	
cense umber	Date	Time Hrs Min	REPAIR	RS - ADJUSTMENTS - SERVIC	E - REMARKS	Signature	License Number
		N53098 Tach :1	_	Lycoming TIO-540-AK1A s/n RL-8417-61A	July 07, 2020 TTSMOH: 314.4		
	Removed aircraft engine cowling, drained oil, removed filter, inspect, no particles found Per SB480F, Install new filter CH48110-1 serviced with Phillips XC20W50. Recowl Run, check for leaks, non found.		ound				

All work accomplished in accordance with Lycoming Maintenance Manual and AC 4313 acceptable practices.

-END OF ENTRY-

\_\_ Date: July 07, 2020

Timothy S. Hart AP3403977

 1 1	
Page Total	All Paneis Data Maria David S. J.
Brought Forward	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and
Total to Date	Certificate Number MUST be Shown.

Serial No.

Date	Time			That I to.				
— Date	Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - REMAR	RKS	Signature	License			
_	N53098 Tach: 12 Perform	Lycoming TIO-540-AKIA S/N RL-8417-61A ed a 100 hr inspection removed engine courts to include the courts and include the courts are included in the court	February 2, 2021 TTSMOH: 348.7	and the second s	Number			
_	Spark pl AD2015	ugs, reinstalled. Compressions as follows #1 74 #2 76 #3	AA48110-2 filter. Cleaned, g 76 #4 75 #5 75 #6 77/80.	apped all				
		s complied with at this time, thru 2021-01. AD listing attact all work done in accordance with Cessna Maintenance Mai						
_	Aviation	Regulations Part 43 and is determined to be in Airworthy C - END OF ENTRY-	Condition,					
	S	February 2, 2021 imothy S. Hart AP 3403977						
	N53098 Tach: 12	Lycoming TIO-540-AKIA S/N RL-8417-61A	February 2, 2021					
_	ומאיי	his aircraft engine has been inspected IAW an annual inspectmined to be in airworthy condition.	TTSMOH: 348.7					
	Mark Ro	bles AP26531311A Total to Date Certification	icate Number MUST de S	nown.				

		n. CW AD 2015-19-07 fuel lines by inspe lower vacuum pump PN AA3216CW, SN	•			116
	<b>ЈОНІ</b>	N MOORE AP2748654IA	m			
		//				
	·					
			CRYSTAL			•••
			104 NOWLIN LN	-		
			CHATTANOOG	M, IN 37421		
		N53098 S/N RL-8417-61A	TACH 1280.7 TTSMOH	394.4 2/25/22 ENGIN	√E	
		At this time performed a ANNUAl and utilizing 182SMM REV 21 as				
	1	AND #6(75). Changed oil (Phillips sample was taken. Cleaned and	66 20W50 X/C 8 qts) and oil t	ilter (Tempest 48110-2). Oil		
		lines. Washed Engine. Ran and o				
j		I CERTIFY THIS ENGINE TO	BE IN AN AIRWORHTY	CONDITION IAW A		
		ANNUAL INSPECTION AT 1	4 9	1/200 -		
1		BRIAN FLIPPO A&P 378467	8 IA	irjes	e Endorsement of a	
		Total to Date		Certificate Number M	is Rating and UST be Shown.	



#### CRYSTAL AIR INC. 104 NOWLIN LN, HANGAR 19 CHATTANOOGA, TN 37421

N53098 S/N RL-8417-61A TACH 1324.6 TTSMOH 438.3 3/6/23 ENGINE

At this time performed a ANNUAL INSPECTION IAW 14 CFR 43, Appendix D (scope and detail) and utilizing 182SMM REV 21 as a guide. Compressions at #1(74) #2(73), #3(74), #4(76), #5(78) AND #6(73). Changed oil (Phillips 66 20W50 X/C 8 qts) and oil filter (Tempest 48110-2). Oil sample was taken. Cleaned and gapped plugs. Checked mag timing to engine. Tighten oil drain lines. Washed Engine. Ran and ops check good. AD 2015-19-07 CW.

	<b>3</b>
I CERTIFY THIS ENGINE TO BE IN ANNUAL INSPECTION AT THIS TII BRIAN FLIPPO A&P 3784678 IA	NAN AIRWORHTY CONDITION IAW A ME. Jun Ham
SET AND	CRYSTAL AIR INC.

104 NOWLIN LN, HANGAR 19 CHATTANOOGA, TN 37421

N53098 S/N RL-8417-61A TACH 1307.3 TTSMOH 421 11/14/22 ENGINE

At this time changed low oil pressure switch (83278). Ops check good

I CERTIFY ALL WORK DONE TO BE IN AN AIRWORTHY CONDITION AT THIS TIME.

BRIAN FLIPPO A&P 3784678 IA

Signature	License Number
	· ·
	-
	Signature

ificated Mechanic, and his Rating and ificate Number MUST be Shown.

					ENGINE	LOG	Serial No.	
icense	36	Date	Ti	me				License
umber			Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE	E - REMARKS	Signature	Number
			: : :	Serviced Valve of Certify Aviation	_,	TTSMOF t, inspected, Per SB480F,(ins I AA48110-2 filter. Removed torqued as required, leak che ttenance Manuel and Federal	H: 483.1 ——spect screen / filter).	
				L	Page Total	All Repair Data Mus	st Bear the Endorsement o	fo
					Brought Forward	Certificated Mechan	ic, and his Rating and	
					Total to Date	Certificate Number	MUST be Shown.	

		ENGINE	LOG Serial No	
Da	The second section of the second section is a second section of the			,
	N53098	Lycoming TIO-540-AKIA	October 10, 2023	License Numbe
	Tach: 1369.4	S/N RL-8417-61A	TTSMOH: 483.1	Mullipe
	Remove engine cowlings Install engine cowlings	, remove oil pressure switch, replace	with new switch p/n 83278, run aircraft check for leaks	
	I certify all work done in	accordance with Cessna Maintenance	e Manuel and Federal	
	Aviation Regulations Par	t 43 and is determined to be in Airwor	thy Condition,	+
	$\sim 1-1$	END OF ENTRY-		
	( HISH	7		
_	Timothy S. Host	A D 2402077		
	Timothy S. Hart	AP 3403977		
			1	+
		•		
	Page Total	al		<u> </u>
	Brought F		All Repair Data Must Bear the Endorsement of	of a
	Total to D		Lertificated Mechanic, and his Rating and	
	Total to L	, o r c	Certificate Number MUST be Shown.	