109478\$ #3 TIFFIN AIRE INC.

1778 West State Route 224
Seneca County Airport (16G)
Tiffin, Ohio 44883
1-800-553-PROP (7767)
1-419-447-4263
Fax 419-448-0064
E-mail taiprop@tiffinaire.com

Propeller Log Book

PROPELLER MAINTENANCE RECORD

Position:	PITCH RANGE
Propeller Model: 2A36CB2-1-EFG	High Feather: 34.6°
Propeller S/N: 691399	Start Lock:
Blade Design: S-84B-Z	Low: 14.1°
Blade S/N's:	Reverse:
No. 1	
No. 2 K83572 YS	Aircraft Manufacturer BEECHERAFT
No. 3	Aircraft Model <u>V35</u>
No. 4	S/N: <u>D-8057</u>
No. 5	Registration: N9478S
No. 6	

SinnerAssemblyPartNo._

1. Approving historial and a Authority/Country

FAA/United States

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

21039

4. Organization Hame and Address:

TIFFIN AIRE, INC. 1778 W. US 224 TIFFIN OH 44883 FAA CRS NO. DTXR341D 8. Work Order/Contract/Invoice Number:

W/O# 21039

6. Book:	7. Description:	8. Part Number:	0. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	McCAULEY PROPELLER ASSEMBLY	2A36C82-T-EFG	NA	1	691399	OVERHAULED
	and the same of th	Andrew State			Mary States	
		Maria Day		1.37		

13. Recounts

COMPLETELY OVERHAULED PROPELLER ASSEMBLY IN ACCORDANCE WITH MCCAULEY SERVICE MANUAL NUMBERS 720415 (Rev. 8, 12/02), SPM100R04(Rev. 4, 06/07) & BOM100R05(Rev. 5, 01/11).

COMPLIED WITH SERVICE LETTERS: 89-5A, 91-5A, 91-11A, 98-5, 98-8B, 01-1F, 07-7, 11-1.

COMPLIED WITH SERVICE BULLETINS: 118, 137AE, 179A, 227B.

COMPLIED WITH A.D. NOTE: 98-25-13.

BLADE MODEL NUMBER: S-84B-2 BLADE SERIAL NUMBERS: K83540YS, K83572YS.

PROPELLER TOTAL TIME SINCE NEW: HUB UNKNOWN BLADES 3666.58

PROPELLER TOTAL TIME SINCE OVERHAUL: 0.0

AIRCRAFT TACH TIME: 1640.48

TIME BETWEEN OVERHAULS: 60 MONTHS OR 1200 HOURS WHICHEVER OCCURS FIRST.

Approved design #		and described in Block 13 was accomplis	Other regulation specified in Block 13 n Block 13, the work identified in Block 12 thed in accordance with Title 14, Code of cct to that work, the items are approved for
S. Authorized Signature:	16. Approval/Authorization No.:	20. Authorized Spratus:	21. Approval/Cartificate No.: DTXR341D
7. Humo (typed or Printed):	18, Date (m/dly):	22. Name (Typed or Printed): Paul B. Flavell	23. Date (m/d/y): DEC/20/2012
N. F. St. St. St. St. St. St. St. St. St. St			

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part / component / assembly.

Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1. Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the hational regulations by the user/installer before the aircraft may be flown.

Date	Prope TSN	TS0	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
4Feb13	3666.8	0.0	rlq _ ;"od i	Removed propeller and neinstalled after
		14/10		sear bulkhead at this time pla 0- 7713-4. Annual Inspection complied with
	2 2 2 2 2 2			19219V9A Muy AP3557843 IA
10ec13	3717.1	50.3	1691.0	annual Impection. J. May AP3557843
16 Dec 14	3738.1	71,3	1712.0	annual Inspection Muy AP3557843
1Jan 16	3804.8	138.0	1112	annual Amportion Muy Al 365 1843 IA
				No.6
				SinnerAssembly Part No.

Oracle Aviation LLC 12916 Millard Airport Plz Omaha, NE 68137



KMLE 402.934.5300 OracleAviation.com worthiness Directives, Service Repair, and Inspections.

Tail #	Tach	Prop TT	SMOH	Date
N9478S	1839.2		198.5	1/19/17

Performed annual inspection as per Bonanza V35 service manual

Checked AD's through this date

I certify that this aircraft propeller has been inspected I/A/W annual inspection and found to be in an airworthy condition.

Barry D. Daniels II

A&P 3439929 IA

SO#	18-24895	Personal M.	SILVERHAWK	DATE	7/3/2018		
REG.	N9478S	Lincoln Municipal Airport [LNK]				TACH	1840.5
MAKE	McCauley	MODEL	2X36C82-T-EFG	SERIAL NO.	691399	ACTT	3866.7
4.56.43	N THE SAME	PTT	3866.7	PTSOH	199.8		

Maintenance Record Propeller

- 1. Complied with Annual Inspection reference the Beechcraft Bonanza V35 Shop Manual, Section 7.
- 2. Performed 100 hour lubrication referencing Beech V35 Shop Manual, Section 2.

I certify this (aircraft) (engine) (propeller) has been inspected in accordance with a Pre buy/Annual inspection as per 14 CFR 91.409 (a)(1) and was determined to be in an airworthy condition.

Dated 18-24895 W.O. July 3, 2018.

Signed: Benjamin A. Taylor

for

Silverhawk Aviation Inc. CRS # YQSR759U Lincoln, NE 68524

Date	TSN TSO Hrs		A/C Hrs		rtaining to Airworthiness Directives, Service ajor or Minor Repair, and Inspections.
14 Aug 2019			52.7	annual Impertion.	My AP3557843
Registrat	tion: N9478S			Eagle Abr	Date: 10-13-2020
McCaule	y 2A36C82-G			REPAIR	
SN: 6545	647			Propeller	TACH: 121.5 PTSOH: 331.3 ACTT: 3998.2
Dressed 20. I ce airworth	propeller ar rtify this pro ny condition	nd checked peller has l at this time	2.	And the second s	
Dressed 20. I ce airworth	propeller ar rtify this pro ny condition	nd checked peller has l at this time	2.	for cracks. Painted propeller. AD ected IAW and Annual inspection erlakAP353	o's checked thru Bi-Weekly issue 2020- n and was determined to be in 8569IA
airworth	propeller ar rtify this pro ny condition on: N9478S	nd checked peller has l at this time	2.	And the second s	
Registrati	ny condition	nd checked peller has l at this time	2.	And the second s	8569IA
Registrati	on: N9478S	nd checked peller has h at this time	2.	erlak Januar AP353	8569IA

Date	Propeller TSN TSC	A/C Description of all operations pert Hrs Documents, Overhaul, Maj	taining to Airworthiness Directivition or Minor Repair, and Inspec	ves, Service tions.
	ation: N94785	Eagle Air		Date: 20DEC22
SN: 654	ley 2A36C82-G 1547	Propeller	TACH: 289.16 ACTT: 4165.86	PTSOH: 498.96
Dressed	d propeller and checked spin ted IAW and Annual inspection	ner for cracks. Painted propeller. AD's checked thru Bi-Weekly is on and was determined to be in airworthy condition at this time.	ssue 2022-26. I certify this propeller ha	and the same to be a
	wo: 000656		Propeller · page 1 of 1	
	McAllister N9478S TACH: 334.98	Aviation · 625 W DEER VALLEY RD · PHOENIX, ARIZONA McCAULEY, 2A36C82-G, S/N: 654547 PTSO: 544.78	85027 · 6025417264 February 08, 2024	
	Performed annual insp	등 기가 되었다. 본 이 왕은 바라 하면 하다가 나를 하는데 하는데 그리다 살이 한 때문이다.		
	With respect to the wo formed are on file with	ork performed, this Propeller is approved for return to McAllister Aviation under work order: 000656.	service. Details of work per-	
	Chris McAllister APIA	3828724		
				II.

12.00