

Propeller Logbook



SENSENICH PROPELLER SERVICE, INC.

McCauley	<input type="checkbox"/>
Hartzell	<input type="checkbox"/>
MT	<input type="checkbox"/>
Sensenich	<input checked="" type="checkbox"/>
Dowty	<input type="checkbox"/>
Hamilton Standard	<input type="checkbox"/>

INSTALLING AGENCY PLEASE NOTE:
Recording of Propeller Total Time Since New (TTSN)
is Required Per F.A.R. 91.417

29598K

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmer Memorial Airport, 1245 Palmour Place, Suite A, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 FAA Certified Repair Station #S46R346N

SERVICE HISTORY

[illegible]

SERVICE HISTORY

Propeller Log

N8025W

Page 1 of 1

9/1/2023

Tach 1350.7

9/17/2023
Removed propeller and reinstalled after overhaul by Sensenich Propeller Service, Inc. see maintenance release dated 8/31/2023. Balanced propeller to less than .07 IPS.

This propeller has been inspected IAW an Annual Inspection and was found airworthy on this date.

Inspector:

Allen Campbell

Certificate #AP2636560 IA

zed Signatures

[illegible]