
MAINTENANCE RECORD

REPAIRS, ADJUSTMENTS, MODIFICATIONS

ORAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.

OCTOBER 7, 2019
MU-2B-40 S/N 403SA N600JE
L/H PROP S/N: CDA3119M3
HOBBS: 528.3 TSMOH: 309.9

CHUSHON AIRCRAFT INC.



COMPLIED WITH 100/200 HOUR INSPECTION I/A/W THE MITSUBISHI & HARTZELL INSPECTION GUIDE. INSPECTED AND LUBRICATED PROP WITH AEROSHELL 6.

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED AND FOUND TO BE IN AIRWORTHY CONDITION


CHARLES P. WALTON III 240005000

CHARLES B. WALTON III 240025393

APRIL 12, 2023 MU-2B-40 S/N 403SA N600JE L/H PROP S/N: CDA3119M3

HOBBS: 589.2 TSMOH: 0

CHUSHON AIRCRAFT INC.



COMPLIED WITH 100/200 HOUR INSPECTION I/A/W THE MITSUBISHI & HARTZELL INSPECTION GUIDE. INSPECTED AND LUBRICATED PROP WITH AEROSHELL 6. LH PROP OVERHAULED BY FIRST FLIGHT PROPELLER. INSTALLED PROP.

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED AND FOUND TO BE IN AIRWORTHY CONDITION.

CHARLES B. WALTON III 240025393

First Flight ropeller, LLC
FAA Approve I No. G7R547X
315 Silv - HI & Dr.
Senatobia, Nis 38668

Chusian Aviation

Customer

Propeller

Item

HC-BHTN-6JL

Model

CPA3119 m3

Serial Number

The propeller, or appliance identified above we OVERHAULED and inspected in accordance will current instructions contained in the maintenant rules of the Federal Aviation Regulations and approved for return to service. Pertinent details this work are on file at this repair station under

W/O No. 3097 Dated 2 12Hia.

Shappers B Hammal

Signature

OVERHAULED

FFP1520

-	
-	
1	