



Accident/Incident Report

This report contains information from the records maintained by NTSB from 1962 to present and the FAA National Aviation Safety Data Analysis Center from 1978 to present.

Summary of Results

N7830Y; PIPER PA-30; S/N 30-906

SEE ATTACHED REPORT(S)

ALWAYS N7830Y FROM 11/17/1965 TO PRESENT

04/16/2023

JH

[Back to Search Results](#)

FAA Accident and Incident Reporting System (AIDS)

GENERAL INFORMATION

Data Source	ACCIDENT AND INCIDENT DATABASE
Report Number	20120903022119I
Local Date	03-SEP-12
City	SPRINGFIELD
State	MO
Airport Name	DOWNTOWN
Event Type	INCIDENT
Mid Air Collision	NOT A MIDAIR

AIRCRAFT INFORMATION

Aircraft Damage	MINOR
Aircraft Make	PIPER
Aircraft Model	PA30
Aircraft Series	NO SERIES EXISTS
Type of Operation	GENERAL OPERATING RULES
Registration Nbr	7830Y
Total Aboard	1
Fatalities	0
Injuries	0
Engine Make	LYCOMI
Engine Model	IO-320 SERIES

Environmental/Operations Info

Pilot In Command

Pilot Certificates

COMMERCIAL PILOT

Event Remarks

PIC NEGLECTED TO EXTEND LANDING GEAR PRIOR TO LANDING. BOTH PROPS STRUCK THE RUNWAY AND THE PIC ATTEMPTED A GO-AROUND. HOWEVER, THE ACFT SETTLED ONTO THE RUNWAY AND SLID OFF ONTO THE GRASS. AIRCRAFT DAMAGE LIMITED TO BENT PROPELLER BLADES AND SCRATCHES TO THE BELLY. AIRPORT MGR REPORTED DAMAGE TO SOME RUNWAY LIGHTS.

END REPORT