0-200-A CONT.



江海至了

Engine Record General Information								
Manufacturer Cont	inenta	Model	0-200-A					
Serial 6284-72-	A-R	Туре Се	ertificate E-252					
This engine is currently	installed in ai	rcraft:N60607						
Minimum Octane Fuel	80	Oil Grade Summer	20 W 50 PHAUPWinter	SAME				
Magneto Time		Point Setting		rder /-3-2-4				
Spark Plug Gap, 019	1019							
Manufacturer's Recomm		nul at 2000.0 hou	rs					

A STATE OF THE PARTY OF THE PAR

100

Note: Original Logbooks Lost. All hours entered have been verified by previous service and maintenance records, which were on file. Round Coopen ASTER 3508760

MO TENDED HERE

POMALTI C. COOPER

YEAR 20 2.1 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	I EDINES HIDS DE D	TIGOLOGG WILL	ns, Tests, Repairs and Name, Rating and Certification See back pages for other s	-4 .
N#: 60607 Date: 12-11-2 This engine AD's & SB of the controls of the coupling during during during during during a coupling a	Make: Con 021 Tach: 2447 has been insp ompleted this of 3:66€ 4: 66€ induction lead induction lead induction lead heat box cable ness / of ma	tinental 7.6 T per MFG late. Eng 5: X 6: k test / p/ griming & pump coup paint / p/ mount /	T Eng: 815.6 service manucleaned, hot of air inlet filter bowl & clean plugs & gent bolding of the color of t	ual, all diff: affles / Lengine end of filter end fuel screen gap of insp/meg rarter / La alt end inj servo. oil leaks / OK, all	WITH LOO HA	INSPECTION AND WA	S

YEA 20 DA

YEAR 20 DATE	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be	endorsed with N	lame, Rating and	Certificate Number of rother specific entries.)
N#: N6060 Date: 08/2		Cont. O-20 2459.1	0-A TT Eng: 827	Ser# 6284-7			
This engi	ne has been i	nsp. per M	FG service m	nanual, all AD's & S	SB		
complete	this date. Er	ng cleaned	, hot diff:				
1: /6/10	2: 7 × 10 3:	78/20 4:	72/96 5	\leq 6 \leq			
				tion leak test <u>///</u> rain car			
				cable /			
				www. mag timing			
	R Vot impu						
	Starter _						
	Prop gov				1		
	Table 1 to 1 t	/	_	∠∕∞ , all fuel & oi			
rnm V	Parts 7	Ame de	pressure @	no fuelor me			
	Non The	- Audila	several.	no fusion me toba questr	ufc		
Jan Marie	To Towned	The Lenn	nu.	~~~ E	NO		
speci	g Ziecu			_			
Plan Prince	i con la la				1		
	CERTIFY THAT	THIS E	NGINE				
	AS BEEN INSP						
	,						
- · · · · · · · · · · · · · · · · · · ·	TH 100 HR	_INSPECT	ION AND W	AS	,		
	ETERNAINED T	DEIN					
make a series and a series and a series and a	RWORTHY C	MOITION	.00	W			
		1 Por	uc con				
	8/24-4	ROMALI	G. COOPER				
		AP 3500	77COLA				
	RWORTHY CO						

AND THE PERSON NAMED OF TH

DAI	Date: 1 Annual exhaus sump s Camgua Inspect the engine spinne	inspection t/muffler, e creen. Clea ard.) Inspection the bear gine. Review assembly. In that this electronined to	Tach: 248 per FAR per	trols, carb-head parkplugs. Reposite cover screets and cams. In D. compliance the spinner. Description of the spinner. Description of the spinner of the spi	dix D and Continental mat mechanism/baffle and laced the air filter. Serve to torques. Removed be estalled and timed to species. Complied with 69-15 pressed the blades. Runcen inspected in according	anuals. Comp: 1-77, 2-77, 3-77, 4-77. Insp: d mount attachments. Inspected the fuel riced the oil and filter. (15/W50 and oth magnetos and installed new gaskets. Dec. Updated the A.D. compliances. Washed 1-03 (mufflers). Inspected the prop and 1-up checked O.K.	-
						AND CONTROL CO	

YEAR	McCLELLAN AIRCRAFT MAINTENANCE, INC. 4270 Torrey Rd. Flint, MI 48507	s and Alterations	
20 Date	07/31/2023 Tach: 2588.1 N60607 C-150J	ertificate Number of her specific entries.)	
-	S/N: 150-70441		
	Continental 0-200-A S/N: L31202-51E		
	ANNUAL INSPECTION performed.		
	#1) Inspected and lubed all engine controls	En Constanting	
	#2) Cleaned and gapped spark plugs.		
	#3) Changed oil & filter with 8 quarts of Phillips 20W50 and Tempest Filter		
	P/N: AA48108-2 - Added CamGuard ~ sent sample to lab for analysis		
	#4) Compression check: #1) 72/80 #2) 77/80 #3) 72/80 #4) 75/80		
- 19040/9840000000000000	#5) Removed and replaced air filter element with new P/N: BA-4108		
	#6) Found left magneto out of time, reset timing.		
	#7) Found low compressions on #1 and #3 Cylinders, removed valve covers, springs,		
	rocker arms and lapped exhaust valves. Reinstalled valve covers, springs and rocker		
	arms. – compressions good.		
	#8) Found tight valve on #1 and #2 cylinders – reamed guides – reinstalled valves,		
rejections	springs and valve covers.		
	#9) Removed #1 cylinder and replaced push rod tube housing seals – reinstalled		
	cylinder and exhaust system.		
	Ran aircraft on ground, checked for leaks. OPS check good.		
	Returned aircraft to service.		
	IT IS CERTIFIED THAT THIS ENGINE HAS BEEN INSPECTED		
and the state of t	IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS		
-Marine Constitution	DETERMINED TO BE IN AIRWORTHY CONDITION.		
	END		
- or reconstitution in	Michael W. Wagner II A&P 2896059 I.A.		

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FI IGHT TIME IN Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name. Rating and Certificate Number of Intries McCLELLAN AIRCRAFT MAINTENANCE, INC. 4270 Torrey Rd. Flint, MI 48507 DATE	10/23/2023 S/N: 150-70441
		07/31/2023 Tach: 2588.1 N60607 C-150J . S/N: 150-70441 McCauley 1A101-DCM S/N: G2293 ANNUAL INSPECTION performed, Per McCauley Service Manuel OPS check good. Returned aircraft to service. IT IS CERTIFIED THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AIRWORTHY CONDITION	Continental #1) Changed oil w Added CamGuard #2) Removed and OPS check good. Charles J. Jernigar

	TAINTENANCE,	TIVC. 4270 Torrey Ra		te Number of
10/23/2023 Tach: 2637.3 S/N: 150-70441	2 N60607	C-150J	her sp	ecific entries
Continental 0-200-A	S/N: L31202-511	E	eliteración de contrata de la contrata del contrata de la contrata de la contrata del contrata de la contrata del la contrata del la contrata de la contrata del la contrata de la contrata de la contrata de la contrata de la contrata del la contrata del la contrata del la contrata del la con	
#1) Changed oil with 6 quarts of Added CamGuard – sent sample #2) Removed and replaced all s	le to lab.		N: AA48108-2	
OPS check good. Returned airc		1	entinggione della figliori attenue menore.	
	END		wile in the control of the propagation of	
Charles Ja Jernigan JR A&P 4	499474			
March 1			- Adambies (Spinish in The Laurice)	
	Î			
	- A Supplier			

The state of the s

YEAR RECOR 20 TACH TIME	RDING TODAY'S FLIGHT		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries	YEAR	RECORDING TACH TIME
	01/29/20 S/N: 150 #1) Insta instruction	024 Tac 0-70441 alled servicea ions. eck good. Re	ch: 2653.3 N60607 C-150J able SkyTec starter P/N: C12ST2 IAW Hartzell STZ Installation eturned aircraft to service. END		

i încert