N199PG

#2



ASA-SA-2

Serial 28 K - 8 218020 Registration Number N199PC N Date of Manufacture Engine(s) currently installed: Manufacturer Model Serial Propeller(s) currently installed: Manufacturer Model Serial HUB Model Serial Serial	ircraft Record General Info	ormation		
Serial 28 R - 8 2 / 8 0 2 0 Registration Number N / 9 P C N Date of Manufacture Engine(s) currently installed: Manufacturer Model Serial Propeller(s) currently installed: Manufacturer Model Serial HUB Model Serial Serial			N. VI	
Serial 28 R - 8 2 / 8020 Registration Number N / 99 PC N Date of Manufacture Engine(s) currently installed: Manufacturer Model Serial Propeller(s) currently installed: Manufacturer Model Serial HUB Model Serial Serial		7.5.76	in a	
Serial 28 K - 8 218020 Registration Number N199PC N Date of Manufacture Engine(s) currently installed: Manufacturer Model Serial Propeller(s) currently installed: Manufacturer Model Serial HUB Model Serial Serial	anufacturer PIPER	<u> </u>	Model <i>PA 28 R</i>	(7-201 CORIGINALLY
Date of Manufacture Engine(s) currently installed: Manufacturer	erial 28 R - 821	8020	Registration Number	N199PG (N506
Engine(s) currently installed: Manufacturer				
Manufacturer Model Serial Manufacturer Model Serial Propeller(s) currently installed: Manufacturer Model Serial Serial				
Manufacturer Model Serial Manufacturer Model Serial Propeller(s) currently installed: Manufacturer Model Serial Serial	ngine(s) currently installed:			
Propeller(s) currently installed: Manufacturer Model Serial Serial	lanufacturer	Model		
Propeller(s) currently installed: Manufacturer Model Serial Serial	lanufacturer	Model	Ser	rial
Manufacturer Model Serial Serial				
HUB Model Serial Serial	ropeller(s) currently installed:	yangan makamatan ya 1881	the title of the same property of of	
	anufacturer	5 (4.4)	Model	
	UB Model	Serial	Ser	rial
Blade Model Serial Serial Serial	lade Model	Serial	Serial	Serial
Blade Model Serial Serial Serial	lade Model	Serial	Serial	Serial
		-22 W 30 m T		

	Stabilime Piazza Robert Daubrè CERTIFICATE OF C	A 16 15 14 Ch 17 17 17 17 17 17 17 17 17 17 17 17 17	YEAR:	6 17	FAA Form 8130-3, AIRWORTH 240 Springwood Avenue • Gibs FAA-PMA (PQ1206CE) [8.	onville, NC 27249 USA	4 48191 Joh OrderContract/Invoice Number: 48191	Sta. No. YV
I	CERTIFICATE OF C	the second secon	DATE	Suction To	Part Number		al/Batch Number 12: Status/Work Newly	
-	P\N Codice materiale 092 - 315 - 0 Tube size Dimensione camera	7 11 1 6 9 9 9 PD - 1 X		HIFAI	ested in accordance with FA		7012 Overhauled	year or 400 hou year or 400 hou han exchange examination is
	Gentleman, we hereby certify that the parts supplied and re according to applicable specifications. Substantiating doc available for inspection upon request. Signori, con quest documento noi certifichiamo che i materiali fabbricazione, sono realizzati conformemente alle specifiche ric	12-54-83/8020 Sheespart 88/12		14. Certifies the items identified above	ere manufactured in conformity to: a condition for safe operation. Id in Block 13. If Approvat/Authorization No.	M 14 CFR 43.9 Return To Service ☐ Other Regulation Specified in Bio Fifther Rel university regulate in back 13, the work And the accounters with 16 4 Code of federal Regulation which is barries. Authorized Signature	sented in bloss 12 and depoted in block 13 was accompant of and in respect to that work, the farm are approved 21. Approved Certificate No.: YV4R688M	s been subject anely affected or its agents sh irmation, repre- cessories, Inc. rosable by the lose, and this s there is given
	sono archiviati e disponibili per ispezione su richiesta. Tubes Quality Assurance Manager Responsabile Garanzia Qualità camere N. me G. ROM	CONTRACTOR		It imposes to understand that the estitions of this document is there the association such a accordance with the relations in componential mode for American which of the or Statements in book 14 and 16 oft not constitute installation readile FAAA form 8130-3 (06-01)	Userfinstaller Re- re des ret adonalisky sontalle allohy to held the performer allore of a Novohness Authorly officer than to A Novohness Authorly officer allow to the Annother allowed the to A Novohness Authority try specified to block to	Figure City, and the country specified in block 1 it is assertful that the country is conficulted to accordance with the national regulations by the	AAR 29 2005 MAR 2 9 2005 mile owns by later fearers and make a	limited to repair if the failure of th flective and cont if it should) of the
	***************************************						and the control of th	
			-					

	Date: 07/20/2005, Aircraft: N199PG, Type: PA28RT-201, S/N: 28R8218020 tach 2220.97 Hobbs 76.6 "*Airframe** Removed pilot seat. Installed new seat recline springs, cams, stop bolts, and roll pins. Removed pilot seat. Installed new seat recline springs and in aircraft.	er of tries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteratio Entries must be endorsed with Name, Rating and Certificate Number o Technician or Repair Facility. (See back pages for other specific entries
TE	Re-installed seat back and uproducty.			Hobbs 66.6		craft: N199	PPG, Type: PA28RT-201, S/N: 28R8218020 Tach 2220.97
	The aircraft, engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station under W/O #25-27-7 dated 7-20-0 \$\frac{2}{2} - 20-0 \$\frac{2}{2} -			***Airframe* Removed sh Accessories	neared va	cuum pum ched. run-u	np. Installed O/H vac pump, p/n 215CC; s/n 37012. See Aero up checked ok.
	file at this repair station under wor #95			accordance determined file at this re signed	with curr airworthy epair stati	ent regulate and appro- on under V	or appliance identified above was repaired and inspected in ions of the Federal Aviation Administration and was oved for return to service. Pertinent details of the repair are on WIO #DOF 33 0 4 2 dated 2000 Shane Norris.
				9	913 Willo	wview Rd,	/Indianapolis Metropolitan Airport Fishers, IN 46038 air Station #AIHR-109C
-0	Work accuracy check by gilot Bill Hill of the SHE autome check & Billy will DUAL System CHECK & COURSE SENSITIVITY CHECK	3 VOR					and the second s

Date: 10/04/2005, Aircraft: N199PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2252.9 Hobbs 100.2 "Airframe" Replaced right main tire inner tube winew, Michelin 6.00x6 tube. Removed and replaced right wing fuel drain winew. Ops check ok. The aircraft, engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station under W/O #OS 33338 dated #OS 404 Approved Repair Station #AIHR-109C BATE Date: 12/05/2005, Aircraft: N199PG, Type: PA28RT-20 "*Airframe*** Removed propeller for repair, McCauley model 2D34C 8685.24, PSMOH 1085.24 from N199PG, PA28RT-20 Tach 2285.24. The aircraft, engine, propeller, or appliance identified accordance with current regulations of the Federal Aviation and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station under W/O #OS 33338 dated #OS 404 Approved Repair Station #AIHR-109C BATE Date: 12/05/2005, Aircraft: N199PG, Type: PA28RT-20 "*Airframe*** Removed propeller for repair, McCauley model 2D34C 8685.24, PSMOH 1085.24 from N199PG, PA28RT-20 Tach 2285.24. The aircraft, engine, propeller, or appliance identified accordance with current regulations of the Federal Aviation and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station yellow for the repair are on determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station yellow for the repair are on file at this repair station yellow for the repair are on file at this repair station yellow for the repair station yellow for the repair are on file at this repair station yellow for the repair station yellow for the repair station yellow for the repair station of the Federal Aviation and yellow for the repair station and	spections, Tests, Repairs and Alterations with Name, Rating and Certificate Number Facility. (See back pages for other specific entries)
The aircraft, engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station under WIO #CS-33335 dated #CS-47-05. Signed #Indianapolis Aviation, Inc/Indianapolis Metropolitan Airport 9913 Willowview Road, Fishers IN 46038 FAA Approved Repair Station #AIHR-109C The aircraft, engine, propeller, or appliance identified accordance with current regulations of the Federal Aviation file at this repair station under WIO #CS-33335 dated #CS-47-05. The aircraft, engine, propeller, or appliance identified accordance with current regulations of the Federal Aviation file at this repair station under WIO #CS-33335 dated #CS-47-05. The aircraft, engine, propeller, or appliance identified accordance with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair station with current regulations of the Federal Aviation file at this repair are on the Federal Aviation file at this repair are on the Federal Aviation file at this repair are on the Federal Aviation file at this repair are on the Federal Aviation file at this repair are on the Federa	D24C215/00D IA-14F: s/n 807428, PTT
	service. Pertinent details of the repair are the dated (2-5-0-5), repolitan Airport 6038

AR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries	TAGE TAGE TAGE TIME Date: 03/01/2006, Aircraft: N199PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2320.0 Page: 03/01/2006, Aircraft: N199PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2320.0
	***Airframe*	** w McCaul raft N199	ey Propelle PG, PA28R	PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2285.24 er model number 2D34C215/90DJA-14E; s/n 042069, 000.0 RT-201; s/n 28R218020, ACTT 8685.24, TAch 2285.24. ecks ok.	
	accordance determined file at this re signed	with curre airworthy pair statio apolis Avii 9913 Willo	ent regulation and approve a under W ation, Inc/Ir awview Roa	r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on the foreign state of the repair are o	The aircraft, engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station under WIO # 06-338000 dated 30000 dated 300000 per signed Indianapolis Aviation, Inc/Indianapolis Metropolitan Airport 9913 Willowview Road, Fishers IN 46038 FAA Approved Repair Station #AIHR-109C

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	8	Repairs and Alteration and Certificate Number of Weight and balance or operating limitation changes shall be est for other specific entries
DATE					DATE D	100	Weight and balance or operating limitation changes continued o compatible with all previous alterations to assure continued o —Total Time
Pe	**Av emoved defe erformed in -	vionics** ective KA - aircraft	42B Loop/S ADF operat	aft: N199PG Type: PA28RT-201 Tach: 2339.9 Sense antenna and installed serviceable replacement. tional check. ADF system checks ok. or appliance identified above was repaired/installed and	8	500 7	8. Description of Work Accomplished (If more space is required, attach additional sheets. Identify with ar retraction. Removed old ELT and installed Ameri-King model AKnd stall warning. panel at fuselage sta. 62.4. Installed new antenna at s panel at fuselage sta. 62.4. Installed new antenna at s Ameri-King installation manual and AC43.13-2A chap Chapter 3,par. 36&37. Weight and balance equipmenistalled new INSTRUCTIONS FOR CONTINUED AIRWORTHINE
i	inspected in	accordan	ce with cur	rent regulations of the Federal Aviation Administration and lapproved for return to service. Pertinent details of the repair station under W.O. # 06-33812 dated 03-20-06.	Re C/ — du AL Tiç — Ins	を (公)	Introduction: Installed Ameri-Ring Lt 1 system is a TSe clamps. Next 2.Description: Ameri-King AK 450 ELT system is a TSe clamps. Next 3.Control: The ELT system is activated thru a remote are built into the ELT. 4.Servicing: The ELT system is to be serviced per FA. 4.Servicing: The ELT system is 2.Perlacement times on A-1550. Leak
_ Sig	ned ///a/	Indiana	9913 Wil	ion, Inc./Indianapolis Metropolitan Airport Ilowview Rd. Fishers, IN 46038 oved Repair Station # AIHR109C	chi Re chi Re got Prii		5.Maintenance: Replace autents of parties where the same exp. date. Remote battery must be registronic and be replaced if transmitter has been in use more than the replaced if transmitter has been in use more than the replaced if transmitter has been in use more than the replaced if transmitter has been in use more than the replaced of transmitter and the replaced of transmitter and the replaced of the replaced
	Mi	ARK			Rei Pai Rei	EE At a	wattmeter, aircraft COM radio tuned to 121.5 times. 6) Coed skin. crash activation. Reconnect all cables and wires. 6) Coed skin. switch to verify proper function. 7) Check ELT per FAI switch to verify proper froubleshoot per Ameri-King AK avvator skin was 6. Troubleshooting. Troubleshoot per Ameri-King AK avvator skin was 7. Removal and replacement info.: To remove ELT: Di bracket strap and remove ELT. Replacement is rever bracket strap and remove ELT.

The formation of the state of t	
with the work with the work of	Date: 07/11/2006, Aircraft: N199PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2379.7 ***Airframe*** Replaced nose and left gear up limit switches w/new and rigged. Normal and emergency gear extension and retract check ok. Re-installed cowling removed for access.
WILLIAMS AIRMOTIVE, INC. 9838N 1100E Kendallville, Indiana 46755 (260) 347-0807 Name:	The aircraft, engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was determined airworthy and approved for return to service. Pertinent details of the repair are on file at this uppair station under WIO # 6.5/266 dated 7-11 0.5 signed Indianapolis Aviation, Inclindianapolis Metropolitan Airport 9913 Willowview Road, Fishers IN 46038 FAA Approved Repair Station #AIHR-109C
Make Piper Model PA28RT-201 N Serial No. Part No. 35873-010 Assembly No. or Title Vertical fin assy. General Description of Repair: 'cal fin inspected and found to be in an airworthy condit END	OWNER REMOVED ALL Old CARPET & INSTALLED NEW CARPET FROM ALRIEX PRODUCTS BULL THE PRODUCTS NIRGHG S/N 28R8218020 TRCH 2379.7

YEAR: RECO TACH TIME DATE	FLIGHT TIME IN SERVICE Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) F.A.A P.M.A. AIRTEX PRODUCTS, INC. NUMBER 37499 PART CARPET 7/83NT% PART CUSHION UPHOLSTERY	YEAR: RECORDING TODAYS TOTAL FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Date: 09/21/2006, Aircraft: N199PG, S/N: 28R8218020, Hobbs: 0.0, Tach: 0.0, Total Time: 0.0 Date: 09/21/2006, Aircraft: N199PG, S/N: 28R8218020, Hobbs: 0.0, Tach: 0.0, Total Time: 0.0 "Airframe*** Replaced hinge, p/n MS20257-1 on new top cowl oil door and installed chafe tape to lower cowl over lap edge, p/n 3M8672. The aircraft, engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was
	PART HEADLINER PART WALL PANELS PART BAGGAGE COMPARTMENT PART FIREWALL COVER PART SEAT SLINGS ELIGIBILITY 1982 Repr Page 28 RT 201	determined airworthy and approved for return to service. Pertinent details of the repair are on file at this repair station under WiO #Clo_3_\USQ_0 dated \frac{9}{-2_\Display}_\Signed indianapolis Aviation, Inc/Indianapolis Metropolitan Airport 9913 Willowview Road, Fishers IN 46038 FAA Approved Repair Station #AIHR-109C
NEW C CUSTIONS	THE SOUR SEAT FRANCES down to THE FRANCE - INSTALLED ONNASS ALL FRANCES (BICKS & SEATS) REMOVED ALL OLD A LIPHUTERY & INSTALLED ALL NEW CUSHIONS & UPHOISTERY BURY THE DUMEN	

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be e	ndorsed with N	Name, Rating	g and Cer	tificate Number of ner specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteratio Entries must be endorsed with Name, Rating and Certificate Number o Technician or Repair Facility. (See back pages for other specific entrie
DATE				-			1	7	DATE	Date: 11/10/200 Painted upper of	6, Aircraft: cowling, stri	N199PG, Typoes on wing a	pe: PA28RT-201, S/N: 28R8218020 Tach Hours: 2447.55***Airframe*** and stripes on fuselage using Imron paint.
	I certify the	ne tests a	and inspecti FAR 43 Ap	ons required by FA opendix E and F.	R 91.411 and WO #_4	d 91.413 w <i>06-345</i>	vere perf	ormed	W	rogulations of t	he Federal	Aviation Adm	nce identified above was repaired and inspected in accordance with current initistration and was determined airworthy and approved for return to service. at this repair station under WIO $= \frac{1}{2} \frac{1}{2}$
	Transpor	#2 Make_ Make nder #1 Ma		Model <u>5934 PP</u> Model	2-T 76A	S/N 609. S/N - S/N 342 S/N 33 S/N -	273 988			signed W Indianapo	olis Aviation 13 Willowvi	. Inc/Indiana w Road, Fis	polis Metropolitan Airport shers IN 46038 ion #AIHR-109C
	Test Al -1000 0 500 1000	tt. #1 0 -20 -10 +0	#2	Fest Alt. #1 4000 -70 6000 + 0 8000 -20 10,000 -40 12,000 -30		18,000 - 20,000 - 22,000 25,000 30,000	#1 -30 -40	#2					
) <u>-</u>	300	0 +0	o Mr	14,000 - 20 16,000 - 20	Indianapolis A	35,000 Aviation Inc.	CRS A1	HR109C					

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
DATE		ELIGIB	PART PART PART PART PART PART PART PART	F.A.A P.M.A. IRTEX PRODUCTS, INC. 37499 CARPET COWL PAD CUSHION UPHOLSTERY HEADLINER	DATE	Date: 2/6/Hobbs 329 ***Airframe Replaced lachecks ok. The aircraff accordance determined file at this rigined	anding ge Serviced t, engine, e with cur I airworth epair state hapolis M 9913 Wi	ear hydraulic hydraulic in propeller, rent regular y and apprion under the solution, incollowiew R	ppg, Type: PA28RT-201, S/N: 28R8218020 Tach 2473.01 ic pressure switch, p/n 587-847; s/n G043227. Ops and leak reservoir. or appliance identified above was repaired and inspected in tions of the Federal Aviation Administration and was oved for return to service. Pertinent details of the repair are on W/N (0 # 0 - 3.5 9.5 9.2 dated 2.9 6.6 9.6 9.6

AR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Re Entries must be endorsed with Name, Rating ar Technician or Repair Facility. (See back pages		RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Re Entries must be endorsed with Name, Rating a Technician or Repair Facility. (See back pages	nd Certificate Number of
DATE	Date: 2/	6/2007,	Aircraft: N19	99PG, Type: PA28RT-201, S/N: 28R8218020	DATE		Miam 11-14-2	County A	raft Services Inc. hirport 913-755-4107 G S/N 28R-8218020	wheels
	+**Engine Changed and lubri	9***	ilter. Servic ntrols. Run-	ed engine with Aeroshell 15W50 oil. Washed e up and leak check ok. No visible metal found i	engine w/solvent n old filter.		Replace I.B. P/N I.B. P/N LH I.B.	76469-946, 76116-000, Flap attach s	ing Hat rails on lower center cabin; Hat rail LH Hat rail LH O.B. P/N 76469-947, Hat rail RH Hat rail RH O.B. fwd P/N 67271-000. Replaced support bracket P/N 62324-000. Installed new	landing
	determin file at thi	ed airwoi s repair s ianapolis	thy and appleted appleted and appleted appleted appleted appleted and appleted appleted appleted appleted appleted appleted appleted ap	Road, Fishers IN 46038	f the repair are on		E S/N 0 manufa cowling Replace 67352-6 67362-6 cover P tire & to hydraul & emer	trocket per ST cturers repair p P/N 67846-1 d step assy. I 00 & -01. Rep 00. Replaced //N 63942-00. ube 600x6x6j ic reservoir. I gency extens	Propeller and spinner assy. Model# BJJ36C424- CT@ SA129CH, installation instructions and rmanual. See 337 form. Replaced lower engine 11 with serviceable cowling. Painted to match. PIN 65384-00. Replaced nose gear doors P/N placed 2 ea. nose gear door retract rook P/N lower wing bolts on LH side & replace bolt. Replaced transponder antenna. Replaced LH, PN Atrhawk. Replaced brike pads. Serviced Placed aircraft on jacks ran 12ea. landing cycles sions, checked gear horn. Lubed gear & all flight	\$
	Miami (10-22-200 Tach: 250 Installed (S/N 0706	County A 17 N199P 13.5 16 State S	# SA129CH.	ces Inc755-4107 .8218020 PROPERTY Model# B3D36C424-E Aircraft Inspected and found la MO to Paola MS K 81.	3 blade peller		controls	s. Cleaned fue corrosion & p	el screens. Removed ELT & Tray eleaned & primed tray, Replaced ELT batteries. ELT tested Next (A 6 e)	(out

YEAR: - 14-07 DATE	TACH TIME 2505.75	TODAYS FLIGHT	TOTAL TIME IN SERVICE 8905,69	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.
CONT	→ ·	Gerdes i USA. A time. I co Annual i condition	gnition switch. ircraft was test ertify this aircr aspection and at this time.	ction 1-4 ops check good. C/W AD93-05-06 Alicraft was re-weighed by Plane Weighs I flown and all systems function normal at this aft has been inspected in accordance with an was determined to be in an airworthy LEAN TO 495680-470 rvices Inc.		***Airframe* Moved comp card. Compa	** bass aft a ass swun	nd up on w g w/radios o	PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2514.7 rindshield bar. Swung compass. Installed compass deviation on. Card reads as follows: 360-01, 030-031, 060-062, -179, 210-209, 240-237, 270-269, 300-269, 300-300, 330-330.
						determined a determined a dile at this rep digned Indiana	with current airworthy pair station polis Avia 1913 Willo	and approven under Winder Inc.	appliance identified above was repaired and inspected in one of the Federal Aviation Administration and was red for return to service. Pertinent details of the repair are on 10 #0 7 - 3 6 4 0 7 dated 12 - 1 3 0 7, dianapolis Metropolitan Airport 4d, Fishers IN 46038 in Station #AIHR-109C
			1.000						


19d	RECORDING TACH	TODAYS FLIGHT		Description	- Commission of the Commission				Description of Inspections, Tests, Repairs and Alteration		
htn E	TIME	nges for c	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name; Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Entries must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other specific entr		
D:	ate: 2/ 4/20 *Airframe***	008, Aircr	aft: N199PC	6, Type: PA28RT-201, S/N: 28R8218020 Took 2524.0	DATE				7828PT-201 S/N: 28R8218020 Hobbs 0406.4		
K	eplaced bat	tery w/ne	NA C25. 0/-	G02347832. Serviced and charged. Ops check good. eplaced AN910-1D fitting to oil pressure switch w/new. Leak		Date: 4/10	/2008, Ai	ircraft: N199	PG, Type: PA28RT-201, S/N: 28R8218020 Hobbs 0406.4		
Sen	eck good. rviced main gear struts w/nitrogen.					***Airframe	Tach 2546.95 ***Airframe*** Legtalled new retaining rir		orward left cowl fastener.		
de	etermined a e at this rea gned Indiana	airworthy pair station polis Avia	and approve p under W/ ation, Inc/In	appliance identified above was repaired and inspected in ns of the Federal Aviation Administration and was ad for return to sarvince. Pertinent details of the repair are on 2 # 08 - 3 # 5 7 5 dated 2 # 4 2008. dianapolis Metropolitan Airport d, Fishers IN 46038		The aircraft accordance determined file at this signed Indian	t, engine, e with cur airworth epair stat napolis A	, propeller, or rrent regular by and appro- tion under V	or appliance identified above was repaired and inspected in tions of the Federal Aviation Administration and was oved for return to service. Pertipent details of the repair are on VIO #08-36827 dated 4/10 2008. Indianapolis Metropolitan Airport bad, Fishers IN 46038 air Station #AIHR-109C		
		, c., pp.									
			1 20 - 10			100					

TEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entrie	es must be	endorse	d with Name,	Rating an	d Certifica	d Alteration ate Number of pecific entries		
	Removed prinspection/relbs. Leak ch	rop, McC epair due leck good	auley B3D3 to scratch I.	PG, Type: PA28RT-201, S/N: 28R8218020 Tach 2547.11 66C424E; s/n 070662 & sent to Aircraft Propeller Service for by tug. See 8130-3, re-installed propeller. Torqued nuts to 60 or appliance identified above was repaired and inspected in	DATE	I certify the in accordance of Altimeter # Encoder Transport	dance with #1 Make #2 Make Make_	United Transc	Appendix Mode Mode	E and F.	34PA-	S/N_S/N_	6093	<u>р</u>	ed		
	accordance determined file at this	with curr airworthy pair stati	ent regulat and appro on under W	ions of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/0 # 09 - 368 96 dated 5 16 / 2008.		Transpond Test Alt.	ler #2 Mak #1	e	Test Alt.	Model	#2	S/N_ Test Alt.	#1	#2	3		
	signed Indian	anolis Av	iation Inc/I	Indianapolis Metropolitan Airport		-1000	10		4000 6000	-20		18,000	-40				
		9913 WII	lowview RC	ad, Fishers III 40030		500	-5		8000	-25		22,000	-50	Limited Street			
_		FAA App	roved Repa	air Station #AIHR-109C				1000	10		10,000	-30		25,000			
						1500	+0		12,000	05-		30,000					
						2000	-10	100	14,000	- 25	1000	35,000					
						3000	-10		16,000/	-151			7				
						Date <u>/ Z/</u>	14/08	ВуМи	# S	1/-	dianapoli	is Aviation Inc	c. CRS All	HR109C			
								Sac al	=_					140			

YEAR: RECORDII TACH TIME	G TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteratic Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
DATE				DATE				
Total Time 8 ""Airframe" Completed a Checked co Bi-weekly 20 Removed ar Installed nev Installed nev Performed E box. ELT ter Remote batt Replaced br Removed rig Goodyear F AD 93-05-06 Replaced br Dis-connect Re-connect	993.02, Ta nual inspirtol surface 08-24. d replaced instrumer vacuum r LT 12 mon te god. Ne te god. Ne te god. Ne th main br d flap. Ops re-cotter r r-Found le r-cotter r r-Found le	ch 2593.02, ection. Serve travels an induction a tair filter, pegulator filter thinspection chapter in the pegulator filter to pegulator filter fil	ic Type: PA28RT-201, S/N: 28R8218020 Hobbs 455.4 iced tires. Repacked wheel bearings. Serviced battery. d cable tensions. Lubed controls. AD's checked thru ir filter winew, p/n BA10. In AAD9-18-1. In AARB3-5-1. In IAW FAR 91-207d (1-4). Cleaned corrosion from battery in due 12/2009. Battery replacement due March 2014. terminal winew. is-assembled, cleaned, inspected, and re-assembled winew bi-installed wheel assy. CS/Gerdes ign switch due 3916.0 Tach. In 164-02000 and linings, p/n 066-10500. If rom flap. Replaced bolt winew AN23-18 bolt. d. Ir ebolt at servo. Ite bolt at servo. Ite bolt at servo. Ite did saket and screen. No defects noted. Removed fuel from 90 dg fitting. Removed fitting, cleaned and re-installed ask check good. Ir de dand re-installed.		63531-000 : Installed pro Replaced st Removed el Installed ner Replaced th placard, p/n Ops checke Removed al Installed duration of the Removed al Installed duration file at this Signed	and safet pper hard ceet tube ceet tube end of inte w cover of factors of the cover	ied. ware in bot from botto rnal wire fr n o cabin do trol cover 1 45. Installe eaned corre ed one whe hub cap) o aft has bee spection an punder W/C viation, Inc. fillowview I	tom cowling. m cowl to oil cooler. om cabin heat scat tube and secured to cabin heat valve. me light. whinew, p/n K67232-27. Fabricated face plate and installed d assy and checked for clearance and proper mixture lock. osion from battery box. Re-installed battery. eel bearing and race on nose wheel. on left main wheel. en inspected in accordance with an d determined to be in airworthy condition. Pertinent details are 0#_08_3_7000

EAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteratio Entries must be endorsed with Name, Rating and Certificate Number o Technician or Repair Facility. (See back pages for other specific entries
	Tach 2625.6			PG, Type: PA28RT-201, S/N: 28R8218020 otacle on lower cowl, p/n 484-483. Touched up rivets w/paint.		Tach 2625.1 ***Airframe* Removed ba	Hobbs 4	89.4 n aircraft ar	PG, Type: PA28RT-201, S/N: 28R8218020 Ind charged. Re-installed battery. Ops check ok.
	accordance determined file at this re signed Indian	with currainworthy pair stati	ent regulative and approon under With a contraction, Inc/I lowview Ro	r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was weed for return to service. Pertinent details of the repair are on I/I/O I/I/O A 8469 dated 6 - I/I - O 2, or		determined a file at this re signed Indiana	with curre airworthy pair statio apolis Avi	and approven under Water and approven under Water attention, Inc/Irowview Road	rappliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 10 #0_1_3 7 5_3 dated 2-2_0_9 didinapolis Metropolitan Airport ad, Fishers IN 46038 ir Station #AIHR-109C
				3.7					

AR:	RECORDING TACH TIME	TODAYS FLIGHT		E IN Entries must be enderged with the	YEAR:	RECORDING TACH	TODAYS FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of
ATE				(See back pages for other specific entries)		TIME		SERVICE	Technician or Repair Facility. (See back pages for other specific entries.)
				PG, Type: PA28RT-201, S/N: 28R8218020 n G02445269. Charged and installed in aircraft. Ops check ok.	DATE	Date: 10/ 8. Tach 2650. ***Airframe Re-secured	15		PG, Type: PA28RT-201, S/N: 28R8218020
	file at this resigned Indiana	pair station s	and approvon under Williation, Inc/Ir	r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was wed for return to service. Pertinent details of the repair are on 1/0 #연구.3 8가 용너 dated 육 고 기 공혹. Idiamapplis Metropolitan Airport ad, Fisher3-N 46038		accordance determined file at this signed indian	with curr airworthy pair stati apolis Av 9913 Will	ent regulation and approven under Williamin, Inc/Ir owview Ros	r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was wed for return to service. Pertinent details of the repair are on
-17									



YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Altere Entries must be endorsed with Name, Rating and Certificate Numb Technician or Repair Facility. (See back pages for other specific er	
DATE					
	Tach: 2654.2 "Airframe** C/W annual Replaced fue check good. Temporarilly Resealed nos Installed a ne Reattached e Removed ext needed. Rein gaskets and h Applied Corro Installed new Readjusted pl Installed new Removed tips Installed new Removed tips Installed new Removed tips Installed new Inst	Dispection of the control of the con	s: 518.5 A/in of aircraft ump breaki both LH & I shimmy da on filter p/n haust scat I cks for shrc khaust scat I cho corrosion e for upper mor rod en pivot stud a e baffle sea lator and in med with p in med with p in a choice in the corrosion of the corrosion e for upper mor rod en pivot stud a e baffle sea lator and in med with p in me	spected inside with a boroscope. Removed surface corrosion	
				LH wheel well aft skin, touched up with paint. flap outboard hinge and touched up.	
_ a	nd top coate	d.	right whee	wheel well wing walk support. Installed with structural	
	apricated do	uhlar nat	oh for sight		

R:	RECORDING TACH TIME	TODAYS	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.		RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
	Removed of coated. Pai Removed Id Removed Id Replaced of Replaced of Replaced of C/W FAR 9 ELT remote 3/2014. AD 93-05-0 A/CTT)	ight flap, orrosion nted rive eft main I alled. p lower t rings in ose whe 1.207d c b battery 6, eff. da	replaced in at both win at both win so from pre anding gea ension spri parking brall assemble heck on El replaced, part to 4/29/199	hboard rib p/n 62328-001, re-installed and touch up painted. In grear mounts, primed with zinc phosphate primer and top In grear mounts, primed with zinc phosphate primer and top In grear and repaired two cracks in the fiberglass, touched up In gr/n 487-378. In gr/n 487-378, serviced tire to 27psi. In No defects noted. Ops checked good. Next due 12/2010. In DLI/3N. New expiration date 12/2017. ELT battery due In gr/n 487-378. In gr/n 497-378. In gr	DATE	Tach 2665. ***TAirframe' Installed Lo Report #41 Installed Wf F.S. 181.0 I balance equ Troubleshot landing light The aircraft, accordance determined file at this se signed	35 Hobbs *** Presti coi and STC helen Eng AW STC Lipment li t landing l t, ops che , engine, , with curr airworthy pair static apolis Avi	mposite wir # SA01982 jineering M SA800EA. st updated. ight. Found cked good. propeller, o ent regulati and appro- on under W	r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Perlinent details of the repair are on 1/0 #_[0_36] rs dated 1 - 2 - 1e_,
	on file at th	100 Hr in is agency	spection a under W/ viation, Ind	sen inspected in accordance with an und determined to be in airworthy condition. Pertinent details are 0 # 0 9 - 3 1116 Date: 12/24/2007 c., Indianapolis Metropolitan Airport, Road, Fishers, IN 46038 tepair Station #AIHR-109C			9913 WIII	owview Ro	ad, Fishers IN 46038 sir Station #AIHR-109C

B.

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries,)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE					DATE				
	Tach 2683.9 ***Airframe**			PG, Type: PA28RT-201, S/N: 28R8218020		Tach 2685.	39 Hobbs	549.6	PPG, Type: PA28RT-201, S/N: 28R8218020 om intake and secured plate to air box.
,	accordance of determined a file at this rep signed Indiana	with curre airworthy pair station polis Avi	ent regulation and approved approved and approved approved approved and approved approv	r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/10 # 10 - 39 536 dated 3 17 - 10 midinapolis Metropolitan Airport ad, Fishers IN 46038 air Station #AIHR-109C		accordance determined file at this re signed Indian	with curr airworthy pair stati apolis Av 9913 Wil	ent regular and appro on under V iation, Inc/ lowview Ro	or appliance identified above was repaired and inspected in tions of the Federal Aviation Administration and was oved for return to service. Pertinent details of the repair are on Windianapolis Metropolitan Airport oad, Fishers IN 46038 air Station #AIHR-109C

	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Pre	Airframe*** pped, prim	lach led, and	painted bot	G, Type: PA28RT-201, S/N: 28R8218020	DATE	TIME		SERVICE	1001 Airport Road Destin, Florida 32540
655 All r	90-001, 65 epaired by	5591-000 Airfram	painted con I. Rudder pi e Compone	er Maintenance Manual after painting all within limits. In Maintenance Manual after painting all within limits. In Starbeno Pin 35640-024, 35640-025, Flaps p/n fn 35879-003. Horizontal stab including tabs p/n 35894-003. Ints by Williams. touched up paint.		N	ALAND W		2 2694 — Recopt as stated below, no other work, inspection, Corrective action or determination of d Associations was made at this time.
dete file a	ermined air at this repa	th currer worthy a ir station olis Avia	nt regulation nd approve under W/C	appliance identified above was repaired and inspected in so of the Federal Aviation Administration and was do for return to service. Pertinent details of the repair are on #/o-39 287 dated 4-27-co . Ilianapolis Metropolitan Airport 1, Fishers IN 46038			cliano	of work perfo all up a 7 times	Power tock Switches Cycled
*				Station #AlHR-109C		in S	Signed Signed		Figure, Averant Engine, Propeller or Appliance was Required and Inspected on of the FAA Administration and is approved for return to service. CRSSDZJR423D Date: 5-6-70

YEAR: RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
Tach 2705.3 **Airframe* Installed cal Engine start Jacked aircr Adjusted pro The aircraft, accordance determined file at this assigned Indian	brated test and run-up aft, swung ft. Service p lever ca engine, pr with currer airworthy a bair station apolis Avia	gauges or o check, ch gear. Test d gear pow oble. Lubed. opeller, or nt regulatio nd approve under W/	G, Type: PA28RT-201, S/N: 28R-8218020 In fuel system. Electric fuel pump operation checked ok.	— 1 — 1 — 2 — 3 — 6	rach 2709. H **Airframe*** roubleshot A liscrepancy. I The aircraft, e locordance w letermined ai le at this repliagred Indianar 99	DF for no Ops check of the Corps	aft: N199PC	Technician or Repair Facility. (See back pages for other special entities G, Type: PA28RT-201, S/N: 28R-8218020 Performed operational checks. Could not duplicate appliance identified above was repaired and inspected in so of the Federal Aviation Administration and was after return to service. Pertinent details of the repair are on 0 #10-39827 dated 7.2009. dianapolis Metropolitan Airport d, Fishers IN 46038 Station #AIHR-109C

Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries	
	DATE					
PG, Type: PA28RT-201, S/N: 28R-8218020 mixture, throttle, and heat control cables. Ops check,		Tach 2741.3 ***Airframe** Removed alt check good.	Hobbs 6 ernator. (Re-instal	05.2 Checked w lled cowling	PG, Type: PA28RT-201, S/N: 28R-8218020 iring and noise filter. Re-installed alternator. Ran engine, ops	
or appliance identified above was repaired and inspected in itions of the Federal Aviation Administration and was oved for return to service. Pertinent details of the repair are on V/O # 10 - 400 / dated 9(17/20/0). Indianapolis Metropolitan Airport oad, Fishers IN 46038 air Station #AIHR-109C		accordance of determined a file at this repsigned Indiana	with curre airworthy pair statio apolis Avia	and approved under Wation, Inc/Irowview Ros	rappliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was yed for return to service. Pertinent details of the repair are on 10 # 10 * 40 2 3 3 dated 11 - 2 4 - 10 . Indianapolis Metropolitan Airport and Fishers IN 46038 ir Station #AIHR-109C	
Otti	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) G, Type: PA28RT-201, S/N: 28R-8218020 mixture, throttle, and heat control cables. Ops check, r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/10 #10 - 4/0011	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) G, Type: PA28RT-201, S/N: 28R-8218020 mixture, throttle, and heat control cables. Ops check, r appliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/10 ± 1/0 - 4/0011	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) G. Type: PA28RT-201, S/N: 28R-8218020 Date: 11/24/ Tach 2741.3 mixture, throttle, and heat control cables. Ops check, rappliance identified above was repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/10 #10 - 4/01 dated 1/17/20/0. Indianapolis Metropolitan Airport and, Fishers IN 46038 indiana fishers IN 46038 indiana fishers IN 46038 indiana fishers IN 46038	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) G. Type: PA28RT-201, S/N: 28R-8218020 Date: 11/24/2010, Air Tach 2741.3 Hobbs 6 ""Air/Trame"." Removed alternator. check good. Re-instata Replaced landing light ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/10 #10 - 4/01 dated 1/21/20/0. Indianapolis Metropolitan Airport and, Fishers IN 46038 Indianapolis Metropolitan Airport (Statien #44IRS-100C) PLEHT TIME PLIGHT TIME PLIGH	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) G. Type: PA28RT-201, S/N: 28R-8218020 mixture, throttle, and heat control cables. Ops check, mixture, throttle, and heat control cables. Ops check, rappliance identified above was_repaired and inspected in ons of the Federal Aviation Administration and was ved for return to service. Pertinent details of the repair are on 1/10 # 10 - 400 ft dated 5/1 1/2070. Indianapolis Metropolitan Airport and, Fishers IN 46038 resistation # 44HR-109C.	