

01D



TJ-472
LH

N-58TR
NEW 10-84

PROPELLER LOGBOOK

Printed in U.S.A.
May 1983

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
4-18-90	594.4	594.4	Prop Resealed By American Propeller	<p>THIS MAINTENANCE RECORD IS NOT VALID UNLESS THE AIRCRAFT IS RETURNED TO AIRWORTHY CONDITION. RETURN AIRCRAFT TO SERVICE - SIGNATURE <i>[Signature]</i> DATE 4-18-90 WO. 500259 T. TIME 594.4 FLIGHTCRAFT Hayward, CA. FAA. A.R.STA. #FCP5831D</p>
<p>DATE 7-19-90 TAC/HR 6330 TOTAL TIME 6330 NEF 6330 <i>APPROVAL</i> INSPECTION WAS PERFORMED ON PROPELLER AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. DETAILS ON W/O 5006265 SIGNATURE <i>[Signature]</i> INSPECTOR, FLIGHTCRAFT, INC./HAYWARD FCP5831D</p>				
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12				

MAINTENANCE & SERVICE HISTORY

Date	Left Propeller Log Entry	Authorized Signatures Repairman and Station Certificate Numbers
	<p>Reg # N58TR MFG McCauley Model 3AF32C511-B Serial #841081 SNEW/SMOH 1813 Hr Meter 1813</p> <ul style="list-style-type: none"> Researched AD's thru 2008-14 (summary provided) AD83-13-06 DNA, AD03-13-17 DNA, AD05-14-11 DNA, AD06-24-07 DNA Dressed blade leading edges Adjusted TO RPM Dynamically balanced engine / propeller assembly IAW ACES guide to dynamic balancing using 2020 probalancer, final solution = .06 IPS with 11 grams of weight added Serviced unfeathering accumulator IAW Beech MM Replaced de-ice brushes C40256-1 brushholder LH & C40256-2 brushholder RH <p>I certify this propeller was inspected in accordance with a 100 hour/Annual inspection and is determined to be in airworthy condition. Returned to service this date.</p> <p>Signature: <i>[Signature]</i> Date: 8/1/2008 David Wayne Beaver AP 3097750 IA 8320 Thora Lane, #F-1, Spring, TX 77379, 281-376-6664</p>	
letins On Pages 11 & 12		

MAINTENANCE & SERVICE HISTORY

Propeller S/N 841081 has been overhauled
this date 3-11-09 I/A/W manual(s)
MPC500; BOM100R04; SPM100R04

under W/O # 11358 The mechanic making
the installation must c/w 14 CFR Part 43.9.
R & D Propeller Service, Inc.
2528 Hatfield Rd., Pearland, TX 77581
FAA CRS# R5DR343X
Signed Alan Paul

Signature Of Work	Authorized Signatures Repairman and Station Certificate Numbers

& Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Abilene Aero Inc. 2850 Airport Blvd. Abilene TX 79601
Date: 3/25/09 Propeller S/N 841081 Total Time: 2082.2
TSMOH: 0.0
Left prop S/N 841081 after overhaul from CRS# R5DR343X. Reinstalled left prop governor S/N 1817051C after overhaul from CRS# R5DR343X. --
Reinstalled left prop spinner after repair by K&K Precision Welding CRS# XKKR436L.

Registration# N58TR
Meter: 2082.2 WO# 10749

[Signature]
Approved for return to service
AP3309979

Abilene Aero Inc. 2850 Airport Blvd. Abilene TX 79601
Propeller S/N 841081 Meter: 2285.9
Airworthiness Directives Through 2009-19
I Certify this propeller has been inspected IAW FAR 43 appendix D 100 hour inspection and found to be in an Airworthy condition. Dressed, and
painted blades.

WO# 11010 Registration# N58TR Date: 9/22/09
Total Time: 2285.7 TSMOH: 203.7

[Signature]
Approved for return to service
AP450828487

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

8

Gregory Langham
A&P458476877


Service Bulletins On Pages 11 & 12

9

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

10

Gregory Langham
A&P3592918
IA458476877

[illegible]

Joe Leonard CRS#: BGSR439C

LET!

Signature
and State
Lumber



Dat

Left Prop

Complied with Left Propeller Annual Inspection IAW Baron 58P AMM Annual Long Form Inspection Guide p/n: 102-590000-19J.

Maintenance Release

The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

Signed: Barbara CRS# BGSR439C

Number

Authorized Signatures
Repairman and Station
Certificate Numbers



FREEDOM

Freedom Aviation
310 Hangar Road
Lynchburg, VA 24502
(434) 237-3342
CRS# BGSR439C

Date: 9/8/2017, Aircraft: N58TR, Type: BE-58, S/N TJ-472; Tach: 630.4, ACTT: 3196.5, WO#: F17-2741
Model: 3AF32C511-B, S/N 841081, TSN: 3196.5

Left Propeller Entries
Complied with Left Propeller Annual Inspection IAW Baron 58P AMM Annual Long
Form Inspection Guide 5-20-00 AMM.

Maintenance Release

Maintenance Release
The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.

JOE LEONARD CRS# BGSR439C

10-01-18 S/N 10472, HOBBS 6015, A/C 3264.1 S/N 1131.3
Annual inspection. Dressed minor nick on blades.
I certify this prop has been inspected ~~and found~~^{inspected} and
determined to be in an airworthy condition.
AP checked thru 2015-16
7 Scott Helms

ATP 3154904 IA 10/1/18