



EAST COAST PROPELLER SERVICE INC.

PROPELLER LOGBOOK

PROPELLER MODEL 3AF32C511-B

PROPELLER S/N 840961

N58TR

R/H Engine

LOG BOOK # 1

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model 3AF32C511-B

Propeller S/N 840961

Blade Design G-82NEA-4

Blade S/N's

No. 1 ANA 26019

No. 2 ANA 26020

No. 3 ANA 26021

No. 4 |

No. 5 |

No. 6 |

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather 82.5°

Start Lock 19.4°

Low 16.1°

Reverse N/A

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
3/4/19		-0-		Propeller model 3AF32C511-B serial number 840961 was overhauled this date. Blade serial numbers D5052, EC427, and AJ233 were replaced with ANA 26019, ANA 26020, and ANA 26021. See form 8130-3 for details.
				MAINTENANCE RELEASE
				The component identified above was repaired and inspected in IAW regulations of the FAA and was found airworthy for return to service. Pertinent details of the work performed are on file at this agency under work order <u>ER13554</u>
				For EAST COAST PROPELLER SERVICE, INC 2079 MAIN STREET LITITZ, PA 17543 FAA REPAIR STATION #E65RO64Y

3/25/2019		-0-		Installed C/H prop to R/H Engine. MODEL # 3AF32C511-B S/N: 840961
TACH 7125				BLADE S/N: D5052, EC427 + AJ233 WERE REPLACED WITH ANA 26019, ANA 26020 and ANA 26021. IAW BEECHCRAFT MM. NEW HARDWARE WAS INSTALLED. Ground RAN Engine. ops checks good.
				7. Scott Hedrick A+P 3154904 IA.
11/13/19				
TACH 767.1				Annual/100hr. inspection. NO discrepancies found. I certify this prop has been inspected IAW Annual/100hr. inspection and was found to be Airworthy. A+P 7. Scott Hedrick IA.

