YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterestries must be endorsed with Name, Rating and Certificate Num Technician or Repair Facility. (See back pages for other specific endorse)
DATE	43.€		.53. ³	
21-2120	uminista en con la timo de Maria de comencia en consecuencia de consecuencia de consecuencia de la consecuencia	obyggene i ki k		N824BH 05-21-2020 Tac 43.0 TT 53.3 Preformed condition inspection as per AC/43 Appendix D. cleaned lubed and inspected heim rod end and control surfaces. Inspected wheel bearings and serviced brakes fluid. Inspected fuel caps lubes o rings. Preformed wheel retraction and extinction and emergence extinction Cleaned Aircraft. Preformed ELT inspection as per CFR 91.207 d (OK). Battery Due 03 2029 Installed new remount battery CR-1/3N dated 3-2029 Installed new canopy lift struts. Patched left landing gear nose door hinge. Readjusted nose doors. I certify appendix D. and was determined to be in airworthy condition. Scott K Rustad A&F 512703346 IA
		aggine acts and consignment of the school asset of the latter and the school asset of	nce et demoire se <mark>mening et en e</mark> n conference planet and et en	
occusio, de sidio internalis Algencia (Alle Californio de Sidio) de una disministratorio de Alleccia (Algencia (Alleccia)) de Californio (Alleccia) de Californio (Alleccia	de de recommissão processor discontração processão de recomer a comissão de recisida de recomer de secunda de c			
not recursión à cultura está tempo desina con está con escutiva escuence para está de escuence de escuencia de	goggene – Ingresse, grek alle film 6/3 Care (33) spålant (film dans) film etter et en en er film (film dans)			
		e de la companya de l	e Line of the second second Second second se	- AND 512703346

Property of the Control of the Contr

DATE YOU 2020	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Rep Facility. (See back pages for other specific entries.)
-21-2696	13.0		53.3	
				N824BH 05-21-2020 TAC 43.0 &TTAC 53.3 TSMOH 53.3. Preformed a condition inspection as per part 43 Appendix D. Cleaned fuel screens compressions cold as #1 76/80 #2 77/80 #3 76/80 #4 77/80#5 77 # 6 78/80 . Serviced propeller as per Hartzell MM cleaned engine .lude condition levers changed engine oil serviced with 12Qt 15W50 changed oil filter with tempest 110-1.set mag timing, and static run. I certify that this aircraft ENGINE & PROP has been inspected as per part 43appendix D. Condition inspection and was determined to be in airworthy condition. Scott K Rustad A&P 512703346
			What was a second	
	COLUNION DE CONTRACTOR DE CONT			
		Constituting the constitution of the constitut		
		ang Malik lapa dia simbara saora matana ana ang Pangalan alam	tion not the state of the state	
	AND THE AREA AND THE STATE OF T			