

YEAR:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance
DATE			
REPORT 2021	Total Time 7284.0	Tech 7284.0	Hour meter 5114.0, SFA 21.0
Annual Inspection completed this date.	Replaced ELT battery with new		
MERL PN RA-1020	New replacement date is Jul 2023.	ELT was checked	
per FAR 91.207(d).	Replaced tail spring bushings with AAT, LLC FAA-PMA-		
PN AAT-0742112	bushings. Replaced bracket air filter element with		
new RA-8103-1 element mfg 7/20.	Complied with AD 2020-21-22 by		
inspection of items per PAR 6 and by following	Cessna Service letter		
SEL-95-01. No cracks were found but 2 ground rivets were found (1 on			
each side of the left elevator hinge bracket in the tail cone reinforcement			
ample for safety & reliability, both left & right tail cone reinforcement			
angles were modified using QNT INC. Tail Cone Reinforcement Angle			
kit per STC SAA02528AK (from McFarlane Aviation Products). The tail			

4 B