

HAAGLE ENGINE

20208 Charlamme Drive
Redding, CA 96002, U.S.A.
FAA REPAIR STATION NO3R717L
(800) 292-7767 Fax (530) 221-5201



Estimate: 102999-1BH
Date: 10/29/99

[illegible]

Q#	Outside Services	Amount
	TAX	
	SUB TOTAL	N/A

Terms & Conditions

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you, your employees or designated subcontractor permission to operate and/or fly the aircraft herein described for the purpose of testing or inspection. You will not be held responsible for loss or damage to the aircraft or articles left in the aircraft, in case of fire, theft, or any other cause beyond your control. An express mechanic's lien is hereby acknowledged on the above aircraft to secure the amounts of repairs thereto. If it becomes necessary for you to employ a collection agency and/or an attorney to collect this account, I agree to pay all court costs plus a reasonable attorney's fee and/or collection agency fee. This agreement has been entered into on the State of California and the parties agree that the Superior Court in and for the County of Shasta, State of California, United States of America, shall be the only forum for any action which may be brought to enforce or interpret the terms of the agreement.

Read and Agreed to by: _____ **Title:** _____ **Date:** _____



EAGLE ENGINE
20208 Charlamme Drive
Redding, CA 96002, U.S.A.
FAA REPAIR STATION NO3R717L
(800) 292-7767 Fax (530) 221-5201



Qty	Parts Description	Amount	Acft Make	Model	Reg No	Customer
1	IRAN INSPECTION PARTS KIT		Continental	O-470-R	N42270	Rick Mann c/o FLIGHTCRAFT - James Allen
	Parts kit includes: main bearings, connecting rod bearings, seal/ gasket set, oil pressure spring, connecting rod bolts / nuts / pins, counterweight plates / clips, cam- shaft gear screws, piston rings oil, oil filter and misc. hardware.	1,578.68				19990 Sky West Drive Hayward, CA 94541
Additional parts required to complete repair:			Labor Description			
6	539467 piston pin	41.95	A.	IRAN Inspection Only of (1) Continental O-470-R engine, for fuel contaminating as per Service Bulletin M88-10 replacing only parts as indicated and Ultrasonic Inspection of crankshaft		
6	653877 lifter	52.64				
6	653888 lifter	35.26				
1	653052 camshaft	518.00	B.	Test Run Engine.		
6	655004 conn rod	363.99				
1	649141 crankshaft	exchange	Terms:	\$11,000.00 deposit required, balance due upon completion.		
6	654959A5 cylinder assy	1101.00				
		14,941.72				
	Less Price adjustment	<804.13>				
	HWC	5.75				
	TAX	As required				
	SUB TOTAL	14,137.59				
				Sub Total Labor 3,700.00		
				Sub Total Parts 14,137.59		
				Sub Total Other Services N/A		
				Incoming freight 180.00		
				TOTAL 18,017.59		

Qty	Outside Services	Amount	Terms & Conditions
			<p>I hereby authorize the repair work to be done along with the necessary material, and hereby grant you, your employees or designated subcontractor permission to operate and or fly the aircraft herein described for the purpose of testing or inspection. You will not be held responsible for loss or damage to the aircraft or articles left in the aircraft, in case of fire, theft, or any other cause beyond your control. An express mechanic's lien is hereby acknowledged on the above aircraft to secure the amounts of repairs thereto. If it becomes necessary for you to employ a collection agency and or an attorney to collect this account, I agree to pay all court costs plus a reasonable attorney's fee and or collection agency fee. This agreement has been entered into on the State of California and the parties agree that the Superior Court in and for the County of Shasta, State of California, United States of America, shall be the only forum for any action which may be brought to enforce or interpret the terms of the agreement.</p>
	TAX		<p>Read and Agreed to by: _____ Title: _____ Date: _____</p>
	SUB TOTAL	As requested	



Date: 10/29/99

[illegible]